





**TOP VIEW**




**FRONT VIEW**

Note on drilling
Solid line : drill on the front side
Broken line: drill on the back side

**Operations:**
---

**Facing for cnc:** ----

**Setup:** ----

| Rabbet Width | Rabbet Depth | Hinge Hole Depth | Hinge Hole Offset *from edge* |
|---|---|---|---|
| 0.30 in | 0.50 in | 0.563 in | 0.955 in |

| Latch |
|---|
| Occupancy Indicator |

| | | | | | |
|---|---|---|---|---|---|
| ORDER NUMBER | | 2X8X-0002 | | | |
| COMPONENT ID | | 1-D1-2X8X-0002 | | | |
| SERIES | | 2X8XG | | | |
| TOLERANCE | | 0.02 in | | | |
| FLOOR CLEARANCE | 9.00 in | SWING | | HINGE | |
| CEILING CLEARANCE | 1.00 in | Outswing | | right-hand hinging | |
| HARDWARE | Continuous | SCALE 1:8 | WEIGHT | | SHEET 1/1 |