





TOP VIEW



FRONT VIEW

Note on drilling
Solid line : drill on the front side
Broken line: drill on the back side

Operations:

Facing for cnc: ----

Setup: ----

Rabbet Width	Rabbet Depth	Hinge Hole Depth	Hinge Hole Offset *from edge*
0.30 in	0.50 in	0.563 in	0.968 in

Latch
Occupancy Indicator

ORDER NUMBER		2X8X-0044			
COMPONENT ID		1-D1-2X8X-0044			
SERIES		2X8XG			
TOLERANCE		0.02 in			
FLOOR CLEARANCE	9.00 in	SWING	HINGE		
CEILING CLEARANCE	1.00 in	Inswing	right-hand hinging		
HARDWARE	Standard	SCALE 1:8	WEIGHT	SHEET 1/1	