



Operations: -left exterior rabbet -right exterior rabbet

Facing for cnc: exterior up

Setup: G57 > rotate > G59




TOP VIEW



RABBET DETAIL


Reference - Only machine if displayed.



no notch

TOP NOTCH DETAIL



Reference - Only machine if displayed in front view.



no notch

BOTTOM NOTCH DETAIL

Reference - Only machine if displayed in front view.



FRONT VIEW

Note on drilling and rabbeting

Only machine if displayed.

Solid circles : machine on the front side

Broken circles: machine on the back side

ORDER NUMBER		3X8X_DV_0015		
COMPONENT ID		3X8XDoor		
SERIES		3X8X		
TOLERANCE		0.02 in		
FLOOR CLEARANCE	5.75 in	SWING Inswing	HINGE left-hand hinging	
CEILING CLEARANCE	4.50 in			
		SCALE 1:8	WEIGHT	SHEET 1/1