





**Operations:** -right interior rabbet -left interior rabbet


**Facing for cnc:** interior up

**Setup:** G57 > rotate > G59




**FRONT VIEW**

Note on drilling and rabbeting  
Only machine if displayed.  
Solid circles : machine on the front side  
Broken circles: machine on the back side




**TOP VIEW**



**RABBET DETAIL**


Reference - Only machine if displayed.



no notch

**TOP NOTCH DETAIL**

Reference - Only machine if displayed in front view.



no notch

**BOTTOM NOTCH DETAIL**

Reference - Only machine if displayed in front view.

|                   |          |                   |                            |           |
|-------------------|----------|-------------------|----------------------------|-----------|
| ORDER NUMBER      |          | 3X8X_DV_0020      |                            |           |
| COMPONENT ID      |          | 3X8XDoor          |                            |           |
| SERIES            |          | 3X8X              |                            |           |
| TOLERANCE         |          | 0.02 in           |                            |           |
| FLOOR CLEARANCE   | 12.00 in | SWING<br>Outswing | HINGE<br>left-hand hinging |           |
| CEILING CLEARANCE | 2.00 in  |                   |                            |           |
|                   |          | SCALE 1:8         | WEIGHT                     | SHEET 1/1 |