





**Operations:** -right interior rabbet


**Facing for cnc:** interior up

**Setup:** G59 only




**FRONT VIEW**

Note on drilling and rabbeting  
Only machine if displayed.  
Solid circles : machine on the front side  
Broken circles: machine on the back side




**TOP VIEW**



**RABBIT DETAIL**


Reference - Only machine if displayed.



no notch

**TOP NOTCH DETAIL**

Reference - Only machine if displayed in front view.



no notch

**BOTTOM NOTCH DETAIL**

Reference - Only machine if displayed in front view.

|                   |          |                   |  |                             |           |
|-------------------|----------|-------------------|--|-----------------------------|-----------|
| ORDER NUMBER      |          | 3X8X_DV_0034      |  |                             |           |
| COMPONENT ID      |          | 3X8XDoor          |  |                             |           |
| SERIES            |          | 3X8X              |  |                             |           |
| TOLERANCE         |          | 0.02 in           |  |                             |           |
| FLOOR CLEARANCE   | 9.00 in  | SWING<br>Outswing |  | HINGE<br>right-hand hinging |           |
| CEILING CLEARANCE | 5.938 in |                   |  |                             |           |
|                   |          | SCALE 1:8         |  | WEIGHT                      | SHEET 1/1 |