





Operations: -left exterior rabbet

Facing for cnc: exterior up

Setup: G57 only




FRONT VIEW

Note on drilling and rabbeting
Only machine if displayed.
Solid circles : machine on the front side
Broken circles: machine on the back side




TOP VIEW




RABBET DETAIL

Reference - Only machine if displayed.



TOP NOTCH DETAIL

Reference - Only machine if displayed in front view.



BOTTOM NOTCH DETAIL

Reference - Only machine if displayed in front view.

ORDER NUMBER		3X8X_DV_0040		
COMPONENT ID		3X8XDoor		
SERIES		3X8X		
TOLERANCE		0.02 in		
FLOOR CLEARANCE	1.00 in	SWING Inswing	HINGE left-hand hinging	
CEILING CLEARANCE	4.375 in			
		SCALE 1:8	WEIGHT	SHEET 1/1