



Operations: -left exterior rabbet -right exterior rabbet -left notch


Facing for cnc: exterior up

Setup: G57 > rotate > G59




FRONT VIEW

Note on drilling and rabbeting  
Only machine if displayed.  
Solid circles : machine on the front side  
Broken circles: machine on the back side




TOP VIEW




RABBET DETAIL

Reference - Only machine if displayed.



TOP NOTCH DETAIL

Reference - Only machine if displayed in front view.



no notch

BOTTOM NOTCH DETAIL

Reference - Only machine if displayed in front view.

|                   |         |                  |                             |           |
|-------------------|---------|------------------|-----------------------------|-----------|
| ORDER NUMBER      |         | 3X8X_DV_0005     |                             |           |
| COMPONENT ID      |         | 3X8XDoor         |                             |           |
| SERIES            |         | 3X8X             |                             |           |
| TOLERANCE         |         | 0.02 in          |                             |           |
| FLOOR CLEARANCE   | 4.50 in | SWING<br>Inswing | HINGE<br>right-hand hinging |           |
| CEILING CLEARANCE | 1.00 in |                  |                             |           |
|                   |         | SCALE 1:8        | WEIGHT                      | SHEET 1/1 |