



Operations: -right interior rabbet -left interior rabbet

Facing for cnc: interior up

Setup: G57 > rotate > G59




TOP VIEW



RABBET DETAIL


Reference - Only machine if displayed.



no notch

TOP NOTCH DETAIL



Reference - Only machine if displayed in front view.



no notch

BOTTOM NOTCH DETAIL

Reference - Only machine if displayed in front view.



FRONT VIEW

Note on drilling and rabbeting

Only machine if displayed.

Solid circles : machine on the front side

Broken circles: machine on the back side

ORDER NUMBER		3X8X_DV_0028		
COMPONENT ID		3X8XDoor		
SERIES		3X8X		
TOLERANCE		0.02 in		
FLOOR CLEARANCE	12.00 in	SWING Outswing	HINGE left-hand hinging	
CEILING CLEARANCE	7.188 in			
		SCALE 1:8	WEIGHT	SHEET 1/1