





Operations: -right exterior rabbet

Facing for cnc: exterior up

Setup: G59 only




FRONT VIEW

Note on drilling and rabbeting


Only machine if displayed.

Solid circles : machine on the front side

Broken circles: machine on the back side




TOP VIEW



RABBET DETAIL

Reference - Only machine if displayed.



no notch

TOP NOTCH DETAIL

Reference - Only machine if displayed in front view.

no notch

BOTTOM NOTCH DETAIL

Reference - Only machine if displayed in front view.

ORDER NUMBER		3X8X_DV_0046		
COMPONENT ID		3X8XDoor		
SERIES		3X8X		
TOLERANCE		0.02 in		
FLOOR CLEARANCE	9.00 in	SWING Inswing	HINGE right-hand hinging	
CEILING CLEARANCE	5.375 in			
		SCALE 1:8	WEIGHT	SHEET 1/1