



Operations: -left interior rabbet -left notch - right notch


Facing for cnc: interior up

Setup: G57 > rotate > G59




FRONT VIEW

Note on drilling and rabbeting
Only machine if displayed.
Solid circles : machine on the front side
Broken circles: machine on the back side




TOP VIEW



RABBET DETAIL

Reference - Only machine if displayed.



TOP NOTCH DETAIL

Reference - Only machine if displayed in front view.

BOTTOM NOTCH DETAIL

Reference - Only machine if displayed in front view.

ORDER NUMBER		3X8X_DV_0059		
COMPONENT ID		3X8XDoor		
SERIES		3X8X		
TOLERANCE		0.02 in		
FLOOR CLEARANCE	1.00 in	SWING Outswing	HINGE left-hand hinging	
CEILING CLEARANCE	3.188 in			
		SCALE 1:8	WEIGHT	SHEET 1/1