


L1 v2



Knee CAD checklist

○ Component list + measurements

○ design L1 + L2

○ insert B.B + axel

○ move to stop mechanism after

