
FD001
FD002
FD003
FD004
% of evaluated engines
premature
unrecognised
coverage
one-sided
central 90%
signed ramp end value (within-condition SD; negative = shift downwards)
premature trigger
unrecognised need
central 90% coverage (PICP)
one-sided coverage of lower bound
LSTM
Transformer