Parts Manufacturing Division Form No. PRS_QCF044 / Rev.02 March 12, 2018

Packaging Arrangement Guidance							Category: C-C					C		
Process –	II I USTRATION							PARTS ARRANGEMENT REQUIREMENT						
INJ							P-CASE QUANT		ANTIT	Υ	PLASTIC QUANTITY		Υ	
							QUANTITY PARTS PER ROW:		N/A	SMALL (3x	6):	200		
							тота	AL NO. OF RO	W:	N/A	MEDIUM (6	x8):	N/A	
							QUANTITY PER LAYER:		ER:	N/A	LARGE (10x14):		N/A	
							TOTAL NO. OF LAYER:		ER:	N/A	MAXIMUM PLASTIC PER P- CASE:		25	
							QUAN	NTITY PER P-CASE		5,000	PAPER LINER:			
	9					QUANTITY PER BUCKET:			N/A	CUSHION FOAM: CARTON:				
											В	UBBLE SHE		
P-CASE:	☐ LIGHT		SMALL	☐ DARK	GRAY	☐ WHITE	BUCKET BO	DX:		☐ SMALL	☐ YELLOW	□ Wi		
		Was a												
	I							Prepared by	: I	Reviewed by:	Approved by:		TE	
													//2018	
01	04/16/2019	14/16/2019 B.M. Rodriguez Additional parts category				v		B.M. Rodriguez		F. Mediante	diante S. Lorete		GE	
REV.NO	REV.DATE	REVISED BY										1	/1	