Parts Manufacturing Division Form No. PRS_QCF044 / Rev.02 March 12, 2018

Packaging Arrangement Guidance							Catego	Category: B-A				
Part Number: Process	KI	D03413-Y54		03 Area	a N	MOLDING	PARTS ARRANGEMENT REQUIREMENT					
INJ							P-CASE QUANTITY			PLASTIC QUANTITY		
							QUA	ANTITY PARTS PER ROW:		SMALL (3x6):		N/A
							тот	AL NO. OF ROW:	N/A	MEDIUM (6x8):		200
							QUA	QUANTITY PER LAYER:		LARGE (10x14):		N/A
							тот	TOTAL NO. OF LAYER:		MAXIMUM PLASTIC PER P- CASE: 25		25
							QUA	NTITY PER P-CASE	5,000	PAPER LINER:		
							QUAI	QUANTITY PER BUCKET:		CUSHION FOAM: CARTON:		
										В	UBBLE SHE	ET:
P-CASE :							BUCKET B					
✓ BLUE	LIGHT		SMALL	☐ DARK	☐ GRAY	WHITE	☐ SMALL	☐ BLUE	☐ SMALL	YELLOW	☐ WH	HITE
	'	1										
	-			I	•		<u>.</u>	Prepared by:	Reviewed by:	Approved by:	DA	TE
												/2018
01	04/29/2019	B.M. Rodrig	guez	Additional parts category.				B.M. Rodriguez	F. Mediante	S. Lorete	PA 1	GE /1
REV.NO	REV.DATE	REVISED	DESCRIPTION DESCRIPTION								1.	