Parts Manufacturing Division Form No. PRS_QCF044 / Rev.02 March 12, 2018

Packaging Arrangement Guidance							Categor	y:		B-A		
Part Number: Process	KI	003928-Y14	8 Rev	03 Are LUSTRATION	ea N	MOLDING	PARTS ARRANGEMENT REQUIREMENT					
INJ							P-CASE QUANTITY			PLASTIC QUANTITY		
							QUANTITY PARTS PER ROW:		N/A	SMALL (3x6):		N/A
							TOTAL NO. OF ROW:		N/A	MEDIUM (6x8): 2		200
							QUANTITY PER LAYER:		N/A	LARGE (10x1	LARGE (10x14):	
							TOTAL NO. OF LAYER:		N/A	MAXIMUM PLASTIC PER P- CASE:		25
							QUANTITY PER P-CASE		5,000	PAPER LINER:		
							QUANTITY PER BUCKET:		: N/A	CUSHION FOAM: CARTON:		
	A. C.									ВІ	JBBLE SHEET	
P-CASE: BLUE	☐ LIGHT		SMALL	☐ DARK	☐ GRAY	☐ WHITE	BUCKET BO	X:	☐ SMALL	☐ YELLOW	☐ WHIT	E
		Was a series										
	ı			'	-			Prepared by:	Reviewed by:	Approved by:	DAT 1	
											PAG	
01	04/17/2010	/17/2019 B.M. Rodriguez Additional parts category. EV.DATE REVISED BY DESCRIPTION						B.M. Rodriguez F. Mediante S. Lorete		1 AU		