



3D Update: One Issue Fixed, One Issue Still Remaining

1. Turning rule



2. Remaining spatial-transition problem



Left is a model schematic. Right is the actual coarse-run diagnostic. The right-hand path must not be used as a final result.