Call 1-866-MB4-AMAP (624-2627) (M-F, 8-6 CT) (Dealer only number)

	HARMAN BECKER COMAND DVD: Current Map v2014 (NTG1 v13.0)						
Model	Chassis	Model Year	DIr-inst H/U Part #	Coverage	MBUSA Part #		
CLS	219	MY06 - MY08	B6 782 3262	US, Canada, PR, VI	BQ 646 0315		
E Wagon	211	MY04 - MY08	B6 782 3251	US, Canada, PR, VI	BQ 646 0315		
E Sedan	211	MY03 - MY08	B6 782 3251	US, Canada, PR, VI	BQ 646 0315		
SLK	171	MY05 - MY08	B6 782 3548	US, Canada, PR, VI	BQ 646 0315		
Maybach	240	MY04 - MY10	N/A	US, Canada, PR, VI	BQ 646 0315		

Comments

BQ 646 0315 released September 2013. It replaces BQ 646 0293 for Harman Becker NTG1 only on selected vehicles.

Approximate installation time: 5 minutes (DVD based system)

*For SL / S / CL vehicles please continue to sell BQ 646 0262 which remains v10.0 of the release (see below).

^{*}Anticipated release for these vehicles is tentatively Q4/2014.

	HARMAN BECKER COMAND DVD: Current Map v2011 (NTG1 v10.0)						
Model	Chassis	Model Year	DIr-inst H/U Part #	Coverage	MBUSA Part #		
CL	215	MY04 - MY06	N/A	US, Canada, PR, VI	BQ 646 0262		
S	220	MY04 - MY06	N/A	US, Canada, PR, VI	BQ 646 0262		
SL	230	MY05 - MY08	N/A	US, Canada, PR, VI	BQ 646 0262		

Comments

BQ 646 0262 released November 2010. It replaces BQ 646 0257.

Approximate installation time: 5 minutes (DVD based system)

	ALPINE NTG2 DVD: Current Map v2014 (NTG2 v11.0)						
Model	Chassis	Model Year	DIr-inst H/U Part #	Coverage	MBUSA Part #		
M	164	MY06 - MY08	B6 782 3637	U.S. & Canada	BQ 646 0316		
С	203	MY05 - MY07	N/A	U.S. & Canada	BQ 646 0316		
CLK	209	MY05 - MY09	B6 782 3582	U.S. & Canada	BQ 646 0316		
GL	X164	MY07 - MY08	B6 782 3637	U.S. & Canada	BQ 646 0316		
G	463	MY07 - MY08	N/A	U.S. & Canada	BQ 646 0316		
R	251	MY06 - MY08	B6 782 3637	U.S. & Canada	BQ 646 0316		

Comments

BQ 646 0316 released October 2013. It replaces BQ 646 0295.

Approximate installation time: 5 minutes (DVD based system)

	ALPINE NTG2.5 DVD: Current Map v2014 (NTG2.5 v12.0)						
Model	Chassis	Model Year	DIr-inst H/U Part #	Coverage	MBUSA Part #		
CLS	219	MY09 - MY10	N/A	US, Canada, PR, VI	BQ 646 0317		
E	211	MY09	N/A	US, Canada, PR, VI	BQ 646 0317		
G	463	MY09 - MY12	N/A	US, Canada, PR, VI	BQ 646 0317		
GL	164	MY09 - MY12	N/A	US, Canada, PR, VI	BQ 646 0317		
M	164	MY09 - MY11	N/A	US, Canada, PR, VI	BQ 646 0317		
R	251	MY09 - MY12	N/A	US, Canada, PR, VI	BQ 646 0317		
SL	230	MY09, 11-12	N/A	US, Canada, PR, VI	BQ 646 0317		
SLK	171	MY09 - MY11	N/A	US, Canada, PR, VI	BQ 646 0317		

Comments

BQ 646 0317 released March 2014. It replaces BQ 646 0302.

Approximate installation time: 1 hour 45 minutes

Features Zagat data, Diesel Flags, voice phenomenes, Extended Lanes. Enhanced 3D footprint.

HARMAN BECKER COMAND DVD: Current Map v2014 (NTG3 v13.0)						
Model	Chassis	Model Year	DIr-inst H/U Part #	Coverage	MBUSA Part #	
CL	216	MY07 - MY09	N/A	US, Canada, PR, VI	BQ 646 0318	
S	221	MY07 - MY09	N/A	US, Canada, PR, VI	BQ 646 0318	

Comments

BQ 646 0318 released October 2013. It replaces BQ 646 0296.

Approximate installation time: 35 minutes

Features RDS Traffic.

HARMAN BECKER COMAND DVD: Current Map v2014.1 (NTG3.5 v10.0)						
Model	Chassis	Model Year	DIr-inst H/U Part #	Coverage	MBUSA Part #	
CL S	216 221	MY10 - MY13 MY10 - MY13	N/A N/A	US, Canada, PR, VI US, Canada, PR, VI	BQ 646 0319 BQ 646 0319	

Comments

BQ 646 0319 released August 2013. It replaces BQ 646 0307.

Approximate installation time: 1 hour 30 minutes

Requires additional PIN that must be obtained through VeDoc in order to update the COMAND system.

Updated October 25, 2013

DVD COMAND and MCS Maps

Call 1-866-MB4-AMAP (624-2627) (M-F, 8-6 CT) (Dealer only number)

	MELCO COMAND DVD: Current Map v2014 (NTG4 v13.0)						
Model	Chassis	Model Year	DIr-inst H/U Part #	Coverage	MBUSA Part #		
С	204	MY08 - MY11	N/A	US, Canada, PR, VI	BQ 646 0322		
GLK	204	MY10 - MY12	N/A	US, Canada, PR, VI	BQ 646 0322		
SLS AMG	197	MY11 - MY13	N/A	US, Canada, PR, VI	BQ 646 0322		

Comments

BQ 646 0322 released January 2014. It replaces BQ 646 0299.

Approximate installation time: 1 hour 30 minutes

Features Zagat data, Diesel Flags, Voice phenomenes and Gracenote.

MELCO COMAND DVD: Current Map v2014 (NTG4-212 v11.0)							
Model	Chassis	Model Year	DIr-inst H/U Part #	Coverage	MBUSA Part #		
CLS	219	MY11	N/A	US, Canada, PR, VI	BQ 646 0323		
E-Sedan	212	MY10 - MY11	N/A	US, Canada, PR, VI	BQ 646 0323		
E-Coupe	207	MY10 - MY11	N/A	US, Canada, PR, VI	BQ 646 0323		
E-Cabrio	207	MY11	N/A	US, Canada, PR, VI	BQ 646 0323		
E-Wagon	212	MY11	N/A	US, Canada, PR, VI	BQ 646 0323		

Comments

BQ 646 0323 released February 2014. It replaces BQ 646 0304.

Approximate installation time: 2 hours

Features Zagat data, Diesel Flags, Voice phenomenes and Gracenote.

*Please note that selected MY11 vehicles have option code 088 which requires the NTG4.5 update.

	MELCO COMAND DVD: Current Map v2014.1 (NTG4.5 v11.0)							
Model	Chassis	Model Year	DIr-inst H/U Part #	Coverage	MBUSA Part #			
C-Coupe	204	MY12 - MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
C-Sedan	204	MY12 - MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
CLS	218	MY12 - MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
E-Sedan	212	MY12 - MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
E-Coupe	207	MY12 - MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
E-Cabrio	207	MY12 - MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
E-Wagon	212	MY12 - MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
G	463	MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
GL	166	MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
GLK	204	MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
М	166	MY12 - MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
SL	231	MY13	N/A	US, Canada, PR, VI	BQ 646 0325			
SLK	172	MY12 - MY13	N/A	US, Canada, PR, VI	BQ 646 0325			

Comments

BQ 646 0325 released January 2014. It replaces BQ 646 0324.

Approximate installation time: 3 hours

Requires additional PIN to update the COMAND system that must be obtained through VeDoc.

Updated October 25, 2013 2 of 3

DVD COMAND and MCS Maps

Call 1-866-MB4-AMAP (624-2627) (M-F, 8-6 CT) (Dealer only number)

	ALPINE MCS1 DVD: Current Map v2008-2009						
Model	Chassis	Model Years	DIr-inst H/U Part #	Coverage	MBUSA Part #		
M	163	MY00 - MY05	BQ 682 0821	U.S. & Canada	BQ 646 0242		

Comments

BQ 646 0242 released September 2008. It replaces BQ646 0228.

No new updates planned

	ALPINE MCS1 Retro DVD: Current Map v2008-2009						
Model	Chassis	Model Years	DIr-inst H/U Part #	Coverage	MBUSA Part #		
M	163	MY00 - MY05	BQ 682 0821	U.S. & Canada	BQ 646 0246		

Comments

BQ 646 0246 released September 2008. It replaces BQ 646 0227.

No new updates planned.

This product is sold as an initial only for the MCS1 navigation system.

	DIr-inst H/U Part #	Coverage	MDUOA D
0 141/00		Coverage	MBUSA Part #
0 - MY02		Map 3: N Central Map 4: S Central Map 5: Midwest Map 6: Ohio Valley Map 7: New England Map 8: Mid-Atlantic Map 9: Southeast Map 10: Canada	BQ 646 0192 BQ 646 0193 BQ 646 0194 BQ 646 0195 BQ 646 0196 BQ 646 0197 BQ 646 0198 BQ 646 0200 BQ 646 0201 BQ 646 0201
,	JU - IVITUZ		Map 2: NW & SW Map 3: N Central Map 4: S Central Map 5: Midwest Map 6: Ohio Valley Map 7: New England Map 8: Mid-Atlantic Map 9: Southeast Map 10: Canada Collection (10-CDs)

Comments

No new updates planned

CD COMAND Maps

Call 1-877-526-3895 (M-F, 7-5 CT) (Dealer only number)

BOSCH COMAND CD (D-Navi): Current Map								
Model	Chassis	Model Years	DIr-inst H/U Part #	Description	Disk Part #			
C & CLK	203/208	MY00 - MY04	N/A	Collection (10-CDs)	BQ 646 0290			
CL & S	215/220	MY00 - MY03	N/A					
E Sedan	210	MY00 - MY02	N/A					
E Wagon	210	MY00 - MY03	N/A					
G	463	MY02 - MY06	N/A					
SL	230	MY02 - MY04	N/A					

Comments

BQ 646 0290 released October 2011. It replaces BQ 646 0273.

BOSCH COMAND CD (C-Navi): Current Map v01/04								
Model	Chassis	Model Year	DIr-inst H/U Part #	Description	Disk Part #			
S	220	MY00	N/A	Collection (10-CDs)	BQ 646 0191			

Comments

No new updates planned

Updated October 25, 2013 3 of 3