

Existing alignment sensitivity ±0.705 ms is not a timing bound. 48 kHz hardware recording cannot resolve exact sub-sample analog shape.