FARMERS INSURANCE

Toll Free: (800) 435-7764
Email: myclaim@farmersinsurance.com
Please include your claim # on any correspondence
National Document Center
P.O. Box 268994
Oklahoma City, OK 73126-8994
www.farmers.com/claimstatus

August 13, 2025

CONCISE RESOLUTION SERVICES, LLC
PMB 353
FORT WORTH TX 76109
Delivered by email to: appraisal@conciseresolution.com

JOHN FOSTER

Delivered by email to: jjlmds@gmail.com

RE:		
	Insured:	Yibiao Lu
	Claim Number:	7007986837-1-1
	Policy Number:	0980554965
	Loss Date:	07/13/2024
	Location of Loss:	17756 George Moran Dr, Eden Prairie, MN
	Subject:	Appraisal

Dear Appraisers:

As you are aware, the appraisal provisions of our policy have been invoked in regard to the above-referenced claim, and you have been appointed to serve as an appraiser. For reference, the contact information for the appointed appraisers is as follows:

Company: Fire Insurance Exchange

Appraiser:	Gregory Tomes
Contact Number:	(612) 237-6830
Email Address:	gregorytomes@gmail.com

Insured: Yibiao Lu

Appraiser:	John Foster
Contact Number:	715-417-2307
Email Address:	jjlmds@gmail.com

The policy's appraisal provisions have been included below in this letter. These provisions set forth the purpose and process of the appraisal, as well as the required qualifications of appraisers. At the outset, we ask that you immediately notify us of any facts which you believe may disqualify you to serve as appraiser in reference to this claim, whether such facts are now known or are later discovered in the appraisal process.

Please note that the scope of appraisal is limited to evaluating the amount of loss, actual cash value, or cost of repair or replacement. Policy interpretation, coverage, and other disputes may not be addressed in appraisal. Although we have agreed to engage in the appraisal process, please understand that we will not pay any portion of an award that includes damages which are not covered under the policy, and we will not be bound by any finding which exceeds the appraisal panel's authority. Our agreement to engage in the appraisal process is not

to be construed as an admission of coverage or a waiver of any of our rights or defenses under the policy, all of which are expressly reserved.

We expect that the appraisal will proceed in accordance with the appraisal provisions of the policy. We ask that any award be itemized to include the repair or replacement cost, depreciation, and actual cash value of each item or category of damaged property. This may be accomplished by providing an itemized estimate upon which the award is based. In the event the appraisal requires the assistance of an umpire, it will also be necessary for the umpire to segregate the replacement cost, depreciation, and actual cash value of the damaged property.

Enclosed you will find documentation we believe to be relevant to the appraisal.

In regard to appraisal, the policy provides as follows:

10. **Appraisal.**

    If you and we fail to agree on the **actual cash value**, amount of loss or damage or the cost of repair or replacement of the loss or damage, either one may make a written demand for appraisal. Each will then select a competent and disinterested, independent appraiser and notify the other of the appraiser's name within 20 days after the written demand is received. The appraisers will choose a competent, independent and disinterested umpire. If the appraisers cannot agree upon an umpire within 15 days, you or we can ask a judge of a court of record in the judicial district where the **residence premises** is located to choose an umpire. Any person or entity which has performed services for either party at any time as respects the particular loss or damage or loss event at issue in the claim may not serve as an appraiser or the umpire.

    The appraisers will then set the amount of loss or damage, stating separately the **actual cash value**, the repair or replacement cost and a description of the damage and extent of damage for each item of property. If the appraisers submit a written agreement to us, the agreed amount will be the amount of loss or damage and **actual cash value**. If the appraisers cannot agree, they will submit their differences to the umpire. A written agreement signed by any two will set the amount of loss or damage and **actual cash value**. Each party will pay the appraiser it chooses. The umpire and all other expenses of the appraisal will be paid equally by you and us.

    Interpretation of this policy and whether any particular loss or damage to covered property is in fact insured under this policy may not be determined under this provision.

Thank you for serving as appraiser in this claim. If you have any questions or require additional documentation or information, please contact the undersigned immediately.

Twonda Miller
Senior General Claims Adjuster
(832) 865-4165
Fire Insurance Exchange

Email communications are preferred and should be sent to myclaim@farmersinsurance.com. If hard copies of communications are required, they should be sent to our National Document Center at P.O. Box 268994, Oklahoma City, OK 73126-8994.

Enclosure(s):

- General Supporting Documents - (3)
- Photographs - (3)
- Correspondence - (2)
- Report of Loss -
- Estimate/Invoice - (2)

DEMAND FOR APPRAISAL

Date: 8/3/2025
Insurer: Farmers
Insurer's Claim Representative: Nic Braun

Regarding:
Insured: Yibiao Lu
Policy #: 0980554965
Claim #: 700798 6837-1-1
Date of Loss: 07/13/2024
Loss Address: 17756 George Moran Dr., Eden Prairie, MN 55347

This letter notifies you that we disagree with the amount of loss on the above-referenced claim. As a result of our inability to reach a mutually agreeable settlement, we are invoking the appraisal clause of our policy.

The items to be considered by the appraisal panel:

1. Windows
2. Siding (repaint)
3. Siding (R&R)
4.
5.
6.

We have selected John Foster as our appraiser, who can be reached at:

Phone: 715-417-2307
Email: jjlmds@gmail.com

We appreciate your prompt attention to this matter. Please notify us and our appraiser regarding your appraiser, including contact information for that individual, so the appraisal process can begin as soon as possible.

If Farmers elects not to participate in this appraisal or fails to elect an appraiser within 20 days, the insured is notifying the insurer of the intent to involve the court in electing an appraiser and/or umpire.

Sincerely,

Insured's Signature:
Insured's Printed Name: Yibiao Lu

SWORN STATEMENT ON PROOF OF LOSS

$886,000
Amount of policy at time of loss

12/1/2014
Date Issued

10/22/2025
Date Expires

0980554965
Policy Number

Peter Pietila Ins Agency Inc
Agency At

Peter Pietila
Agent

To: Farmers

At the time of loss, by the above indicated policy of insurance your insured, Yibiao Lu against loss by hail to the property described under Coverage A/Dwelling, according to the terms and conditions of the said policy and all forms, endorsements, transfers and assignments attached thereto.

1. Time and Origin: A hail loss occurred on or about 07/13/25

2. Occupancy: The building described, or containing the property described, was occupied at the time of the loss as follows, and for no other purpose whatever: Residential Owner occupied.

3. Title and Interest: At the time of the loss the interest of your insured in the property described herein was: Owner. No other person or persons had any interest therein or encumbrance thereon, except: none.

4. Changes: Since the said policy was issued there has been assignment thereof, or change of interest, use, occupancy, possession, location of exposure of the property described, except: none.

5.Total Insurance: The total amount of insurance upon the property described by this policy was, at the time of the loss, (coverage A, and C), besides which there was no policy or other contract of insurance, written or oral, valid or invalid.

6.	**The Actual Cash Value** of said property at the time of the loss was----------	$886,000
7.	**The Whole Loss and Damage** was----------	$310,000
8.	**Less Amount of Deductible**----------	$17,720
9.	**The Amount Claimed** under this Proof of Loss is ----------	$292,280

The furnishing of this Proof of Loss is offered as required by the insurance policy and the statutory language found in the Minnesota Standard Fire Policy found in Minnesota Statute 65A.01. The request for money in lines 6, 7, 8, and 9 above does not constitute a final settlement or complete payment for damage arising out of the above loss. The furnishing of this proof of loss does not diminish any rights of the insured to make additional claims for additional funds or submit any dispute regarding amount of loss or actual cash value to appraisal as provided by the policy and Minnesota law 65A.01.

The furnishing of this blank or the preparation of proofs by a representative of the above insurance company is not a waiver of any of its rights.

65A.01 MINNESOTA STANDARD FIRE INSURANCE POLICY.

Subd. 3.**Policy provisions.**

In case the insured and this company, except in case of total loss on buildings, shall fail to agree as to the actual cash value or the amount of loss, then, on the written demand of either, each shall select a competent and disinterested appraiser and notify the other of the appraiser selected within **20 days** of such demand. In case either fails to select an appraiser within the time provided, then a presiding judge of the district court of the county wherein the loss occurs may appoint such appraiser for such party upon application of the other party in writing by giving five days' notice thereof in writing to the party failing to appoint. The appraisers shall first select a competent and disinterested umpire; and failing for **15 days** to agree upon such umpire, then a presiding judge of the above mentioned court may appoint such an umpire upon application of party in writing by giving five days' notice thereof in writing to the other party. The appraisers shall then appraise the loss, stating separately actual value and loss to each item; and, failing to agree, shall submit their differences, only, to the umpire. An award in writing, so itemized, of any two when filed with this company shall determine the amount of actual value and loss. Each appraiser shall be paid by the selecting party, or the party for whom selected, and the expense of the appraisal and umpire shall be paid by the parties equally.

It shall be optional with this company to take all of the property at the agreed or appraised value, and also to repair, rebuild or replace the property destroyed or damaged with other of like kind and quality within a reasonable time, on giving notice of its intention so to do within 30 days after the receipt of the proof of loss herein required.

Direct Inspection

Prepared by Hancock Claims Consultants

INSPECTED BY
Jayden Grimm Tel: (507) 327-2595, **08/29/2024 9:00 AM**, 75°F

LOSS LOCATION	INSURED	CARRIER
11756 GEORGE MORAN DR EDEN PRAIRIE, Minnesota 55347-2163	YIBIAO LU	Farmers
PRESENT AT INSPECTION	**ADJUSTER**	**CLAIM NUMBER**
Insured,	Christian Dudley	7007986837-1

Property Overview

Roof

The structure assessed was a **story structure with a style roof** with the following predominant pitches:

- Front Pitch: **N/A**
- Left Pitch: **N/A**
- Back Pitch: **N/A**
- Right Pitch: **N/A**

The roof was comprised of a **(NA) shingle system.** The entirety of the roof system was inspected for wind related damages finding no damages.Hail test squares were conducted on each directional slope finding no hail strikes within nor to any other field shingles. No prior repairs were observed.

Elevation

A walk around inspection of all elevations was completed.

No sudden loss created damages.

Other areas of concern if any are noted in the additional summary.

Storm Info

Storm Damage Present: No
N/A

Non Storm Related Damage

N/A

Roof - Hail

Hail damage to a composition shingle roof system consists of bruising or fracturing of the shingle mat. Bruising is most common at unsupported locations and usually requires manual examination to confirm that damage has occurred to the shingle mat. Fracturing typically occurs at unsupported locations and is readily evident. These conditions can promote the absorption of moisture and subsequent deterioration of a shingle. Hail damage to a roof is quantified by the analysis of "test squares" (10' x 10' Area). The purpose of the test squares is to determine the amount of hail damage in a representative area of the roof. The test square results are then applied to individual roof fields, or the roof as a whole, to estimate the total damage incurred. Protocol calls for the examination of four (4) test squares ▌One (1) facing each direction. Larger and/or more complex roofs typically require additional test squares at the discretion of the adjuster. Additionally, a cursory overview of the remainder of each field is conducted to confirm the findings of the test squares.

Roof - Wind

Wind damage to an asphalt composition shingle consists of; creasing, tearing, complete detachment, and impacts from wind driven objects. Wind damage totals are acquired on a shingles damaged per slope basis.

Roof - Metal Accessory Items

Metal roof accessory items rarely suffer functional damage from hail impact. However, hail may cause aesthetic damage in the form of indentations. Rooftop penetrations can offer clear and permanent indications of hailstone impacts, including hail size and direction of the hail fall. Light gauge metal items will often suffer indentations even when the roofing material escapes damage.

Additional Summary

NA

Inspection Summary

Slope/Direction	Hail Damage +	Wind Damage	Other Damage
Front Slope/South		0	
Back Slope/North		0	
Left Slope/West		0	
Right Slope/East		0	

Roof Summary

Category	Description
Roof Type	
Roof Material	
Ice and Water	No
Valley Type	
Universal Starter	No
Rake	No
Felt Paper	
Shingle Exposure	NA
Shingle Width	0 (in)
Tarp Install	No
Soffit Depth	0 (in)
Outside Adjuster Present	No
Outside Adjuster Present on Roof	NA
Public Adjuster Present	No
Public Adjuster Present On Roof	NA
Insured Present	Yes
Contractor Present	No
Contractor Present On Roof	NA
Eagle View Provided	NA
LA Arrived On Time	NA
LA Accompanied OA	NA

Roof Components

Roof Component	Quantity	Qty Dmg	Painted	Material

Collateral Section - Front/South, Back/North, Left/West, Right/East

Collateral	Damage	Damage Amount	Size	Material	Additional Notes

Hancock
Claims Consultants



Ridge Shingle	Chimney Flashing	Hail	Wind	Shingle	Pitch	Vents		Misc	
HI PRO	LARGE	N 0	N 0	20 yr 3 Tab Comp	0/12	Box P/NP	0	Pipe Boot P/NP	0
Valley Metal	Fascia Material	S 0	S 0	25 yr 3 Tab Comp	# Layers	Turbine P/NP	0	HVAC Cap P/NP	0
N/A	6" Alum	E 0	E 0	25 yr 3 tab Organic	1	Power P/NP	0	Satellite	0
Drip Edge P/NP	Gutter P/NP	W 0	W 0	30 yr Laminate	Ice & Water Shield	Ridge Vent	0 l.f.	Mast Head	0
YES	5"Alum	Total Roof Sq.		40 yr Laminate	YES	Off Ridge	0	Skylight	0
Soffit Overhang	Gutter Guard P/NP	NA		50 yr Laminate	Felt Paper	Dryer Vent	0	Gooseneck P/NP	0
12"	N/A				15 lbs.				

Roof Age :11-15 years

× = Wind Damage = Water Leak = Repair

= GUTTER = RIDGE VENT = STORM RELATED DAMAGE

Front ↓ Risk

Hancock
Claims Consultants

Inspection Photos

Service Date: **08/29/2024 9:00 AM**

Claim Number: **7007986837-1**

Insured: **YIBIAO LU**

1. Address



Hancock
Claims Consultants

Inspection Photos

Service Date: **08/29/2024 7:00 PM**

Claim Number: **7007986837-1**

Insured: **YIBIAO LU**

1. Window Wrap North Damaged - No

2. Window Wrap North Damaged - No_2

3. Window Wrap North Damaged - No_3

4. Window Wrap North Damaged - No_4

5. Window Wrap North Damaged - No_5

6. Window Wrap North Damaged - No_6

7. Window Wrap North Damaged - No_7

8. Window Wrap North Damaged - No_8

9. Window Wrap North Damaged - No_9

10. Window Wrap North Damaged - No_10

11. Window Wrap North Damaged - No_11

12. Window Wrap North Damaged - No_12

13. Window Wrap South Damaged - No

14. Window Wrap South Damaged - No_2

15. Window Wrap South Damaged - No_3

16. Window Wrap South Damaged - No_4

17. Window Wrap South Damaged - No_5



18. Window Wrap South Damaged - No_6



19. Window Wrap South Damaged - No_7

20. Window Wrap South Damaged - No_8



21. Window Wrap South Damaged - No_9

22. Window Wrap South Damaged - No_10

23. Window Wrap South Damaged - No_11

24. Window Wrap South Damaged - No_12

25. Window Wrap South Damaged - No_13

26. Window Wrap West Damaged - No

27. Window Wrap West Damaged - No_2

28. Window Wrap West Damaged - No_3

29. Window Wrap West Damaged - No_4

30. Window Wrap West Damaged - No_5

31. Window Wrap West Damaged - No_6

32. Window Wrap West Damaged - No_7



33. Window Wrap West Damaged - No_8



34. Window Wrap West Damaged - No_9

35. Window Wrap West Damaged - No_10

36. Window Wrap West Damaged - No_11

37. Window Wrap West Damaged - No_12



38. Window Wrap West Damaged - No_13



HOVER **Complete Measurements**

11756 GEORGE MORAN DR

VIEW 3D MODEL

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

PROPERTY ID: 13444333
7007986837-1
LU
29 AUG 2024

Areas	Siding	Other
Facades	3603 ft²	180 ft²
Openings	1217 ft²	26 ft²
Trims*	370 ft²	21 ft²
Unknown (no photos)*	119 ft²	-
Total	5309 ft²	227 ft²

*Any trim or unknown material that touches siding is included in the 'Siding' column. If it does not touch siding, then it's included in the 'Other' column.

Openings	Siding	Other
Quantity	83	1
Tops Length	176′ 6″	5′ 11″
Sills Length	198′ 9″	7′ 9″
Sides Length	370′ 1″	33′ 10″
Total Perimeter	745′ 5″	47′ 6″

Corners	Siding	Other
Inside Qty	29	8
Inside Length	334′ 11″	41′ 11″
Outside Qty	26	12
Outside Length	340′ 8″	57′ 7″

Accessories	Siding	Other
Shutter Qty	0	0
Shutter Area	0 ft²	0 ft²
Vents Qty	0	0
Vents Area	0 ft²	0 ft²

Trim	Siding	Other
Level Starter	283′	60′ 1″
Sloped Trim	133′ 2″	1′ 9″
Vertical Trim	173′ 1″	60′ 7″

Roofline	Length	Avg. Depth	Soffit Area
Eaves Fascia	357′ 6″	-	-
Level Frieze Board	354′ 10″	1′ 2″	498 ft²
Rakes Fascia	41′ 9″	-	-
Sloped Frieze Board	29′ 1″	10″	28 ft²

SIDING WASTE TOTALS

Siding & Trim Only*	Area	Squares
Zero Waste	4097 ft²	41
+10%	4506 ft²	45¼
+18%	4835 ft²	48½

+ Openings < 20ft²	Area	Squares
Zero Waste	4965 ft²	49¾
+10%	5463 ft²	54¾
+18%	5860 ft²	58¾

+ Openings < 33ft²	Area	Squares
Zero Waste	5018 ft²	50¼
+10%	5521 ft²	55¼
+18%	5923 ft²	59¼

*The first three rows of the Siding Waste Factor table are calculated using the total ft² of siding facades, ft² of trim touching siding, and ft² of unknowns touching siding.

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Roof	Area	Total	Length
Roof Facets	3984 ft²	36	-
Ridges / Hips	-	34	392′
Valleys	-	12	141′ 11″
Rakes	-	9	41′ 9″
Eaves	-	35	357′ 6″
Flashing	-	15	45′ 2″
Step Flashing	-	25	62′ 1″
Drip Edge/Perimeter	-	-	399′ 3″

Roof Pitch*	Area	Percentage
10 / 12	3526 ft²	88.5%
6 / 12	316 ft²	7.93%
7 / 12	133 ft²	3.34%
12 / 12	9 ft²	0.23%



Example Waste Factor Calculations

	Zero Waste	+5%	+10%	+15%	+20%
Area	3984 ft²	4183 ft²	4382 ft²	4582 ft²	4781 ft²
Squares	40	42	44	46	48

The table above provides the total roof area of a given property using waste percentages as noted. Please consider that area values and specific waste factors can be influenced by the size and complexity of the property, captured image quality, specific roofing techniques, and your own level of expertise. Additional square footage for Hip, Ridge, and Starter shingles are not included in this waste factor and will require additional materials. This table is only intended to make common waste calculations easier and should not be interpreted as recommendations.

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.



Number of Stories: > 1

Footprint Perimeter: 273′ 5″

Footprint Area: 2522 ft²



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Gutters

	Gutter	Length	Sections
	Group 1	167′	15
	Group 2	12′	1
	Group 3	114′	7
	Group 4	35′	5
	Total	327′	28

Downspouts

	Downspout	Length	Count
	Group 1	104′	5
	Group 2	13′	1
	Group 3	39′	3
	Group 4	12′	1
	Total	166′	10

⚠ **Gutter section above 20′ from ground**



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.



Number of Stories: > 1



Siding Per Elevation

FRONT			RIGHT			LEFT			BACK		
SI-1	-	31 ft²	SI-3	-	72 ft²	SI-38	-	14 ft²	SI-24	-	54 ft²
SI-2	-	70 ft²	SI-4	-	19 ft²	SI-40	-	5 ft²	SI-25	-	23 ft²
SI-5	-	71 ft²	SI-8	-	28 ft²	SI-41	-	5 ft²	SI-26	-	14 ft²
SI-6	-	33 ft²	SI-9	-	3 ft²	SI-42	-	36 ft²	SI-27	-	141 ft²
SI-7	-	153 ft²	SI-12	-	19 ft²	SI-43	-	119 ft²	SI-28	-	48 ft²
SI-10	-	11 ft²	SI-14	-	26 ft²	SI-44	-	7 ft²	SI-29	-	49 ft²
SI-11	-	24 ft²	SI-16	-	7 ft²	SI-45	-	28 ft²	SI-30	-	51 ft²
SI-13	-	19 ft²	SI-18	-	194 ft²	SI-46	-	5 ft²	SI-31	-	184 ft²
SI-15	-	127 ft²	SI-20	-	140 ft²	SI-47	-	22 ft²	SI-33	-	27 ft²
SI-17	-	43 ft²	SI-22	-	90 ft²	SI-48	-	19 ft²	SI-34	-	284 ft²
SI-19	-	94 ft²	SI-23	-	161 ft²	SI-49	-	298 ft²	SI-35	-	327 ft²
SI-21	-	51 ft²	SI-32	-	11 ft²	SI-50	-	32 ft²	SI-36	-	23 ft²
						SI-51	-	11 ft²	SI-37	-	17 ft²
						SI-52	-	251 ft²	SI-39	-	12 ft²
727 ft²			**770 ft²**			**852 ft²**			**1254 ft²**		

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

	Cornice Returns	Length	Count
■	Returns Story 1	5′	2
	Total	**5′**	**2**



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Soffit Summary

Depth	Type	Count	Total Length	Total Area
1″ - 6″	rakes	2	6′ 10″	3 ft²
	eaves	3	9′	8 ft²
6″ - 12″	rakes	10	5′ 11″	5 ft²
	eaves	18	40′ 4″	37 ft²
12″ - 18″	rakes	2	19′ 3″	21 ft²
	eaves	27	271′ 7″	329 ft²
18″ - 24″	eaves	2	24′ 6″	39 ft²
24″ - 48″	eaves	5	31′ 4″	85 ft²
> 48″	-	1	11′ 7″	140 ft²
		Totals	**420′ 4″**	**667 ft²**



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Soffit Breakdown

num	Type	Depth	Length	Area	Pitch
1	rake	10″	7″	0 ft²	7 / 12
2	rake	10″	7″	0 ft²	7 / 12
3	rake	10″	7″	0 ft²	7 / 12
4	rake	10″	7″	0 ft²	7 / 12
5	rake	10″	7″	0 ft²	7 / 12
6	eave	18″	12′ 10″	20 ft²	7 / 12
7	eave	7″	10″	0 ft²	7 / 12
8	eave	35″	9′ 8″	28 ft²	7 / 12
9	eave	7″	10″	0 ft²	7 / 12
10	rake	10″	7″	0 ft²	7 / 12
11	rake	10″	7″	0 ft²	7 / 12
12	rake	10″	7″	0 ft²	7 / 12
13	eave	14″	6′ 2″	7 ft²	10 / 12
14	rake	10″	7″	0 ft²	7 / 12
15	rake	10″	7″	0 ft²	7 / 12
16	eave	28″	1′ 7″	4 ft²	7 / 12
17	eave	17″	22′ 9″	32 ft²	10 / 12
18	eave	11″	12′ 10″	12 ft²	10 / 12
19	eave	17″	3′ 5″	5 ft²	10 / 12
20	eave	17″	11′	15 ft²	10 / 12
21	eave	15″	21′ 9″	27 ft²	10 / 12
22	eave	13″	24′ 1″	27 ft²	10 / 12
23	eave	17″	32′ 6″	45 ft²	10 / 12
24	eave	13″	12′ 10″	14 ft²	10 / 12
25	eave	4″	4′ 5″	5 ft²	6 / 12
26	eave	12″	8′ 11″	9 ft²	6 / 12
27	eave	16″	6′ 7″	11 ft²	6 / 12
28	eave	13″	5′ 8″	6 ft²	10 / 12
29	eave	13″	14′	15 ft²	10 / 12
30	eave	13″	4′ 4″	4 ft²	6 / 12
31	eave	11″	6′ 9″	6 ft²	6 / 12
32	eave	15″	3′ 1″	3 ft²	10 / 12
33	eave	15″	6′ 10″	8 ft²	10 / 12
34	eave	15″	3′ 5″	5 ft²	10 / 12
35	eave	3″	3′ 4″	3 ft²	6 / 12
36	eave	10″	8′ 7″	7 ft²	6 / 12
37	eave	13″	17′	18 ft²	10 / 12
38	eave	10″	2′ 9″	3 ft²	6 / 12
39	eave	13″	4′ 9″	5 ft²	10 / 12
40	eave	13″	11′ 5″	13 ft²	10 / 12
41	eave	13″	3′ 4″	4 ft²	10 / 12
42	eave	13″	12′ 9″	14 ft²	10 / 12
43	eave	14″	3′ 2″	4 ft²	6 / 12
44	rake	14″	9′ 8″	10 ft²	10 / 12
45	eave	14″	8′ 2″	9 ft²	10 / 12
46	rake	14″	9′ 8″	10 ft²	10 / 12
47	eave	14″	1′ 9″	2 ft²	6 / 12
48	eave	5″	1′ 3″	1 ft²	6 / 12
49	rake	5″	3′ 3″	1 ft²	6 / 12
50	eave	24″	9′ 7″	19 ft²	10 / 12
51	eave	10″	8″	1 ft²	6 / 12
52	eave	10″	8″	1 ft²	6 / 12
53	eave	41″	8′ 11″	30 ft²	6 / 12
54	eave	10″	8″	1 ft²	6 / 12
55	eave	10″	8″	1 ft²	6 / 12
56	eave	10″	8″	1 ft²	6 / 12
57	eave	10″	8″	1 ft²	6 / 12

Feature is too small to label on the plan diagram

– Feature could not be labelled with complete certainty

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Soffit Breakdown (cont.)

num	Type	Depth	Length	Area	Pitch
58	eave	10″	8″	1 ft²	6 / 12
59	eave	20″	11′ 8″	20 ft²	6 / 12
60	eave	10″	8″	1 ft²	6 / 12
61	eave	10″	8″	1 ft²	6 / 12
62	eave	10″	8″	1 ft²	6 / 12
63	eave	10″	8″	1 ft²	6 / 12
64	eave	10″	8″	1 ft²	6 / 12
65	rake	5″	3′ 8″	2 ft²	6 / 12
66	eave	13″	14′ 5″	16 ft²	10 / 12
67	eave	16″	6′ 10″	9 ft²	10 / 12
68	eave	28″	1′ 8″	4 ft²	7 / 12
69	eave	17″	6″	1 ft²	7 / 12
70	-	131″	11′ 7″	140 ft²	6 / 12

Feature is too small to label on the plan diagram

\- Feature could not be labelled with complete certainty

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

11756 GEORGE MORAN DR

BACK-LEFT

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.





Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

11756 GEORGE MORAN DR
LEFT-FRONT





Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Siding

Facade	Area	Inside Corners	Outside Corners	Openings	Shutters	Vents
SI-1	31 ft²	1	-	1	-	-
SI-2	70 ft²	-	2	1	-	-
SI-3	72 ft²	1	1	-	-	-
SI-4	19 ft²	2	-	-	-	-
SI-5	71 ft²	2	-	2	-	-
SI-6	33 ft²	1	1	-	-	-
SI-7	153 ft²	1	2	6	-	-
SI-8	28 ft²	2	-	-	-	-
SI-9	3 ft²	1	1	-	-	-
SI-10	11 ft²	-	2	-	-	-
SI-11	24 ft²	2	-	3	-	-
SI-12	19 ft²	1	1	-	-	-
SI-13	19 ft²	-	2	6	-	-
SI-14	26 ft²	1	1	1	-	-
SI-15	127 ft²	3	2	3	-	-
SI-16	7 ft²	1	1	-	-	-
SI-17	43 ft²	-	-	-	-	-
SI-18	194 ft²	1	1	-	-	-
SI-19	94 ft²	1	1	-	-	-

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Siding (cont.)

Facade	Area	Inside Corners	Outside Corners	Openings	Shutters	Vents
SI-20	140 ft²	1	1	9	-	-
SI-21	51 ft²	1	2	-	-	-
SI-22	90 ft²	1	1	-	-	-
SI-23	161 ft²	-	2	-	-	-
SI-24	54 ft²	1	2	-	-	-
SI-25	23 ft²	1	1	3	-	-
SI-26	14 ft²	-	-	3	-	-
SI-27	141 ft²	3	1	5	-	-
SI-28	48 ft²	-	2	6	-	-
SI-29	49 ft²	1	-	3	-	-
SI-30	51 ft²	1	2	3	-	-
SI-31	184 ft²	3	1	3	-	-
SI-32	11 ft²	-	1	1	-	-
SI-33	27 ft²	-	-	1	-	-
SI-34	284 ft²	1	1	9	-	-
SI-35	327 ft²	1	1	4	-	-
SI-36	23 ft²	1	1	3	-	-
SI-37	17 ft²	1	1	1	-	-
SI-38	14 ft²	-	2	-	-	-

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Siding (cont.)

Facade	Area	Inside Corners	Outside Corners	Openings	Shutters	Vents
SI-39	12 ft²	1	1	1	-	-
SI-40	5 ft²	-	-	-	-	-
SI-41	5 ft²	-	-	1	-	-
SI-42	36 ft²	1	-	4	-	-
SI-43	119 ft²	1	1	-	-	-
SI-44	7 ft²	1	1	-	-	-
SI-45	28 ft²	2	-	-	-	-
SI-46	5 ft²	1	1	-	-	-
SI-47	22 ft²	1	1	-	-	-
SI-48	19 ft²	2	-	-	-	-
SI-49	298 ft²	1	2	-	-	-
SI-50	32 ft²	1	1	-	-	-
SI-51	11 ft²	1	1	-	-	-
SI-52	251 ft²	-	2	-	-	-
Total	3603 ft²	51	51	83	0	0

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Stone

Facade	Area	Openings	Shutters	Vents
STO-1	3 ft^2	-	-	-
STO-2	3 ft^2	-	-	-
STO-3	14 ft^2	-	-	-
STO-4	12 ft^2	-	-	-
STO-5	6 ft^2	-	-	-
STO-6	6 ft^2	-	-	-
STO-7	5 ft^2	-	-	-
STO-8	6 ft^2	-	-	-
STO-9	11 ft^2	-	-	-
STO-10	4 ft^2	-	-	-
STO-11	32 ft^2	1	-	-
STO-12	11 ft^2	-	-	-
STO-13	14 ft^2	-	-	-
STO-14	3 ft^2	-	-	-
STO-15	3 ft^2	-	-	-
STO-16	6 ft^2	-	-	-
STO-17	6 ft^2	-	-	-
STO-18	4 ft^2	-	-	-
STO-19	14 ft^2	-	-	-

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Stone (cont.)

Facade	Area	Openings	Shutters	Vents
STO-20	5 ft^2	-	-	-
STO-21	10 ft^2	-	-	-
STO-22*	1 ft^2	-	-	-
STO-23*	1 ft^2	-	-	-
Total	180 ft^2	1	0	0

* Facet is not visible due to size or location

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Unknown (missing photos)

Facade	Area	Openings	Shutters	Vents
UN-1	29 ft^2	-	-	-
UN-2	69 ft^2	-	-	-
UN-3	21 ft^2	-	-	-
Total	119 ft^2	0	0	0

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Facades

		Trim			Corners		Roofline		Openings		
Facade	Area	Level Starter	Sloped	Vertical	Inside	Outside	Level Frieze Board	Sloped Frieze Board	Tops	Sills	Sides
SI-1	31 ft²	2″	-	3′ 6″	6′ 5″	-	10′ 10″	-	1′ 9″	-	12′
SI-2	70 ft²	3′ 7″	-	-	-	12′ 9″	21′	-	2′ 9″	-	20′ 11″
SI-3	72 ft²	1′ 1″	6′ 6″	10′ 11″	3′ 5″	6′ 5″	7′ 5″	-	-	-	-
SI-4	19 ft²	2′ 4″	-	4′ 10″	11′ 8″	-	2′ 4″	-	-	-	-
SI-5	71 ft²	12′ 10″	-	-	16′ 6″	-	12′ 10″	-	6′ 3″	6′ 3″	22′ 7″
SI-6	33 ft²	22′ 5″	-	6′ 11″	4′ 6″	4′ 6″	13′ 11″	-	-	-	-
SI-7	153 ft²	14′ 4″	-	10′ 7″	11′ 5″	13′ 6″	6′ 7″	-	7′ 9″	15′ 5″	22′ 7″
SI-8	28 ft²	3′ 5″	-	3′ 1″	13′ 5″	-	3′ 5″	-	-	-	-
SI-9	3 ft²	-	8″	-	5′ 4″	5′ 10″	7″	-	-	-	-
SI-10	11 ft²	3′ 3″	7′ 2″	4′ 6″	-	6′ 9″	10′ 2″	-	-	-	-
SI-11	24 ft²	9′ 7″	-	-	10′ 8″	-	9′ 7″	-	-	9′ 7″	11′ 10″
SI-12	19 ft²	2′ 7″	-	6′ 9″	12′ 4″	3′ 4″	-	2′ 10″	-	-	-
SI-13	19 ft²	7′ 6″	-	-	-	15′ 6″	7′ 6″	-	6′ 1″	6′ 1″	12′ 11″
SI-14	26 ft²	6′ 2″	-	-	10′ 1″	10′ 1″	6′ 2″	-	5′ 3″	5′ 3″	13′ 8″
SI-15	127 ft²	9′ 1″	12′ 11″	2′ 1″	31′ 5″	25′ 5″	3′ 7″	-	7′ 9″	7′ 9″	11′ 2″
SI-16	7 ft²	2′ 2″	-	-	9′ 6″	7′ 9″	-	2′ 10″	-	-	-
SI-17	43 ft²	12′ 4″	-	2′ 2″	-	-	-	17′ 4″	-	-	-
SI-18	194 ft²	9′ 1″	12′ 10″	15′ 2″	22′ 10″	19′ 6″	12′ 5″	-	-	-	-

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Facades (cont.)

		Trim			Corners		Roofline		Openings		
Facade	**Area**	**Level Starter**	**Sloped**	**Vertical**	**Inside**	**Outside**	**Level Frieze Board**	**Sloped Frieze Board**	**Tops**	**Sills**	**Sides**
SI-19	94 ft²	3′ 5″	8″	-	22′ 10″	22′ 9″	4′ 1″	-	-	-	-
SI-20	140 ft²	-	10′ 1″	-	23′ 7″	22′ 9″	10′	-	6′ 7″	16′ 1″	32′
SI-21	51 ft²	1′ 9″	1′ 8″	8″	23′ 7″	33′ 9″	1′ 1″	-	-	-	-
SI-22	90 ft²	-	3′ 9″	-	25′ 11″	27′ 9″	3′ 4″	-	-	-	-
SI-23	161 ft²	-	5′ 6″	-	-	60′ 11″	-	-	-	-	-
SI-24	54 ft²	-	3′ 6″	8″	25′ 11″	35′ 5″	1′ 1″	-	-	-	-
SI-25	23 ft²	2′ 2″	-	1′ 9″	21′	21′	2′ 2″	-	5′ 4″	5′ 4″	18′
SI-26	14 ft²	7′ 4″	-	1′ 10″	-	-	-	-	-	7′ 4″	-
SI-27	141 ft²	11′ 11″	8′ 5″	1′ 2″	69′ 10″	27′ 9″	19′ 11″	-	14′ 8″	14′ 8″	6′ 9″
SI-28	48 ft²	-	-	-	-	42′	7′ 4″	-	21′ 8″	14′ 4″	15′ 7″
SI-29	49 ft²	3′ 1″	-	27′ 9″	27′ 9″	-	3′ 1″	-	6′ 10″	6′ 10″	31′
SI-30	51 ft²	5′ 7″	11″	14′ 6″	10′ 1″	16′ 7″	6′ 5″	-	15′ 3″	15′ 3″	24′ 2″
SI-31	184 ft²	18′ 5″	12′ 7″	8′ 8″	25′ 2″	27′ 9″	24′ 5″	-	7′ 5″	7′ 5″	8′ 11″
SI-32	11 ft²	2′ 6″	-	4′ 3″	-	10′ 1″	2′ 6″	-	2′ 5″	2′ 5″	5′ 10″
SI-33	27 ft²	6′ 4″	-	14′ 5″	-	-	6′ 4″	-	6′ 4″	6′ 4″	5′ 10″
SI-34	284 ft²	13′ 7″	-	-	27′ 9″	27′ 9″	13′ 7″	-	22′ 2″	22′ 2″	25′ 6″
SI-35	327 ft²	30′ 11″	-	-	11′ 11″	11′ 11″	30′ 11″	-	10′	10′	16′ 6″
SI-36	23 ft²	2′ 2″	-	-	21′	21′	2′ 2″	-	5′ 5″	5′ 5″	25′ 8″

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Facades (cont.)

		Trim			Corners		Roofline		Openings		
Facade	**Area**	**Level Starter**	**Sloped**	**Vertical**	**Inside**	**Outside**	**Level Frieze Board**	**Sloped Frieze Board**	**Tops**	**Sills**	**Sides**
SI-37	17 ft²	3′ 6″	-	-	8′ 3″	8′ 3″	3′ 6″	-	2′ 4″	2′ 4″	10′ 3″
SI-38	14 ft²	-	7′	-	-	8′ 3″	-	-	-	-	-
SI-39	12 ft²	-	3′ 4″	-	6′ 10″	8′ 3″	3′ 1″	-	2′ 1″	2′ 1″	10′ 6″
SI-40	5 ft²	2′ 4″	-	4′ 5″	-	-	-	-	-	2′ 4″	-
SI-41	5 ft²	-	-	4′ 2″	-	-	2′ 4″	-	2′ 4″	-	-
SI-42	36 ft²	8′ 3″	-	4′ 3″	10′ 1″	-	8′ 3″	-	8′ 2″	8′ 2″	5′ 10″
SI-43	119 ft²	4′ 3″	-	-	27′ 9″	27′ 9″	4′ 3″	-	-	-	-
SI-44	7 ft²	2′ 2″	-	-	9′ 6″	7′ 9″	-	2′ 10″	-	-	-
SI-45	28 ft²	3′ 5″	-	3′ 1″	13′ 5″	-	3′ 5″	-	-	-	-
SI-46	5 ft²	-	1′ 1″	-	5′ 4″	6′	1′	-	-	-	-
SI-47	22 ft²	2′ 11″	-	5′ 8″	11′ 5″	3′ 4″	-	3′ 3″	-	-	-
SI-48	19 ft²	2′ 4″	-	4′ 10″	11′ 8″	-	2′ 4″	-	-	-	-
SI-49	298 ft²	-	28′ 5″	5″	11′ 11″	32′ 3″	22′ 9″	-	-	-	-
SI-50	32 ft²	-	6′ 2″	-	4′ 6″	7′ 9″	5′ 5″	-	-	-	-
SI-51	11 ft²	1′ 9″	-	-	6′ 5″	6′ 5″	1′ 9″	-	-	-	-
SI-52	251 ft²	21′ 1″	-	-	-	18′ 4″	21′ 1″	-	-	-	-
Total*	3603 ft²	283′	133′ 2″	173′ 1″	334′ 11″	340′ 8″	345′ 11″	29′ 1″	176′ 6″	198′ 9″	370′ 1″

*Totals de-duplicate any line segments that are shared between multiple facades, and as a result may not represent a total summation of the corresponding column.

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Example Waste Factor Calculations

SIDING & TRIM ONLY

	Zero Waste	+10%	+18%
SI-1	31 ft²	34 ft²	37 ft²
SI-2	70 ft²	77 ft²	83 ft²
SI-3	72 ft²	79 ft²	85 ft²
SI-4	19 ft²	21 ft²	22 ft²
SI-5	71 ft²	78 ft²	84 ft²
SI-6	33 ft²	36 ft²	39 ft²
SI-7	153 ft²	168 ft²	181 ft²
SI-8	28 ft²	31 ft²	33 ft²
SI-9	3 ft²	3 ft²	4 ft²
SI-10	11 ft²	12 ft²	13 ft²
SI-11	24 ft²	26 ft²	28 ft²
SI-12	19 ft²	21 ft²	22 ft²
SI-13	19 ft²	21 ft²	22 ft²
SI-14	26 ft²	29 ft²	31 ft²
SI-15	127 ft²	140 ft²	150 ft²
SI-16	7 ft²	8 ft²	8 ft²

+ OPENINGS < 20FT²

Zero Waste	+10%	+18%
31 ft²	34 ft²	37 ft²
70 ft²	77 ft²	83 ft²
72 ft²	79 ft²	85 ft²
19 ft²	21 ft²	22 ft²
96 ft²	106 ft²	113 ft²
33 ft²	36 ft²	39 ft²
204 ft²	224 ft²	241 ft²
28 ft²	31 ft²	33 ft²
3 ft²	3 ft²	4 ft²
11 ft²	12 ft²	13 ft²
41 ft²	45 ft²	48 ft²
19 ft²	21 ft²	22 ft²
43 ft²	47 ft²	51 ft²
26 ft²	29 ft²	31 ft²
151 ft²	166 ft²	178 ft²
7 ft²	8 ft²	8 ft²

+ OPENINGS < 33FT²

Zero Waste	+10%	+18%
31 ft²	34 ft²	37 ft²
70 ft²	77 ft²	83 ft²
72 ft²	79 ft²	85 ft²
19 ft²	21 ft²	22 ft²
96 ft²	106 ft²	113 ft²
33 ft²	36 ft²	39 ft²
204 ft²	224 ft²	241 ft²
28 ft²	31 ft²	33 ft²
3 ft²	3 ft²	4 ft²
11 ft²	12 ft²	13 ft²
41 ft²	45 ft²	48 ft²
19 ft²	21 ft²	22 ft²
43 ft²	47 ft²	51 ft²
26 ft²	29 ft²	31 ft²
151 ft²	166 ft²	178 ft²
7 ft²	8 ft²	8 ft²

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

SIDING & TRIM ONLY (CONT.)

	Zero Waste	+10%	+18%
SI-17	43 ft²	47 ft²	51 ft²
SI-18	194 ft²	213 ft²	229 ft²
SI-19	94 ft²	103 ft²	111 ft²
SI-20	140 ft²	154 ft²	165 ft²
SI-21	51 ft²	56 ft²	60 ft²
SI-22	90 ft²	99 ft²	106 ft²
SI-23	161 ft²	177 ft²	190 ft²
SI-24	54 ft²	59 ft²	64 ft²
SI-25	23 ft²	25 ft²	27 ft²
SI-26	14 ft²	15 ft²	17 ft²
SI-27	141 ft²	155 ft²	166 ft²
SI-28	48 ft²	53 ft²	57 ft²
SI-29	49 ft²	54 ft²	58 ft²
SI-30	51 ft²	56 ft²	60 ft²
SI-31	184 ft²	202 ft²	217 ft²
SI-32	11 ft²	12 ft²	13 ft²

+ OPENINGS < 20FT²

Zero Waste	+10%	+18%
43 ft²	47 ft²	51 ft²
194 ft²	213 ft²	229 ft²
94 ft²	103 ft²	111 ft²
194 ft²	213 ft²	229 ft²
51 ft²	56 ft²	60 ft²
90 ft²	99 ft²	106 ft²
161 ft²	177 ft²	190 ft²
54 ft²	59 ft²	64 ft²
38 ft²	42 ft²	45 ft²
41 ft²	45 ft²	48 ft²
156 ft²	172 ft²	184 ft²
87 ft²	96 ft²	103 ft²
75 ft²	83 ft²	89 ft²
51 ft²	56 ft²	60 ft²
208 ft²	229 ft²	245 ft²
22 ft²	24 ft²	26 ft²

+ OPENINGS < 33FT²

Zero Waste	+10%	+18%
43 ft²	47 ft²	51 ft²
194 ft²	213 ft²	229 ft²
94 ft²	103 ft²	111 ft²
194 ft²	213 ft²	229 ft²
51 ft²	56 ft²	60 ft²
90 ft²	99 ft²	106 ft²
161 ft²	177 ft²	190 ft²
54 ft²	59 ft²	64 ft²
38 ft²	42 ft²	45 ft²
41 ft²	45 ft²	48 ft²
156 ft²	172 ft²	184 ft²
87 ft²	96 ft²	103 ft²
75 ft²	83 ft²	89 ft²
72 ft²	79 ft²	85 ft²
208 ft²	229 ft²	245 ft²
22 ft²	24 ft²	26 ft²

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

SIDING & TRIM ONLY (CONT.)

	Zero Waste	+10%	+18%
SI-33	27 ft²	30 ft²	32 ft²
SI-34	284 ft²	312 ft²	335 ft²
SI-35	327 ft²	360 ft²	386 ft²
SI-36	23 ft²	25 ft²	27 ft²
SI-37	17 ft²	19 ft²	20 ft²
SI-38	14 ft²	15 ft²	17 ft²
SI-39	12 ft²	13 ft²	14 ft²
SI-40	5 ft²	6 ft²	6 ft²
SI-41	5 ft²	6 ft²	6 ft²
SI-42	36 ft²	40 ft²	42 ft²
SI-43	119 ft²	131 ft²	140 ft²
SI-44	7 ft²	8 ft²	8 ft²
SI-45	28 ft²	31 ft²	33 ft²
SI-46	5 ft²	6 ft²	6 ft²
SI-47	22 ft²	24 ft²	26 ft²
SI-48	19 ft²	21 ft²	22 ft²

+ OPENINGS < 20FT²

Zero Waste	+10%	+18%
27 ft²	30 ft²	32 ft²
350 ft²	385 ft²	413 ft²
355 ft²	391 ft²	419 ft²
38 ft²	42 ft²	45 ft²
26 ft²	29 ft²	31 ft²
14 ft²	15 ft²	17 ft²
20 ft²	22 ft²	24 ft²
5 ft²	6 ft²	6 ft²
16 ft²	18 ft²	19 ft²
72 ft²	79 ft²	85 ft²
119 ft²	131 ft²	140 ft²
7 ft²	8 ft²	8 ft²
28 ft²	31 ft²	33 ft²
5 ft²	6 ft²	6 ft²
22 ft²	24 ft²	26 ft²
19 ft²	21 ft²	22 ft²

+ OPENINGS < 33FT²

Zero Waste	+10%	+18%
59 ft²	65 ft²	70 ft²
350 ft²	385 ft²	413 ft²
355 ft²	391 ft²	419 ft²
38 ft²	42 ft²	45 ft²
26 ft²	29 ft²	31 ft²
14 ft²	15 ft²	17 ft²
20 ft²	22 ft²	24 ft²
5 ft²	6 ft²	6 ft²
16 ft²	18 ft²	19 ft²
72 ft²	79 ft²	85 ft²
119 ft²	131 ft²	140 ft²
7 ft²	8 ft²	8 ft²
28 ft²	31 ft²	33 ft²
5 ft²	6 ft²	6 ft²
22 ft²	24 ft²	26 ft²
19 ft²	21 ft²	22 ft²

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

SIDING & TRIM ONLY (CONT.)

	Zero Waste	+10%	+18%
SI-49	298 ft²	328 ft²	352 ft²
SI-50	32 ft²	35 ft²	38 ft²
SI-51	11 ft²	12 ft²	13 ft²
SI-52	251 ft²	276 ft²	296 ft²
UN-1	29 ft²	32 ft²	34 ft²
UN-2	69 ft²	76 ft²	81 ft²
UN-3	21 ft²	23 ft²	25 ft²
Trims	375 ft²	413 ft²	443 ft²
Total	4097 ft²	4506 ft²	4835 ft²

+ OPENINGS < 20FT²

Zero Waste	+10%	+18%
298 ft²	328 ft²	352 ft²
32 ft²	35 ft²	38 ft²
11 ft²	12 ft²	13 ft²
251 ft²	276 ft²	296 ft²
29 ft²	32 ft²	34 ft²
69 ft²	76 ft²	81 ft²
21 ft²	23 ft²	25 ft²
718 ft²	790 ft²	847 ft²
4965 ft²	5463 ft²	5860 ft²

+ OPENINGS < 33FT²

Zero Waste	+10%	+18%
298 ft²	328 ft²	352 ft²
32 ft²	35 ft²	38 ft²
11 ft²	12 ft²	13 ft²
251 ft²	276 ft²	296 ft²
29 ft²	32 ft²	34 ft²
69 ft²	76 ft²	81 ft²
21 ft²	23 ft²	25 ft²
718 ft²	790 ft²	847 ft²
5018 ft²	5521 ft²	5923 ft²

The first Siding Waste Factor table is calculated using the total ft² of siding facades, ft² of trim touching siding, and ft² of unknowns touching siding.

The tables above provide the area of siding on a given property, segmented by individual and in sum total form. Values include openings (doors & windows) and waste percentages as noted. Please consider that area values and specific waste factors can be influenced by the size and complexity of the property, captured image quality, specific siding techniques, and your own level of expertise. Accessories are not included in these values and may require additional material.

These tables are only intended to make common waste calculations easier and should not be interpreted as recommendations.

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Windows (displaying first 66 of 77 total windows)

Group	Group Width x Height	Group United Inches	Opening	Width x Height	United Inches	Area
WG-1	15″ x 55″	71″	W-101	15″ x 55″	71″	6 ft²
WG-2	83″ x 55″	138″	W-102	23″ x 55″	79″	9 ft²
			W-103	23″ x 55″	79″	9 ft²
			W-104	23″ x 55″	79″	9 ft²
WG-3	15″ x 55″	71″	W-105	15″ x 55″	71″	6 ft²
WG-4	22″ x 55″	78″	W-106	22″ x 55″	78″	9 ft²
WG-5	22″ x 55″	78″	W-107	22″ x 55″	78″	9 ft²
WG-6	81″ x 46″	126″	W-108	24″ x 46″	70″	8 ft²
			W-109	24″ x 46″	70″	8 ft²
			W-110	24″ x 46″	70″	8 ft²
WG-7	81″ x 46″	126″	W-111	24″ x 46″	70″	8 ft²
			W-112	24″ x 46″	70″	8 ft²
			W-113	24″ x 46″	70″	8 ft²
WG-8	25″ x 38″	63″	W-214	25″ x 38″	63″	7 ft²
WG-9	79″ x 55″	134″	W-215	23″ x 55″	78″	9 ft²
			W-216	23″ x 55″	78″	9 ft²
			W-217	23″ x 55″	78″	9 ft²

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Windows (cont.)

Group	Group Width x Height	Group United Inches	Opening	Width x Height	United Inches	Area
WG-10	65″ x 70″	135″	W-218	18″ x 58″	77″	7 ft²
			W-219	18″ x 58″	77″	7 ft²
			W-220	18″ x 58″	77″	7 ft²
			W-221	18″ x 6″	25″	1 ft²
			W-222	18″ x 6″	25″	1 ft²
			W-223	18″ x 6″	25″	1 ft²
WG-11	65″ x 43″	107″	W-224	13″ x 43″	55″	4 ft²
			W-225	30″ x 43″	72″	9 ft²
			W-226	13″ x 43″	55″	4 ft²
WG-12	16″ x 36″	51″	W-227	16″ x 36″	51″	4 ft²
WG-13	16″ x 45″	60″	W-228	16″ x 45″	60″	5 ft²
WG-14	80″ x 36″	116″	W-229	16″ x 36″	51″	4 ft²
			W-230	37″ x 36″	72″	9 ft²
			W-231	16″ x 36″	51″	4 ft²
WG-15	80″ x 46″	126″	W-232	16″ x 46″	61″	5 ft²
			W-233	37″ x 46″	82″	12 ft²
			W-234	16″ x 46″	61″	5 ft²
WG-16	16″ x 36″	51″	W-235	16″ x 36″	51″	4 ft²

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Windows (cont.)

Group	Group Width x Height	Group United Inches	Opening	Width x Height	United Inches	Area
WG-17	16″ x 45″	60″	W-236	16″ x 45″	60″	5 ft²
WG-18	22″ x 55″	78″	W-237	22″ x 55″	78″	9 ft²
WG-19	25″ x 64″	89″	W-238	25″ x 64″	89″	11 ft²
WG-20	72″ x 64″	136″	W-239	72″ x 64″	136″	32 ft²
WG-21	25″ x 64″	89″	W-240	25″ x 64″	89″	11 ft²
WG-22	93″ x 64″	157″	W-241	21″ x 64″	85″	9 ft²
			W-242	21″ x 64″	85″	9 ft²
			W-243	21″ x 64″	85″	9 ft²
			W-244	21″ x 64″	85″	9 ft²
WG-23	81″ x 42″	122″	W-245	24″ x 42″	66″	7 ft²
			W-246	24″ x 42″	66″	7 ft²
			W-247	24″ x 42″	66″	7 ft²
WG-24	52″ x 42″	93″	W-248	23″ x 42″	65″	7 ft²
			W-249	23″ x 42″	65″	7 ft²
WG-25	52″ x 42″	93″	W-250	23″ x 42″	65″	7 ft²
			W-251	23″ x 42″	65″	7 ft²

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Windows (cont.)

Group	Group Width x Height	Group United Inches	Opening	Width x Height	United Inches	Area
WG-26	79″ x 53″	132″	W-352	23″ x 53″	76″	8 ft²
			W-353	23″ x 53″	76″	8 ft²
			W-354	23″ x 53″	76″	8 ft²
WG-27	67″ x 49″	116″	W-355	12″ x 30″	43″	3 ft²
			W-356	31″ x 49″	80″	11 ft²
			W-357	12″ x 30″	43″	3 ft²
WG-28	79″ x 53″	132″	W-358	23″ x 53″	76″	8 ft²
			W-359	23″ x 53″	76″	8 ft²
			W-360	23″ x 53″	76″	8 ft²
WG-29	65″ x 109″	173″	W-361	13″ x 53″	65″	5 ft²
			W-362	30″ x 53″	82″	11 ft²
			W-363	13″ x 53″	65″	5 ft²
			W-364	13″ x 29″	41″	3 ft²
			W-365	30″ x 48″	78″	10 ft²
			W-366	13″ x 29″	41″	3 ft²
			Total*	-	5202″	560 ft²

* Total row sums all 77 windows, but only 66 are shown on table. Please use online 3D Model for remainder.

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided “as is.” HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Doors

Opening	Width x Height
D-1	120″ x 84″
D-2	192″ x 96″
D-3	32″ x 80″
D-4	36″ x 80″
SGD-1	60″ x 80″
SGD-2	60″ x 80″
SGD-3	60″ x 80″

*Door height and width have been snapped to standard

Entire Doors

Opening	Width x Height	Area
D-1	116″ x 99″	76 ft^2
D-2	194″ x 100″	130 ft^2
D-3	32″ x 79″	17 ft^2
D-4	65″ x 78″	35 ft^2
SGD-1	59″ x 78″	32 ft^2
SGD-2	59″ x 78″	32 ft^2
SGD-3	59″ x 78″	32 ft^2
Total	-	354 ft^2

*Total door square footage includes entire door package (e.g. with transoms, sidelites, etc.)

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Roof	Length
Ridges (RI)	58′ 8″
Hips (H)	333′ 5″
Valleys (V)	141′ 11″
Rakes (RA)	41′ 9″
Eaves (E)	357′ 6″
Flashing (F)*	45′ 2″
Step Flashing (SF)*	62′ 1″
Transition Line (TL)	-

*Please view the 3D model for more detail (e.g. flashing, step flashing and some other roof lines may be difficult to see on the PDF)



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Roof Facets

Facet	Area	Pitch
RF-1	133 ft²	7/12
RF-2	131 ft²	10/12
RF-3	189 ft²	10/12
RF-4	73 ft²	6/12
RF-5	433 ft²	10/12
RF-6	206 ft²	10/12
RF-7	210 ft²	10/12
RF-8	377 ft²	10/12
RF-9	23 ft²	10/12
RF-10	196 ft²	10/12
RF-11	48 ft²	10/12
RF-12	2 ft²	6/12
RF-13	27 ft²	10/12
RF-14	170 ft²	10/12
RF-15	64 ft²	6/12
RF-16	215 ft²	10/12
RF-17	201 ft²	10/12
RF-18	3 ft²	6/12
RF-19	280 ft²	10/12



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Roof Facets (cont.)

Facet	Area	Pitch
RF-20	58 ft²	6/12
RF-21	501 ft²	10/12
RF-22	9 ft²	12/12
RF-23	26 ft²	10/12
RF-24	10 ft²	10/12
RF-25	62 ft²	10/12
RF-26	35 ft²	6/12
RF-27	22 ft²	6/12
RF-28	22 ft²	6/12
RF-29	6 ft²	6/12
RF-30	28 ft²	10/12
RF-31	39 ft²	10/12
RF-32	142 ft²	10/12
RF-33	25 ft²	6/12
RF-34	6 ft²	6/12
RF-35	6 ft²	10/12
RF-36	6 ft²	10/12



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Roof	Facets	Total
Total	36	3984 ft²



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Roof Pitch	Area	Percentage
10 / 12	3526 ft²	88.5%
6 / 12	316 ft²	7.93%
7 / 12	133 ft²	3.34%
12 / 12	9 ft²	0.23%



Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

Powered by HOVER

© 2024 HOVER Inc. All rights reserved. This document and the images, measurement data, format and contents are the exclusive property of HOVER. HOVER is the registered trademark of Hover Inc. All other brands, products and company names mentioned herein may be trademarks or registered trademarks of their respective holders.

Use of this document is subject to HOVER's Terms of Use and is provided "as is." HOVER makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise relating to this document or its contents or use, including but not limited to, quality, accuracy, completeness, reliability, or fitness for a particular purpose.

FARMERS INSURANCE

Toll Free: (800) 435-7764
Email: myclaim@farmersinsurance.com
Please include your claim # on any correspondence
National Document Center
P.O. Box 268994
Oklahoma City, OK 73126-8994
www.farmers.com/claimstatus

September 3, 2024

YIBIAO LU
17756 GEORGE MORAN DR
EDEN PRAIRIE MN 55347-1061
Delivered by email to: BILL_Y_LU@YAHOO.COM

RE:	Insured:	Yibiao Lu
	Claim Number:	7007986837-1-1
	Policy Number:	0980554965
	Loss Date:	07/13/2024
	Location of Loss:	17756 George Moran Dr, Eden Prairie, MN
	Subject:	Claim Outcome Letter

Dear YIBIAO LU:

Thank you for being a valued customer. We are proud to serve you.

You reported water damage inside your home.

As we discussed on September 3, 2024, our investigation found your policy provides coverage for direct physical loss to insured property, less uninsured or excluded. As part of our investigation we had your home inspected. At the inspection, interior water damage around your windows was observed. There were no other damages observed. There was no opening created by the direct force of wind or hail that could have occurred and allowed water to enter and cause immediate damage. Your policy excludes interior water damage without an opening created by wind or hail. Unfortunately, there is no coverage for your claim based on the information known at this time.

We encourage you to review the terms of your Next Generation Homeowners Policy Minnesota, 2nd Ed, as endorsed. They form the basis for our decision. We have attached a "Coverage Outcome – Policy Provisions" document that refers you to the applicable sections of the policy.

We reserve all rights and defenses under the policy and law and no activity on our part should be construed as a waiver. Even though only parts of the policy may be mentioned or quoted in this letter, additional portions if found to be relevant will be applied.

Please note there are time limits set forth in the Conditions ("Lawsuits Against Us" or "Legal Action Against Us" or "Suit Against Us") section of the policy which, depending on your state, may affect the time within which you may pursue your claim. This period may have been extended by statute or case law.

We've completed the adjustment of your loss and we are closing your claim. Closing your claim does not affect processing payments for recoverable depreciation, or outstanding payment for any other covered part of the

claim that has already been accepted and adjusted. Closing your claim does not prevent you from providing us with additional information, including supplemental claims and requests for recoverable depreciation, within the time limits stated in your policy. We will inform you in writing if any such additional information results in reopening your claim.

Although we remain available to discuss this matter with you, pursuant to MN Insurance Regulation 72A.201 we are required to advise you that if some or all of your claim has been denied you have the right to file a complaint with the Minnesota Department of Commerce. Minnesota Department of Commerce - 85 7th Place East, Suite 280 - St. Paul, MN 55101- Toll Free Number 800-657-3602.

We encourage you to visit **www.farmers.com** to learn more about our self-service options available to you, including the ability to view your claim status, upload documents and photos and find local service providers.

If you have any questions, or additional information you think may affect your coverage, please contact me.

Thank you.

Christian Dudley
Catastrophe Claims Representative
(913) 309-7398
Fire Insurance Exchange

Email communications are preferred and should be sent to myclaim@farmersinsurance.com. If hard copies of communications are required, they should be sent to our National Document Center at P.O. Box 268994, Oklahoma City, OK 73126-8994.

CC: JIE HU
Enclosure(s):
General Supporting Documents -
Photographs - (2)

Coverage Outcome - Policy Provisions

DEFINITIONS

...

5. **Building structure** - means a structure fully enclosed with walls and a roof. A roof or wall does not include a temporary roof or wall structure or any kind of temporary tarp, sheeting or other covering, except a temporary roof or wall or temporary covering which has been installed for temporary purposes because of recent damage covered under this policy.

...

33. **Water** - means **water** (H2O) alone, whether in liquid, frozen, or vapor form, or any liquid, sewage or sludge which contains **water**, whether or not contaminated or combined with or containing other chemicals, particulates, microorganisms or impurities. **Water** includes but is not limited to rain, snow, sleet, slush, ice, dampness, vapor, condensation, moisture, steam and humidity.

...

SECTION I - EXTENSIONS OF COVERAGE

...

1. **Limited Water Coverage.**

...

SECTION I - UNINSURED LOSS OR DAMAGE and EXCLUDED CAUSES OF LOSS OR DAMAGE

A. **Uninsured Types of Loss or Damage.**

...

1. **Water Damage.**

...

3. **Construction Defect.**

...

4. **Inherent Vice or Latent Defect.**

...

7. **Wear and tear or mechanical breakdown.**

...

9. **Corrosion, Deterioration, Decay or Rust.**

...

B. **Excluded Causes of Loss or Damage.**

...

2. **Water.**

...

4. **Neglect or Lack of Maintenance or Failure to Make Repairs.**
5. **Faulty, Inadequate, Defective or Incomplete Planning, Zoning, Maintenance, Repairs, Renovation, Manufacture or Construction.**

...

6. **Inherent Vice or Latent Defect.**

...

8. **Wear and Tear, Deterioration or Mechanical Breakdown.**

...

9. **Corrosion, Deterioration, Decay or Rust.**

...

26. **Windstorm or hail.**

...

33. **Weather Conditions.**

Hancock
Claims Consultants

LU
7007986837-1 | 8/29/24

Ridge Shingle	Chimney Flashing	Hail	Wind	Shingle	Pitch	Vents		Misc	
SHAKE	N/A	N 0	N 0	20 yr 3 Tab Comp	7/12	Box P/NP	0	Pipe Boot P/NP	0
Valley Metal	Fascia Material	S 0	S 0	25 yr 3 Tab Comp	# Layers	Turbine P/NP	0	HVAC Cap P/NP	0
N/A	6" Alum	E 0	E 0	25 yr 3 tab Organic	1	Power P/NP	0	Satellite	0
Drip Edge P/NP	Gutter P/NP	W 0	W 0	30 yr Laminate	Ice & Water Shield	Ridge Vent	0 l.f.	Mast Head	0
YES	5"Alum	Total Roof Sq.		40 yr Laminate	YES	Off Ridge	0	Skylight	0
Soffit Overhang	Gutter Guard P/NP	NA		50 yr Laminate	Felt Paper	Dryer Vent	0	Gooseneck P/NP	0
12"	N/A				15 lbs.			Roof Age : 1-5 years	

× = Wind Damage = Water Leak = Repair

= GUTTER = RIDGE VENT = STORM RELATED DAMAGE

INSURED STATED ROOF DOES NOT NEED INSPECTION DUE TO CEDAR SHAKE ONKY BEING 2 YEARS OLD.



Front ↓ Risk

Hancock
Claims Consultants

Inspection Photos

Service Date: **08/29/2024 7:00 PM**

Claim Number: **7007986837-1**

Insured: **YIBIAO LU**

1. Window Wrap North Damaged - No

2. Window Wrap North Damaged - No_2

3. Window Wrap North Damaged - No_3

4. Window Wrap North Damaged - No_4

5. Window Wrap North Damaged - No_5

6. Window Wrap North Damaged - No_6

7. Window Wrap North Damaged - No_7

8. Window Wrap North Damaged - No_8

9. Window Wrap North Damaged - No_9

10. Window Wrap North Damaged - No_10

11. Window Wrap North Damaged - No_11

12. Window Wrap North Damaged - No_12

13. Window Wrap South Damaged - No

14. Window Wrap South Damaged - No_2

15. Window Wrap South Damaged - No_3

16. Window Wrap South Damaged - No_4

17. Window Wrap South Damaged - No_5



18. Window Wrap South Damaged - No_6



19. Window Wrap South Damaged - No_7

20. Window Wrap South Damaged - No_8



21. Window Wrap South Damaged - No_9

22. Window Wrap South Damaged - No_10

23. Window Wrap South Damaged - No_11

24. Window Wrap South Damaged - No_12

25. Window Wrap South Damaged - No_13

26. Window Wrap West Damaged - No

27. Window Wrap West Damaged - No_2

28. Window Wrap West Damaged - No_3

29. Window Wrap West Damaged - No_4

30. Window Wrap West Damaged - No_5

31. Window Wrap West Damaged - No_6

32. Window Wrap West Damaged - No_7



33. Window Wrap West Damaged - No_8



34. Window Wrap West Damaged - No_9

35. Window Wrap West Damaged - No_10

36. Window Wrap West Damaged - No_11

37. Window Wrap West Damaged - No_12



38. Window Wrap West Damaged - No_13



Hancock
Claims Consultants

Inspection Photos

Service Date: **08/29/2024 7:00 PM**

Claim Number: **7007986837-1**

Insured: **YIBIAO LU**

1. Address

2. Front Risk

3. Elevation North/ Back

4. Elevation North/ Back _2

5. Window Wrap North Damaged - No

6. Window Wrap North Damaged - No_2

7. Window Wrap North Damaged - No_3

8. Window Wrap North Damaged - No_4

9. Window Wrap North Damaged - No_5

10. Window Wrap North Damaged - No_6

11. Window Wrap North Damaged - No_7

12. Window Wrap North Damaged - No_8

13. Window Wrap North Damaged - No_9

14. Window Wrap North Damaged - No_10

15. Window Wrap North Damaged - No_11

16. Window Wrap North Damaged - No_12

17. Window Wrap North Damaged - No_13

18. Window Wrap North Damaged - No_14

19. Window Wrap North Damaged - No_15

20. Window Wrap North Damaged - No_16

21. Window Wrap North Damaged - No_17

22. Window Wrap North Damaged - No_18

23. Window Wrap North Damaged - No_19

24. Window Wrap North Damaged - No_20

25. Siding North Damage - No

26. Siding North Damage - No_2

27. Siding North Damage - No_3

28. Siding North Damage - No_4

29. Siding North Damage - No_5

30. Siding North Damage - No_6

31. Siding North Damage - No_7

32. Siding North Damage - No_8

33. Window Wrap South Damaged - No

34. Window Wrap South Damaged - No_2

35. Window Wrap South Damaged - No_3

36. Window Wrap South Damaged - No_4

37. Window Wrap South Damaged - No_5



38. Window Wrap South Damaged - No_6



39. Window Wrap South Damaged - No_7

40. Window Wrap South Damaged - No_8



41. Window Wrap South Damaged - No_9

42. Window Wrap South Damaged - No_10

43. Window Wrap South Damaged - No_11

44. Window Wrap South Damaged - No_12

45. Window Wrap South Damaged - No_13

46. Window Wrap South Damaged - No_14

47. Window Wrap South Damaged - No_15

48. Window Wrap South Damaged - No_16

49. Window Wrap South Damaged - No_17

50. Siding South Damage - No

51. Siding South Damage - No_2

52. Siding South Damage - No_3

53. Siding South Damage - No_4

54. Siding South Damage - No_5

55. Siding South Damage - No_6

56. Siding South Damage - No_7

57. Siding South Damage - No_8

58. Siding South Damage - No_9

59. Siding South Damage - No_10

60. Siding South Damage - No_11

61. Siding South Damage - No_12

62. Siding South Damage - No_13

63. Siding South Damage - No_14

64. Siding South Damage - No_15

65. Garage South Damaged - No

66. Garage South Damaged - No_2

67. Garage South Damaged - No_3

68. Garage South Damaged - No_4

69. Garage South Damaged - No_5

70. Elevation East/ Right

71. Window Wrap East Damaged - No

72. Window Wrap East Damaged - No_2

73. Siding East Damage - No

74. Siding East Damage - No_2

75. Siding East Damage - No_3

76. Siding East Damage - No_4

77. Siding East Damage - No_5

78. Siding East Damage - No_6

79. Elevation West/ Left

80. Window Wrap West Damaged - No

81. Window Wrap West Damaged - No_2

82. Window Wrap West Damaged - No_3

83. Window Wrap West Damaged - No_4

84. Window Wrap West Damaged - No_5

85. Window Wrap West Damaged - No_6

86. Window Wrap West Damaged - No_7



87. Window Wrap West Damaged - No_8



88. Window Wrap West Damaged - No_9

89. Window Wrap West Damaged - No_10

90. Window Wrap West Damaged - No_11

91. Window Wrap West Damaged - No_12



92. Window Wrap West Damaged - No_13



93. Siding West Damage - No

94. Siding West Damage - No_2

95. Siding West Damage - No_3

96. Siding West Damage - No_4

97. Siding West Damage - No_5

98. Down Spouts Damaged East/ Right - No

99. Down Spouts Damaged South/ Front - No

100. Down Spouts Damaged South/ Front - No_2

Field inspection photos

PDF Created on September 6, 2024 at 13:27:35 PM

Claim Number: 7007986837-1

Front elevations of home overview











Right elevations of home overview



Rear elevations of home overview

















Left elevation of home overview

CHIPS



Homeowner has some water damage on interior not related to hail no penetrations or openings to cause this water there is somewhere in tear on caulking on the exterior of the windows and there was heavy wind driven rain around these areas

Following photo show front of home overview homeowner pointed these items out

Falling photo show rear photos homeowners pointed these items out













Fall photos show interior windows homeowners showed these items to me as well



Entry Guard

DEPRESS ARM
TO DETACH
TRUTH











PRIEVE ENGINEERING LLC

FORENSIC STRUCTURAL CIVIL

EVALUATION OF CONDITION OF WINDOWS AS RELATES TO HAIL

FILE NUMBER 241008

17756 GEORGE MORAN DRIVE
EDEN PRAIRIE, MN 55347

SITE VISIT DATE: OCTOBER 9, 2024

REPORT DATE: NOVEMBER 4, 2024

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the state of Minnesota.

Signature: 

Typed or Printed Name: Nathan E Prieve

Date: 11-4-24 License Number: 46203

BACKGROUND:

Per the request of Nic Brau of Farmers Insurance, our office visited the subject property on October 9, 2024. The subject structure is a 2 story, walkout style, wood frame, private residence. The exterior is finished in composite lap siding. The roof membrane is finished in cedar shingles. We understand the structure to have been constructed in 1993. Convective storm activity and hail have been reported on multiple occasions in the area of the subject structure. The roof of the structure was replaced prior to the site visit related to a hail claim. Additional damage has been reported to windows in the home due to hail. Our office was retained to evaluate the condition of windows in the home as relates to hail and to provide recommendations for repairs for purposes of valuation.

This project scope is limited to the specific claim and/or incident at the subject structure. This report has been prepared to assist with evaluation of a property damage claim. This evaluation and report have been prepared within customary and usual standards and budgetary constraints based on information provided to our office. Prieve Engineering LLC is not the Engineer of Record for the subject structure. All other aspects of the subject structure and property are excluded from this evaluation and report.

This report is to be utilized only by the contracted party and is the copyright of Prieve Engineering LLC. This report is only applicable to the subject property and is not to be duplicated or used for any other properties or by any other parties.

ACTIVITIES:

This evaluation included, but was not limited to, review of the following documents and performance of the following activities.

- 2020 Minnesota Residential Code,
- Farmers Insurance Photo Log dated September 11, 2014,
- Farmers Insurance Estimate dated September 16, 2014,
- Farmers Insurance Estimated dated July 15, 2015,
- Inspection Photos dated October 13, 2020,
- Building Loss Worksheet dated 10-7-21,
- Farmers Insurance Letter and Estimate dated February 18, 2022,
- Window Condition Summary (by owner),
- Weather Records,
- Site visit October 9, 2024.

SITE VISIT OCTOBER 9, 2024 OBSERVATIONS:

The site was visited on October 9, 2024. Present front his office was Nathan Prieve P.E. Present at the site were the homeowners. Weather conditions at the time of the site visit were partly cloudy skies with outside temperatures approximately 70 degrees Fahrenheit. For purposes of clarity in the report, the front of the home will be referred to as the west side.

INTERIOR:

The interior of the home was observed at the time of the site visit at areas of reported water entry around windows. Various windows were observed as noted by the owners.

A window group appears at the front/west side above the main entry as shown in photograph A-1 and subsequent photos. A round top center unit appears flanked by adjacent fixed windows. Staining is present on the wall below the left side of the window unit to the upper left corner of the main entry door.

A bay projection appears at the rear/east family room with lower and upper window units along with a high row of single windows. Stain patterns appear below the left side of the single casement facing northeast as shown in photograph A-5. Staining appears below the left side of the main lower center window group in the east wall of the family room. Stains appear at the lower right corner of a window sash as shown n photograph A-7. Additional areas of staining were observed below corners of upper window units as shown in photographs A-9 and A-10. Discoloration was observed along the bottom sill of the lower southeast facing window unit in this area as shown in photograph A-13.

The upper stairway landing windows were observed at the south side, central quadrant of the home. Cracking appears in the wall at the lower left corner of the window unit in the south wall as shown in photograph A-15. The lower stairway landing windows were observed with units in the south and west walls. Cracking appears at the southwest wall corner between the lower corners of windows as shown in photograph A-18.

The window unit in the front wall of the upper southwest bedroom was observed. Apparent staining is present on the wall below the left side of the window. The lower sill of the window was observed to be deteriorated as shown in photograph A-21.

The rear 3 unit window at the upper level northeast bedroom was observed at the time of the site visit with leakage reported from the lower left corner. A penetration was observed in a siding panel below this window at the exterior with impact marks at the center of the penetration. Photographs A-26, A-27 and A-212 show conditions at the penetration in siding.

A four season porch appears at the main level, rear/central quadrant. Wallpaper appears in this room. Apparent staining and discoloration appear in wallpaper below the right corner of the southeast facing window and right side of the northeast facing window.

Windows appear at the northeast corner of the kitchen in the north and east walls. Staining appears at the joint between trim at the lower left corner of the window in the north wall. A southeast facing window appears at the south of the sliding door to the deck in the area south of the kitchen. Patching appears on the wall below the right side of the window as shown in photograph A-37.

EXTERIOR:

Front/West Side;

A triple window unit appears at the main level to the north of the main entry as shown in photograph A-38. Rounded dents were observed at sashes of this window unit. We note that prior claim information and photo logs indicate dents were previously noted at this window unit with replacement of the window unit included with a prior hail claim.

A similar 3 unit window appears at the upper level to the north of the main entry. A scrape mark was observed along the bottom outer frame of the window near a weep. Two dents with sharp marks/indentations appear long the left side of the left sash as shown in photograph A-45. A scrape mark was observed in the face of the bottom corner of a sash not consistent with hail.

The window group above the main entry was observed via at the front entry roof at the time of the site visit. A protrusion was observed along the bottom outer frame of the window unit. Caulking appears at the lower right corner of the window. No hail dents were observed at the window unit.

A triple window group appears at the main level, southwest quadrant on the front. A chip appears in the trim board along the left side of the window bump-out as shown in photograph A-53. We note this chip is visible in prior photo logs from Farmers Insurance dated October 13, 2020. All surfaces of this window were observed with no hail dents visible at frames or sashes.

The upper level bedroom window at the southwest quadrant was observed. Caulk appears at lower corners and lower mullion areas of the window. A dent appears in a window sash with a scrape mark present inside the dent as shown in photograph A-64.

Two single unit windows appear at the west side, north quadrant over the north covered entry door. No hail dents were observed at the sashes or frames of the two windows.

South Side;

Windows were observed at the south side of the home. Two single casement units appear at the west quadrant, one at the main level and one at the upper level. No hail dents were observed at the sashes or frames of the windows.

Two windows appear at the west side of the stairway, one at the upper landing area and one at the lower landing area. No hail dents were observed in frames or sashes of the two windows at the west side of the stairway.

The lower main stairway window group was observed at the south side, central quadrant. No hail dents were observed at sashes or frames of this window group.

The main upper stairway windows were observed via a ladder. Caulking appears over mullions of the upper window section along with lower corners of window frames. All surfaces were observed including sashes and frames with no hail dents visible on windows. A chip was observed in the trim board at the wall corner to the east of the stairway with underlying surfaces aged as shown in photograph A-90.

East Side;

Three levels appear exposed at the rear/east side of the home. Lower level windows and a patio door were observed under the deck and porch. No dents or marks were observed at windows and doors under the deck. A 3 unit window appears at the lower level, northeast quadrant of the home. No hail dents were observed at this window unit at the frame or sashes.

The main level family room windows were observed at the southeast quadrant as shown in photograph A-101 and subsequent photos. A dent with scrape marks was observed in the frame of the upper southeast facing window as shown in photograph A-107. Caulk appears at various areas of windows including corners of sashes and at mullions and corners of frames. An indentation appears on the left side of the center window accessory groove not consistent with hail along with a mark in the frame with loss of finishes as shown in photograph A-113. Two dents appear in the face of the sash at the lower left corner of the main window with scrape marks present inside and around areas of dents. A dent with marks present appears in the face of the drip cap of the upper center window unit. A scrape mark appears in the face of the frame of this window as shown in photograph A-121. A dent appears in the bottom accessory groove of the upper northeast facing window not consistent with hail. An upper bank of single window units appears above the bay projection at the south quadrant. Caulk appears at lower corners of frames. No hail dents appear at sashes or frames at the single unit windows. A scrape mark appears in the sash of the north window unit as shown in photograph A-146.

Two sliding doors appear at the rear deck with one facing east and one facing south at the porch. A southeast facing window appears to the left of the doors. Scrape marks appear in the frame of the window along the right side not consistent with hail. A dent with a scrape mark present appears in the bottom screen frame of the east facing sliding door.

A bay projection appears at the upper level, central quadrant above the east deck door. A dent appears along the left accessory groove of the southeast facing window not consistent with hail. Various scrape marks and a dent appear along the bottom frame of the center window not consistent with hail. Dents with scrape marks appear at the lower left corner of the sash of the northeast facing window not consistent with hail.

An upper level east facing window appears over the four season porch at the rear side. A dent appears along the bottom accessory groove not consistent with hail. A similar dent appears along the left side as shown in photograph A-163 not consistent with hail.

Windows were observed around the four season porch with southeast, east, northeast and north facing windows present. Scrape marks and dents with sharp marks appear at the southeast facing window as shown in photographs A-165 and A-166. Caulk appears visible along the bottom of the east facing window against glazing. The drip cap at this window was observed uneven at the right portion. A dent was observed along the bottom accessory groove of the northeast facing window as shown in photograph A-174. A four unit window appears in the north wall of the porch. Two dents appear at the lower left corner of the left casement which are generally smooth. This window was noted to have been included for full replacement from a prior hail claim as noted in past estimates provided by Farmers Insurance. A dent appears in the bottom accessory groove of the window not consistent with hail.

The north and east facing windows at the kitchen were observed. A scrape mark and dent appear at the right side of the east facing window not consistent with hail. Caulk appears at

the lower right corners of the north kitchen window. No hail dents appear at sashes or frames of kitchen windows.

A 3 unit window appears at the main level, northeast quadrant of the home. A dent appears in the left accessory groove similar to those observed elsewhere. Scrape marks appear along the lower frame as shown in photograph A-199 and A-201. Caulk appears at lower mullions of the window.

An upper level north facing window was observed above the kitchen. No hail dents were observed at the window sash or frame. A dent appears in the left accessory groove at the lower corner of the window.

The upper level 3 unit bedroom window was observed from a ladder at the northeast quadrant. No hail marks or dents were observed at this window at the frame or sashes.

A 2 unit window appears at the rear/east side of the garage adjacent to a shed. Various scrape marks appear in the frame of the window not consistent with hail. No smooth or rounded dents were observed in the frame or sashes.

Weather Records;

Weather data was reviewed for the area of the subject structure including stormersite. Reported observed past hail in the area includes 1.25” on June 19, 2015 to the east of the subject structure, 1.75” on July 25, 2017 to the east of the structure, 1” hail on September 6, 2020 to the east of the property, and multiple reports on August 9, 2020 ranging from 1 to 2 inches to the east, west and north of the property. Similar past estimated hail appears in a summary from the NOAA Storm Events Database with most recent hail in Eden Prairie reported in 2020.

CONCLUSIONS AND RECOMMENDATIONS:

After visiting the site, reviewing available data and documents, and based upon the training and expertise of the investigator, we have formed the following conclusions and recommendations to a reasonable degree of engineering certainty.

Prieve Engineering LLC reserves the right to supplement or amend the report pending further discovery. Any and all recommendations in the report are for budgeting and estimating purposes only and are not for permitting and/or construction. Detailed recommendations for permitting and construction will require separate stamped drawings and contract. Prieve Engineering LLC is not the Engineer of Record for the subject structure.

1) It is our opinion that no recent hail damage has occurred to windows in the subject structure related to any recent hail or other storm activity. Past storm data indicates a storm occurred on or around August 9, 2020 in the area. This is consistent with past claims including replacement of the roof due to hail damage. We note that prior claim estimates and information include 2 windows in the home noted for potential hail damage and replacement including the main level window to the left of the main entry and north facing window at the rear four season porch. Dents shown in prior claim photographs are similar to those observed during the site inspection. Given these 2 windows have already been included and we understand paid for due to prior storm activity, no additional payments in our opinion are appropriate for the 2 windows.

2) It is our opinion that no other damage occurred to windows around the home due to hail or any other catastrophic causation that warrants any repair or replacement. Dents and scrape marks appear at various areas of windows around the home not constant with hail. Dents noted at sashes and frames in our opinion include scrape marks inside dents consistent with impacts from blunt objects other than hail. Dents in accessory grooves are consistent with impacts other than hail or damage occurring during or following installation of windows at the time of construction of the home. Further, it is our opinion that past hail at the site was not of sufficient size to dent window frames or the face of sashes. No repairs or replacement of any further windows is warranted or required at the subject property due to hail or any other catastrophic causation other than the 2 windows already included and paid in prior claims.

3) It is our opinion that reported water leakage and water entry at windows is unrelated to hail or any other catastrophic causation. Stains present on walls at certain windows in our opinion are consistent with condensation and/or leakage through windows. We note that many windows have various applications of caulking at exterior sashes and frames consistent with past attempts to prevent water entry. Areas of staining and deterioration appear at the interior of windows consistent with long term aging and deterioration to units. The conditions observed at windows, including reported leakage and water entry, in our opinion relate to wear and tear and aging of units and are unrelated to hail or any other catastrophic causation. No repairs or replacement of windows are warranted as relates to hail and alleged leakage of units.

4) It is our opinion that the siding penetration at the rear upper level of the home is unrelated to hail. Marks appear inside the penetration consistent with an impact from a blunt object other than hail. Further, recent storm activity in the area generally consists of storms moving from west to east with hail originating from a westerly direction. The penetration in siding appears at the east side, opposite typical origination of hail in recent storm activity in the area. No repairs in our opinion are warranted to siding as relates to hail.

PRIEVE ENGINEERING LLC

FORENSIC STRUCTURAL CIVIL

FILE NUMBER: 241008

17756 GEORGE MORAN DRIVE
EDEN PRAIRIE, MN 55347

PHOTO APPENDIX A

SITE VISIT DATE: OCTOBER 9, 2024

This document is copyright of Prieve Engineering LLC. Duplication or reproduction is prohibited. This document relates only to the subject address and is to be used only by the contracted party.



A-1: INTERIOR UPPER WINDOW ABOVE MAIN ENTRY



A-2: STAIN PATTERNS VISIBLE BELOW LEFT CORNER OF WINDOW

A-3: UPPER LEFT CORNER OF ENTRY DOOR, STAINING VISIBLE ON WALL

A-4: REAR NORTHEAST FACING WINDOW AT FAMILY ROOM

A-5: VIEW OF WALL BELOW LEFT CORNER OF WINDOW

A-6: CENTER WINDOW GROUP, EAST WALL, VIEW OF LOWER LEFT CORNER

A-7: LOWER RIGHT CORNER AT SASH, STAINING PRESENT



A-8: LOWER LEFT CORNER OF MAIN CENTER WINDOW GROUP, FAMILY ROOM

A-9: LOWER RIGHT CORNER OF CENTER WINDOW GROUP AT EAST FAMILY ROOM WALL

A-10: UPPER SOUTHEAST WINDOW IN FAMILY ROOM

A-11: LOWER SOUTHEAST FACING WINDOW IN FAMILY ROOM

A-12: LOWER LEFT CORNER OF WINDOW

A-13: LOWER RIGHT CORNER, DETERIORATION PRESENT

A-14: SOUTH STAIRWAY WINDOW, MAIN LEVEL TO UPPER LEVEL LANDING

A-15: LOWER LEFT CORNER OF WINDOW



A-16: LOWER CORNER OF WINDOW

A-17: SOUTHWEST WINDOWS AT LOWER STAIRWAY LANDING

A-18: WALL CORNER BETWEEN WINDOWS AT STAIRWAY

A-19: UPPER LEVEL FRONT WINDOW AT SOUTHWEST BEDROOM

A-20: LOWER LEFT CORNER OF WINDOW AT WALL

A-21: LOWER WINDOW CORNER, DETERIORATION PRESENT

A-22: REAR NORTHEAST BEDROOM, EAST WINDOW

A-23: WALL BELOW LEFT SIDE OF WINDOW



A-24: LOWER LEFT CORNER OF WINDOW

A-25: EXTERIOR, VIEW OF SIDING BELOW UPPER BEDROOM WINDOW

A-26: PENETRATION IN SIDING PANEL BELOW UPPER EAST BEDROOM WINDOW

A-27: VIEW OF PENETRATION IN SIDING PANEL

A-28: SOUTHEAST FACING WINDOW AT REAR MAIN LEVEL PORCH

A-29: VIEW OF WALLPAPER BELOW RIGHT SIDE OF WINDOW

A-30: LOWER RIGHT CORNER OF WINDOW, SOUTHEAST FACING

A-31: NORTHEAST FACING WINDOW IN REAR MAIN LEVEL PORCH

A-32: VIEW OF WALL BELOW RIGHT SIDE OF WINDOW

A-33: LOWER RIGHT CORNER OF WINDOW

A-34: LOWER LEFT CORNER OF NORTH WINDOW IN KITCHEN



A-35: VIEW OF JOINT IN TRIM AT LOWER LEFT CORNER OF KITCHEN WINDOW

A-36: LOWER LEFT CORNER OF WINDOW AT SASH

A-37: SOUTHEAST FACING WINDOW SOUTH OF DECK DOOR

A-38: MAIN LEVEL, WEST WINDOW NORTH OF ENTRY

A-39: VIEW OF DENT IN SASH AT RIGHT CASEMENT



A-40: DENT IN SASH ALONG LEFT SIDE OF CASEMENT

A-41: LEFT CASEMENT, VIEW OF DENT IN SASH

A-42: DOWNSPOUT EXTENSION AT FRONT, VIEW OF DENT AT UPPER EDGE



A-43: UPPER WINDOW, WEST SIDE NORTH OF ENTRY

A-44: VIEW ALONG BOTTOM OF WINDOW

A-45: DENTS WITH SHARP MARKS PRESENT AT LEFT SASH

A-46: LOWER RIGHT CORNER OF SASH AT UPPER WINDOW

A-47: VIEW ALONG BOTTOM OF WINDOW, UPPER WEST BEDROOM



A-48: UPPER WINDOW ABOVE MAIN ENTRY

A-49: LOWER RIGHT CORNER OF CENTER FIXED SASH

A-50: VIEW ALONG BOTTOM OF WINDOW FRAME, OUTWARD PROTRUSION

A-51: LOWER RIGHT CORNER OF UPPER WINDOW

A-52: MAIN LEVEL WINDOW, WEST SIDE SOUTH OF ENTRY

A-53: CHIP IN TRIM ALONG LEFT SIDE OF BUMP-OUT

A-54: VIEW OF FLASHING ALONG BOTTOM OF BUMP-OUT



A-55: LEFT SIDE OF WINDOW GROUP AT MAIN LEVEL IN BUMP-OUT

A-56: VIEW ALONG BOTTOM OF WINDOW FRAME

A-57: ADJACENT AREA ALONG BOTTOM OF WINDOW

A-58: RIGHT SIDE OF WINDOW, MAIN LEVEL, SOUTHWEST QUADRANT

A-59: UPPER BEDROOM WINDOW, WEST SIDE SOUTH OF ENTRY

A-60: LOWER RIGHT CORNER OF WINDOW

A-61: VIEW OF RIGHT MULLION

A-62: LEFT MULLION, CAULK PRESENT

A-63: LOWER LEFT CORNER OF WINDOW

A-64: SASH WITH DENT PRESENT AND SCRAPE MARK IN DENT

A-65: VIEW ALONG BOTTOM OF WINDOW FRAME

A-66: UPPER WINDOWS AT WEST SIDE, NORTH QUADRANT

A-67: LOWER LEFT CORNER OF LEFT UPPER WINDOW

A-68: LOWER LEFT CORNER OF RIGHT/SOUTH WINDOW AT UPPER LEVEL

A-69: SOUTH SIDE OF HOME, AREA OF STAIRWAY

A-70: SOUTH WINDOW AT MAIN LEVEL WEST OF STAIRWAY

A-71: WEST WINDOW AT LOWER STAIRWAY

A-72: LOWER RIGHT CORNER OF WEST FACING WINDOW AT STAIRWAY

A-73: UPPER WEST WINDOW AT UPPER STAIRWAY LANDING

A-74: UPPER SOUTH FACING WINDOW WEST OF STAIRWAY

A-75: LOWER STAIRWAY WINDOW GROUP, SOUTH WALL

A-76: LOWER LEFT CORNER OF WINDOW

A-77: LOWER RIGHT CORNER OF WINDOW AT LOWER STAIRWAY LANDING

A-78: VIEW ALONG BOTTOM OF WINDOW

A-79: WINDOW GROUP AT UPPER STAIRWAY LANDING, SOUTH WALL

A-80: VIEW ALONG BOTTOM OF WEST SASH AT LOWER WINDOW

A-81: LOWER RIGHT CORNER OF UPPER STAIRWAY WINDOW GROUP

A-82: MULLION AT WINDOW, CUALK PRESENT

A-83: UPPER PORTION OF MULLION AT STAIRWAY WINDOW GROUP

A-84: LEFT MULLION AT STAIRWAY WINDOW GROUP

A-85: UPPER WEST WINDOW AT STAIRWAY



A-86: LEFT SIDE OF UPPER CENTER WINDOW

A-87: RIGHT MULLION AT UPPER WINDOWS, CAULK PRESENT

A-88: VIEW OF UPPER MULLION INTERSECTION AT STAIRWAY WINDOWS

A-89: WEST FACING WALL AT PROJECTION ON SOUTH SIDE EAST OF STAIRWAY

A-90: AREA OF CHIPPED FINISHES AT TRIM BOARD

A-91: DOWNSPOUT EXTENSION AT SOUTH SIDE OF HOME

A-92: VIEW OF DOWNSPOUT, DENT PRESENT

A-93: ADJACENT AREA SHOWING DENT IN DOWNSPOUT

A-94: OVERVIEW OF EAST SIDE OF HOME

A-95: LOWER WINDOW GROUP UNDER DECK AT SOUTH QUADRANT

A-96: LOWER DOOR AND WINDOWS BELOW DECK, ADJACENT AREA TO THE NORTH

A-97: ADJACENT LOWER WINDOW GROUP UNDER PORCH AT EAST SIDE

A-98: DOWNSPOUT AT EASET SIDE SHOWING DENT

A-99: DENT IN DOWNSPOUT WITH CREASE PRESENT

A-100: LOWER LEVEL WINDOW GROUP, EAST SIDE AT NORTH QUADRANT

A-101: EAST WINDOW GROUP IN FAMILY ROOM AT MAIN LEVEL



A-102: LOWER SOUTHEAST FACING WINDOW

A-103: VIEW OF DENTS IN FLASHING AT BASE OF WALL ALONG DECK

A-104: UPPER LEFT CORNER OF SOUTHEAST FACING LOWER WINDOW

A-105: LEFT SIDE AT SOUTHEAST FACING WINDOW

A-106: UPPER SOUTHEAST FACING WINDOW AT FAMILY ROOM

A-107: LOWER RIGHT CORNER OF WINDOW

A-108: MAIN EAST FACING WINDOW GROUP AT FAMILY ROOM

A-109: BOTTOM OF RIGHT CASEMENT

A-110: VIEW OF RIGHT MULLION

A-111: SCRAPE MARKS AT MULLION

A-112: LEFT SIDE OF WINDOW FRAME

A-113: VIEW OF DENT WITH SCRAPE MARKS AT UPPER PORTION OF WINDOW

A-114: VIEW ALONG SILL, DENT WITH SCRAPE MARK

A-115: LOWER LEFT CORNER, 2 DENTS PRESENT ALIGNED VERTICALLY

A-116: UPPER DENT, SCRAPE MARK PRESENT

A-117: VIEW OF LOWER DENT, VARIOUS SCRAPE MARKS ON SURFACES

A-118: UPPER EAST WINDOW GROUP AT FAMILY ROOM

A-119: VIEW OF DENT IN DRIP CAP WITH MARK PRESENT IN DENT

A-120: ADJACENT AREA ALONG TOP OF UPPER WINDOW

A-121: LOWER PORTION OF WINDOW, SCRAPE MARK PRESENT

A-122: VIEW ALONG BOTTOM OF WINDOW FRAME

A-123: VIEW ALONG BOTTOM OF WINDOW FRAME

A-124: LOWER RIGHT CORNER OF WINDOW

A-125: NORTHEAST FACING WINDOW AT FAMILY ROOM

A-126: LOWER RIGHT CORNER OF WINDOW

A-127: LOWER LEFT CORNER, LOWER NORTHEAST FAMILY ROOM WINDOW

A-128: VIEW OF FLASHING AT DECK ALONG BASE OF WALL

A-129: ADJACENT AREA SHOWING FLASHING ALONG DECK AT EAST WALL

A-130: SCRAPE MARK ALONG BOTTOM FRAME OF WINDOW

A-131: VIEW ALONG BOTTOM OF WINDOW, NORTHEAST FACING FAMILY ROOM

A-132: VIEW OF DRIP CAP ABOVE WINDOW, NO DENTS OBSERVED

A-133: UPPER NORTHEAST FACING WINDOW AT FAMILY ROOM

A-134: DENT IN BOTTOM OF WINDOW FRAME AT ACCESSORY GROOVE

A-135: VIEW OF FACE OF WINDOW FRAME AT UPPER NORTHEAST WINDOW UNIT

A-136: WINDOW AND SLIDING DOOR, EAST SIDE AT DECK

A-137: LOWER LEFT CORNER OF WINDOW, SOUTHEAST FACING

A-138: LOWER RIGHT CORNER OF WINDOW

A-139: RIGHT SIDE, SCRAPE MARK IN FRAME

A-140: VIEW OF SCRAPE MARKS IN FRAME AND SASH

A-141: DENT IN SCREEN AT DOOR WINDOW SCRAPE MARK PRESENT

A-142: UPPER WINDOWS, EAST WALL AT SOUTH QUADRANT

A-143: LOWER LEFT CORNER OF SOUTH WINDOW

A-144: LOWER RIGHT CORNER, CAULK AT WINDOW CORNERS

A-145: NORTH WINDOW AT UPPER FAMILY ROOM

A-146: SCRAPE MARK ALONG LEFT SIDE OF SASH AT NORTH WINDOW

A-147: UPPER BAY WINDOW GROUP AT EAST SIDE, CENTRAL QUADRANT

A-148: VIEW OF TRIM ADJACENT TO WINDOW CORNER

A-149: DENT IN ACCESSORY GROOVE ALONG LEFT SIDE OF WINDOW

A-150: LOWER LEFT CORNER OF WINDOW

A-151: VIEW ALONG LEFT SIDE, INDENTATION IN ACCESSORY GROOVE

A-152: LOWER RIGHT CORNER OF WINDOW, SOUTHEAST FACING

A-153: CENTER EAST WINDOW, VIEW OF LOWER RIGHT CORNER

A-154: VIEW TOWARDS LEFT CORNER AT CENTER EAST WINDOW ABOVE DOOR



A-155: SCRAPING ALONG EDGE OF BOTTOM WINDOW FRAME

A-156: ADJACENT AREA ALONG BOTTOM WINDOW FRAME, DENT WITH SCRAPE MARKS

A-157: NORTHEAST FACING WINDOW AT CENTER BAY PROJECTION

A-158: LOWER LEFT CORNER OF WINDOW

A-159: VIEW OF SASH, DENT WITH SCRAPE MARK PRESENT

A-160: LOWER DENT ALONG LEFT SIDE OF SASH, MARKS VISIBLE

A-161: UPPER EAST WINDOW ABOVE PORCH

A-162: VIEW OF DENT ALONG BOTTOM ACCESSORY GROOVE

A-163: DENT IN LEFT SIDE ALONG ACCESSORY GROOVE

A-164: SOUTH DOOR, SOUTHEAST WINDOW AT PORCH



A-165: DENT WITH MISSING FINISHES ALONG BOTTOM OF WINDOW

A-166: DENT WITH SCRAPE MARK AT LEFT SIDE OF SASH

A-167: EAST AND NORTHEAST FACING WINDOWS AT PORCH

A-168: LOWER RIGHT CORNER OF EAST PICTURE WINDOW

A-169: BOTTOM SASH, SEALANT VISIBLE ALONG GLAZING

A-170: VIEW OF DRIP CAP ALONG TOP OF WINDOW

A-171: UPPER RIGHT CORNER OF WINDOW

A-172: ADJACENT AREA ALONG DRIP CAP, OUTER EDGE UNEVEN

A-173: LOWER PORTION OF NORTHEAST FACING WINDOW

A-174: UPWARD DENT ALONG BOTTOM ACCESSORY GROOVE

A-175: SCRAPE MARKS AT RIGHT SIDE FRAME

A-176: NORTH FACING WINDOW GROUP AT REAR PORCH

A-177: VIEW OF BASE OF LEFT MULLION

A-178: LOWER LEFT CORNER OF WINDOW GROUP

A-179: VERTICALLY ALIGNED DENTS AT LEFT SASH

A-180: VIEW ALONG BOTTOM OF SASH, SCRAPE PRESENT

A-181: VIEW OF MULLION CAP AT LEFT MULLION OF WINDOW

A-182: RIGHT MULLION AT NORTH FACING PORCH WINDOW

A-183: UPWARD DENT IN ACCESSORY GROOVE AT FRAME

A-184: NORTH AND EAST FACING WINDOWS AT CORNER OF KITCHEN

A-185: EAST WINDOW, RIGHT SIDE, DENT WITH SCRAPE MARK

A-186: VIEW OF LOWER CORNER OF UPPER WINDOW AT EAST WALL

A-187: VENTS IN EAST WALL

A-188: NO DENTS VISIBLE IN SURFACE OF VENT

A-189: VIEW OF ADJACENT VENT HOOD

A-190: LOWER RIGHT CORNER OF NORTH KITCHEN WINDOW

A-191: CAULKING AT LOWER RIGHT CORNER

A-192: LOWER LEFT CORNER OF WINDOW

A-193: SCRAPE ALONG LEFT SASH NEAR CORNER

A-194: VIEW BETWEEN UPPER AND LOWER WINDOW AT NORTH KITCHEN WALL

A-195: LEFT SIDE BETWEEN UPPER AND LOWER NORTH KITCHEN WINDOWS



A-196: MAIN LEVEL WINDOW, EAST SIDE AT NORTH QUADRANT

A-197: VIEW ALONG TOP OF WINDOW

A-198: LOWER LEFT CORNER OF WINDOW

A-199: SCRAPE MARKS ALONG OUTER EDGE OF LOWER FRAME

A-200: LEFT SIDE, DENT IN ACCESSORY GROOVE

A-201: SCRAPE MARK WITH DAMAGE TO FINISHES AT BOTTOM FRAME

A-202: VIEW OF CAULKING AT MULLION

A-203: ADJACENT MULLION SHOWING CAULKING

A-204: LOWER RIGHT CORNER OF WINDOW

A-205: UPPER LEVEL NORTH FACING WINDOW ABOVE KITCHEN

A-206: LOWER LEFT CORNER, DENT IN ACCESSORY GROOVE

A-207: UPPER EAST BEDROOM WINDOW GROUP AT NORTH QUADRANT

A-208: AREA OF SIDING PENETRATION BELOW WINDOW

A-209: VIEW ALONG BOTTOM OF WINDOW NEAR MULLION

A-210: VIEW NORTH ALONG BOTTOM SASH OF RIGHT CASEMENT

A-211: AREA OF MULLION AT UPPER BEDROOM WINDOW

A-212: VIEW OF SIDING PENETRATION FROM LADDER

A-213: WINDOW AT REAR/EAST SIDE OF GARAGE

A-214: LOWER LEFT CORNER, SCRAPE MARKS IN ACCESSORY GROOVE

A-215: LEFT SIDE OF WINDOW AT GARAGE

A-216: LOWER RIGHT CORNER OF GARAGE WINDOW

A-217: VIEW OF MULLION AT GARAGE WINDOW

FARMERS INSURANCE

Toll Free: (800) 435-7764
Email: myclaim@farmersinsurance.com
Please include your claim # on any correspondence
National Document Center
P.O. Box 268994
Oklahoma City, OK 73126-8994
www.farmers.com/claimstatus

November 4, 2024

YIBIAO LU
17756 GEORGE MORAN DR
EDEN PRAIRIE MN 55347-1061
Delivered by email to: BILL_Y_LU@YAHOO.COM

RE:		
	Insured:	Yibiao Lu
	Claim Number:	7007986837-1-1
	Policy Number:	0980554965
	Loss Date:	07/13/2024
	Location of Loss:	17756 George Moran Dr, Eden Prairie, MN
	Subject:	Claim Outcome Letter

Dear Yibiao Lu & Jie Hu:

Thank you for being a valued customer. We are proud to serve you.

You reported hail to the window and water inside.

Our investigation found the condition of the window and components to be from wear/tear as referrenced in the attached engineer report. Unfortunately, there is no coverage for your claim based on the information known at this time.

We encourage you to review the terms of your Next Generation Homeowners Policy Minnesota, 2nd Ed, as endorsed. They form the basis for our decision. We have attached a “Coverage Outcome – Policy Provisions” document that refers you to the applicable sections of the policy.

We reserve all rights and defenses under the policy and law and no activity on our part should be construed as a waiver. Even though only parts of the policy may be mentioned or quoted in this letter, additional portions if found to be relevant will be applied.

Please note there are time limits set forth in the Conditions (“Lawsuits Against Us" or “Legal Action Against Us” or "Suit Against Us”) section of the policy which, depending on your state, may affect the time within which you may pursue your claim. This period may have been extended by statute or case law.

Although we remain available to discuss this matter with you, pursuant to MN Insurance Regulation 72A.201 we are required to advise you that if some or all of your claim has been denied you have the right to file a complaint with the Minnesota Department of Commerce. Minnesota Department of Commerce - 85 7th Place East, Suite 280 - St. Paul, MN 55101- Toll Free Number 800-657-3602.

We encourage you to visit www.farmers.com to learn more about our self-service options available to you, including the ability to view your claim status, upload documents and photos and find local service providers.

If you have any questions, or additional information you think may affect your coverage, please contact me.

Thank you.

Nicholas Brau
Claims Spec Rep Prop
(651) 587-3157
Fire Insurance Exchange

Email communications are preferred and should be sent to myclaim@farmersinsurance.com. If hard copies of communications are required, they should be sent to our National Document Center at P.O. Box 268994, Oklahoma City, OK 73126-8994.

Enclosure(s):
Report of Loss -

Coverage Outcome - Policy Provisions

DEFINITIONS

...

16. **Marring** - means any disfigurement, blemish, discoloration weathering or stretching, or the like, of or to covered property, including by way of example but not limited to scratching, scorching, denting, creasing, gouging, fading, staining, tearing or thinning.

...

SECTION I - UNINSURED LOSS OR DAMAGE and EXCLUDED CAUSES OF LOSS OR DAMAGE

A. **Uninsured Types of Loss or Damage.**

...

4. **Inherent Vice or Latent Defect.**

...

7. **Wear and tear or mechanical breakdown.**

...

8. **Marring.**

...

9. **Corrosion, Deterioration, Decay or Rust.**

...

14. **Exceptions to Uninsured types of damage.**

...

B. **Excluded Causes of Loss or Damage.**

...

4. **Neglect or Lack of Maintenance or Failure to Make Repairs.**
5. **Faulty, Inadequate, Defective or Incomplete Planning, Zoning, Maintenance, Repairs, Renovation, Manufacture or Construction.**

...

6. **Inherent Vice or Latent Defect.**

...

8. **Wear and Tear, Deterioration or Mechanical Breakdown.**

...

9. **Corrosion, Deterioration, Decay or Rust.**

PRIEVE ENGINEERING LLC

FORENSIC STRUCTURAL CIVIL

EVALUATION OF CONDITION OF WINDOWS AS RELATES TO HAIL

FILE NUMBER 241008

17756 GEORGE MORAN DRIVE
EDEN PRAIRIE, MN 55347

SITE VISIT DATE: OCTOBER 9, 2024

REPORT DATE: NOVEMBER 4, 2024

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Professional Engineer under the laws of the state of Minnesota.

Signature:

Typed or Printed Name: Nathan E Prieve

Date: 11-4-24 License Number: 46203

BACKGROUND:

Per the request of Nic Brau of Farmers Insurance, our office visited the subject property on October 9, 2024. The subject structure is a 2 story, walkout style, wood frame, private residence. The exterior is finished in composite lap siding. The roof membrane is finished in cedar shingles. We understand the structure to have been constructed in 1993. Convective storm activity and hail have been reported on multiple occasions in the area of the subject structure. The roof of the structure was replaced prior to the site visit related to a hail claim. Additional damage has been reported to windows in the home due to hail. Our office was retained to evaluate the condition of windows in the home as relates to hail and to provide recommendations for repairs for purposes of valuation.

This project scope is limited to the specific claim and/or incident at the subject structure. This report has been prepared to assist with evaluation of a property damage claim. This evaluation and report have been prepared within customary and usual standards and budgetary constraints based on information provided to our office. Prieve Engineering LLC is not the Engineer of Record for the subject structure. All other aspects of the subject structure and property are excluded from this evaluation and report.

This report is to be utilized only by the contracted party and is the copyright of Prieve Engineering LLC. This report is only applicable to the subject property and is not to be duplicated or used for any other properties or by any other parties.

ACTIVITIES:

This evaluation included, but was not limited to, review of the following documents and performance of the following activities.

- 2020 Minnesota Residential Code,
- Farmers Insurance Photo Log dated September 11, 2014,
- Farmers Insurance Estimate dated September 16, 2014,
- Farmers Insurance Estimated dated July 15, 2015,
- Inspection Photos dated October 13, 2020,
- Building Loss Worksheet dated 10-7-21,
- Farmers Insurance Letter and Estimate dated February 18, 2022,
- Window Condition Summary (by owner),
- Weather Records,
- Site visit October 9, 2024.

SITE VISIT OCTOBER 9, 2024 OBSERVATIONS:

The site was visited on October 9, 2024. Present front his office was Nathan Prieve P.E. Present at the site were the homeowners. Weather conditions at the time of the site visit were partly cloudy skies with outside temperatures approximately 70 degrees Fahrenheit. For purposes of clarity in the report, the front of the home will be referred to as the west side.

INTERIOR:

The interior of the home was observed at the time of the site visit at areas of reported water entry around windows. Various windows were observed as noted by the owners.

A window group appears at the front/west side above the main entry as shown in photograph A-1 and subsequent photos. A round top center unit appears flanked by adjacent fixed windows. Staining is present on the wall below the left side of the window unit to the upper left corner of the main entry door.

A bay projection appears at the rear/east family room with lower and upper window units along with a high row of single windows. Stain patterns appear below the left side of the single casement facing northeast as shown in photograph A-5. Staining appears below the left side of the main lower center window group in the east wall of the family room. Stains appear at the lower right corner of a window sash as shown n photograph A-7. Additional areas of staining were observed below corners of upper window units as shown in photographs A-9 and A-10. Discoloration was observed along the bottom sill of the lower southeast facing window unit in this area as shown in photograph A-13.

The upper stairway landing windows were observed at the south side, central quadrant of the home. Cracking appears in the wall at the lower left corner of the window unit in the south wall as shown in photograph A-15. The lower stairway landing windows were observed with units in the south and west walls. Cracking appears at the southwest wall corner between the lower corners of windows as shown in photograph A-18.

The window unit in the front wall of the upper southwest bedroom was observed. Apparent staining is present on the wall below the left side of the window. The lower sill of the window was observed to be deteriorated as shown in photograph A-21.

The rear 3 unit window at the upper level northeast bedroom was observed at the time of the site visit with leakage reported from the lower left corner. A penetration was observed in a siding panel below this window at the exterior with impact marks at the center of the penetration. Photographs A-26, A-27 and A-212 show conditions at the penetration in siding.

A four season porch appears at the main level, rear/central quadrant. Wallpaper appears in this room. Apparent staining and discoloration appear in wallpaper below the right corner of the southeast facing window and right side of the northeast facing window.

Windows appear at the northeast corner of the kitchen in the north and east walls. Staining appears at the joint between trim at the lower left corner of the window in the north wall. A southeast facing window appears at the south of the sliding door to the deck in the area south of the kitchen. Patching appears on the wall below the right side of the window as shown in photograph A-37.

EXTERIOR:

Front/West Side;

A triple window unit appears at the main level to the north of the main entry as shown in photograph A-38. Rounded dents were observed at sashes of this window unit. We note that prior claim information and photo logs indicate dents were previously noted at this window unit with replacement of the window unit included with a prior hail claim.

A similar 3 unit window appears at the upper level to the north of the main entry. A scrape mark was observed along the bottom outer frame of the window near a weep. Two dents with sharp marks/indentations appear long the left side of the left sash as shown in photograph A-45. A scrape mark was observed in the face of the bottom corner of a sash not consistent with hail.

The window group above the main entry was observed via at the front entry roof at the time of the site visit. A protrusion was observed along the bottom outer frame of the window unit. Caulking appears at the lower right corner of the window. No hail dents were observed at the window unit.

A triple window group appears at the main level, southwest quadrant on the front. A chip appears in the trim board along the left side of the window bump-out as shown in photograph A-53. We note this chip is visible in prior photo logs from Farmers Insurance dated October 13, 2020. All surfaces of this window were observed with no hail dents visible at frames or sashes.

The upper level bedroom window at the southwest quadrant was observed. Caulk appears at lower corners and lower mullion areas of the window. A dent appears in a window sash with a scrape mark present inside the dent as shown in photograph A-64.

Two single unit windows appear at the west side, north quadrant over the north covered entry door. No hail dents were observed at the sashes or frames of the two windows.

South Side;

Windows were observed at the south side of the home. Two single casement units appear at the west quadrant, one at the main level and one at the upper level. No hail dents were observed at the sashes or frames of the windows.

Two windows appear at the west side of the stairway, one at the upper landing area and one at the lower landing area. No hail dents were observed in frames or sashes of the two windows at the west side of the stairway.

The lower main stairway window group was observed at the south side, central quadrant. No hail dents were observed at sashes or frames of this window group.

The main upper stairway windows were observed via a ladder. Caulking appears over mullions of the upper window section along with lower corners of window frames. All surfaces were observed including sashes and frames with no hail dents visible on windows. A chip was observed in the trim board at the wall corner to the east of the stairway with underlying surfaces aged as shown in photograph A-90.

East Side;

Three levels appear exposed at the rear/east side of the home. Lower level windows and a patio door were observed under the deck and porch. No dents or marks were observed at windows and doors under the deck. A 3 unit window appears at the lower level, northeast quadrant of the home. No hail dents were observed at this window unit at the frame or sashes.

The main level family room windows were observed at the southeast quadrant as shown in photograph A-101 and subsequent photos. A dent with scrape marks was observed in the frame of the upper southeast facing window as shown in photograph A-107. Caulk appears at various areas of windows including corners of sashes and at mullions and corners of frames. An indentation appears on the left side of the center window accessory groove not consistent with hail along with a mark in the frame with loss of finishes as shown in photograph A-113. Two dents appear in the face of the sash at the lower left corner of the main window with scrape marks present inside and around areas of dents. A dent with marks present appears in the face of the drip cap of the upper center window unit. A scrape mark appears in the face of the frame of this window as shown in photograph A-121. A dent appears in the bottom accessory groove of the upper northeast facing window not consistent with hail. An upper bank of single window units appears above the bay projection at the south quadrant. Caulk appears at lower corners of frames. No hail dents appear at sashes or frames at the single unit windows. A scrape mark appears in the sash of the north window unit as shown in photograph A-146.

Two sliding doors appear at the rear deck with one facing east and one facing south at the porch. A southeast facing window appears to the left of the doors. Scrape marks appear in the frame of the window along the right side not consistent with hail. A dent with a scrape mark present appears in the bottom screen frame of the east facing sliding door.

A bay projection appears at the upper level, central quadrant above the east deck door. A dent appears along the left accessory groove of the southeast facing window not consistent with hail. Various scrape marks and a dent appear along the bottom frame of the center window not consistent with hail. Dents with scrape marks appear at the lower left corner of the sash of the northeast facing window not consistent with hail.

An upper level east facing window appears over the four season porch at the rear side. A dent appears along the bottom accessory groove not consistent with hail. A similar dent appears along the left side as shown in photograph A-163 not consistent with hail.

Windows were observed around the four season porch with southeast, east, northeast and north facing windows present. Scrape marks and dents with sharp marks appear at the southeast facing window as shown in photographs A-165 and A-166. Caulk appears visible along the bottom of the east facing window against glazing. The drip cap at this window was observed uneven at the right portion. A dent was observed along the bottom accessory groove of the northeast facing window as shown in photograph A-174. A four unit window appears in the north wall of the porch. Two dents appear at the lower left corner of the left casement which are generally smooth. This window was noted to have been included for full replacement from a prior hail claim as noted in past estimates provided by Farmers Insurance. A dent appears in the bottom accessory groove of the window not consistent with hail.

The north and east facing windows at the kitchen were observed. A scrape mark and dent appear at the right side of the east facing window not consistent with hail. Caulk appears at

the lower right corners of the north kitchen window. No hail dents appear at sashes or frames of kitchen windows.

A 3 unit window appears at the main level, northeast quadrant of the home. A dent appears in the left accessory groove similar to those observed elsewhere. Scrape marks appear along the lower frame as shown in photograph A-199 and A-201. Caulk appears at lower mullions of the window.

An upper level north facing window was observed above the kitchen. No hail dents were observed at the window sash or frame. A dent appears in the left accessory groove at the lower corner of the window.

The upper level 3 unit bedroom window was observed from a ladder at the northeast quadrant. No hail marks or dents were observed at this window at the frame or sashes.

A 2 unit window appears at the rear/east side of the garage adjacent to a shed. Various scrape marks appear in the frame of the window not consistent with hail. No smooth or rounded dents were observed in the frame or sashes.

Weather Records;

Weather data was reviewed for the area of the subject structure including stormersite. Reported observed past hail in the area includes 1.25” on June 19, 2015 to the east of the subject structure, 1.75” on July 25, 2017 to the east of the structure, 1” hail on September 6, 2020 to the east of the property, and multiple reports on August 9, 2020 ranging from 1 to 2 inches to the east, west and north of the property. Similar past estimated hail appears in a summary from the NOAA Storm Events Database with most recent hail in Eden Prairie reported in 2020.

CONCLUSIONS AND RECOMMENDATIONS:

After visiting the site, reviewing available data and documents, and based upon the training and expertise of the investigator, we have formed the following conclusions and recommendations to a reasonable degree of engineering certainty.

Prieve Engineering LLC reserves the right to supplement or amend the report pending further discovery. Any and all recommendations in the report are for budgeting and estimating purposes only and are not for permitting and/or construction. Detailed recommendations for permitting and construction will require separate stamped drawings and contract. Prieve Engineering LLC is not the Engineer of Record for the subject structure.

1) It is our opinion that no recent hail damage has occurred to windows in the subject structure related to any recent hail or other storm activity. Past storm data indicates a storm occurred on or around August 9, 2020 in the area. This is consistent with past claims including replacement of the roof due to hail damage. We note that prior claim estimates and information include 2 windows in the home noted for potential hail damage and replacement including the main level window to the left of the main entry and north facing window at the rear four season porch. Dents shown in prior claim photographs are similar to those observed during the site inspection. Given these 2 windows have already been included and we understand paid for due to prior storm activity, no additional payments in our opinion are appropriate for the 2 windows.

2) It is our opinion that no other damage occurred to windows around the home due to hail or any other catastrophic causation that warrants any repair or replacement. Dents and scrape marks appear at various areas of windows around the home not constant with hail. Dents noted at sashes and frames in our opinion include scrape marks inside dents consistent with impacts from blunt objects other than hail. Dents in accessory grooves are consistent with impacts other than hail or damage occurring during or following installation of windows at the time of construction of the home. Further, it is our opinion that past hail at the site was not of sufficient size to dent window frames or the face of sashes. No repairs or replacement of any further windows is warranted or required at the subject property due to hail or any other catastrophic causation other than the 2 windows already included and paid in prior claims.

3) It is our opinion that reported water leakage and water entry at windows is unrelated to hail or any other catastrophic causation. Stains present on walls at certain windows in our opinion are consistent with condensation and/or leakage through windows. We note that many windows have various applications of caulking at exterior sashes and frames consistent with past attempts to prevent water entry. Areas of staining and deterioration appear at the interior of windows consistent with long term aging and deterioration to units. The conditions observed at windows, including reported leakage and water entry, in our opinion relate to wear and tear and aging of units and are unrelated to hail or any other catastrophic causation. No repairs or replacement of windows are warranted as relates to hail and alleged leakage of units.

4) It is our opinion that the siding penetration at the rear upper level of the home is unrelated to hail. Marks appear inside the penetration consistent with an impact from a blunt object other than hail. Further, recent storm activity in the area generally consists of storms moving from west to east with hail originating from a westerly direction. The penetration in siding appears at the east side, opposite typical origination of hail in recent storm activity in the area. No repairs in our opinion are warranted to siding as relates to hail.

Proposal - Detailed

Pella Window and Door Showroom of Plymouth
13810 24th Avenue North Suite 430
Plymouth, MN 55441
Phone: (952) 915-6080 **Fax:**

Sales Rep Name: Conyard, Tim
Sales Rep Phone: 612-237-6392
Sales Rep E-Mail: conyardt@pellamn.com
Sales Rep Fax:

Customer Information	Project/Delivery Address	Order Information
PURE Construction 16471 Territorial Trl MAPLE GROVE, MN 55369-2223 **Primary Phone:** (763) 307-3826 **Mobile Phone:** (952) 292-8004 ext. Zach S **Fax Number:** **E-Mail:** info@pureconstructionmn.com **Contact Name:** **Great Plains #:** 1007847596 **Customer Number:** 1011586231 **Customer Account:** 1007847596	**17756 George Moran Drive,EP- Lu Bill** 16471 Territorial Trl **Lot #** Maple Grove, MN 55369-2223 **County:** **Owner Name:** **Owner Phone:**	**Quote Name:** RESERVE/ LS TRAD- WHT-GLD OAK-FULL FRAME INSTALL **Order Number:** 004 **Quote Number:** **19753775** **Order Type:** Installed Sales **Wall Depth:** **Payment Terms:** **Tax Code:** NALABOR **Cust Delivery Date:** None **Quoted Date:** 7/17/2025 **Contracted Date:** **Booked Date:** **Customer PO #:**

Accessories Managed / Delivery Date

Window Screens	1/1/0001	Hinge & Sliding Door Screens	1/1/0001	Window Hardware	1/1/0001

Customer Notes: Project Checklist - Please verify the following prior to ordering: FULL FRAME INSTALLATION INCLUDED - 2 YEAR CRAFTMANSHIP - 10 YEAR WATER INTRUSION
___Pella Brand (Model): RESERVE/LIFESTYLE TRADITIONAL - LIFETIME WOOD WARRANTY
___Exterior Color: WHITE
___Interior Color: GOLDEN OAK - TO BE APPROVED
___Insulated Glass Option: ANNEALED ADV LOW E
___Window Hardware Type & Color: BROWN - TO BE CONFIRMED
___Window Screen Type & Frame Color: BROWN - TO BE CONFIRMED
___Door Hardware Type & Color + Keyway:
___Door Screen: YES
___Grille Type:
___Grille Color (interior/exterior):
___Blinds/Shades: YES, MANUAL - GOLDEN (TBC)
___Jamb Extended Wall Depth: 6 11/16
___Hinging and Operation is viewed from the exterior, verified: TO BE CONFIRMED UPON ACCEPTANCE
___Casing: COLONIAL OAK PREFINISHED - GOLDEN OAK
NOTE: FULL FRAME INSTALLATION INCLUDES COMPLETE REMOVAL OF WINDOWS/DOORS, INSTALL NEW WINDOWS/DOORS AND NEW INTERIOR OAK CASINGS.

Line #	Location:	Attributes
10	LAUNDRY W 358,359	

Viewed From Exterior

PK #
2208

Lifestyle, Casement Left, With HGP, White

Item Price	Qty	Ext'd Price
$2,544.89	2	$5,089.78

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL11865, STC 32, OITC 26, Clear Opening Width 16.25, Clear Opening Height 35.875, Clear Opening Area 4.048394, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,

Line #	Location:	Attributes
15	Bedroom 1 W-360-362	

PK # 2208

Viewed From Exterior

Lifestyle, 3-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$8,170.87	1	$8,170.87

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11877
Grille: No Grille,
3: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical
Vertical Mull 2: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Customer Notes: EGRESS ACCESS REQUIRED

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
20	Foyer-W 363-365	**Architect Reserve, Traditional, Direct Set Fixed Frame Rectangle, Architect Reserve, Traditional, Direct Set Fixed Frame Springline, Architect Reserve, Traditional, Direct**	$7,113.40	1	$7,113.40

PK #
2208

Viewed From Exterior

1: Fixed Frame Direct Set
General Information: Interior Glazed, Factory Assembled, Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.28, SHGC 0.32, VLT 0.62, CPD PEL-N-18-04208-00001, Performance Class AW, PG 90, Calculated Positive DP Rating 90, Calculated Negative DP Rating 90, FPA FL10354, STC 27, OITC 22
Grille: No Grille,
2: Fixed Frame Direct Set Springline
General Information: Interior Glazed, Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.28, SHGC 0.29, VLT 0.55, CPD PEL-N-18-04209-00001, Performance Class AW, PG 85, Calculated Positive DP Rating 85, Calculated Negative DP Rating 85, FPA FL10354
Grille: GBG, No Custom Grille, 3/4" Contour, Sunburst (3W2H), Harvest, White
3: Fixed Frame Direct Set
General Information: Interior Glazed, Factory Assembled, Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.28, SHGC 0.32, VLT 0.62, CPD PEL-N-18-04208-00001, Performance Class AW, PG 90, Calculated Positive DP Rating 90, Calculated Negative DP Rating 90, FPA FL10354, STC 27, OITC 22
Grille: No Grille,
Vertical Mull 1: FactoryMull, Reinforcing Plate, Frame To Frame Width- 0", Mull Design Pressure- 20
Vertical Mull 2: FactoryMull, Reinforcing Plate, Frame To Frame Width- 0", Mull Design Pressure- 20

Line #	Location:	Attributes
25	Bedroom 2 W-366-368	

PK #
2208

Viewed From Exterior

Lifestyle, 3-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$8,170.87	1	$8,170.87

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11877
Grille: No Grille,
3: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical
Vertical Mull 2: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Customer Notes: EGRESS ACCESS REQUIRED

Line #	Location:	Attributes
30	Living W 218-223	



PK #
2208

Viewed From Exterior

Lifestyle, 3-Wide Casement, Pella Reserve, 3-Wide Sash Set, White

Item Price	Qty	Ext'd Price
$13,880.00	1	$13,880.00

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11877
Grille: No Grille,
3: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
4: SizeNon-Standard Size Fixed Sash Set
General Information: Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Sash / Panel: Putty Glaze, Ogee, Standard
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.27, SHGC 0.30, VLT 0.57, CPD PEL-N-1-59311-00001, Performance Class CW, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL31312

Grille: No Grille,
5: SizeNon-Standard Size Fixed Sash Set
General Information: Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Sash / Panel: Putty Glaze, Ogee, Standard
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.27, SHGC 0.30, VLT 0.57, CPD PEL-N-1-59311-00001, Performance Class CW, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL31312
Grille: No Grille,
6: SizeNon-Standard Size Fixed Sash Set
General Information: Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Sash / Panel: Putty Glaze, Ogee, Standard
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.27, SHGC 0.30, VLT 0.57, CPD PEL-N-1-59311-00001, Performance Class CW, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL31312
Grille: No Grille,
Horizontal Mull 1: FactoryMull, Reinforcing Plate, Frame To Frame Width- 0", Mull Design Pressure- 20, Overall Thru Direction- Horizontal
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Horizontal
Vertical Mull 2: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Horizontal
Vertical Mull 3: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Horizontal
Vertical Mull 4: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Horizontal

Customer Notes: EGRESS ACCESS REQUIRED

Line #	Location:	Attributes
35	Dining 215-217	

PK # 2208

Viewed From Exterior

Lifestyle, 3-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$8,170.87	1	$8,170.87

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11877
Grille: No Grille,
3: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical
Vertical Mull 2: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Customer Notes: EGRESS ACCESS REQUIRED

Line #	Location:	Attributes
40	Family W 378-382	

Viewed From Exterior

PK #
2208

Lifestyle, Sash Set, Fixed, With HGP, White

Item Price	Qty	Ext'd Price
$1,949.25	5	$9,746.25

1: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL11877
Grille: No Grille,

Line #	Location:	Attributes
45	Family W 229	

Viewed From Exterior

PK #
2208

Lifestyle, Casement Left, With HGP, White

Item Price	Qty	Ext'd Price
$2,814.90	1	$2,814.90

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL11865, STC 32, OITC 26, Clear Opening Width 12.25, Clear Opening Height 53.875, Clear Opening Area 4.583117, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,

Line #	Location:	Attributes
50	Family W 231-233	



PK # 2208

Viewed From Exterior

Lifestyle, 3-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$8,474.28	1	$8,474.28

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 40, Calculated Positive DP Rating 40, Calculated Negative DP Rating 40, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 53.875, Clear Opening Area 5.33138, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 40, Calculated Positive DP Rating 40, Calculated Negative DP Rating 40, FPA FL11877
Grille: No Grille,
3: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 40, Calculated Positive DP Rating 40, Calculated Negative DP Rating 40, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 53.875, Clear Opening Area 5.33138, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical
Vertical Mull 2: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Customer Notes: EGRESS ACCESS REQUIRED

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
55	Family W 234	**Lifestyle, Casement Right, With HGP, White**	$2,814.90	1	$2,814.90

Viewed From Exterior

PK #
2208

1: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL11865, STC 32, OITC 26, Clear Opening Width 12.25, Clear Opening Height 53.875, Clear Opening Area 4.583117, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
60	Family W 230	**Lifestyle, Casement Left, With HGP, White**	$2,814.90	1	$2,814.90

Viewed From Exterior

PK #
2208

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL11865, STC 32, OITC 26, Clear Opening Width 12.25, Clear Opening Height 53.875, Clear Opening Area 4.583117, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,

Line #	Location:	Attributes
65	Family W 234-236	



PK # 2208

Viewed From Exterior

Lifestyle, 3-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$8,474.28	1	$8,474.28

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 40, Calculated Positive DP Rating 40, Calculated Negative DP Rating 40, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 53.875, Clear Opening Area 5.33138, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 40, Calculated Positive DP Rating 40, Calculated Negative DP Rating 40, FPA FL11877
Grille: No Grille,
3: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 40, Calculated Positive DP Rating 40, Calculated Negative DP Rating 40, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 53.875, Clear Opening Area 5.33138, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical
Vertical Mull 2: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Customer Notes: EGRESS ACCESS REQUIRED

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
70	Family W 237	**Lifestyle, Casement Right, With HGP, White**	$2,814.90	1	$2,814.90

Viewed From Exterior

PK # 2208

1: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL11865, STC 32, OITC 26, Clear Opening Width 12.25, Clear Opening Height 53.875, Clear Opening Area 4.583117, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
75	Master W-383	**Lifestyle, Casement Left, With HGP, White**	$2,850.02	1	$2,850.02

Viewed From Exterior

PK # 2208

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 12.25, Clear Opening Height 55.875, Clear Opening Area 4.753255, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,

Line #	Location:	Attributes
80	Master W - 384	

Viewed From Exterior

Lifestyle, Sash Set, Fixed, With HGP, White

Item Price	Qty	Ext'd Price
$3,504.74	1	$3,504.74

PK #
2208

1: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.23, SHGC 0.26, VLT 0.48, CPD PEL-N-244-00365-00001, Performance Class CW, PG 35, Calculated Positive DP Rating 35, Calculated Negative DP Rating 35, FPA FL11877, STC 34, OITC 28
Grille: No Grille,

Line #	Location:	Attributes
85	Master W-385	

Viewed From Exterior

Lifestyle, Casement Right, With HGP, White

Item Price	Qty	Ext'd Price
$2,850.02	1	$2,850.02

PK #
2208

1: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 12.25, Clear Opening Height 55.875, Clear Opening Area 4.753255, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
90	Nook W-239	**Lifestyle, Casement Left, With HGP, White**	$2,850.02	1	$2,850.02

Viewed From Exterior

PK #
2208

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 12.25, Clear Opening Height 55.875, Clear Opening Area 4.753255, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
95	Nook SGD-3	**Lifestyle, Double Sliding Door, Contemporary, , Vent Right / Fixed, With HGP, White**	$13,078.13	1	$13,078.13

Viewed From Exterior

PK #
2208

1: SizeNon-Standard Size Vent Right / Fixed Double Sliding Door
Unit Type: No Program, Sliding Door (New)
General Information: No Package, With Hinged Glass Panel, Factory Assembled, Standard, Clad, Pine, 5 7/8", 4 9/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Sash / Panel: Square, Square
Glass: Insulated Tempered Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Tempered, Black
Frame Selection: Wood Trim Cover, Factory Applied
Hardware Options: Vent Lock, Black, Keylock Included, Standard, Handle Included, Handle Included, Brown, White, Random, Chrome, No Integrated Sensor
Screen: Sliding Screen, White, White, TuffScreen®
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.26, SHGC 0.26, VLT 0.48, CPD PEL-N-304-00286-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL47325, STC 34, OITC 29
Grille: No Grille,

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
100	Porch SGD-1	**Lifestyle, Double Sliding Door, Contemporary, , Vent Right / Fixed, With HGP, White**	$13,078.13	1	$13,078.13

Viewed From Exterior

PK #
2208

1: SizeNon-Standard Size Vent Right / Fixed Double Sliding Door
Unit Type: No Program, Sliding Door (New)
General Information: No Package, With Hinged Glass Panel, Factory Assembled, Standard, Clad, Pine, 5 7/8", 4 9/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Sash / Panel: Square, Square
Glass: Insulated Tempered Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Tempered, Black
Frame Selection: Wood Trim Cover, Factory Applied
Hardware Options: Vent Lock, Black, Keylock Included, Standard, Handle Included, Handle Included, Brown, White, Random, Chrome, No Integrated Sensor
Screen: Sliding Screen, White, White, TuffScreen®
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.26, SHGC 0.26, VLT 0.48, CPD PEL-N-304-00286-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL47325, STC 34, OITC 29
Grille: No Grille,

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
105	Porch W 240	**Lifestyle, Casement Left, With HGP, White**	$2,850.02	1	$2,850.02

Viewed From Exterior

PK #
2208

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 12.25, Clear Opening Height 55.875, Clear Opening Area 4.753255, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
110	Porch W 241	**Pella Reserve, Traditional Direct Set, Fixed Frame, White**	$3,148.15	1	$3,148.15

Viewed From Exterior

PK #
2208

1: Fixed Frame Direct Set
General Information: Interior Glazed, Factory Assembled, Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.27, SHGC 0.32, VLT 0.60, CPD PEL-N-18-04240-00001, Performance Class AW, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL10354, STC 28, OITC 24
Grille: No Grille,

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
115	Porch W 242	**Lifestyle, Casement Right, With HGP, White**	$2,850.02	1	$2,850.02

Viewed From Exterior

PK #
2208

1: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 12.25, Clear Opening Height 55.875, Clear Opening Area 4.753255, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,

Line #	Location:	Attributes
120	Porch W 243, 244	

Viewed From Exterior

PK #
2208

Lifestyle, 2-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$6,041.61	1	$6,041.61

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 35, Calculated Positive DP Rating 35, Calculated Negative DP Rating 35, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 59.875, Clear Opening Area 5.92513, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 35, Calculated Positive DP Rating 35, Calculated Negative DP Rating 35, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 59.875, Clear Opening Area 5.92513, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Line #	Location:	Attributes
125	Porch W 245, 246	

Viewed From Exterior

PK #
2208

Lifestyle, 2-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$6,041.61	1	$6,041.61

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 35, Calculated Positive DP Rating 35, Calculated Negative DP Rating 35, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 59.875, Clear Opening Area 5.92513, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 35, Calculated Positive DP Rating 35, Calculated Negative DP Rating 35, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 59.875, Clear Opening Area 5.92513, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Line #	Location:	Attributes
126	W-247-249	

Viewed From Exterior

PK #
2208

Lifestyle, Casement, Pella Reserve, Sash Set, White

Item Price	Qty	Ext'd Price
$4,389.11	1	$4,389.11

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, White, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL11865, STC 32, OITC 26, Clear Opening Width 21, Clear Opening Height 29.875, Clear Opening Area 4.356771, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
General Information: Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Sash / Panel: Putty Glaze, Ogee, Standard
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.27, SHGC 0.30, VLT 0.57, CPD PEL-N-1-59311-00001, Performance Class CW, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL31312
Grille: No Grille,
Horizontal Mull 1: FactoryMull, Standard Joining Mullion, Frame To Frame Width- 0", Mull Design Pressure- 20

Line #	Location:	Attributes
127	W-247-249	

Viewed From Exterior

PK #
2208

Lifestyle, Casement, Pella Reserve, Sash Set, White

Item Price	Qty	Ext'd Price
$4,389.11	1	$4,389.11

1: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, White, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL11865, STC 32, OITC 26, Clear Opening Width 21, Clear Opening Height 29.875, Clear Opening Area 4.356771, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
General Information: Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Sash / Panel: Putty Glaze, Ogee, Standard
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.27, SHGC 0.30, VLT 0.57, CPD PEL-N-1-59311-00001, Performance Class CW, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL31312
Grille: No Grille,
Horizontal Mull 1: FactoryMull, Standard Joining Mullion, Frame To Frame Width- 0", Mull Design Pressure- 20

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
130	Misc W 386	**Lifestyle, Casement Right, With HGP, White**	$2,898.48	1	$2,898.48

Viewed From Exterior

PK #
2208

1: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 24.25, Clear Opening Height 43.875, Clear Opening Area 7.388672, Egress Meets minimum clear opening and 5.7 sq.ft
Grille: No Grille,

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
135	Misc W 387	**Lifestyle, Sash Set, Fixed, With HGP, White**	$2,657.83	1	$2,657.83

Viewed From Exterior

PK #
2208

1: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11877
Grille: No Grille,

Line #	Location:	Attributes
140	Bedroom 3 W-388-390	

PK # 2208

Viewed From Exterior

Lifestyle, 3-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$8,170.87	1	$8,170.87

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11877
Grille: No Grille,
3: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical
Vertical Mull 2: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Customer Notes: EGRESS ACCESS REQUIRED

Line #	Location:	Attributes
145	Office W 251-253	

PK # 2208

Viewed From Exterior

Lifestyle, 3-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$8,170.87	1	$8,170.87

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11877
Grille: No Grille,
3: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical
Vertical Mull 2: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Line #	Location:	Attributes
150	Bedroom 5 W11-113	

Lifestyle, 3-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$8,170.87	1	$8,170.87

PK #
2208

Viewed From Exterior

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11877
Grille: No Grille,
3: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical
Vertical Mull 2: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Customer Notes: EGRESS ACCESS REQUIRED

Line #	Location:	Attributes
155	W254/255/256/257	

Viewed From Exterior

PK # 2208

Lifestyle, 2-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$5,382.90	2	$10,765.80

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 43.875, Clear Opening Area 4.341797, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 50, Calculated Positive DP Rating 50, Calculated Negative DP Rating 50, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 43.875, Clear Opening Area 4.341797, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
160	South W 375-377	**Architect Reserve, Traditional, Direct Set Fixed Frame Rectangle, Architect Reserve, Traditional, Direct Set Fixed Frame Springline, Architect Reserve, Traditional, Direct**	$6,713.00	1	$6,713.00

PK #
2208

Viewed From Exterior

1: Fixed Frame Direct Set
General Information: Interior Glazed, Factory Assembled, Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.28, SHGC 0.32, VLT 0.62, CPD PEL-N-18-04208-00001, Performance Class AW, PG 90, Calculated Positive DP Rating 90, Calculated Negative DP Rating 90, FPA FL10354, STC 27, OITC 22
Grille: No Grille,
2: Fixed Frame Direct Set Springline
General Information: Interior Glazed, Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.28, SHGC 0.32, VLT 0.62, CPD PEL-N-18-04208-00001, Performance Class AW, PG 85, Calculated Positive DP Rating 85, Calculated Negative DP Rating 85, FPA FL10354
Grille: No Grille,
3: Fixed Frame Direct Set
General Information: Interior Glazed, Factory Assembled, Standard, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Painted, Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Dual Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Performance Information: U-Factor 0.28, SHGC 0.32, VLT 0.62, CPD PEL-N-18-04208-00001, Performance Class AW, PG 90, Calculated Positive DP Rating 90, Calculated Negative DP Rating 90, FPA FL10354, STC 27, OITC 22
Grille: No Grille,
Vertical Mull 1: FactoryMull, Reinforcing Plate, Frame To Frame Width- 0", Mull Design Pressure- 20
Vertical Mull 2: FactoryMull, Reinforcing Plate, Frame To Frame Width- 0", Mull Design Pressure- 20

Line #	Location:	Attributes
165	South W 372-374	

PK #
2208

Viewed From Exterior

Lifestyle, 3-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$8,170.87	1	$8,170.87

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Mocha, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Mocha, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11877
Grille: No Grille,
3: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Mocha, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical
Vertical Mull 2: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Line #	Location:	Attributes
170	South W 372-374	

PK # 2208

Viewed From Exterior

Lifestyle, 3-Wide Casement, With HGP, White

Item Price	Qty	Ext'd Price
$8,587.52	1	$8,587.52

1: SizeNon-Standard Size Left Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
2: SizeNon-Standard Size Fixed Sash Set
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Brown
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.22, SHGC 0.27, VLT 0.50, CPD PEL-N-244-00361-00001, Performance Class CW, PG 40, Calculated Positive DP Rating 40, Calculated Negative DP Rating 40, FPA FL11877
Grille: No Grille,
3: SizeNon-Standard Size Right Casement
Unit Type: No Program
General Information: No Package, With Hinged Glass Panel, Clad, Pine, 5", 3 11/16"
Exterior Color / Finish: Standard Enduraclad, White
Interior Color / Finish: Golden Oak Stain Interior
Glass: Insulated Low-E Advanced Low-E Insulating Glass Argon Non High Altitude
Hinge Panel: Clear, Annealed
Hardware Options: Wash Hinge Hardware, Fold-Away Crank, Brown, No Window Opening Control Device, No Limited Opening Hardware, No Integrated Sensor
Screen: Full Screen, Brown, InView™
Unit Accessories: Snap-In Between-The-Glass Blind Bottom-Up, Golden, Manual
Performance Information: U-Factor 0.24, SHGC 0.27, VLT 0.50, CPD PEL-N-245-00361-00001, Performance Class LC, PG 45, Calculated Positive DP Rating 45, Calculated Negative DP Rating 45, FPA FL11865, STC 32, OITC 26, Clear Opening Width 14.25, Clear Opening Height 47.875, Clear Opening Area 4.73763, Egress Does not meet typical United States egress, but may comply with local code requirements
Grille: No Grille,
Vertical Mull 1: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical
Vertical Mull 2: FactoryMull, Standard Joining Mullion, Mull Design Pressure- 20, Overall Thru Direction- Vertical

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
175	INSTALLATION LABOR	**LABOR FOR WINDOW, DOORS, INTERIOR CASING, REMOVAL, INSTALL...**	$51,452.94	1	$51,452.94

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
180	CASING ALL WINDOW/DR	**Wood Products 2 1/2 Colonial 1, Length: 96, Golden Oak Stain. Wood Type: Oak**	$106.48	99	$10,541.52

PK #
2208

1: Accessory
General Information: Oak, 2 1/2 Colonial 1
Interior Color / Finish: Golden Oak Stain Interior

Viewed From Exterior

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
185	LIFT 5-7DAYS	**ON SITE LIFT- 5 TO 7 DAYS**	$3,417.98	1	$3,417.98

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
190	CUSTOM ARCH	**CUSTOM ARCH TOP X 2**	$2,062.71	1	$2,062.71

Line #	Location:	Attributes	Item Price	Qty	Ext'd Price
195	HARDWARE/SCREENS	**SHOPWOMINM900008 - Tier 3 VIP Services >15 Units**	$3,200.00	1	$3,200.00

Customer Notes: PELLA TO INSTALL HARDWARE, SCREENS AFTER INSTALLATION PROCESS

Thank You For Your Interest In Pella® Products

PELLA WARRANTY:

Pella products are covered by Pella's limited warranties in effect at the time of sale. All applicable product warranties are incorporated into and become a part of this contract. Please see the warranties for complete details, taking special note of the two important notice sections regarding installation of Pella products and proper management of moisture within the wall system. Neither Pella Corporation nor the Seller will be bound by any other warranty unless specifically set out in this contract. However, Pella Corporation will not be liable for branch warranties which create obligations in addition to or obligations which are inconsistent with Pella written warranties.

Clear opening (egress) information does not take into consideration the addition of a Rolscreen [or any other accessory] to the product. You should consult your local building code to ensure your Pella products meet local egress requirements.

Per the manufacturer's limited warranty, unfinished mahogany exterior windows and doors must be finished upon receipt prior to installing and refinished annually, thereafter. Variations in wood grain, color, texture or natural characteristics are not covered under the limited warranty.

INSYNCTIVE PRODUCTS: In addition, Pella Insynctive Products are covered by the Pella Insynctive Products Software License Agreement and Pella Insynctive Products Privacy Policy in effect at the time of sale, which can be found at Insynctive.pella.com. By installing or using Your Insynctive Products you are acknowledging the Insynctive Software Agreement and Privacy Policy are part of the terms of sale.

Notice of Collection of Personal Information: We may collect your personal information when you interact with us. Under the California Consumer Privacy Act (CCPA), California residents have specific rights to request this information, request to delete this information, and opt out of the sharing or sale of this information to third parties. To learn more about our collection practices and your rights under the CCPA please visit our link https://www.pella.com/california-rights-policy/ at pella.com.

ARBITRATION AND CLASS ACTION WAIVER ("ARBITRATION AGREEMENT")

YOU and Pella and its subsidiaries and the Pella Branded Distributor **AGREE TO ARBITRATE DISPUTES ARISING OUT OF OR RELATING TO YOUR PELLA PRODUCTS (INCLUDES PELLA GOODS AND PELLA SERVICES) AND WAIVE THE RIGHT TO HAVE A COURT OR JURY DECIDE DISPUTES. YOU WAIVE ALL RIGHTS TO PROCEED AS A MEMBER OR REPRESENTATIVE OF A CLASS ACTION, INCLUDING CLASS ARBITRATION, REGARDING DISPUTES ARISING OUT OF OR RELATING TO YOUR PELLA PRODUCTS.** You may opt out of this Arbitration Agreement by providing notice to Pella no later than ninety (90) calendar days from the date You purchased or otherwise took ownership of Your Pella Goods. To opt out, You must send notice by e-mail to pellawebsupport@pella.com , with the subject line: "Arbitration Opt Out" or by calling (877) 473-5527. Opting out of the Arbitration Agreement will not affect the coverage provided by any applicable limited warranty pertaining to Your Pella Products. For complete information, including the full terms and conditions of this Arbitration Agreement, which are incorporated herein by reference, please visit www.pella.com/arbitration or e-mail to pellawebsupport@pella.com, with the subject line: "Arbitration Details" or call (877) 473-5527. D'ARBITRAGE ET RENONCIATION AU RECOURS COLLECTIF ("convention d'arbitrage") EN FRANÇAIS SEE PELLA.COM/ARBITRATION. DE ARBITRAJE Y RENUNCIA COLECTIVA ("acuerdo de arbitraje") EN ESPAÑOL VER PELLA.COM/ARBITRATION.

Seller shall not be held liable for failure or delay in the performance of its obligations under this Agreement, if such performance is hindered or delayed by the occurrence of an act or event beyond the Seller's reasonable control (force majeure event), including but not limited to earthquakes, unusually severe weather and other Acts of God, fire, strikes and labor unrest, epidemics, riots, war, civil unrest, and government interventions. Seller shall give timely notice of a force majeure event and take such reasonable action to mitigate the impacts of such an event.

Product Performance Information:

U-Factor, Solar Heat Gain Coefficient (SHGC), and Visible Light Transmittance (VLT) are certified by the National Fenestration Rating Council (NFRC).

Manufacturer stipulates that these ratings conform to applicable NFRC procedures for determining whole product performance. NFRC ratings are determined for a fixed set of environmental conditions and a specific product size. NFRC does not recommend any products and does not warrant the suitability of any product for any specific use.

Design Pressure (DP), Performance Class, and Performance Grade (PG) are certified by a third party organization, in many cases the Window and Door Manufacturers Association (WDMA). The certification requires the performance of at least one product of the product line to be tested in accordance with the applicable performance standards and verified by an independent party. The certification indicates that the product(s) of the product line passed the applicable tests. The certification does not apply to mulled and/or product combinations unless noted. Actual product results will vary and change over the products life.

For more performance information along with information on Florida Product Approval System (FPAS) Number and Texas Dept. of Insurance (TDI) number go to www.pella.com/performance.

Including during the construction period, casement windows should never be left open and unlocked for prolong periods or during high wind conditions to avoid sash detachment/damage.

Actual sizes tested for documented STC and OITC ratings may vary from the ASTM E 1425 sizes to better represent Pella product offering.

STC and OITC ratings shown may be conservatively based on products tested with thinner panes of glass.

STC and OITC ratings may be from test results from an equivalent product.

BRANCH WARRANTY:

TERMS & CONDITIONS:
Quotes valid for 30 days.

Order Totals	
Taxable Subtotal	$236,799.21
Sales Tax @ 0%	$0.00
Non-taxable Subtotal	$54,652.94
Total	$291,452.15
Deposit Received	$0.00
Amount Due	**$291,452.15**

Pure Co Roofing LLC

16471 Territorial Trl
Maple Grove, MN 55369

Insured:	Bill Lu
Property:	17756 George Moran Drive Eden Prairie, MN 55347

Claim Number:	**Policy Number:**	**Type of Loss:**

Date of Loss:		Date Received:	
Date Inspected:		Date Entered:	8/5/2025 1:32 PM

Price List:	MNMN8X_AUG25 Restoration/Service/Remodel
Estimate:	X-252246_LU-1

Pure Co Roofing LLC

16471 Territorial Trl
Maple Grove, MN 55369

X-252246_LU-1

Siding

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
1. R&R Siding - cedar shingle	1.00 SF	16.41	0.72	3.42	20.55	(0.00)	20.55
2. Clean with pressure/chemical spray	3,470.00 SF	0.50	180.45	347.60	2,263.05	(0.00)	2,263.05
3. Seal & paint wood siding	3,470.00 SF	2.61	174.53	1,846.24	11,077.47	(0.00)	11,077.47
4. Scaffold - per section (per day)	12.00 DA	27.74	0.00	66.58	399.46	(0.00)	399.46
For three sections for a week							
5. Labor to set up and take down scaffold - per section	12.00 EA	41.86	0.00	100.46	602.78	(0.00)	602.78
Totals: Siding			**355.70**	**2,364.30**	**14,363.31**	**0.00**	**14,363.31**

Windows

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
6. Windows - Aluminum (Bid Item)	1.00 EA	291,452.15	0.00	58,290.44	349,742.59	(0.00)	349,742.59
Totals: Windows			**0.00**	**58,290.44**	**349,742.59**	**0.00**	**349,742.59**

Debris Removal

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
7. Dumpster load - Approx. 12 yards, 1-3 tons of debris	1.00 EA	570.00	0.00	114.00	684.00	(0.00)	684.00
Totals: Debris Removal			**0.00**	**114.00**	**684.00**	**0.00**	**684.00**

Labor Minimums Applied

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	O&P	RCV	DEPREC.	ACV
8. Siding labor minimum	1.00 EA	503.07	0.00	100.62	603.69	(0.00)	603.69
Totals: Labor Minimums Applied			**0.00**	**100.62**	**603.69**	**0.00**	**603.69**
Line Item Totals: X-252246_LU-1			**355.70**	**60,869.36**	**365,393.59**	**0.00**	**365,393.59**

FIE 0671

Pure Co Roofing LLC

16471 Territorial Trl
Maple Grove, MN 55369

Summary for Dwelling

Line Item Total	304,168.53
Matl Sales Tax Reimb	178.21
Subtotal	304,346.74
Overhead	30,434.68
Profit	30,434.68
Cleaning Sales Tax	177.49
Replacement Cost Value	**$365,393.59**
Net Claim	**$365,393.59**