Direct Inspection

Prepared by Hancock Claims Consultants

INSPECTED BY
Jayden Grimm Tel: (507) 327-2595, **08/29/2024 9:00 AM**, 75°F

LOSS LOCATION	INSURED	CARRIER
11756 GEORGE MORAN DR EDEN PRAIRIE, Minnesota 55347-2163	YIBIAO LU	Farmers
PRESENT AT INSPECTION	**ADJUSTER**	**CLAIM NUMBER**
Insured,	Christian Dudley	7007986837-1

Property Overview

Roof

The structure assessed was a **story structure with a style roof** with the following predominant pitches:

- Front Pitch: **N/A**
- Left Pitch: **N/A**
- Back Pitch: **N/A**
- Right Pitch: **N/A**

The roof was comprised of a **(NA) shingle system.** The entirety of the roof system was inspected for wind related damages finding no damages.Hail test squares were conducted on each directional slope finding no hail strikes within nor to any other field shingles. No prior repairs were observed.

Elevation

A walk around inspection of all elevations was completed.

No sudden loss created damages.

Other areas of concern if any are noted in the additional summary.

Storm Info

Storm Damage Present: No
N/A

Non Storm Related Damage

N/A

Roof - Hail

Hail damage to a composition shingle roof system consists of bruising or fracturing of the shingle mat. Bruising is most common at unsupported locations and usually requires manual examination to confirm that damage has occurred to the shingle mat. Fracturing typically occurs at unsupported locations and is readily evident. These conditions can promote the absorption of moisture and subsequent deterioration of a shingle. Hail damage to a roof is quantified by the analysis of "test squares" (10' x 10' Area). The purpose of the test squares is to determine the amount of hail damage in a representative area of the roof. The test square results are then applied to individual roof fields, or the roof as a whole, to estimate the total damage incurred. Protocol calls for the examination of four (4) test squares ▌One (1) facing each direction. Larger and/or more complex roofs typically require additional test squares at the discretion of the adjuster. Additionally, a cursory overview of the remainder of each field is conducted to confirm the findings of the test squares.

Roof - Wind

Wind damage to an asphalt composition shingle consists of; creasing, tearing, complete detachment, and impacts from wind driven objects. Wind damage totals are acquired on a shingles damaged per slope basis.

Roof - Metal Accessory Items

Metal roof accessory items rarely suffer functional damage from hail impact. However, hail may cause aesthetic damage in the form of indentations. Rooftop penetrations can offer clear and permanent indications of hailstone impacts, including hail size and direction of the hail fall. Light gauge metal items will often suffer indentations even when the roofing material escapes damage.

Additional Summary

NA

Inspection Summary

Slope/Direction	Hail Damage +	Wind Damage	Other Damage
Front Slope/South		0	
Back Slope/North		0	
Left Slope/West		0	
Right Slope/East		0	

Roof Summary

Category	Description
Roof Type	
Roof Material	
Ice and Water	No
Valley Type	
Universal Starter	No
Rake	No
Felt Paper	
Shingle Exposure	NA
Shingle Width	0 (in)
Tarp Install	No
Soffit Depth	0 (in)
Outside Adjuster Present	No
Outside Adjuster Present on Roof	NA
Public Adjuster Present	No
Public Adjuster Present On Roof	NA
Insured Present	Yes
Contractor Present	No
Contractor Present On Roof	NA
Eagle View Provided	NA
LA Arrived On Time	NA
LA Accompanied OA	NA


Roof Components

Roof Component	Quantity	Qty Dmg	Painted	Material

Collateral Section - Front/South, Back/North, Left/West, Right/East

Collateral	Damage	Damage Amount	Size	Material	Additional Notes

Hancock
Claims Consultants



Ridge Shingle	Chimney Flashing	Hail	Wind	Shingle	Pitch	Vents		Misc	
HI PRO	LARGE	N 0	N 0	20 yr 3 Tab Comp	0/12	Box P/NP	0	Pipe Boot P/NP	0
Valley Metal	Fascia Material	S 0	S 0	25 yr 3 Tab Comp	# Layers	Turbine P/NP	0	HVAC Cap P/NP	0
N/A	6" Alum	E 0	E 0	25 yr 3 tab Organic	1	Power P/NP	0	Satellite	0
Drip Edge P/NP	Gutter P/NP	W 0	W 0	30 yr Laminate	Ice & Water Shield	Ridge Vent	0 l.f.	Mast Head	0
YES	5"Alum			40 yr Laminate	YES	Off Ridge	0	Skylight	0
Soffit Overhang	Gutter Guard P/NP	Total Roof Sq.		50 yr Laminate	Felt Paper	Dryer Vent	0	Gooseneck P/NP	0
12"	N/A	NA			15 lbs.				

Roof Age :11-15years

× = Wind Damage = Water Leak = Repair

= GUTTER = RIDGE VENT = STORM RELATED DAMAGE



Front ↓ Risk

Hancock
Claims Consultants

Inspection Photos

Service Date: **08/29/2024 9:00 AM**

Claim Number: **7007986837-1**

Insured: **YIBIAO LU**

1. Address

