

Farbübersetzung HKS-K zu AMANN ISACORD

11170		1010077
HKS		ISACORD
1 K	=	0630
2 K	=	0600
3 K	=	0605
4 K	=	0700
5 K	=	0702
6 K	~	0904
7 K	~	1102
8 K	=	1300
10 K	=	1305
11 K	~	1352
12 K	~	(1305)
13 K	=	1703
14 K	=	1704
15 K	=	1904
16 K	=	1913
17 K	=	2011
18 K	=	2222
21 K	~	(1840)
22 K	~	1701
23 K	=	1903
24 K	~	2320
25 K	=	2320
26 K	~	2300
27 K	~	(2300)
28 K	=	1906
29 K	=	2720
31 K	~	(2300)
32 K	=	2521
33 K	~	2704
34 K	~	2900
35 K	~	3541
36 K	=	2900
37 K	=	2900
38 K	=	3444
39 K	~	3522
40 K	~	(3901)
41 K	=	3444
42 K	=	3544
43 K	~	3522
44 K	~	(3902)
45 K	~	3210
46 K	~	3901
47 K	~	3901
48 K	=	4103

HKS		ISACORD
49 K	~	4103
50 K	=	4113
51 K	~	4423
52 K	~	5100
53 K	~	(5210)
54 K	=	5515
55 K	=	5100
56 K	=	5335
57 K	=	5415
58 K	=	5643
59 K	=	4410
60 K	=	5513
61 K	=	5944
62 K	=	5934
63 K	=	5633
64 K	=	5510
65 K	~	5500
66 K	=	5912
67 K	~	(5830)
68 K	=	0221
69 K	~	0221
71 K	=	0821
72 K	~	0940
73 K	~	0932
74 K	~	0941
75 K	=	0345
76 K	~	1055
77 K	=	1355
78 K	=	1342
81 K	=	1114
82 K	=	1334
83 K	=	1344
84 K	=	1355
88 K	=	0020
89 K	~	0763
90 K	~	1375
91 K	~	(0142)
92 K	=	0111
93 K	=	0132
95 K	~	0873
96 K	~	0152
97 K	~	1375
98 K	~	0934
99 K	~	0131

98 K = ISAMET metallic 0500 (best) 99 K = ISAMET metallic 0511 (best)