

HYDERABAD DISASTER RESPONSE & ASSET PROTECTION AGENCY
ENQUIRY REPORT

Petition No : _____ Date: _____

Enquiry Officer & Rank : _____

Type of Encroachment : Park/Nala/Lake/Govt Land/Openspace/FTL/Buffer Zone/Road

Time limit of Enquiry : Immediate/Priority/Normal/_____.

Type of petition : Individual/Association/official/Public/representative/others.

1.	Name & Address of the petitioner:
2.	Name & Address of the Respondent:
3.	Brief facts of the complaint:
4.	Location of encroachment:
5.	Field Visit Date:
6.	Any Court cases pending:
7.	<p>Preliminary Enquiry Findings of the IO:</p> <p style="text-align: center;">Signature, EO, APC SEZ, HYDRAA.</p> <p style="text-align: right;">Signature, I/C, APC, HYD, HYDRAA.</p>
8.	<p>Orders of the Additional Commissioner</p> <p style="text-align: right;">Signature. Additional, Commissioner</p>
9.	<p>Orders of the Commissioner:</p> <p style="text-align: right;">Signature. HYDRAA, Commissioner</p>

HYDERABAD DISASTER RESPONSE & ASSET PROTECTION AGENCY
ENQUIRY REPORT

Petition No
Enquiry Officer& Rank
Type of Encroachment
Time limit for Enquiry
Type of Petition

:17/2025/RAC/HYDRAA
: Sri. M. Bachi Reddy (FRO).
: Encroachment of Lake.
: Priority.
: Individual.

Dt: 20-01-2025.

1.	Name & Address of the petitioner:	Murthy
2.	Name & Address of the Respondent:	Nil
3.	Brief facts of the complaint:	Encroachment of Nala and Buffer Zone of Kaprai Lake (Kappala Cheruvu) situated at Saheb Nagar Kalan, Hayathnagar Mandal, Ranga Reddy District.
4.	Location of encroachment:	Saheb Nagar Kalan, Hayathnagar Mandal, Ranga Reddy District.
5.	Field Visit Date:	22.01.2025
6.	Any Court cases pending:	Nil
7.	Preliminary Enquiry Findings of the IO: During the site inspection, it was observed that that the main bund of kaprai cheruvu on the right side was not existing on the site and it was levelled to the ground level to a length of approx. 30meters.there were houses on the upstream side. A significant portion of the lake area had been occupied and developed into Harihara Puram Colony, resulting in the lake being reduced to a much smaller area. A new bund has been constructed around the remaining lake portion, along with the development of a green belt. Additionally, an underground Nala has been constructed to facilitate the discharge of water from the existing lake. It was further observed that the Nala constructed for water discharge is narrower than the approved specifications, with a width of only 3 meters. This could affect the flow capacity and drainage efficiency, especially during periods of heavy rainfall. In response to these findings, a letter was addressed to the Executive Engineer, North Tank Division, Irrigation and CAD Department, requesting the demarcation of the levelled bund area on the ground. And the identity of the encroachers and any plots that may have been developed on the bund, to enable further necessary action. As seen from the reply furnished by the irrigation Officials, it was revealed that Sri Sudhir goud & others are trespassed and damaged the main bund for making house sites and an FIR had been registered in the police station of Vanasthalipuram by irrigation dept against the encroachers. It is also noted that preliminary notification (P.N.) for the lake was issued, and presently, houses exist on approximately two-thirds of the notified original lake area and a joint survey of the levelled bund area to retrieve the area is pending and awaited report from the irrigation dept.	
	Signature, EO, APC SEZ, HYDRAA.	Signature, I/C, APC, HYD, HYDRAA.
8.	Orders of the Additional Commissioner	Signature. Additional, Commissioner

9.	<p>Orders of the Commissioner:</p> <p style="text-align: right;">Signature. HYDRAA, Commissioner</p>
----	--