




SURGE SHORETM

POWERTECH LLP

*Driving
Performance*







SURGE SHORE™
POWERTECH LLP

An iso 9001:2015 certified company

MES MODEL 2 POLE - 3000 RPM



Model	K.W	HP	A	B	C	D	E	F	OH	M	CENTRIFUGAL FORCE(N)	WEIGHT OF MOTOR (KG)
MES 0.18	0.18	0.25	250	170	155	95	130	26	4 X 11	125	2500	7







SURGE SHORE™
POWERTECH LLP

An iso 9001:2015 certified company

MES MODEL 2 POLE - 3000 RPM



Model	K.W	HP	A	B	C	D	E	F	OH	M	CENTRIFUGAL FORCE(N)	WEIGHT OF MOTOR (KG)
MES 0.37	0.37	0.5	280	190	160	70	131	20	4 X 11	100	3500	11







SURGE SHORE™
POWERTECH LLP

An iso 9001:2015 certified company

MES MODEL 2 POLE - 3000 RPM



Model	K.W	HP	A	B	C	D	E	F	OH	M	CENTRIFUGAL FORCE(N)	WEIGHT OF MOTOR (KG)
MES 0.75	0.75	1	340	215	210	70	170	25	4 X 13	105	8000	16







SURGE SHORE™
POWERTECH LLP

An iso 9001:2015 certified company

MES MODEL 2 POLE - 3000 RPM



Model	K.W	HP	A	B	C	D	E	F	OH	M	CENTRIFUGAL FORCE(N)	WEIGHT OF MOTOR (KG)
MES 1.5	1.5	2	390	230	230	145	195	50	4 X 16	190	15800	38



How To Choose A Vibromotor

$$F_c = \frac{m_u \cdot e \cdot w^2}{1000}$$

$$w = 2\pi f_m$$

$$F_m = \frac{1}{n_s}$$

F_c = Centrifugal Force (Vibrating Force) IN KN

M_u = Mass Of The Eccentric Disc In Kg

E = Distance From The Centre Of Gravity To The Centre Of Motion In (m)

W = Angular Speed Of Motor Eccentric In 1/s

F_m = Mechanical Frequency

N_s = Motor Speed In Rpm



SCAN FOR LOCATION



SURGE SHORETM
POWERTECH LLP

Address. Plot No. 1/7, Copper Ind. Area, Nr. Korat Chowk,
Rajkot, Gujarat - 360022

w. www.surgeshorepowertech.com

E. Surgeshorepowertech@gmail.com

Contact. +91 91739 59019