


Strain at sensor T11 due to Truck 1 moving across bridge 705



Strain at sensor T12 due to Truck 1 moving across bridge 705

