


Strain at sensor T2 due to Truck 1 moving across bridge 705



Strain at sensor T3 due to Truck 1 moving across bridge 705

