


Strain at sensor T14 due to Truck 1 moving across bridge 705



Strain at sensor T15 due to Truck 1 moving across bridge 705

