


Strain at sensor T5 due to Truck 1 moving across bridge 705



Strain at sensor T6 due to Truck 1 moving across bridge 705

