


Strain at sensor O4 due to Truck 1 moving across bridge 705



Strain at sensor O9 due to Truck 1 moving across bridge 705

