
Physical Security Assessment

February 6, 2026

Overview

The _____ has been studying locksmithing and has developed some skill in assessment of defenses against burglarious attacks such as lockpicking, lock bypass, and destructive entry. Applying these new skills, they performed an assessment of the physical security of _____. This assessment took place on February 4, 2026.

This assessment was performed by _____ through visual inspection and non-destructive offensive testing of doors and door locks. Included in the scope of this assessment are all doors and door locks which pertain to _____ or to spaces shared by _____. Excluded from the assessment are all doors and door locks which pertain to _____, all cabinets and cabinet locks, and all software-based access controls.

Results

The assessors determined that the building is in general adequately secured, with good locks and appropriate fortifications. However, they found two notable weaknesses:

1. _____ – Latch Subject to Loiding & Accelerated Wear
2. Exterior Doors – Lock Cylinders Unprotected from Wrenching

Weakness 1: _____ – Latch Subject to Loiding & Accelerated Wear

The door to _____ has an alignment problem. Whereas the main part of the latch is meant to enter the strike hole, the *deadlatch pin* is meant not to. As currently aligned, the deadlatch pin enters the strike hole whenever an attacker pulls on the handle or whenever the door is forcefully closed.

Impact

High severity. This makes the lock vulnerable to “loiding”. That is, an attacker can forcibly retract the latch with a flexible celluloid card (such as a credit card or a hotel key), gaining unauthorized access to _____. It also subjects the lock to accelerated wear as the extended deadlatch pin binds against the strike plate, leading to premature lock failure.

Recommendation

Replace or modify the strike plate, or thicken the vertical weather strip, such that pulling on the outside handle or forcefully closing the door cannot cause the deadlatch to enter the strike hole.

Weakness 2: Exterior Doors – Lock Cylinders Unprotected from Wrenching

The rim cylinder in each of the exterior doors, including those with key-operated cylinders and those with dummy cylinders, lacks the anti-wrench collar that is customarily placed on them for protection against forced entry.

Impact

Medium severity. Without an anti-wrench collar, these lock cylinders are easily removed by an attacker with a pipe wrench or large channel-lock pliers. Once a cylinder is removed, gaining unauthorized access to _____ is as simple as _____.

Recommendation

Install an anti-wrench collar on each exterior rim cylinder – both on key-operated cylinders and on dummy cylinders.