## TEMPERATURE AND HUMIDITY CHECK

## **WOKWI LINK:**

https://wokwi.com/projects/364984991429628929


## PROGRAM:

```
import random import time from machine import
Pin, PWM, ADC         TEMP_THRESHOLD
= 30
HUMIDITY_THRESHOLD = 70

BUZZER_PIN = 5
BUZZER_FREQ = 2000 BUZZER_DUTY = 512 buzzer =
PWM(Pin(BUZZER_PIN), freq=BUZZER_FREQ, duty=0)
```

```
HUMIDITY_PIN = 34 TEMPERATURE_PIN
= 35 adc = ADC(Pin(HUMIDITY_PIN))
adc.atten(ADC.ATTN 11DB)
                   temperature = random.uniform(10,
while True:
       humidity = adc.read()
45)
                      print("Temperature:
/ 4095 * 100
{:.2f} C, Humidity: {:.2f}
%".format(temperature, humidity))
   if temperature > TEMP_THRESHOLD or humidity >
                      print("ALARM! Temperature or Humidity
HUMIDITY THRESHOLD:
is too high!")
buzzer.duty(BUZZER_DUTY)
                               time.sleep(0.5)
buzzer.duty(0)
                      time.sleep(0.5)
                                          time.sleep(1)
```

## CONNECTION DIAGRAM:



OUTPUT:

```
Temperature: 19.46 C, Humidity: 48.69 % Temperature: 25.74 C, Humidity: 44.00 % Temperature: 25.98 C, Humidity: 46.30 % Temperature: 21.86 C, Humidity: 47.77 % Temperature: 10.09 C, Humidity: 49.89 %
Temperature: 15.45 C, Humidity: 47.06 %
Temperature: 33.75 C, Humidity: 51.75 %
ALARM! Temperature or Humidity is too high!
Temperature: 15.60 C, Humidity: 55.07 %
Temperature: 38.41 C, Humidity: 53.68 %
ALARM! Temperature or Humidity is too high!
Temperature: 30.46 C, Humidity: 49.79 %
ALARM! Temperature or Humidity is too high!
Temperature: 25.62 C, Humidity: 51.77 %
Temperature: 21.74 C, Humidity: 50.26 %
Temperature: 16.44 C, Humidity: 47.30 %
Temperature: 24.02 C, Humidity: 49.43 %
Temperature: 21.18 C, Humidity: 48.55 %
Temperature: 10.50 C, Humidity: 46.69 %
Temperature: 30.29 C, Humidity: 44.86 %
ALARM! Temperature or Humidity is too high!
Temperature: 38.00 C, Humidity: 46.50 %
ALARM! Temperature or Humidity is too high!
Temperature: 36.55 C, Humidity: 47.13 %
ALARM! Temperature or Humidity is too high!
Temperature: 40.82 C, Humidity: 43.81 %
ALARM! Temperature or Humidity is too high!
Temperature: 40.92 C, Humidity: 47.28 %
```