## Jesse Mayer

16886	wiayei							
					HW#3			
2.a.	LDR	R0,=0	b.	LDR	R0,=0	c.	LDR	R0,=0
	STRB	R0,u8		STRH	R0,u16		STR	R0,u32
	BX	LR		BX	LR		BX	LR
d.	LDRD	R0,R1,=0	e.	LDRB	R0,u8	f.	LDRB	R0,u8
	STRD	R0,R1,u64		STRH	R0,u16		STR	R0,u32
	BX	LR		BX	LR		BX	LR
g.	LDRH	R0,u16	h.	LDR	R0,u32	i.	LDRB	R0,u32
	STR	R0,u32		LDR	R1,=0		STRB	R0,u8
	BX	LR		STRD	R0,R1,u64		BX	LR
				BX	LR			
j.	LDRB	R0,u16	k.	LDRH	R0,u32			
	STRB	R0,u8		STRH	R0,u16			
	BX	LR		BX	LR			
3.a.	LDR	R0,=-1	b.	LDR	R0,=-1	c.	LDR	R0,=-1
	STRB	R0,s8		STRH	R0,s16		STR	R0,s32
	BX	LR		BX	LR		BX	LR
d.	LDR	R0,=-1	e. I	LDRSB	R0,s8	f. LI	DRSB	R0,s8
	STRD	R0,s64		LDRH	R0,s16		STR	R0,s32
	BX	LR		BX	LR		BX	LR
g.	LDRSH	R0,s16	h.	LDR	R0,s32	i.	LDRB	R0,s32
	STR	R0,s32		ASR	R1,R0,31		STRB	R0,s8
	BX	LR		STRD	R0,R1,s64		BX	LR
				BX	LR			
j.	LDRB	R0,s16	k.	LDRH	R0,s32			
	STRB	R0,s8		STRH	R0,s16			
	BX	LR		BX	LR			
4.a.	ADR	R0,s32	b.	ADR	R0,s8	c.	LDRB	R0,ps8
	STR	R0,ps32			R0,ps8			R0,R0,1
	BX	LR			LR		BX	LR
d.	LDR	R0,ps32	e.		R0,ps32	f.		R0,ps8
	ADD	R0,R0,1			R1,=0			R1,=0
	BX	LR			R1,[R0]		STR	R1,[R0,4]
					LR		BX	LR

g.	LDR	R0,ps32	h.	LDR	R0,ps32	i.	LDR	R0,=0
	LDR	R1,=0		LDR	R1,s32		ADR	R1,s32
	STR	R1,[R0,4]		LDR	R2,=0		STRB	R1,[R2]
	BX	LR		STR	R2,[R0,R1]		STRB	R0,[R2,LSL1]
				BX	LR		BX	LR

7. MOV [R2],[R0] MOV [R0],[R1] MOV [R1],[R2] BX LR