
1. ARR = 3 PSC = 399999

2. PE3

PA6: 22 PC6: 39 PB4: 56

- 3. 250ms
- 4. Duty cycle was high for more of the period as CCRx increased.
- 5. Duty cycle was low for more of the period as CCRx increased.



7. PWM mode 1

ARR increases period

CCRx changes the percentage that each mode is on.