

Application Note

Galway Steinhart Coefficients, A, B and C constants for Standard Part Numbers

	"A"	"B"	"C"	Temperature
Part No.	Constant	Constant	Constant	reference points °C
0.1K1A	1.942952x10-3	2.989769x10-4	3.504383x10-7	-20°C, 25°C and 50°C
0.3K1A	1.627660x10-3	2.933316x10-4	2.870016x10-7	-20°C, 25°C and 50°C
1K2A	1.373168x10-3	2.772261x10-4	1.997412x10-7	-20°C, 25°C and 50°C
1K7A	1.446059x10-3	2.683626x10-4	1.643561x10-7	-20°C, 25°C and 50°C
2K3A	1.498872x10-3	2.379047x10-4	1.066953x10-7	0°C, 25°C and 70°C
2.2K3A	1.471388x10-3	2.376138x10-4	1.051058x10-7	0°C, 25°C and 70°C
3K3A	1.405027x10-3	2.369386x10-4	1.012660x10-7	0°C, 25°C and 70°C
5K3A	1.287450x10-3	2.357394x10-4	9.505200x10-8	0°C, 25°C and 70°C
10K3A	1.129241x10-3	2.341077x10-4	8.775468x10-8	0°C, 25°C and 70°C
10K4A	1.028444x10-3	2.392435x10-4	1.562216x10-7	0°C, 25°C and 70°C
30K5A	9.331754x10-4	2.213978x10-4	1.263817x10-7	0°C, 25°C and 70°C
30K6A	1.068981x10-3	2.120700x10-4	9.019537x10-8	0°C, 25°C and 70°C
50K6A	9.657154x10-4	2.106840x10-4	8.585481x10-8	0°C, 25°C and 70°C
100K6A	8.271111x10-4	2.088020x10-4	8.059200x10-8	0°C, 25°C and 70°C
1M9A	7.402387x10-4	1.760865x10-4	6.865999x10-8	25°C, 100°C and 150°C