

$$P_{mon}(t) = u(t) \cdot i(t) = U \cdot \sin(\omega t) \cdot I \cdot \sin(\omega t)$$
$$= U \cdot I \cdot \sin^{2}(\omega t)$$

$$P_{gem}\Big|_{T} = \frac{1}{T} \int_{0}^{t} u(t) \cdot i(t) \, \mathrm{d}t \tag{1a}$$

$$= \frac{1}{T} \int_0^T U \cdot \sin(\omega t) \cdot I \cdot \sin(\omega t) dt$$
 (1b)

$$= \frac{1}{T} \int_0^T U \cdot I \cdot \sin^2(\omega t) \, dt \tag{1c}$$

$$= U \cdot I \cdot \frac{1}{T} \int_0^T \sin^2(\omega t) \, \mathrm{d}t \tag{1d}$$

$$= U \cdot I \cdot \frac{1}{T} \int_0^T \left(\frac{1}{2} - \frac{1}{2} \cdot \cos(2\omega t) \right) dt \tag{1e}$$

$$= \frac{U \cdot I}{2 \cdot T} \left(\int_0^T 1 \, \mathrm{d}t + \int_0^T \cos(2\omega t) \, \mathrm{d}t \right) \tag{1f}$$

$$= \frac{U \cdot I}{2 \cdot T} \left(T - 0 \right) \tag{1g}$$

$$= \frac{1}{2} \cdot U \cdot I \tag{1h}$$