

Lesson Overview

After repairs and maintenance are completed, a technician performs a **Final Inspection**.

TESDA NC II requires that **ALL components—hardware, software, and network—must be checked** before restarting the system.

This ensures the computer is safe, properly connected, and ready for normal use.

PART 1 — Hardware Inspection Checklist RAM &

Internal Components

- RAM firmly locked in place
- GPU seated correctly
- SATA/power cables fully inserted
- No loose connectors
- Fans spin freely (no cable obstruction) **Cooling & Airflow**
- CPU and exhaust fans clean
- Air vents clear
- Cables tied away from fans
- Proper case airflow path

Storage & Power Supply

- HDD/SSD cables tight
- PSU switch accessible
- No burnt smell or overheating spots

PART 2 — Network Inspection Checklist Cable Connections

- Ethernet cable securely connected
- No damaged or bent connectors

IP Settings

- Correct IPv4 address
- Subnet mask, gateway, DNS properly configured
- No IP conflict warnings

Device Detection

- Network adapter enabled
- Router/modem detected if applicable

PART 3 — Software Inspection Checklist Antivirus & Updates

- Antivirus installed and active
- No malware pop-ups
- OS updates completed

System Stability

- No warning messages
- No missing drivers
- Boot device correctly set (BIOS not showing errors)

Files & Backup

- Important files backed up
- Restored folders accessible
- No corrupted files detected

FOR MORE READINGS:

Technical Education and Skills Development Authority. (2019). *Computer Systems Servicing NC II training regulations*. TESDA. [TR Computer Systems Servicing NC II .pdf](#)