Safety Checklist — saw cutting

Silica controls (wet cutting) in place; PPE verified; toolbox talk held (synthetic)