CITABRIA 7ECA GROUND PROCEDURES			
DISPATCH	Radios SET	Mixture IDLE C/O	
Weather BRIEF	ATIS <b>GET</b>	Evacuage GO	
NOTAMsCHECK	BarometerSET	IF NO START	
W&B <b>CHECK</b>	XPDR <b>SET</b>	Crank CONTINUE	
Perf. Reqs CHECK	Taxi Diag OPEN	Mixture IDLE C/O	
SquawksCHECK	TAXI	Throttle FULL	
IMSAFE CHECK	Brakes TEST	Fuel Shutoff OUT	
INSPECTION	Controls WIND	Evacuage GO	
Fuel DRAIN, CHECK	RUNUP		
AV1ATE CHECK	Doors CLOSED		
AROWCHECK	Seatbelts CHECK		
Mags <b>OFF</b>	Brakes SET		
Fuel GaugesTRUE	Controls CORRECT		
Fuel ShutoffIN	Trim TAKEOFF		
Master ON	Flight Inst CHECK		
Lights CHECK Stall Horn CHECK	Fuel ShutoffIN		
Master OFF	Mixture BEST POWER		
ELT ARMED	Throttle 1800 RPM		
Oil5-6 qts	Mags CHECK Carb. Heat CHECK		
Exterior CHECK	Engine Inst CHECK		
Ties/Chocks REMOVE	Throttle 1000 RPM		
Walkaround EXECUTE			
	SWITCH TO FLIGHT		
START	SHUTDOWN		
START Passengers BRIEF	SHUTDOWN  XPDRSET, OFF		
START  Passengers BRIEF  Seatbelts CHECK	SHUTDOWN  XPDR SET, OFF Brakes SET		
START Passengers BRIEF	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF		
START  Passengers BRIEF  Seatbelts CHECK  Stick FULL AFT	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF		
START  Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING  Front Lap Belt AROUND		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH HOT: SKIP PRIME	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING  Front Lap Belt AROUND STICK		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH HOT: SKIP PRIME Prime 4x Primer LOCKED Master Switch ON	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING  Front Lap Belt AROUND STICK Back Lap Belt BUCKLE		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH HOT: SKIP PRIME Prime 4x Primer LOCKED Master Switch ON Mags ON	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING  Front Lap Belt AROUND STICK Back Lap Belt BUCKLE Hobbs/Tach NOTE		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH HOT: SKIP PRIME Prime 4x Primer LOCKED Master Switch ON Mags ON Throttle SLIGHT	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING  Front Lap Belt AROUND STICK Back Lap Belt BUCKLE Hobbs/Tach NOTE Squawks NOTE		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH HOT: SKIP PRIME Prime 4x Primer LOCKED Master Switch ON Mags ON Throttle SLIGHT Brakes SET	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING  Front Lap Belt AROUND STICK Back Lap Belt BUCKLE Hobbs/Tach NOTE		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH HOT: SKIP PRIME Prime 4x Primer LOCKED Master Switch ON Mags ON Throttle SLIGHT Brakes SET Clear Prop ANNOUNCE	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING  Front Lap Belt AROUND STICK Back Lap Belt BUCKLE Hobbs/Tach NOTE Squawks NOTE Sun Shades REPLACE		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH HOT: SKIP PRIME Prime 4x Primer LOCKED Master Switch ON Mags ON Throttle SLIGHT Brakes SET Clear Prop ANNOUNCE Starter PUSH	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING  Front Lap Belt AROUND STICK Back Lap Belt BUCKLE Hobbs/Tach NOTE Squawks NOTE Sun Shades REPLACE Wheels CHOCK		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH HOT: SKIP PRIME Prime 4x Primer LOCKED Master Switch ON Mags ON Throttle SLIGHT Brakes SET Clear Prop ANNOUNCE Starter PUSH Throttle 1000 RPM	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING  Front Lap Belt AROUND STICK Back Lap Belt BUCKLE Hobbs/Tach NOTE Squawks NOTE Sun Shades REPLACE Wheels CHOCK Tail Wheel REORIENT		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH HOT: SKIP PRIME Prime 4x Primer LOCKED Master Switch ON Mags ON Throttle SLIGHT Brakes SET Clear Prop ANNOUNCE Starter PUSH Throttle 1000 RPM Oil Pressure CHECK	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING Front Lap Belt AROUND STICK Back Lap Belt BUCKLE Hobbs/Tach NOTE Squawks NOTE Squawks NOTE Sun Shades REPLACE Wheels CHOCK Tail Wheel REORIENT Ties TIE		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH HOT: SKIP PRIME Prime 4x Primer LOCKED Master Switch ON Mags ON Throttle SLIGHT Brakes SET Clear Prop ANNOUNCE Starter PUSH Throttle 1000 RPM Oil Pressure CHECK Ammeter CHECK	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING  Front Lap Belt AROUND STICK Back Lap Belt BUCKLE Hobbs/Tach NOTE Squawks NOTE Sun Shades REPLACE Wheels CHOCK Tail Wheel REORIENT Ties TIE Doors LOCK		
Passengers BRIEF Seatbelts CHECK Stick FULL AFT Breakers CHECK Fuel Shutoff IN Electrical OFF Door CLOSED Carb. Heat COLD Mixture RICH HOT: SKIP PRIME Prime 4x Primer LOCKED Master Switch ON Mags ON Throttle SLIGHT Brakes SET Clear Prop ANNOUNCE Starter PUSH Throttle 1000 RPM Oil Pressure CHECK	SHUTDOWN  XPDR SET, OFF Brakes SET Lights OFF GPS OFF Mixture IDLE C/O Mags OFF Master OFF Flight Plan CLOSE  SECURING  Front Lap Belt AROUND STICK Back Lap Belt BUCKLE Hobbs/Tach NOTE Squawks NOTE Sun Shades REPLACE Wheels CHOCK Tail Wheel REORIENT Ties TIE Doors LOCK		

CITABRIA 7ECA FLIGHT PROCEDURES			
TAKEOFF BRIEF	APPROACH CFGS	NOTES	
Runway CHECK Crosswind CHECK Abort Speed NOTE Technique NOTE Min. Ret. Alt NOTE Best Glide NOTE Time NOTE Mixture BEST POWER	NORMAL Speed	<ul> <li>All airspeeds in MPH</li> <li>Carb. heat always on if icing suspected, indicated by gradual loss of RPM</li> <li>Use only rudder on</li> </ul>	
CLIMB	LOW VOLTAGE Master	takeoff and landing (no brakes)	
ThrottleOPEN  IF BELOW 5000	Nonessentials OFF Flight TERMINATE	Mixture should be leaned at any altitude when un-	
Mixture BEST POWER Engine Inst CHECK Speed 75-80 Best Rate 69	OVERVOLTAGE  Master CYCLE Flight TERMINATE  ENGINE FAILURE	der 75% power. Lean until engine roughness, then enrichen to smoothness.	
Best Angle58	Best Glide65	IMPORTANT NUM.	
PRE-DESCENT	Fuel Shutoff ON Throttle HALF	V <sub>rotate</sub> 60	
Engine Inst	Throttle FULL Mixture VARY Primer TRY Carb. Heat HOT Mags TEST BOTH	$\begin{array}{cccc} V_x & & & 58 \\ V_y & & 69 \\ V_a & & 120 \\ V_{no} & & 120 \\ V_{ne} & & 162 \\ Best Glide & & 65 \\ \end{array}$	
	IF NO RESTART	Max Gross1800	
AFTER LANDING  Carb. Heat COLD  Trim TAKEOFF  Mixture LEAN  Taxi Diag OPEN	Squawk	Max Crosswind15 Fuel35	
SWITCH TO GROUND	ENGINE FIRE		
NORMAL Rotate	Mixture IDLE C/O Fuel Shutoff OUT Switches ALL OFF Cabin Heat OFF Extinguisher USE Flight TERMINATE		
Rotate	ELECTRICAL FIRE Electrical OFF Vents OPEN		
Attitude TAIL LOW After Liftoff LEVEL	Extinguisher USE  IF FIRE CONTINUES		

Flight ..... TERMINATE