PIN PAD SECURITY POLICY

EXPECTATIONS

Store Management is responsible for the physical security of the pin pad equipment during Store hours.

GUIDELINES

Prior to Store Opening

- Complete the Daily Pin Pad Security Survey
 - Manager or Coordinator must carefully inspect each pin pads daily for tampering prior to opening (see the Daily Pin Pad Security Survey in Reflexis or for Sierra in ThinkTime).
 - Utilizing the Verifone Anti-Skimmer device, check each pin pad daily to ensure they have not been tampered with.
 - Utilize the Anti-Skimmer Device job aid for directions on use of the Anti-Skimmer Device (refer to Knowledge Base or for Sierra refer to the Summit)

If there no obstruction of the card slot, the tool will show **GREEN** with "No Overlay Detected" (see photo).

And distancing Took Monte Fore

Insurrections

1. Shart the test application
2. Insert field bod into slot.
3. Power LEO will distance field
6. Impact security of press field
6. Cross the test specialized
6. Cross the test specialized

Invariant test spe

If there is an obstruction of the card slot, the tool will show **RED** with "Overlay Detected" (see photo).





PIN PAD SECURITY POLICY

GUIDELINES

- If you identify any issues with a pin pad:
 - Immediately suspend the use of that register(s)
 - Notify your DM and DLPM
 - Contact the Systems Service Desk at 1-888-444-4848 and select Option 2.
 Advise the Service Desk Agent you would like to report a "security concern or event with a pin pad" and provide the following:
 - Division
 - Store #
 - Register #
 - A brief description of the potential issue

If a "Overlay Detected" displays on a PIN Pad email the SOC@tjx.com while copying (cc) your DM and DLPM

SECURING EQUIPMENT AND SUPPLIES:

- Pin pads must be secured by a tether.
 - There are two methods of securing a pin pad:
 - Immobile- On a base with a tether (Majority of Registers).
 - Mobile- Without a base, but is tethered to the counter (Register 1).
 - Verifone Anti-Skimmer Device should be kept at the frontline in the locked change fund drawer.
 - Pin pad keys must be always kept in the key lock box in the safe.
 - If a pin pad key(s) is lost or stolen, contact your District Manager and District Loss
 Prevention Manager IMMEDIATELY.
- Access to ports on the pin pads must be blocked by a steel security plate. Report any unblocked ports to the Systems Service Desk.
 - If a Credit Card Skimmer was found on the PIN Pad, a register was stolen, or anything other than a PIN Pad/register/test tool needing to be repaired or replaced-

Email SOC@tjx.com and cc your District Manager and District Loss Prevention Manager. In the email include

2

- Store number, city and state
- Register number, serial number
- A brief description of the potential issue



02.24


PIN PAD SECURITY POLICY

SECURING EQUIPMENT AND SUPPLIES:


Front of Pin Pad
Note no signs of tampering


- · No Pry Marks
- No Scratches
- No Damage

Directly below the keypad is the insert slot where chip credit cards are inserted



Access to ports are blocked by a steel plate as seen in this top-down view







 All register rear covers must be securely locked except for stores that have a distributed register setup. A distributed setup is where the register drawer and "brain" are housed on separate shelves below the countertop.