
Convolution Accelerator v1 Pinmap



- CK: Clock Signal
- MOSI: Master Out Slave In
- MISO: Master In Slave Out
- RST: Reset Signal (Neg)
- SCK: SPI Clock Signal
- SS: Slave Select Signal (Neg)
- DONE: Command Done Signal