
BP5 Function

Note: Api call must be serial call, that is, after the end of a Api, you can call the next Api, otherwise it will appear Api function failure.




Note: The above 3 functions are parallel relations, there is no order.

BP5 Function A - Online Measurement Function

Note: 1. Api call must be serial call, that is, after the end of a Api, you can call the next Api, otherwise it will appear Api function failure.

2. In the BP5 measurement process, only to receive the stop measurement function (A-2), other Api failure.




A-1: commandStartMeasureWithUser: clientID:

A-2: stopBPMeassureErrorBlock: errorBlock:

BP5 Function B - Upload Offline Data


Note: BP5 (B-1) must be called before using the offline measurement function of the Api, otherwise the offline data time may be wrong.



B-1: commandFounction: errorBlock:

B-2: commandBatchUpload: pregress:

BP5 Function C -Querying and Setting Function



C-1: commandFounction: errorBlock:

C-2: commandEnergy: errorBlock:

C-3: commandSetBlueConnect: respond:

C-4: commandSetOffline: errorBlock: