1. IIC Work Requirements

1.1. PC Electrical and Communication Characteristics

Parameters	Marking	Minimum Value	!4	Maximum Value	Unit	备注
Clock Frequency	f.scl.			400	kHz	
Clock Low Pulse Duration	tLow.	1.3			us	
Clock High Pulse Duration	t High.	0.6			us	
SDA Setup Time	tsudat.	0.1			us	
SDA Hold Time	t hddat.	0.0			us	
Duration of start condition maintenance	tsusta	0.6			us	
Start condition hold time	t HDSTA	0.6			us	
Time of establishment for stop time	tsusto.	0.6			us	
Interval time between two communications	t buf.	1.3			us	

2. Function description

2.1 Definition of registers

Address	Bit address	Register name	Default value	Description	
0x30			4' b 0000	0000b: 0ms , 0001b: 62.5ms1111b: 937. 5ms , valid only in sleep mode	
	3	Sco	1'b 0	1: "Start data collection; automatically reset to 0 when collection ends	
	2 -0	Measurement_ctrl<2:0>	3'b	000b: Single Temperature Measurement Mode 001b: Single Sensor Signal Measurement Mode 010b: Combined Measurement Mode (performs a temperature measurement followed immediately by a sensor signal measurement) 011b: Sleep Mode (periodically performs a combined measurement mode, with the interval time determined by 'sleep_time') 100b: Continuous Temperature Measurement Mode 101b: Continuous Sensor Signal Measurement Mode	
0x06	7 –0	PDATA<23:16>	0x00	Signed integer, 2's complement: stores calibrated pressure sensor data; when	
0x07	7 - 0	PDATA<15:8>	0x00	'RAW_P' = 1, stores the ADC output of	
0x08	7 - 0	PDATA<7:0>	0x00	the main signal channel; when 'RAW_P' = 0, stores the calibrated sensor data. Code_P = Data0x06*2^ 16+ Data0x07*2^8+ Data0x08;	

0x09	7 - 0	TDATA<23:16>	0x00	Signed integer, 2's complement: When 'RAW_T' = 1, stores the ADC output code of the temperature channel; when 'RAW T' =
0x0A	7 - 0	TDATA<15:8>	0x00	0, stores the calibrated temperature data. LSB= 1/2^8°C Code_T = Data0x09*2^ 16+ Data0x0A*2^8;

2 2 Data normalization calculation (range: [-1, 1])

Pressure Conversion: Two's Complement

- 1 . After powering on, directly read the calibrated register data from 0x06, 0x07, and 0x08 to form a 24-bit pressure ADC value. The most significant bit is the sign bit, where a value of "1" indicates "negative" and "0" indicates "positive."
 - 2 . Perform the following calculations to determine the pressure value:

eg: if the decimal values read from REG0x06, REG0x07, and

REG0x08 are x, y, and z respectively, the pressure ADC (Code) value

is: m=x * 2^16+y* 2^8+z

Sign Handling:

If m > 2^23, it indicates a negative value, and the normalized value is (m - 2^24) / 2^23.

If m < 2^23 , it indicates a positive value, and the normalized value is m / 2^23 .

Temperature Conversion: Two's Complement

- 1 Read the calibrated register data from 0x09 and 0x0A to form a 24-bit temperature ADC value. The most significant bit is the sign bit, where a value of "1" indicates "negative" and "0" indicates "positive."
 - 2 . Perform the following calculations to determine the temperature value:

eg: Assume that the decimal values read from

REG0x09 and REG0x0A are x and y. The temperature

ADC (Code) value is:

m=x*2^16+y*2^8

Sign Handling:

if m>2^23, it is a negative value. The temperature in degrees Celsius (°C) is calculated as (m-2^24)/2^8;

if m<2^23, it is a positive value. The temperature in degrees Celsius (°C) is calculated as m/2^8;

2.3. Digital Output Transfer Function

Using the following equation, the pressure value can be converted to a digital output register value:

$$Y = Kx + B$$

Where Code is the chip register value, and P is the actual pressure value in kPa;

Table 2.3.1 Typical Digital Output Reference Table

Example Part	Pressure Range kPa		Digital	Output code		
Number	PL	Рн	OL	Он	Transfer Function Coefficients	
NSA2300/2302	-100	100	838861	7549746		
	Digital Normalized Value					
NSA2300/2302	Y ₁	Y ₂	X ₁	X ₂	К	В
	-100	100	0.1	0.9	250	-125

Combining the Code-to-pressure conversion formula from section 2.3, the measured pressure value can be calculated:

eg: if the values of the 0x06, 0x07, and 0x08 registers are 0x40, 0x00, and 0x00 respectively, then: Using the transfer function coefficient parameters:

Normalize the value: = $(64*2^16+0+0) / 2^23 = 0.5$, P(kPa) = (0.5*(250)) - 125, Thus, the final pressure value is approximately 0 kPa.

24 PC Communication Interface Protocol

I² C bus uses SCL (Serial Clock Line) and SDA (Serial Data Line) as signal lines. Both lines are connected to VDD via pull-up resistors and remain high when not communicating. The I2C device addresses for this series of products are as follows:

А7	A6	A5	A4	А3	A2	A1	W/R
1	1	1	1	1	1	1	0/1

Table 2.4.1: I2C Address

In the I2C communication protocol, a special Start (S) and Stop (P) condition are used. Data transmission begins when SDA falls while SCL is high. The master device sends the 7-bit address of the slave device along with a read/write control bit. Upon recognizing the address, the slave sends an acknowledgment signal by pulling SDA low during the ninth clock cycle. After receiving this acknowledgment, the master continues by sending 8-bit register addresses and, upon acknowledgment, continues to send or read data. The communication ends with a Stop condition, where SDA rises while SCL is high. Data must be stable when SCL is high, and can change when SCL is low. All data in I2C communication is transferred in 8-bit units, with an acknowledgment bit required after every 8 bits to continue the transfer.




图 2.4.2 I2C 协议

Byte Write SDA Dl ACK By ACK By Start Slave Slave Frame 1 Device address Frame 2 Word address SCL (Continued) SDA (Continued) D3 DI DO D4 D2 ACK By STOP Slave

Frame 3 Data Byte

Figure 2.4.3 I²C write timing

Random Read




Figure 2.4.4 I²C read timing

Software IIC example code shared




Figure 2.4.5 Register Read Logic

2.5. Change I2C Address(NSA2302 Only)

- 1 Read the value of 0xA4 and store it as REGA4; Write the value REGA4 = REGA4 | 0x08 to 0xA4;
- 2 \ Write I2C Address<6:0> | 0x80 to 0xA3.

For example, if the I2C address is 0xDA (1101 1010 for write) and 0xDB (1101 1011 for read), the address to write is 0x6D (0110 1101). Then, combine 0x6D (0110 101) with 0x80 (1000 0000), resulting in writing 0xED (1110 1101) to 0xA3.

- 3 Write 0x40 to 0x6A, write 0x6A to 0x6C, and then wait 1 second for EEPROM programming to complete.
- 4 . To reset the chip and activate the new I2C address, either power cycle the device or write 0x24 to 0x00. After this, the new address will be effective, and both the new address and the wildcard addresses 0xFF/0xFE can access the NSA2302.

3. Revision History

Revision	Description	Date
0.1	Initial Version	2023/6/7

Notes:

1. I2C Example Code

```
void IIC_Init(void)
                      //IIC Initialization
#define ACK 1
#define NACK 0
unsigned char number=1;
unsigned char REG30[1]={0};
unsigned char CalData[5]={0,0,0,0,0}
Float Pressure , Temperature ;
Float k,b;
                                 //Calculate the transfer function coefficients based on the range.
                       //NC Start signal: When SCL is high, SDA
void IIC_Start(void)
                                  transitions from high to low
                      //SCL outputs high
    IIC_SCL(1);
                      //SDA outputs high
    SDA_OUT(1);
    Delay_us(2);
                      //SDA outputs low
    SDA_OUT(0);
    Delay_us(2);
}
                      //NC Stop signal: When SCL is high, SDA
void IIC_Stop(void)
                                  transitions from low to high
    IIC_SCL(0);
    Delay_us(2);
    IIC_SCL(1);
    SDA OUT(0);
    Delay us(2);
    SDA_OUT(1);
    Delay_us(2);
}
                      //IIC Ack signal (low level)
void IIC_ACK(void)
{
    SDA_OUT(0);
    IIC_SCL(1);
    Delay_us(2);
    IIC_SCL(0);
}
                      //IIC NACK signal (high level)
void IIC_NACK(void)
{
    SDA_OUT(1);
    IIC_SCL(1);
    Delay_us(2);
    IIC_SCL(0);
```

}

```
unsigned char IIC_Wait_ACK(void)
                                          //IIC Ack wait check, return 0 indicates success; otherwise, error.
{
    int ErrTime=0;
    SDA_IN();
                                //SDA Set to input mode
    IIC_SCL(1);
     Delay_us(2);
    while(Read_SDA)
              ErrTime++;
              if(ErrTime>200)
                        IIC_Stop();
                        return 1;
              }
     IIC_SCL(0);
    SDA_OUT(0);
     Delay_us(2);
    return 0;
}
void IIC_Send(uchar IIC_Data) //IIC Send
     uchar i;
     IIC SCL(0);
     Delay us(2);
    for(i=0;i<8;i++)
              if((IIC_Data&0x80)>>7)
                        SDA_OUT(1);
              else
                       SDA_OUT(0);
              IIC_Data<<=1;
IIC_SCL(1);</pre>
              Delay_us(2);
              IIC_SCL(0);
              Delay_us(2);
}
unsigned char IIC_Receive(uchar ACK)
                                         //IIC Receive
{
     uchar i, Receive Data=0;
    SDA_IN();
                                //SDA Set to input mode
    for(i=0;i<8;i++)
              IIC_SCL(0);
              Delay us(2);
              IIC SCL(1);
              Receive_Data<<= 1;
```

IIC_Start();
IIC_Send(0xDA | 0x01); IIC_Wait_ACK();

pBuffer[0]=IIC Receive(ACK);

```
if(Read_SDA==1)
                       Receive_Data++;
              Delay_us(2);
    }
    IIC_SCL(0);
    Delay us(2);
    if(ACK==0x01)
              IIC_ACK();
    else
              IIC NACK();
    return Receive_Data;
}
void IIC_Write_Byte(unsigned char WriteAddr,unsigned char WriteData)
// NC Single write operation
    IIC Start();
    IIC_Send(0xDA | 0x00);
    IIC_Wait_ACK();
    IIC_Send(WriteAddr);
    IIC_Wait_ACK();
    IIC_Send(WriteData);
    IIC_Wait_ACK();
    IIC_Stop();
}
void IIC_Read_Byte(unsigned char ReadAddr, unsigned char *pBuffer)
// NC Single read operation
{
    IIC Start();
    IIC_Send(0xDA | 0x00);
    IIC_Wait_ACK();
    IIC Send(ReadAddr);
    IIC_Wait_ACK();
    IIC_Start();
    IIC_Send(0xDA | 0x01);
    IIC_Wait_ACK();
    pBuffer[0]=IIC_ Receive(NACK);
    IIC_Stop();
}
void IIC_Read_5Byte(unsigned char ReadAddr, unsigned char *pBuffer)
//IIC Continuous read operation (5byte)
{
    IIC Start();
    IIC Send(0xDA | 0x00);
    IIC_Wait_ACK();
    IIC_Send(ReadAddr);
    IIC_Wait_ACK();
```

```
pBuffer[1]=IIC_Receive(ACK);
    pBuffer[2]=IIC_Receive(ACK);
    pBuffer[3]=IIC_Receive(ACK);
    pBuffer[4]=IIC_ Receive(NACK);
    IIC_Stop();
}
void Main()
                                          //NSA2862X , 1: OWI disabled; 0: OWI not disabled
    Delay_3ms();
    #else
    Delay_25ms();
    #else if
    while(1)
             IIC_Write_Byte(0x30,0x0A);
                                                 //Combination conversion mode
             While(1)
                       if(number<=50)
                                number++;
                                Delay_ms(1);
                                IIC_Read_Byte(0x30, REG30);
                                if(0x02 == REG30[1])
                               {
                                         Number=1;
                                         REG02[0]=REG02[1]=0;
                                         break;
                               }
                      if(number>50)
                                number=1;
                               //can add error messages, such as serial port errors
                               break;
             }
    IIC_ Read_5Byte(0x06, CalData);
    Pressure = CalData[0] *65536 + CalData[1] *256 + CalData[2];
    if(Pressure > 8388607)
             Pressure = ((Pressure - 16777216) /8388607) *k +b
                                                                              //Pressure value, with units according to the
                                                                                  transfer function specification.
    else
             Pressure = (Pressure /8388607) *k +b
```