


Summary

Total Test Objects: 13
Successful: 11
Failed: 2
Not Executed: 0
Date: 2016-06-29
Time: 14:12:10+0530

Overall Test Object Results (including Coverage)




Selected Project Items

Test Object "CBD_UnitTest/GMSrComOutput/Appl_1E5MsgTxAck_CE"
 Test Object "CBD_UnitTest/GMSrComOutput/Appl_1E5MsgTxAck_HS"
 Test Object "CBD_UnitTest/GMSrComOutput/ApplNwmBusoff"
 Test Object "CBD_UnitTest/GMSrComOutput/ApplNwmBusoffEnd"
 Test Object "CBD_UnitTest/GMSrComOutput/ISOToGMStatus"
 Test Object "CBD_UnitTest/GMSrComOutput/SrComOuput_BusOffHandlerInit"
 Test Object "CBD_UnitTest/GMSrComOutput/SrComOuput_Reset778ReportedDTCs"
 Test Object "CBD_UnitTest/GMSrComOutput/SrComOutput_BusOffHandler"
 Test Object "CBD_UnitTest/GMSrComOutput/SrComOutput_Init1"
 Test Object "CBD_UnitTest/GMSrComOutput/SrComOutput_Per1"
 Test Object "CBD_UnitTest/GMSrComOutput/SrComOutput_Per2"
 Test Object "CBD_UnitTest/GMSrComOutput/SrComOutput_Trns1"
 Test Object "CBD_UnitTest/GMSrComOutput/SrComOutput_WarningIndicatorHandler"

Used Test Environments


TI TMS 570 PLS UDE (Default)

Test Case Results for Each Test Object (without Coverage)




The table above shows each test object on the x axis and the number of test cases of the respective test object on the y axis. Each bar is divided into passed, not executed and failed test cases. The test case results do not take into account any coverage result (i.e. if all test cases of a test object are passed in this table but the coverage is failed, the overall test object result will be failed).

Statement (C0) Coverage: Total Statements for Each Test Object




The table above shows each test object on the x axis and the number of statements of the respective test object on the y axis. Each bar is divided into reached statements (i.e. statements that have been executed during the test) and unreached statements.

Branch (C1) Coverage: Total Branches for Each Test Object



The table above shows each test object on the x axis and the number of branches of the respective test object on the y axis. Each bar is divided into reached branches (i.e. branches that have been executed during the test) and unreached branches.


Decision Coverage: Total Decision Outcomes for Each Test Object



The table above shows test objects on the x axis and the number of possible outcomes of all decisions of the respective test object on the y axis. To achieve full DC coverage, each decision must evaluate to both true and false.

Each bar is divided into reached and unreached decision outcomes.


MC/DC Coverage: Total Condition Combinations for Each Test Object



The table above shows test objects on the x axis and the number of condition combinations of all decisions of the respective test object on the y axis. The number of condition combinations is based on the number of boolean conditions within each decision of the test object. To achieve full MC/DC coverage, each decision requires all contained atomic conditions to evaluate to both true and false independently of all other conditions. The cumulated number of rows within such tables of condition combinations is what is displayed in this table.

Each bar is divided into reached condition combinations (i.e. combinations of boolean condition values that have been executed during the test) and unreached condition combinations.

MCC Coverage: Total Condition Combinations for Each Test Object



The table above shows test objects on the x axis and the number of condition combinations of all decisions of the respective test object on the y axis. The number of condition combinations is based on the number of boolean conditions within each decision of the test object. To achieve full MCC coverage, each decision requires all contained atomic conditions to evaluate to all possible combinations of true and false values. The cumulated number of rows within such tables of condition combinations is what is displayed in this table.

Each bar is divided into reached condition combinations (i.e. combinations of boolean condition values that have been executed during the test) and unreached condition combinations.

TEST OVERVIEW REPORT

2016-06-29, 14:12:10+0530

Project GMSrComOutput



Test Object List

The following table lists all test objects with their test case and coverage results. The cumulated results for modules, folders and test collections are also displayed, the indentation within the name column indicates the parent relationship of the elements.

Please note that only test objects are numbered within the first column. This number is referenced on the x axis within the overview charts for test case and coverage results available on previous pages (if included into the report).

No.	Name	C0	C1	DC	MC/DC	MCC	Test Cases	Result
	GMSrComOutput	94.11 %	91.89 %	91.5 %	92.3 %	92.3 %	28 of 28 passed	✖
	CBD_UnitTest	94.11 %	91.89 %	91.5 %	92.3 %	92.3 %	28 of 28 passed	✖
	GMSrComOutput	94.11 %	91.89 %	91.5 %	92.3 %	92.3 %	28 of 28 passed	✖
1	Appl_1E5MsgTxAck_CE	100 %	100 %	-	-	-	1 of 1 passed	✓
2	Appl_1E5MsgTxAck_HS	100 %	100 %	-	-	-	1 of 1 passed	✓
3	ApplNwmBusoff	100 %	100 %	100 %	100 %	100 %	3 of 3 passed	✓
4	ApplNwmBusoffEnd	100 %	100 %	-	-	-	1 of 1 passed	✓
5	ISOToGMStatus	100 %	100 %	100 %	100 %	100 %	3 of 3 passed	✓
6	SrlComOuput_BusOffHandlerInit	100 %	100 %	-	-	-	1 of 1 passed	✓
7	SrlComOuput_Reset778ReportedDTCs	100 %	100 %	-	-	-	1 of 1 passed	✓
8	SrlComOutput_BusOffHandler	100 %	100 %	100 %	100 %	100 %	3 of 3 passed	✓
9	SrlComOutput_Init1	100 %	100 %	100 %	100 %	100 %	3 of 3 passed	✓
10	SrlComOutput_Per1	92.85 %	89.58 %	89.58 %	90.74 %	90.74 %	3 of 3 passed	✖
11	SrlComOutput_Per2	86.2 %	80 %	80 %	82.6 %	82.6 %	3 of 3 passed	✖
12	SrlComOutput_Trns1	100 %	100 %	100 %	100 %	100 %	2 of 2 passed	✓
13	SrlComOutput_WarningIndicatorHandler	100 %	100 %	100 %	100 %	100 %	3 of 3 passed	✓

TEST DETAILS REPORT

2016-06-29, 13:45:56+0530



Appl_1E5MsgTxAck_CE

Project	GMSrComOutput
Module	GMSrComOutput
Test Object	Appl_1E5MsgTxAck_CE

Instrumentation: Test Object Only

Statement (C0) Coverage	100 %
Branch (C1) Coverage	100 %

Statistics

Total Testcases	1
Successful	1 ✓
Failed	0
Not Executed	0

Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrComOutput
Configuration File	D:\Synergy_Work_Area\GMSrComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\src\Ap_SrComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\utp\contract -I\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
------	------

TEST DETAILS REPORT

2016-06-29, 13:45:56+0530



Appl_1E5MsgTxAck_CE

Module 'GMSrComOutput'

***** Unit Test Description*****

Name of Tester:Namrata Morbale
Code File(s) Under Test:Ap_SrComOutput.c
Code File(s) Version:5
Module Design Document:Serial_Communication_Output_MDD.doc
Module Design Document Version:3
Data Dictionary Version:3
Unit Test Plan Version:1
Optimization Level:Level 2
Compiler (CodeGen) Version:TMS470_4.9.5
Model Type:Excel Macro
Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32
Total FLASH Used (Bytes):3574
Total RAM Used (Bytes):304
Total CALS Used (Bytes):15
Special Test Requirements:NA
Test Date:6/29/2016
Comments:Note1:Inline function defined in Globalmacro.h is not unit tested.

Note2:In function ""SriComOutput_Per1"" and ""SriComOutput_Per2"" ,typecasting code is added in VBA to avoid overflow issue.

Note3:In function ""SriComOutput_Per1"" ,100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path.

Note4:In function ""SriComOutput_Per1"" , 100% path coverage is not achieved because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKA_TorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKA_TorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro.

Note5:In function ""SriComOutput_Per2"" , 100% path coverage is not achieved because at src line 1292 conditions ""(SriComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SriComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro.

Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "" .

Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference.

Attributes	
Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

Test Case 1: Range Test

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS1.1 12 Cycles

TS1.2 12 Cycles

Description Vector Description:

TS1.1All_Min

TS1.2All_Max

Test Step 1.1 (Repeat Count = 1)

Name		Input Value		
txObject		0		
Name		Actual Value	Expected Value	Result
BusOffPresentChannel1_Cnt_M_lgc		0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

Test Step 1.2 (Repeat Count = 1)

Name		Input Value		
txObject		1		
Name		Actual Value	Expected Value	Result
BusOffPresentChannel1_Cnt_M_lgc		0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

TEST DETAILS REPORT

2016-06-29, 13:49:53+0530

ISOToGMStatus



Project	GMSrIComOutput
Module	GMSrIComOutput
Test Object	ISOToGMStatus

Instrumentation: Test Object Only

Statement (C0) Coverage	100 %
Decision Coverage	100 %
Branch (C1) Coverage	100 %
MCC Coverage	100 %
MC/DC Coverage	100 %

Statistics

Total Testcases	3
Successful	3 ✓
Failed	0
Not Executed	0

TEST DETAILS REPORT

2016-06-29, 13:49:53+0530

ISOToGMStatus



Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrComOutput
Configuration File	D:\Synergy_Work_Area\GMSrComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\src\Ap_SrComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\utp\contract -I\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
Module 'GMSrComOutput'	***** Unit Test Description***** Name of Tester:Namrata Morbale Code File(s) Under Test:Ap_SrComOutput.c Code File(s) Version:5 Module Design Document:Serial_Communication_Output_MDD.doc Module Design Document Version:3 Data Dictionary Version:3 Unit Test Plan Version:1 Optimization Level:Level 2 Compiler (CodeGen) Version:TMS470_4.9.5 Model Type:Excel Macro Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32 Total FLASH Used (Bytes):3574 Total RAM Used (Bytes):304 Total CALS Used (Bytes):15 Special Test Requirements:NA Test Date:6/29/2016 Comments:Note1:Inline function defined in Globalmacro.h is not unit tested. Note2:In function ""SrlComOutput_Per1"" and ""SrlComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue. Note3:In function ""SrlComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path. Note4:In function ""SrlComOutput_Per1"", 100% path coverage is not acheived because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKATorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKATorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note5:In function ""SrlComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SrlComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SrlComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "". Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference. *****

Attributes

Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

TEST DETAILS REPORT

2016-06-29, 13:49:53+0530

ISOToGMStatus



Test Case 1: Metrics Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment)
	CPU Cycles: TS1.1 41.00 Cycles TS1.2 41.00 Cycles
Description	Vector Description: TS1.1 "Shortest Execution Path: (0U != (statusMask & D_TESTFAILED_CNT_U8))=False (0U != (statusMask & D_CONFIRMED_CNT_U8))=False (0U != (statusMask & D_WARNINGIND_CNT_U8))=False" TS1.2 "Longest Execution Path: (0U != (statusMask & D_TESTFAILED_CNT_U8))=True (0U != (statusMask & D_CONFIRMED_CNT_U8))=True (0U != (statusMask & D_WARNINGIND_CNT_U8))=True"

Test Step 1.1 (Repeat Count = 1)

Name	Input Value		
statusMask	0		
Name	Actual Value	Expected Value	Result
ISOToGMStatus()	1	1	✓

Test Step 1.2 (Repeat Count = 1)

Name	Input Value		
statusMask	255		
Name	Actual Value	Expected Value	Result
ISOToGMStatus()	147	147	✓

Test Case 2: Range Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment)
	CPU Cycles: TS2.1 41.00 Cycles TS2.2 41.00 Cycles TS2.3 41.00 Cycles
Description	Vector Description: TS2.1 statusMask=Min TS2.2 statusMask=Max TS2.3 statusMask=Pos

Test Step 2.1 (Repeat Count = 1)

Name	Input Value		
statusMask	0		
Name	Actual Value	Expected Value	Result
ISOToGMStatus()	1	1	✓

Test Step 2.2 (Repeat Count = 1)

Name	Input Value		
statusMask	255		
Name	Actual Value	Expected Value	Result
ISOToGMStatus()	147	147	✓

Test Step 2.3 (Repeat Count = 1)

Name	Input Value		
statusMask	215		
Name	Actual Value	Expected Value	Result
ISOToGMStatus()	131	131	✓

Test Case 3: Path Test

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS3.1 41.00 Cycles
TS3.2 41.00 Cycles

Description Vector Description:

TS3.1 "(OU != (statusMask & D_TESTFAILED_CNT_U8))=False
(OU != (statusMask & D_CONFIRMED_CNT_U8))=False
(OU != (statusMask & D_WARNINGIND_CNT_U8))=False"
TS3.2 "(OU != (statusMask & D_TESTFAILED_CNT_U8))=True
(OU != (statusMask & D_CONFIRMED_CNT_U8))=True
(OU != (statusMask & D_WARNINGIND_CNT_U8))=True"

Test Step 3.1 (Repeat Count = 1)

Name	Input Value		
statusMask	0		
Name	Actual Value	Expected Value	Result
ISOToGMStatus()	1	1	✓

Test Step 3.2 (Repeat Count = 1)

Name	Input Value		
statusMask	255		
Name	Actual Value	Expected Value	Result
ISOToGMStatus()	147	147	✓

TEST DETAILS REPORT

2016-06-29, 13:47:19+0530

ApplNwmBusoff



Project	GMSrIComOutput
Module	GMSrIComOutput
Test Object	ApplNwmBusoff

Instrumentation: Test Object Only

Statement (C0) Coverage	100 %
Decision Coverage	100 %
Branch (C1) Coverage	100 %
MCC Coverage	100 %
MC/DC Coverage	100 %

Statistics

Total Testcases	3
Successful	3 ✓
Failed	0
Not Executed	0

TEST DETAILS REPORT

2016-06-29, 13:47:19+0530

ApplNwmBusoff



Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrComOutput
Configuration File	D:\Synergy_Work_Area\GMSrComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\src\Ap_SrComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\utp\contract -I\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
Module 'GMSrComOutput'	***** Unit Test Description***** Name of Tester:Namrata Morbale Code File(s) Under Test:Ap_SrComOutput.c Code File(s) Version:5 Module Design Document:Serial_Communication_Output_MDD.doc Module Design Document Version:3 Data Dictionary Version:3 Unit Test Plan Version:1 Optimization Level:Level 2 Compiler (CodeGen) Version:TMS470_4.9.5 Model Type:Excel Macro Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32 Total FLASH Used (Bytes):3574 Total RAM Used (Bytes):304 Total CALS Used (Bytes):15 Special Test Requirements:NA Test Date:6/29/2016 Comments:Note1:Inline function defined in Globalmacro.h is not unit tested. Note2:In function ""SriComOutput_Per1"" and ""SriComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue. Note3:In function ""SriComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path. Note4:In function ""SriComOutput_Per1"", 100% path coverage is not acheived because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKATorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKATorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note5:In function ""SriComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SriComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SriComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "". Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference. *****

Attributes

Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

Test Case 1: Range Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment)
	CPU Cycles: TS1.1 20 Cycles TS1.2 41 Cycles
Description	Vector Description:
	TS1.1All_Min TS1.2All_Max

Test Step 1.1 (Repeat Count = 1)

Name	Input Value		
BusOffPresentChannel0_Cnt_M_Igc	0		
BusOffPresentChannel1_Cnt_M_Igc	0		
channel	0		
Name	Actual Value	Expected Value	Result
BusOffPresentChannel0_Cnt_M_Igc	1	1	✓
BusOffPresentChannel1_Cnt_M_Igc	0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

Test Step 1.2 (Repeat Count = 1)

Name	Input Value		
BusOffPresentChannel0_Cnt_M_Igc	1		
BusOffPresentChannel1_Cnt_M_Igc	1		
channel	1		
Name	Actual Value	Expected Value	Result
BusOffPresentChannel0_Cnt_M_Igc	1	1	✓
BusOffPresentChannel1_Cnt_M_Igc	1	1	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

Test Case 2: Path Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment)
	CPU Cycles: TS2.1 20 Cycles TS2.2 41 Cycles
Description	Vector Description:
	TS2.1(0U == channel)=True TS2.2(0U == channel)=False

Test Step 2.1 (Repeat Count = 1)

Name	Input Value		
BusOffPresentChannel0_Cnt_M_Igc	0		
BusOffPresentChannel1_Cnt_M_Igc	0		
channel	0		
Name	Actual Value	Expected Value	Result
BusOffPresentChannel0_Cnt_M_Igc	1	1	✓
BusOffPresentChannel1_Cnt_M_Igc	0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

TEST DETAILS REPORT

2016-06-29, 13:47:19+0530

ApplNwmBusoff



Test Step 2.2 (Repeat Count = 1)

Name	Input Value		
BusOffPresentChannel0_Cnt_M_Igc	1		
BusOffPresentChannel1_Cnt_M_Igc	1		
channel	1		
Name	Actual Value	Expected Value	Result
BusOffPresentChannel0_Cnt_M_Igc	1	1	✓
BusOffPresentChannel1_Cnt_M_Igc	1	1	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

Test Case 3: Metrics Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment) CPU Cycles: TS3.1 20 Cycles TS3.2 41 Cycles
Description	Vector Description: TS3.1Shortest Execution Path:(OU == channel)=True TS3.2Longest Execution Path:(OU == channel)=False

Test Step 3.1 (Repeat Count = 1)

Name	Input Value		
BusOffPresentChannel0_Cnt_M_Igc	0		
BusOffPresentChannel1_Cnt_M_Igc	0		
channel	0		
Name	Actual Value	Expected Value	Result
BusOffPresentChannel0_Cnt_M_Igc	1	1	✓
BusOffPresentChannel1_Cnt_M_Igc	0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

Test Step 3.2 (Repeat Count = 1)

Name	Input Value		
BusOffPresentChannel0_Cnt_M_Igc	1		
BusOffPresentChannel1_Cnt_M_Igc	1		
channel	1		
Name	Actual Value	Expected Value	Result
BusOffPresentChannel0_Cnt_M_Igc	1	1	✓
BusOffPresentChannel1_Cnt_M_Igc	1	1	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530

SriComOutput_Per2



Project	GMSriComOutput
Module	GMSriComOutput
Test Object	SriComOutput_Per2

Instrumentation: Test Object Only

Statement (C0) Coverage	86.2 %
Decision Coverage	80 %
Branch (C1) Coverage	80 %
MCC Coverage	82.6 %
MC/DC Coverage	82.6 %

Statistics

Total Testcases	3
Successful	3 ✓
Failed	0
Not Executed	0

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrIComOutput_Per2

Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrIComOutput
Configuration File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\src\Ap_SrIComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\utp\contract -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
Module 'GMSrIComOutput'	***** Unit Test Description***** Name of Tester:Namrata Morbale Code File(s) Under Test:Ap_SrIComOutput.c Code File(s) Version:5 Module Design Document:Serial_Communication_Output_MDD.doc Module Design Document Version:3 Data Dictionary Version:3 Unit Test Plan Version:1 Optimization Level:Level 2 Compiler (CodeGen) Version:TMS470_4.9.5 Model Type:Excel Macro Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32 Total FLASH Used (Bytes):3574 Total RAM Used (Bytes):304 Total CALS Used (Bytes):15 Special Test Requirements:NA Test Date:6/29/2016 Comments:Note1:Inline function defined in Globalmacro.h is not unit tested. Note2:In function ""SrIComOutput_Per1"" and ""SrIComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue. Note3:In function ""SrIComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path. Note4:In function ""SrIComOutput_Per1"", 100% path coverage is not acheived because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKATorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKATorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note5:In function ""SrIComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SrIComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SrIComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "". Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference. *****

Attributes

Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530

SriComOutput_Per2



Test Case 1: Metrics Test

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS" Environment)

CPU Cycles:

TS 1.1 14022 cycles
TS 1.2 10141 cycles

Description Vector Description:

TS 1.1"Longest Execution Path: if (FALSE == DiagStsHwPosDis_Cnt_T_Igc)=> FALSE,
if (TRUE == HandwheelVelValid_Cnt_Igc)=>TRUE, if (TRUE == TrimCompEOL_Cnt_Igc)=>TRUE,

if (TRUE == k_APAMfgEnable_Cnt_Igc)=>TRUE, if (TRUE == k_APAMfgEnable_Cnt_Igc)=> TRUE,if (TRUE == Electric_Power_Steering_CE_conf_b)=>TRUE,
if ((TRUE == T1vsT2Active_Cnt_T_Igc) ||
(TRUE == T1OutOfRangeActive_Cnt_T_Igc) ||
(TRUE == T2OutOfRangeActive_Cnt_T_Igc) ||
(TRUE == TrqSensorNotTrimmedActive_Cnt_T_Igc))=>TRUE"
TS 1.2"Shortest Execution Path: if (FALSE == DiagStsHwPosDis_Cnt_T_Igc)=>TRUE,
if (TRUE == HandwheelVelValid_Cnt_Igc)=>FALSE,
if (TRUE == TrimCompEOL_Cnt_Igc)=>FALSE, if (TRUE == k_APAMfgEnable_Cnt_Igc)=>FALSE"

Test Step 1.1 (Repeat Count = 1)

Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_Igc	1
BusOffDiagActiveChannel1_Cnt_M_Igc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295
BusOffPresentChannel0_Cnt_M_Igc	1
BusOffPresentChannel1_Cnt_M_Igc	1
DrvStrIntrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	255
PPEI_Steering_Wheel_Angle_c[1]	255
PPEI_Steering_Wheel_Angle_c[2]	255
PPEI_Steering_Wheel_Angle_c[3]	255
PPEI_Steering_Wheel_Angle_c[4]	255
PPEI_Steering_Wheel_Angle_c[5]	255
PPEI_Steering_Wheel_Angle_c[6]	255
PPEI_Steering_Wheel_Angle_c[7]	255
PPEI_Steering_Wheel_Angle_CE_c[0]	255
PPEI_Steering_Wheel_Angle_CE_c[1]	255
PPEI_Steering_Wheel_Angle_CE_c[2]	255
PPEI_Steering_Wheel_Angle_CE_c[3]	255
PPEI_Steering_Wheel_Angle_CE_c[4]	255
PPEI_Steering_Wheel_Angle_CE_c[5]	255
PPEI_Steering_Wheel_Angle_CE_c[6]	255
PPEI_Steering_Wheel_Angle_CE_c[7]	255
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_Igc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_Igc_data
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_Igc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_Igc_data
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_Igc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_Igc_data
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_Igc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_Igc_data
StWhlAngAliveRollCnt_Cnt_M_u08	255
k_APAMfgEnable_Cnt_Igc	1
k_BusOffFaultTimeChannel0_mS_u16	65535
k_BusOffFaultTimeChannel1_mS_u16	65535
k_BusOffRecoveryTimeChannel0_mS_u16	65535
k_BusOffRecoveryTimeChannel1_mS_u16	65535
k_SComTrqPosPol_Cnt_s08	1
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4294967295
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_Igc_data	1
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	4
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_Igc_data	1
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	32
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_Igc_data	1

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1440.10999		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_Igc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_Igc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_Igc	1	1	✓
BusOffFltChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✓
BusOffFltChannel0RecoverTimer_mS_M_u32	4294967295	4294967295	✓
BusOffFltChannel1DetectionTimer_mS_M_u32	4294967295	4294967295	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	4294967295	4294967295	✓
DrvStrIntfrDetARC_Cnt_M_u08	0	0	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_Igc(data)	1	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_Igc(data)	1	1	✓
StWhlAngAliveRollCnt_Cnt_M_u08	0	0	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_Igc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_Igc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_Igc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_Igc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_Igc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_Igc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStWhlAngAliveRollCnt_0	1	IIPutTxStWhlAngAliveRollCnt_0	1	✓
IIPutTxStWhlAngAliveRollCnt_1	1	IIPutTxStWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_Igc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_Igc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtcdV	1	IIPutTxDrvStrIntfrDtcdV	1	✓
IIPutTxDrvStrIntfrDtcd	1	IIPutTxDrvStrIntfrDtcd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtcdGroup	1	IIPutTxDrvStrIntfrDtcdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
ITxTask	2	ITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_Igc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_Igc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_Igc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_Igc	1	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530

SriComOutput_Per2



Test Step 1.2 (Repeat Count = 1)				✓
Name	Input Value			
BusOffDiagActiveChannel0_Cnt_M_lgc	0			
BusOffDiagActiveChannel1_Cnt_M_lgc	0			
BusOffFitChannel0DetectionTimer_mS_M_u32	0			
BusOffFitChannel0RecoverTimer_mS_M_u32	0			
BusOffFitChannel1DetectionTimer_mS_M_u32	0			
BusOffFitChannel1RecoverTimer_mS_M_u32	0			
BusOffPresentChannel0_Cnt_M_lgc	0			
BusOffPresentChannel1_Cnt_M_lgc	0			
DrvStrIntrDetARC_Cnt_M_u08	0			
ElcPwrStrAvalStatARC_Cnt_M_u08	0			
Electric_Power_Steering_CE_conf_b	0			
PPEI_Steering_Wheel_Angle_c[0]	0			
PPEI_Steering_Wheel_Angle_c[1]	0			
PPEI_Steering_Wheel_Angle_c[2]	0			
PPEI_Steering_Wheel_Angle_c[3]	0			
PPEI_Steering_Wheel_Angle_c[4]	0			
PPEI_Steering_Wheel_Angle_c[5]	0			
PPEI_Steering_Wheel_Angle_c[6]	0			
PPEI_Steering_Wheel_Angle_c[7]	0			
PPEI_Steering_Wheel_Angle_CE_c[0]	0			
PPEI_Steering_Wheel_Angle_CE_c[1]	0			
PPEI_Steering_Wheel_Angle_CE_c[2]	0			
PPEI_Steering_Wheel_Angle_CE_c[3]	0			
PPEI_Steering_Wheel_Angle_CE_c[4]	0			
PPEI_Steering_Wheel_Angle_CE_c[5]	0			
PPEI_Steering_Wheel_Angle_CE_c[6]	0			
PPEI_Steering_Wheel_Angle_CE_c[7]	0			
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime			
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime			
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data			
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data			
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data			
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data			
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data			
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data			
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data			
StWhlAngAliveRollCnt_Cnt_M_u08	0			
k_APAMfgEnable_Cnt_lgc	0			
k_BusOffFaultTimeChannel0_mS_u16	0			
k_BusOffFaultTimeChannel1_mS_u16	0			
k_BusOffRecoveryTimeChannel0_mS_u16	0			
k_BusOffRecoveryTimeChannel1_mS_u16	0			
k_SComTrqPosPol_Cnt_s08	-1			
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	0			
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	0			
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0			
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	0			
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0			
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-32			
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0			
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	-1440.10999			
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0			
Name	Actual Value	Expected Value	Result	
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓	
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓	
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✓	
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✓	
BusOffFitChannel1DetectionTimer_mS_M_u32	0	0	✓	
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✓	
DrvStrIntrDetARC_Cnt_M_u08	0	0	✓	
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✓	
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✓	
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓	
StWhlAngAliveRollCnt_Cnt_M_u08	1	1	✓	
NTC	0x0100	0x0100	✓	
Param	0x0001	0x0001	✓	
Status	0x0000	0x0000	✓	
NTC	0x0110	0x0110	✓	
Param	0x0001	0x0001	✓	
Status	0x0000	0x0000	✓	

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
CanPartOffline	1	CanPartOffline	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓



Test Case 2: Range Test



TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS 2.1 10140 Cycles
TS 2.2 14062 Cycles
TS 2.3 13819 Cycles
TS 2.4 14088 Cycles
TS 2.5 13542 Cycles
TS 2.6 13793 Cycles
TS 2.7 13536 Cycles
TS 2.8 13526 Cycles
TS 2.9 14057 Cycles
TS 2.10 14067 Cycles
TS 2.11 13555 Cycles
TS 2.12 14051 Cycles
TS 2.13 13544 Cycles
TS 2.14 13797 Cycles
TS 2.15 14066 Cycles
TS 2.16 13792 Cycles
TS 2.17 13533 Cycles
TS 2.18 13554 Cycles
TS 2.19 13534 Cycles
TS 2.20 13800 Cycles
TS 2.21 13540 Cycles
TS 2.22 13547 Cycles
TS 2.23 13532 Cycles
TS 2.24 13553 Cycles
TS 2.25 14063 Cycles
TS 2.26 10149 Cycles
TS 2.27 13537 Cycles
TS 2.28 13808 Cycles
TS 2.29 13538 Cycles
TS 2.30 10147 Cycles
TS 2.31 10413 Cycles
TS 2.32 13539 Cycles
TS 2.33 13536 Cycles
TS 2.34 13556 Cycles
TS 2.35 13812 Cycles
TS 2.36 14068 Cycles
TS 2.37 13796 Cycles
TS 2.38 13790 Cycles
TS 2.39 13538 Cycles
TS 2.40 13806 Cycles
TS 2.41 13809 Cycles
TS 2.42 13533 Cycles
TS 2.43 13552 Cycles
TS 2.44 13537 Cycles
TS 2.45 13802 Cycles
TS 2.46 14079 Cycles
TS 2.47 13546 Cycles
TS 2.48 13541 Cycles
TS 2.49 13533 Cycles
TS 2.50 10405 Cycles
TS 2.51 13799 Cycles
TS 2.52 13802 Cycles
TS 2.53 14072 Cycles
TS 2.54 13549 Cycles
TS 2.55 14067 Cycles
TS 2.56 13537 Cycles
TS 2.57 14071 Cycles
TS 2.58 13543 Cycles
TS 2.59 13556 Cycles
TS 2.60 14073 Cycles
TS 2.61 14060 Cycles
TS 2.62 13549 Cycles
TS 2.63 13551 Cycles
TS 2.64 13558 Cycles
TS 2.65 13546 Cycles
TS 2.66 13541 Cycles
TS 2.67 13802 Cycles
TS 2.68 13802 Cycles
TS 2.69 13533 Cycles
TS 2.70 13807 Cycles
TS 2.71 13540 Cycles
TS 2.72 14059 Cycles
TS 2.73 13559 Cycles
TS 2.74 13543 Cycles
TS 2.75 10410 Cycles
TS 2.76 13548 Cycles
TS 2.77 13810 Cycles
TS 2.78 14057 Cycles
TS 2.79 10413 Cycles
TS 2.80 10158 Cycles
TS 2.81 13808 Cycles
TS 2.82 14074 Cycles
TS 2.83 14081 Cycles
TS 2.84 13811 Cycles
TS 2.85 13559 Cycles
TS 2.86 13550 Cycles
TS 2.87 13808 Cycles
TS 2.88 13545 Cycles

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Description	Vector Description:
	TS2.1All Min
	TS2.2All Max
	TS2.3SrlComHwPos_HwDeg_f32==>Min
	TS2.4SrlComHwPos_HwDeg_f32==>Max
	TS2.5SrlComHwPos_HwDeg_f32==>Pos
	TS2.6SrlComHwPos_HwDeg_f32==>Zero
	TS2.7SrlComHwPos_HwDeg_f32==>Neg
	TS2.8HandwheelVel_HwRadpS_f32==>Min
	TS2.9HandwheelVel_HwRadpS_f32==>Max
	TS2.10HandwheelVel_HwRadpS_f32==>Pos
	TS2.11HandwheelVel_HwRadpS_f32==>Zero
	TS2.12HandwheelVel_HwRadpS_f32==>Neg
	TS2.13HwVelValid_Cnt_lgc==>Min
	TS2.14HwVelValid_Cnt_lgc==>Max
	TS2.15TrimCompEOL_Cnt_lgc==>Min
	TS2.16TrimCompEOL_Cnt_lgc==>Max
	TS2.17k_SComTrqPosPol_Cnt_s08==>Min/Default
	TS2.18k_SComTrqPosPol_Cnt_s08==>Max
	TS2.19StWhlAngAliveRollCnt_Cnt_M_u08==>Min
	TS2.20StWhlAngAliveRollCnt_Cnt_M_u08==>Max
	TS2.21StWhlAngAliveRollCnt_Cnt_M_u08==>Pos
	TS2.22PPEI_Steering_Wheel_Angle.c[8]==>Min
	TS2.23PPEI_Steering_Wheel_Angle.c[8]==>Max
	TS2.24PPEI_Steering_Wheel_Angle.c[8]==>Pos
	TS2.25PPEI_Steering_Wheel_Angle_CE.c[8]==>Min
	TS2.26PPEI_Steering_Wheel_Angle_CE.c[8]==>Max
	TS2.27PPEI_Steering_Wheel_Angle_CE.c[8]==>Pos
	TS2.28k_APAMfgEnable_Cnt_lgc==>Min
	TS2.29k_APAMfgEnable_Cnt_lgc==>Max/Default
	TS2.30DrvStrIntfrDetARC_Cnt_M_u08==>Min
	TS2.31DrvStrIntfrDetARC_Cnt_M_u08==>Max
	TS2.32DrvStrIntfrDetARC_Cnt_M_u08==>Pos
	TS2.33ElcPwrStrAvalStatARC_Cnt_M_u08==>Min
	TS2.34ElcPwrStrAvalStatARC_Cnt_M_u08==>Max
	TS2.35ElcPwrStrAvalStatARC_Cnt_M_u08==>Pos
	TS2.36Electric_Power_Steering_CE_conf_b==>Min
	TS2.37Electric_Power_Steering_CE_conf_b==>Max
	TS2.38APADrvrInterventionDetected_Cnt_lgc==>Min
	TS2.39APADrvrInterventionDetected_Cnt_lgc==>Max
	TS2.40APAState_State_enum=APA_Templnhibit
	TS2.41APAState_State_enum=APA_AvailCntrl
	TS2.42APAState_State_enum=APA_Active
	TS2.43APAState_State_enum=APA_PermanentlyFailed
	TS2.44APAState_State_enum=APA_ManufacturingDisable
	TS2.45Rte_Call_NxtrDiagMgr_GetNTCActive[6]==>Min
	TS2.46Rte_Call_NxtrDiagMgr_GetNTCActive[6]==>Max
	TS2.47DiagStsHwPosDis_Cnt_lgc=>FALSE
	TS2.48DiagStsHwPosDis_Cnt_lgc=>TRUE
	TS2.49BusOffPresentChannel0_Cnt_M_lgc=>FALSE
	TS2.50BusOffPresentChannel0_Cnt_M_lgc=>TRUE
	TS2.51BusOffDiagActiveChannel0_Cnt_M_lgc=>FALSE
	TS2.52BusOffDiagActiveChannel0_Cnt_M_lgc=>TRUE
	TS2.53BusOffFltChannel0RecoverTimer_mS_M_u32=>Min
	TS2.54BusOffFltChannel0RecoverTimer_mS_M_u32=>Max
	TS2.55BusOffFltChannel0RecoverTimer_mS_M_u32=>Pos
	TS2.56BusOffFltChannel0DetectionTimer_mS_M_u32=>Min
	TS2.57BusOffFltChannel0DetectionTimer_mS_M_u32=>Max
	TS2.58BusOffFltChannel0DetectionTimer_mS_M_u32=>Pos
	TS2.59BusOffFltChannel1RecoverTimer_mS_M_u32=>Min
	TS2.60BusOffFltChannel1RecoverTimer_mS_M_u32=>Max
	TS2.61BusOffFltChannel1RecoverTimer_mS_M_u32=>Pos
	TS2.62BusOffFltChannel1DetectionTimer_mS_M_u32=>Min
	TS2.63BusOffFltChannel1DetectionTimer_mS_M_u32=>Max
	TS2.64BusOffFltChannel1DetectionTimer_mS_M_u32=>Pos
	TS2.65k_BusOffFaultTimeChannel0_mS_u16=>Min
	TS2.66k_BusOffFaultTimeChannel0_mS_u16=>Max
	TS2.67k_BusOffFaultTimeChannel0_mS_u16=>Pos
	TS2.68k_BusOffFaultTimeChannel0_mS_u16=>Default
	TS2.69k_BusOffRecoveryTimeChannel0_mS_u16=>Min/Default
	TS2.70k_BusOffRecoveryTimeChannel0_mS_u16=>Max
	TS2.71k_BusOffRecoveryTimeChannel0_mS_u16=>Pos
	TS2.72BusOffPresentChannel1_Cnt_M_lgc=>FALSE
	TS2.73BusOffPresentChannel1_Cnt_M_lgc=>TRUE
	TS2.74BusOffDiagActiveChannel1_Cnt_M_lgc=>FALSE
	TS2.75BusOffDiagActiveChannel1_Cnt_M_lgc=>TRUE
	TS2.76k_BusOffFaultTimeChannel1_mS_u16=>Min
	TS2.77k_BusOffFaultTimeChannel1_mS_u16=>Max
	TS2.78k_BusOffFaultTimeChannel1_mS_u16=>Pos
	TS2.79k_BusOffFaultTimeChannel1_mS_u16=>Default
	TS2.80k_BusOffRecoveryTimeChannel1_mS_u16=>Min/Default
	TS2.81k_BusOffRecoveryTimeChannel1_mS_u16=>Max
	TS2.82k_BusOffRecoveryTimeChannel1_mS_u16=>Pos
	TS2.83Rte_Call_SystemTime_GetSystemTime_mS_u32=>Min
	TS2.84Rte_Call_SystemTime_GetSystemTime_mS_u32=>Max
	TS2.85Rte_Call_SystemTime_GetSystemTime_mS_u32=>Pos
	TS2.86Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16=>Min
	TS2.87Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16=>Max
	TS2.88Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16=>Pos

Test Step 2.1 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
BusOffDiagActiveChannel1_Cnt_M_lgc	0		
BusOffFitChannel0DetectionTimer_mS_M_u32	0		
BusOffFitChannel0RecoverTimer_mS_M_u32	0		
BusOffFitChannel1DetectionTimer_mS_M_u32	0		
BusOffFitChannel1RecoverTimer_mS_M_u32	0		
BusOffPresentChannel0_Cnt_M_lgc	0		
BusOffPresentChannel1_Cnt_M_lgc	0		
DrvStrIntrDetARC_Cnt_M_u08	0		
ElcPwrStrAvalStatARC_Cnt_M_u08	0		
Electric_Power_Steering_CE_conf_b	0		
PPEI_Steering_Wheel_Angle._c[0]	0		
PPEI_Steering_Wheel_Angle._c[1]	0		
PPEI_Steering_Wheel_Angle._c[2]	0		
PPEI_Steering_Wheel_Angle._c[3]	0		
PPEI_Steering_Wheel_Angle._c[4]	0		
PPEI_Steering_Wheel_Angle._c[5]	0		
PPEI_Steering_Wheel_Angle._c[6]	0		
PPEI_Steering_Wheel_Angle._c[7]	0		
PPEI_Steering_Wheel_Angle_CE._c[0]	0		
PPEI_Steering_Wheel_Angle_CE._c[1]	0		
PPEI_Steering_Wheel_Angle_CE._c[2]	0		
PPEI_Steering_Wheel_Angle_CE._c[3]	0		
PPEI_Steering_Wheel_Angle_CE._c[4]	0		
PPEI_Steering_Wheel_Angle_CE._c[5]	0		
PPEI_Steering_Wheel_Angle_CE._c[6]	0		
PPEI_Steering_Wheel_Angle_CE._c[7]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	0		
k_APAMfgEnable_Cnt_lgc	0		
k_BusOffFaultTimeChannel0_mS_u16	0		
k_BusOffFaultTimeChannel1_mS_u16	0		
k_BusOffRecoveryTimeChannel0_mS_u16	0		
k_BusOffRecoveryTimeChannel1_mS_u16	0		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	0		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-32		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-1440.10999		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	0	0	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	1	1	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
CanPartOffline	1	CanPartOffline	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.2 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	255
PPEI_Steering_Wheel_Angle_c[1]	255
PPEI_Steering_Wheel_Angle_c[2]	255
PPEI_Steering_Wheel_Angle_c[3]	255
PPEI_Steering_Wheel_Angle_c[4]	255
PPEI_Steering_Wheel_Angle_c[5]	255
PPEI_Steering_Wheel_Angle_c[6]	255
PPEI_Steering_Wheel_Angle_c[7]	255
PPEI_Steering_Wheel_Angle_CE_c[0]	255
PPEI_Steering_Wheel_Angle_CE_c[1]	255
PPEI_Steering_Wheel_Angle_CE_c[2]	255
PPEI_Steering_Wheel_Angle_CE_c[3]	255
PPEI_Steering_Wheel_Angle_CE_c[4]	255
PPEI_Steering_Wheel_Angle_CE_c[5]	255

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle_CE_c[6]	255		
PPEI_Steering_Wheel_Angle_CE_c[7]	255		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	255		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	65535		
k_BusOffFaultTimeChannel1_mS_u16	65535		
k_BusOffRecoveryTimeChannel0_mS_u16	65535		
k_BusOffRecoveryTimeChannel1_mS_u16	65535		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	65535		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	4294967295		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	32		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1440.10999		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFltChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFltChannel0RecoverTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFltChannel1DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFltChannel1RecoverTimer_mS_M_u32	4294967295	4294967295	✔
DrvStrIntfrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	0	0	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtcdV	1	IIPutTxDrvStrIntfrDtcdV	1	✓
IIPutTxDrvStrIntfrDtcd	1	IIPutTxDrvStrIntfrDtcd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtcdGroup	1	IIPutTxDrvStrIntfrDtcdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.3 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	4294967295
BusOffFltChannel0RecoverTimer_mS_M_u32	0
BusOffFltChannel1DetectionTimer_mS_M_u32	1894110714
BusOffFltChannel1RecoverTimer_mS_M_u32	3861796421
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	10
PPEI_Steering_Wheel_Angle_c[1]	20
PPEI_Steering_Wheel_Angle_c[2]	30

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	40		
PPEI_Steering_Wheel_Angle._c[4]	50		
PPEI_Steering_Wheel_Angle._c[5]	60		
PPEI_Steering_Wheel_Angle._c[6]	70		
PPEI_Steering_Wheel_Angle._c[7]	80		
PPEI_Steering_Wheel_Angle_CE._c[0]	14		
PPEI_Steering_Wheel_Angle_CE._c[1]	28		
PPEI_Steering_Wheel_Angle_CE._c[2]	42		
PPEI_Steering_Wheel_Angle_CE._c[3]	56		
PPEI_Steering_Wheel_Angle_CE._c[4]	70		
PPEI_Steering_Wheel_Angle_CE._c[5]	84		
PPEI_Steering_Wheel_Angle_CE._c[6]	98		
PPEI_Steering_Wheel_Angle_CE._c[7]	112		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	83		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	60825		
k_BusOffFaultTimeChannel1_mS_u16	25406		
k_BusOffRecoveryTimeChannel0_mS_u16	25882		
k_BusOffRecoveryTimeChannel1_mS_u16	8229		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	11354		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3072927859		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	13.8599997		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	-1440.10999		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3072927859	3072927859	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3072927859	3072927859	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3072927859	3072927859	✔
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	84	84	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtcdV	1	IIPutTxDrvStrIntfrDtcdV	1	✓
IIPutTxDrvStrIntfrDtcd	1	IIPutTxDrvStrIntfrDtcd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtcdGroup	1	IIPutTxDrvStrIntfrDtcdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.4 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	3739593150
BusOffFltChannel0RecoverTimer_mS_M_u32	2061747645
BusOffFltChannel1DetectionTimer_mS_M_u32	1932051216
BusOffFltChannel1RecoverTimer_mS_M_u32	3193379438
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	12
PPEI_Steering_Wheel_Angle_c[1]	24
PPEI_Steering_Wheel_Angle_c[2]	36

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	48		
PPEI_Steering_Wheel_Angle._c[4]	60		
PPEI_Steering_Wheel_Angle._c[5]	72		
PPEI_Steering_Wheel_Angle._c[6]	84		
PPEI_Steering_Wheel_Angle._c[7]	96		
PPEI_Steering_Wheel_Angle_CE._c[0]	28		
PPEI_Steering_Wheel_Angle_CE._c[1]	56		
PPEI_Steering_Wheel_Angle_CE._c[2]	84		
PPEI_Steering_Wheel_Angle_CE._c[3]	112		
PPEI_Steering_Wheel_Angle_CE._c[4]	140		
PPEI_Steering_Wheel_Angle_CE._c[5]	168		
PPEI_Steering_Wheel_Angle_CE._c[6]	196		
PPEI_Steering_Wheel_Angle_CE._c[7]	224		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	250		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	10778		
k_BusOffFaultTimeChannel1_mS_u16	53272		
k_BusOffRecoveryTimeChannel0_mS_u16	15197		
k_BusOffRecoveryTimeChannel1_mS_u16	28600		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	47437		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2738556798		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	2.67000008		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1440.10999		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2738556798	2738556798	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	2738556798	2738556798	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	2738556798	2738556798	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	2738556798	2738556798	✓
DrvStrIntfrDetARC_Cnt_M_u08	3	3	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓
StWhlAngAliveRollCnt_Cnt_M_u08	251	251	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.5 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	1246334520
BusOffFltChannel0RecoverTimer_mS_M_u32	4294967295
BusOffFltChannel1DetectionTimer_mS_M_u32	1665706824
BusOffFltChannel1RecoverTimer_mS_M_u32	4193367413
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	14
PPEI_Steering_Wheel_Angle_c[1]	28

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[2]	42		
PPEI_Steering_Wheel_Angle._c[3]	56		
PPEI_Steering_Wheel_Angle._c[4]	70		
PPEI_Steering_Wheel_Angle._c[5]	84		
PPEI_Steering_Wheel_Angle._c[6]	98		
PPEI_Steering_Wheel_Angle._c[7]	112		
PPEI_Steering_Wheel_Angle_CE._c[0]	30		
PPEI_Steering_Wheel_Angle_CE._c[1]	60		
PPEI_Steering_Wheel_Angle_CE._c[2]	90		
PPEI_Steering_Wheel_Angle_CE._c[3]	120		
PPEI_Steering_Wheel_Angle_CE._c[4]	150		
PPEI_Steering_Wheel_Angle_CE._c[5]	180		
PPEI_Steering_Wheel_Angle_CE._c[6]	210		
PPEI_Steering_Wheel_Angle_CE._c[7]	240		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	148		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	64680		
k_BusOffFaultTimeChannel1_mS_u16	39725		
k_BusOffRecoveryTimeChannel0_mS_u16	30312		
k_BusOffRecoveryTimeChannel1_mS_u16	54157		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	44983		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1430223038		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	5.66800022		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	52.4000015		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1430223038	1430223038	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1430223038	1430223038	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1665706824	1665706824	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	4193367413	4193367413	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	149	149	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.6 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	1356285497
BusOffFltChannel0RecoverTimer_mS_M_u32	0
BusOffFltChannel1DetectionTimer_mS_M_u32	729974407
BusOffFltChannel1RecoverTimer_mS_M_u32	490622811
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	28
PPEI_Steering_Wheel_Angle_c[1]	56
PPEI_Steering_Wheel_Angle_c[2]	84
PPEI_Steering_Wheel_Angle_c[3]	112

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	140		
PPEI_Steering_Wheel_Angle._c[5]	168		
PPEI_Steering_Wheel_Angle._c[6]	196		
PPEI_Steering_Wheel_Angle._c[7]	224		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	62		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	15049		
k_BusOffFaultTimeChannel1_mS_u16	58080		
k_BusOffRecoveryTimeChannel0_mS_u16	56097		
k_BusOffRecoveryTimeChannel1_mS_u16	10981		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	55747		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3106101192		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-13.1700001		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	0		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1356285497	1356285497	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3106101192	3106101192	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3106101192	3106101192	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3106101192	3106101192	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	63	63	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStWhlAngAliveRollCnt_0	1	IIPutTxStWhlAngAliveRollCnt_0	1	✓
IIPutTxStWhlAngAliveRollCnt_1	1	IIPutTxStWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.7 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	3953105980
BusOffFltChannel0RecoverTimer_mS_M_u32	1944666162
BusOffFltChannel1DetectionTimer_mS_M_u32	672947379
BusOffFltChannel1RecoverTimer_mS_M_u32	947495828
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	30
PPEI_Steering_Wheel_Angle_c[1]	60
PPEI_Steering_Wheel_Angle_c[2]	90
PPEI_Steering_Wheel_Angle_c[3]	120

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	150		
PPEI_Steering_Wheel_Angle._c[5]	180		
PPEI_Steering_Wheel_Angle._c[6]	210		
PPEI_Steering_Wheel_Angle._c[7]	240		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	241		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	60017		
k_BusOffFaultTimeChannel1_mS_u16	43514		
k_BusOffRecoveryTimeChannel0_mS_u16	49676		
k_BusOffRecoveryTimeChannel1_mS_u16	32711		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	24947		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2370584731		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-12.3699999		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-866.950012		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3953105980	3953105980	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	2370584731	2370584731	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	672947379	672947379	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	947495828	947495828	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	242	242	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStWhlAngAliveRollCnt_0	1	IIPutTxStWhlAngAliveRollCnt_0	1	✓
IIPutTxStWhlAngAliveRollCnt_1	1	IIPutTxStWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.8 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	2346189251
BusOffFltChannel0RecoverTimer_mS_M_u32	0
BusOffFltChannel1DetectionTimer_mS_M_u32	2218074122
BusOffFltChannel1RecoverTimer_mS_M_u32	1424814936
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	22
PPEI_Steering_Wheel_Angle_c[1]	44
PPEI_Steering_Wheel_Angle_c[2]	66
PPEI_Steering_Wheel_Angle_c[3]	88

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	110		
PPEI_Steering_Wheel_Angle._c[5]	132		
PPEI_Steering_Wheel_Angle._c[6]	154		
PPEI_Steering_Wheel_Angle._c[7]	176		
PPEI_Steering_Wheel_Angle_CE._c[0]	26		
PPEI_Steering_Wheel_Angle_CE._c[1]	52		
PPEI_Steering_Wheel_Angle_CE._c[2]	78		
PPEI_Steering_Wheel_Angle_CE._c[3]	104		
PPEI_Steering_Wheel_Angle_CE._c[4]	130		
PPEI_Steering_Wheel_Angle_CE._c[5]	156		
PPEI_Steering_Wheel_Angle_CE._c[6]	182		
PPEI_Steering_Wheel_Angle_CE._c[7]	208		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	7		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	61618		
k_BusOffFaultTimeChannel1_mS_u16	61919		
k_BusOffRecoveryTimeChannel0_mS_u16	55520		
k_BusOffRecoveryTimeChannel1_mS_u16	17834		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	32276		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3048395838		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-32		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	504.209991		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	2346189251	2346189251	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3048395838	3048395838	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2218074122	2218074122	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3048395838	3048395838	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	8	8	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.9 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	2898070163
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295
BusOffFitChannel1DetectionTimer_mS_M_u32	270336042
BusOffFitChannel1RecoverTimer_mS_M_u32	1767109984
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	24
PPEI_Steering_Wheel_Angle_c[1]	48
PPEI_Steering_Wheel_Angle_c[2]	72
PPEI_Steering_Wheel_Angle_c[3]	96

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	120		
PPEI_Steering_Wheel_Angle._c[5]	144		
PPEI_Steering_Wheel_Angle._c[6]	168		
PPEI_Steering_Wheel_Angle._c[7]	192		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	202		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	13677		
k_BusOffFaultTimeChannel1_mS_u16	45957		
k_BusOffRecoveryTimeChannel0_mS_u16	48255		
k_BusOffRecoveryTimeChannel1_mS_u16	25447		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	62435		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3427553675		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	32		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1167.76001		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	2898070163	2898070163	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3427553675	3427553675	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	270336042	270336042	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3427553675	3427553675	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	203	203	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.10 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	0
BusOffFltChannel0RecoverTimer_mS_M_u32	3739593150
BusOffFltChannel1DetectionTimer_mS_M_u32	3782661189
BusOffFltChannel1RecoverTimer_mS_M_u32	2505595112
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	26
PPEI_Steering_Wheel_Angle_c[1]	52
PPEI_Steering_Wheel_Angle_c[2]	78

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	104		
PPEI_Steering_Wheel_Angle._c[4]	130		
PPEI_Steering_Wheel_Angle._c[5]	156		
PPEI_Steering_Wheel_Angle._c[6]	182		
PPEI_Steering_Wheel_Angle._c[7]	208		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	184		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	50513		
k_BusOffFaultTimeChannel1_mS_u16	50500		
k_BusOffRecoveryTimeChannel0_mS_u16	9605		
k_BusOffRecoveryTimeChannel1_mS_u16	60825		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	19690		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3561892702		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	24.0100002		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	1083.19995		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3561892702	3561892702	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3561892702	3561892702	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3782661189	3782661189	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3561892702	3561892702	✔
DrvStrIntfrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	185	185	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.11 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	0
BusOffFitChannel0RecoverTimer_mS_M_u32	1246334520
BusOffFitChannel1DetectionTimer_mS_M_u32	32931645
BusOffFitChannel1RecoverTimer_mS_M_u32	2167135746
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	16
PPEI_Steering_Wheel_Angle_c[1]	32
PPEI_Steering_Wheel_Angle_c[2]	48
PPEI_Steering_Wheel_Angle_c[3]	64

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	80		
PPEI_Steering_Wheel_Angle._c[5]	96		
PPEI_Steering_Wheel_Angle._c[6]	112		
PPEI_Steering_Wheel_Angle._c[7]	128		
PPEI_Steering_Wheel_Angle_CE._c[0]	28		
PPEI_Steering_Wheel_Angle_CE._c[1]	56		
PPEI_Steering_Wheel_Angle_CE._c[2]	84		
PPEI_Steering_Wheel_Angle_CE._c[3]	112		
PPEI_Steering_Wheel_Angle_CE._c[4]	140		
PPEI_Steering_Wheel_Angle_CE._c[5]	168		
PPEI_Steering_Wheel_Angle_CE._c[6]	196		
PPEI_Steering_Wheel_Angle_CE._c[7]	224		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	101		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	47282		
k_BusOffFaultTimeChannel1_mS_u16	2704		
k_BusOffRecoveryTimeChannel0_mS_u16	22238		
k_BusOffRecoveryTimeChannel1_mS_u16	10778		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	13990		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	420180266		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	0		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-239.600006		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	420180266	420180266	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	420180266	420180266	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	32931645	32931645	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	420180266	420180266	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	102	102	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.12 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	4294967295
BusOffFltChannel0RecoverTimer_mS_M_u32	1356285497
BusOffFltChannel1DetectionTimer_mS_M_u32	280775064
BusOffFltChannel1RecoverTimer_mS_M_u32	176554267
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	18
PPEI_Steering_Wheel_Angle_c[1]	36
PPEI_Steering_Wheel_Angle_c[2]	54

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	72		
PPEI_Steering_Wheel_Angle._c[4]	90		
PPEI_Steering_Wheel_Angle._c[5]	108		
PPEI_Steering_Wheel_Angle._c[6]	126		
PPEI_Steering_Wheel_Angle._c[7]	144		
PPEI_Steering_Wheel_Angle_CE._c[0]	30		
PPEI_Steering_Wheel_Angle_CE._c[1]	60		
PPEI_Steering_Wheel_Angle_CE._c[2]	90		
PPEI_Steering_Wheel_Angle_CE._c[3]	120		
PPEI_Steering_Wheel_Angle_CE._c[4]	150		
PPEI_Steering_Wheel_Angle_CE._c[5]	180		
PPEI_Steering_Wheel_Angle_CE._c[6]	210		
PPEI_Steering_Wheel_Angle_CE._c[7]	240		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	154		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	34946		
k_BusOffFaultTimeChannel1_mS_u16	18957		
k_BusOffRecoveryTimeChannel0_mS_u16	25881		
k_BusOffRecoveryTimeChannel1_mS_u16	64680		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	49757		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3903181889		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-5.30000019		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	-1085.47998		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3903181889	3903181889	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	280775064	280775064	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3903181889	3903181889	✓
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✓
StWhlAngAliveRollCnt_Cnt_M_u08	155	155	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.13 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	3739593150
BusOffFltChannel0RecoverTimer_mS_M_u32	3953105980
BusOffFltChannel1DetectionTimer_mS_M_u32	2029058766
BusOffFltChannel1RecoverTimer_mS_M_u32	3978790070
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	28
PPEI_Steering_Wheel_Angle_c[1]	56
PPEI_Steering_Wheel_Angle_c[2]	84

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	112		
PPEI_Steering_Wheel_Angle._c[4]	140		
PPEI_Steering_Wheel_Angle._c[5]	168		
PPEI_Steering_Wheel_Angle._c[6]	196		
PPEI_Steering_Wheel_Angle._c[7]	224		
PPEI_Steering_Wheel_Angle_CE._c[0]	14		
PPEI_Steering_Wheel_Angle_CE._c[1]	28		
PPEI_Steering_Wheel_Angle_CE._c[2]	42		
PPEI_Steering_Wheel_Angle_CE._c[3]	56		
PPEI_Steering_Wheel_Angle_CE._c[4]	70		
PPEI_Steering_Wheel_Angle_CE._c[5]	84		
PPEI_Steering_Wheel_Angle_CE._c[6]	98		
PPEI_Steering_Wheel_Angle_CE._c[7]	112		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	62		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	48424		
k_BusOffFaultTimeChannel1_mS_u16	6270		
k_BusOffRecoveryTimeChannel0_mS_u16	13073		
k_BusOffRecoveryTimeChannel1_mS_u16	15049		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	27251		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2484519884		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	19.2999992		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1309.02002		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2484519884	2484519884	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	2484519884	2484519884	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	2029058766	2029058766	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	2484519884	2484519884	✓
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓
StWhlAngAliveRollCnt_Cnt_M_u08	63	63	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.14 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	2016567863
BusOffFltChannel0RecoverTimer_mS_M_u32	2061747645
BusOffFltChannel1DetectionTimer_mS_M_u32	744697633
BusOffFltChannel1RecoverTimer_mS_M_u32	0
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	30
PPEI_Steering_Wheel_Angle_c[1]	60
PPEI_Steering_Wheel_Angle_c[2]	90

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	120		
PPEI_Steering_Wheel_Angle._c[4]	150		
PPEI_Steering_Wheel_Angle._c[5]	180		
PPEI_Steering_Wheel_Angle._c[6]	210		
PPEI_Steering_Wheel_Angle._c[7]	240		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	241		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	39530		
k_BusOffFaultTimeChannel1_mS_u16	18300		
k_BusOffRecoveryTimeChannel0_mS_u16	58477		
k_BusOffRecoveryTimeChannel1_mS_u16	60017		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	56972		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2653016018		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-7.71999979		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	857.078003		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2653016018	2653016018	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	2653016018	2653016018	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	2653016018	2653016018	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	2653016018	2653016018	✓
DrvStrIntfrDetARC_Cnt_M_u08	0	0	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓
StWhlAngAliveRollCnt_Cnt_M_u08	242	242	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.15 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	2346189251
BusOffFitChannel0RecoverTimer_mS_M_u32	4167849
BusOffFitChannel1DetectionTimer_mS_M_u32	4106390335
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	14
PPEI_Steering_Wheel_Angle_c[1]	28
PPEI_Steering_Wheel_Angle_c[2]	42
PPEI_Steering_Wheel_Angle_c[3]	56

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	70		
PPEI_Steering_Wheel_Angle._c[5]	84		
PPEI_Steering_Wheel_Angle._c[6]	98		
PPEI_Steering_Wheel_Angle._c[7]	112		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	185		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	30588		
k_BusOffFaultTimeChannel1_mS_u16	30149		
k_BusOffRecoveryTimeChannel0_mS_u16	4022		
k_BusOffRecoveryTimeChannel1_mS_u16	28632		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	4481		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1059205007		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	30.5		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	566.039978		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	2346189251	2346189251	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1059205007	1059205007	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4106390335	4106390335	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295	4294967295	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	186	186	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.16 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	2898070163
BusOffFitChannel0RecoverTimer_mS_M_u32	2016567863
BusOffFitChannel1DetectionTimer_mS_M_u32	652843089
BusOffFitChannel1RecoverTimer_mS_M_u32	3739593150
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	16
PPEI_Steering_Wheel_Angle_c[1]	32
PPEI_Steering_Wheel_Angle_c[2]	48
PPEI_Steering_Wheel_Angle_c[3]	64

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	80		
PPEI_Steering_Wheel_Angle._c[5]	96		
PPEI_Steering_Wheel_Angle._c[6]	112		
PPEI_Steering_Wheel_Angle._c[7]	128		
PPEI_Steering_Wheel_Angle_CE._c[0]	20		
PPEI_Steering_Wheel_Angle_CE._c[1]	40		
PPEI_Steering_Wheel_Angle_CE._c[2]	60		
PPEI_Steering_Wheel_Angle_CE._c[3]	80		
PPEI_Steering_Wheel_Angle_CE._c[4]	100		
PPEI_Steering_Wheel_Angle_CE._c[5]	120		
PPEI_Steering_Wheel_Angle_CE._c[6]	140		
PPEI_Steering_Wheel_Angle_CE._c[7]	160		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	101		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	22532		
k_BusOffFaultTimeChannel1_mS_u16	53147		
k_BusOffRecoveryTimeChannel0_mS_u16	8229		
k_BusOffRecoveryTimeChannel1_mS_u16	40570		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	37881		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4165916706		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	24.6399994		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-282.899994		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	4165916706	4165916706	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4165916706	4165916706	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	652843089	652843089	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3739593150	3739593150	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	102	102	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.17 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	1944666162
BusOffFitChannel0RecoverTimer_mS_M_u32	2346189251
BusOffFitChannel1DetectionTimer_mS_M_u32	0
BusOffFitChannel1RecoverTimer_mS_M_u32	131738029
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	18
PPEI_Steering_Wheel_Angle_c[1]	36
PPEI_Steering_Wheel_Angle_c[2]	54
PPEI_Steering_Wheel_Angle_c[3]	72

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	90		
PPEI_Steering_Wheel_Angle._c[5]	108		
PPEI_Steering_Wheel_Angle._c[6]	126		
PPEI_Steering_Wheel_Angle._c[7]	144		
PPEI_Steering_Wheel_Angle_CE._c[0]	22		
PPEI_Steering_Wheel_Angle_CE._c[1]	44		
PPEI_Steering_Wheel_Angle_CE._c[2]	66		
PPEI_Steering_Wheel_Angle_CE._c[3]	88		
PPEI_Steering_Wheel_Angle_CE._c[4]	110		
PPEI_Steering_Wheel_Angle_CE._c[5]	132		
PPEI_Steering_Wheel_Angle_CE._c[6]	154		
PPEI_Steering_Wheel_Angle_CE._c[7]	176		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	154		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	12028		
k_BusOffFaultTimeChannel1_mS_u16	2090		
k_BusOffRecoveryTimeChannel0_mS_u16	28600		
k_BusOffRecoveryTimeChannel1_mS_u16	16326		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	23810		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1723068811		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-28.2999992		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-1393.09998		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1723068811	1723068811	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1723068811	1723068811	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	1723068811	1723068811	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	1723068811	1723068811	✓
DrvStrIntrDetARC_Cnt_M_u08	3	3	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓
StWhlAngAliveRollCnt_Cnt_M_u08	155	155	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.18 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	4078039705
BusOffFltChannel0RecoverTimer_mS_M_u32	2898070163
BusOffFltChannel1DetectionTimer_mS_M_u32	4294967295
BusOffFltChannel1RecoverTimer_mS_M_u32	1730250954
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	20
PPEI_Steering_Wheel_Angle_c[1]	40
PPEI_Steering_Wheel_Angle_c[2]	60

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	80		
PPEI_Steering_Wheel_Angle._c[4]	100		
PPEI_Steering_Wheel_Angle._c[5]	120		
PPEI_Steering_Wheel_Angle._c[6]	140		
PPEI_Steering_Wheel_Angle._c[7]	160		
PPEI_Steering_Wheel_Angle_CE._c[0]	24		
PPEI_Steering_Wheel_Angle_CE._c[1]	48		
PPEI_Steering_Wheel_Angle_CE._c[2]	72		
PPEI_Steering_Wheel_Angle_CE._c[3]	96		
PPEI_Steering_Wheel_Angle_CE._c[4]	120		
PPEI_Steering_Wheel_Angle_CE._c[5]	144		
PPEI_Steering_Wheel_Angle_CE._c[6]	168		
PPEI_Steering_Wheel_Angle_CE._c[7]	192		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	141		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	41300		
k_BusOffFaultTimeChannel1_mS_u16	35503		
k_BusOffRecoveryTimeChannel0_mS_u16	54157		
k_BusOffRecoveryTimeChannel1_mS_u16	61618		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	51470		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1852121206		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	29.7000008		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	-956.73999		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1852121206	1852121206	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1852121206	1852121206	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1730250954	1730250954	✔
DrvStrIntfrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	142	142	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.19 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	1555615171
BusOffFitChannel0RecoverTimer_mS_M_u32	1944666162
BusOffFitChannel1DetectionTimer_mS_M_u32	3739593150
BusOffFitChannel1RecoverTimer_mS_M_u32	2138001447
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	22
PPEI_Steering_Wheel_Angle_c[1]	44
PPEI_Steering_Wheel_Angle_c[2]	66
PPEI_Steering_Wheel_Angle_c[3]	88

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	110		
PPEI_Steering_Wheel_Angle._c[5]	132		
PPEI_Steering_Wheel_Angle._c[6]	154		
PPEI_Steering_Wheel_Angle._c[7]	176		
PPEI_Steering_Wheel_Angle_CE._c[0]	30		
PPEI_Steering_Wheel_Angle_CE._c[1]	60		
PPEI_Steering_Wheel_Angle_CE._c[2]	90		
PPEI_Steering_Wheel_Angle_CE._c[3]	120		
PPEI_Steering_Wheel_Angle_CE._c[4]	150		
PPEI_Steering_Wheel_Angle_CE._c[5]	180		
PPEI_Steering_Wheel_Angle_CE._c[6]	210		
PPEI_Steering_Wheel_Angle_CE._c[7]	240		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	0		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	39281		
k_BusOffFaultTimeChannel1_mS_u16	30643		
k_BusOffRecoveryTimeChannel0_mS_u16	10981		
k_BusOffRecoveryTimeChannel1_mS_u16	13677		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	18596		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4269617388		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-8.39999962		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-966.900024		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1555615171	1555615171	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4269617388	4269617388	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4269617388	4269617388	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	4269617388	4269617388	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	1	1	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.20 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	4267903143
BusOffFltChannel0RecoverTimer_mS_M_u32	4078039705
BusOffFltChannel1DetectionTimer_mS_M_u32	340025677
BusOffFltChannel1RecoverTimer_mS_M_u32	705030171
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	24
PPEI_Steering_Wheel_Angle_c[1]	48
PPEI_Steering_Wheel_Angle_c[2]	72
PPEI_Steering_Wheel_Angle_c[3]	96

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	120		
PPEI_Steering_Wheel_Angle._c[5]	144		
PPEI_Steering_Wheel_Angle._c[6]	168		
PPEI_Steering_Wheel_Angle._c[7]	192		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	255		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	0		
k_BusOffFaultTimeChannel1_mS_u16	45863		
k_BusOffRecoveryTimeChannel0_mS_u16	32711		
k_BusOffRecoveryTimeChannel1_mS_u16	50513		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	12198		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1791563905		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	2.1099999		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	28.5		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1791563905	1791563905	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1791563905	1791563905	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	340025677	340025677	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1791563905	1791563905	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	0	0	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.21 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	1317627907
BusOffFitChannel0RecoverTimer_mS_M_u32	1555615171
BusOffFitChannel1DetectionTimer_mS_M_u32	1215337533
BusOffFitChannel1RecoverTimer_mS_M_u32	1522237236
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	26
PPEI_Steering_Wheel_Angle_c[1]	52
PPEI_Steering_Wheel_Angle_c[2]	78
PPEI_Steering_Wheel_Angle_c[3]	104

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	130		
PPEI_Steering_Wheel_Angle._c[5]	156		
PPEI_Steering_Wheel_Angle._c[6]	182		
PPEI_Steering_Wheel_Angle._c[7]	208		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	120		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	65535		
k_BusOffFaultTimeChannel1_mS_u16	58966		
k_BusOffRecoveryTimeChannel0_mS_u16	17447		
k_BusOffRecoveryTimeChannel1_mS_u16	47282		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	31748		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4101945562		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	17.8600006		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-270.149994		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	4101945562	4101945562	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4101945562	4101945562	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1215337533	1215337533	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1522237236	1522237236	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	121	121	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.22 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	4221959842
BusOffFltChannel0RecoverTimer_mS_M_u32	4267903143
BusOffFltChannel1DetectionTimer_mS_M_u32	2478357172
BusOffFltChannel1RecoverTimer_mS_M_u32	3474385282
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	0
PPEI_Steering_Wheel_Angle_c[1]	0
PPEI_Steering_Wheel_Angle_c[2]	0
PPEI_Steering_Wheel_Angle_c[3]	0

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	0		
PPEI_Steering_Wheel_Angle._c[5]	0		
PPEI_Steering_Wheel_Angle._c[6]	0		
PPEI_Steering_Wheel_Angle._c[7]	0		
PPEI_Steering_Wheel_Angle_CE._c[0]	20		
PPEI_Steering_Wheel_Angle_CE._c[1]	40		
PPEI_Steering_Wheel_Angle_CE._c[2]	60		
PPEI_Steering_Wheel_Angle_CE._c[3]	80		
PPEI_Steering_Wheel_Angle_CE._c[4]	100		
PPEI_Steering_Wheel_Angle_CE._c[5]	120		
PPEI_Steering_Wheel_Angle_CE._c[6]	140		
PPEI_Steering_Wheel_Angle_CE._c[7]	160		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	13		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	13677		
k_BusOffFaultTimeChannel1_mS_u16	26756		
k_BusOffRecoveryTimeChannel0_mS_u16	23359		
k_BusOffRecoveryTimeChannel1_mS_u16	34946		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	41680		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3146080493		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-28.5		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-1134.31006		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	4221959842	4221959842	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3146080493	3146080493	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3146080493	3146080493	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3146080493	3146080493	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	14	14	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.23 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	2119330630
BusOffFltChannel0RecoverTimer_mS_M_u32	1317627907
BusOffFltChannel1DetectionTimer_mS_M_u32	986753449
BusOffFltChannel1RecoverTimer_mS_M_u32	526492108
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	255
PPEI_Steering_Wheel_Angle_c[1]	255
PPEI_Steering_Wheel_Angle_c[2]	255

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	255		
PPEI_Steering_Wheel_Angle._c[4]	255		
PPEI_Steering_Wheel_Angle._c[5]	255		
PPEI_Steering_Wheel_Angle._c[6]	255		
PPEI_Steering_Wheel_Angle._c[7]	255		
PPEI_Steering_Wheel_Angle_CE._c[0]	22		
PPEI_Steering_Wheel_Angle_CE._c[1]	44		
PPEI_Steering_Wheel_Angle_CE._c[2]	66		
PPEI_Steering_Wheel_Angle_CE._c[3]	88		
PPEI_Steering_Wheel_Angle_CE._c[4]	110		
PPEI_Steering_Wheel_Angle_CE._c[5]	132		
PPEI_Steering_Wheel_Angle_CE._c[6]	154		
PPEI_Steering_Wheel_Angle_CE._c[7]	176		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	139		
k_APAMfgEnable_Cnt_lgc	0		
k_BusOffFaultTimeChannel0_mS_u16	1000		
k_BusOffFaultTimeChannel1_mS_u16	57796		
k_BusOffRecoveryTimeChannel0_mS_u16	790		
k_BusOffRecoveryTimeChannel1_mS_u16	48424		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	34471		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3791435509		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	6.5		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	-644.530029		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3791435509	3791435509	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3791435509	3791435509	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	986753449	986753449	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3791435509	3791435509	✔
DrvStrIntfrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	140	140	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
CanPartOffline	1	CanPartOffline	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.24 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	3973381665
BusOffFitChannel0RecoverTimer_mS_M_u32	4221959842
BusOffFitChannel1DetectionTimer_mS_M_u32	3313785296
BusOffFitChannel1RecoverTimer_mS_M_u32	1924756999
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	10
PPEI_Steering_Wheel_Angle_c[1]	20
PPEI_Steering_Wheel_Angle_c[2]	30
PPEI_Steering_Wheel_Angle_c[3]	40
PPEI_Steering_Wheel_Angle_c[4]	50
PPEI_Steering_Wheel_Angle_c[5]	60
PPEI_Steering_Wheel_Angle_c[6]	70
PPEI_Steering_Wheel_Angle_c[7]	80
PPEI_Steering_Wheel_Angle_CE_c[0]	24
PPEI_Steering_Wheel_Angle_CE_c[1]	48
PPEI_Steering_Wheel_Angle_CE_c[2]	72
PPEI_Steering_Wheel_Angle_CE_c[3]	96
PPEI_Steering_Wheel_Angle_CE_c[4]	120
PPEI_Steering_Wheel_Angle_CE_c[5]	144

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle_CE_c[6]	168		
PPEI_Steering_Wheel_Angle_CE_c[7]	192		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	245		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	32540		
k_BusOffFaultTimeChannel1_mS_u16	41512		
k_BusOffRecoveryTimeChannel0_mS_u16	0		
k_BusOffRecoveryTimeChannel1_mS_u16	39530		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	19705		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1839329192		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-1.5		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	412.640015		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFltChannel0DetectionTimer_mS_M_u32	1839329192	1839329192	✔
BusOffFltChannel0RecoverTimer_mS_M_u32	1839329192	1839329192	✔
BusOffFltChannel1DetectionTimer_mS_M_u32	3313785296	3313785296	✔
BusOffFltChannel1RecoverTimer_mS_M_u32	1924756999	1924756999	✔
DrvStrIntfrDetARC_Cnt_M_u08	3	3	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	246	246	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.25 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	2899086231
BusOffFitChannel0RecoverTimer_mS_M_u32	2119330630
BusOffFitChannel1DetectionTimer_mS_M_u32	2422532780
BusOffFitChannel1RecoverTimer_mS_M_u32	3985430462
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	24
PPEI_Steering_Wheel_Angle_c[1]	48
PPEI_Steering_Wheel_Angle_c[2]	72
PPEI_Steering_Wheel_Angle_c[3]	96

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	120		
PPEI_Steering_Wheel_Angle._c[5]	144		
PPEI_Steering_Wheel_Angle._c[6]	168		
PPEI_Steering_Wheel_Angle._c[7]	192		
PPEI_Steering_Wheel_Angle_CE._c[0]	0		
PPEI_Steering_Wheel_Angle_CE._c[1]	0		
PPEI_Steering_Wheel_Angle_CE._c[2]	0		
PPEI_Steering_Wheel_Angle_CE._c[3]	0		
PPEI_Steering_Wheel_Angle_CE._c[4]	0		
PPEI_Steering_Wheel_Angle_CE._c[5]	0		
PPEI_Steering_Wheel_Angle_CE._c[6]	0		
PPEI_Steering_Wheel_Angle_CE._c[7]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	57		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	4620		
k_BusOffFaultTimeChannel1_mS_u16	16758		
k_BusOffRecoveryTimeChannel0_mS_u16	65535		
k_BusOffRecoveryTimeChannel1_mS_u16	30588		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	8561		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	4085748062		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-12.6000004		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	1006.29999		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	2899086231	2899086231	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4085748062	4085748062	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2422532780	2422532780	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3985430462	3985430462	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	58	58	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.26 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	50782532
BusOffFitChannel0RecoverTimer_mS_M_u32	3973381665
BusOffFitChannel1DetectionTimer_mS_M_u32	4227646013
BusOffFitChannel1RecoverTimer_mS_M_u32	2282040120
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	26
PPEI_Steering_Wheel_Angle_c[1]	52
PPEI_Steering_Wheel_Angle_c[2]	78
PPEI_Steering_Wheel_Angle_c[3]	104

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	130		
PPEI_Steering_Wheel_Angle._c[5]	156		
PPEI_Steering_Wheel_Angle._c[6]	182		
PPEI_Steering_Wheel_Angle._c[7]	208		
PPEI_Steering_Wheel_Angle_CE._c[0]	255		
PPEI_Steering_Wheel_Angle_CE._c[1]	255		
PPEI_Steering_Wheel_Angle_CE._c[2]	255		
PPEI_Steering_Wheel_Angle_CE._c[3]	255		
PPEI_Steering_Wheel_Angle_CE._c[4]	255		
PPEI_Steering_Wheel_Angle_CE._c[5]	255		
PPEI_Steering_Wheel_Angle_CE._c[6]	255		
PPEI_Steering_Wheel_Angle_CE._c[7]	255		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	88		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	60421		
k_BusOffFaultTimeChannel1_mS_u16	29787		
k_BusOffRecoveryTimeChannel0_mS_u16	42112		
k_BusOffRecoveryTimeChannel1_mS_u16	55218		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	21481		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	827644878		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	8.39999962		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-5.30000019		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	827644878	827644878	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	827644878	827644878	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4227646013	4227646013	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	827644878	827644878	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	89	89	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.27 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	652294597
BusOffFitChannel0RecoverTimer_mS_M_u32	2899086231
BusOffFitChannel1DetectionTimer_mS_M_u32	1889078943
BusOffFitChannel1RecoverTimer_mS_M_u32	2555580428
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	28
PPEI_Steering_Wheel_Angle_c[1]	56
PPEI_Steering_Wheel_Angle_c[2]	84
PPEI_Steering_Wheel_Angle_c[3]	112

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	140		
PPEI_Steering_Wheel_Angle._c[5]	168		
PPEI_Steering_Wheel_Angle._c[6]	196		
PPEI_Steering_Wheel_Angle._c[7]	224		
PPEI_Steering_Wheel_Angle_CE._c[0]	10		
PPEI_Steering_Wheel_Angle_CE._c[1]	20		
PPEI_Steering_Wheel_Angle_CE._c[2]	30		
PPEI_Steering_Wheel_Angle_CE._c[3]	40		
PPEI_Steering_Wheel_Angle_CE._c[4]	50		
PPEI_Steering_Wheel_Angle_CE._c[5]	60		
PPEI_Steering_Wheel_Angle_CE._c[6]	70		
PPEI_Steering_Wheel_Angle_CE._c[7]	80		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	227		
k_APAMfgEnable_Cnt_lgc	0		
k_BusOffFaultTimeChannel0_mS_u16	28859		
k_BusOffFaultTimeChannel1_mS_u16	35820		
k_BusOffRecoveryTimeChannel0_mS_u16	4520		
k_BusOffRecoveryTimeChannel1_mS_u16	38620		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	27331		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2262440084		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	10.1000004		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-899.088013		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	2262440084	2262440084	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	2262440084	2262440084	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1889078943	1889078943	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	2555580428	2555580428	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	228	228	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
CanPartOffline	1	CanPartOffline	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.28 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	104612948
BusOffFitChannel0RecoverTimer_mS_M_u32	50782532
BusOffFitChannel1DetectionTimer_mS_M_u32	1033077435
BusOffFitChannel1RecoverTimer_mS_M_u32	1737034940
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	10
PPEI_Steering_Wheel_Angle_c[1]	20
PPEI_Steering_Wheel_Angle_c[2]	30
PPEI_Steering_Wheel_Angle_c[3]	40
PPEI_Steering_Wheel_Angle_c[4]	50
PPEI_Steering_Wheel_Angle_c[5]	60
PPEI_Steering_Wheel_Angle_c[6]	70
PPEI_Steering_Wheel_Angle_c[7]	80
PPEI_Steering_Wheel_Angle_CE_c[0]	24
PPEI_Steering_Wheel_Angle_CE_c[1]	48
PPEI_Steering_Wheel_Angle_CE_c[2]	72
PPEI_Steering_Wheel_Angle_CE_c[3]	96
PPEI_Steering_Wheel_Angle_CE_c[4]	120
PPEI_Steering_Wheel_Angle_CE_c[5]	144

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle_CE_c[6]	168		
PPEI_Steering_Wheel_Angle_CE_c[7]	192		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	14		
k_APAMfgEnable_Cnt_lgc	0		
k_BusOffFaultTimeChannel0_mS_u16	2793		
k_BusOffFaultTimeChannel1_mS_u16	15182		
k_BusOffRecoveryTimeChannel0_mS_u16	26741		
k_BusOffRecoveryTimeChannel1_mS_u16	10764		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	61600		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3003207712		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-14.8500004		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	1143.22998		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFltChannel0DetectionTimer_mS_M_u32	3003207712	3003207712	✓
BusOffFltChannel0RecoverTimer_mS_M_u32	3003207712	3003207712	✓
BusOffFltChannel1DetectionTimer_mS_M_u32	3003207712	3003207712	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	3003207712	3003207712	✓
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓
StWhlAngAliveRollCnt_Cnt_M_u08	15	15	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
CanPartOffline	1	CanPartOffline	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.29 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	1011278496
BusOffFitChannel0RecoverTimer_mS_M_u32	652294597
BusOffFitChannel1DetectionTimer_mS_M_u32	2220883010
BusOffFitChannel1RecoverTimer_mS_M_u32	2377469754
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntrDetARC_Cnt_M_u08	3
EicPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	12
PPEI_Steering_Wheel_Angle_c[1]	24
PPEI_Steering_Wheel_Angle_c[2]	36
PPEI_Steering_Wheel_Angle_c[3]	48
PPEI_Steering_Wheel_Angle_c[4]	60
PPEI_Steering_Wheel_Angle_c[5]	72
PPEI_Steering_Wheel_Angle_c[6]	84
PPEI_Steering_Wheel_Angle_c[7]	96
PPEI_Steering_Wheel_Angle_CE_c[0]	26
PPEI_Steering_Wheel_Angle_CE_c[1]	52
PPEI_Steering_Wheel_Angle_CE_c[2]	78
PPEI_Steering_Wheel_Angle_CE_c[3]	104
PPEI_Steering_Wheel_Angle_CE_c[4]	130

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle_CE_c[5]	156		
PPEI_Steering_Wheel_Angle_CE_c[6]	182		
PPEI_Steering_Wheel_Angle_CE_c[7]	208		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	28		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	62580		
k_BusOffFaultTimeChannel1_mS_u16	15156		
k_BusOffRecoveryTimeChannel0_mS_u16	46662		
k_BusOffRecoveryTimeChannel1_mS_u16	14680		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	9281		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	613865157		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-13.8000002		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-365.940002		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	613865157	613865157	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	613865157	613865157	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2220883010	2220883010	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	2377469754	2377469754	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	29	29	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.30 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	182109366
BusOffFitChannel0RecoverTimer_mS_M_u32	104612948
BusOffFitChannel1DetectionTimer_mS_M_u32	3453754701
BusOffFitChannel1RecoverTimer_mS_M_u32	4105035950
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	14
PPEI_Steering_Wheel_Angle_c[1]	28
PPEI_Steering_Wheel_Angle_c[2]	42
PPEI_Steering_Wheel_Angle_c[3]	56

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	70		
PPEI_Steering_Wheel_Angle._c[5]	84		
PPEI_Steering_Wheel_Angle._c[6]	98		
PPEI_Steering_Wheel_Angle._c[7]	112		
PPEI_Steering_Wheel_Angle_CE._c[0]	28		
PPEI_Steering_Wheel_Angle_CE._c[1]	56		
PPEI_Steering_Wheel_Angle_CE._c[2]	84		
PPEI_Steering_Wheel_Angle_CE._c[3]	112		
PPEI_Steering_Wheel_Angle_CE._c[4]	140		
PPEI_Steering_Wheel_Angle_CE._c[5]	168		
PPEI_Steering_Wheel_Angle_CE._c[6]	196		
PPEI_Steering_Wheel_Angle_CE._c[7]	224		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	42		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	31747		
k_BusOffFaultTimeChannel1_mS_u16	31747		
k_BusOffRecoveryTimeChannel0_mS_u16	35074		
k_BusOffRecoveryTimeChannel1_mS_u16	58671		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	11119		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3243810254		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	21.9300003		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-507.869995		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3243810254	3243810254	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3243810254	3243810254	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3243810254	3243810254	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3243810254	3243810254	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	43	43	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.31 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	3748819617
BusOffFitChannel0RecoverTimer_mS_M_u32	1011278496
BusOffFitChannel1DetectionTimer_mS_M_u32	3527207520
BusOffFitChannel1RecoverTimer_mS_M_u32	4000133609
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	28
PPEI_Steering_Wheel_Angle_c[1]	56
PPEI_Steering_Wheel_Angle_c[2]	84
PPEI_Steering_Wheel_Angle_c[3]	112

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	140		
PPEI_Steering_Wheel_Angle._c[5]	168		
PPEI_Steering_Wheel_Angle._c[6]	196		
PPEI_Steering_Wheel_Angle._c[7]	224		
PPEI_Steering_Wheel_Angle_CE._c[0]	10		
PPEI_Steering_Wheel_Angle_CE._c[1]	20		
PPEI_Steering_Wheel_Angle_CE._c[2]	30		
PPEI_Steering_Wheel_Angle_CE._c[3]	40		
PPEI_Steering_Wheel_Angle_CE._c[4]	50		
PPEI_Steering_Wheel_Angle_CE._c[5]	60		
PPEI_Steering_Wheel_Angle_CE._c[6]	70		
PPEI_Steering_Wheel_Angle_CE._c[7]	80		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	56		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	16570		
k_BusOffFaultTimeChannel1_mS_u16	0		
k_BusOffRecoveryTimeChannel0_mS_u16	29693		
k_BusOffRecoveryTimeChannel1_mS_u16	63449		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	1431		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3197582565		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	21.5900002		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	780.820007		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3748819617	3748819617	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3197582565	3197582565	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3197582565	3197582565	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3197582565	3197582565	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	57	57	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.32 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	530037193
BusOffFitChannel0RecoverTimer_mS_M_u32	182109366
BusOffFitChannel1DetectionTimer_mS_M_u32	70982200
BusOffFitChannel1RecoverTimer_mS_M_u32	3895554299
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	30
PPEI_Steering_Wheel_Angle_c[1]	60
PPEI_Steering_Wheel_Angle_c[2]	90
PPEI_Steering_Wheel_Angle_c[3]	120

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	150		
PPEI_Steering_Wheel_Angle._c[5]	180		
PPEI_Steering_Wheel_Angle._c[6]	210		
PPEI_Steering_Wheel_Angle._c[7]	240		
PPEI_Steering_Wheel_Angle_CE._c[0]	12		
PPEI_Steering_Wheel_Angle_CE._c[1]	24		
PPEI_Steering_Wheel_Angle_CE._c[2]	36		
PPEI_Steering_Wheel_Angle_CE._c[3]	48		
PPEI_Steering_Wheel_Angle_CE._c[4]	60		
PPEI_Steering_Wheel_Angle_CE._c[5]	72		
PPEI_Steering_Wheel_Angle_CE._c[6]	84		
PPEI_Steering_Wheel_Angle_CE._c[7]	96		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	70		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	55579		
k_BusOffFaultTimeChannel1_mS_u16	65535		
k_BusOffRecoveryTimeChannel0_mS_u16	28062		
k_BusOffRecoveryTimeChannel1_mS_u16	49144		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	58132		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3888356062		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	6.29500008		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	-812.002991		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	530037193	530037193	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3888356062	3888356062	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	70982200	70982200	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3888356062	3888356062	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	71	71	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStWhlAngAliveRollCnt_0	1	IIPutTxStWhlAngAliveRollCnt_0	1	✓
IIPutTxStWhlAngAliveRollCnt_1	1	IIPutTxStWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.33 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	3011938866
BusOffFltChannel0RecoverTimer_mS_M_u32	3748819617
BusOffFltChannel1DetectionTimer_mS_M_u32	580719151
BusOffFltChannel1RecoverTimer_mS_M_u32	267463338
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	16
PPEI_Steering_Wheel_Angle_c[1]	32
PPEI_Steering_Wheel_Angle_c[2]	48
PPEI_Steering_Wheel_Angle_c[3]	64

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	80		
PPEI_Steering_Wheel_Angle._c[5]	96		
PPEI_Steering_Wheel_Angle._c[6]	112		
PPEI_Steering_Wheel_Angle._c[7]	128		
PPEI_Steering_Wheel_Angle_CE._c[0]	14		
PPEI_Steering_Wheel_Angle_CE._c[1]	28		
PPEI_Steering_Wheel_Angle_CE._c[2]	42		
PPEI_Steering_Wheel_Angle_CE._c[3]	56		
PPEI_Steering_Wheel_Angle_CE._c[4]	70		
PPEI_Steering_Wheel_Angle_CE._c[5]	84		
PPEI_Steering_Wheel_Angle_CE._c[6]	98		
PPEI_Steering_Wheel_Angle_CE._c[7]	112		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	84		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	22316		
k_BusOffFaultTimeChannel1_mS_u16	12452		
k_BusOffRecoveryTimeChannel0_mS_u16	21163		
k_BusOffRecoveryTimeChannel1_mS_u16	12901		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	26581		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1722143059		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	12.3000002		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-152.220001		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3011938866	3011938866	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1722143059	1722143059	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	580719151	580719151	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1722143059	1722143059	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	85	85	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.34 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	2019950303
BusOffFltChannel0RecoverTimer_mS_M_u32	530037193
BusOffFltChannel1DetectionTimer_mS_M_u32	3403856094
BusOffFltChannel1RecoverTimer_mS_M_u32	3714298874
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	18
PPEI_Steering_Wheel_Angle_c[1]	36
PPEI_Steering_Wheel_Angle_c[2]	54

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	72		
PPEI_Steering_Wheel_Angle._c[4]	90		
PPEI_Steering_Wheel_Angle._c[5]	108		
PPEI_Steering_Wheel_Angle._c[6]	126		
PPEI_Steering_Wheel_Angle._c[7]	144		
PPEI_Steering_Wheel_Angle_CE._c[0]	28		
PPEI_Steering_Wheel_Angle_CE._c[1]	56		
PPEI_Steering_Wheel_Angle_CE._c[2]	84		
PPEI_Steering_Wheel_Angle_CE._c[3]	112		
PPEI_Steering_Wheel_Angle_CE._c[4]	140		
PPEI_Steering_Wheel_Angle_CE._c[5]	168		
PPEI_Steering_Wheel_Angle_CE._c[6]	196		
PPEI_Steering_Wheel_Angle_CE._c[7]	224		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	98		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	14724		
k_BusOffFaultTimeChannel1_mS_u16	1000		
k_BusOffRecoveryTimeChannel0_mS_u16	57840		
k_BusOffRecoveryTimeChannel1_mS_u16	116		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	51060		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	947628747		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	27.2099991		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-760.059998		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	947628747	947628747	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	947628747	947628747	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3403856094	3403856094	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	947628747	947628747	✔
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	99	99	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.35 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	2749249828
BusOffFltChannel0RecoverTimer_mS_M_u32	3011938866
BusOffFltChannel1DetectionTimer_mS_M_u32	513365892
BusOffFltChannel1RecoverTimer_mS_M_u32	1427923961
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	20
PPEI_Steering_Wheel_Angle_c[1]	40
PPEI_Steering_Wheel_Angle_c[2]	60

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	80		
PPEI_Steering_Wheel_Angle._c[4]	100		
PPEI_Steering_Wheel_Angle._c[5]	120		
PPEI_Steering_Wheel_Angle._c[6]	140		
PPEI_Steering_Wheel_Angle._c[7]	160		
PPEI_Steering_Wheel_Angle_CE._c[0]	30		
PPEI_Steering_Wheel_Angle_CE._c[1]	60		
PPEI_Steering_Wheel_Angle_CE._c[2]	90		
PPEI_Steering_Wheel_Angle_CE._c[3]	120		
PPEI_Steering_Wheel_Angle_CE._c[4]	150		
PPEI_Steering_Wheel_Angle_CE._c[5]	180		
PPEI_Steering_Wheel_Angle_CE._c[6]	210		
PPEI_Steering_Wheel_Angle_CE._c[7]	240		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	112		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	3323		
k_BusOffFaultTimeChannel1_mS_u16	0		
k_BusOffRecoveryTimeChannel0_mS_u16	18840		
k_BusOffRecoveryTimeChannel1_mS_u16	0		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	31289		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	90465543		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-17.2000008		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	1090.69995		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2749249828	2749249828	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	90465543	90465543	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	90465543	90465543	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	90465543	90465543	✓
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✓
StWhlAngAliveRollCnt_Cnt_M_u08	113	113	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStWhlAngAliveRollCnt_0	1	IIPutTxStWhlAngAliveRollCnt_0	1	✓
IIPutTxStWhlAngAliveRollCnt_1	1	IIPutTxStWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.36 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	1786924653
BusOffFitChannel0RecoverTimer_mS_M_u32	2019950303
BusOffFitChannel1DetectionTimer_mS_M_u32	3337019614
BusOffFitChannel1RecoverTimer_mS_M_u32	242703394
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	22
PPEI_Steering_Wheel_Angle_c[1]	44
PPEI_Steering_Wheel_Angle_c[2]	66
PPEI_Steering_Wheel_Angle_c[3]	88

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	110		
PPEI_Steering_Wheel_Angle._c[5]	132		
PPEI_Steering_Wheel_Angle._c[6]	154		
PPEI_Steering_Wheel_Angle._c[7]	176		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	126		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	52026		
k_BusOffFaultTimeChannel1_mS_u16	52026		
k_BusOffRecoveryTimeChannel0_mS_u16	10137		
k_BusOffRecoveryTimeChannel1_mS_u16	65535		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	26129		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2742837091		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	13.1000004		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	318.681		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	2742837091	2742837091	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	2742837091	2742837091	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3337019614	3337019614	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	2742837091	2742837091	✔
DrvStrIntrDetARC_Cnt_M_u08	3	3	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	127	127	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.37 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	1625499818
BusOffFitChannel0RecoverTimer_mS_M_u32	2749249828
BusOffFitChannel1DetectionTimer_mS_M_u32	3946204200
BusOffFitChannel1RecoverTimer_mS_M_u32	1893154369
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	24
PPEI_Steering_Wheel_Angle_c[1]	48
PPEI_Steering_Wheel_Angle_c[2]	72
PPEI_Steering_Wheel_Angle_c[3]	96

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	120		
PPEI_Steering_Wheel_Angle._c[5]	144		
PPEI_Steering_Wheel_Angle._c[6]	168		
PPEI_Steering_Wheel_Angle._c[7]	192		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	140		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	5547		
k_BusOffFaultTimeChannel1_mS_u16	31145		
k_BusOffRecoveryTimeChannel0_mS_u16	6836		
k_BusOffRecoveryTimeChannel1_mS_u16	34565		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	38512		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1838444304		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	31.7000008		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-361.279999		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1625499818	1625499818	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1838444304	1838444304	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1838444304	1838444304	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1838444304	1838444304	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	141	141	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.38 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	104711241
BusOffFltChannel0RecoverTimer_mS_M_u32	1786924653
BusOffFltChannel1DetectionTimer_mS_M_u32	3508479400
BusOffFltChannel1RecoverTimer_mS_M_u32	4275504771
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	28
PPEI_Steering_Wheel_Angle_c[1]	56
PPEI_Steering_Wheel_Angle_c[2]	84
PPEI_Steering_Wheel_Angle_c[3]	112

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	140		
PPEI_Steering_Wheel_Angle._c[5]	168		
PPEI_Steering_Wheel_Angle._c[6]	196		
PPEI_Steering_Wheel_Angle._c[7]	224		
PPEI_Steering_Wheel_Angle_CE._c[0]	26		
PPEI_Steering_Wheel_Angle_CE._c[1]	52		
PPEI_Steering_Wheel_Angle_CE._c[2]	78		
PPEI_Steering_Wheel_Angle_CE._c[3]	104		
PPEI_Steering_Wheel_Angle_CE._c[4]	130		
PPEI_Steering_Wheel_Angle_CE._c[5]	156		
PPEI_Steering_Wheel_Angle_CE._c[6]	182		
PPEI_Steering_Wheel_Angle_CE._c[7]	208		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	196		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	2125		
k_BusOffFaultTimeChannel1_mS_u16	2125		
k_BusOffRecoveryTimeChannel0_mS_u16	54702		
k_BusOffRecoveryTimeChannel1_mS_u16	38574		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	29911		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	0		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	24.2999992		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1243.91003		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3508479400	3508479400	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	197	197	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.39 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	1246334520
BusOffFltChannel0RecoverTimer_mS_M_u32	1625499818
BusOffFltChannel1DetectionTimer_mS_M_u32	1475957856
BusOffFltChannel1RecoverTimer_mS_M_u32	1817281359
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	30
PPEI_Steering_Wheel_Angle_c[1]	60
PPEI_Steering_Wheel_Angle_c[2]	90

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	120		
PPEI_Steering_Wheel_Angle._c[4]	150		
PPEI_Steering_Wheel_Angle._c[5]	180		
PPEI_Steering_Wheel_Angle._c[6]	210		
PPEI_Steering_Wheel_Angle._c[7]	240		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	210		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	32741		
k_BusOffFaultTimeChannel1_mS_u16	32741		
k_BusOffRecoveryTimeChannel0_mS_u16	9305		
k_BusOffRecoveryTimeChannel1_mS_u16	39326		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	34204		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	4294967295		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	11.9499998		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	50.0349998		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1475957856	1475957856	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1817281359	1817281359	✔
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	211	211	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.40 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	1356285497
BusOffFitChannel0RecoverTimer_mS_M_u32	104711241
BusOffFitChannel1DetectionTimer_mS_M_u32	1072722438
BusOffFitChannel1RecoverTimer_mS_M_u32	939309710
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	14
PPEI_Steering_Wheel_Angle_c[1]	28
PPEI_Steering_Wheel_Angle_c[2]	42
PPEI_Steering_Wheel_Angle_c[3]	56

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	70		
PPEI_Steering_Wheel_Angle._c[5]	84		
PPEI_Steering_Wheel_Angle._c[6]	98		
PPEI_Steering_Wheel_Angle._c[7]	112		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	224		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	31110		
k_BusOffFaultTimeChannel1_mS_u16	5547		
k_BusOffRecoveryTimeChannel0_mS_u16	36064		
k_BusOffRecoveryTimeChannel1_mS_u16	46468		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	29477		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	234577		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-30.9699993		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-488.440002		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1356285497	1356285497	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	234577	234577	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	234577	234577	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	234577	234577	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	225	225	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStWhlAngAliveRollCnt_0	1	IIPutTxStWhlAngAliveRollCnt_0	1	✓
IIPutTxStWhlAngAliveRollCnt_1	1	IIPutTxStWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.41 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	3953105980
BusOffFitChannel0RecoverTimer_mS_M_u32	1246334520
BusOffFitChannel1DetectionTimer_mS_M_u32	3730734968
BusOffFitChannel1RecoverTimer_mS_M_u32	219715415
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	16
PPEI_Steering_Wheel_Angle_c[1]	32
PPEI_Steering_Wheel_Angle_c[2]	48
PPEI_Steering_Wheel_Angle_c[3]	64

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	80		
PPEI_Steering_Wheel_Angle._c[5]	96		
PPEI_Steering_Wheel_Angle._c[6]	112		
PPEI_Steering_Wheel_Angle._c[7]	128		
PPEI_Steering_Wheel_Angle_CE._c[0]	28		
PPEI_Steering_Wheel_Angle_CE._c[1]	56		
PPEI_Steering_Wheel_Angle_CE._c[2]	84		
PPEI_Steering_Wheel_Angle_CE._c[3]	112		
PPEI_Steering_Wheel_Angle_CE._c[4]	140		
PPEI_Steering_Wheel_Angle_CE._c[5]	168		
PPEI_Steering_Wheel_Angle_CE._c[6]	196		
PPEI_Steering_Wheel_Angle_CE._c[7]	224		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	238		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	9247		
k_BusOffFaultTimeChannel1_mS_u16	9247		
k_BusOffRecoveryTimeChannel0_mS_u16	61		
k_BusOffRecoveryTimeChannel1_mS_u16	59923		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1148692970		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	5.38000011		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1062.09595		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3953105980	3953105980	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1148692970	1148692970	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3730734968	3730734968	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1148692970	1148692970	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	239	239	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.42 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	0
BusOffFitChannel0RecoverTimer_mS_M_u32	1356285497
BusOffFitChannel1DetectionTimer_mS_M_u32	1037570068
BusOffFitChannel1RecoverTimer_mS_M_u32	4249868551
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	18
PPEI_Steering_Wheel_Angle_c[1]	36
PPEI_Steering_Wheel_Angle_c[2]	54
PPEI_Steering_Wheel_Angle_c[3]	72

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	90		
PPEI_Steering_Wheel_Angle._c[5]	108		
PPEI_Steering_Wheel_Angle._c[6]	126		
PPEI_Steering_Wheel_Angle._c[7]	144		
PPEI_Steering_Wheel_Angle_CE._c[0]	30		
PPEI_Steering_Wheel_Angle_CE._c[1]	60		
PPEI_Steering_Wheel_Angle_CE._c[2]	90		
PPEI_Steering_Wheel_Angle_CE._c[3]	120		
PPEI_Steering_Wheel_Angle_CE._c[4]	150		
PPEI_Steering_Wheel_Angle_CE._c[5]	180		
PPEI_Steering_Wheel_Angle_CE._c[6]	210		
PPEI_Steering_Wheel_Angle_CE._c[7]	240		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	252		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	4520		
k_BusOffFaultTimeChannel1_mS_u16	4520		
k_BusOffRecoveryTimeChannel0_mS_u16	51915		
k_BusOffRecoveryTimeChannel1_mS_u16	17167		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	65535		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3109709954		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-25.4899998		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-693.697998		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3109709954	3109709954	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3109709954	3109709954	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1037570068	1037570068	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3109709954	3109709954	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	253	253	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.43 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	0
BusOffFltChannel0RecoverTimer_mS_M_u32	3953105980
BusOffFltChannel1DetectionTimer_mS_M_u32	1034796526
BusOffFltChannel1RecoverTimer_mS_M_u32	4003070099
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	20
PPEI_Steering_Wheel_Angle_c[1]	40
PPEI_Steering_Wheel_Angle_c[2]	60

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	80		
PPEI_Steering_Wheel_Angle._c[4]	100		
PPEI_Steering_Wheel_Angle._c[5]	120		
PPEI_Steering_Wheel_Angle._c[6]	140		
PPEI_Steering_Wheel_Angle._c[7]	160		
PPEI_Steering_Wheel_Angle_CE._c[0]	14		
PPEI_Steering_Wheel_Angle_CE._c[1]	28		
PPEI_Steering_Wheel_Angle_CE._c[2]	42		
PPEI_Steering_Wheel_Angle_CE._c[3]	56		
PPEI_Steering_Wheel_Angle_CE._c[4]	70		
PPEI_Steering_Wheel_Angle_CE._c[5]	84		
PPEI_Steering_Wheel_Angle_CE._c[6]	98		
PPEI_Steering_Wheel_Angle_CE._c[7]	112		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	45		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	0		
k_BusOffFaultTimeChannel1_mS_u16	3323		
k_BusOffRecoveryTimeChannel0_mS_u16	45892		
k_BusOffRecoveryTimeChannel1_mS_u16	8580		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	12542		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	297671690		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-25.2999992		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	-692.309998		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	297671690	297671690	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	297671690	297671690	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	297671690	297671690	✓
DrvStrIntfrDetARC_Cnt_M_u08	3	3	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✓
StWhlAngAliveRollCnt_Cnt_M_u08	46	46	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStWhlAngAliveRollCnt_0	1	IIPutTxStWhlAngAliveRollCnt_0	1	✓
IIPutTxStWhlAngAliveRollCnt_1	1	IIPutTxStWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.44 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	2798961936
BusOffFltChannel0RecoverTimer_mS_M_u32	1944666162
BusOffFltChannel1DetectionTimer_mS_M_u32	1414042488
BusOffFltChannel1RecoverTimer_mS_M_u32	2060037031
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	22
PPEI_Steering_Wheel_Angle_c[1]	44
PPEI_Steering_Wheel_Angle_c[2]	66

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	88		
PPEI_Steering_Wheel_Angle._c[4]	110		
PPEI_Steering_Wheel_Angle._c[5]	132		
PPEI_Steering_Wheel_Angle._c[6]	154		
PPEI_Steering_Wheel_Angle._c[7]	176		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	23		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	29045		
k_BusOffFaultTimeChannel1_mS_u16	65292		
k_BusOffRecoveryTimeChannel0_mS_u16	18371		
k_BusOffRecoveryTimeChannel1_mS_u16	53541		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	11731		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4281705497		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	19.9200001		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	-925.200012		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2798961936	2798961936	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	4281705497	4281705497	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	1414042488	1414042488	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	4281705497	4281705497	✓
DrvStrIntfrDetARC_Cnt_M_u08	3	3	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✓
StWhlAngAliveRollCnt_Cnt_M_u08	24	24	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.45 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	2083038980
BusOffFitChannel0RecoverTimer_mS_M_u32	4078039705
BusOffFitChannel1DetectionTimer_mS_M_u32	3986521469
BusOffFitChannel1RecoverTimer_mS_M_u32	964517160
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	20
PPEI_Steering_Wheel_Angle_c[1]	40
PPEI_Steering_Wheel_Angle_c[2]	60
PPEI_Steering_Wheel_Angle_c[3]	80

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	100		
PPEI_Steering_Wheel_Angle._c[5]	120		
PPEI_Steering_Wheel_Angle._c[6]	140		
PPEI_Steering_Wheel_Angle._c[7]	160		
PPEI_Steering_Wheel_Angle_CE._c[0]	14		
PPEI_Steering_Wheel_Angle_CE._c[1]	28		
PPEI_Steering_Wheel_Angle_CE._c[2]	42		
PPEI_Steering_Wheel_Angle_CE._c[3]	56		
PPEI_Steering_Wheel_Angle_CE._c[4]	70		
PPEI_Steering_Wheel_Angle_CE._c[5]	84		
PPEI_Steering_Wheel_Angle_CE._c[6]	98		
PPEI_Steering_Wheel_Angle_CE._c[7]	112		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	45		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	36751		
k_BusOffFaultTimeChannel1_mS_u16	35391		
k_BusOffRecoveryTimeChannel0_mS_u16	27065		
k_BusOffRecoveryTimeChannel1_mS_u16	33026		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	14504		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	25292635		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-13.5		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-440.450012		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	25292635	25292635	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	25292635	25292635	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3986521469	3986521469	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	25292635	25292635	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	46	46	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.46 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	4123039664
BusOffFitChannel0RecoverTimer_mS_M_u32	1555615171
BusOffFitChannel1DetectionTimer_mS_M_u32	2837299039
BusOffFitChannel1RecoverTimer_mS_M_u32	4198855525
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	22
PPEI_Steering_Wheel_Angle_c[1]	44
PPEI_Steering_Wheel_Angle_c[2]	66
PPEI_Steering_Wheel_Angle_c[3]	88

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	110		
PPEI_Steering_Wheel_Angle._c[5]	132		
PPEI_Steering_Wheel_Angle._c[6]	154		
PPEI_Steering_Wheel_Angle._c[7]	176		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	23		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	24498		
k_BusOffFaultTimeChannel1_mS_u16	29038		
k_BusOffRecoveryTimeChannel0_mS_u16	18463		
k_BusOffRecoveryTimeChannel1_mS_u16	49189		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	6805		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1869156293		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-29.0319996		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-1432.80005		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1869156293	1869156293	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1869156293	1869156293	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2837299039	2837299039	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1869156293	1869156293	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	24	24	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.47 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	2406253046
BusOffFitChannel0RecoverTimer_mS_M_u32	4267903143
BusOffFitChannel1DetectionTimer_mS_M_u32	3102403768
BusOffFitChannel1RecoverTimer_mS_M_u32	2569653453
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	0
PPEI_Steering_Wheel_Angle_c[1]	0
PPEI_Steering_Wheel_Angle_c[2]	0
PPEI_Steering_Wheel_Angle_c[3]	0

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	0		
PPEI_Steering_Wheel_Angle._c[5]	0		
PPEI_Steering_Wheel_Angle._c[6]	0		
PPEI_Steering_Wheel_Angle._c[7]	0		
PPEI_Steering_Wheel_Angle_CE._c[0]	0		
PPEI_Steering_Wheel_Angle_CE._c[1]	0		
PPEI_Steering_Wheel_Angle_CE._c[2]	0		
PPEI_Steering_Wheel_Angle_CE._c[3]	0		
PPEI_Steering_Wheel_Angle_CE._c[4]	0		
PPEI_Steering_Wheel_Angle_CE._c[5]	0		
PPEI_Steering_Wheel_Angle_CE._c[6]	0		
PPEI_Steering_Wheel_Angle_CE._c[7]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	211		
k_APAMfgEnable_Cnt_lgc	0		
k_BusOffFaultTimeChannel0_mS_u16	10400		
k_BusOffFaultTimeChannel1_mS_u16	39659		
k_BusOffRecoveryTimeChannel0_mS_u16	10335		
k_BusOffRecoveryTimeChannel1_mS_u16	11778		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	51909		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3711846142		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	17.8625107		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-87.7214355		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3711846142	3711846142	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3711846142	3711846142	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3102403768	3102403768	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3711846142	3711846142	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
EicPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	212	212	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
CanPartOffline	1	CanPartOffline	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.48 (Repeat Count = 1)

Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	606501335
BusOffFitChannel0RecoverTimer_mS_M_u32	0
BusOffFitChannel1DetectionTimer_mS_M_u32	3623247888
BusOffFitChannel1RecoverTimer_mS_M_u32	311922031
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntrDetARC_Cnt_M_u08	1
EicPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	255
PPEI_Steering_Wheel_Angle_c[1]	255
PPEI_Steering_Wheel_Angle_c[2]	255
PPEI_Steering_Wheel_Angle_c[3]	255
PPEI_Steering_Wheel_Angle_c[4]	255
PPEI_Steering_Wheel_Angle_c[5]	255
PPEI_Steering_Wheel_Angle_c[6]	255
PPEI_Steering_Wheel_Angle_c[7]	255
PPEI_Steering_Wheel_Angle_CE_c[0]	255
PPEI_Steering_Wheel_Angle_CE_c[1]	255
PPEI_Steering_Wheel_Angle_CE_c[2]	255
PPEI_Steering_Wheel_Angle_CE_c[3]	255
PPEI_Steering_Wheel_Angle_CE_c[4]	255

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle_CE_c[5]	255		
PPEI_Steering_Wheel_Angle_CE_c[6]	255		
PPEI_Steering_Wheel_Angle_CE_c[7]	255		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	130		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	42377		
k_BusOffFaultTimeChannel1_mS_u16	12175		
k_BusOffRecoveryTimeChannel0_mS_u16	27045		
k_BusOffRecoveryTimeChannel1_mS_u16	26400		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	64387		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3504432747		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	31.1123791		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	101.37014		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFltChannel0DetectionTimer_mS_M_u32	3504432747	3504432747	✓
BusOffFltChannel0RecoverTimer_mS_M_u32	3504432747	3504432747	✓
BusOffFltChannel1DetectionTimer_mS_M_u32	3623247888	3623247888	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	3504432747	3504432747	✓
DrvStrIntrDetARC_Cnt_M_u08	2	2	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓
StWhlAngAliveRollCnt_Cnt_M_u08	131	131	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.49 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	152648937
BusOffFltChannel0RecoverTimer_mS_M_u32	4294967295
BusOffFltChannel1DetectionTimer_mS_M_u32	1949651875
BusOffFltChannel1RecoverTimer_mS_M_u32	1866081990
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	10
PPEI_Steering_Wheel_Angle_c[1]	20
PPEI_Steering_Wheel_Angle_c[2]	30

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	40		
PPEI_Steering_Wheel_Angle._c[4]	50		
PPEI_Steering_Wheel_Angle._c[5]	60		
PPEI_Steering_Wheel_Angle._c[6]	70		
PPEI_Steering_Wheel_Angle._c[7]	80		
PPEI_Steering_Wheel_Angle_CE._c[0]	14		
PPEI_Steering_Wheel_Angle_CE._c[1]	28		
PPEI_Steering_Wheel_Angle_CE._c[2]	42		
PPEI_Steering_Wheel_Angle_CE._c[3]	56		
PPEI_Steering_Wheel_Angle_CE._c[4]	70		
PPEI_Steering_Wheel_Angle_CE._c[5]	84		
PPEI_Steering_Wheel_Angle_CE._c[6]	98		
PPEI_Steering_Wheel_Angle_CE._c[7]	112		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	197		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	398		
k_BusOffFaultTimeChannel1_mS_u16	15941		
k_BusOffRecoveryTimeChannel0_mS_u16	56158		
k_BusOffRecoveryTimeChannel1_mS_u16	48482		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	33088		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1826161495		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	6.10467768		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-485.542328		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1826161495	1826161495	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1826161495	1826161495	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	1949651875	1949651875	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	1826161495	1826161495	✓
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓
StWhlAngAliveRollCnt_Cnt_M_u08	198	198	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.50 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	2900684737
BusOffFltChannel0RecoverTimer_mS_M_u32	2968757993
BusOffFltChannel1DetectionTimer_mS_M_u32	3651027920
BusOffFltChannel1RecoverTimer_mS_M_u32	2820655991
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	12
PPEI_Steering_Wheel_Angle_c[1]	24
PPEI_Steering_Wheel_Angle_c[2]	36

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	48		
PPEI_Steering_Wheel_Angle._c[4]	60		
PPEI_Steering_Wheel_Angle._c[5]	72		
PPEI_Steering_Wheel_Angle._c[6]	84		
PPEI_Steering_Wheel_Angle._c[7]	96		
PPEI_Steering_Wheel_Angle_CE._c[0]	28		
PPEI_Steering_Wheel_Angle_CE._c[1]	56		
PPEI_Steering_Wheel_Angle_CE._c[2]	84		
PPEI_Steering_Wheel_Angle_CE._c[3]	112		
PPEI_Steering_Wheel_Angle_CE._c[4]	140		
PPEI_Steering_Wheel_Angle_CE._c[5]	168		
PPEI_Steering_Wheel_Angle_CE._c[6]	196		
PPEI_Steering_Wheel_Angle_CE._c[7]	224		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	73		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	2350		
k_BusOffFaultTimeChannel1_mS_u16	7724		
k_BusOffRecoveryTimeChannel0_mS_u16	28397		
k_BusOffRecoveryTimeChannel1_mS_u16	47119		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	8510		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2379726396		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	21.8368683		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	64.8679657		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2900684737	2900684737	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	2379726396	2379726396	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3651027920	3651027920	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	2379726396	2379726396	✓
DrvStrIntfrDetARC_Cnt_M_u08	3	3	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✓
StWhlAngAliveRollCnt_Cnt_M_u08	74	74	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.51 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	1241492956
BusOffFltChannel0RecoverTimer_mS_M_u32	260150396
BusOffFltChannel1DetectionTimer_mS_M_u32	4253613675
BusOffFltChannel1RecoverTimer_mS_M_u32	346064350
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	14
PPEI_Steering_Wheel_Angle_c[1]	28
PPEI_Steering_Wheel_Angle_c[2]	42

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	56		
PPEI_Steering_Wheel_Angle._c[4]	70		
PPEI_Steering_Wheel_Angle._c[5]	84		
PPEI_Steering_Wheel_Angle._c[6]	98		
PPEI_Steering_Wheel_Angle._c[7]	112		
PPEI_Steering_Wheel_Angle_CE._c[0]	30		
PPEI_Steering_Wheel_Angle_CE._c[1]	60		
PPEI_Steering_Wheel_Angle_CE._c[2]	90		
PPEI_Steering_Wheel_Angle_CE._c[3]	120		
PPEI_Steering_Wheel_Angle_CE._c[4]	150		
PPEI_Steering_Wheel_Angle_CE._c[5]	180		
PPEI_Steering_Wheel_Angle_CE._c[6]	210		
PPEI_Steering_Wheel_Angle_CE._c[7]	240		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	47		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	36241		
k_BusOffFaultTimeChannel1_mS_u16	51569		
k_BusOffRecoveryTimeChannel0_mS_u16	44753		
k_BusOffRecoveryTimeChannel1_mS_u16	7185		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	39703		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1266070877		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-20.2109203		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	1104.9104		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1266070877	1266070877	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1266070877	1266070877	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4253613675	4253613675	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1266070877	1266070877	✔
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	48	48	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.52 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	356514100
BusOffFitChannel0RecoverTimer_mS_M_u32	1484790616
BusOffFitChannel1DetectionTimer_mS_M_u32	2732433729
BusOffFitChannel1RecoverTimer_mS_M_u32	3369665085
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	28
PPEI_Steering_Wheel_Angle_c[1]	56
PPEI_Steering_Wheel_Angle_c[2]	84
PPEI_Steering_Wheel_Angle_c[3]	112

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	140		
PPEI_Steering_Wheel_Angle._c[5]	168		
PPEI_Steering_Wheel_Angle._c[6]	196		
PPEI_Steering_Wheel_Angle._c[7]	224		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	76		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	15428		
k_BusOffFaultTimeChannel1_mS_u16	22966		
k_BusOffRecoveryTimeChannel0_mS_u16	35991		
k_BusOffRecoveryTimeChannel1_mS_u16	4329		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	51108		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1855444263		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	17.6353207		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-22.9596329		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1855444263	1855444263	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1855444263	1855444263	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2732433729	2732433729	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1855444263	1855444263	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	77	77	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.53 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	1507762891
BusOffFltChannel0RecoverTimer_mS_M_u32	0
BusOffFltChannel1DetectionTimer_mS_M_u32	3250810228
BusOffFltChannel1RecoverTimer_mS_M_u32	1843762418
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	30
PPEI_Steering_Wheel_Angle_c[1]	60

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[2]	90		
PPEI_Steering_Wheel_Angle._c[3]	120		
PPEI_Steering_Wheel_Angle._c[4]	150		
PPEI_Steering_Wheel_Angle._c[5]	180		
PPEI_Steering_Wheel_Angle._c[6]	210		
PPEI_Steering_Wheel_Angle._c[7]	240		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	186		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	3801		
k_BusOffFaultTimeChannel1_mS_u16	62734		
k_BusOffRecoveryTimeChannel0_mS_u16	48048		
k_BusOffRecoveryTimeChannel1_mS_u16	12534		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	4690		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2095807797		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	7.01976871		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-1325.50146		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1507762891	1507762891	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3250810228	3250810228	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	2095807797	2095807797	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
EicPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	187	187	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.54 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	3590391628
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295
BusOffFitChannel1DetectionTimer_mS_M_u32	605320333
BusOffFitChannel1RecoverTimer_mS_M_u32	3035835599
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	16
PPEI_Steering_Wheel_Angle_c[1]	32
PPEI_Steering_Wheel_Angle_c[2]	48
PPEI_Steering_Wheel_Angle_c[3]	64

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	80		
PPEI_Steering_Wheel_Angle._c[5]	96		
PPEI_Steering_Wheel_Angle._c[6]	112		
PPEI_Steering_Wheel_Angle._c[7]	128		
PPEI_Steering_Wheel_Angle_CE._c[0]	20		
PPEI_Steering_Wheel_Angle_CE._c[1]	40		
PPEI_Steering_Wheel_Angle_CE._c[2]	60		
PPEI_Steering_Wheel_Angle_CE._c[3]	80		
PPEI_Steering_Wheel_Angle_CE._c[4]	100		
PPEI_Steering_Wheel_Angle_CE._c[5]	120		
PPEI_Steering_Wheel_Angle_CE._c[6]	140		
PPEI_Steering_Wheel_Angle_CE._c[7]	160		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	249		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	13637		
k_BusOffFaultTimeChannel1_mS_u16	8971		
k_BusOffRecoveryTimeChannel0_mS_u16	19358		
k_BusOffRecoveryTimeChannel1_mS_u16	32172		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	55166		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3240586460		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-5.75987291		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	689.842346		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3240586460	3240586460	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3240586460	3240586460	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3240586460	3240586460	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3240586460	3240586460	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	250	250	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.55 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	3566905543
BusOffFltChannel0RecoverTimer_mS_M_u32	3739593150
BusOffFltChannel1DetectionTimer_mS_M_u32	1459989844
BusOffFltChannel1RecoverTimer_mS_M_u32	636010725
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	18
PPEI_Steering_Wheel_Angle_c[1]	36

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[2]	54		
PPEI_Steering_Wheel_Angle._c[3]	72		
PPEI_Steering_Wheel_Angle._c[4]	90		
PPEI_Steering_Wheel_Angle._c[5]	108		
PPEI_Steering_Wheel_Angle._c[6]	126		
PPEI_Steering_Wheel_Angle._c[7]	144		
PPEI_Steering_Wheel_Angle_CE._c[0]	22		
PPEI_Steering_Wheel_Angle_CE._c[1]	44		
PPEI_Steering_Wheel_Angle_CE._c[2]	66		
PPEI_Steering_Wheel_Angle_CE._c[3]	88		
PPEI_Steering_Wheel_Angle_CE._c[4]	110		
PPEI_Steering_Wheel_Angle_CE._c[5]	132		
PPEI_Steering_Wheel_Angle_CE._c[6]	154		
PPEI_Steering_Wheel_Angle_CE._c[7]	176		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	18		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	62758		
k_BusOffFaultTimeChannel1_mS_u16	58595		
k_BusOffRecoveryTimeChannel0_mS_u16	47006		
k_BusOffRecoveryTimeChannel1_mS_u16	25633		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	3034		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3002574782		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	9.15370941		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-183.128632		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3566905543	3566905543	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3002574782	3002574782	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1459989844	1459989844	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	636010725	636010725	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
EicPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	19	19	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStWhlAngAliveRollCnt_0	1	IIPutTxStWhlAngAliveRollCnt_0	1	✓
IIPutTxStWhlAngAliveRollCnt_1	1	IIPutTxStWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.56 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	0
BusOffFitChannel0RecoverTimer_mS_M_u32	940325521
BusOffFitChannel1DetectionTimer_mS_M_u32	4112820998
BusOffFitChannel1RecoverTimer_mS_M_u32	3926186858
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	20
PPEI_Steering_Wheel_Angle_c[1]	40
PPEI_Steering_Wheel_Angle_c[2]	60
PPEI_Steering_Wheel_Angle_c[3]	80

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	100		
PPEI_Steering_Wheel_Angle._c[5]	120		
PPEI_Steering_Wheel_Angle._c[6]	140		
PPEI_Steering_Wheel_Angle._c[7]	160		
PPEI_Steering_Wheel_Angle_CE._c[0]	24		
PPEI_Steering_Wheel_Angle_CE._c[1]	48		
PPEI_Steering_Wheel_Angle_CE._c[2]	72		
PPEI_Steering_Wheel_Angle_CE._c[3]	96		
PPEI_Steering_Wheel_Angle_CE._c[4]	120		
PPEI_Steering_Wheel_Angle_CE._c[5]	144		
PPEI_Steering_Wheel_Angle_CE._c[6]	168		
PPEI_Steering_Wheel_Angle_CE._c[7]	192		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	187		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	51156		
k_BusOffFaultTimeChannel1_mS_u16	24265		
k_BusOffRecoveryTimeChannel0_mS_u16	36439		
k_BusOffRecoveryTimeChannel1_mS_u16	19435		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	13581		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2919309050		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-21.3762703		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-1177.56677		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	2919309050	2919309050	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4112820998	4112820998	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3926186858	3926186858	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	188	188	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.57 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295
BusOffFitChannel0RecoverTimer_mS_M_u32	2475359527
BusOffFitChannel1DetectionTimer_mS_M_u32	1642439818
BusOffFitChannel1RecoverTimer_mS_M_u32	2738218569
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	22
PPEI_Steering_Wheel_Angle_c[1]	44
PPEI_Steering_Wheel_Angle_c[2]	66
PPEI_Steering_Wheel_Angle_c[3]	88

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	110		
PPEI_Steering_Wheel_Angle._c[5]	132		
PPEI_Steering_Wheel_Angle._c[6]	154		
PPEI_Steering_Wheel_Angle._c[7]	176		
PPEI_Steering_Wheel_Angle_CE._c[0]	26		
PPEI_Steering_Wheel_Angle_CE._c[1]	52		
PPEI_Steering_Wheel_Angle_CE._c[2]	78		
PPEI_Steering_Wheel_Angle_CE._c[3]	104		
PPEI_Steering_Wheel_Angle_CE._c[4]	130		
PPEI_Steering_Wheel_Angle_CE._c[5]	156		
PPEI_Steering_Wheel_Angle_CE._c[6]	182		
PPEI_Steering_Wheel_Angle_CE._c[7]	208		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	104		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	29535		
k_BusOffFaultTimeChannel1_mS_u16	58448		
k_BusOffRecoveryTimeChannel0_mS_u16	12500		
k_BusOffRecoveryTimeChannel1_mS_u16	16513		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	35990		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2709874136		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	12.0301609		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-229.48642		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	2709874136	2709874136	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2709874136	2709874136	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	2709874136	2709874136	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
EicPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	105	105	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.58 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	346507361
BusOffFltChannel0RecoverTimer_mS_M_u32	3714978491
BusOffFltChannel1DetectionTimer_mS_M_u32	509811933
BusOffFltChannel1RecoverTimer_mS_M_u32	2346001902
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	24
PPEI_Steering_Wheel_Angle_c[1]	48
PPEI_Steering_Wheel_Angle_c[2]	72

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	96		
PPEI_Steering_Wheel_Angle._c[4]	120		
PPEI_Steering_Wheel_Angle._c[5]	144		
PPEI_Steering_Wheel_Angle._c[6]	168		
PPEI_Steering_Wheel_Angle._c[7]	192		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	27		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	13617		
k_BusOffFaultTimeChannel1_mS_u16	33161		
k_BusOffRecoveryTimeChannel0_mS_u16	26195		
k_BusOffRecoveryTimeChannel1_mS_u16	5117		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	53843		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	134749651		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	5.55456495		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	827.908081		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	346507361	346507361	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	134749651	134749651	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	134749651	134749651	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	134749651	134749651	✔
DrvStrIntfrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	28	28	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.59 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	322219708
BusOffFltChannel0RecoverTimer_mS_M_u32	2596786916
BusOffFltChannel1DetectionTimer_mS_M_u32	203401356
BusOffFltChannel1RecoverTimer_mS_M_u32	0
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	26
PPEI_Steering_Wheel_Angle_c[1]	52
PPEI_Steering_Wheel_Angle_c[2]	78

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	104		
PPEI_Steering_Wheel_Angle._c[4]	130		
PPEI_Steering_Wheel_Angle._c[5]	156		
PPEI_Steering_Wheel_Angle._c[6]	182		
PPEI_Steering_Wheel_Angle._c[7]	208		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	4		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	47604		
k_BusOffFaultTimeChannel1_mS_u16	13552		
k_BusOffRecoveryTimeChannel0_mS_u16	31360		
k_BusOffRecoveryTimeChannel1_mS_u16	38324		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	15964		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2695384328		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-22.6454563		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	982.915405		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	322219708	322219708	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	2695384328	2695384328	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	203401356	203401356	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✓
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✓
StWhlAngAliveRollCnt_Cnt_M_u08	5	5	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.60 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	10483402
BusOffFitChannel0RecoverTimer_mS_M_u32	1617814296
BusOffFitChannel1DetectionTimer_mS_M_u32	1753118193
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	16
PPEI_Steering_Wheel_Angle_c[1]	32
PPEI_Steering_Wheel_Angle_c[2]	48
PPEI_Steering_Wheel_Angle_c[3]	64

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	80		
PPEI_Steering_Wheel_Angle._c[5]	96		
PPEI_Steering_Wheel_Angle._c[6]	112		
PPEI_Steering_Wheel_Angle._c[7]	128		
PPEI_Steering_Wheel_Angle_CE._c[0]	28		
PPEI_Steering_Wheel_Angle_CE._c[1]	56		
PPEI_Steering_Wheel_Angle_CE._c[2]	84		
PPEI_Steering_Wheel_Angle_CE._c[3]	112		
PPEI_Steering_Wheel_Angle_CE._c[4]	140		
PPEI_Steering_Wheel_Angle_CE._c[5]	168		
PPEI_Steering_Wheel_Angle_CE._c[6]	196		
PPEI_Steering_Wheel_Angle_CE._c[7]	224		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	222		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	55704		
k_BusOffFaultTimeChannel1_mS_u16	62445		
k_BusOffRecoveryTimeChannel0_mS_u16	38441		
k_BusOffRecoveryTimeChannel1_mS_u16	53551		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	30525		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3177587742		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	23.8710594		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-10.6546631		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	10483402	10483402	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3177587742	3177587742	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1753118193	1753118193	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3177587742	3177587742	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	223	223	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.61 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	4266546253
BusOffFitChannel0RecoverTimer_mS_M_u32	3446052970
BusOffFitChannel1DetectionTimer_mS_M_u32	2292957595
BusOffFitChannel1RecoverTimer_mS_M_u32	2379236738
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	18
PPEI_Steering_Wheel_Angle_c[1]	36
PPEI_Steering_Wheel_Angle_c[2]	54
PPEI_Steering_Wheel_Angle_c[3]	72

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	90		
PPEI_Steering_Wheel_Angle._c[5]	108		
PPEI_Steering_Wheel_Angle._c[6]	126		
PPEI_Steering_Wheel_Angle._c[7]	144		
PPEI_Steering_Wheel_Angle_CE._c[0]	30		
PPEI_Steering_Wheel_Angle_CE._c[1]	60		
PPEI_Steering_Wheel_Angle_CE._c[2]	90		
PPEI_Steering_Wheel_Angle_CE._c[3]	120		
PPEI_Steering_Wheel_Angle_CE._c[4]	150		
PPEI_Steering_Wheel_Angle_CE._c[5]	180		
PPEI_Steering_Wheel_Angle_CE._c[6]	210		
PPEI_Steering_Wheel_Angle_CE._c[7]	240		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	62		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	13467		
k_BusOffFaultTimeChannel1_mS_u16	52426		
k_BusOffRecoveryTimeChannel0_mS_u16	59299		
k_BusOffRecoveryTimeChannel1_mS_u16	8252		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	15730		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1849319786		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	12.11724		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	219.916		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	4266546253	4266546253	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3446052970	3446052970	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2292957595	2292957595	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1849319786	1849319786	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	63	63	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.62 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	3879368437
BusOffFitChannel0RecoverTimer_mS_M_u32	3532567080
BusOffFitChannel1DetectionTimer_mS_M_u32	0
BusOffFitChannel1RecoverTimer_mS_M_u32	3595671880
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	28
PPEI_Steering_Wheel_Angle_c[1]	56
PPEI_Steering_Wheel_Angle_c[2]	84
PPEI_Steering_Wheel_Angle_c[3]	112

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	140		
PPEI_Steering_Wheel_Angle._c[5]	168		
PPEI_Steering_Wheel_Angle._c[6]	196		
PPEI_Steering_Wheel_Angle._c[7]	224		
PPEI_Steering_Wheel_Angle_CE._c[0]	14		
PPEI_Steering_Wheel_Angle_CE._c[1]	28		
PPEI_Steering_Wheel_Angle_CE._c[2]	42		
PPEI_Steering_Wheel_Angle_CE._c[3]	56		
PPEI_Steering_Wheel_Angle_CE._c[4]	70		
PPEI_Steering_Wheel_Angle_CE._c[5]	84		
PPEI_Steering_Wheel_Angle_CE._c[6]	98		
PPEI_Steering_Wheel_Angle_CE._c[7]	112		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	120		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	8515		
k_BusOffFaultTimeChannel1_mS_u16	11917		
k_BusOffRecoveryTimeChannel0_mS_u16	61499		
k_BusOffRecoveryTimeChannel1_mS_u16	48982		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	10036		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3279727013		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-21.6176167		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1050.73535		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3879368437	3879368437	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3532567080	3532567080	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	0	0	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3279727013	3279727013	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	121	121	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.63 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	4021703263
BusOffFitChannel0RecoverTimer_mS_M_u32	1199704833
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295
BusOffFitChannel1RecoverTimer_mS_M_u32	2617033908
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	30
PPEI_Steering_Wheel_Angle_c[1]	60
PPEI_Steering_Wheel_Angle_c[2]	90
PPEI_Steering_Wheel_Angle_c[3]	120

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	150		
PPEI_Steering_Wheel_Angle._c[5]	180		
PPEI_Steering_Wheel_Angle._c[6]	210		
PPEI_Steering_Wheel_Angle._c[7]	240		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	1		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	27549		
k_BusOffFaultTimeChannel1_mS_u16	45222		
k_BusOffRecoveryTimeChannel0_mS_u16	35030		
k_BusOffRecoveryTimeChannel1_mS_u16	20204		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	5001		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4097806987		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	13.563405		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	516.446106		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	4097806987	4097806987	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4097806987	4097806987	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	4097806987	4097806987	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	2	2	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.64 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	3000594849
BusOffFltChannel0RecoverTimer_mS_M_u32	1623494647
BusOffFltChannel1DetectionTimer_mS_M_u32	339895615
BusOffFltChannel1RecoverTimer_mS_M_u32	1054179161
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	14
PPEI_Steering_Wheel_Angle_c[1]	28
PPEI_Steering_Wheel_Angle_c[2]	42
PPEI_Steering_Wheel_Angle_c[3]	56

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	70		
PPEI_Steering_Wheel_Angle._c[5]	84		
PPEI_Steering_Wheel_Angle._c[6]	98		
PPEI_Steering_Wheel_Angle._c[7]	112		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	219		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	10515		
k_BusOffFaultTimeChannel1_mS_u16	53708		
k_BusOffRecoveryTimeChannel0_mS_u16	56018		
k_BusOffRecoveryTimeChannel1_mS_u16	23150		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	61861		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	368983725		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	3.7332654		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-1114.31091		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	368983725	368983725	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	368983725	368983725	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	339895615	339895615	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	368983725	368983725	✔
DrvStrIntrDetARC_Cnt_M_u08	3	3	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	220	220	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.65 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	3829863315
BusOffFltChannel0RecoverTimer_mS_M_u32	701423612
BusOffFltChannel1DetectionTimer_mS_M_u32	2196850372
BusOffFltChannel1RecoverTimer_mS_M_u32	2449618624
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	16
PPEI_Steering_Wheel_Angle_c[1]	32
PPEI_Steering_Wheel_Angle_c[2]	48

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	64		
PPEI_Steering_Wheel_Angle._c[4]	80		
PPEI_Steering_Wheel_Angle._c[5]	96		
PPEI_Steering_Wheel_Angle._c[6]	112		
PPEI_Steering_Wheel_Angle._c[7]	128		
PPEI_Steering_Wheel_Angle_CE._c[0]	20		
PPEI_Steering_Wheel_Angle_CE._c[1]	40		
PPEI_Steering_Wheel_Angle_CE._c[2]	60		
PPEI_Steering_Wheel_Angle_CE._c[3]	80		
PPEI_Steering_Wheel_Angle_CE._c[4]	100		
PPEI_Steering_Wheel_Angle_CE._c[5]	120		
PPEI_Steering_Wheel_Angle_CE._c[6]	140		
PPEI_Steering_Wheel_Angle_CE._c[7]	160		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	57		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	0		
k_BusOffFaultTimeChannel1_mS_u16	63029		
k_BusOffRecoveryTimeChannel0_mS_u16	34655		
k_BusOffRecoveryTimeChannel1_mS_u16	12731		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	51616		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1780267911		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-15.7024565		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	235.354706		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1780267911	1780267911	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1780267911	1780267911	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	1780267911	1780267911	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	1780267911	1780267911	✓
DrvStrIntfrDetARC_Cnt_M_u08	1	1	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓
StWhlAngAliveRollCnt_Cnt_M_u08	58	58	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.66 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	1920885447
BusOffFltChannel0RecoverTimer_mS_M_u32	3871103185
BusOffFltChannel1DetectionTimer_mS_M_u32	1548604095
BusOffFltChannel1RecoverTimer_mS_M_u32	4123841434
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	18
PPEI_Steering_Wheel_Angle_c[1]	36
PPEI_Steering_Wheel_Angle_c[2]	54

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	72		
PPEI_Steering_Wheel_Angle._c[4]	90		
PPEI_Steering_Wheel_Angle._c[5]	108		
PPEI_Steering_Wheel_Angle._c[6]	126		
PPEI_Steering_Wheel_Angle._c[7]	144		
PPEI_Steering_Wheel_Angle_CE._c[0]	22		
PPEI_Steering_Wheel_Angle_CE._c[1]	44		
PPEI_Steering_Wheel_Angle_CE._c[2]	66		
PPEI_Steering_Wheel_Angle_CE._c[3]	88		
PPEI_Steering_Wheel_Angle_CE._c[4]	110		
PPEI_Steering_Wheel_Angle_CE._c[5]	132		
PPEI_Steering_Wheel_Angle_CE._c[6]	154		
PPEI_Steering_Wheel_Angle_CE._c[7]	176		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	107		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	65535		
k_BusOffFaultTimeChannel1_mS_u16	61563		
k_BusOffRecoveryTimeChannel0_mS_u16	64736		
k_BusOffRecoveryTimeChannel1_mS_u16	65534		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	56520		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	758994773		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	17.7155647		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	715.671692		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	758994773	758994773	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	758994773	758994773	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1548604095	1548604095	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	4123841434	4123841434	✔
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	108	108	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.67 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	2510747909
BusOffFitChannel0RecoverTimer_mS_M_u32	4159399220
BusOffFitChannel1DetectionTimer_mS_M_u32	62619783
BusOffFitChannel1RecoverTimer_mS_M_u32	3350796487
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	20
PPEI_Steering_Wheel_Angle_c[1]	40
PPEI_Steering_Wheel_Angle_c[2]	60
PPEI_Steering_Wheel_Angle_c[3]	80

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	100		
PPEI_Steering_Wheel_Angle._c[5]	120		
PPEI_Steering_Wheel_Angle._c[6]	140		
PPEI_Steering_Wheel_Angle._c[7]	160		
PPEI_Steering_Wheel_Angle_CE._c[0]	24		
PPEI_Steering_Wheel_Angle_CE._c[1]	48		
PPEI_Steering_Wheel_Angle_CE._c[2]	72		
PPEI_Steering_Wheel_Angle_CE._c[3]	96		
PPEI_Steering_Wheel_Angle_CE._c[4]	120		
PPEI_Steering_Wheel_Angle_CE._c[5]	144		
PPEI_Steering_Wheel_Angle_CE._c[6]	168		
PPEI_Steering_Wheel_Angle_CE._c[7]	192		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	145		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	13677		
k_BusOffFaultTimeChannel1_mS_u16	19603		
k_BusOffRecoveryTimeChannel0_mS_u16	5500		
k_BusOffRecoveryTimeChannel1_mS_u16	19174		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	51560		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3765029529		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-0.558855772		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-872.09967		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3765029529	3765029529	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3765029529	3765029529	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3765029529	3765029529	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3765029529	3765029529	✔
DrvStrIntrDetARC_Cnt_M_u08	3	3	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	146	146	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.68 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	1937912948
BusOffFltChannel0RecoverTimer_mS_M_u32	4139276937
BusOffFltChannel1DetectionTimer_mS_M_u32	2002847163
BusOffFltChannel1RecoverTimer_mS_M_u32	631492272
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	22
PPEI_Steering_Wheel_Angle_c[1]	44
PPEI_Steering_Wheel_Angle_c[2]	66

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	88		
PPEI_Steering_Wheel_Angle._c[4]	110		
PPEI_Steering_Wheel_Angle._c[5]	132		
PPEI_Steering_Wheel_Angle._c[6]	154		
PPEI_Steering_Wheel_Angle._c[7]	176		
PPEI_Steering_Wheel_Angle_CE._c[0]	30		
PPEI_Steering_Wheel_Angle_CE._c[1]	60		
PPEI_Steering_Wheel_Angle_CE._c[2]	90		
PPEI_Steering_Wheel_Angle_CE._c[3]	120		
PPEI_Steering_Wheel_Angle_CE._c[4]	150		
PPEI_Steering_Wheel_Angle_CE._c[5]	180		
PPEI_Steering_Wheel_Angle_CE._c[6]	210		
PPEI_Steering_Wheel_Angle_CE._c[7]	240		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	198		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	1000		
k_BusOffFaultTimeChannel1_mS_u16	8966		
k_BusOffRecoveryTimeChannel0_mS_u16	37486		
k_BusOffRecoveryTimeChannel1_mS_u16	57711		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	40279		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3454533914		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-21.5827389		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	1219.24609		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3454533914	3454533914	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3454533914	3454533914	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2002847163	2002847163	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	631492272	631492272	✔
DrvStrIntfrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	199	199	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.69 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	3590884330
BusOffFltChannel0RecoverTimer_mS_M_u32	2708829278
BusOffFltChannel1DetectionTimer_mS_M_u32	3368336096
BusOffFltChannel1RecoverTimer_mS_M_u32	1039625514
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	24
PPEI_Steering_Wheel_Angle_c[1]	48
PPEI_Steering_Wheel_Angle_c[2]	72
PPEI_Steering_Wheel_Angle_c[3]	96

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	120		
PPEI_Steering_Wheel_Angle._c[5]	144		
PPEI_Steering_Wheel_Angle._c[6]	168		
PPEI_Steering_Wheel_Angle._c[7]	192		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	126		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	45900		
k_BusOffFaultTimeChannel1_mS_u16	4898		
k_BusOffRecoveryTimeChannel0_mS_u16	0		
k_BusOffRecoveryTimeChannel1_mS_u16	7991		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	52626		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1201609826		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-4.86617661		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	987.564758		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3590884330	3590884330	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1201609826	1201609826	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1201609826	1201609826	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1201609826	1201609826	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	127	127	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtcdV	1	IIPutTxDrvStrIntfrDtcdV	1	✓
IIPutTxDrvStrIntfrDtcd	1	IIPutTxDrvStrIntfrDtcd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtcdGroup	1	IIPutTxDrvStrIntfrDtcdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.70 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	1110183199
BusOffFltChannel0RecoverTimer_mS_M_u32	3658412100
BusOffFltChannel1DetectionTimer_mS_M_u32	1131764025
BusOffFltChannel1RecoverTimer_mS_M_u32	3848154127
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	26
PPEI_Steering_Wheel_Angle_c[1]	52
PPEI_Steering_Wheel_Angle_c[2]	78

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	104		
PPEI_Steering_Wheel_Angle._c[4]	130		
PPEI_Steering_Wheel_Angle._c[5]	156		
PPEI_Steering_Wheel_Angle._c[6]	182		
PPEI_Steering_Wheel_Angle._c[7]	208		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	38		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	49007		
k_BusOffFaultTimeChannel1_mS_u16	35115		
k_BusOffRecoveryTimeChannel0_mS_u16	65535		
k_BusOffRecoveryTimeChannel1_mS_u16	65035		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	36190		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3015894455		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	25.6192493		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-540.052551		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1110183199	1110183199	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3015894455	3015894455	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1131764025	1131764025	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3848154127	3848154127	✔
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	39	39	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.71 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	1330775293
BusOffFitChannel0RecoverTimer_mS_M_u32	1580957345
BusOffFitChannel1DetectionTimer_mS_M_u32	2000596085
BusOffFitChannel1RecoverTimer_mS_M_u32	242359490
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	22
PPEI_Steering_Wheel_Angle_c[1]	44
PPEI_Steering_Wheel_Angle_c[2]	66
PPEI_Steering_Wheel_Angle_c[3]	88

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	110		
PPEI_Steering_Wheel_Angle._c[5]	132		
PPEI_Steering_Wheel_Angle._c[6]	154		
PPEI_Steering_Wheel_Angle._c[7]	176		
PPEI_Steering_Wheel_Angle_CE._c[0]	30		
PPEI_Steering_Wheel_Angle_CE._c[1]	60		
PPEI_Steering_Wheel_Angle_CE._c[2]	90		
PPEI_Steering_Wheel_Angle_CE._c[3]	120		
PPEI_Steering_Wheel_Angle_CE._c[4]	150		
PPEI_Steering_Wheel_Angle_CE._c[5]	180		
PPEI_Steering_Wheel_Angle_CE._c[6]	210		
PPEI_Steering_Wheel_Angle_CE._c[7]	240		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	213		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	40524		
k_BusOffFaultTimeChannel1_mS_u16	16398		
k_BusOffRecoveryTimeChannel0_mS_u16	42112		
k_BusOffRecoveryTimeChannel1_mS_u16	63242		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	18723		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1043293152		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	10.8111286		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-291.093994		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1330775293	1330775293	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	1043293152	1043293152	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2000596085	2000596085	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	242359490	242359490	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	214	214	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.72 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	559451262
BusOffFltChannel0RecoverTimer_mS_M_u32	3395211183
BusOffFltChannel1DetectionTimer_mS_M_u32	4141957109
BusOffFltChannel1RecoverTimer_mS_M_u32	2919438812
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	24
PPEI_Steering_Wheel_Angle_c[1]	48
PPEI_Steering_Wheel_Angle_c[2]	72
PPEI_Steering_Wheel_Angle_c[3]	96

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	120		
PPEI_Steering_Wheel_Angle._c[5]	144		
PPEI_Steering_Wheel_Angle._c[6]	168		
PPEI_Steering_Wheel_Angle._c[7]	192		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	64		
k_APAMfgEnable_Cnt_lgc	0		
k_BusOffFaultTimeChannel0_mS_u16	23652		
k_BusOffFaultTimeChannel1_mS_u16	29681		
k_BusOffRecoveryTimeChannel0_mS_u16	11968		
k_BusOffRecoveryTimeChannel1_mS_u16	63297		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	31943		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	390454589		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-22.6247292		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	188.352951		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	559451262	559451262	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	390454589	390454589	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4141957109	4141957109	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	2919438812	2919438812	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	65	65	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
CanPartOffline	1	CanPartOffline	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.73 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	4059583279
BusOffFitChannel0RecoverTimer_mS_M_u32	2729308455
BusOffFitChannel1DetectionTimer_mS_M_u32	3860271505
BusOffFitChannel1RecoverTimer_mS_M_u32	3517419345
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	26
PPEI_Steering_Wheel_Angle_c[1]	52
PPEI_Steering_Wheel_Angle_c[2]	78
PPEI_Steering_Wheel_Angle_c[3]	104
PPEI_Steering_Wheel_Angle_c[4]	130
PPEI_Steering_Wheel_Angle_c[5]	156
PPEI_Steering_Wheel_Angle_c[6]	182
PPEI_Steering_Wheel_Angle_c[7]	208
PPEI_Steering_Wheel_Angle_CE_c[0]	18
PPEI_Steering_Wheel_Angle_CE_c[1]	36
PPEI_Steering_Wheel_Angle_CE_c[2]	54
PPEI_Steering_Wheel_Angle_CE_c[3]	72
PPEI_Steering_Wheel_Angle_CE_c[4]	90
PPEI_Steering_Wheel_Angle_CE_c[5]	108

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle_CE_c[6]	126		
PPEI_Steering_Wheel_Angle_CE_c[7]	144		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	7		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	47376		
k_BusOffFaultTimeChannel1_mS_u16	35461		
k_BusOffRecoveryTimeChannel0_mS_u16	9391		
k_BusOffRecoveryTimeChannel1_mS_u16	47006		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	28751		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2613937981		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-30.8670444		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	943.59198		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFltChannel0DetectionTimer_mS_M_u32	4059583279	4059583279	✓
BusOffFltChannel0RecoverTimer_mS_M_u32	2613937981	2613937981	✓
BusOffFltChannel1DetectionTimer_mS_M_u32	3860271505	3860271505	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	2613937981	2613937981	✓
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✓
StWhlAngAliveRollCnt_Cnt_M_u08	8	8	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.74 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	1466035259
BusOffFitChannel0RecoverTimer_mS_M_u32	1576912992
BusOffFitChannel1DetectionTimer_mS_M_u32	147909499
BusOffFitChannel1RecoverTimer_mS_M_u32	997502199
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	0
PPEI_Steering_Wheel_Angle_c[1]	0
PPEI_Steering_Wheel_Angle_c[2]	0
PPEI_Steering_Wheel_Angle_c[3]	0

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	0		
PPEI_Steering_Wheel_Angle._c[5]	0		
PPEI_Steering_Wheel_Angle._c[6]	0		
PPEI_Steering_Wheel_Angle._c[7]	0		
PPEI_Steering_Wheel_Angle_CE._c[0]	20		
PPEI_Steering_Wheel_Angle_CE._c[1]	40		
PPEI_Steering_Wheel_Angle_CE._c[2]	60		
PPEI_Steering_Wheel_Angle_CE._c[3]	80		
PPEI_Steering_Wheel_Angle_CE._c[4]	100		
PPEI_Steering_Wheel_Angle_CE._c[5]	120		
PPEI_Steering_Wheel_Angle_CE._c[6]	140		
PPEI_Steering_Wheel_Angle_CE._c[7]	160		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	217		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	54819		
k_BusOffFaultTimeChannel1_mS_u16	65211		
k_BusOffRecoveryTimeChannel0_mS_u16	5793		
k_BusOffRecoveryTimeChannel1_mS_u16	36439		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	57140		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3291116685		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	25.8563137		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	-331.132233		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1466035259	1466035259	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3291116685	3291116685	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	147909499	147909499	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3291116685	3291116685	✔
DrvStrIntrDetARC_Cnt_M_u08	3	3	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	218	218	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.75 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	658205117
BusOffFitChannel0RecoverTimer_mS_M_u32	3609228358
BusOffFitChannel1DetectionTimer_mS_M_u32	3035880882
BusOffFitChannel1RecoverTimer_mS_M_u32	1661613199
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	255
PPEI_Steering_Wheel_Angle_c[1]	255
PPEI_Steering_Wheel_Angle_c[2]	255
PPEI_Steering_Wheel_Angle_c[3]	255

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	255		
PPEI_Steering_Wheel_Angle._c[5]	255		
PPEI_Steering_Wheel_Angle._c[6]	255		
PPEI_Steering_Wheel_Angle._c[7]	255		
PPEI_Steering_Wheel_Angle_CE._c[0]	22		
PPEI_Steering_Wheel_Angle_CE._c[1]	44		
PPEI_Steering_Wheel_Angle_CE._c[2]	66		
PPEI_Steering_Wheel_Angle_CE._c[3]	88		
PPEI_Steering_Wheel_Angle_CE._c[4]	110		
PPEI_Steering_Wheel_Angle_CE._c[5]	132		
PPEI_Steering_Wheel_Angle_CE._c[6]	154		
PPEI_Steering_Wheel_Angle_CE._c[7]	176		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	57		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	26830		
k_BusOffFaultTimeChannel1_mS_u16	19929		
k_BusOffRecoveryTimeChannel0_mS_u16	17265		
k_BusOffRecoveryTimeChannel1_mS_u16	12500		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65288		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2423526790		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-24.1671791		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1162.44739		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	658205117	658205117	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	2423526790	2423526790	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3035880882	3035880882	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	2423526790	2423526790	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	58	58	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStWhlAngAliveRollCnt_0	1	IIPutTxStWhlAngAliveRollCnt_0	1	✓
IIPutTxStWhlAngAliveRollCnt_1	1	IIPutTxStWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.76 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	3858153056
BusOffFltChannel0RecoverTimer_mS_M_u32	3523057207
BusOffFltChannel1DetectionTimer_mS_M_u32	3887482753
BusOffFltChannel1RecoverTimer_mS_M_u32	1442058602
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	10
PPEI_Steering_Wheel_Angle_c[1]	20
PPEI_Steering_Wheel_Angle_c[2]	30

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	40		
PPEI_Steering_Wheel_Angle._c[4]	50		
PPEI_Steering_Wheel_Angle._c[5]	60		
PPEI_Steering_Wheel_Angle._c[6]	70		
PPEI_Steering_Wheel_Angle._c[7]	80		
PPEI_Steering_Wheel_Angle_CE._c[0]	24		
PPEI_Steering_Wheel_Angle_CE._c[1]	48		
PPEI_Steering_Wheel_Angle_CE._c[2]	72		
PPEI_Steering_Wheel_Angle_CE._c[3]	96		
PPEI_Steering_Wheel_Angle_CE._c[4]	120		
PPEI_Steering_Wheel_Angle_CE._c[5]	144		
PPEI_Steering_Wheel_Angle_CE._c[6]	168		
PPEI_Steering_Wheel_Angle_CE._c[7]	192		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	93		
k_APAMfgEnable_Cnt_lgc	0		
k_BusOffFaultTimeChannel0_mS_u16	55932		
k_BusOffFaultTimeChannel1_mS_u16	0		
k_BusOffRecoveryTimeChannel0_mS_u16	10907		
k_BusOffRecoveryTimeChannel1_mS_u16	26195		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	7560		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3192053280		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-9.36545563		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1236.32922		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	3858153056	3858153056	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3192053280	3192053280	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3887482753	3887482753	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3192053280	3192053280	✓
DrvStrIntfrDetARC_Cnt_M_u08	0	0	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✓
StWhlAngAliveRollCnt_Cnt_M_u08	94	94	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
CanPartOffline	1	CanPartOffline	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.77 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	2655332625
BusOffFitChannel0RecoverTimer_mS_M_u32	2015922170
BusOffFitChannel1DetectionTimer_mS_M_u32	313288734
BusOffFitChannel1RecoverTimer_mS_M_u32	155157144
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntrDetARC_Cnt_M_u08	1
EicPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	24
PPEI_Steering_Wheel_Angle_c[1]	48
PPEI_Steering_Wheel_Angle_c[2]	72
PPEI_Steering_Wheel_Angle_c[3]	96
PPEI_Steering_Wheel_Angle_c[4]	120
PPEI_Steering_Wheel_Angle_c[5]	144
PPEI_Steering_Wheel_Angle_c[6]	168
PPEI_Steering_Wheel_Angle_c[7]	192
PPEI_Steering_Wheel_Angle_CE_c[0]	0
PPEI_Steering_Wheel_Angle_CE_c[1]	0
PPEI_Steering_Wheel_Angle_CE_c[2]	0
PPEI_Steering_Wheel_Angle_CE_c[3]	0
PPEI_Steering_Wheel_Angle_CE_c[4]	0

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle_CE_c[5]	0		
PPEI_Steering_Wheel_Angle_CE_c[6]	0		
PPEI_Steering_Wheel_Angle_CE_c[7]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	68		
k_APAMfgEnable_Cnt_lgc	0		
k_BusOffFaultTimeChannel0_mS_u16	17146		
k_BusOffFaultTimeChannel1_mS_u16	65535		
k_BusOffRecoveryTimeChannel0_mS_u16	39759		
k_BusOffRecoveryTimeChannel1_mS_u16	31360		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	39753		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2850387517		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	10.6451216		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	549.426819		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2655332625	2655332625	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	2015922170	2015922170	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	313288734	313288734	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	2850387517	2850387517	✓
DrvStrIntfrDetARC_Cnt_M_u08	1	1	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓
StWhlAngAliveRollCnt_Cnt_M_u08	69	69	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
CanPartOffline	1	CanPartOffline	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.78 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	737424416
BusOffFitChannel0RecoverTimer_mS_M_u32	1204362992
BusOffFitChannel1DetectionTimer_mS_M_u32	2055402607
BusOffFitChannel1RecoverTimer_mS_M_u32	2021722745
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrInfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	26
PPEI_Steering_Wheel_Angle_c[1]	52
PPEI_Steering_Wheel_Angle_c[2]	78
PPEI_Steering_Wheel_Angle_c[3]	104
PPEI_Steering_Wheel_Angle_c[4]	130
PPEI_Steering_Wheel_Angle_c[5]	156
PPEI_Steering_Wheel_Angle_c[6]	182
PPEI_Steering_Wheel_Angle_c[7]	208
PPEI_Steering_Wheel_Angle_CE_c[0]	255
PPEI_Steering_Wheel_Angle_CE_c[1]	255
PPEI_Steering_Wheel_Angle_CE_c[2]	255
PPEI_Steering_Wheel_Angle_CE_c[3]	255
PPEI_Steering_Wheel_Angle_CE_c[4]	255
PPEI_Steering_Wheel_Angle_CE_c[5]	255

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle_CE_c[6]	255		
PPEI_Steering_Wheel_Angle_CE_c[7]	255		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	101		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	62055		
k_BusOffFaultTimeChannel1_mS_u16	12452		
k_BusOffRecoveryTimeChannel0_mS_u16	62363		
k_BusOffRecoveryTimeChannel1_mS_u16	18371		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	61686		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	48424		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-4.64953566		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1330.83582		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFltChannel0DetectionTimer_mS_M_u32	737424416	737424416	✔
BusOffFltChannel0RecoverTimer_mS_M_u32	1204362992	1204362992	✔
BusOffFltChannel1DetectionTimer_mS_M_u32	2055402607	2055402607	✔
BusOffFltChannel1RecoverTimer_mS_M_u32	48424	48424	✔
DrvStrIntfrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	102	102	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtcdV	1	IIPutTxDrvStrIntfrDtcdV	1	✓
IIPutTxDrvStrIntfrDtcd	1	IIPutTxDrvStrIntfrDtcd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtcdGroup	1	IIPutTxDrvStrIntfrDtcdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.79 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	2262677549
BusOffFltChannel0RecoverTimer_mS_M_u32	2197589316
BusOffFltChannel1DetectionTimer_mS_M_u32	963718930
BusOffFltChannel1RecoverTimer_mS_M_u32	2096261112
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	28
PPEI_Steering_Wheel_Angle_c[1]	56
PPEI_Steering_Wheel_Angle_c[2]	84

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	112		
PPEI_Steering_Wheel_Angle._c[4]	140		
PPEI_Steering_Wheel_Angle._c[5]	168		
PPEI_Steering_Wheel_Angle._c[6]	196		
PPEI_Steering_Wheel_Angle._c[7]	224		
PPEI_Steering_Wheel_Angle_CE._c[0]	10		
PPEI_Steering_Wheel_Angle_CE._c[1]	20		
PPEI_Steering_Wheel_Angle_CE._c[2]	30		
PPEI_Steering_Wheel_Angle_CE._c[3]	40		
PPEI_Steering_Wheel_Angle_CE._c[4]	50		
PPEI_Steering_Wheel_Angle_CE._c[5]	60		
PPEI_Steering_Wheel_Angle_CE._c[6]	70		
PPEI_Steering_Wheel_Angle_CE._c[7]	80		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElaspedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElaspedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	135		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	29759		
k_BusOffFaultTimeChannel1_mS_u16	1000		
k_BusOffRecoveryTimeChannel0_mS_u16	31364		
k_BusOffRecoveryTimeChannel1_mS_u16	27065		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElaspedTime_mS_u16_ElapsedTime	56603		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	39530		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	14.1935577		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	1238.29565		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	39530	39530	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	39530	39530	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	963718930	963718930	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	39530	39530	✔
DrvStrIntfrDetARC_Cnt_M_u08	3	3	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	136	136	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.80 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	3179664607
BusOffFltChannel0RecoverTimer_mS_M_u32	2448003744
BusOffFltChannel1DetectionTimer_mS_M_u32	2640720543
BusOffFltChannel1RecoverTimer_mS_M_u32	2436843441
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	2
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	10
PPEI_Steering_Wheel_Angle_c[1]	20

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[2]	30		
PPEI_Steering_Wheel_Angle._c[3]	40		
PPEI_Steering_Wheel_Angle._c[4]	50		
PPEI_Steering_Wheel_Angle._c[5]	60		
PPEI_Steering_Wheel_Angle._c[6]	70		
PPEI_Steering_Wheel_Angle._c[7]	80		
PPEI_Steering_Wheel_Angle_CE._c[0]	24		
PPEI_Steering_Wheel_Angle_CE._c[1]	48		
PPEI_Steering_Wheel_Angle_CE._c[2]	72		
PPEI_Steering_Wheel_Angle_CE._c[3]	96		
PPEI_Steering_Wheel_Angle_CE._c[4]	120		
PPEI_Steering_Wheel_Angle_CE._c[5]	144		
PPEI_Steering_Wheel_Angle_CE._c[6]	168		
PPEI_Steering_Wheel_Angle_CE._c[7]	192		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	40		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	20080		
k_BusOffFaultTimeChannel1_mS_u16	21509		
k_BusOffRecoveryTimeChannel0_mS_u16	52831		
k_BusOffRecoveryTimeChannel1_mS_u16	0		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	63136		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	30588		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-26.4363842		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	1124.91003		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	30588	30588	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	30588	30588	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2640720543	2640720543	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	30588	30588	✔
DrvStrIntrDetARC_Cnt_M_u08	3	3	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	41	41	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.81 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	1520636547
BusOffFltChannel0RecoverTimer_mS_M_u32	3731736754
BusOffFltChannel1DetectionTimer_mS_M_u32	3378742667
BusOffFltChannel1RecoverTimer_mS_M_u32	831859909
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	18
PPEI_Steering_Wheel_Angle_c[1]	36

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[2]	54		
PPEI_Steering_Wheel_Angle._c[3]	72		
PPEI_Steering_Wheel_Angle._c[4]	90		
PPEI_Steering_Wheel_Angle._c[5]	108		
PPEI_Steering_Wheel_Angle._c[6]	126		
PPEI_Steering_Wheel_Angle._c[7]	144		
PPEI_Steering_Wheel_Angle_CE._c[0]	22		
PPEI_Steering_Wheel_Angle_CE._c[1]	44		
PPEI_Steering_Wheel_Angle_CE._c[2]	66		
PPEI_Steering_Wheel_Angle_CE._c[3]	88		
PPEI_Steering_Wheel_Angle_CE._c[4]	110		
PPEI_Steering_Wheel_Angle_CE._c[5]	132		
PPEI_Steering_Wheel_Angle_CE._c[6]	154		
PPEI_Steering_Wheel_Angle_CE._c[7]	176		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	6		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	11622		
k_BusOffFaultTimeChannel1_mS_u16	29949		
k_BusOffRecoveryTimeChannel0_mS_u16	64467		
k_BusOffRecoveryTimeChannel1_mS_u16	65535		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	31124		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	55218		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-16.3532429		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	882.278748		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1520636547	1520636547	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3731736754	3731736754	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3378742667	3378742667	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	55218	55218	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	7	7	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtcdV	1	IIPutTxDrvStrIntfrDtcdV	1	✓
IIPutTxDrvStrIntfrDtcd	1	IIPutTxDrvStrIntfrDtcd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtcdGroup	1	IIPutTxDrvStrIntfrDtcdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.82 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	1182004451
BusOffFltChannel0RecoverTimer_mS_M_u32	1240928749
BusOffFltChannel1DetectionTimer_mS_M_u32	1356970811
BusOffFltChannel1RecoverTimer_mS_M_u32	3778347883
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	20
PPEI_Steering_Wheel_Angle_c[1]	40
PPEI_Steering_Wheel_Angle_c[2]	60

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	80		
PPEI_Steering_Wheel_Angle._c[4]	100		
PPEI_Steering_Wheel_Angle._c[5]	120		
PPEI_Steering_Wheel_Angle._c[6]	140		
PPEI_Steering_Wheel_Angle._c[7]	160		
PPEI_Steering_Wheel_Angle_CE._c[0]	24		
PPEI_Steering_Wheel_Angle_CE._c[1]	48		
PPEI_Steering_Wheel_Angle_CE._c[2]	72		
PPEI_Steering_Wheel_Angle_CE._c[3]	96		
PPEI_Steering_Wheel_Angle_CE._c[4]	120		
PPEI_Steering_Wheel_Angle_CE._c[5]	144		
PPEI_Steering_Wheel_Angle_CE._c[6]	168		
PPEI_Steering_Wheel_Angle_CE._c[7]	192		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	226		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	18107		
k_BusOffFaultTimeChannel1_mS_u16	39781		
k_BusOffRecoveryTimeChannel0_mS_u16	18204		
k_BusOffRecoveryTimeChannel1_mS_u16	34565		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	9230		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2793		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	16.7141685		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	821.422607		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1182004451	1182004451	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	2793	2793	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	1356970811	1356970811	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	2793	2793	✓
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✓
StWhlAngAliveRollCnt_Cnt_M_u08	227	227	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.83 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	2220103868
BusOffFltChannel0RecoverTimer_mS_M_u32	4215023642
BusOffFltChannel1DetectionTimer_mS_M_u32	1465552565
BusOffFltChannel1RecoverTimer_mS_M_u32	334769454
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	22
PPEI_Steering_Wheel_Angle_c[1]	44
PPEI_Steering_Wheel_Angle_c[2]	66
PPEI_Steering_Wheel_Angle_c[3]	88

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	110		
PPEI_Steering_Wheel_Angle._c[5]	132		
PPEI_Steering_Wheel_Angle._c[6]	154		
PPEI_Steering_Wheel_Angle._c[7]	176		
PPEI_Steering_Wheel_Angle_CE._c[0]	26		
PPEI_Steering_Wheel_Angle_CE._c[1]	52		
PPEI_Steering_Wheel_Angle_CE._c[2]	78		
PPEI_Steering_Wheel_Angle_CE._c[3]	104		
PPEI_Steering_Wheel_Angle_CE._c[4]	130		
PPEI_Steering_Wheel_Angle_CE._c[5]	156		
PPEI_Steering_Wheel_Angle_CE._c[6]	182		
PPEI_Steering_Wheel_Angle_CE._c[7]	208		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	23		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	49039		
k_BusOffFaultTimeChannel1_mS_u16	10524		
k_BusOffRecoveryTimeChannel0_mS_u16	61512		
k_BusOffRecoveryTimeChannel1_mS_u16	14445		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	3781		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	0		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-1.74688768		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	-54.1897316		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	2220103868	2220103868	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	1465552565	1465552565	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✔
DrvStrIntrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	24	24	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.84 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	2024005050
BusOffFitChannel0RecoverTimer_mS_M_u32	1508051886
BusOffFitChannel1DetectionTimer_mS_M_u32	2310498599
BusOffFitChannel1RecoverTimer_mS_M_u32	3407389039
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	24
PPEI_Steering_Wheel_Angle_c[1]	48
PPEI_Steering_Wheel_Angle_c[2]	72
PPEI_Steering_Wheel_Angle_c[3]	96

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	120		
PPEI_Steering_Wheel_Angle._c[5]	144		
PPEI_Steering_Wheel_Angle._c[6]	168		
PPEI_Steering_Wheel_Angle._c[7]	192		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	165		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	16031		
k_BusOffFaultTimeChannel1_mS_u16	63401		
k_BusOffRecoveryTimeChannel0_mS_u16	20459		
k_BusOffRecoveryTimeChannel1_mS_u16	42549		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	33400		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4294967295		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	20.6225338		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	858.048828		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2310498599	2310498599	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295	4294967295	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	166	166	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.85 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	1141139473
BusOffFltChannel0RecoverTimer_mS_M_u32	3028661363
BusOffFltChannel1DetectionTimer_mS_M_u32	4133502332
BusOffFltChannel1RecoverTimer_mS_M_u32	869954929
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	26
PPEI_Steering_Wheel_Angle_c[1]	52
PPEI_Steering_Wheel_Angle_c[2]	78

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	104		
PPEI_Steering_Wheel_Angle._c[4]	130		
PPEI_Steering_Wheel_Angle._c[5]	156		
PPEI_Steering_Wheel_Angle._c[6]	182		
PPEI_Steering_Wheel_Angle._c[7]	208		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	216		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	62882		
k_BusOffFaultTimeChannel1_mS_u16	32626		
k_BusOffRecoveryTimeChannel0_mS_u16	47297		
k_BusOffRecoveryTimeChannel1_mS_u16	62480		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	16862		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	181274224		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-7.97779417		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	412.973419		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1141139473	1141139473	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3028661363	3028661363	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4133502332	4133502332	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	181274224	181274224	✔
DrvStrIntfrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	217	217	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStWhlAngAliveRollCnt_0	1	IIPutTxStWhlAngAliveRollCnt_0	1	✓
IIPutTxStWhlAngAliveRollCnt_1	1	IIPutTxStWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.86 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	1389564581
BusOffFltChannel0RecoverTimer_mS_M_u32	559735629
BusOffFltChannel1DetectionTimer_mS_M_u32	799101998
BusOffFltChannel1RecoverTimer_mS_M_u32	1186371908
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	16
PPEI_Steering_Wheel_Angle_c[1]	32
PPEI_Steering_Wheel_Angle_c[2]	48
PPEI_Steering_Wheel_Angle_c[3]	64

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	80		
PPEI_Steering_Wheel_Angle._c[5]	96		
PPEI_Steering_Wheel_Angle._c[6]	112		
PPEI_Steering_Wheel_Angle._c[7]	128		
PPEI_Steering_Wheel_Angle_CE._c[0]	28		
PPEI_Steering_Wheel_Angle_CE._c[1]	56		
PPEI_Steering_Wheel_Angle_CE._c[2]	84		
PPEI_Steering_Wheel_Angle_CE._c[3]	112		
PPEI_Steering_Wheel_Angle_CE._c[4]	140		
PPEI_Steering_Wheel_Angle_CE._c[5]	168		
PPEI_Steering_Wheel_Angle_CE._c[6]	196		
PPEI_Steering_Wheel_Angle_CE._c[7]	224		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	16		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	38048		
k_BusOffFaultTimeChannel1_mS_u16	40526		
k_BusOffRecoveryTimeChannel0_mS_u16	20076		
k_BusOffRecoveryTimeChannel1_mS_u16	61434		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	50513		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-25.6838264		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	639.865845		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1389564581	1389564581	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	559735629	559735629	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	50513	50513	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	50513	50513	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	2	2	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	17	17	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.87 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	2507748237
BusOffFitChannel0RecoverTimer_mS_M_u32	1156015995
BusOffFitChannel1DetectionTimer_mS_M_u32	3166590578
BusOffFitChannel1RecoverTimer_mS_M_u32	2863529211
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	18
PPEI_Steering_Wheel_Angle_c[1]	36
PPEI_Steering_Wheel_Angle_c[2]	54
PPEI_Steering_Wheel_Angle_c[3]	72

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	90		
PPEI_Steering_Wheel_Angle._c[5]	108		
PPEI_Steering_Wheel_Angle._c[6]	126		
PPEI_Steering_Wheel_Angle._c[7]	144		
PPEI_Steering_Wheel_Angle_CE._c[0]	30		
PPEI_Steering_Wheel_Angle_CE._c[1]	60		
PPEI_Steering_Wheel_Angle_CE._c[2]	90		
PPEI_Steering_Wheel_Angle_CE._c[3]	120		
PPEI_Steering_Wheel_Angle_CE._c[4]	150		
PPEI_Steering_Wheel_Angle_CE._c[5]	180		
PPEI_Steering_Wheel_Angle_CE._c[6]	210		
PPEI_Steering_Wheel_Angle_CE._c[7]	240		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	38		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	48016		
k_BusOffFaultTimeChannel1_mS_u16	15566		
k_BusOffRecoveryTimeChannel0_mS_u16	10225		
k_BusOffRecoveryTimeChannel1_mS_u16	37061		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	47282		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	-25.6503906		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	1027.47131		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	47282	47282	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	47282	47282	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3166590578	3166590578	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	47282	47282	✓
DrvStrIntrDetARC_Cnt_M_u08	2	2	✓
EicPwrStrAvalStatARC_Cnt_M_u08	2	2	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	1	1	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓
StWhlAngAliveRollCnt_Cnt_M_u08	39	39	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 2.88 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	72584429
BusOffFltChannel0RecoverTimer_mS_M_u32	4213323502
BusOffFltChannel1DetectionTimer_mS_M_u32	3646356462
BusOffFltChannel1RecoverTimer_mS_M_u32	752442014
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	28
PPEI_Steering_Wheel_Angle_c[1]	56

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[2]	84		
PPEI_Steering_Wheel_Angle._c[3]	112		
PPEI_Steering_Wheel_Angle._c[4]	140		
PPEI_Steering_Wheel_Angle._c[5]	168		
PPEI_Steering_Wheel_Angle._c[6]	196		
PPEI_Steering_Wheel_Angle._c[7]	224		
PPEI_Steering_Wheel_Angle_CE._c[0]	14		
PPEI_Steering_Wheel_Angle_CE._c[1]	28		
PPEI_Steering_Wheel_Angle_CE._c[2]	42		
PPEI_Steering_Wheel_Angle_CE._c[3]	56		
PPEI_Steering_Wheel_Angle_CE._c[4]	70		
PPEI_Steering_Wheel_Angle_CE._c[5]	84		
PPEI_Steering_Wheel_Angle_CE._c[6]	98		
PPEI_Steering_Wheel_Angle_CE._c[7]	112		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	226		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	14816		
k_BusOffFaultTimeChannel1_mS_u16	1000		
k_BusOffRecoveryTimeChannel0_mS_u16	18050		
k_BusOffRecoveryTimeChannel1_mS_u16	59917		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	12542		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	34946		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	2.03915954		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	485.390015		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	72584429	72584429	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4213323502	4213323502	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3646356462	3646356462	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	34946	34946	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	227	227	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32	1	Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SriComOutput_SriComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SriComOutput_SriComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SriComOutput_APASState_State_enum	1	Rte_Read_Ap_SriComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtcdV	1	IIPutTxDrvStrIntfrDtcdV	1	✓
IIPutTxDrvStrIntfrDtcd	1	IIPutTxDrvStrIntfrDtcd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtcdGroup	1	IIPutTxDrvStrIntfrDtcdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SriComOutput_BusOffHandler	1	SriComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc	1	✓

Test Case 3: Path Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment) CPU Cycles: TS 3.1 10140 Cycles TS 3.2 14055 Cycles TS 3.3 13833 Cycles TS 3.4 13571 Cycles TS 3.5 13810 Cycles TS 3.6 13576 Cycles TS 3.7 13589 Cycles
Description	Vector Description: TS 3.1"if (FALSE == DiagStsHwPosDis_Cnt_T_lgc)==>TRUE , if (TRUE == HandwheelVelValid_Cnt_lgc)==>FALSE if (TRUE == TrimCompEOL_Cnt_lgc)==>FALSE if (TRUE == k_APAMfgEnable_Cnt_lgc)==>FALSE" TS 3.2"if (FALSE == DiagStsHwPosDis_Cnt_T_lgc)==>FALSE, if (TRUE == HandwheelVelValid_Cnt_lgc)==>TRUE, if (TRUE == TrimCompEOL_Cnt_lgc)==>TRUE if (TRUE == k_APAMfgEnable_Cnt_lgc)==>TRUE if (TRUE == Electric_Power_Steering_CE_conf_b)==>TRUE if (TRUE == T1vsT2Active_Cnt_T_lgc)==>TRUE" TS 3.3if (TRUE == TrqSensorNotTrimmedActive_Cnt_T_lgc)==>TRUE TS 3.4if (TRUE == T2OutOfRangeActive_Cnt_T_lgc)==>TRUE TS 3.5if (TRUE == Electric_Power_Steering_CE_conf_b)==>FALSE TS 3.6if (TRUE == T1OutOfRangeActive_Cnt_T_lgc) ==>TRUE TS 3.7"if ((TRUE == T1vsT2Active_Cnt_T_lgc) (TRUE == T1OutOfRangeActive_Cnt_T_lgc) (TRUE == T2OutOfRangeActive_Cnt_T_lgc) (TRUE == TrqSensorNotTrimmedActive_Cnt_T_lgc))==>FALSE"

Test Step 3.1 (Repeat Count = 1)

Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	0
BusOffFltChannel0RecoverTimer_mS_M_u32	0
BusOffFltChannel1DetectionTimer_mS_M_u32	0
BusOffFltChannel1RecoverTimer_mS_M_u32	0
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	0
PPEI_Steering_Wheel_Angle_c[1]	0
PPEI_Steering_Wheel_Angle_c[2]	0
PPEI_Steering_Wheel_Angle_c[3]	0
PPEI_Steering_Wheel_Angle_c[4]	0
PPEI_Steering_Wheel_Angle_c[5]	0
PPEI_Steering_Wheel_Angle_c[6]	0
PPEI_Steering_Wheel_Angle_c[7]	0
PPEI_Steering_Wheel_Angle_CE_c[0]	0
PPEI_Steering_Wheel_Angle_CE_c[1]	0
PPEI_Steering_Wheel_Angle_CE_c[2]	0
PPEI_Steering_Wheel_Angle_CE_c[3]	0
PPEI_Steering_Wheel_Angle_CE_c[4]	0
PPEI_Steering_Wheel_Angle_CE_c[5]	0
PPEI_Steering_Wheel_Angle_CE_c[6]	0
PPEI_Steering_Wheel_Angle_CE_c[7]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadPS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadPS_f32_data
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data
StWhlAngAliveRollCnt_Cnt_M_u08	0
k_APAMfgEnable_Cnt_lgc	0
k_BusOffFaultTimeChannel0_mS_u16	0
k_BusOffFaultTimeChannel1_mS_u16	0
k_BusOffRecoveryTimeChannel0_mS_u16	0
k_BusOffRecoveryTimeChannel1_mS_u16	0

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Name	Input Value		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	0		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-32		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-1440.10999		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	0	0	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	1	1	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStWhlAngAliveRollCnt_0	1	IIPutTxStWhlAngAliveRollCnt_0	1	✓
IIPutTxStWhlAngAliveRollCnt_1	1	IIPutTxStWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
CanPartOffline	1	CanPartOffline	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Test Step 3.2 (Repeat Count = 1)				✓
Name		Input Value		
BusOffDiagActiveChannel0_Cnt_M_lgc		1		
BusOffDiagActiveChannel1_Cnt_M_lgc		1		
BusOffFitChannel0DetectionTimer_mS_M_u32		4294967295		
BusOffFitChannel0RecoverTimer_mS_M_u32		4294967295		
BusOffFitChannel1DetectionTimer_mS_M_u32		4294967295		
BusOffFitChannel1RecoverTimer_mS_M_u32		4294967295		
BusOffPresentChannel0_Cnt_M_lgc		1		
BusOffPresentChannel1_Cnt_M_lgc		1		
DrvStrIntrDetARC_Cnt_M_u08		3		
ElcPwrStrAvalStatARC_Cnt_M_u08		3		
Electric_Power_Steering_CE_conf_b		1		
PPEI_Steering_Wheel_Angle_c[0]		255		
PPEI_Steering_Wheel_Angle_c[1]		255		
PPEI_Steering_Wheel_Angle_c[2]		255		
PPEI_Steering_Wheel_Angle_c[3]		255		
PPEI_Steering_Wheel_Angle_c[4]		255		
PPEI_Steering_Wheel_Angle_c[5]		255		
PPEI_Steering_Wheel_Angle_c[6]		255		
PPEI_Steering_Wheel_Angle_c[7]		255		
PPEI_Steering_Wheel_Angle_CE_c[0]		255		
PPEI_Steering_Wheel_Angle_CE_c[1]		255		
PPEI_Steering_Wheel_Angle_CE_c[2]		255		
PPEI_Steering_Wheel_Angle_CE_c[3]		255		
PPEI_Steering_Wheel_Angle_CE_c[4]		255		
PPEI_Steering_Wheel_Angle_CE_c[5]		255		
PPEI_Steering_Wheel_Angle_CE_c[6]		255		
PPEI_Steering_Wheel_Angle_CE_c[7]		255		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)		target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)		target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)		target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)		target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)		target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)		target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)		target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08		255		
k_APAMfgEnable_Cnt_lgc		1		
k_BusOffFaultTimeChannel0_mS_u16		65535		
k_BusOffFaultTimeChannel1_mS_u16		65535		
k_BusOffRecoveryTimeChannel0_mS_u16		65535		
k_BusOffRecoveryTimeChannel1_mS_u16		65535		
k_SComTrqPosPol_Cnt_s08		1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		65535		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		4294967295		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		32		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		1440.10999		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		1		
Name		Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc		1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc		1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32		4294967295	4294967295	✓
BusOffFitChannel0RecoverTimer_mS_M_u32		4294967295	4294967295	✓
BusOffFitChannel1DetectionTimer_mS_M_u32		4294967295	4294967295	✓
BusOffFitChannel1RecoverTimer_mS_M_u32		4294967295	4294967295	✓
DrvStrIntrDetARC_Cnt_M_u08		0	0	✓
ElcPwrStrAvalStatARC_Cnt_M_u08		0	0	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)		1	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)		1	1	✓
StWhlAngAliveRollCnt_Cnt_M_u08		0	0	✓
NTC		0x0110	0x0110	✓
Param		0x0001	0x0001	✓
Status		0x0001	0x0001	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtcdV	1	IIPutTxDrvStrIntfrDtcdV	1	✓
IIPutTxDrvStrIntfrDtcd	1	IIPutTxDrvStrIntfrDtcd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtcdGroup	1	IIPutTxDrvStrIntfrDtcdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 3.3 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	4294967295
BusOffFltChannel0RecoverTimer_mS_M_u32	0
BusOffFltChannel1DetectionTimer_mS_M_u32	1894110714
BusOffFltChannel1RecoverTimer_mS_M_u32	3861796421
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	0
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	10
PPEI_Steering_Wheel_Angle_c[1]	20
PPEI_Steering_Wheel_Angle_c[2]	30

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	40		
PPEI_Steering_Wheel_Angle._c[4]	50		
PPEI_Steering_Wheel_Angle._c[5]	60		
PPEI_Steering_Wheel_Angle._c[6]	70		
PPEI_Steering_Wheel_Angle._c[7]	80		
PPEI_Steering_Wheel_Angle_CE._c[0]	14		
PPEI_Steering_Wheel_Angle_CE._c[1]	28		
PPEI_Steering_Wheel_Angle_CE._c[2]	42		
PPEI_Steering_Wheel_Angle_CE._c[3]	56		
PPEI_Steering_Wheel_Angle_CE._c[4]	70		
PPEI_Steering_Wheel_Angle_CE._c[5]	84		
PPEI_Steering_Wheel_Angle_CE._c[6]	98		
PPEI_Steering_Wheel_Angle_CE._c[7]	112		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	83		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	60825		
k_BusOffFaultTimeChannel1_mS_u16	25406		
k_BusOffRecoveryTimeChannel0_mS_u16	25882		
k_BusOffRecoveryTimeChannel1_mS_u16	8229		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	11354		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3072927859		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	13.8599997		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	-1440.10999		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3072927859	3072927859	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3072927859	3072927859	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3072927859	3072927859	✔
DrvStrIntfrDetARC_Cnt_M_u08	2	2	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	84	84	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 3.4 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	1246334520
BusOffFltChannel0RecoverTimer_mS_M_u32	4294967295
BusOffFltChannel1DetectionTimer_mS_M_u32	1665706824
BusOffFltChannel1RecoverTimer_mS_M_u32	4193367413
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	3
ElcPwrStrAvalStatARC_Cnt_M_u08	2
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	14
PPEI_Steering_Wheel_Angle_c[1]	28
PPEI_Steering_Wheel_Angle_c[2]	42

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[3]	56		
PPEI_Steering_Wheel_Angle._c[4]	70		
PPEI_Steering_Wheel_Angle._c[5]	84		
PPEI_Steering_Wheel_Angle._c[6]	98		
PPEI_Steering_Wheel_Angle._c[7]	112		
PPEI_Steering_Wheel_Angle_CE._c[0]	30		
PPEI_Steering_Wheel_Angle_CE._c[1]	60		
PPEI_Steering_Wheel_Angle_CE._c[2]	90		
PPEI_Steering_Wheel_Angle_CE._c[3]	120		
PPEI_Steering_Wheel_Angle_CE._c[4]	150		
PPEI_Steering_Wheel_Angle_CE._c[5]	180		
PPEI_Steering_Wheel_Angle_CE._c[6]	210		
PPEI_Steering_Wheel_Angle_CE._c[7]	240		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data		
Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	148		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	64680		
k_BusOffFaultTimeChannel1_mS_u16	39725		
k_BusOffRecoveryTimeChannel0_mS_u16	30312		
k_BusOffRecoveryTimeChannel1_mS_u16	54157		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	44983		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1430223038		
target_Rte_Read_Ap_SriComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_HandwheelVel_HwRadpS_f32_data	5.66800022		
target_Rte_Read_Ap_SriComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_SriComHwPos_HwDeg_f32_data	52.4000015		
target_Rte_Read_Ap_SriComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1430223038	1430223038	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1430223038	1430223038	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	1665706824	1665706824	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	4193367413	4193367413	✓
DrvStrIntfrDetARC_Cnt_M_u08	0	0	✓
ElcPwrStrAvalStatARC_Cnt_M_u08	3	3	✓
Rte_Write_Ap_SriComOutput_BusOffCE_Cnt_lgc(data)	0	0	✓
Rte_Write_Ap_SriComOutput_BusOffHS_Cnt_lgc(data)	0	0	✓
StWhlAngAliveRollCnt_Cnt_M_u08	149	149	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 3.5 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	1356285497
BusOffFitChannel0RecoverTimer_mS_M_u32	0
BusOffFitChannel1DetectionTimer_mS_M_u32	729974407
BusOffFitChannel1RecoverTimer_mS_M_u32	490622811
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	28
PPEI_Steering_Wheel_Angle_c[1]	56
PPEI_Steering_Wheel_Angle_c[2]	84
PPEI_Steering_Wheel_Angle_c[3]	112

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	140		
PPEI_Steering_Wheel_Angle._c[5]	168		
PPEI_Steering_Wheel_Angle._c[6]	196		
PPEI_Steering_Wheel_Angle._c[7]	224		
PPEI_Steering_Wheel_Angle_CE._c[0]	16		
PPEI_Steering_Wheel_Angle_CE._c[1]	32		
PPEI_Steering_Wheel_Angle_CE._c[2]	48		
PPEI_Steering_Wheel_Angle_CE._c[3]	64		
PPEI_Steering_Wheel_Angle_CE._c[4]	80		
PPEI_Steering_Wheel_Angle_CE._c[5]	96		
PPEI_Steering_Wheel_Angle_CE._c[6]	112		
PPEI_Steering_Wheel_Angle_CE._c[7]	128		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	62		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	15049		
k_BusOffFaultTimeChannel1_mS_u16	58080		
k_BusOffRecoveryTimeChannel0_mS_u16	56097		
k_BusOffRecoveryTimeChannel1_mS_u16	10981		
k_SComTrqPosPol_Cnt_s08	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	55747		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3106101192		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-13.1700001		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	0		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	1		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	1356285497	1356285497	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3106101192	3106101192	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3106101192	3106101192	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3106101192	3106101192	✔
DrvStrIntrDetARC_Cnt_M_u08	0	0	✔
EicPwrStrAvalStatARC_Cnt_M_u08	3	3	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	63	63	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVai	1	IIPutTxElcPwrStrAvalStatPVai	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 3.6 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	3953105980
BusOffFitChannel0RecoverTimer_mS_M_u32	1944666162
BusOffFitChannel1DetectionTimer_mS_M_u32	672947379
BusOffFitChannel1RecoverTimer_mS_M_u32	947495828
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
DrvStrIntfrDetARC_Cnt_M_u08	1
ElcPwrStrAvalStatARC_Cnt_M_u08	1
Electric_Power_Steering_CE_conf_b	0
PPEI_Steering_Wheel_Angle_c[0]	30
PPEI_Steering_Wheel_Angle_c[1]	60
PPEI_Steering_Wheel_Angle_c[2]	90
PPEI_Steering_Wheel_Angle_c[3]	120

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	150		
PPEI_Steering_Wheel_Angle._c[5]	180		
PPEI_Steering_Wheel_Angle._c[6]	210		
PPEI_Steering_Wheel_Angle._c[7]	240		
PPEI_Steering_Wheel_Angle_CE._c[0]	18		
PPEI_Steering_Wheel_Angle_CE._c[1]	36		
PPEI_Steering_Wheel_Angle_CE._c[2]	54		
PPEI_Steering_Wheel_Angle_CE._c[3]	72		
PPEI_Steering_Wheel_Angle_CE._c[4]	90		
PPEI_Steering_Wheel_Angle_CE._c[5]	108		
PPEI_Steering_Wheel_Angle_CE._c[6]	126		
PPEI_Steering_Wheel_Angle_CE._c[7]	144		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	241		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	60017		
k_BusOffFaultTimeChannel1_mS_u16	43514		
k_BusOffRecoveryTimeChannel0_mS_u16	49676		
k_BusOffRecoveryTimeChannel1_mS_u16	32711		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	24947		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2370584731		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-12.3699999		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-866.950012		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3953105980	3953105980	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	2370584731	2370584731	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	672947379	672947379	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	947495828	947495828	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	1	1	✔
StWhlAngAliveRollCnt_Cnt_M_u08	242	242	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGrdGroup_0	1	IIPutTxStrWhAngGrdGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVval	1	IIPutTxElcPwrStrAvalStatPVval	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

Test Step 3.7 (Repeat Count = 1)	
Name	Input Value
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	2083038980
BusOffFltChannel0RecoverTimer_mS_M_u32	4078039705
BusOffFltChannel1DetectionTimer_mS_M_u32	3986521469
BusOffFltChannel1RecoverTimer_mS_M_u32	964517160
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
DrvStrIntfrDetARC_Cnt_M_u08	0
ElcPwrStrAvalStatARC_Cnt_M_u08	3
Electric_Power_Steering_CE_conf_b	1
PPEI_Steering_Wheel_Angle_c[0]	20
PPEI_Steering_Wheel_Angle_c[1]	40
PPEI_Steering_Wheel_Angle_c[2]	60
PPEI_Steering_Wheel_Angle_c[3]	80

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SriComOutput_Per2

Name	Input Value		
PPEI_Steering_Wheel_Angle._c[4]	100		
PPEI_Steering_Wheel_Angle._c[5]	120		
PPEI_Steering_Wheel_Angle._c[6]	140		
PPEI_Steering_Wheel_Angle._c[7]	160		
PPEI_Steering_Wheel_Angle_CE._c[0]	14		
PPEI_Steering_Wheel_Angle_CE._c[1]	28		
PPEI_Steering_Wheel_Angle_CE._c[2]	42		
PPEI_Steering_Wheel_Angle_CE._c[3]	56		
PPEI_Steering_Wheel_Angle_CE._c[4]	70		
PPEI_Steering_Wheel_Angle_CE._c[5]	84		
PPEI_Steering_Wheel_Angle_CE._c[6]	98		
PPEI_Steering_Wheel_Angle_CE._c[7]	112		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_APASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32(data)	target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data		
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32(data)	target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data		
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data		
StWhlAngAliveRollCnt_Cnt_M_u08	45		
k_APAMfgEnable_Cnt_lgc	1		
k_BusOffFaultTimeChannel0_mS_u16	36751		
k_BusOffFaultTimeChannel1_mS_u16	35391		
k_BusOffRecoveryTimeChannel0_mS_u16	27065		
k_BusOffRecoveryTimeChannel1_mS_u16	33026		
k_SComTrqPosPol_Cnt_s08	-1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	14504		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	25292635		
target_Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_APASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32_data	-13.5		
target_Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32_data	-440.450012		
target_Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc_data	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	25292635	25292635	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	25292635	25292635	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	3986521469	3986521469	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	25292635	25292635	✔
DrvStrIntrDetARC_Cnt_M_u08	1	1	✔
ElcPwrStrAvalStatARC_Cnt_M_u08	0	0	✔
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc(data)	1	1	✔
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc(data)	0	0	✔
StWhlAngAliveRollCnt_Cnt_M_u08	46	46	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 14:06:13+0530



SrlComOutput_Per2

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	Rte_Read_Ap_SrlComOutput_SrlComHwPos_HwDeg_f32	1	✓
Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	Rte_Read_Ap_SrlComOutput_HandwheelVel_HwRadpS_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_HwVelValid_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_TrimCompEOL_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagStsHwPosDis_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	Rte_Read_Ap_SrlComOutput_SrlComSysPwrMd_Cnt_enum	1	✓
IIPutTxStrWhAngMsk_0	1	IIPutTxStrWhAngMsk_0	1	✓
IIPutTxStrWhAngV_0	1	IIPutTxStrWhAngV_0	1	✓
IIPutTxStrWhAngMsk_1	1	IIPutTxStrWhAngMsk_1	1	✓
IIPutTxStrWhAngV_1	1	IIPutTxStrWhAngV_1	1	✓
IIPutTxStrWhAngGrdMsk_0	1	IIPutTxStrWhAngGrdMsk_0	1	✓
IIPutTxStrWhAngGrdV_0	1	IIPutTxStrWhAngGrdV_0	1	✓
IIPutTxStrWhAngGrdMsk_1	1	IIPutTxStrWhAngGrdMsk_1	1	✓
IIPutTxStrWhAngGrdV_1	1	IIPutTxStrWhAngGrdV_1	1	✓
IIPutTxStrWhlAngSenCalStat_0	1	IIPutTxStrWhlAngSenCalStat_0	1	✓
IIPutTxStrWhlAngSenCalStat_1	1	IIPutTxStrWhlAngSenCalStat_1	1	✓
IIPutTxStrWhlAngAliveRollCnt_0	1	IIPutTxStrWhlAngAliveRollCnt_0	1	✓
IIPutTxStrWhlAngAliveRollCnt_1	1	IIPutTxStrWhlAngAliveRollCnt_1	1	✓
IIPutTxStrWhlAngSenTyp_0	1	IIPutTxStrWhlAngSenTyp_0	1	✓
IIPutTxStrWhlAngSenTyp_1	1	IIPutTxStrWhlAngSenTyp_1	1	✓
IIPutTxStrWhAng_0	1	IIPutTxStrWhAng_0	1	✓
IIPutTxStrWhAng_1	1	IIPutTxStrWhAng_1	1	✓
IIPutTxStrWhAngGrd_0	1	IIPutTxStrWhAngGrd_0	1	✓
IIPutTxStrWhAngGrd_1	1	IIPutTxStrWhAngGrd_1	1	✓
IIPutTxStrWhAngGroup_0	1	IIPutTxStrWhAngGroup_0	1	✓
IIPutTxStrWhAngGroup_1	1	IIPutTxStrWhAngGroup_1	1	✓
IIPutTxStrWhAngGrdGroup_1	1	IIPutTxStrWhAngGrdGroup_1	1	✓
IIPutTxStrAngSnsChksm_0	1	IIPutTxStrAngSnsChksm_0	1	✓
IIPutTxStrAngSnsChksm_1	1	IIPutTxStrAngSnsChksm_1	1	✓
Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_APADrvrInterventionDetected_Cnt_lgc	1	✓
Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	Rte_Read_Ap_SrlComOutput_APASState_State_enum	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	4	✓
IIPutTxElecPwrStrAvalStat	1	IIPutTxElecPwrStrAvalStat	1	✓
IIPutTxDrvStrIntfrDtdV	1	IIPutTxDrvStrIntfrDtdV	1	✓
IIPutTxDrvStrIntfrDtd	1	IIPutTxDrvStrIntfrDtd	1	✓
IIPutTxDrvStrIntfrDetARC	1	IIPutTxDrvStrIntfrDetARC	1	✓
IIPutTxDrvStrIntfrDetPrtVal	1	IIPutTxDrvStrIntfrDetPrtVal	1	✓
IIPutTxElcPwrStrAvalStatARC	1	IIPutTxElcPwrStrAvalStatARC	1	✓
IIPutTxElcPwrStrAvalStatPVal	1	IIPutTxElcPwrStrAvalStatPVal	1	✓
IIPutTxDrvStrIntfrDtdGroup	1	IIPutTxDrvStrIntfrDtdGroup	1	✓
T1_AppHandler	1	T1_AppHandler	1	✓
IITxTask	2	IITxTask	2	✓
SrlComOutput_BusOffHandler	1	SrlComOutput_BusOffHandler	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffHS_Cnt_lgc	1	✓
Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	Rte_Write_Ap_SrlComOutput_BusOffCE_Cnt_lgc	1	✓

TEST DETAILS REPORT

2016-06-29, 14:08:50+0530



SrlComOutput_Trns1

Project	GMSrlComOutput
Module	GMSrlComOutput
Test Object	SrlComOutput_Trns1

Instrumentation: Test Object Only

Statement (C0) Coverage	100 %
Decision Coverage	100 %
Branch (C1) Coverage	100 %
MCC Coverage	100 %
MC/DC Coverage	100 %

Statistics

Total Testcases	2
Successful	2 ✓
Failed	0
Not Executed	0

TEST DETAILS REPORT

2016-06-29, 14:08:50+0530



SrIComOutput_Trns1

Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrIComOutput
Configuration File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\src\Ap_SrIComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\utp\contract -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
Module 'GMSrIComOutput'	***** Unit Test Description***** Name of Tester:Namrata Morbale Code File(s) Under Test:Ap_SrIComOutput.c Code File(s) Version:5 Module Design Document:Serial_Communication_Output_MDD.doc Module Design Document Version:3 Data Dictionary Version:3 Unit Test Plan Version:1 Optimization Level:Level 2 Compiler (CodeGen) Version:TMS470_4.9.5 Model Type:Excel Macro Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32 Total FLASH Used (Bytes):3574 Total RAM Used (Bytes):304 Total CALS Used (Bytes):15 Special Test Requirements:NA Test Date:6/29/2016 Comments:Note1:Inline function defined in Globalmacro.h is not unit tested. Note2:In function ""SrIComOutput_Per1"" and ""SrIComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue. Note3:In function ""SrIComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path. Note4:In function ""SrIComOutput_Per1"", 100% path coverage is not acheived because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKATorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKATorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note5:In function ""SrIComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SrIComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SrIComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "". Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference. *****

Attributes

Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

TEST DETAILS REPORT

2016-06-29, 14:08:50+0530

SrlComOutput_Trns1



Test Case 1: Range Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment)
	CPU Cycles: TS1.1 952.00 Cycles TS1.2 16542.00 Cycles
Description	Vector Description: TS1.1DTCTriggeredFlag_Cnt_M_lgc[32]=Min TS1.2DTCTriggeredFlag_Cnt_M_lgc[362]=Max

Test Step 1.1 (Repeat Count = 1)

Name	Input Value		
DTCTriggeredFlag_Cnt_M_lgc[0]	0		
DTCTriggeredFlag_Cnt_M_lgc[1]	0		
DTCTriggeredFlag_Cnt_M_lgc[2]	0		
DTCTriggeredFlag_Cnt_M_lgc[3]	0		
DTCTriggeredFlag_Cnt_M_lgc[4]	0		
DTCTriggeredFlag_Cnt_M_lgc[5]	0		
DTCTriggeredFlag_Cnt_M_lgc[6]	0		
DTCTriggeredFlag_Cnt_M_lgc[7]	0		
DTCTriggeredFlag_Cnt_M_lgc[8]	0		
DTCTriggeredFlag_Cnt_M_lgc[9]	0		
DTCTriggeredFlag_Cnt_M_lgc[10]	0		
DTCTriggeredFlag_Cnt_M_lgc[11]	0		
DTCTriggeredFlag_Cnt_M_lgc[12]	0		
DTCTriggeredFlag_Cnt_M_lgc[13]	0		
DTCTriggeredFlag_Cnt_M_lgc[14]	0		
DTCTriggeredFlag_Cnt_M_lgc[15]	0		
DTCTriggeredFlag_Cnt_M_lgc[16]	0		
DTCTriggeredFlag_Cnt_M_lgc[17]	0		
DTCTriggeredFlag_Cnt_M_lgc[18]	0		
DTCTriggeredFlag_Cnt_M_lgc[19]	0		
DTCTriggeredFlag_Cnt_M_lgc[20]	0		
DTCTriggeredFlag_Cnt_M_lgc[21]	0		
DTCTriggeredFlag_Cnt_M_lgc[22]	0		
DTCTriggeredFlag_Cnt_M_lgc[23]	0		
DTCTriggeredFlag_Cnt_M_lgc[24]	0		
DTCTriggeredFlag_Cnt_M_lgc[25]	0		
DTCTriggeredFlag_Cnt_M_lgc[26]	0		
DTCTriggeredFlag_Cnt_M_lgc[27]	0		
DTCTriggeredFlag_Cnt_M_lgc[28]	0		
DTCTriggeredFlag_Cnt_M_lgc[29]	0		
DTCTriggeredFlag_Cnt_M_lgc[30]	0		
DTCTriggeredFlag_Cnt_M_lgc[31]	0		
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
target_Pim_DTCTrigSts[0]	0	0	✓
target_Pim_DTCTrigSts[1]	0	0	✓
target_Pim_DTCTrigSts[2]	0	0	✓
target_Pim_DTCTrigSts[3]	0	0	✓
target_Pim_DTCTrigSts[4]	0	0	✓
target_Pim_DTCTrigSts[5]	0	0	✓
target_Pim_DTCTrigSts[6]	0	0	✓
target_Pim_DTCTrigSts[7]	0	0	✓
target_Pim_DTCTrigSts[8]	0	0	✓
target_Pim_DTCTrigSts[9]	0	0	✓
target_Pim_DTCTrigSts[10]	0	0	✓
target_Pim_DTCTrigSts[11]	0	0	✓
target_Pim_DTCTrigSts[12]	0	0	✓
target_Pim_DTCTrigSts[13]	0	0	✓
target_Pim_DTCTrigSts[14]	0	0	✓
target_Pim_DTCTrigSts[15]	0	0	✓
target_Pim_DTCTrigSts[16]	0	0	✓
target_Pim_DTCTrigSts[17]	0	0	✓
target_Pim_DTCTrigSts[18]	0	0	✓
target_Pim_DTCTrigSts[19]	0	0	✓
target_Pim_DTCTrigSts[20]	0	0	✓
target_Pim_DTCTrigSts[21]	0	0	✓
target_Pim_DTCTrigSts[22]	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:08:50+0530



SrlComOutput_Trns1

Name	Actual Value	Expected Value	Result
target_Pim_DTCTrigSts[23]	0	0	✓
target_Pim_DTCTrigSts[24]	0	0	✓
target_Pim_DTCTrigSts[25]	0	0	✓
target_Pim_DTCTrigSts[26]	0	0	✓
target_Pim_DTCTrigSts[27]	0	0	✓
target_Pim_DTCTrigSts[28]	0	0	✓
target_Pim_DTCTrigSts[29]	0	0	✓
target_Pim_DTCTrigSts[30]	0	0	✓
target_Pim_DTCTrigSts[31]	0	0	✓
target_Pim_DTCTrigSts[32]	0	*none*	✓
target_Pim_DTCTrigSts[33]	0	*none*	✓
target_Pim_DTCTrigSts[34]	0	*none*	✓
target_Pim_DTCTrigSts[35]	0	*none*	✓
target_Pim_DTCTrigSts[36]	0	*none*	✓
target_Pim_DTCTrigSts[37]	0	*none*	✓
target_Pim_DTCTrigSts[38]	0	*none*	✓
target_Pim_DTCTrigSts[39]	0	*none*	✓

Test Step Call Trace					✓
Actual Function	Count	Expected Function	Count	Result	
Rte_Call_Ap_SrlComOutput_DTCTrigSts_WriteBlock	1	Rte_Call_Ap_SrlComOutput_DTCTrigSts_WriteBlock	1	✓	

Test Step 1.2 (Repeat Count = 1) ✓

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts

Name	Actual Value	Expected Value	Result
target_Pim_DTCTrigSts[0]	0	0	✓
target_Pim_DTCTrigSts[1]	1	1	✓
target_Pim_DTCTrigSts[2]	1	1	✓
target_Pim_DTCTrigSts[3]	1	1	✓
target_Pim_DTCTrigSts[4]	1	1	✓
target_Pim_DTCTrigSts[5]	1	1	✓
target_Pim_DTCTrigSts[6]	1	1	✓
target_Pim_DTCTrigSts[7]	1	1	✓
target_Pim_DTCTrigSts[8]	1	1	✓
target_Pim_DTCTrigSts[9]	1	1	✓
target_Pim_DTCTrigSts[10]	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:08:50+0530



SrlComOutput_Trns1

Name	Actual Value	Expected Value	Result
target_Pim_DTCTrigSts[11]	1	1	✓
target_Pim_DTCTrigSts[12]	1	1	✓
target_Pim_DTCTrigSts[13]	1	1	✓
target_Pim_DTCTrigSts[14]	1	1	✓
target_Pim_DTCTrigSts[15]	1	1	✓
target_Pim_DTCTrigSts[16]	1	1	✓
target_Pim_DTCTrigSts[17]	1	1	✓
target_Pim_DTCTrigSts[18]	1	1	✓
target_Pim_DTCTrigSts[19]	1	1	✓
target_Pim_DTCTrigSts[20]	1	1	✓
target_Pim_DTCTrigSts[21]	1	1	✓
target_Pim_DTCTrigSts[22]	1	1	✓
target_Pim_DTCTrigSts[23]	1	1	✓
target_Pim_DTCTrigSts[24]	1	1	✓
target_Pim_DTCTrigSts[25]	1	1	✓
target_Pim_DTCTrigSts[26]	1	1	✓
target_Pim_DTCTrigSts[27]	1	1	✓
target_Pim_DTCTrigSts[28]	1	1	✓
target_Pim_DTCTrigSts[29]	1	1	✓
target_Pim_DTCTrigSts[30]	1	1	✓
target_Pim_DTCTrigSts[31]	1	1	✓
target_Pim_DTCTrigSts[32]	0	*none*	✓
target_Pim_DTCTrigSts[33]	0	*none*	✓
target_Pim_DTCTrigSts[34]	0	*none*	✓
target_Pim_DTCTrigSts[35]	0	*none*	✓
target_Pim_DTCTrigSts[36]	0	*none*	✓
target_Pim_DTCTrigSts[37]	0	*none*	✓
target_Pim_DTCTrigSts[38]	0	*none*	✓
target_Pim_DTCTrigSts[39]	0	*none*	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_DTCTrigSts_WriteBlock	1	Rte_Call_Ap_SrlComOutput_DTCTrigSts_WriteBlock	1	✓

Test Case 2: Metrics Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment) CPU Cycles: TS1.1 952.00 Cycles TS1.2 16542.00 Cycles
Description	Vector Description: TS2.1"Shortest Execution Path: (EvtCnt = 1U; EvntCnt <= D_NUMOFDEMEVENTS_CNT_U08; EvntCnt++)=TRUE/FALSE" TS2.2"Longest Execution Path: (EvtCnt = 1U; EvntCnt <= D_NUMOFDEMEVENTS_CNT_U08; EvntCnt++)=TRUE/FALSE"

Test Step 2.1 (Repeat Count = 1)

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	0
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	0

TEST DETAILS REPORT

2016-06-29, 14:08:50+0530



SrlComOutput_Trns1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	0
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts

Name	Actual Value	Expected Value	Result
target_Pim_DTCTrigSts[0]	0	0	✓
target_Pim_DTCTrigSts[1]	1	1	✓
target_Pim_DTCTrigSts[2]	1	1	✓
target_Pim_DTCTrigSts[3]	0	0	✓
target_Pim_DTCTrigSts[4]	1	1	✓
target_Pim_DTCTrigSts[5]	0	0	✓
target_Pim_DTCTrigSts[6]	1	1	✓
target_Pim_DTCTrigSts[7]	1	1	✓
target_Pim_DTCTrigSts[8]	0	0	✓
target_Pim_DTCTrigSts[9]	1	1	✓
target_Pim_DTCTrigSts[10]	1	1	✓
target_Pim_DTCTrigSts[11]	0	0	✓
target_Pim_DTCTrigSts[12]	0	0	✓
target_Pim_DTCTrigSts[13]	0	0	✓
target_Pim_DTCTrigSts[14]	1	1	✓
target_Pim_DTCTrigSts[15]	1	1	✓
target_Pim_DTCTrigSts[16]	0	0	✓
target_Pim_DTCTrigSts[17]	0	0	✓
target_Pim_DTCTrigSts[18]	0	0	✓
target_Pim_DTCTrigSts[19]	1	1	✓
target_Pim_DTCTrigSts[20]	0	0	✓
target_Pim_DTCTrigSts[21]	1	1	✓
target_Pim_DTCTrigSts[22]	1	1	✓
target_Pim_DTCTrigSts[23]	0	0	✓
target_Pim_DTCTrigSts[24]	1	1	✓
target_Pim_DTCTrigSts[25]	0	0	✓
target_Pim_DTCTrigSts[26]	1	1	✓
target_Pim_DTCTrigSts[27]	1	1	✓
target_Pim_DTCTrigSts[28]	0	0	✓
target_Pim_DTCTrigSts[29]	1	1	✓
target_Pim_DTCTrigSts[30]	1	1	✓
target_Pim_DTCTrigSts[31]	0	0	✓
target_Pim_DTCTrigSts[32]	0	*none*	✓
target_Pim_DTCTrigSts[33]	0	*none*	✓
target_Pim_DTCTrigSts[34]	0	*none*	✓
target_Pim_DTCTrigSts[35]	0	*none*	✓
target_Pim_DTCTrigSts[36]	0	*none*	✓
target_Pim_DTCTrigSts[37]	0	*none*	✓
target_Pim_DTCTrigSts[38]	0	*none*	✓
target_Pim_DTCTrigSts[39]	0	*none*	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_DTCTrigSts_WriteBlock	1	Rte_Call_Ap_SrlComOutput_DTCTrigSts_WriteBlock	1	✓

Test Step 2.2 (Repeat Count = 1)	
Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	0
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1

TEST DETAILS REPORT

2016-06-29, 14:08:50+0530



SrlComOutput_Trns1

Name	Input Value		
DTCTriggeredFlag_Cnt_M_lgc[7]	0		
DTCTriggeredFlag_Cnt_M_lgc[8]	1		
DTCTriggeredFlag_Cnt_M_lgc[9]	1		
DTCTriggeredFlag_Cnt_M_lgc[10]	0		
DTCTriggeredFlag_Cnt_M_lgc[11]	0		
DTCTriggeredFlag_Cnt_M_lgc[12]	0		
DTCTriggeredFlag_Cnt_M_lgc[13]	1		
DTCTriggeredFlag_Cnt_M_lgc[14]	1		
DTCTriggeredFlag_Cnt_M_lgc[15]	0		
DTCTriggeredFlag_Cnt_M_lgc[16]	0		
DTCTriggeredFlag_Cnt_M_lgc[17]	0		
DTCTriggeredFlag_Cnt_M_lgc[18]	1		
DTCTriggeredFlag_Cnt_M_lgc[19]	0		
DTCTriggeredFlag_Cnt_M_lgc[20]	1		
DTCTriggeredFlag_Cnt_M_lgc[21]	1		
DTCTriggeredFlag_Cnt_M_lgc[22]	0		
DTCTriggeredFlag_Cnt_M_lgc[23]	1		
DTCTriggeredFlag_Cnt_M_lgc[24]	0		
DTCTriggeredFlag_Cnt_M_lgc[25]	1		
DTCTriggeredFlag_Cnt_M_lgc[26]	1		
DTCTriggeredFlag_Cnt_M_lgc[27]	0		
DTCTriggeredFlag_Cnt_M_lgc[28]	1		
DTCTriggeredFlag_Cnt_M_lgc[29]	1		
DTCTriggeredFlag_Cnt_M_lgc[30]	0		
DTCTriggeredFlag_Cnt_M_lgc[31]	0		
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
target_Pim_DTCTrigSts[0]	0	0	✓
target_Pim_DTCTrigSts[1]	0	0	✓
target_Pim_DTCTrigSts[2]	0	0	✓
target_Pim_DTCTrigSts[3]	1	1	✓
target_Pim_DTCTrigSts[4]	0	0	✓
target_Pim_DTCTrigSts[5]	1	1	✓
target_Pim_DTCTrigSts[6]	1	1	✓
target_Pim_DTCTrigSts[7]	0	0	✓
target_Pim_DTCTrigSts[8]	1	1	✓
target_Pim_DTCTrigSts[9]	1	1	✓
target_Pim_DTCTrigSts[10]	0	0	✓
target_Pim_DTCTrigSts[11]	0	0	✓
target_Pim_DTCTrigSts[12]	0	0	✓
target_Pim_DTCTrigSts[13]	1	1	✓
target_Pim_DTCTrigSts[14]	1	1	✓
target_Pim_DTCTrigSts[15]	0	0	✓
target_Pim_DTCTrigSts[16]	0	0	✓
target_Pim_DTCTrigSts[17]	0	0	✓
target_Pim_DTCTrigSts[18]	1	1	✓
target_Pim_DTCTrigSts[19]	0	0	✓
target_Pim_DTCTrigSts[20]	1	1	✓
target_Pim_DTCTrigSts[21]	1	1	✓
target_Pim_DTCTrigSts[22]	0	0	✓
target_Pim_DTCTrigSts[23]	1	1	✓
target_Pim_DTCTrigSts[24]	0	0	✓
target_Pim_DTCTrigSts[25]	1	1	✓
target_Pim_DTCTrigSts[26]	1	1	✓
target_Pim_DTCTrigSts[27]	0	0	✓
target_Pim_DTCTrigSts[28]	1	1	✓
target_Pim_DTCTrigSts[29]	1	1	✓
target_Pim_DTCTrigSts[30]	0	0	✓
target_Pim_DTCTrigSts[31]	0	0	✓
target_Pim_DTCTrigSts[32]	0	*none*	✓
target_Pim_DTCTrigSts[33]	0	*none*	✓
target_Pim_DTCTrigSts[34]	0	*none*	✓
target_Pim_DTCTrigSts[35]	0	*none*	✓
target_Pim_DTCTrigSts[36]	0	*none*	✓
target_Pim_DTCTrigSts[37]	0	*none*	✓
target_Pim_DTCTrigSts[38]	0	*none*	✓
target_Pim_DTCTrigSts[39]	0	*none*	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_DTCTrigSts_WriteBlock	1	Rte_Call_Ap_SrlComOutput_DTCTrigSts_WriteBlock	1	✓

TEST DETAILS REPORT

2016-06-29, 13:51:04+0530

SrIComOuput_BusOffHandlerInit



Project	GMSrIComOutput
Module	GMSrIComOutput
Test Object	SrIComOuput_BusOffHandlerInit

Instrumentation: Test Object Only

Statement (C0) Coverage	100 %
Branch (C1) Coverage	100 %

Statistics

Total Testcases	1
Successful	1 ✓
Failed	0
Not Executed	0

Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrIComOutput
Configuration File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\src\Ap_SrIComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\utp\contract -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
------	------

TEST DETAILS REPORT

2016-06-29, 13:51:04+0530



SrIComOuput_BusOffHandlerInit

Module 'GMSrIComOutput'

***** Unit Test Description*****

Name of Tester:Namrata Morbale
Code File(s) Under Test:Ap_SrIComOutput.c
Code File(s) Version:5
Module Design Document:Serial_Communication_Output_MDD.doc
Module Design Document Version:3
Data Dictionary Version:3
Unit Test Plan Version:1
Optimization Level:Level 2
Compiler (CodeGen) Version:TMS470_4.9.5
Model Type:Excel Macro
Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32
Total FLASH Used (Bytes):3574
Total RAM Used (Bytes):304
Total CALS Used (Bytes):15
Special Test Requirements:NA
Test Date:6/29/2016
Comments:Note1:Inline function defined in Globalmacro.h is not unit tested.

Note2:In function ""SrIComOutput_Per1"" and ""SrIComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue.

Note3:In function ""SrIComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path.

Note4:In function ""SrIComOutput_Per1"", 100% path coverage is not achieved because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKA_TorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKA_TorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro.

Note5:In function ""SrIComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SrIComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SrIComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro.

Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "" .

Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference.

Attributes	
Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

TEST DETAILS REPORT

2016-06-29, 13:51:04+0530

SriComOuput_BusOffHandlerInit



Test Case 1: Range Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment)
	CPU Cycles:
Description	TS1.1 260 Cycles
	TS1.2 260 Cycles
	TS1.3 260 Cycles
	Vector Description:
TS 1.1 Rte_Call_SystemTime_GetSystemTime_mS_u32=Min	
TS 1.2 Rte_Call_SystemTime_GetSystemTime_mS_u32=Max	
TS 1.3 Rte_Call_SystemTime_GetSystemTime_mS_u32=Pos	

Test Step 1.1 (Repeat Count = 1)

Name		Input Value		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren		0		
Name	Actual Value	Expected Value	Result	
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✓	
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✓	
BusOffFitChannel1DetectionTimer_mS_M_u32	0	0	✓	
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✓	

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓

Test Step 1.2 (Repeat Count = 1)

Name		Input Value		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren		4294967295		
Name	Actual Value	Expected Value	Result	
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✓	
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295	4294967295	✓	
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295	4294967295	✓	
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295	4294967295	✓	

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓

Test Step 1.3 (Repeat Count = 1)

Name		Input Value		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren		3426999552		
Name	Actual Value	Expected Value	Result	
BusOffFitChannel0DetectionTimer_mS_M_u32	3426999552	3426999552	✓	
BusOffFitChannel0RecoverTimer_mS_M_u32	3426999552	3426999552	✓	
BusOffFitChannel1DetectionTimer_mS_M_u32	3426999552	3426999552	✓	
BusOffFitChannel1RecoverTimer_mS_M_u32	3426999552	3426999552	✓	

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530

SrlComOutput_Init1



Project	GMSrlComOutput
Module	GMSrlComOutput
Test Object	SrlComOutput_Init1

Instrumentation: Test Object Only

Statement (C0) Coverage	100 %
Decision Coverage	100 %
Branch (C1) Coverage	100 %
MCC Coverage	100 %
MC/DC Coverage	100 %

Statistics

Total Testcases	3
Successful	3 ✓
Failed	0
Not Executed	0

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrIComOutput_Init1

Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrIComOutput
Configuration File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\src\Ap_SrIComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\utp\contract -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
Module 'GMSrIComOutput'	***** Unit Test Description***** Name of Tester:Namrata Morbale Code File(s) Under Test:Ap_SrIComOutput.c Code File(s) Version:5 Module Design Document:Serial_Communication_Output_MDD.doc Module Design Document Version:3 Data Dictionary Version:3 Unit Test Plan Version:1 Optimization Level:Level 2 Compiler (CodeGen) Version:TMS470_4.9.5 Model Type:Excel Macro Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32 Total FLASH Used (Bytes):3574 Total RAM Used (Bytes):304 Total CALS Used (Bytes):15 Special Test Requirements:NA Test Date:6/29/2016 Comments:Note1:Inline function defined in Globalmacro.h is not unit tested. Note2:In function ""SrIComOutput_Per1"" and ""SrIComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue. Note3:In function ""SrIComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path. Note4:In function ""SrIComOutput_Per1"", 100% path coverage is not acheived because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKATorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKATorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note5:In function ""SrIComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SrIComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SrIComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "". Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference. *****

Attributes

Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530

SrlComOutput_Init1



Test Case 1: Range Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment)
	CPU Cycles: TS 1.1 1785 Cycles TS 1.2 1786 Cycles TS 1.3 1786 Cycles TS 1.4 1786 Cycles TS 1.5 1786 Cycles TS 1.6 1786 Cycles TS 1.7 1786 Cycles TS 1.8 1786 Cycles TS 1.9 1786 Cycles TS 1.10 1786 Cycles TS 1.11 1786 Cycles
Description	Vector Description: TS1.1Rte_Call_SystemTime_GetSystemTime_mS_u32= =>Min TS1.2Rte_Call_SystemTime_GetSystemTime_mS_u32= =>Max TS1.3Rte_Call_SystemTime_GetSystemTime_mS_u32= =>Pos TS1.4Rte_Pim_DTCTrigSts[40]= =>Min TS1.5Rte_Pim_DTCTrigSts[40]= =>Max TS1.6Rte_Pim_DTCTrigSts[40]= =>Pos TS1.7Dem_GetEventStatus= =>Min TS1.8Dem_GetEventStatus= =>Max TS1.9Dem_GetEventStatus= =>Pos TS1.10All Min TS1.11All Max

Test Step 1.1 (Repeat Count = 1)

Name	Input Value
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput
target_Dem_GetEventStatus_EventStatusExtended	0
target_Pim_DTCTrigSts[0]	1
target_Pim_DTCTrigSts[1]	1
target_Pim_DTCTrigSts[2]	1
target_Pim_DTCTrigSts[3]	0
target_Pim_DTCTrigSts[4]	1
target_Pim_DTCTrigSts[5]	0
target_Pim_DTCTrigSts[6]	1
target_Pim_DTCTrigSts[7]	1
target_Pim_DTCTrigSts[8]	0
target_Pim_DTCTrigSts[9]	1
target_Pim_DTCTrigSts[10]	1
target_Pim_DTCTrigSts[11]	0
target_Pim_DTCTrigSts[12]	0
target_Pim_DTCTrigSts[13]	0
target_Pim_DTCTrigSts[14]	1
target_Pim_DTCTrigSts[15]	1
target_Pim_DTCTrigSts[16]	0
target_Pim_DTCTrigSts[17]	0
target_Pim_DTCTrigSts[18]	0
target_Pim_DTCTrigSts[19]	1
target_Pim_DTCTrigSts[20]	0
target_Pim_DTCTrigSts[21]	1
target_Pim_DTCTrigSts[22]	1
target_Pim_DTCTrigSts[23]	0
target_Pim_DTCTrigSts[24]	1
target_Pim_DTCTrigSts[25]	0
target_Pim_DTCTrigSts[26]	1
target_Pim_DTCTrigSts[27]	1
target_Pim_DTCTrigSts[28]	0
target_Pim_DTCTrigSts[29]	1
target_Pim_DTCTrigSts[30]	1
target_Pim_DTCTrigSts[31]	0
target_Pim_DTCTrigSts[32]	0
target_Pim_DTCTrigSts[33]	0
target_Pim_DTCTrigSts[34]	1
target_Pim_DTCTrigSts[35]	1
target_Pim_DTCTrigSts[36]	0
target_Pim_DTCTrigSts[37]	0
target_Pim_DTCTrigSts[38]	0
target_Pim_DTCTrigSts[39]	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	0

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Input Value		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	0	0	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✓
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	32	32	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓

Test Step 1.2 (Repeat Count = 1)		✓
Name	Input Value	
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput	
target_Dem_GetEventStatus_EventStatusExtended	255	
target_Pim_DTCTrigSts[0]	1	
target_Pim_DTCTrigSts[1]	0	
target_Pim_DTCTrigSts[2]	0	
target_Pim_DTCTrigSts[3]	1	
target_Pim_DTCTrigSts[4]	0	
target_Pim_DTCTrigSts[5]	1	
target_Pim_DTCTrigSts[6]	1	
target_Pim_DTCTrigSts[7]	0	
target_Pim_DTCTrigSts[8]	1	
target_Pim_DTCTrigSts[9]	1	
target_Pim_DTCTrigSts[10]	0	
target_Pim_DTCTrigSts[11]	0	
target_Pim_DTCTrigSts[12]	0	
target_Pim_DTCTrigSts[13]	1	
target_Pim_DTCTrigSts[14]	1	
target_Pim_DTCTrigSts[15]	0	
target_Pim_DTCTrigSts[16]	0	
target_Pim_DTCTrigSts[17]	0	
target_Pim_DTCTrigSts[18]	1	
target_Pim_DTCTrigSts[19]	0	
target_Pim_DTCTrigSts[20]	1	
target_Pim_DTCTrigSts[21]	1	
target_Pim_DTCTrigSts[22]	0	

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Input Value		
target_Pim_DTCTrigSts[23]	1		
target_Pim_DTCTrigSts[24]	0		
target_Pim_DTCTrigSts[25]	1		
target_Pim_DTCTrigSts[26]	1		
target_Pim_DTCTrigSts[27]	0		
target_Pim_DTCTrigSts[28]	1		
target_Pim_DTCTrigSts[29]	1		
target_Pim_DTCTrigSts[30]	0		
target_Pim_DTCTrigSts[31]	0		
target_Pim_DTCTrigSts[32]	0		
target_Pim_DTCTrigSts[33]	1		
target_Pim_DTCTrigSts[34]	1		
target_Pim_DTCTrigSts[35]	0		
target_Pim_DTCTrigSts[36]	0		
target_Pim_DTCTrigSts[37]	0		
target_Pim_DTCTrigSts[38]	0		
target_Pim_DTCTrigSts[39]	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	4294967295		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295	4294967295	✔
CTCEventIdSV_Cnt_M_u8	0	0	✔
CTCEventId_Cnt_M_u8	32	32	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✔

Test Step 1.3 (Repeat Count = 1)	
Name	Input Value
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput
target_Dem_GetEventStatus_EventStatusExtended	123
target_Pim_DTCTrigSts[0]	1
target_Pim_DTCTrigSts[1]	1
target_Pim_DTCTrigSts[2]	1
target_Pim_DTCTrigSts[3]	1
target_Pim_DTCTrigSts[4]	1

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Input Value		
target_Pim_DTCTrigSts[5]	1		
target_Pim_DTCTrigSts[6]	1		
target_Pim_DTCTrigSts[7]	1		
target_Pim_DTCTrigSts[8]	1		
target_Pim_DTCTrigSts[9]	1		
target_Pim_DTCTrigSts[10]	1		
target_Pim_DTCTrigSts[11]	1		
target_Pim_DTCTrigSts[12]	1		
target_Pim_DTCTrigSts[13]	1		
target_Pim_DTCTrigSts[14]	1		
target_Pim_DTCTrigSts[15]	1		
target_Pim_DTCTrigSts[16]	1		
target_Pim_DTCTrigSts[17]	1		
target_Pim_DTCTrigSts[18]	1		
target_Pim_DTCTrigSts[19]	1		
target_Pim_DTCTrigSts[20]	1		
target_Pim_DTCTrigSts[21]	1		
target_Pim_DTCTrigSts[22]	1		
target_Pim_DTCTrigSts[23]	1		
target_Pim_DTCTrigSts[24]	1		
target_Pim_DTCTrigSts[25]	1		
target_Pim_DTCTrigSts[26]	0		
target_Pim_DTCTrigSts[27]	1		
target_Pim_DTCTrigSts[28]	0		
target_Pim_DTCTrigSts[29]	1		
target_Pim_DTCTrigSts[30]	0		
target_Pim_DTCTrigSts[31]	1		
target_Pim_DTCTrigSts[32]	1		
target_Pim_DTCTrigSts[33]	1		
target_Pim_DTCTrigSts[34]	1		
target_Pim_DTCTrigSts[35]	1		
target_Pim_DTCTrigSts[36]	1		
target_Pim_DTCTrigSts[37]	1		
target_Pim_DTCTrigSts[38]	1		
target_Pim_DTCTrigSts[39]	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	3426999552		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	3426999552	3426999552	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3426999552	3426999552	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3426999552	3426999552	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3426999552	3426999552	✓
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	32	32	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓

Test Step 1.4 (Repeat Count = 1) ✓

Name	Input Value		
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput		
target_Dem_GetEventStatus_EventStatusExtended	124		
target_Pim_DTCTrigSts[0]	0		
target_Pim_DTCTrigSts[1]	0		
target_Pim_DTCTrigSts[2]	0		
target_Pim_DTCTrigSts[3]	0		
target_Pim_DTCTrigSts[4]	0		
target_Pim_DTCTrigSts[5]	0		
target_Pim_DTCTrigSts[6]	0		
target_Pim_DTCTrigSts[7]	0		
target_Pim_DTCTrigSts[8]	0		
target_Pim_DTCTrigSts[9]	0		
target_Pim_DTCTrigSts[10]	0		
target_Pim_DTCTrigSts[11]	0		
target_Pim_DTCTrigSts[12]	0		
target_Pim_DTCTrigSts[13]	0		
target_Pim_DTCTrigSts[14]	0		
target_Pim_DTCTrigSts[15]	0		
target_Pim_DTCTrigSts[16]	0		
target_Pim_DTCTrigSts[17]	0		
target_Pim_DTCTrigSts[18]	0		
target_Pim_DTCTrigSts[19]	0		
target_Pim_DTCTrigSts[20]	0		
target_Pim_DTCTrigSts[21]	0		
target_Pim_DTCTrigSts[22]	0		
target_Pim_DTCTrigSts[23]	0		
target_Pim_DTCTrigSts[24]	0		
target_Pim_DTCTrigSts[25]	0		
target_Pim_DTCTrigSts[26]	0		
target_Pim_DTCTrigSts[27]	0		
target_Pim_DTCTrigSts[28]	0		
target_Pim_DTCTrigSts[29]	0		
target_Pim_DTCTrigSts[30]	0		
target_Pim_DTCTrigSts[31]	0		
target_Pim_DTCTrigSts[32]	0		
target_Pim_DTCTrigSts[33]	0		
target_Pim_DTCTrigSts[34]	0		
target_Pim_DTCTrigSts[35]	0		
target_Pim_DTCTrigSts[36]	0		
target_Pim_DTCTrigSts[37]	0		
target_Pim_DTCTrigSts[38]	0		
target_Pim_DTCTrigSts[39]	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	12334		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	12334	12334	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	12334	12334	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	12334	12334	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	12334	12334	✔
CTCEventIdSV_Cnt_M_u8	0	0	✔
CTCEventId_Cnt_M_u8	32	32	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✔
DTCTriqaredFlag_Cnt_M_lac[9]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SriComOutput_Init1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530

SrlComOutput_Init1



Test Step 1.5 (Repeat Count = 1)				✓
Name	Input Value			
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended			
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime			
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput			
target_Dem_GetEventStatus_EventStatusExtended	125			
target_Pim_DTCTrigSts[0]	1			
target_Pim_DTCTrigSts[1]	1			
target_Pim_DTCTrigSts[2]	1			
target_Pim_DTCTrigSts[3]	1			
target_Pim_DTCTrigSts[4]	1			
target_Pim_DTCTrigSts[5]	1			
target_Pim_DTCTrigSts[6]	1			
target_Pim_DTCTrigSts[7]	1			
target_Pim_DTCTrigSts[8]	1			
target_Pim_DTCTrigSts[9]	1			
target_Pim_DTCTrigSts[10]	1			
target_Pim_DTCTrigSts[11]	1			
target_Pim_DTCTrigSts[12]	1			
target_Pim_DTCTrigSts[13]	1			
target_Pim_DTCTrigSts[14]	1			
target_Pim_DTCTrigSts[15]	1			
target_Pim_DTCTrigSts[16]	1			
target_Pim_DTCTrigSts[17]	1			
target_Pim_DTCTrigSts[18]	1			
target_Pim_DTCTrigSts[19]	1			
target_Pim_DTCTrigSts[20]	1			
target_Pim_DTCTrigSts[21]	1			
target_Pim_DTCTrigSts[22]	1			
target_Pim_DTCTrigSts[23]	1			
target_Pim_DTCTrigSts[24]	1			
target_Pim_DTCTrigSts[25]	1			
target_Pim_DTCTrigSts[26]	1			
target_Pim_DTCTrigSts[27]	1			
target_Pim_DTCTrigSts[28]	1			
target_Pim_DTCTrigSts[29]	1			
target_Pim_DTCTrigSts[30]	1			
target_Pim_DTCTrigSts[31]	1			
target_Pim_DTCTrigSts[32]	1			
target_Pim_DTCTrigSts[33]	1			
target_Pim_DTCTrigSts[34]	1			
target_Pim_DTCTrigSts[35]	1			
target_Pim_DTCTrigSts[36]	1			
target_Pim_DTCTrigSts[37]	1			
target_Pim_DTCTrigSts[38]	1			
target_Pim_DTCTrigSts[39]	1			
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	23456			
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts			
Name	Actual Value	Expected Value	Result	
BusOffFitChannel0DetectionTimer_mS_M_u32	23456	23456		✓
BusOffFitChannel0RecoverTimer_mS_M_u32	23456	23456		✓
BusOffFitChannel1DetectionTimer_mS_M_u32	23456	23456		✓
BusOffFitChannel1RecoverTimer_mS_M_u32	23456	23456		✓
CTCEventIdSV_Cnt_M_u8	0	0		✓
CTCEventId_Cnt_M_u8	32	32		✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0		✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*		✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1		✓

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓

Test Step 1.6 (Repeat Count = 1) ✓

Name	Input Value		
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput		
target_Dem_GetEventStatus_EventStatusExtended	126		
target_Pim_DTCTrigSts[0]	1		
target_Pim_DTCTrigSts[1]	1		
target_Pim_DTCTrigSts[2]	1		
target_Pim_DTCTrigSts[3]	0		
target_Pim_DTCTrigSts[4]	1		
target_Pim_DTCTrigSts[5]	0		
target_Pim_DTCTrigSts[6]	1		
target_Pim_DTCTrigSts[7]	1		
target_Pim_DTCTrigSts[8]	0		
target_Pim_DTCTrigSts[9]	1		
target_Pim_DTCTrigSts[10]	1		
target_Pim_DTCTrigSts[11]	0		
target_Pim_DTCTrigSts[12]	0		
target_Pim_DTCTrigSts[13]	0		
target_Pim_DTCTrigSts[14]	1		
target_Pim_DTCTrigSts[15]	1		
target_Pim_DTCTrigSts[16]	0		
target_Pim_DTCTrigSts[17]	0		
target_Pim_DTCTrigSts[18]	0		
target_Pim_DTCTrigSts[19]	1		
target_Pim_DTCTrigSts[20]	0		
target_Pim_DTCTrigSts[21]	1		
target_Pim_DTCTrigSts[22]	1		
target_Pim_DTCTrigSts[23]	0		
target_Pim_DTCTrigSts[24]	1		
target_Pim_DTCTrigSts[25]	0		
target_Pim_DTCTrigSts[26]	1		
target_Pim_DTCTrigSts[27]	1		
target_Pim_DTCTrigSts[28]	0		
target_Pim_DTCTrigSts[29]	1		
target_Pim_DTCTrigSts[30]	1		
target_Pim_DTCTrigSts[31]	0		
target_Pim_DTCTrigSts[32]	0		
target_Pim_DTCTrigSts[33]	0		
target_Pim_DTCTrigSts[34]	1		
target_Pim_DTCTrigSts[35]	1		
target_Pim_DTCTrigSts[36]	0		
target_Pim_DTCTrigSts[37]	0		
target_Pim_DTCTrigSts[38]	0		
target_Pim_DTCTrigSts[39]	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	34578		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	34578	34578	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	34578	34578	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	34578	34578	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	34578	34578	✔
CTCEventIdSV_Cnt_M_u8	0	0	✔
CTCEventId_Cnt_M_u8	32	32	✔

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓

Test Step 1.7 (Repeat Count = 1)		✓
Name	Input Value	
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput	
target_Dem_GetEventStatus_EventStatusExtended	0	
target_Pim_DTCTrigSts[0]	1	
target_Pim_DTCTrigSts[1]	0	
target_Pim_DTCTrigSts[2]	0	
target_Pim_DTCTrigSts[3]	1	
target_Pim_DTCTrigSts[4]	0	
target_Pim_DTCTrigSts[5]	1	
target_Pim_DTCTrigSts[6]	1	
target_Pim_DTCTrigSts[7]	0	
target_Pim_DTCTrigSts[8]	1	
target_Pim_DTCTrigSts[9]	1	
target_Pim_DTCTrigSts[10]	0	
target_Pim_DTCTrigSts[11]	0	
target_Pim_DTCTrigSts[12]	0	
target_Pim_DTCTrigSts[13]	1	
target_Pim_DTCTrigSts[14]	1	
target_Pim_DTCTrigSts[15]	0	
target_Pim_DTCTrigSts[16]	0	
target_Pim_DTCTrigSts[17]	0	
target_Pim_DTCTrigSts[18]	1	
target_Pim_DTCTrigSts[19]	0	
target_Pim_DTCTrigSts[20]	1	
target_Pim_DTCTrigSts[21]	1	
target_Pim_DTCTrigSts[22]	0	
target_Pim_DTCTrigSts[23]	1	
target_Pim_DTCTrigSts[24]	0	
target_Pim_DTCTrigSts[25]	1	
target_Pim_DTCTrigSts[26]	1	
target_Pim_DTCTrigSts[27]	0	
target_Pim_DTCTrigSts[28]	1	
target_Pim_DTCTrigSts[29]	1	
target_Pim_DTCTrigSts[30]	0	

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Input Value		
target_Pim_DTCTrigSts[31]	0		
target_Pim_DTCTrigSts[32]	0		
target_Pim_DTCTrigSts[33]	1		
target_Pim_DTCTrigSts[34]	1		
target_Pim_DTCTrigSts[35]	0		
target_Pim_DTCTrigSts[36]	0		
target_Pim_DTCTrigSts[37]	0		
target_Pim_DTCTrigSts[38]	0		
target_Pim_DTCTrigSts[39]	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	45700		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	45700	45700	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	45700	45700	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	45700	45700	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	45700	45700	✓
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	32	32	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓

Test Step 1.8 (Repeat Count = 1)		✓
Name	Input Value	
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput	
target_Dem_GetEventStatus_EventStatusExtended	255	
target_Pim_DTCTrigSts[0]	1	
target_Pim_DTCTrigSts[1]	1	
target_Pim_DTCTrigSts[2]	1	
target_Pim_DTCTrigSts[3]	1	
target_Pim_DTCTrigSts[4]	1	
target_Pim_DTCTrigSts[5]	1	
target_Pim_DTCTrigSts[6]	1	
target_Pim_DTCTrigSts[7]	1	
target_Pim_DTCTrigSts[8]	1	
target_Pim_DTCTrigSts[9]	1	
target_Pim_DTCTrigSts[10]	1	
target_Pim_DTCTrigSts[11]	1	
target_Pim_DTCTrigSts[12]	1	

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Input Value		
target_Pim_DTCTrigSts[13]	1		
target_Pim_DTCTrigSts[14]	1		
target_Pim_DTCTrigSts[15]	1		
target_Pim_DTCTrigSts[16]	1		
target_Pim_DTCTrigSts[17]	1		
target_Pim_DTCTrigSts[18]	1		
target_Pim_DTCTrigSts[19]	1		
target_Pim_DTCTrigSts[20]	1		
target_Pim_DTCTrigSts[21]	1		
target_Pim_DTCTrigSts[22]	1		
target_Pim_DTCTrigSts[23]	1		
target_Pim_DTCTrigSts[24]	1		
target_Pim_DTCTrigSts[25]	1		
target_Pim_DTCTrigSts[26]	0		
target_Pim_DTCTrigSts[27]	1		
target_Pim_DTCTrigSts[28]	0		
target_Pim_DTCTrigSts[29]	1		
target_Pim_DTCTrigSts[30]	0		
target_Pim_DTCTrigSts[31]	1		
target_Pim_DTCTrigSts[32]	1		
target_Pim_DTCTrigSts[33]	1		
target_Pim_DTCTrigSts[34]	1		
target_Pim_DTCTrigSts[35]	1		
target_Pim_DTCTrigSts[36]	1		
target_Pim_DTCTrigSts[37]	1		
target_Pim_DTCTrigSts[38]	1		
target_Pim_DTCTrigSts[39]	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	56822		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	56822	56822	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	56822	56822	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	56822	56822	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	56822	56822	✓
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	32	32	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Test Step 1.9 (Repeat Count = 1)				✓
Name	Input Value			
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended			
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime			
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput			
target_Dem_GetEventStatus_EventStatusExtended	123			
target_Pim_DTCTrigSts[0]	1			
target_Pim_DTCTrigSts[1]	1			
target_Pim_DTCTrigSts[2]	1			
target_Pim_DTCTrigSts[3]	0			
target_Pim_DTCTrigSts[4]	1			
target_Pim_DTCTrigSts[5]	0			
target_Pim_DTCTrigSts[6]	1			
target_Pim_DTCTrigSts[7]	1			
target_Pim_DTCTrigSts[8]	0			
target_Pim_DTCTrigSts[9]	1			
target_Pim_DTCTrigSts[10]	1			
target_Pim_DTCTrigSts[11]	0			
target_Pim_DTCTrigSts[12]	0			
target_Pim_DTCTrigSts[13]	0			
target_Pim_DTCTrigSts[14]	1			
target_Pim_DTCTrigSts[15]	1			
target_Pim_DTCTrigSts[16]	0			
target_Pim_DTCTrigSts[17]	0			
target_Pim_DTCTrigSts[18]	0			
target_Pim_DTCTrigSts[19]	1			
target_Pim_DTCTrigSts[20]	0			
target_Pim_DTCTrigSts[21]	1			
target_Pim_DTCTrigSts[22]	1			
target_Pim_DTCTrigSts[23]	0			
target_Pim_DTCTrigSts[24]	1			
target_Pim_DTCTrigSts[25]	0			
target_Pim_DTCTrigSts[26]	1			
target_Pim_DTCTrigSts[27]	1			
target_Pim_DTCTrigSts[28]	0			
target_Pim_DTCTrigSts[29]	1			
target_Pim_DTCTrigSts[30]	1			
target_Pim_DTCTrigSts[31]	0			
target_Pim_DTCTrigSts[32]	0			
target_Pim_DTCTrigSts[33]	0			
target_Pim_DTCTrigSts[34]	1			
target_Pim_DTCTrigSts[35]	1			
target_Pim_DTCTrigSts[36]	0			
target_Pim_DTCTrigSts[37]	0			
target_Pim_DTCTrigSts[38]	0			
target_Pim_DTCTrigSts[39]	0			
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	67944			
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts			
Name	Actual Value	Expected Value	Result	
BusOffFitChannel0DetectionTimer_mS_M_u32	67944	67944		✓
BusOffFitChannel0RecoverTimer_mS_M_u32	67944	67944		✓
BusOffFitChannel1DetectionTimer_mS_M_u32	67944	67944		✓
BusOffFitChannel1RecoverTimer_mS_M_u32	67944	67944		✓
CTCEventIdSV_Cnt_M_u8	0	0		✓
CTCEventId_Cnt_M_u8	32	32		✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0		✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*		✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0		✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0		✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0		✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0		✓
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0		✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0		✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1		✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0		✓

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓

Test Step 1.10 (Repeat Count = 1)

✓

Name	Input Value		
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput		
target_Dem_GetEventStatus_EventStatusExtended	0		
target_Pim_DTCTrigSts[0]	0		
target_Pim_DTCTrigSts[1]	0		
target_Pim_DTCTrigSts[2]	0		
target_Pim_DTCTrigSts[3]	0		
target_Pim_DTCTrigSts[4]	0		
target_Pim_DTCTrigSts[5]	0		
target_Pim_DTCTrigSts[6]	0		
target_Pim_DTCTrigSts[7]	0		
target_Pim_DTCTrigSts[8]	0		
target_Pim_DTCTrigSts[9]	0		
target_Pim_DTCTrigSts[10]	0		
target_Pim_DTCTrigSts[11]	0		
target_Pim_DTCTrigSts[12]	0		
target_Pim_DTCTrigSts[13]	0		
target_Pim_DTCTrigSts[14]	0		
target_Pim_DTCTrigSts[15]	0		
target_Pim_DTCTrigSts[16]	0		
target_Pim_DTCTrigSts[17]	0		
target_Pim_DTCTrigSts[18]	0		
target_Pim_DTCTrigSts[19]	0		
target_Pim_DTCTrigSts[20]	0		
target_Pim_DTCTrigSts[21]	0		
target_Pim_DTCTrigSts[22]	0		
target_Pim_DTCTrigSts[23]	0		
target_Pim_DTCTrigSts[24]	0		
target_Pim_DTCTrigSts[25]	0		
target_Pim_DTCTrigSts[26]	0		
target_Pim_DTCTrigSts[27]	0		
target_Pim_DTCTrigSts[28]	0		
target_Pim_DTCTrigSts[29]	0		
target_Pim_DTCTrigSts[30]	0		
target_Pim_DTCTrigSts[31]	0		
target_Pim_DTCTrigSts[32]	0		
target_Pim_DTCTrigSts[33]	0		
target_Pim_DTCTrigSts[34]	0		
target_Pim_DTCTrigSts[35]	0		
target_Pim_DTCTrigSts[36]	0		
target_Pim_DTCTrigSts[37]	0		
target_Pim_DTCTrigSts[38]	0		
target_Pim_DTCTrigSts[39]	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	0		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	0	0	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✔
CTCEventIdSV_Cnt_M_u8	0	0	✔
CTCEventId_Cnt_M_u8	32	32	✔

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓

Test Step 1.11 (Repeat Count = 1) ✓

Name	Input Value
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput
target_Dem_GetEventStatus_EventStatusExtended	255
target_Pim_DTCTrigSts[0]	1
target_Pim_DTCTrigSts[1]	1
target_Pim_DTCTrigSts[2]	1
target_Pim_DTCTrigSts[3]	1
target_Pim_DTCTrigSts[4]	1
target_Pim_DTCTrigSts[5]	1
target_Pim_DTCTrigSts[6]	1
target_Pim_DTCTrigSts[7]	1
target_Pim_DTCTrigSts[8]	1
target_Pim_DTCTrigSts[9]	1
target_Pim_DTCTrigSts[10]	1
target_Pim_DTCTrigSts[11]	1
target_Pim_DTCTrigSts[12]	1
target_Pim_DTCTrigSts[13]	1
target_Pim_DTCTrigSts[14]	1
target_Pim_DTCTrigSts[15]	1
target_Pim_DTCTrigSts[16]	1
target_Pim_DTCTrigSts[17]	1
target_Pim_DTCTrigSts[18]	1
target_Pim_DTCTrigSts[19]	1
target_Pim_DTCTrigSts[20]	1
target_Pim_DTCTrigSts[21]	1
target_Pim_DTCTrigSts[22]	1
target_Pim_DTCTrigSts[23]	1
target_Pim_DTCTrigSts[24]	1
target_Pim_DTCTrigSts[25]	1
target_Pim_DTCTrigSts[26]	1
target_Pim_DTCTrigSts[27]	1
target_Pim_DTCTrigSts[28]	1
target_Pim_DTCTrigSts[29]	1
target_Pim_DTCTrigSts[30]	1

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Input Value		
target_Pim_DTCTrigSts[31]	1		
target_Pim_DTCTrigSts[32]	1		
target_Pim_DTCTrigSts[33]	1		
target_Pim_DTCTrigSts[34]	1		
target_Pim_DTCTrigSts[35]	1		
target_Pim_DTCTrigSts[36]	1		
target_Pim_DTCTrigSts[37]	1		
target_Pim_DTCTrigSts[38]	1		
target_Pim_DTCTrigSts[39]	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	4294967295		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295	4294967295	✔
CTCEventIdSV_Cnt_M_u8	0	0	✔
CTCEventId_Cnt_M_u8	32	32	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Test Case 2: Path Test

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS 2.1 1785 Cycles
TS 2.2 1788 Cycles
TS 2.3 1789 Cycles

Description Vector Description:

TS2.1(EvntCnt = 1U; EvntCnt <= D_NUMOFDEMEVENTS_CNT_U08; EvntCnt++)=false/true && (TRUE == (*(Rte_Pim_DTCTrigSts()))
[EvntCnt]=true/false &&(ISOSstatus_Cnt_T_u8 & D_FAILEDTHISCYC_CNT_U8) != D_FAILEDTHISCYC_CNT_U8)=true
&&(ISOSstatus_Cnt_T_u8 & D_TESTNCTHISCYC_CNT_U8) != D_TESTNCTHISCYC_CNT_U8)=true
TS2.2(ISOSstatus_Cnt_T_u8 & D_FAILEDTHISCYC_CNT_U8) != D_FAILEDTHISCYC_CNT_U8)=false
TS2.3(ISOSstatus_Cnt_T_u8 & D_FAILEDTHISCYC_CNT_U8) != D_FAILEDTHISCYC_CNT_U8)=true &&(ISOSstatus_Cnt_T_u8 &
D_TESTNCTHISCYC_CNT_U8) != D_TESTNCTHISCYC_CNT_U8)=false

Test Step 2.1 (Repeat Count = 1)

Name		Input Value	
Dem_GetEventStatus(EventStatusExtended)		target_Dem_GetEventStatus_EventStatusExtended	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	
Rte_Inst_Ap_SrlComOutput		target_Rte_Inst_Ap_SrlComOutput	
target_Dem_GetEventStatus_EventStatusExtended		0	
target_Pim_DTCTrigSts[0]		1	
target_Pim_DTCTrigSts[1]		1	
target_Pim_DTCTrigSts[2]		1	
target_Pim_DTCTrigSts[3]		0	
target_Pim_DTCTrigSts[4]		1	
target_Pim_DTCTrigSts[5]		0	
target_Pim_DTCTrigSts[6]		1	
target_Pim_DTCTrigSts[7]		1	
target_Pim_DTCTrigSts[8]		0	
target_Pim_DTCTrigSts[9]		1	
target_Pim_DTCTrigSts[10]		1	
target_Pim_DTCTrigSts[11]		0	
target_Pim_DTCTrigSts[12]		0	
target_Pim_DTCTrigSts[13]		0	
target_Pim_DTCTrigSts[14]		1	
target_Pim_DTCTrigSts[15]		1	
target_Pim_DTCTrigSts[16]		0	
target_Pim_DTCTrigSts[17]		0	
target_Pim_DTCTrigSts[18]		0	
target_Pim_DTCTrigSts[19]		1	
target_Pim_DTCTrigSts[20]		0	
target_Pim_DTCTrigSts[21]		1	
target_Pim_DTCTrigSts[22]		1	
target_Pim_DTCTrigSts[23]		0	
target_Pim_DTCTrigSts[24]		1	
target_Pim_DTCTrigSts[25]		0	
target_Pim_DTCTrigSts[26]		1	
target_Pim_DTCTrigSts[27]		1	
target_Pim_DTCTrigSts[28]		0	
target_Pim_DTCTrigSts[29]		1	
target_Pim_DTCTrigSts[30]		1	
target_Pim_DTCTrigSts[31]		0	
target_Pim_DTCTrigSts[32]		0	
target_Pim_DTCTrigSts[33]		0	
target_Pim_DTCTrigSts[34]		1	
target_Pim_DTCTrigSts[35]		1	
target_Pim_DTCTrigSts[36]		0	
target_Pim_DTCTrigSts[37]		0	
target_Pim_DTCTrigSts[38]		0	
target_Pim_DTCTrigSts[39]		0	
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren		0	
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts		target_Pim_DTCTrigSts	
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	0	0	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✓
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	32	32	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✓

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓

Test Step 2.2 (Repeat Count = 1)		✓
Name	Input Value	
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput	
target_Dem_GetEventStatus_EventStatusExtended	255	
target_Pim_DTCTrigSts[0]	1	
target_Pim_DTCTrigSts[1]	0	
target_Pim_DTCTrigSts[2]	0	
target_Pim_DTCTrigSts[3]	1	
target_Pim_DTCTrigSts[4]	0	
target_Pim_DTCTrigSts[5]	1	
target_Pim_DTCTrigSts[6]	1	
target_Pim_DTCTrigSts[7]	0	
target_Pim_DTCTrigSts[8]	1	
target_Pim_DTCTrigSts[9]	1	
target_Pim_DTCTrigSts[10]	0	
target_Pim_DTCTrigSts[11]	0	
target_Pim_DTCTrigSts[12]	0	
target_Pim_DTCTrigSts[13]	1	
target_Pim_DTCTrigSts[14]	1	
target_Pim_DTCTrigSts[15]	0	
target_Pim_DTCTrigSts[16]	0	
target_Pim_DTCTrigSts[17]	0	
target_Pim_DTCTrigSts[18]	1	
target_Pim_DTCTrigSts[19]	0	
target_Pim_DTCTrigSts[20]	1	
target_Pim_DTCTrigSts[21]	1	
target_Pim_DTCTrigSts[22]	0	
target_Pim_DTCTrigSts[23]	1	
target_Pim_DTCTrigSts[24]	0	
target_Pim_DTCTrigSts[25]	1	
target_Pim_DTCTrigSts[26]	1	
target_Pim_DTCTrigSts[27]	0	
target_Pim_DTCTrigSts[28]	1	
target_Pim_DTCTrigSts[29]	1	
target_Pim_DTCTrigSts[30]	0	
target_Pim_DTCTrigSts[31]	0	
target_Pim_DTCTrigSts[32]	0	

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Input Value		
target_Pim_DTCTrigSts[33]	1		
target_Pim_DTCTrigSts[34]	1		
target_Pim_DTCTrigSts[35]	0		
target_Pim_DTCTrigSts[36]	0		
target_Pim_DTCTrigSts[37]	0		
target_Pim_DTCTrigSts[38]	0		
target_Pim_DTCTrigSts[39]	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	4294967295		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295	4294967295	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295	4294967295	✔
CTCEventIdSV_Cnt_M_u8	0	0	✔
CTCEventId_Cnt_M_u8	32	32	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✔

Test Step 2.3 (Repeat Count = 1)		✓
Name	Input Value	
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput	
target_Dem_GetEventStatus_EventStatusExtended	125	
target_Pim_DTCTrigSts[0]	1	
target_Pim_DTCTrigSts[1]	1	
target_Pim_DTCTrigSts[2]	1	
target_Pim_DTCTrigSts[3]	1	
target_Pim_DTCTrigSts[4]	1	
target_Pim_DTCTrigSts[5]	1	
target_Pim_DTCTrigSts[6]	1	
target_Pim_DTCTrigSts[7]	1	
target_Pim_DTCTrigSts[8]	1	
target_Pim_DTCTrigSts[9]	1	
target_Pim_DTCTrigSts[10]	1	
target_Pim_DTCTrigSts[11]	1	
target_Pim_DTCTrigSts[12]	1	
target_Pim_DTCTrigSts[13]	1	
target_Pim_DTCTrigSts[14]	1	

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Input Value		
target_Pim_DTCTrigSts[15]	1		
target_Pim_DTCTrigSts[16]	1		
target_Pim_DTCTrigSts[17]	1		
target_Pim_DTCTrigSts[18]	1		
target_Pim_DTCTrigSts[19]	1		
target_Pim_DTCTrigSts[20]	1		
target_Pim_DTCTrigSts[21]	1		
target_Pim_DTCTrigSts[22]	1		
target_Pim_DTCTrigSts[23]	1		
target_Pim_DTCTrigSts[24]	1		
target_Pim_DTCTrigSts[25]	1		
target_Pim_DTCTrigSts[26]	1		
target_Pim_DTCTrigSts[27]	1		
target_Pim_DTCTrigSts[28]	1		
target_Pim_DTCTrigSts[29]	1		
target_Pim_DTCTrigSts[30]	1		
target_Pim_DTCTrigSts[31]	1		
target_Pim_DTCTrigSts[32]	1		
target_Pim_DTCTrigSts[33]	1		
target_Pim_DTCTrigSts[34]	1		
target_Pim_DTCTrigSts[35]	1		
target_Pim_DTCTrigSts[36]	1		
target_Pim_DTCTrigSts[37]	1		
target_Pim_DTCTrigSts[38]	1		
target_Pim_DTCTrigSts[39]	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	23456		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	23456	23456	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	23456	23456	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	23456	23456	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	23456	23456	✓
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	32	32	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Test Case 3: Metrics Test

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS 3.1 1788 Cycles
TS 3.2 1785 Cycles

Description Vector Description:

TS3.1Shortest Execution Path:(EvtCnt = 1U; EvtCnt <= D_NUMOFDEMEVENTS_CNT_U08; EvtCnt++)=true/false &&(TRUE ==
(*(&Rte_Pim_DTCTrigSts()))[EvtCnt])=false
TS3.2Longest Execution Path:(TRUE == (*(&Rte_Pim_DTCTrigSts()))[EvtCnt])=true &&(ISOSStatus_Cnt_T_u8 & D_FAILEDTHISCYC_CNT_U8) !
= D_FAILEDTHISCYC_CNT_U8)=true &&ISOSStatus_Cnt_T_u8 & D_TESTNCTHISCYC_CNT_U8) != D_TESTNCTHISCYC_CNT_U8)=true

Test Step 3.1 (Repeat Count = 1)

Name	Input Value		
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Inst_Ap_SrlComOutput	target_Rte_Inst_Ap_SrlComOutput		
target_Dem_GetEventStatus_EventStatusExtended	130		
target_Pim_DTCTrigSts[0]	0		
target_Pim_DTCTrigSts[1]	0		
target_Pim_DTCTrigSts[2]	0		
target_Pim_DTCTrigSts[3]	0		
target_Pim_DTCTrigSts[4]	0		
target_Pim_DTCTrigSts[5]	0		
target_Pim_DTCTrigSts[6]	0		
target_Pim_DTCTrigSts[7]	0		
target_Pim_DTCTrigSts[8]	0		
target_Pim_DTCTrigSts[9]	0		
target_Pim_DTCTrigSts[10]	0		
target_Pim_DTCTrigSts[11]	0		
target_Pim_DTCTrigSts[12]	0		
target_Pim_DTCTrigSts[13]	0		
target_Pim_DTCTrigSts[14]	0		
target_Pim_DTCTrigSts[15]	0		
target_Pim_DTCTrigSts[16]	0		
target_Pim_DTCTrigSts[17]	0		
target_Pim_DTCTrigSts[18]	0		
target_Pim_DTCTrigSts[19]	0		
target_Pim_DTCTrigSts[20]	0		
target_Pim_DTCTrigSts[21]	0		
target_Pim_DTCTrigSts[22]	0		
target_Pim_DTCTrigSts[23]	0		
target_Pim_DTCTrigSts[24]	0		
target_Pim_DTCTrigSts[25]	0		
target_Pim_DTCTrigSts[26]	0		
target_Pim_DTCTrigSts[27]	0		
target_Pim_DTCTrigSts[28]	0		
target_Pim_DTCTrigSts[29]	0		
target_Pim_DTCTrigSts[30]	0		
target_Pim_DTCTrigSts[31]	0		
target_Pim_DTCTrigSts[32]	0		
target_Pim_DTCTrigSts[33]	0		
target_Pim_DTCTrigSts[34]	0		
target_Pim_DTCTrigSts[35]	0		
target_Pim_DTCTrigSts[36]	0		
target_Pim_DTCTrigSts[37]	0		
target_Pim_DTCTrigSts[38]	0		
target_Pim_DTCTrigSts[39]	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	79066		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	79066	79066	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	79066	79066	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	79066	79066	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	79066	79066	✔
CTCEventIdSV_Cnt_M_u8	0	0	✔
CTCEventId_Cnt_M_u8	32	32	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SriComOutput_Init1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓

Test Step 3.2 (Repeat Count = 1)		✓
Name	Input Value	
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended	
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	
Rte_Inst_Ap_SriComOutput	target_Rte_Inst_Ap_SriComOutput	
target_Dem_GetEventStatus_EventStatusExtended	0	
target_Pim_DTCTrigSts[0]	1	
target_Pim_DTCTrigSts[1]	1	
target_Pim_DTCTrigSts[2]	1	
target_Pim_DTCTrigSts[3]	0	
target_Pim_DTCTrigSts[4]	1	
target_Pim_DTCTrigSts[5]	0	
target_Pim_DTCTrigSts[6]	1	
target_Pim_DTCTrigSts[7]	1	
target_Pim_DTCTrigSts[8]	0	
target_Pim_DTCTrigSts[9]	1	
target_Pim_DTCTrigSts[10]	1	
target_Pim_DTCTrigSts[11]	0	
target_Pim_DTCTrigSts[12]	0	
target_Pim_DTCTrigSts[13]	0	
target_Pim_DTCTrigSts[14]	1	
target_Pim_DTCTrigSts[15]	1	
target_Pim_DTCTrigSts[16]	0	
target_Pim_DTCTrigSts[17]	0	
target_Pim_DTCTrigSts[18]	0	
target_Pim_DTCTrigSts[19]	1	
target_Pim_DTCTrigSts[20]	0	
target_Pim_DTCTrigSts[21]	1	
target_Pim_DTCTrigSts[22]	1	
target_Pim_DTCTrigSts[23]	0	
target_Pim_DTCTrigSts[24]	1	
target_Pim_DTCTrigSts[25]	0	
target_Pim_DTCTrigSts[26]	1	
target_Pim_DTCTrigSts[27]	1	
target_Pim_DTCTrigSts[28]	0	
target_Pim_DTCTrigSts[29]	1	
target_Pim_DTCTrigSts[30]	1	
target_Pim_DTCTrigSts[31]	0	
target_Pim_DTCTrigSts[32]	0	
target_Pim_DTCTrigSts[33]	0	
target_Pim_DTCTrigSts[34]	1	
target_Pim_DTCTrigSts[35]	1	

TEST DETAILS REPORT

2016-06-29, 13:56:22+0530



SrlComOutput_Init1

Name	Input Value		
target_Pim_DTCTrigSts[36]	0		
target_Pim_DTCTrigSts[37]	0		
target_Pim_DTCTrigSts[38]	0		
target_Pim_DTCTrigSts[39]	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	0		
target_Rte_Inst_Ap_SrlComOutput.Pim_DTCTrigSts	target_Pim_DTCTrigSts		
Name	Actual Value	Expected Value	Result
BusOffFltChannel0DetectionTimer_mS_M_u32	0	0	✓
BusOffFltChannel0RecoverTimer_mS_M_u32	0	0	✓
BusOffFltChannel1DetectionTimer_mS_M_u32	0	0	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	0	0	✓
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	32	32	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	*none*	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓

TEST DETAILS REPORT

2016-06-29, 13:52:01+0530



SrIComOuput_Reset778ReportedDTCs

Project	GMSrIComOutput
Module	GMSrIComOutput
Test Object	SrIComOuput_Reset778ReportedDTCs

Instrumentation: Test Object Only

Statement (C0) Coverage	100 %
Branch (C1) Coverage	100 %

Statistics

Total Testcases	1
Successful	1 ✓
Failed	0
Not Executed	0

Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrIComOutput
Configuration File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\src\Ap_SrIComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\utp\contract -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
------	------

TEST DETAILS REPORT

2016-06-29, 13:52:01+0530



SriComOuput_Reset778ReportedDTCs

Module 'GMSrComOutput'

***** Unit Test Description*****

Name of Tester:Namrata Morbale
Code File(s) Under Test:Ap_SrComOutput.c
Code File(s) Version:5
Module Design Document:Serial_Communication_Output_MDD.doc
Module Design Document Version:3
Data Dictionary Version:3
Unit Test Plan Version:1
Optimization Level:Level 2
Compiler (CodeGen) Version:TMS470_4.9.5
Model Type:Excel Macro
Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32
Total FLASH Used (Bytes):3574
Total RAM Used (Bytes):304
Total CALS Used (Bytes):15
Special Test Requirements:NA
Test Date:6/29/2016
Comments:Note1:Inline function defined in Globalmacro.h is not unit tested.

Note2:In function ""SriComOutput_Per1"" and ""SriComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue.

Note3:In function ""SriComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path.

Note4:In function ""SriComOutput_Per1"", 100% path coverage is not achieved because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKA_TorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKA_TorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro.

Note5:In function ""SriComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SriComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SriComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro.

Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "".

Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference.

Attributes	
Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

TEST DETAILS REPORT

2016-06-29, 13:52:01+0530

SrlComOuput_Reset778ReportedDTCs



Test Case 1: Range Test

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS 1.1 20 Cycles

Description Vector Description:

TS1.1Check for Outputs

Test Step 1.1 (Repeat Count = 1)

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	32	32	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
memset	1	memset	1	✓

TEST DETAILS REPORT

2016-06-29, 13:46:42+0530

Appl_1E5MsgTxAck_HS



Project	GMSrComOutput
Module	GMSrComOutput
Test Object	Appl_1E5MsgTxAck_HS

Instrumentation: Test Object Only

Statement (C0) Coverage	100 %
Branch (C1) Coverage	100 %

Statistics

Total Testcases	1
Successful	1 ✓
Failed	0
Not Executed	0

Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrComOutput
Configuration File	D:\Synergy_Work_Area\GMSrComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\src\Ap_SrComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\utp\contract -I\$(PROJECTROOT)\GMSrComOutput\GMSrComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
------	------

TEST DETAILS REPORT

2016-06-29, 13:46:42+0530

Appl_1E5MsgTxAck_HS



Module 'GMSrComOutput'

***** Unit Test Description*****

Name of Tester:Namrata Morbale
Code File(s) Under Test:Ap_SrComOutput.c
Code File(s) Version:5
Module Design Document:Serial_Communication_Output_MDD.doc
Module Design Document Version:3
Data Dictionary Version:3
Unit Test Plan Version:1
Optimization Level:Level 2
Compiler (CodeGen) Version:TMS470_4.9.5
Model Type:Excel Macro
Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32
Total FLASH Used (Bytes):3574
Total RAM Used (Bytes):304
Total CALS Used (Bytes):15
Special Test Requirements:NA
Test Date:6/29/2016
Comments:Note1:Inline function defined in Globalmacro.h is not unit tested.

Note2:In function ""SriComOutput_Per1"" and ""SriComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue.

Note3:In function ""SriComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path.

Note4:In function ""SriComOutput_Per1"", 100% path coverage is not achieved because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKA_TorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKA_TorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro.

Note5:In function ""SriComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SriComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SriComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegps_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegps_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro.

Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "" .

Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference.

Attributes	
Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

Test Case 1: Range Test

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS1.1 Cycles

TS1.2 Cycles

Description Vector Description:

TS1.1All_Min

TS1.2All_Max

Test Step 1.1 (Repeat Count = 1)

Name	Input Value		
txObject	0		
Name	Actual Value	Expected Value	Result
BusOffPresentChannel0_Cnt_M_lgc	0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

Test Step 1.2 (Repeat Count = 1)

Name	Input Value		
txObject	1		
Name	Actual Value	Expected Value	Result
BusOffPresentChannel0_Cnt_M_lgc	0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

TEST DETAILS REPORT

2016-06-29, 14:10:18+0530



SriComOutput_WarningIndicatorHandler

Project	GMSriComOutput
Module	GMSriComOutput
Test Object	SriComOutput_WarningIndicatorHandler

Instrumentation: Test Object Only

Statement (C0) Coverage	100 %
Decision Coverage	100 %
Branch (C1) Coverage	100 %
MCC Coverage	100 %
MC/DC Coverage	100 %

Statistics

Total Testcases	3
Successful	3 ✓
Failed	0
Not Executed	0

TEST DETAILS REPORT

2016-06-29, 14:10:18+0530



SrIComOutput_WarningIndicatorHandler

Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrIComOutput
Configuration File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\src\Ap_SrIComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\utp\contract -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
Module 'GMSrIComOutput'	***** Unit Test Description***** Name of Tester:Namrata Morbale Code File(s) Under Test:Ap_SrIComOutput.c Code File(s) Version:5 Module Design Document:Serial_Communication_Output_MDD.doc Module Design Document Version:3 Data Dictionary Version:3 Unit Test Plan Version:1 Optimization Level:Level 2 Compiler (CodeGen) Version:TMS470_4.9.5 Model Type:Excel Macro Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32 Total FLASH Used (Bytes):3574 Total RAM Used (Bytes):304 Total CALS Used (Bytes):15 Special Test Requirements:NA Test Date:6/29/2016 Comments:Note1:Inline function defined in Globalmacro.h is not unit tested. Note2:In function ""SrIComOutput_Per1"" and ""SrIComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue. Note3:In function ""SrIComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path. Note4:In function ""SrIComOutput_Per1"", 100% path coverage is not acheived because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKATorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKATorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note5:In function ""SrIComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SrIComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SrIComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "". Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference. *****

Attributes

Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

Test Case 1: Range Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment)
	CPU Cycles: TS 1.1 1585 Cycles TS 1.2 1588 Cycles TS 1.3 1591 Cycles TS 1.4 1594 Cycles TS 1.5 1597 Cycles TS 1.6 1600 Cycles TS 1.7 1603 Cycles TS 1.8 1606 Cycles TS 1.9 1609 Cycles TS 1.10 1612 Cycles
Description	Vector Description: TS1.1Dem_IndicatorId==>Min TS1.2Dem_IndicatorId==>Max TS1.3Dem_IndicatorId==>Pos TS1.4PrevWarningIndSignal_Cnt_M_u08[3]==>Min TS1.5PrevWarningIndSignal_Cnt_M_u08[3]==>Max TS1.6PrevWarningIndSignal_Cnt_M_u08[3]==>Pos TS1.7Dem_GetIndicatorStatus==>Min TS1.8Dem_GetIndicatorStatus==>Max TS1.9All Min TS1.10All Max

Test Step 1.1 (Repeat Count = 1)

Name	Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId	0		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	0		
Name	Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
SriComOutput_WarningIndicatorHandler()	0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓

Test Step 1.2 (Repeat Count = 1)

Name	Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId	255		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
Name	Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
SriComOutput_WarningIndicatorHandler()	0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

Test Step 1.3 (Repeat Count = 1)

Name	Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId	1		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	1		

TEST DETAILS REPORT

2016-06-29, 14:10:18+0530



SriComOutput_WarningIndicatorHandler

Name	Input Value		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
Name	Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]	0	0	✔
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✔
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✔
SrlComOutput_WarningIndicatorHandler()	1	1	✔

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓

Test Step 1.4 (Repeat Count = 1)				✔
Name		Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)		target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId		2		
PrevWarningIndSignal_Cnt_M_u08[0]		0		
PrevWarningIndSignal_Cnt_M_u08[1]		0		
PrevWarningIndSignal_Cnt_M_u08[2]		0		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		1		
Name		Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]		0	0	✔
PrevWarningIndSignal_Cnt_M_u08[1]		0	0	✔
PrevWarningIndSignal_Cnt_M_u08[2]		1	1	✔
SrlComOutput_WarningIndicatorHandler()		1	1	✔

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓

Test Step 1.5 (Repeat Count = 1)				✓
Name		Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)		target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId		2		
PrevWarningIndSignal_Cnt_M_u08[0]		1		
PrevWarningIndSignal_Cnt_M_u08[1]		1		
PrevWarningIndSignal_Cnt_M_u08[2]		1		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		0		
Name		Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]		1	1	✓
PrevWarningIndSignal_Cnt_M_u08[1]		1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]		0	0	✓
SrlComOutput_WarningIndicatorHandler()		0	0	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓

Test Step 1.6 (Repeat Count = 1)				✓
Name		Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)		target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId		1		
PrevWarningIndSignal_Cnt_M_u08[0]		0		
PrevWarningIndSignal_Cnt_M_u08[1]		1		
PrevWarningIndSignal_Cnt_M_u08[2]		0		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		1		
Name		Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]		0	0	✓
PrevWarningIndSignal_Cnt_M_u08[1]		1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]		0	0	✓
SrlComOutput_WarningIndicatorHandler()		1	1	✓

TEST DETAILS REPORT

SriComOutput_WarningIndicatorHandler

2016-06-29, 14:10:18+0530



Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓

Test Step 1.7 (Repeat Count = 1)

Name	Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId	2		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	0		
Name	Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
SriComOutput_WarningIndicatorHandler()	0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓

Test Step 1.8 (Repeat Count = 1)

Name	Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId	1		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
Name	Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
SriComOutput_WarningIndicatorHandler()	1	1	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓

Test Step 1.9 (Repeat Count = 1)

Name	Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId	0		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	0		
Name	Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
SriComOutput_WarningIndicatorHandler()	0	0	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓

TEST DETAILS REPORT

SriComOutput_WarningIndicatorHandler

2016-06-29, 14:10:18+0530



Test Step 1.10 (Repeat Count = 1)

Name	Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId	255		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
Name	Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]	1	1	✔
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✔
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✔
SrlComOutput_WarningIndicatorHandler()	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

Test Case 2: Path Test

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS 2.1 1594 Cycles
TS 2.2 1597 Cycles
TS 2.3 1600 Cycles
TS 2.4 1603 Cycles

Description Vector Description:

TS2.1(Dem_IndicatorId < (Dem_IndicatorIdType)DEM_NUMBER_OF_INDICATORS)=true &&(WarningIndSignal_Cnt_T_u08 !=
PrevWarningIndSignal_Cnt_M_u08[Dem_IndicatorId])=false &&(WarningIndStatus_Cnt_T_u08 == DEM_INDICATOR_CONTINUOUS)? 1U :
0U=false
TS2.2(Dem_IndicatorId < (Dem_IndicatorIdType)DEM_NUMBER_OF_INDICATORS)=false
TS2.3(WarningIndStatus_Cnt_T_u08 == DEM_INDICATOR_CONTINUOUS)? 1U : 0U=true
TS2.4(WarningIndSignal_Cnt_T_u08 != PrevWarningIndSignal_Cnt_M_u08[Dem_IndicatorId])=true

Test Step 2.1 (Repeat Count = 1)

Name	Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId	0		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	0		
Name	Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]	0	0	✔
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✔
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✔
SrlComOutput_WarningIndicatorHandler()	0	0	✔

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓

Test Step 2.2 (Repeat Count = 1)

Name		Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)		target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId		255		
PrevWarningIndSignal_Cnt_M_u08[0]		1		
PrevWarningIndSignal_Cnt_M_u08[1]		1		
PrevWarningIndSignal_Cnt_M_u08[2]		1		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		1		
Name		Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]		1	1	✔
PrevWarningIndSignal_Cnt_M_u08[1]		1	1	✔
PrevWarningIndSignal_Cnt_M_u08[2]		1	1	✔
				✔

TEST DETAILS REPORT

2016-06-29, 14:10:18+0530



SrlComOutput_WarningIndicatorHandler

Name	Actual Value	Expected Value	Result
SrlComOutput_WarningIndicatorHandler()	0	0	

Test Step Call Trace ✓

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓

Test Step 2.3 (Repeat Count = 1) ✓

Name	Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId	1		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
Name	Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]	0	0	✔
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✔
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✔
SrlComOutput_WarningIndicatorHandler()	1	1	✔

Test Step Call Trace ✓

Actual Function	Count	Expected Function	Count	Result
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓

Test Step 2.4 (Repeat Count = 1) ✓

Name	Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId	1		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
Name	Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]	0	0	✔
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✔
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✔
SrlComOutput_WarningIndicatorHandler()	1	1	✔

Test Step Call Trace ✓

Actual Function	Count	Expected Function	Count	Result
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓

Test Case 3: Metrics Test ✓

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS 3.1 1603 Cycles

TS 3.2 1606 Cycles

Description Vector Description:

TS3.1Shortest Execution Path:(Dem_IndicatorId < (Dem_IndicatorIdType)DEM_NUMBER_OF_INDICATORS)=false

TS3.2Longest Execution Path:(Dem_IndicatorId < (Dem_IndicatorIdType)DEM_NUMBER_OF_INDICATORS)=true

&&(WarningIndSignal_Cnt_T_u08 != PrevWarningIndSignal_Cnt_M_u08[Dem_IndicatorId])=true &&(WarningIndStatus_Cnt_T_u08 == DEM_INDICATOR_CONTINUOUS)? 1U : 0U=true

Test Step 3.1 (Repeat Count = 1) ✓

Name	Input Value
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
Dem_IndicatorId	255
PrevWarningIndSignal_Cnt_M_u08[0]	1

TEST DETAILS REPORT

2016-06-29, 14:10:18+0530



SrlComOutput_WarningIndicatorHandler

Name	Input Value		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
Name	Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
SrlComOutput_WarningIndicatorHandler()	0	0	✓

Test Step Call Trace					✓
Actual Function	Count	Expected Function	Count	Result	
none	0	*** No Call Expected ***	0	✓	

Test Step 3.2 (Repeat Count = 1)				✓
Name		Input Value		
Dem_GetIndicatorStatus(Dem_IndicatorStatus)		target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		
Dem_IndicatorId		1		
PrevWarningIndSignal_Cnt_M_u08[0]		0		
PrevWarningIndSignal_Cnt_M_u08[1]		0		
PrevWarningIndSignal_Cnt_M_u08[2]		0		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus		1		
Name		Actual Value	Expected Value	Result
PrevWarningIndSignal_Cnt_M_u08[0]		0	0	✓
PrevWarningIndSignal_Cnt_M_u08[1]		1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]		0	0	✓
SrlComOutput_WarningIndicatorHandler()		1	1	✓

Test Step Call Trace					✓
Actual Function	Count	Expected Function	Count	Result	
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓	
IISetEvent	1	IISetEvent	1	✓	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SrlComOutput_Per1



Project	GMSrlComOutput
Module	GMSrlComOutput
Test Object	SrlComOutput_Per1

Instrumentation: Test Object Only

Statement (C0) Coverage	92.85 %
Decision Coverage	89.58 %
Branch (C1) Coverage	89.58 %
MCC Coverage	90.74 %
MC/DC Coverage	90.74 %

Statistics

Total Testcases	3
Successful	3 ✓
Failed	0
Not Executed	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrIComOutput_Per1

Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrIComOutput
Configuration File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\src\Ap_SrIComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\utp\contract -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
Module 'GMSrIComOutput'	***** Unit Test Description***** Name of Tester:Namrata Morbale Code File(s) Under Test:Ap_SrIComOutput.c Code File(s) Version:5 Module Design Document:Serial_Communication_Output_MDD.doc Module Design Document Version:3 Data Dictionary Version:3 Unit Test Plan Version:1 Optimization Level:Level 2 Compiler (CodeGen) Version:TMS470_4.9.5 Model Type:Excel Macro Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32 Total FLASH Used (Bytes):3574 Total RAM Used (Bytes):304 Total CALS Used (Bytes):15 Special Test Requirements:NA Test Date:6/29/2016 Comments:Note1:Inline function defined in Globalmacro.h is not unit tested. Note2:In function ""SrIComOutput_Per1"" and ""SrIComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue. Note3:In function ""SrIComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path. Note4:In function ""SrIComOutput_Per1"", 100% path coverage is not acheived because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKATorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKATorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note5:In function ""SrIComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SrIComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SrIComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "". Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference. *****

Attributes

Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SrlComOutput_Per1



Test Case 1: Metrics Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment) CPU Cycles: TS1.1 6091.00 Cycles TS1.2 40250.00 Cycles
Description	Vector Description: TS1.1"Shortest Execution Path: (DEM_INDICATOR_CONTINUOUS == PwrStrngIndicatorOn_Cnt_T_enum)=True (DEM_INDICATOR_CONTINUOUS == StrAsstReduced_Cnt_T_enum)=True (PwrStrIOlmpCmdSV_Cnt_M_lgc != (Data.PwrStrIO)) (StrAsstRedLmpCmdSV_Cnt_M_lgc != (Data.StrAsstReduced)))=False (CTCEventId_Cnt_M_u8 == D_NUMOFDEMEVENTS_CNT_U08)=False (TRUE == k_LKAMfgEnable_Cnt_lgc)=False ((((GMStatus_Cnt_M_u8[CTCEventId_Cnt_M_u8] & D_FAILEDTHISCYC_CNT_U8) == D_FAILEDTHISCYC_CNT_U8) && (DTCTriggeredFlag_Cnt_M_lgc[CTCEventId_Cnt_M_u8] == FALSE))=True (CTCEventIdSV_Cnt_M_u8 != CTCEventId_Cnt_M_u8)=True" TS1.2"Longest Execution Path: (DEM_INDICATOR_CONTINUOUS == PwrStrngIndicatorOn_Cnt_T_enum)=False (DEM_INDICATOR_CONTINUOUS == StrAsstReduced_Cnt_T_enum)=False (PwrStrIOlmpCmdSV_Cnt_M_lgc != (Data.PwrStrIO)) (StrAsstRedLmpCmdSV_Cnt_M_lgc != (Data.StrAsstReduced)))=True (CTCEventId_Cnt_M_u8 == D_NUMOFDEMEVENTS_CNT_U08)=True (TRUE == k_LKAMfgEnable_Cnt_lgc)=True (TRUE == LKAPreviouslyDisabled_Cnt_M_lgc)=True ((TRUE == HwTrqSensorActive_Cnt_T_lgc) (TRUE == AnaVsDigHwTrqActive_Cnt_T_lgc) (TRUE == T1vsT2Active_Cnt_T_lgc) (TRUE == T1OutofRangeActive_Cnt_T_lgc) (TRUE == T2OutofRangeActive_Cnt_T_lgc) (TRUE == DigT1vsT2Active_Cnt_T_lgc) (TRUE == DigT1OutofRangeActive_Cnt_T_lgc) (TRUE == DigT2OutofRangeActive_Cnt_T_lgc) (TRUE == TrqSensorScaleNotSetActive_Cnt_T_lgc) (TRUE == TrqSensorNotTrimmedActive_Cnt_T_lgc) (TRUE == DigTrqSensorScaleNotSetActive_Cnt_T_lgc) (TRUE == DigTrqSensorNotTrimmedActive_Cnt_T_lgc))=True"

Test Step 1.1 (Repeat Count = 1)

Name	Input Value
CTCEventIdSV_Cnt_M_u8	1
CTCEventId_Cnt_M_u8	0
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	0
DTCDData.DTCNumber	0
DTCDData.DTCFailType	0
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	0
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	0
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	0
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	0
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	0
DemDTCNum_Cnt_M_u32[1]	0
DemDTCNum_Cnt_M_u32[2]	0
DemDTCNum_Cnt_M_u32[3]	0
DemDTCNum_Cnt_M_u32[4]	0
DemDTCNum_Cnt_M_u32[5]	0
DemDTCNum_Cnt_M_u32[6]	0
DemDTCNum_Cnt_M_u32[7]	0
DemDTCNum_Cnt_M_u32[8]	0
DemDTCNum_Cnt_M_u32[9]	0
DemDTCNum_Cnt_M_u32[10]	0
DemDTCNum_Cnt_M_u32[11]	0
DemDTCNum_Cnt_M_u32[12]	0
DemDTCNum_Cnt_M_u32[13]	0
DemDTCNum_Cnt_M_u32[14]	0
DemDTCNum_Cnt_M_u32[15]	0
DemDTCNum_Cnt_M_u32[16]	0
DemDTCNum_Cnt_M_u32[17]	0
DemDTCNum_Cnt_M_u32[18]	0
DemDTCNum_Cnt_M_u32[19]	0
DemDTCNum_Cnt_M_u32[20]	0
DemDTCNum_Cnt_M_u32[21]	0
DemDTCNum_Cnt_M_u32[22]	0
DemDTCNum_Cnt_M_u32[23]	0
DemDTCNum_Cnt_M_u32[24]	0
DemDTCNum_Cnt_M_u32[25]	0
DemDTCNum_Cnt_M_u32[26]	0
DemDTCNum_Cnt_M_u32[27]	0
DemDTCNum_Cnt_M_u32[28]	0
DemDTCNum_Cnt_M_u32[29]	0
DemDTCNum_Cnt_M_u32[30]	0
DemDTCNum_Cnt_M_u32[31]	0
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	1
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	1
GMStatus_Cnt_M_u8[2]	1
GMStatus_Cnt_M_u8[3]	1
GMStatus_Cnt_M_u8[4]	1
GMStatus_Cnt_M_u8[5]	1
GMStatus_Cnt_M_u8[6]	1
GMStatus_Cnt_M_u8[7]	1
GMStatus_Cnt_M_u8[8]	1
GMStatus_Cnt_M_u8[9]	1
GMStatus_Cnt_M_u8[10]	1
GMStatus_Cnt_M_u8[11]	1
GMStatus_Cnt_M_u8[12]	1
GMStatus_Cnt_M_u8[13]	1
GMStatus_Cnt_M_u8[14]	1
GMStatus_Cnt_M_u8[15]	1
GMStatus_Cnt_M_u8[16]	1
GMStatus_Cnt_M_u8[17]	1
GMStatus_Cnt_M_u8[18]	1
GMStatus_Cnt_M_u8[19]	1
GMStatus_Cnt_M_u8[20]	1
GMStatus_Cnt_M_u8[21]	1
GMStatus_Cnt_M_u8[22]	1
GMStatus_Cnt_M_u8[23]	1
GMStatus_Cnt_M_u8[24]	1
GMStatus_Cnt_M_u8[25]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[26]	1		
GMStatus_Cnt_M_u8[27]	1		
GMStatus_Cnt_M_u8[28]	1		
GMStatus_Cnt_M_u8[29]	1		
GMStatus_Cnt_M_u8[30]	1		
GMStatus_Cnt_M_u8[31]	1		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	0		
LKATrqOvrDlvdRC_Cnt_M_u8	0		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	0		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	0		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	0		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	0		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	0		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	0		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	0		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	0		
LastReportedDTCEventID_Cnt_M_u8	0		
LastReportedGMStatus_Cnt_M_u8	1		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	0		
Steering_Torque_Overlay_Stat_CE_c[0]	0		
Steering_Torque_Overlay_Stat_CE_c[1]	0		
Steering_Torque_Overlay_Stat_CE_c[2]	0		
Steering_Torque_Overlay_Stat_CE_c[3]	0		
Steering_Torque_Overlay_Stat_CE_c[4]	0		
Steering_Torque_Overlay_Stat_CE_c[5]	0		
Steering_Torque_Overlay_Stat_CE_c[6]	0		
Steering_Torque_Overlay_Stat_CE_c[7]	0		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	0		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	0		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	10.2299995		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	0		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-3		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	0	0	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSrc	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	2	2	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	1	1	✓
GMStatus_Cnt_M_u8[2]	1	1	✓
GMStatus_Cnt_M_u8[3]	1	1	✓
GMStatus_Cnt_M_u8[4]	1	1	✓
GMStatus_Cnt_M_u8[5]	1	1	✓
GMStatus_Cnt_M_u8[6]	1	1	✓
GMStatus_Cnt_M_u8[7]	1	1	✓
GMStatus_Cnt_M_u8[8]	1	1	✓
GMStatus_Cnt_M_u8[9]	1	1	✓
GMStatus_Cnt_M_u8[10]	1	1	✓
GMStatus_Cnt_M_u8[11]	1	1	✓
GMStatus_Cnt_M_u8[12]	1	1	✓
GMStatus_Cnt_M_u8[13]	1	1	✓
GMStatus_Cnt_M_u8[14]	1	1	✓
GMStatus_Cnt_M_u8[15]	1	1	✓
GMStatus_Cnt_M_u8[16]	1	1	✓
GMStatus_Cnt_M_u8[17]	1	1	✓
GMStatus_Cnt_M_u8[18]	1	1	✓
GMStatus_Cnt_M_u8[19]	1	1	✓
GMStatus_Cnt_M_u8[20]	1	1	✓
GMStatus_Cnt_M_u8[21]	1	1	✓
GMStatus_Cnt_M_u8[22]	1	1	✓
GMStatus_Cnt_M_u8[23]	1	1	✓
GMStatus_Cnt_M_u8[24]	1	1	✓
GMStatus_Cnt_M_u8[25]	1	1	✓
GMStatus_Cnt_M_u8[26]	1	1	✓
GMStatus_Cnt_M_u8[27]	1	1	✓
GMStatus_Cnt_M_u8[28]	1	1	✓
GMStatus_Cnt_M_u8[29]	1	1	✓
GMStatus_Cnt_M_u8[30]	1	1	✓
GMStatus_Cnt_M_u8[31]	1	1	✓
LKATrqOvriDlvdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	0	0	✓
LastReportedGMStatus_Cnt_M_u8	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SriComOutput_Per1



Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItItqDlrd	1	IIPutTxElPwrStItItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSouce_778	1	IIPutTxDTCl_DTCSouce_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 1.2 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	35
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSouce	49
DTCDData.DTCTNumber	65535
DTCDData.DTCTFailType	255
DTCDData.DTCTWrnIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCTHistStat	1
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCTCurrentStatus	1
DTCDData.DTCTCodeSupported	1
DTCDData.DTCTFaulttype	255
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	4294967295
DemDTCNum_Cnt_M_u32[1]	4294967295
DemDTCNum_Cnt_M_u32[2]	4294967295
DemDTCNum_Cnt_M_u32[3]	4294967295
DemDTCNum_Cnt_M_u32[4]	4294967295
DemDTCNum_Cnt_M_u32[5]	4294967295
DemDTCNum_Cnt_M_u32[6]	4294967295
DemDTCNum_Cnt_M_u32[7]	4294967295
DemDTCNum_Cnt_M_u32[8]	4294967295
DemDTCNum_Cnt_M_u32[9]	4294967295
DemDTCNum_Cnt_M_u32[10]	4294967295
DemDTCNum_Cnt_M_u32[11]	4294967295
DemDTCNum_Cnt_M_u32[12]	4294967295
DemDTCNum_Cnt_M_u32[13]	4294967295
DemDTCNum_Cnt_M_u32[14]	4294967295
DemDTCNum_Cnt_M_u32[15]	4294967295
DemDTCNum_Cnt_M_u32[16]	4294967295
DemDTCNum_Cnt_M_u32[17]	4294967295
DemDTCNum_Cnt_M_u32[18]	4294967295
DemDTCNum_Cnt_M_u32[19]	4294967295
DemDTCNum_Cnt_M_u32[20]	4294967295
DemDTCNum_Cnt_M_u32[21]	4294967295
DemDTCNum_Cnt_M_u32[22]	4294967295
DemDTCNum_Cnt_M_u32[23]	4294967295
DemDTCNum_Cnt_M_u32[24]	4294967295
DemDTCNum_Cnt_M_u32[25]	4294967295
DemDTCNum_Cnt_M_u32[26]	4294967295
DemDTCNum_Cnt_M_u32[27]	4294967295
DemDTCNum_Cnt_M_u32[28]	4294967295
DemDTCNum_Cnt_M_u32[29]	4294967295
DemDTCNum_Cnt_M_u32[30]	4294967295
DemDTCNum_Cnt_M_u32[31]	4294967295
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	147
GMStatus_Cnt_M_u8[1]	147
GMStatus_Cnt_M_u8[2]	147
GMStatus_Cnt_M_u8[3]	147
GMStatus_Cnt_M_u8[4]	147
GMStatus_Cnt_M_u8[5]	147
GMStatus_Cnt_M_u8[6]	147
GMStatus_Cnt_M_u8[7]	147
GMStatus_Cnt_M_u8[8]	147
GMStatus_Cnt_M_u8[9]	147
GMStatus_Cnt_M_u8[10]	147
GMStatus_Cnt_M_u8[11]	147
GMStatus_Cnt_M_u8[12]	147
GMStatus_Cnt_M_u8[13]	147
GMStatus_Cnt_M_u8[14]	147
GMStatus_Cnt_M_u8[15]	147
GMStatus_Cnt_M_u8[16]	147
GMStatus_Cnt_M_u8[17]	147
GMStatus_Cnt_M_u8[18]	147
GMStatus_Cnt_M_u8[19]	147
GMStatus_Cnt_M_u8[20]	147
GMStatus_Cnt_M_u8[21]	147
GMStatus_Cnt_M_u8[22]	147

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[23]	147		
GMStatus_Cnt_M_u8[24]	147		
GMStatus_Cnt_M_u8[25]	147		
GMStatus_Cnt_M_u8[26]	147		
GMStatus_Cnt_M_u8[27]	147		
GMStatus_Cnt_M_u8[28]	147		
GMStatus_Cnt_M_u8[29]	147		
GMStatus_Cnt_M_u8[30]	147		
GMStatus_Cnt_M_u8[31]	147		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	255		
LKATrqOvrDlvdRC_Cnt_M_u8	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	255		
LastReportedDTCEventID_Cnt_M_u8	35		
LastReportedGMStatus_Cnt_M_u8	147		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	4294967295		
Steering_Torque_Overlay_Stat_CE_c[0]	255		
Steering_Torque_Overlay_Stat_CE_c[1]	255		
Steering_Torque_Overlay_Stat_CE_c[2]	255		
Steering_Torque_Overlay_Stat_CE_c[3]	255		
Steering_Torque_Overlay_Stat_CE_c[4]	255		
Steering_Torque_Overlay_Stat_CE_c[5]	255		
Steering_Torque_Overlay_Stat_CE_c[6]	255		
Steering_Torque_Overlay_Stat_CE_c[7]	255		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	1		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	255		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	255		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4294967295		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-10.2399998		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	1		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	3.5		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	3		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	35	35	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTTriggered	1	1	✔
DTCDData.DTCSorce	49	49	✔
DTCDData.DTCNNumber	65535	65535	✔
DTCDData.DTCFailType	255	255	✔
DTCDData.DTCWrmIndRqdSt	1	1	✔
DTCDData.DTCTstFldPwrUpSt	1	1	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdClrdStat	1	1	✔
DTCDData.DTCTstNPsdCdClrdSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTData.DTCFaulttype	255	255	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	3	3	✓
GMStatus_Cnt_M_u8[0]	147	147	✓
GMStatus_Cnt_M_u8[1]	147	147	✓
GMStatus_Cnt_M_u8[2]	147	147	✓
GMStatus_Cnt_M_u8[3]	147	147	✓
GMStatus_Cnt_M_u8[4]	147	147	✓
GMStatus_Cnt_M_u8[5]	147	147	✓
GMStatus_Cnt_M_u8[6]	147	147	✓
GMStatus_Cnt_M_u8[7]	147	147	✓
GMStatus_Cnt_M_u8[8]	147	147	✓
GMStatus_Cnt_M_u8[9]	147	147	✓
GMStatus_Cnt_M_u8[10]	147	147	✓
GMStatus_Cnt_M_u8[11]	147	147	✓
GMStatus_Cnt_M_u8[12]	147	147	✓
GMStatus_Cnt_M_u8[13]	147	147	✓
GMStatus_Cnt_M_u8[14]	147	147	✓
GMStatus_Cnt_M_u8[15]	147	147	✓
GMStatus_Cnt_M_u8[16]	147	147	✓
GMStatus_Cnt_M_u8[17]	147	147	✓
GMStatus_Cnt_M_u8[18]	147	147	✓
GMStatus_Cnt_M_u8[19]	147	147	✓
GMStatus_Cnt_M_u8[20]	147	147	✓
GMStatus_Cnt_M_u8[21]	147	147	✓
GMStatus_Cnt_M_u8[22]	147	147	✓
GMStatus_Cnt_M_u8[23]	147	147	✓
GMStatus_Cnt_M_u8[24]	147	147	✓
GMStatus_Cnt_M_u8[25]	147	147	✓
GMStatus_Cnt_M_u8[26]	147	147	✓
GMStatus_Cnt_M_u8[27]	147	147	✓
GMStatus_Cnt_M_u8[28]	147	147	✓
GMStatus_Cnt_M_u8[29]	147	147	✓
GMStatus_Cnt_M_u8[30]	147	147	✓
GMStatus_Cnt_M_u8[31]	147	147	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	35	35	✓
LastReportedGMStatus_Cnt_M_u8	147	147	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4294967295	4294967295	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrStTtItqDlvd	1	IIPutTxLKAEIPwrStTtItqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓



Test Case 2: Range Test



TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS2.1 5657.00 Cycles
TS2.2 41014.00 Cycles
TS2.3 5877.00 Cycles
TS2.4 10196.00 Cycles
TS2.5 36831.00 Cycles
TS2.6 5848.00 Cycles
TS2.7 10407.00 Cycles
TS2.8 10159.00 Cycles
TS2.9 41070.00 Cycles
TS2.10 10224.00 Cycles
TS2.11 10010.00 Cycles
TS2.12 10182.00 Cycles
TS2.13 10416.00 Cycles
TS2.14 10190.00 Cycles
TS2.15 10223.00 Cycles
TS2.16 10185.00 Cycles
TS2.17 10158.00 Cycles
TS2.18 10202.00 Cycles
TS2.19 40917.00 Cycles
TS2.20 5870.00 Cycles
TS2.21 10420.00 Cycles
TS2.22 5896.00 Cycles
TS2.23 10408.00 Cycles
TS2.24 10166.00 Cycles
TS2.25 5673.00 Cycles
TS2.26 6102.00 Cycles
TS2.27 10400.00 Cycles
TS2.28 5672.00 Cycles
TS2.29 10199.00 Cycles
TS2.30 10215.00 Cycles
TS2.31 5673.00 Cycles
TS2.32 10183.00 Cycles
TS2.33 5668.00 Cycles
TS2.34 5876.00 Cycles
TS2.35 5657.00 Cycles
TS2.36 10171.00 Cycles
TS2.37 10171.00 Cycles
TS2.38 5873.00 Cycles
TS2.39 10206.00 Cycles
TS2.40 10413.00 Cycles
TS2.41 10160.00 Cycles
TS2.42 10155.00 Cycles
TS2.43 5847.00 Cycles
TS2.44 10161.00 Cycles
TS2.45 5678.00 Cycles
TS2.46 10209.00 Cycles
TS2.47 36546.00 Cycles
TS2.48 10168.00 Cycles
TS2.49 5874.00 Cycles
TS2.50 5677.00 Cycles
TS2.51 5847.00 Cycles
TS2.52 10171.00 Cycles
TS2.53 10175.00 Cycles
TS2.54 5876.00 Cycles
TS2.55 10207.00 Cycles
TS2.56 5860.00 Cycles
TS2.57 5866.00 Cycles
TS2.58 10427.00 Cycles
TS2.59 10400.00 Cycles
TS2.60 5847.00 Cycles
TS2.61 5867.00 Cycles
TS2.62 10412.00 Cycles
TS2.63 9979.00 Cycles
TS2.64 5673.00 Cycles
TS2.65 10166.00 Cycles
TS2.66 10188.00 Cycles
TS2.67 5867.00 Cycles
TS2.68 5874.00 Cycles
TS2.69 10181.00 Cycles
TS2.70 10201.00 Cycles
TS2.71 5876.00 Cycles
TS2.72 10415.00 Cycles
TS2.73 5671.00 Cycles
TS2.74 10182.00 Cycles
TS2.75 6082.00 Cycles
TS2.76 10164.00 Cycles
TS2.77 41257.00 Cycles
TS2.78 10206.00 Cycles
TS2.79 5677.00 Cycles
TS2.80 5842.00 Cycles
TS2.81 5875.00 Cycles
TS2.82 10004.00 Cycles
TS2.83 10216.00 Cycles
TS2.84 5869.00 Cycles
TS2.85 10188.00 Cycles
TS2.86 10410.00 Cycles
TS2.87 10171.00 Cycles
TS2.88 36247.00 Cycles
TS2.89 10182.00 Cycles
TS2.90 36243.00 Cycles
TS2.91 36181.00 Cycles
TS2.92 36713.00 Cycles
TS2.93 40723.00 Cycles
TS2.94 41271.00 Cycles
TS2.95 36584.00 Cycles
TS2.96 10188.00 Cycles
TS2.97 10155.00 Cycles
TS2.98 10425.00 Cycles
TS2.99 6131.00 Cycles
TS2.100 10448.00 Cycles
TS2.101 6091.00 Cycles
TS2.102 10410.00 Cycles
TS2.103 6089.00 Cycles
TS2.104 5674.00 Cycles
TS2.105 10208.00 Cycles
TS2.106 5673.00 Cycles
TS2.107 41072.00 Cycles
TS2.108 41487.00 Cycles

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

TS2.109 40885.00 Cycles
TS2.110 10167.00 Cycles
TS2.111 6125.00 Cycles
TS2.112 10456.00 Cycles
TS2.113 5868.00 Cycles
TS2.114 10409.00 Cycles
TS2.115 6096.00 Cycles
TS2.116 5674.00 Cycles
TS2.117 10197.00 Cycles
TS2.118 5869.00 Cycles
TS2.119 10108.00 Cycles
TS2.120 10126.00 Cycles
TS2.121 5674.00 Cycles
TS2.122 10117.00 Cycles
TS2.123 5673.00 Cycles

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Description	Vector Description:
	TS2.1All min
	TS2.2All max
	TS2.3HwTrq_HwNm_f32=Min
	TS2.4HwTrq_HwNm_f32=Max
	TS2.5HwTrq_HwNm_f32=Pos
	TS2.6HwTrq_HwNm_f32=Zero
	TS2.7HwTrq_HwNm_f32=Neg
	TS2.8LKASState_State_enum=LKA_Inactive
	TS2.9LKASState_State_enum=LKA_Active
	TS2.10LKASState_State_enum=LKA_TemporarilyLimited
	TS2.11LKASState_State_enum=LKA_PermanentlyFailed
	TS2.12LKASState_State_enum=LKA_ManufacturingDisable
	TS2.13LKATrqDelivered_HwNm_f32=Min
	TS2.14LKATrqDelivered_HwNm_f32=Max
	TS2.15LKATrqDelivered_HwNm_f32=Pos
	TS2.16LKATrqDelivered_HwNm_f32=Zero
	TS2.17LKATrqDelivered_HwNm_f32=Neg
	TS2.18CTCEventId_Cnt_M_u8=Min
	TS2.19CTCEventId_Cnt_M_u8=Max
	TS2.20CTCEventId_Cnt_M_u8=Pos
	TS2.21CTCEventIdSV_Cnt_M_u8=Min
	TS2.22CTCEventIdSV_Cnt_M_u8=Max
	TS2.23CTCEventIdSV_Cnt_M_u8=Pos
	TS2.24CurrentDTCSentThisIC_Cnt_M_lgc=Min
	TS2.25CurrentDTCSentThisIC_Cnt_M_lgc=Max
	TS2.26DemDTCNum_Cnt_M_u32[36]=Min
	TS2.27DemDTCNum_Cnt_M_u32[36]=Max
	TS2.28DemDTCNum_Cnt_M_u32[36]=Pos
	TS2.29DTCData.DTCTriggered=Min
	TS2.30DTCData.DTCTriggered=Max
	TS2.31DTCData.DTCSource=Min
	TS2.32DTCData.DTCSource=Max
	TS2.33DTCData.DTCSource=Pos
	TS2.34DTCData.DTCNumber=Min
	TS2.35DTCData.DTCNumber=Max
	TS2.36DTCData.DTCNumber=Pos
	TS2.37DTCData.DTCFailType=Min
	TS2.38DTCData.DTCFailType=Max
	TS2.39DTCData.DTCFailType=Pos
	TS2.40DTCData.DTCWrnIndRqdSt=Min
	TS2.41DTCData.DTCWrnIndRqdSt=Max
	TS2.42DTCData.DTCTstFldPwrUpSt=Min
	TS2.43DTCData.DTCTstFldPwrUpSt=Max
	TS2.44DTCData.DTCTstNPsdPwrupSt=Min
	TS2.45DTCData.DTCTstNPsdPwrupSt=Max
	TS2.46DTCData.DTCHistStat=Min
	TS2.47DTCData.DTCHistStat=Max
	TS2.48DTCData.DTCTstFldCdCldStat=Min
	TS2.49DTCData.DTCTstFldCdCldStat=Max
	TS2.50DTCData.DTCTstNPsdCdCldSt=Min
	TS2.51DTCData.DTCTstNPsdCdCldSt=Max
	TS2.52DTCData.DTCCurrentStatus=Min
	TS2.53DTCData.DTCCurrentStatus=Max
	TS2.54DTCData.DTCCodeSupported=Min
	TS2.55DTCData.DTCCodeSupported=Max
	TS2.56DTCData.DTCFaulttype=Min
	TS2.57DTCData.DTCFaulttype=Max
	TS2.58DTCData.DTCFaulttype=Pos
	TS2.59DTCTriggeredFlag_Cnt_M_lgc[36]=Min
	TS2.60DTCTriggeredFlag_Cnt_M_lgc[36]=Max
	TS2.61GMStatus_Cnt_M_u8[36]=Min
	TS2.62GMStatus_Cnt_M_u8[36]=Max
	TS2.63GMStatus_Cnt_M_u8[36]=Pos
	TS2.64k_sComTrqPosPol_Cnt_s08=Min / Default
	TS2.65k_sComTrqPosPol_Cnt_s08=Max
	TS2.66LastReportedDTCEventID_Cnt_M_u8=Min
	TS2.67LastReportedDTCEventID_Cnt_M_u8=Max
	TS2.68LastReportedDTCEventID_Cnt_M_u8=Pos
	TS2.69LastReportedGMStatus_Cnt_M_u8=Min
	TS2.70LastReportedGMStatus_Cnt_M_u8=Max
	TS2.71LastReportedGMStatus_Cnt_M_u8=Pos
	TS2.72LKA_Steering_Trq_Overlay_Stat_HS.c[8]=Min
	TS2.73LKA_Steering_Trq_Overlay_Stat_HS.c[8]=Max
	TS2.74LKA_Steering_Trq_Overlay_Stat_HS.c[8]=Pos
	TS2.75k_LKAMfgEnable_Cnt_lgc=Min
	TS2.76k_LKAMfgEnable_Cnt_lgc=Max / Default
	TS2.77LKATrqOvriDlvdRC_Cnt_M_u8=Min
	TS2.78LKATrqOvriDlvdRC_Cnt_M_u8=Max
	TS2.79LKATrqOvriDlvdRC_Cnt_M_u8=Pos
	TS2.80ESCRollCount_Cnt_M_u08=Min
	TS2.81ESCRollCount_Cnt_M_u08=Max
	TS2.82ESCRollCount_Cnt_M_u08=Pos
	TS2.83StartTimerToSetDTCFlag_mS_M_u32p0=Min
	TS2.84StartTimerToSetDTCFlag_mS_M_u32p0=Max
	TS2.85StartTimerToSetDTCFlag_mS_M_u32p0=Pos
	TS2.86Steering_Torque_Overlay_Stat_CE.c[7]=Min
	TS2.87Steering_Torque_Overlay_Stat_CE.c[7]=Max
	TS2.88Steering_Torque_Overlay_Stat_CE.c[7]=Pos
	TS2.89Dem_GetEventStatus=Min
	TS2.90Dem_GetEventStatus=Max
	TS2.91Dem_GetEventStatus=Pos
	TS2.92Rte_Call_NxtrDiagMgr_GetNTCActive[6]=Min
	TS2.93Rte_Call_NxtrDiagMgr_GetNTCActive[6]=Max
	TS2.94Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16=Min

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

TS2.95Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16=Max
 TS2.96Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16=Pos
 TS2.97Rte_Call_SystemTime_GetSystemTime_mS_u32=Min
 TS2.98Rte_Call_SystemTime_GetSystemTime_mS_u32=Max
 TS2.99Rte_Call_SystemTime_GetSystemTime_mS_u32=Pos
 TS2.100HOWEstimate_Uls_f32=Min
 TS2.101HOWEstimate_Uls_f32=Max
 TS2.102HOWEstimate_Uls_f32=Pos
 TS2.103k_MaxHOWEstimate_Uls_f32=Min
 TS2.104k_MaxHOWEstimate_Uls_f32=Max
 TS2.105k_MaxHOWEstimate_Uls_f32=Pos / Default
 TS2.106LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1=Min
 TS2.107LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1=Max
 TS2.108LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1=Pos
 TS2.109LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0=Min
 TS2.110LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0=Max
 TS2.111LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0=Pos
 TS2.112ESCTorqueDelivered_HwNm_f32=Min
 TS2.113ESCTorqueDelivered_HwNm_f32=Max
 TS2.114ESCTorqueDelivered_HwNm_f32=Zero
 TS2.115ESCTorqueDelivered_HwNm_f32=Pos
 TS2.116ESCTorqueDelivered_HwNm_f32=Neg
 TS2.117ESCState_State_enum=ESC_Inactive
 TS2.118ESCState_State_enum=ESC_Active
 TS2.119ESCState_State_enum=ESC_TemporarilyLimited
 TS2.120ESCState_State_enumESC_PermanentlyFailed
 TS2.121ESCState_State_enumESC_ManufacturingDisable
 TS2.122DiagRmpToZeroActive_Cnt_Igc = False
 TS2.123DiagRmpToZeroActive_Cnt_Igc = True

Test Step 2.1 (Repeat Count = 1)



Name	Input Value
CTCEventIdSV_Cnt_M_u8	0
CTCEventId_Cnt_M_u8	0
CurrentDTCSentThisIC_Cnt_M_Igc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	0
DTCDData.DTCNumber	0
DTCDData.DTCFailType	0
DTCDData.DTCWrmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	0
DTCTriggeredFlag_Cnt_M_Igc[0]	0
DTCTriggeredFlag_Cnt_M_Igc[1]	0
DTCTriggeredFlag_Cnt_M_Igc[2]	0
DTCTriggeredFlag_Cnt_M_Igc[3]	0
DTCTriggeredFlag_Cnt_M_Igc[4]	0
DTCTriggeredFlag_Cnt_M_Igc[5]	0
DTCTriggeredFlag_Cnt_M_Igc[6]	0
DTCTriggeredFlag_Cnt_M_Igc[7]	0
DTCTriggeredFlag_Cnt_M_Igc[8]	0
DTCTriggeredFlag_Cnt_M_Igc[9]	0
DTCTriggeredFlag_Cnt_M_Igc[10]	0
DTCTriggeredFlag_Cnt_M_Igc[11]	0
DTCTriggeredFlag_Cnt_M_Igc[12]	0
DTCTriggeredFlag_Cnt_M_Igc[13]	0
DTCTriggeredFlag_Cnt_M_Igc[14]	0
DTCTriggeredFlag_Cnt_M_Igc[15]	0
DTCTriggeredFlag_Cnt_M_Igc[16]	0
DTCTriggeredFlag_Cnt_M_Igc[17]	0
DTCTriggeredFlag_Cnt_M_Igc[18]	0
DTCTriggeredFlag_Cnt_M_Igc[19]	0
DTCTriggeredFlag_Cnt_M_Igc[20]	0
DTCTriggeredFlag_Cnt_M_Igc[21]	0
DTCTriggeredFlag_Cnt_M_Igc[22]	0
DTCTriggeredFlag_Cnt_M_Igc[23]	0
DTCTriggeredFlag_Cnt_M_Igc[24]	0
DTCTriggeredFlag_Cnt_M_Igc[25]	0
DTCTriggeredFlag_Cnt_M_Igc[26]	0
DTCTriggeredFlag_Cnt_M_Igc[27]	0
DTCTriggeredFlag_Cnt_M_Igc[28]	0
DTCTriggeredFlag_Cnt_M_Igc[29]	0
DTCTriggeredFlag_Cnt_M_Igc[30]	0
DTCTriggeredFlag_Cnt_M_Igc[31]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[0]	0
DemDTCNum_Cnt_M_u32[1]	0
DemDTCNum_Cnt_M_u32[2]	0
DemDTCNum_Cnt_M_u32[3]	0
DemDTCNum_Cnt_M_u32[4]	0
DemDTCNum_Cnt_M_u32[5]	0
DemDTCNum_Cnt_M_u32[6]	0
DemDTCNum_Cnt_M_u32[7]	0
DemDTCNum_Cnt_M_u32[8]	0
DemDTCNum_Cnt_M_u32[9]	0
DemDTCNum_Cnt_M_u32[10]	0
DemDTCNum_Cnt_M_u32[11]	0
DemDTCNum_Cnt_M_u32[12]	0
DemDTCNum_Cnt_M_u32[13]	0
DemDTCNum_Cnt_M_u32[14]	0
DemDTCNum_Cnt_M_u32[15]	0
DemDTCNum_Cnt_M_u32[16]	0
DemDTCNum_Cnt_M_u32[17]	0
DemDTCNum_Cnt_M_u32[18]	0
DemDTCNum_Cnt_M_u32[19]	0
DemDTCNum_Cnt_M_u32[20]	0
DemDTCNum_Cnt_M_u32[21]	0
DemDTCNum_Cnt_M_u32[22]	0
DemDTCNum_Cnt_M_u32[23]	0
DemDTCNum_Cnt_M_u32[24]	0
DemDTCNum_Cnt_M_u32[25]	0
DemDTCNum_Cnt_M_u32[26]	0
DemDTCNum_Cnt_M_u32[27]	0
DemDTCNum_Cnt_M_u32[28]	0
DemDTCNum_Cnt_M_u32[29]	0
DemDTCNum_Cnt_M_u32[30]	0
DemDTCNum_Cnt_M_u32[31]	0
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	0
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	1
GMStatus_Cnt_M_u8[2]	1
GMStatus_Cnt_M_u8[3]	1
GMStatus_Cnt_M_u8[4]	1
GMStatus_Cnt_M_u8[5]	1
GMStatus_Cnt_M_u8[6]	1
GMStatus_Cnt_M_u8[7]	1
GMStatus_Cnt_M_u8[8]	1
GMStatus_Cnt_M_u8[9]	1
GMStatus_Cnt_M_u8[10]	1
GMStatus_Cnt_M_u8[11]	1
GMStatus_Cnt_M_u8[12]	1
GMStatus_Cnt_M_u8[13]	1
GMStatus_Cnt_M_u8[14]	1
GMStatus_Cnt_M_u8[15]	1
GMStatus_Cnt_M_u8[16]	1
GMStatus_Cnt_M_u8[17]	1
GMStatus_Cnt_M_u8[18]	1
GMStatus_Cnt_M_u8[19]	1
GMStatus_Cnt_M_u8[20]	1
GMStatus_Cnt_M_u8[21]	1
GMStatus_Cnt_M_u8[22]	1
GMStatus_Cnt_M_u8[23]	1
GMStatus_Cnt_M_u8[24]	1
GMStatus_Cnt_M_u8[25]	1
GMStatus_Cnt_M_u8[26]	1
GMStatus_Cnt_M_u8[27]	1
GMStatus_Cnt_M_u8[28]	1
GMStatus_Cnt_M_u8[29]	1
GMStatus_Cnt_M_u8[30]	1
GMStatus_Cnt_M_u8[31]	1
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	0
LKATrqOvriDlvdRC_Cnt_M_u8	0
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	0
LastReportedDTCEventID_Cnt_M_u8	0
LastReportedGMStatus_Cnt_M_u8	1
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	0
Steering_Torque_Overlay_Stat_CE_c[0]	0
Steering_Torque_Overlay_Stat_CE_c[1]	0
Steering_Torque_Overlay_Stat_CE_c[2]	0
Steering_Torque_Overlay_Stat_CE_c[3]	0
Steering_Torque_Overlay_Stat_CE_c[4]	0
Steering_Torque_Overlay_Stat_CE_c[5]	0
Steering_Torque_Overlay_Stat_CE_c[6]	0
Steering_Torque_Overlay_Stat_CE_c[7]	0
k_LKAMfgEnable_Cnt_Igc	0
k_MaxHOWEstimate_Uls_f32	0
k_SComTrqPosPol_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	0
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	0
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	0
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-10.2399998
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-10
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	0
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-3

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	1	1	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	1	1	✓
GMStatus_Cnt_M_u8[2]	1	1	✓
GMStatus_Cnt_M_u8[3]	1	1	✓
GMStatus_Cnt_M_u8[4]	1	1	✓
GMStatus_Cnt_M_u8[5]	1	1	✓
GMStatus_Cnt_M_u8[6]	1	1	✓
GMStatus_Cnt_M_u8[7]	1	1	✓
GMStatus_Cnt_M_u8[8]	1	1	✓
GMStatus_Cnt_M_u8[9]	1	1	✓
GMStatus_Cnt_M_u8[10]	1	1	✓
GMStatus_Cnt_M_u8[11]	1	1	✓
GMStatus_Cnt_M_u8[12]	1	1	✓
GMStatus_Cnt_M_u8[13]	1	1	✓
GMStatus_Cnt_M_u8[14]	1	1	✓
GMStatus_Cnt_M_u8[15]	1	1	✓
GMStatus_Cnt_M_u8[16]	1	1	✓
GMStatus_Cnt_M_u8[17]	1	1	✓
GMStatus_Cnt_M_u8[18]	1	1	✓
GMStatus_Cnt_M_u8[19]	1	1	✓
GMStatus_Cnt_M_u8[20]	1	1	✓
GMStatus_Cnt_M_u8[21]	1	1	✓
GMStatus_Cnt_M_u8[22]	1	1	✓
GMStatus_Cnt_M_u8[23]	1	1	✓
GMStatus_Cnt_M_u8[24]	1	1	✓
GMStatus_Cnt_M_u8[25]	1	1	✓
GMStatus_Cnt_M_u8[26]	1	1	✓
GMStatus_Cnt_M_u8[27]	1	1	✓
GMStatus_Cnt_M_u8[28]	1	1	✓
GMStatus_Cnt_M_u8[29]	1	1	✓
GMStatus_Cnt_M_u8[30]	1	1	✓
GMStatus_Cnt_M_u8[31]	1	1	✓
LKATrqOvriDlvdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	0	0	✓
LastReportedGMStatus_Cnt_M_u8	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItTqDlrd	1	IIPutTxElPwrStItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrcSource_778	1	IIPutTxDTCl_DTCSrcSource_778	1	✓
IIPutTxDTCl_DTCCNumber_778	1	IIPutTxDTCl_DTCCNumber_778	1	✓
IIPutTxDTCl_DTCCFailType_778	1	IIPutTxDTCl_DTCCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCCFaultType_778	1	IIPutTxDTCl_DTCCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.2 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	35
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSrcSource	49
DTCDData.DTCCNumber	65535
DTCDData.DTCCFailType	255
DTCDData.DTCCWrmIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCCFaulttype	255
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	4294967295
DemDTCNum_Cnt_M_u32[1]	4294967295
DemDTCNum_Cnt_M_u32[2]	4294967295
DemDTCNum_Cnt_M_u32[3]	4294967295
DemDTCNum_Cnt_M_u32[4]	4294967295
DemDTCNum_Cnt_M_u32[5]	4294967295
DemDTCNum_Cnt_M_u32[6]	4294967295
DemDTCNum_Cnt_M_u32[7]	4294967295
DemDTCNum_Cnt_M_u32[8]	4294967295
DemDTCNum_Cnt_M_u32[9]	4294967295
DemDTCNum_Cnt_M_u32[10]	4294967295
DemDTCNum_Cnt_M_u32[11]	4294967295
DemDTCNum_Cnt_M_u32[12]	4294967295
DemDTCNum_Cnt_M_u32[13]	4294967295
DemDTCNum_Cnt_M_u32[14]	4294967295
DemDTCNum_Cnt_M_u32[15]	4294967295
DemDTCNum_Cnt_M_u32[16]	4294967295
DemDTCNum_Cnt_M_u32[17]	4294967295
DemDTCNum_Cnt_M_u32[18]	4294967295
DemDTCNum_Cnt_M_u32[19]	4294967295
DemDTCNum_Cnt_M_u32[20]	4294967295
DemDTCNum_Cnt_M_u32[21]	4294967295
DemDTCNum_Cnt_M_u32[22]	4294967295
DemDTCNum_Cnt_M_u32[23]	4294967295
DemDTCNum_Cnt_M_u32[24]	4294967295
DemDTCNum_Cnt_M_u32[25]	4294967295
DemDTCNum_Cnt_M_u32[26]	4294967295
DemDTCNum_Cnt_M_u32[27]	4294967295
DemDTCNum_Cnt_M_u32[28]	4294967295
DemDTCNum_Cnt_M_u32[29]	4294967295
DemDTCNum_Cnt_M_u32[30]	4294967295
DemDTCNum_Cnt_M_u32[31]	4294967295
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	15
GMStatus_Cnt_M_u8[0]	147
GMStatus_Cnt_M_u8[1]	147
GMStatus_Cnt_M_u8[2]	147
GMStatus_Cnt_M_u8[3]	147
GMStatus_Cnt_M_u8[4]	147
GMStatus_Cnt_M_u8[5]	147
GMStatus_Cnt_M_u8[6]	147
GMStatus_Cnt_M_u8[7]	147
GMStatus_Cnt_M_u8[8]	147
GMStatus_Cnt_M_u8[9]	147
GMStatus_Cnt_M_u8[10]	147
GMStatus_Cnt_M_u8[11]	147
GMStatus_Cnt_M_u8[12]	147
GMStatus_Cnt_M_u8[13]	147
GMStatus_Cnt_M_u8[14]	147
GMStatus_Cnt_M_u8[15]	147
GMStatus_Cnt_M_u8[16]	147
GMStatus_Cnt_M_u8[17]	147
GMStatus_Cnt_M_u8[18]	147
GMStatus_Cnt_M_u8[19]	147
GMStatus_Cnt_M_u8[20]	147
GMStatus_Cnt_M_u8[21]	147
GMStatus_Cnt_M_u8[22]	147
GMStatus_Cnt_M_u8[23]	147
GMStatus_Cnt_M_u8[24]	147
GMStatus_Cnt_M_u8[25]	147

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[26]	147		
GMStatus_Cnt_M_u8[27]	147		
GMStatus_Cnt_M_u8[28]	147		
GMStatus_Cnt_M_u8[29]	147		
GMStatus_Cnt_M_u8[30]	147		
GMStatus_Cnt_M_u8[31]	147		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	255		
LKATrqOvrIdlvdRC_Cnt_M_u8	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	255		
LastReportedDTCEventID_Cnt_M_u8	35		
LastReportedGMStatus_Cnt_M_u8	147		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	4294967295		
Steering_Torque_Overlay_Stat_CE_c[0]	255		
Steering_Torque_Overlay_Stat_CE_c[1]	255		
Steering_Torque_Overlay_Stat_CE_c[2]	255		
Steering_Torque_Overlay_Stat_CE_c[3]	255		
Steering_Torque_Overlay_Stat_CE_c[4]	255		
Steering_Torque_Overlay_Stat_CE_c[5]	255		
Steering_Torque_Overlay_Stat_CE_c[6]	255		
Steering_Torque_Overlay_Stat_CE_c[7]	255		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	1		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	255		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	255		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4294967295		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	10.2299995		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	1		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	3		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	35	35	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTTriggered	1	1	✔
DTCDData.DTCSources	49	49	✔
DTCDData.DTCNumber	65535	65535	✔
DTCDData.DTCFailType	255	255	✔
DTCDData.DTCWmIndRqdSt	1	1	✔
DTCDData.DTCTstFldPwrUpSt	1	1	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	255	255	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	0	0	✓
GMStatus_Cnt_M_u8[0]	147	147	✓
GMStatus_Cnt_M_u8[1]	147	147	✓
GMStatus_Cnt_M_u8[2]	147	147	✓
GMStatus_Cnt_M_u8[3]	147	147	✓
GMStatus_Cnt_M_u8[4]	147	147	✓
GMStatus_Cnt_M_u8[5]	147	147	✓
GMStatus_Cnt_M_u8[6]	147	147	✓
GMStatus_Cnt_M_u8[7]	147	147	✓
GMStatus_Cnt_M_u8[8]	147	147	✓
GMStatus_Cnt_M_u8[9]	147	147	✓
GMStatus_Cnt_M_u8[10]	147	147	✓
GMStatus_Cnt_M_u8[11]	147	147	✓
GMStatus_Cnt_M_u8[12]	147	147	✓
GMStatus_Cnt_M_u8[13]	147	147	✓
GMStatus_Cnt_M_u8[14]	147	147	✓
GMStatus_Cnt_M_u8[15]	147	147	✓
GMStatus_Cnt_M_u8[16]	147	147	✓
GMStatus_Cnt_M_u8[17]	147	147	✓
GMStatus_Cnt_M_u8[18]	147	147	✓
GMStatus_Cnt_M_u8[19]	147	147	✓
GMStatus_Cnt_M_u8[20]	147	147	✓
GMStatus_Cnt_M_u8[21]	147	147	✓
GMStatus_Cnt_M_u8[22]	147	147	✓
GMStatus_Cnt_M_u8[23]	147	147	✓
GMStatus_Cnt_M_u8[24]	147	147	✓
GMStatus_Cnt_M_u8[25]	147	147	✓
GMStatus_Cnt_M_u8[26]	147	147	✓
GMStatus_Cnt_M_u8[27]	147	147	✓
GMStatus_Cnt_M_u8[28]	147	147	✓
GMStatus_Cnt_M_u8[29]	147	147	✓
GMStatus_Cnt_M_u8[30]	147	147	✓
GMStatus_Cnt_M_u8[31]	147	147	✓
LKATrqOvriDlvdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	35	35	✓
LastReportedGMStatus_Cnt_M_u8	147	147	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4294967295	4294967295	✓



Test Step Call Trace



SrlComOutput Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrStTtTqDlvd	1	IIPutTxLKAEIPwrStTtTqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.3 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	29	
CTCEventId_Cnt_M_u8	34	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DTCTriggered	0	
DTCDData.DTCSOURCE	1	
DTCDData.DTCTNumber	54010	
DTCDData.DTCTFailType	69	
DTCDData.DTCTWrnIndRqdSt	1	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	0	
DTCDData.DTCTHistStat	1	
DTCDData.DTCTstFldCdClrdStat	1	
DTCDData.DTCTstNPsdCdClrdSt	0	
DTCDData.DTCTCurrentStatus	0	
DTCDData.DTCTCodeSupported	0	
DTCDData.DTCTFaulttype	1	
DTCTriggeredFlag_Cnt_M_lgc[0]	0	
DTCTriggeredFlag_Cnt_M_lgc[1]	1	
DTCTriggeredFlag_Cnt_M_lgc[2]	0	
DTCTriggeredFlag_Cnt_M_lgc[3]	1	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	0	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	1	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	1	
DTCTriggeredFlag_Cnt_M_lgc[14]	0	
DTCTriggeredFlag_Cnt_M_lgc[15]	1	
DTCTriggeredFlag_Cnt_M_lgc[16]	0	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	1	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	0	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	207		
LKATrqOvrldvldRC_Cnt_M_u8	49		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26		
LastReportedDTCEventID_Cnt_M_u8	21		
LastReportedGMStatus_Cnt_M_u8	1		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	3967127296		
Steering_Torque_Overlay_Stat_CE_c[0]	12		
Steering_Torque_Overlay_Stat_CE_c[1]	14		
Steering_Torque_Overlay_Stat_CE_c[2]	16		
Steering_Torque_Overlay_Stat_CE_c[3]	18		
Steering_Torque_Overlay_Stat_CE_c[4]	20		
Steering_Torque_Overlay_Stat_CE_c[5]	22		
Steering_Torque_Overlay_Stat_CE_c[6]	24		
Steering_Torque_Overlay_Stat_CE_c[7]	26		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.100000001		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	11		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	53757		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3426999552		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	1.10000002		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.889999986		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.20000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	29	29	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSrc	1	1	✔
DTCDData.DTCNumber	54010	54010	✔
DTCDData.DTCFailType	69	69	✔
DTCDData.DTCWrmIndRqdSt	1	1	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdClrdStat	1	1	✔
DTCDData.DTCTstNPsdCdClrdSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	3	3	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	19	19	✓
GMStatus_Cnt_M_u8[2]	19	19	✓
GMStatus_Cnt_M_u8[3]	19	19	✓
GMStatus_Cnt_M_u8[4]	19	19	✓
GMStatus_Cnt_M_u8[5]	19	19	✓
GMStatus_Cnt_M_u8[6]	19	19	✓
GMStatus_Cnt_M_u8[7]	19	19	✓
GMStatus_Cnt_M_u8[8]	19	19	✓
GMStatus_Cnt_M_u8[9]	19	19	✓
GMStatus_Cnt_M_u8[10]	19	19	✓
GMStatus_Cnt_M_u8[11]	19	19	✓
GMStatus_Cnt_M_u8[12]	19	19	✓
GMStatus_Cnt_M_u8[13]	19	19	✓
GMStatus_Cnt_M_u8[14]	19	19	✓
GMStatus_Cnt_M_u8[15]	19	19	✓
GMStatus_Cnt_M_u8[16]	19	19	✓
GMStatus_Cnt_M_u8[17]	19	19	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	19	19	✓
GMStatus_Cnt_M_u8[20]	19	19	✓
GMStatus_Cnt_M_u8[21]	19	19	✓
GMStatus_Cnt_M_u8[22]	19	19	✓
GMStatus_Cnt_M_u8[23]	19	19	✓
GMStatus_Cnt_M_u8[24]	19	19	✓
GMStatus_Cnt_M_u8[25]	19	19	✓
GMStatus_Cnt_M_u8[26]	19	19	✓
GMStatus_Cnt_M_u8[27]	19	19	✓
GMStatus_Cnt_M_u8[28]	19	19	✓
GMStatus_Cnt_M_u8[29]	19	19	✓
GMStatus_Cnt_M_u8[30]	19	19	✓
GMStatus_Cnt_M_u8[31]	19	19	✓
LKATrqOvriDivdRC_Cnt_M_u8	49	49	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3967127296	3967127296	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxDTCL_TstNPsdCdCldSt_778	1	IIPutTxDTCL_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.4 (Repeat Count = 1) ✓

Name	Input Value
CTCEventIdSV_Cnt_M_u8	25
CTCEventId_Cnt_M_u8	33
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	3
DTCDData.DTCNumber	10044
DTCDData.DTCFailType	172
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	109
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	4
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	57
LKATrqOvrIDlvdRC_Cnt_M_u8	239
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52
LastReportedDTCEventID_Cnt_M_u8	17
LastReportedGMStatus_Cnt_M_u8	3
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2335839744		
Steering_Torque_Overlay_Stat_CE_c[0]	24		
Steering_Torque_Overlay_Stat_CE_c[1]	28		
Steering_Torque_Overlay_Stat_CE_c[2]	32		
Steering_Torque_Overlay_Stat_CE_c[3]	36		
Steering_Torque_Overlay_Stat_CE_c[4]	40		
Steering_Torque_Overlay_Stat_CE_c[5]	44		
Steering_Torque_Overlay_Stat_CE_c[6]	48		
Steering_Torque_Overlay_Stat_CE_c[7]	52		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.200000003		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	12		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	109		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	49026		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3464965120		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	1.20000005		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.620000005		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	0.200000003		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	25	25	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSource	3	3	✔
DTCDData.DTCNumber	10044	10044	✔
DTCDData.DTCFailType	172	172	✔
DTCDData.DTCWrnIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	0	0	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	109	109	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	5	5	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	17	17	✓
GMStatus_Cnt_M_u8[2]	17	17	✓
GMStatus_Cnt_M_u8[3]	17	17	✓
GMStatus_Cnt_M_u8[4]	17	17	✓
GMStatus_Cnt_M_u8[5]	17	17	✓
GMStatus_Cnt_M_u8[6]	17	17	✓
GMStatus_Cnt_M_u8[7]	17	17	✓
GMStatus_Cnt_M_u8[8]	17	17	✓
GMStatus_Cnt_M_u8[9]	17	17	✓
GMStatus_Cnt_M_u8[10]	17	17	✓
GMStatus_Cnt_M_u8[11]	17	17	✓
GMStatus_Cnt_M_u8[12]	17	17	✓
GMStatus_Cnt_M_u8[13]	17	17	✓
GMStatus_Cnt_M_u8[14]	17	17	✓
GMStatus_Cnt_M_u8[15]	17	17	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	17	17	✓
GMStatus_Cnt_M_u8[18]	17	17	✓
GMStatus_Cnt_M_u8[19]	17	17	✓
GMStatus_Cnt_M_u8[20]	17	17	✓
GMStatus_Cnt_M_u8[21]	17	17	✓
GMStatus_Cnt_M_u8[22]	17	17	✓
GMStatus_Cnt_M_u8[23]	17	17	✓
GMStatus_Cnt_M_u8[24]	17	17	✓
GMStatus_Cnt_M_u8[25]	17	17	✓
GMStatus_Cnt_M_u8[26]	17	17	✓
GMStatus_Cnt_M_u8[27]	17	17	✓
GMStatus_Cnt_M_u8[28]	17	17	✓
GMStatus_Cnt_M_u8[29]	17	17	✓
GMStatus_Cnt_M_u8[30]	17	17	✓
GMStatus_Cnt_M_u8[31]	17	17	✓
LKATrqOvriDlvdRC_Cnt_M_u8	240	240	✓
LastReportedDTCEventID_Cnt_M_u8	17	17	✓
LastReportedGMStatus_Cnt_M_u8	3	3	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2335839744	2335839744	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFidCdClrdStat_778	1	IIPutTxDTCl_TstFidCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFidPwrUpSt_778	1	IIPutTxDTCl_TstFidPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.5 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	32	
CTCEventId_Cnt_M_u8	35	
CurrentDTCSentThisIC_Cnt_M_lgc	0	
DTCDData.DTCTriggered	1	
DTCDData.DTCSource	5	
DTCDData.DTCNumber	51986	
DTCDData.DTCFailType	255	
DTCDData.DTCWrmIndRqdSt	1	
DTCDData.DTCTstFidPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	1	
DTCDData.DTCHistStat	0	
DTCDData.DTCTstFidCdClrdStat	0	
DTCDData.DTCTstNPsdCdClrdSt	1	
DTCDData.DTCCurrentStatus	0	
DTCDData.DTCCodeSupported	0	
DTCDData.DTCFaulttype	63	
DTCTriggeredFlag_Cnt_M_lgc[0]	0	
DTCTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTriggeredFlag_Cnt_M_lgc[2]	1	
DTCTriggeredFlag_Cnt_M_lgc[3]	1	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	0	
DTCTriggeredFlag_Cnt_M_lgc[6]	1	
DTCTriggeredFlag_Cnt_M_lgc[7]	1	
DTCTriggeredFlag_Cnt_M_lgc[8]	0	
DTCTriggeredFlag_Cnt_M_lgc[9]	1	
DTCTriggeredFlag_Cnt_M_lgc[10]	0	
DTCTriggeredFlag_Cnt_M_lgc[11]	1	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	1	
DTCTriggeredFlag_Cnt_M_lgc[14]	0	
DTCTriggeredFlag_Cnt_M_lgc[15]	1	
DTCTriggeredFlag_Cnt_M_lgc[16]	0	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	0	
DTCTriggeredFlag_Cnt_M_lgc[19]	1	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	
DTCTriggeredFlag_Cnt_M_lgc[26]	0	
DTCTriggeredFlag_Cnt_M_lgc[27]	0	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	1
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	11

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKATrqOvrldIvdRC_Cnt_M_u8	104		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	42		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	54		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	66		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	78		
LastReportedDTCEventID_Cnt_M_u8	12		
LastReportedGMStatus_Cnt_M_u8	5		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	1304985856		
Steering_Torque_Overlay_Stat_CE_c[0]	36		
Steering_Torque_Overlay_Stat_CE_c[1]	42		
Steering_Torque_Overlay_Stat_CE_c[2]	48		
Steering_Torque_Overlay_Stat_CE_c[3]	54		
Steering_Torque_Overlay_Stat_CE_c[4]	60		
Steering_Torque_Overlay_Stat_CE_c[5]	66		
Steering_Torque_Overlay_Stat_CE_c[6]	72		
Steering_Torque_Overlay_Stat_CE_c[7]	78		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.300000012		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	13		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	63		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	33357		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3149479680		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	1.29999995		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.5		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	2.0999999		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-2.06999993		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	32	32	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	5	5	✓
DTCDData.DTCNumber	51986	51986	✓
DTCDData.DTCFailType	255	255	✓
DTCDData.DTCWmIndRqdSt	1	1	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrUpSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	63	63	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	2	2	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	19	19	✓
GMStatus_Cnt_M_u8[2]	19	19	✓
GMStatus_Cnt_M_u8[3]	19	19	✓
GMStatus_Cnt_M_u8[4]	19	19	✓
GMStatus_Cnt_M_u8[5]	19	19	✓
GMStatus_Cnt_M_u8[6]	19	19	✓
GMStatus_Cnt_M_u8[7]	19	19	✓
GMStatus_Cnt_M_u8[8]	19	19	✓
GMStatus_Cnt_M_u8[9]	19	19	✓
GMStatus_Cnt_M_u8[10]	19	19	✓
GMStatus_Cnt_M_u8[11]	19	19	✓
GMStatus_Cnt_M_u8[12]	19	19	✓
GMStatus_Cnt_M_u8[13]	19	19	✓
GMStatus_Cnt_M_u8[14]	19	19	✓
GMStatus_Cnt_M_u8[15]	19	19	✓
GMStatus_Cnt_M_u8[16]	19	19	✓
GMStatus_Cnt_M_u8[17]	19	19	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	19	19	✓
GMStatus_Cnt_M_u8[20]	19	19	✓
GMStatus_Cnt_M_u8[21]	19	19	✓
GMStatus_Cnt_M_u8[22]	19	19	✓
GMStatus_Cnt_M_u8[23]	19	19	✓
GMStatus_Cnt_M_u8[24]	19	19	✓
GMStatus_Cnt_M_u8[25]	19	19	✓
GMStatus_Cnt_M_u8[26]	19	19	✓
GMStatus_Cnt_M_u8[27]	19	19	✓
GMStatus_Cnt_M_u8[28]	19	19	✓
GMStatus_Cnt_M_u8[29]	19	19	✓
GMStatus_Cnt_M_u8[30]	19	19	✓
GMStatus_Cnt_M_u8[31]	19	19	✓
LKATrqOvriDivdRC_Cnt_M_u8	104	104	✓
LastReportedDTCEventID_Cnt_M_u8	12	12	✓
LastReportedGMStatus_Cnt_M_u8	5	5	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1304985856	1304985856	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdCldSt_778	1	IIPutTxDTCL_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.6 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	8	
CTCEventId_Cnt_M_u8	30	
CurrentDTCSentThisIC_Cnt_M_lgc	0	
DTCDData.DTCTriggered	0	
DTCDData.DTCSource	7	
DTCDData.DTCNumber	28091	
DTCDData.DTCFailType	97	
DTCDData.DTCWrnIndRqdSt	0	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	0	
DTCDData.DTCHistStat	0	
DTCDData.DTCTstFldCdCldStat	0	
DTCDData.DTCTstNPsdCdCldSt	0	
DTCDData.DTCCurrentStatus	1	
DTCDData.DTCCodeSupported	1	
DTCDData.DTCFaulttype	249	
DTCTriggeredFlag_Cnt_M_lgc[0]	1	
DTCTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTriggeredFlag_Cnt_M_lgc[2]	1	
DTCTriggeredFlag_Cnt_M_lgc[3]	0	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	1	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	0	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	0	
DTCTriggeredFlag_Cnt_M_lgc[14]	1	
DTCTriggeredFlag_Cnt_M_lgc[15]	0	
DTCTriggeredFlag_Cnt_M_lgc[16]	1	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	0	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	
DTCTriggeredFlag_Cnt_M_lgc[26]	0	
DTCTriggeredFlag_Cnt_M_lgc[27]	1	
DTCTriggeredFlag_Cnt_M_lgc[28]	0	
DTCTriggeredFlag_Cnt_M_lgc[29]	1	
DTCTriggeredFlag_Cnt_M_lgc[30]	1	
DTCTriggeredFlag_Cnt_M_lgc[31]	0	
DemDTCNum_Cnt_M_u32[0]	100	
DemDTCNum_Cnt_M_u32[1]	200	
DemDTCNum_Cnt_M_u32[2]	300	
DemDTCNum_Cnt_M_u32[3]	400	
DemDTCNum_Cnt_M_u32[4]	500	
DemDTCNum_Cnt_M_u32[5]	600	
DemDTCNum_Cnt_M_u32[6]	700	
DemDTCNum_Cnt_M_u32[7]	800	
DemDTCNum_Cnt_M_u32[8]	900	
DemDTCNum_Cnt_M_u32[9]	1000	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	3
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	149
LKATrqOvriDlvdRC_Cnt_M_u8	210
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104
LastReportedDTCEventID_Cnt_M_u8	19
LastReportedGMStatus_Cnt_M_u8	7
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2575908864		
Steering_Torque_Overlay_Stat_CE_c[0]	48		
Steering_Torque_Overlay_Stat_CE_c[1]	56		
Steering_Torque_Overlay_Stat_CE_c[2]	64		
Steering_Torque_Overlay_Stat_CE_c[3]	72		
Steering_Torque_Overlay_Stat_CE_c[4]	80		
Steering_Torque_Overlay_Stat_CE_c[5]	88		
Steering_Torque_Overlay_Stat_CE_c[6]	96		
Steering_Torque_Overlay_Stat_CE_c[7]	104		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.400000006		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	14		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	249		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	2008		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	137299456		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	1.39999998		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.400000006		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	0		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.10000002		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	8	8	✔
CTCEventId_Cnt_M_u8	31	31	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	0	0	✔
DTCDData.DTCFailType	0	0	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdClrdStat	0	0	✔
DTCDData.DTCTstNPsdCdClrdSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	4	4	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrldIvdRC_Cnt_M_u8	210	210	✓
LastReportedDTCEventID_Cnt_M_u8	19	19	✓
LastReportedGMStatus_Cnt_M_u8	7	7	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCTFlag_ms_M_u32p0	2575908864	2575908864	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItTqDlrd	1	IIPutTxElPwrStItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrcSource_778	1	IIPutTxDTCl_DTCSrcSource_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.7 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSrcSource	9
DTCDData.DTCTNumber	35642
DTCDData.DTCTFailType	93
DTCDData.DTCTWrmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCTCurrentStatus	0
DTCDData.DTCTCodeSupported	1
DTCDData.DTCTFaulttype	240
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	8
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[26]	27		
GMStatus_Cnt_M_u8[27]	28		
GMStatus_Cnt_M_u8[28]	29		
GMStatus_Cnt_M_u8[29]	30		
GMStatus_Cnt_M_u8[30]	31		
GMStatus_Cnt_M_u8[31]	32		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	104		
LKATrqOvrDlvdRC_Cnt_M_u8	63		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130		
LastReportedDTCEventID_Cnt_M_u8	13		
LastReportedGMStatus_Cnt_M_u8	9		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2885878528		
Steering_Torque_Overlay_Stat_CE_c[0]	60		
Steering_Torque_Overlay_Stat_CE_c[1]	70		
Steering_Torque_Overlay_Stat_CE_c[2]	80		
Steering_Torque_Overlay_Stat_CE_c[3]	90		
Steering_Torque_Overlay_Stat_CE_c[4]	100		
Steering_Torque_Overlay_Stat_CE_c[5]	110		
Steering_Torque_Overlay_Stat_CE_c[6]	120		
Steering_Torque_Overlay_Stat_CE_c[7]	130		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.5		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	15		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	240		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	48500		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	380219648		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	1.5		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.439999998		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-3.5999999		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-2.0999999		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	14	14	✔
CTCEventId_Cnt_M_u8	14	14	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSrc	49	49	✔
DTCDData.DTCNumber	1	1	✔
DTCDData.DTCFailType	69	69	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	9	9	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvriDlvdRC_Cnt_M_u8	64	64	✓
LastReportedDTCEventID_Cnt_M_u8	13	13	✓
LastReportedGMStatus_Cnt_M_u8	9	9	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	380219648	380219648	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrlTrqDStat	1	IIPutTxTrqOvrlTrqDStat	1	✓
IIPutTxTrqOvrlDvrdARC	1	IIPutTxTrqOvrlDvrdARC	1	✓
IIPutTxTrqOvrlDltTrqDlrd	1	IIPutTxTrqOvrlDltTrqDlrd	1	✓
IIPutTxTrqOvrlDChksm	1	IIPutTxTrqOvrlDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.8 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	19
CTCEventId_Cnt_M_u8	28
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	11
DTCDData.DTCNumber	4682
DTCDData.DTCFailType	117
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	139
DTCTriggeredFlag_Cnt_M_lgc[0]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	11
LKATrqOvrIDlvdRC_Cnt_M_u8	105
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	23
LastReportedGMStatus_Cnt_M_u8	11
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKAState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	2204219904
Steering_Torque_Overlay_Stat_CE_c[0]	72
Steering_Torque_Overlay_Stat_CE_c[1]	84
Steering_Torque_Overlay_Stat_CE_c[2]	96
Steering_Torque_Overlay_Stat_CE_c[3]	108
Steering_Torque_Overlay_Stat_CE_c[4]	120
Steering_Torque_Overlay_Stat_CE_c[5]	132
Steering_Torque_Overlay_Stat_CE_c[6]	144
Steering_Torque_Overlay_Stat_CE_c[7]	156
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.600000024
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	16
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	139
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	47598
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2141564928
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	1.60000002
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.0900000036
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	6.19999981
target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data	0
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.29999995

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	19	19	✓
CTCEventId_Cnt_M_u8	29	29	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	106	106	✓
LastReportedDTCEventID_Cnt_M_u8	23	23	✓
LastReportedGMStatus_Cnt_M_u8	11	11	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2204219904	2204219904	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFidCdClrdStat_778	1	IIPutTxDTCl_TstFidCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFidPwrUpSt_778	1	IIPutTxDTCl_TstFidPwrUpSt_778	1	✓
IIPutTxDTCl_WrmlndRqdSt_778	1	IIPutTxDTCl_WrmlndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.9 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTriggered	0
DTCDData.DTCSrc	13
DTCDData.DTCNbr	3704
DTCDData.DTCFailType	184
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	102
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	10
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	164
LKATrqOvrldvldRC_Cnt_M_u8	77
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	20
LastReportedGMStatus_Cnt_M_u8	13
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	14783744
Steering_Torque_Overlay_Stat_CE_c[0]	84
Steering_Torque_Overlay_Stat_CE_c[1]	98
Steering_Torque_Overlay_Stat_CE_c[2]	112
Steering_Torque_Overlay_Stat_CE_c[3]	126
Steering_Torque_Overlay_Stat_CE_c[4]	140
Steering_Torque_Overlay_Stat_CE_c[5]	154
Steering_Torque_Overlay_Stat_CE_c[6]	168
Steering_Torque_Overlay_Stat_CE_c[7]	182

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.699999988		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	17		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	102		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	40092		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	929936128		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	1.70000005		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.300000012		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-9.69999981		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	2.79999995		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	12	12	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSorce	13	13	✓
DTCDData.DTCNumber	3704	3704	✓
DTCDData.DTCFailType	184	184	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldrStat	0	0	✓
DTCDData.DTCTstNPsdCdCldrSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	102	102	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	11	11	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	3	3	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	3	3	✓
GMStatus_Cnt_M_u8[4]	3	3	✓
GMStatus_Cnt_M_u8[5]	3	3	✓
GMStatus_Cnt_M_u8[6]	3	3	✓
GMStatus_Cnt_M_u8[7]	3	3	✓
GMStatus_Cnt M_u8[8]	3	3	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[9]	3	3	✓
GMStatus_Cnt_M_u8[10]	3	3	✓
GMStatus_Cnt_M_u8[11]	3	3	✓
GMStatus_Cnt_M_u8[12]	3	3	✓
GMStatus_Cnt_M_u8[13]	3	3	✓
GMStatus_Cnt_M_u8[14]	3	3	✓
GMStatus_Cnt_M_u8[15]	3	3	✓
GMStatus_Cnt_M_u8[16]	3	3	✓
GMStatus_Cnt_M_u8[17]	3	3	✓
GMStatus_Cnt_M_u8[18]	3	3	✓
GMStatus_Cnt_M_u8[19]	3	3	✓
GMStatus_Cnt_M_u8[20]	3	3	✓
GMStatus_Cnt_M_u8[21]	3	3	✓
GMStatus_Cnt_M_u8[22]	3	3	✓
GMStatus_Cnt_M_u8[23]	3	3	✓
GMStatus_Cnt_M_u8[24]	3	3	✓
GMStatus_Cnt_M_u8[25]	3	3	✓
GMStatus_Cnt_M_u8[26]	3	3	✓
GMStatus_Cnt_M_u8[27]	3	3	✓
GMStatus_Cnt_M_u8[28]	3	3	✓
GMStatus_Cnt_M_u8[29]	3	3	✓
GMStatus_Cnt_M_u8[30]	3	3	✓
GMStatus_Cnt_M_u8[31]	3	3	✓
LKATrqOvriDlvdRC_Cnt_M_u8	78	78	✓
LastReportedDTCEventID_Cnt_M_u8	20	20	✓
LastReportedGMStatus_Cnt_M_u8	13	13	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	14783744	14783744	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.10 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	7	
CTCEventId_Cnt_M_u8	9	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DTCTriggered	0	
DTCDData.DTCSource	15	
DTCDData.DTCNumber	54744	
DTCDData.DTCFailType	65	
DTCDData.DTCWrmIndRqdSt	0	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	0	
DTCDData.DTCHistStat	1	
DTCDData.DTCTstFldCdClrdStat	1	
DTCDData.DTCTstNPsdCdClrdSt	1	
DTCDData.DTCCurrentStatus	1	
DTCDData.DTCCodeSupported	0	
DTCDData.DTCFaulttype	67	
DTCTriggeredFlag_Cnt_M_lgc[0]	1	
DTCTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTriggeredFlag_Cnt_M_lgc[2]	1	
DTCTriggeredFlag_Cnt_M_lgc[3]	0	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	1	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	0	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	0	
DTCTriggeredFlag_Cnt_M_lgc[14]	1	
DTCTriggeredFlag_Cnt_M_lgc[15]	0	
DTCTriggeredFlag_Cnt_M_lgc[16]	1	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	0	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	
DTCTriggeredFlag_Cnt_M_lgc[26]	0	
DTCTriggeredFlag_Cnt_M_lgc[27]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	14
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	77

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKATrqOvrDlvdRC_Cnt_M_u8	106		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventID_Cnt_M_u8	4		
LastReportedGMStatus_Cnt_M_u8	15		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3985507328		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.800000012		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	18		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	67		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	56381		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	669100544		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	1.79999995		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.810000002		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	5.96999979		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	2.70000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	7	7	✓
CTCEventId_Cnt_M_u8	10	10	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	29	29	✓
DTCDData.DTCFailType	76	76	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrUpSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	15	15	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	107	107	✓
LastReportedDTCEventID_Cnt_M_u8	4	4	✓
LastReportedGMStatus_Cnt_M_u8	15	15	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3985507328	3985507328	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStTtITqDlrd	1	IIPutTxElPwrStTtITqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrStTtITqDlvd	1	IIPutTxLKAEIPwrStTtITqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.11 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	2
CTCEventId_Cnt_M_u8	18
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	17
DTCDData.DTCNumber	46609
DTCDData.DTCFailType	42
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	9
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	11
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	113
LKATrqOvrDivdRC_Cnt_M_u8	4
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	17
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3478930944
Steering_Torque_Overlay_Stat_CE_c[0]	72
Steering_Torque_Overlay_Stat_CE_c[1]	84
Steering_Torque_Overlay_Stat_CE_c[2]	96
Steering_Torque_Overlay_Stat_CE_c[3]	108
Steering_Torque_Overlay_Stat_CE_c[4]	120
Steering_Torque_Overlay_Stat_CE_c[5]	132
Steering_Torque_Overlay_Stat_CE_c[6]	144
Steering_Torque_Overlay_Stat_CE_c[7]	156
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.899999976
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	19
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	9
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	22783
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2357713920
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	1.89999998
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.600000024
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	7.0999999
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	2.69000006

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	2	2	✓
CTCEventId_Cnt_M_u8	19	19	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	2	*none*	✓
DTCDData.DTCFailType	68	*none*	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	12	12	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	5	5	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	17	17	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_ms_M_u32p0	3478930944	3478930944	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.12 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	17
CTCEventId_Cnt_M_u8	28
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCSource	19
DTCDData.DTCNumber	12114
DTCDData.DTCFailType	169
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	33
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	5
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	186
LKATrqOvrIDlvdRC_Cnt_M_u8	248
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	15
LastReportedGMStatus_Cnt_M_u8	19
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	102887680
Steering_Torque_Overlay_Stat_CE_c[0]	84
Steering_Torque_Overlay_Stat_CE_c[1]	98
Steering_Torque_Overlay_Stat_CE_c[2]	112
Steering_Torque_Overlay_Stat_CE_c[3]	126
Steering_Torque_Overlay_Stat_CE_c[4]	140
Steering_Torque_Overlay_Stat_CE_c[5]	154
Steering_Torque_Overlay_Stat_CE_c[6]	168
Steering_Torque_Overlay_Stat_CE_c[7]	182
k_LKAMfgEnable_Cnt_lgc	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_MaxHOWEstimate_Uls_f32	0.00999999978		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	20		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	8857		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2692165376		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	2		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.800000012		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	4.800000019		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-1.5		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	17	17	✓
CTCEventId_Cnt_M_u8	29	29	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSrc	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	6	6	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvriDlvdRC_Cnt_M_u8	249	249	✓
LastReportedDTCEventID_Cnt_M_u8	15	15	✓
LastReportedGMStatus_Cnt_M_u8	19	19	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	102887680	102887680	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrItqDStat	1	IIPutTxTrqOvrItqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtmD	1	IIPutTxHndsOffStrWhlDtmD	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrItqDStat	1	IIPutTxLKATrqOvrItqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.13 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	20
CTCEventId_Cnt_M_u8	6
CurrentDTCSentThisIC_Cnt_M_Igc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSOURCE	21
DTCDData.DTCTNumber	64499
DTCDData.DTCTFailType	223
DTCDData.DTCTWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCTHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCTCurrentStatus	1
DTCDData.DTCTCodeSupported	0
DTCDData.DTCTFaulttype	13
DTCTriggeredFlag_Cnt_M_Igc[0]	0
DTCTriggeredFlag_Cnt_M_Igc[1]	1
DTCTriggeredFlag_Cnt_M_Igc[2]	0
DTCTriggeredFlag_Cnt_M_Igc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	7
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	11		
GMStatus_Cnt_M_u8[11]	12		
GMStatus_Cnt_M_u8[12]	13		
GMStatus_Cnt_M_u8[13]	14		
GMStatus_Cnt_M_u8[14]	15		
GMStatus_Cnt_M_u8[15]	16		
GMStatus_Cnt_M_u8[16]	17		
GMStatus_Cnt_M_u8[17]	18		
GMStatus_Cnt_M_u8[18]	19		
GMStatus_Cnt_M_u8[19]	20		
GMStatus_Cnt_M_u8[20]	21		
GMStatus_Cnt_M_u8[21]	22		
GMStatus_Cnt_M_u8[22]	23		
GMStatus_Cnt_M_u8[23]	24		
GMStatus_Cnt_M_u8[24]	25		
GMStatus_Cnt_M_u8[25]	26		
GMStatus_Cnt_M_u8[26]	27		
GMStatus_Cnt_M_u8[27]	28		
GMStatus_Cnt_M_u8[28]	29		
GMStatus_Cnt_M_u8[29]	30		
GMStatus_Cnt_M_u8[30]	31		
GMStatus_Cnt_M_u8[31]	32		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	50		
LKATrqOvriDlvdRC_Cnt_M_u8	228		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26		
LastReportedDTCEventID_Cnt_M_u8	9		
LastReportedGMStatus_Cnt_M_u8	21		
PrevWarningIndSignal_Cnt_M_u8[0]	0		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	2818881280		
Steering_Torque_Overlay_Stat_CE_c[0]	12		
Steering_Torque_Overlay_Stat_CE_c[1]	14		
Steering_Torque_Overlay_Stat_CE_c[2]	16		
Steering_Torque_Overlay_Stat_CE_c[3]	18		
Steering_Torque_Overlay_Stat_CE_c[4]	20		
Steering_Torque_Overlay_Stat_CE_c[5]	22		
Steering_Torque_Overlay_Stat_CE_c[6]	24		
Steering_Torque_Overlay_Stat_CE_c[7]	26		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.0299999993		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	21		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	13		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	5719		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1059177728		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	2.09999999		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.300000012		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-9.01000023		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-3		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	6	6	✓
CTCEventId_Cnt_M_u8	6	6	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSrc	49	49	✓
DTCDData.DTCNbr	2	2	✓
DTCDData.DTCFailType	188	188	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	8	8	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvriDlvdRC_Cnt_M_u8	229	229	✓
LastReportedDTCEventID_Cnt_M_u8	9	9	✓
LastReportedGMStatus_Cnt_M_u8	21	21	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1059177728	1059177728	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMtd	1	IIPutTxHndsOffStrWhlDtMtd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.14 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	22
CTCEventId_Cnt_M_u8	25
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCTData.DTCTTriggered	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCSource	23
DTCDData.DTCNumber	1263
DTCDData.DTCFailType	200
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	128
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	6
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	131
LKATrqOvrIDlvdRC_Cnt_M_u8	120
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52
LastReportedDTCEventID_Cnt_M_u8	13
LastReportedGMStatus_Cnt_M_u8	23
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCTFlag_mS_M_u32p0	3878460928
Steering_Torque_Overlay_Stat_CE_c[0]	24
Steering_Torque_Overlay_Stat_CE_c[1]	28
Steering_Torque_Overlay_Stat_CE_c[2]	32
Steering_Torque_Overlay_Stat_CE_c[3]	36
Steering_Torque_Overlay_Stat_CE_c[4]	40
Steering_Torque_Overlay_Stat_CE_c[5]	44
Steering_Torque_Overlay_Stat_CE_c[6]	48
Steering_Torque_Overlay_Stat_CE_c[7]	52
k_LKAMfgEnable_Cnt_lgc	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_MaxHOWEstimate_Uls_f32	0.0500000007		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	22		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	27924		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2945283072		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	2.20000005		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.389999986		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-1.29999995		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	3		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	22	22	✓
CTCEventId_Cnt_M_u8	26	26	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	54	54	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	7	7	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDlvdRC_Cnt_M_u8	121	121	✓
LastReportedDTCEventID_Cnt_M_u8	13	13	✓
LastReportedGMStatus_Cnt_M_u8	23	23	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3878460928	3878460928	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SrlComOutput_Per1



Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.15 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	5
CTCEventId_Cnt_M_u8	0
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	25
DTCDData.DTCNumber	43033
DTCDData.DTCFailType	118
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	226
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	83
LKATrqOvrDlvdRC_Cnt_M_u8	104
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	42
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	54
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	66
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	78
LastReportedDTCEventID_Cnt_M_u8	21
LastReportedGMStatus_Cnt_M_u8	25
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	235989248
Steering_Torque_Overlay_Stat_CE_c[0]	36
Steering_Torque_Overlay_Stat_CE_c[1]	42
Steering_Torque_Overlay_Stat_CE_c[2]	48
Steering_Torque_Overlay_Stat_CE_c[3]	54
Steering_Torque_Overlay_Stat_CE_c[4]	60
Steering_Torque_Overlay_Stat_CE_c[5]	66
Steering_Torque_Overlay_Stat_CE_c[6]	72
Steering_Torque_Overlay_Stat_CE_c[7]	78
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.0700000003
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	23
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	226
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	35257
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3955648256
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	2.29999995
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.200000003
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	8.10000038
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	0.49000001

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	0	0	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	115	115	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvriDlvdRC_Cnt_M_u8	105	105	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	25	25	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3955648256	3955648256	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDlvdARC	1	IIPutTxTrqOvriDlvdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDltSt	1	IIPutTxHndsOffStrWhlDltSt	1	✓
IIPutTxHndsOffStrWhlDltMd	1	IIPutTxHndsOffStrWhlDltMd	1	✓
IIPutTxHndsOffStrWhlDltStV	1	IIPutTxHndsOffStrWhlDltStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDltStGroup	1	IIPutTxHndsOffStrWhlDltStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.16 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	2

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
CTCEventId_Cnt_M_u8	12
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTTriggered	0
DTCDData.DTCSSource	27
DTCDData.DTCNumber	62535
DTCDData.DTCFailType	32
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	251
DTCTTriggeredFlag_Cnt_M_lgc[0]	1
DTCTTriggeredFlag_Cnt_M_lgc[1]	0
DTCTTriggeredFlag_Cnt_M_lgc[2]	1
DTCTTriggeredFlag_Cnt_M_lgc[3]	0
DTCTTriggeredFlag_Cnt_M_lgc[4]	1
DTCTTriggeredFlag_Cnt_M_lgc[5]	1
DTCTTriggeredFlag_Cnt_M_lgc[6]	1
DTCTTriggeredFlag_Cnt_M_lgc[7]	0
DTCTTriggeredFlag_Cnt_M_lgc[8]	1
DTCTTriggeredFlag_Cnt_M_lgc[9]	0
DTCTTriggeredFlag_Cnt_M_lgc[10]	1
DTCTTriggeredFlag_Cnt_M_lgc[11]	0
DTCTTriggeredFlag_Cnt_M_lgc[12]	1
DTCTTriggeredFlag_Cnt_M_lgc[13]	0
DTCTTriggeredFlag_Cnt_M_lgc[14]	1
DTCTTriggeredFlag_Cnt_M_lgc[15]	0
DTCTTriggeredFlag_Cnt_M_lgc[16]	1
DTCTTriggeredFlag_Cnt_M_lgc[17]	1
DTCTTriggeredFlag_Cnt_M_lgc[18]	1
DTCTTriggeredFlag_Cnt_M_lgc[19]	0
DTCTTriggeredFlag_Cnt_M_lgc[20]	0
DTCTTriggeredFlag_Cnt_M_lgc[21]	1
DTCTTriggeredFlag_Cnt_M_lgc[22]	0
DTCTTriggeredFlag_Cnt_M_lgc[23]	1
DTCTTriggeredFlag_Cnt_M_lgc[24]	1
DTCTTriggeredFlag_Cnt_M_lgc[25]	1
DTCTTriggeredFlag_Cnt_M_lgc[26]	0
DTCTTriggeredFlag_Cnt_M_lgc[27]	1
DTCTTriggeredFlag_Cnt_M_lgc[28]	0
DTCTTriggeredFlag_Cnt_M_lgc[29]	1
DTCTTriggeredFlag_Cnt_M_lgc[30]	1
DTCTTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	13
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	202
LKATrqOvrDlvdRC_Cnt_M_u8	130
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104
LastReportedDTCEventID_Cnt_M_u8	19
LastReportedGMStatus_Cnt_M_u8	27
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	1548748800
Steering_Torque_Overlay_Stat_CE_c[0]	48
Steering_Torque_Overlay_Stat_CE_c[1]	56
Steering_Torque_Overlay_Stat_CE_c[2]	64
Steering_Torque_Overlay_Stat_CE_c[3]	72
Steering_Torque_Overlay_Stat_CE_c[4]	80
Steering_Torque_Overlay_Stat_CE_c[5]	88

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
Steering_Torque_Overlay_Stat_CE_c[6]	96		
Steering_Torque_Overlay_Stat_CE_c[7]	104		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.0900000036		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	24		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	16694		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Current	2124910080		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-6.5		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.6000000024		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	6.59999999		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	0		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	2	2	✔
CTCEventId_Cnt_M_u8	13	13	✔
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✔
DTCData.DTCTriggered	0	0	✔
DTCData.DTCSource	49	49	✔
DTCData.DTCNumber	0	0	✔
DTCData.DTCFailType	0	0	✔
DTCData.DTCWmIndRqdSt	0	0	✔
DTCData.DTCTstFldPwrUpSt	0	0	✔
DTCData.DTCTstNPsdPwrupSt	0	0	✔
DTCData.DTCHistStat	0	0	✔
DTCData.DTCTstFldCdCldStat	0	0	✔
DTCData.DTCTstNPsdCdCldSt	0	0	✔
DTCData.DTCCurrentStatus	0	0	✔
DTCData.DTCCodeSupported	0	0	✔
DTCData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[31]	0	0	✔
ESCRollCount_Cnt_M_u08	14	14	✔
GMStatus_Cnt_M_u8[0]	2	2	✔
GMStatus_Cnt_M_u8[1]	4	4	✔
GMStatus_Cnt_M_u8[2]	6	6	✔
GMStatus_Cnt_M_u8[3]	8	8	✔
GMStatus_Cnt_M_u8[4]	10	10	✔
GMStatus_Cnt_M_u8[5]	12	12	✔
GMStatus_Cnt_M_u8[6]	14	14	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	131	131	✓
LastReportedDTCEventID_Cnt_M_u8	19	19	✓
LastReportedGMStatus_Cnt_M_u8	27	27	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1548748800	1548748800	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.17 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	22
CTCEventId_Cnt_M_u8	24
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	29
DTCDData.DTCNumber	7865
DTCDData.DTCFailType	50
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	165
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	12
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	36
LKATrqOvrDivdRC_Cnt_M_u8	166
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130
LastReportedDTCEventID_Cnt_M_u8	19
LastReportedGMStatus_Cnt_M_u8	29
PrevWarningIndSignal_Cnt_M_u8[0]	1
PrevWarningIndSignal_Cnt_M_u8[1]	1
PrevWarningIndSignal_Cnt_M_u8[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3637422848
Steering_Torque_Overlay_Stat_CE_c[0]	60
Steering_Torque_Overlay_Stat_CE_c[1]	70
Steering_Torque_Overlay_Stat_CE_c[2]	80
Steering_Torque_Overlay_Stat_CE_c[3]	90
Steering_Torque_Overlay_Stat_CE_c[4]	100
Steering_Torque_Overlay_Stat_CE_c[5]	110
Steering_Torque_Overlay_Stat_CE_c[6]	120
Steering_Torque_Overlay_Stat_CE_c[7]	130
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.109999999
k_SComTrqPosPol_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	25
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	165
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	41594
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	526391552
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-6.30000019
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.5
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-2.1500001
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.20000005

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	22	22	✓
CTCEventId_Cnt_M_u8	25	25	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	13	13	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvrIDvdRC_Cnt_M_u8	167	167	✓
LastReportedDTCEventID_Cnt_M_u8	19	19	✓
LastReportedGMStatus_Cnt_M_u8	29	29	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3637422848	3637422848	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrIDtrqDStat	1	IIPutTxTrqOvrIDtrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKAState_State_enum	1	Rte_Read_Ap_SriComOutput_LKAState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrIDtrqDStat	1	IIPutTxLKATrqOvrIDtrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDvrdRC	1	IIPutTxLKATrqOvrIDvrdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIDStatChksm	1	IIPutTxLKATrqOvrIDStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdCldSt_778	1	IIPutTxDTCL_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.18 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	30
CTCEventId_Cnt_M_u8	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
CurrentDTCSThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	31
DTCDData.DTCNumber	25199
DTCDData.DTCFailType	62
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	183
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	135
LKATrqOvriDlvdRC_Cnt_M_u8	88
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	31
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	496943616
Steering_Torque_Overlay_Stat_CE_c[0]	72
Steering_Torque_Overlay_Stat_CE_c[1]	84
Steering_Torque_Overlay_Stat_CE_c[2]	96
Steering_Torque_Overlay_Stat_CE_c[3]	108
Steering_Torque_Overlay_Stat_CE_c[4]	120
Steering_Torque_Overlay_Stat_CE_c[5]	132
Steering_Torque_Overlay_Stat_CE_c[6]	144

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
Steering_Torque_Overlay_Stat_CE_c[7]	156		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.129999995		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	26		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	55162		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2703390720		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-6.0999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.280000001		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	2.70000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	30	30	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	12	*none*	✔
DTCDData.DTCFailType	128	*none*	✔
DTCDData.DTCWmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrUpSt	0	0	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[17]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[20]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[21]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[22]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[23]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[26]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[27]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[30]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	3	3	✔
GMStatus_Cnt_M_u8[0]	3	3	✔
GMStatus_Cnt_M_u8[1]	6	6	✔
GMStatus_Cnt_M_u8[2]	9	9	✔
GMStatus_Cnt_M_u8[3]	12	12	✔
GMStatus_Cnt_M_u8[4]	15	15	✔
GMStatus_Cnt_M_u8[5]	18	18	✔
GMStatus_Cnt_M_u8[6]	21	21	✔
GMStatus_Cnt_M_u8[7]	24	24	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SriComOutput_Per1



Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvriDlvdRC_Cnt_M_u8	89	89	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	31	31	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	496943616	496943616	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.19 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	23
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	33
DTCDData.DTCNumber	32296
DTCDData.DTCFailType	254
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaultype	137
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	4
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	40		
GMStatus_Cnt_M_u8[10]	44		
GMStatus_Cnt_M_u8[11]	48		
GMStatus_Cnt_M_u8[12]	52		
GMStatus_Cnt_M_u8[13]	56		
GMStatus_Cnt_M_u8[14]	60		
GMStatus_Cnt_M_u8[15]	64		
GMStatus_Cnt_M_u8[16]	68		
GMStatus_Cnt_M_u8[17]	72		
GMStatus_Cnt_M_u8[18]	76		
GMStatus_Cnt_M_u8[19]	80		
GMStatus_Cnt_M_u8[20]	84		
GMStatus_Cnt_M_u8[21]	88		
GMStatus_Cnt_M_u8[22]	92		
GMStatus_Cnt_M_u8[23]	96		
GMStatus_Cnt_M_u8[24]	100		
GMStatus_Cnt_M_u8[25]	104		
GMStatus_Cnt_M_u8[26]	108		
GMStatus_Cnt_M_u8[27]	112		
GMStatus_Cnt_M_u8[28]	116		
GMStatus_Cnt_M_u8[29]	120		
GMStatus_Cnt_M_u8[30]	124		
GMStatus_Cnt_M_u8[31]	128		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	254		
LKATrqOvriDlvdRC_Cnt_M_u8	149		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182		
LastReportedDTCEventID_Cnt_M_u8	27		
LastReportedGMStatus_Cnt_M_u8	33		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	1347058944		
Steering_Torque_Overlay_Stat_CE_c[0]	84		
Steering_Torque_Overlay_Stat_CE_c[1]	98		
Steering_Torque_Overlay_Stat_CE_c[2]	112		
Steering_Torque_Overlay_Stat_CE_c[3]	126		
Steering_Torque_Overlay_Stat_CE_c[4]	140		
Steering_Torque_Overlay_Stat_CE_c[5]	154		
Steering_Torque_Overlay_Stat_CE_c[6]	168		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.150000006		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	27		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	24088		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2685885184		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-5.9000001		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.699999988		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	8.30000019		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.60000002		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	23	23	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	33	33	✓
DTCDData.DTCNumber	32296	32296	✓
DTCDData.DTCFailType	254	254	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	137	137	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	5	5	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	19	19	✓
GMStatus_Cnt_M_u8[2]	19	19	✓
GMStatus_Cnt_M_u8[3]	19	19	✓
GMStatus_Cnt_M_u8[4]	19	19	✓
GMStatus_Cnt_M_u8[5]	19	19	✓
GMStatus_Cnt_M_u8[6]	19	19	✓
GMStatus_Cnt_M_u8[7]	19	19	✓
GMStatus_Cnt_M_u8[8]	19	19	✓
GMStatus_Cnt_M_u8[9]	19	19	✓
GMStatus_Cnt_M_u8[10]	19	19	✓
GMStatus_Cnt_M_u8[11]	19	19	✓
GMStatus_Cnt_M_u8[12]	19	19	✓
GMStatus_Cnt_M_u8[13]	19	19	✓
GMStatus_Cnt_M_u8[14]	19	19	✓
GMStatus_Cnt_M_u8[15]	19	19	✓
GMStatus_Cnt_M_u8[16]	19	19	✓
GMStatus_Cnt_M_u8[17]	19	19	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	19	19	✓
GMStatus_Cnt_M_u8[20]	19	19	✓
GMStatus_Cnt_M_u8[21]	19	19	✓
GMStatus_Cnt_M_u8[22]	19	19	✓
GMStatus_Cnt_M_u8[23]	19	19	✓
GMStatus_Cnt_M_u8[24]	19	19	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	19	19	✓
GMStatus_Cnt_M_u8[26]	19	19	✓
GMStatus_Cnt_M_u8[27]	19	19	✓
GMStatus_Cnt_M_u8[28]	19	19	✓
GMStatus_Cnt_M_u8[29]	19	19	✓
GMStatus_Cnt_M_u8[30]	19	19	✓
GMStatus_Cnt_M_u8[31]	19	19	✓
LKATrqOvriDlvdRC_Cnt_M_u8	150	150	✓
LastReportedDTCEventID_Cnt_M_u8	27	27	✓
LastReportedGMStatus_Cnt_M_u8	33	33	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1347058944	1347058944	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrStTtTqDlvd	1	IIPutTxLKAEIPwrStTtTqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.20 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	15	
CTCEventId_Cnt_M_u8	6	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DTCTriggered	0	
DTCDData.DTCSOURCE	35	
DTCDData.DTCTNumber	58986	
DTCDData.DTCTFailType	3	
DTCDData.DTCTWrnIndRqdSt	0	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	1	
DTCDData.DTCTHistStat	1	
DTCDData.DTCTstFldCdClrdStat	0	
DTCDData.DTCTstNPsdCdClrdSt	0	
DTCDData.DTCTCurrentStatus	1	
DTCDData.DTCTCodeSupported	0	
DTCDData.DTCTFaulttype	106	
DTCTriggeredFlag_Cnt_M_lgc[0]	1	
DTCTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTriggeredFlag_Cnt_M_lgc[2]	1	
DTCTriggeredFlag_Cnt_M_lgc[3]	0	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	1	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	0	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	0	
DTCTriggeredFlag_Cnt_M_lgc[14]	1	
DTCTriggeredFlag_Cnt_M_lgc[15]	0	
DTCTriggeredFlag_Cnt_M_lgc[16]	1	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	0	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	1
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	235		
LKATrqOvrldIvdRC_Cnt_M_u8	212		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventID_Cnt_M_u8	27		
LastReportedGMStatus_Cnt_M_u8	35		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	619924480		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.170000002		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	28		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	51561		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	109359616		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-5.69999981		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.899999976		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-8.81000042		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-0.0599999987		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	15	15	✔
CTCEventId_Cnt_M_u8	7	7	✔
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	2	2	✔
DTCDData.DTCFailType	8	8	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstINPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdClrdStat	0	0	✔
DTCDData.DTCTstINPsdCdClrdSt	0	0	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	2	2	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvriDivdRC_Cnt_M_u8	212	212	✓
LastReportedDTCEventID_Cnt_M_u8	27	27	✓
LastReportedGMStatus_Cnt_M_u8	35	35	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	619924480	619924480	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItTqDlrd	1	IIPutTxElPwrStItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrcSource_778	1	IIPutTxDTCl_DTCSrcSource_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.21 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	0
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSrcSource	37
DTCDData.DTCTNumber	11102
DTCDData.DTCTFailType	83
DTCDData.DTCTWrmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCTCurrentStatus	0
DTCDData.DTCTCodeSupported	1
DTCDData.DTCTFaulttype	111
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	3
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[26]	27		
GMStatus_Cnt_M_u8[27]	28		
GMStatus_Cnt_M_u8[28]	29		
GMStatus_Cnt_M_u8[29]	30		
GMStatus_Cnt_M_u8[30]	31		
GMStatus_Cnt_M_u8[31]	32		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	89		
LKATrqOvrDlvdRC_Cnt_M_u8	100		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26		
LastReportedDTCEventID_Cnt_M_u8	1		
LastReportedGMStatus_Cnt_M_u8	37		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	284483328		
Steering_Torque_Overlay_Stat_CE_c[0]	12		
Steering_Torque_Overlay_Stat_CE_c[1]	14		
Steering_Torque_Overlay_Stat_CE_c[2]	16		
Steering_Torque_Overlay_Stat_CE_c[3]	18		
Steering_Torque_Overlay_Stat_CE_c[4]	20		
Steering_Torque_Overlay_Stat_CE_c[5]	22		
Steering_Torque_Overlay_Stat_CE_c[6]	24		
Steering_Torque_Overlay_Stat_CE_c[7]	26		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.189999998		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	29		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	111		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	14834		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3646467328		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-5.5		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.140000001		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	9.939999958		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	0.670000017		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	14	14	✔
CTCEventId_Cnt_M_u8	14	14	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSorce	49	49	✔
DTCDData.DTCNumber	1	1	✔
DTCDData.DTCFailType	244	244	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	4	4	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	101	101	✓
LastReportedDTCEventID_Cnt_M_u8	1	1	✓
LastReportedGMStatus_Cnt_M_u8	37	37	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3646467328	3646467328	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCI_DTCTriggered_778	1	IIPutTxDTCI_DTCTriggered_778	1	✓
IIPutTxDTCI_DTCSOURCE_778	1	IIPutTxDTCI_DTCSOURCE_778	1	✓
IIPutTxDTCI_DTCNumber_778	1	IIPutTxDTCI_DTCNumber_778	1	✓
IIPutTxDTCI_DTCFailType_778	1	IIPutTxDTCI_DTCFailType_778	1	✓
IIPutTxDTCI_CodeSupported_778	1	IIPutTxDTCI_CodeSupported_778	1	✓
IIPutTxDTCI_CurrentStatus_778	1	IIPutTxDTCI_CurrentStatus_778	1	✓
IIPutTxDTCI_TstNPsdCdClrdSt_778	1	IIPutTxDTCI_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCI_TstFldCdClrdStat_778	1	IIPutTxDTCI_TstFldCdClrdStat_778	1	✓
IIPutTxDTCI_HistStat_778	1	IIPutTxDTCI_HistStat_778	1	✓
IIPutTxDTCI_TstNPsdPwrUpSt_778	1	IIPutTxDTCI_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCI_TstFldPwrUpSt_778	1	IIPutTxDTCI_TstFldPwrUpSt_778	1	✓
IIPutTxDTCI_WrnIndRqdSt_778	1	IIPutTxDTCI_WrnIndRqdSt_778	1	✓
IIPutTxDTCI_DTCFaultType_778	1	IIPutTxDTCI_DTCFaultType_778	1	✓
IIPutTxDTCTInfo_778	1	IIPutTxDTCTInfo_778	1	✓

Test Step 2.22 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	35
CTCEventId_Cnt_M_u8	20
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSOURCE	39
DTCDData.DTCNumber	54095
DTCDData.DTCFailType	182
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaultType	87
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	8
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	10		
GMStatus_Cnt_M_u8[10]	11		
GMStatus_Cnt_M_u8[11]	12		
GMStatus_Cnt_M_u8[12]	13		
GMStatus_Cnt_M_u8[13]	14		
GMStatus_Cnt_M_u8[14]	18		
GMStatus_Cnt_M_u8[15]	16		
GMStatus_Cnt_M_u8[16]	17		
GMStatus_Cnt_M_u8[17]	18		
GMStatus_Cnt_M_u8[18]	19		
GMStatus_Cnt_M_u8[19]	20		
GMStatus_Cnt_M_u8[20]	26		
GMStatus_Cnt_M_u8[21]	22		
GMStatus_Cnt_M_u8[22]	23		
GMStatus_Cnt_M_u8[23]	25		
GMStatus_Cnt_M_u8[24]	25		
GMStatus_Cnt_M_u8[25]	26		
GMStatus_Cnt_M_u8[26]	27		
GMStatus_Cnt_M_u8[27]	28		
GMStatus_Cnt_M_u8[28]	29		
GMStatus_Cnt_M_u8[29]	30		
GMStatus_Cnt_M_u8[30]	31		
GMStatus_Cnt_M_u8[31]	32		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	115		
LKATrqOvriDlvdRC_Cnt_M_u8	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventID_Cnt_M_u8	13		
LastReportedGMStatus_Cnt_M_u8	39		
PrevWarningIndSignal_Cnt_M_u8[0]	1		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	4277937664		
Steering_Torque_Overlay_Stat_CE_c[0]	24		
Steering_Torque_Overlay_Stat_CE_c[1]	28		
Steering_Torque_Overlay_Stat_CE_c[2]	32		
Steering_Torque_Overlay_Stat_CE_c[3]	36		
Steering_Torque_Overlay_Stat_CE_c[4]	40		
Steering_Torque_Overlay_Stat_CE_c[5]	44		
Steering_Torque_Overlay_Stat_CE_c[6]	48		
Steering_Torque_Overlay_Stat_CE_c[7]	52		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.209999993		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	30		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	87		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	49378		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3196632064		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-5.30000019		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.0299999993		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-2.3499999		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-0.649999976		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	20	20	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	20	20	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	123	123	✓
DTCDData.DTCFailType	12	12	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdClrdStat	1	1	✓
DTCDData.DTCTstNPsdCdClrdSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	9	9	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	18	18	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	26	26	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	25	25	✓
GMStatus_Cnt_M_u8[24]	25	25	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvriDlvdRC_Cnt_M_u8	60	60	✓
LastReportedDTCEventID_Cnt_M_u8	13	13	✓
LastReportedGMStatus_Cnt_M_u8	39	39	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3196632064	3196632064	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItIqDlrd	1	IIPutTxElPwrStItIqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSources_778	1	IIPutTxDTCL_DTCSources_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdCldSt_778	1	IIPutTxDTCL_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrmIndRqdSt_778	1	IIPutTxDTCL_WrmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.23 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	15
CTCEventId_Cnt_M_u8	11
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSources	41
DTCDData.DTCNumber	42777
DTCDData.DTCFailType	73
DTCDData.DTCWrmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaultType	239
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	26
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	156
LKATrqOvrDivdRC_Cnt_M_u8	202
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	42
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	54
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	66
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	78
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	41
PrevWarningIndSignal_Cnt_M_u8[0]	0
PrevWarningIndSignal_Cnt_M_u8[1]	1
PrevWarningIndSignal_Cnt_M_u8[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	1321357568
Steering_Torque_Overlay_Stat_CE_c[0]	36
Steering_Torque_Overlay_Stat_CE_c[1]	42
Steering_Torque_Overlay_Stat_CE_c[2]	48
Steering_Torque_Overlay_Stat_CE_c[3]	54
Steering_Torque_Overlay_Stat_CE_c[4]	60
Steering_Torque_Overlay_Stat_CE_c[5]	66
Steering_Torque_Overlay_Stat_CE_c[6]	72
Steering_Torque_Overlay_Stat_CE_c[7]	78
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.230000004
k_SComTrqPosPol_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	31
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	239
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	53869
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2784268032
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	3.0999999
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.00999999978
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	1.01999998
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	2.02999997

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	11	11	✓
CTCEventId_Cnt_M_u8	11	11	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	4	4	✓
DTCDData.DTCFailType	176	176	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	26	26	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrIDvdRC_Cnt_M_u8	203	203	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	41	41	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2784268032	2784268032	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTqDlrd	1	IIPutTxTrqOvrIDItTqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	✓
IIPutTxLKADrvAppldTqV	1	IIPutTxLKADrvAppldTqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDvrdRC	1	IIPutTxLKATrqOvrIDvrdRC	1	✓
IIPutTxLKATrqOvrIDItTqDlvd	1	IIPutTxLKATrqOvrIDItTqDlvd	1	✓
IIPutTxLKADrvAppldTq	1	IIPutTxLKADrvAppldTq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTqGroup	1	IIPutTxLKADrvAppldTqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.24 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	32
CTCEventId_Cnt_M_u8	26

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
CurrentDTCSThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	43
DTCDData.DTCNumber	62641
DTCDData.DTCFailType	18
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	50
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	10
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	205
LKATrqOvriDlvdRC_Cnt_M_u8	37
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	42
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	54
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	66
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	78
LastReportedDTCEventID_Cnt_M_u8	21
LastReportedGMStatus_Cnt_M_u8	43
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCTFlag_mS_M_u32p0	847034624
Steering_Torque_Overlay_Stat_CE_c[0]	36
Steering_Torque_Overlay_Stat_CE_c[1]	42
Steering_Torque_Overlay_Stat_CE_c[2]	48
Steering_Torque_Overlay_Stat_CE_c[3]	54
Steering_Torque_Overlay_Stat_CE_c[4]	60
Steering_Torque_Overlay_Stat_CE_c[5]	66
Steering_Torque_Overlay_Stat_CE_c[6]	72

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
Steering_Torque_Overlay_Stat_CE_c[7]	78		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.25		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	32		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	50		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	60171		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	400799488		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	3.20000005		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.699999988		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	6.09999999		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.62		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	32	32	✔
CTCEventId_Cnt_M_u8	27	27	✔
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	0	0	✔
DTCDData.DTCFailType	0	0	✔
DTCDData.DTCWmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrUpSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	0	0	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[31]	0	0	✔
ESCRollCount_Cnt_M_u08	11	11	✔
GMStatus_Cnt_M_u8[0]	3	3	✔
GMStatus_Cnt_M_u8[1]	6	6	✔
GMStatus_Cnt_M_u8[2]	9	9	✔
GMStatus_Cnt_M_u8[3]	12	12	✔
GMStatus_Cnt_M_u8[4]	15	15	✔
GMStatus_Cnt_M_u8[5]	18	18	✔
GMStatus_Cnt_M_u8[6]	21	21	✔
GMStatus_Cnt_M_u8[7]	24	24	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SriComOutput_Per1



Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	38	38	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	43	43	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	847034624	847034624	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrItqDStat	1	IIPutTxTrqOvrItqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtmD	1	IIPutTxHndsOffStrWhlDtmD	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrItqDStat	1	IIPutTxLKATrqOvrItqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIDStatChksm	1	IIPutTxLKATrqOvrIDStatChksm	1	✓
IIPutTxDTCI_DTCTriggered_778	1	IIPutTxDTCI_DTCTriggered_778	1	✓
IIPutTxDTCI_DTCSOURCE_778	1	IIPutTxDTCI_DTCSOURCE_778	1	✓
IIPutTxDTCI_DTCNumber_778	1	IIPutTxDTCI_DTCNumber_778	1	✓
IIPutTxDTCI_DTCFailType_778	1	IIPutTxDTCI_DTCFailType_778	1	✓
IIPutTxDTCI_CodeSupported_778	1	IIPutTxDTCI_CodeSupported_778	1	✓
IIPutTxDTCI_CurrentStatus_778	1	IIPutTxDTCI_CurrentStatus_778	1	✓
IIPutTxDTCI_TstNPsdCdCldSt_778	1	IIPutTxDTCI_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCI_TstFldCdCldStat_778	1	IIPutTxDTCI_TstFldCdCldStat_778	1	✓
IIPutTxDTCI_HistStat_778	1	IIPutTxDTCI_HistStat_778	1	✓
IIPutTxDTCI_TstNPsdPwrUpSt_778	1	IIPutTxDTCI_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCI_TstFldPwrUpSt_778	1	IIPutTxDTCI_TstFldPwrUpSt_778	1	✓
IIPutTxDTCI_WrnIndRqdSt_778	1	IIPutTxDTCI_WrnIndRqdSt_778	1	✓
IIPutTxDTCI_DTCFaultType_778	1	IIPutTxDTCI_DTCFaultType_778	1	✓
IIPutTxDTCIInfo_778	1	IIPutTxDTCIInfo_778	1	✓

Test Step 2.25 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	23
CurrentDTCSentThisIC_Cnt_M_Igc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	45
DTCDData.DTCNumber	13756
DTCDData.DTCFailType	161
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	14
DTCTriggeredFlag_Cnt_M_Igc[0]	0
DTCTriggeredFlag_Cnt_M_Igc[1]	1
DTCTriggeredFlag_Cnt_M_Igc[2]	0
DTCTriggeredFlag_Cnt_M_Igc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	14
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	22		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	44		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	97		
LKATrqOvriDlvdRC_Cnt_M_u8	117		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104		
LastReportedDTCEventID_Cnt_M_u8	18		
LastReportedGMStatus_Cnt_M_u8	45		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	575444992		
Steering_Torque_Overlay_Stat_CE_c[0]	48		
Steering_Torque_Overlay_Stat_CE_c[1]	56		
Steering_Torque_Overlay_Stat_CE_c[2]	64		
Steering_Torque_Overlay_Stat_CE_c[3]	72		
Steering_Torque_Overlay_Stat_CE_c[4]	80		
Steering_Torque_Overlay_Stat_CE_c[5]	88		
Steering_Torque_Overlay_Stat_CE_c[6]	96		
Steering_Torque_Overlay_Stat_CE_c[7]	104		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.270000011		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	33		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	14		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	26753		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3549404672		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	3.29999995		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.699999988		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-8.80000019		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-0.419999987		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	12	12	✓
CTCEventId_Cnt_M_u8	24	24	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNNumber	1	1	✓
DTCDData.DTCFailType	129	129	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	15	15	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	117	117	✓
LastReportedDTCEventID_Cnt_M_u8	18	18	✓
LastReportedGMStatus_Cnt_M_u8	45	45	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	575444992	575444992	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItItqDlrd	1	IIPutTxElPwrStItItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDItTrqDlrd	1	IIPutTxTrqOvriDItTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrmIndRqdSt_778	1	IIPutTxDTCL_WrmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.26 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	27
CTCEventId_Cnt_M_u8	10
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSource	47
DTCDData.DTCNumber	14567
DTCDData.DTCFailType	81
DTCDData.DTCWrmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	162
DTCTTriggeredFlag_Cnt_M_lgc[0]	0
DTCTTriggeredFlag_Cnt_M_lgc[1]	1
DTCTTriggeredFlag_Cnt_M_lgc[2]	0
DTCTTriggeredFlag_Cnt_M_lgc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	0
DemDTCNum_Cnt_M_u32[1]	0
DemDTCNum_Cnt_M_u32[2]	0
DemDTCNum_Cnt_M_u32[3]	0
DemDTCNum_Cnt_M_u32[4]	0
DemDTCNum_Cnt_M_u32[5]	0
DemDTCNum_Cnt_M_u32[6]	0
DemDTCNum_Cnt_M_u32[7]	0
DemDTCNum_Cnt_M_u32[8]	0
DemDTCNum_Cnt_M_u32[9]	0
DemDTCNum_Cnt_M_u32[10]	0
DemDTCNum_Cnt_M_u32[11]	0
DemDTCNum_Cnt_M_u32[12]	0
DemDTCNum_Cnt_M_u32[13]	0
DemDTCNum_Cnt_M_u32[14]	0
DemDTCNum_Cnt_M_u32[15]	0
DemDTCNum_Cnt_M_u32[16]	0
DemDTCNum_Cnt_M_u32[17]	0
DemDTCNum_Cnt_M_u32[18]	0
DemDTCNum_Cnt_M_u32[19]	0
DemDTCNum_Cnt_M_u32[20]	0
DemDTCNum_Cnt_M_u32[21]	0
DemDTCNum_Cnt_M_u32[22]	0
DemDTCNum_Cnt_M_u32[23]	0
DemDTCNum_Cnt_M_u32[24]	0
DemDTCNum_Cnt_M_u32[25]	0
DemDTCNum_Cnt_M_u32[26]	0
DemDTCNum_Cnt_M_u32[27]	0
DemDTCNum_Cnt_M_u32[28]	0
DemDTCNum_Cnt_M_u32[29]	0
DemDTCNum_Cnt_M_u32[30]	0
DemDTCNum_Cnt_M_u32[31]	0
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	11
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	11		
GMStatus_Cnt_M_u8[11]	12		
GMStatus_Cnt_M_u8[12]	13		
GMStatus_Cnt_M_u8[13]	14		
GMStatus_Cnt_M_u8[14]	15		
GMStatus_Cnt_M_u8[15]	16		
GMStatus_Cnt_M_u8[16]	17		
GMStatus_Cnt_M_u8[17]	18		
GMStatus_Cnt_M_u8[18]	19		
GMStatus_Cnt_M_u8[19]	20		
GMStatus_Cnt_M_u8[20]	21		
GMStatus_Cnt_M_u8[21]	22		
GMStatus_Cnt_M_u8[22]	23		
GMStatus_Cnt_M_u8[23]	24		
GMStatus_Cnt_M_u8[24]	25		
GMStatus_Cnt_M_u8[25]	26		
GMStatus_Cnt_M_u8[26]	27		
GMStatus_Cnt_M_u8[27]	28		
GMStatus_Cnt_M_u8[28]	29		
GMStatus_Cnt_M_u8[29]	30		
GMStatus_Cnt_M_u8[30]	31		
GMStatus_Cnt_M_u8[31]	32		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	96		
LKATrqOvriDlvdRC_Cnt_M_u8	206		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104		
LastReportedDTCEventID_Cnt_M_u8	31		
LastReportedGMStatus_Cnt_M_u8	47		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2178666496		
Steering_Torque_Overlay_Stat_CE_c[0]	48		
Steering_Torque_Overlay_Stat_CE_c[1]	56		
Steering_Torque_Overlay_Stat_CE_c[2]	64		
Steering_Torque_Overlay_Stat_CE_c[3]	72		
Steering_Torque_Overlay_Stat_CE_c[4]	80		
Steering_Torque_Overlay_Stat_CE_c[5]	88		
Steering_Torque_Overlay_Stat_CE_c[6]	96		
Steering_Torque_Overlay_Stat_CE_c[7]	104		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.2899999992		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	34		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	6841		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	448599552		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	3.4000001		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.200000003		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	2.4000001		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.10000002		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	10	10	✓
CTCEventId_Cnt_M_u8	10	10	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSrc	49	49	✓
DTCDData.DTCNbr	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	12	12	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	206	206	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	47	47	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	448599552	448599552	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItITqDlrd	1	IIPutTxElPwrStItITqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFidCdClrdStat_778	1	IIPutTxDTCl_TstFidCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFidPwrUpSt_778	1	IIPutTxDTCl_TstFidPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.27 (Repeat Count = 1)

Name	Input Value
CTCEventIDSV_Cnt_M_u8	13
CTCEventID_Cnt_M_u8	1
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSource	1
DTCDData.DTCNumber	3064
DTCDData.DTCFailType	38
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCtstFidPwrUpSt	0
DTCDData.DTCtstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCtstFidCdClrdStat	0
DTCDData.DTCtstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	193
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	4294967295
DemDTCNum_Cnt_M_u32[1]	4294967295
DemDTCNum_Cnt_M_u32[2]	4294967295
DemDTCNum_Cnt_M_u32[3]	4294967295
DemDTCNum_Cnt_M_u32[4]	4294967295
DemDTCNum_Cnt_M_u32[5]	4294967295
DemDTCNum_Cnt_M_u32[6]	4294967295
DemDTCNum_Cnt_M_u32[7]	4294967295
DemDTCNum_Cnt_M_u32[8]	4294967295
DemDTCNum_Cnt_M_u32[9]	4294967295
DemDTCNum_Cnt_M_u32[10]	4294967295
DemDTCNum_Cnt_M_u32[11]	4294967295
DemDTCNum_Cnt_M_u32[12]	4294967295
DemDTCNum_Cnt_M_u32[13]	4294967295
DemDTCNum_Cnt_M_u32[14]	4294967295
DemDTCNum_Cnt_M_u32[15]	4294967295
DemDTCNum_Cnt_M_u32[16]	4294967295
DemDTCNum_Cnt_M_u32[17]	4294967295
DemDTCNum_Cnt_M_u32[18]	4294967295
DemDTCNum_Cnt_M_u32[19]	4294967295
DemDTCNum_Cnt_M_u32[20]	4294967295
DemDTCNum_Cnt_M_u32[21]	4294967295
DemDTCNum_Cnt_M_u32[22]	4294967295
DemDTCNum_Cnt_M_u32[23]	4294967295
DemDTCNum_Cnt_M_u32[24]	4294967295
DemDTCNum_Cnt_M_u32[25]	4294967295
DemDTCNum_Cnt_M_u32[26]	4294967295
DemDTCNum_Cnt_M_u32[27]	4294967295
DemDTCNum_Cnt_M_u32[28]	4294967295
DemDTCNum_Cnt_M_u32[29]	4294967295
DemDTCNum_Cnt_M_u32[30]	4294967295
DemDTCNum_Cnt_M_u32[31]	4294967295
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	5
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	40		
GMStatus_Cnt_M_u8[10]	44		
GMStatus_Cnt_M_u8[11]	48		
GMStatus_Cnt_M_u8[12]	52		
GMStatus_Cnt_M_u8[13]	56		
GMStatus_Cnt_M_u8[14]	60		
GMStatus_Cnt_M_u8[15]	64		
GMStatus_Cnt_M_u8[16]	68		
GMStatus_Cnt_M_u8[17]	72		
GMStatus_Cnt_M_u8[18]	76		
GMStatus_Cnt_M_u8[19]	80		
GMStatus_Cnt_M_u8[20]	84		
GMStatus_Cnt_M_u8[21]	88		
GMStatus_Cnt_M_u8[22]	92		
GMStatus_Cnt_M_u8[23]	96		
GMStatus_Cnt_M_u8[24]	100		
GMStatus_Cnt_M_u8[25]	104		
GMStatus_Cnt_M_u8[26]	108		
GMStatus_Cnt_M_u8[27]	112		
GMStatus_Cnt_M_u8[28]	116		
GMStatus_Cnt_M_u8[29]	120		
GMStatus_Cnt_M_u8[30]	124		
GMStatus_Cnt_M_u8[31]	128		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	163		
LKATrqOvrlDlvdRC_Cnt_M_u8	234		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130		
LastReportedDTCEventID_Cnt_M_u8	29		
LastReportedGMStatus_Cnt_M_u8	49		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	827020032		
Steering_Torque_Overlay_Stat_CE_c[0]	60		
Steering_Torque_Overlay_Stat_CE_c[1]	70		
Steering_Torque_Overlay_Stat_CE_c[2]	80		
Steering_Torque_Overlay_Stat_CE_c[3]	90		
Steering_Torque_Overlay_Stat_CE_c[4]	100		
Steering_Torque_Overlay_Stat_CE_c[5]	110		
Steering_Torque_Overlay_Stat_CE_c[6]	120		
Steering_Torque_Overlay_Stat_CE_c[7]	130		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.310000002		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	35		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	193		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	31506		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1799323904		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	3.5		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.600000024		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-0.100000001		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-2.57200003		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTTriggered	1	1	✓
DTCDData.DTCSSource	49	49	✓
DTCDData.DTCNumber	65535	65535	✓
DTCDData.DTCFailType	255	255	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaultype	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	6	6	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvrDlvdRC_Cnt_M_u8	235	235	✓
LastReportedDTCEventID_Cnt_M_u8	29	29	✓
LastReportedGMStatus_Cnt_M_u8	49	49	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1799323904	1799323904	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdCldSt_778	1	IIPutTxDTCL_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.28 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	17
CTCEventId_Cnt_M_u8	11

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
CurrentDTCSThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSrc	5
DTCDData.DTCNbr	59730
DTCDData.DTCFailType	82
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	175
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	7
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	114
LKATrqOvriDlvdRC_Cnt_M_u8	147
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	25
LastReportedGMStatus_Cnt_M_u8	51
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCTFlag_mS_M_u32p0	952683008
Steering_Torque_Overlay_Stat_CE_c[0]	72
Steering_Torque_Overlay_Stat_CE_c[1]	84
Steering_Torque_Overlay_Stat_CE_c[2]	96
Steering_Torque_Overlay_Stat_CE_c[3]	108
Steering_Torque_Overlay_Stat_CE_c[4]	120
Steering_Torque_Overlay_Stat_CE_c[5]	132
Steering_Torque_Overlay_Stat_CE_c[6]	144

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
Steering_Torque_Overlay_Stat_CE_c[7]	156		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.330000013		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	36		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	175		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	40531		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3710140416		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	3.5999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.800000012		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-3.73000002		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.29999995		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	17	17	✓
CTCEventId_Cnt_M_u8	12	12	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	234	234	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrUpSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	8	8	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvriDlvdRC_Cnt_M_u8	147	147	✓
LastReportedDTCEventID_Cnt_M_u8	25	25	✓
LastReportedGMStatus_Cnt_M_u8	51	51	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	952683008	952683008	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItItqDlrd	1	IIPutTxElPwrStItItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFidCdCldStat_778	1	IIPutTxDTCl_TstFidCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFidPwrUpSt_778	1	IIPutTxDTCl_TstFidPwrUpSt_778	1	✓
IIPutTxDTCl_WrmlndRqdSt_778	1	IIPutTxDTCl_WrmlndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.29 (Repeat Count = 1)

Name	Input Value
CTCEventIdSV_Cnt_M_u8	19
CTCEventId_Cnt_M_u8	13
CurrentDTCSentThisIC_Cnt_M_lgc	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTriggered	0
DTCDData.DTCSrc	9
DTCDData.DTCNumber	32160
DTCDData.DTCFailType	122
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdpwrUpSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdpCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	58
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	6
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	89
LKATrqOvrldvldRC_Cnt_M_u8	77
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	7
LastReportedGMStatus_Cnt_M_u8	53
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	283927808
Steering_Torque_Overlay_Stat_CE_c[0]	84
Steering_Torque_Overlay_Stat_CE_c[1]	98
Steering_Torque_Overlay_Stat_CE_c[2]	112
Steering_Torque_Overlay_Stat_CE_c[3]	126
Steering_Torque_Overlay_Stat_CE_c[4]	140
Steering_Torque_Overlay_Stat_CE_c[5]	154
Steering_Torque_Overlay_Stat_CE_c[6]	168
Steering_Torque_Overlay_Stat_CE_c[7]	182

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.349999994		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	37		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	58		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	38829		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	221381376		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	3.70000005		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.699999988		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	3.06999993		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.99100006		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	19	19	✓
CTCEventId_Cnt_M_u8	14	14	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	220	220	✓
DTCDData.DTCWrnIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	7	7	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SriComOutput_Per1



Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrldDlvdRC_Cnt_M_u8	78	78	✓
LastReportedDTCEventID_Cnt_M_u8	7	7	✓
LastReportedGMStatus_Cnt_M_u8	53	53	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	283927808	283927808	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrItqDStat	1	IIPutTxTrqOvrItqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlTmd	1	IIPutTxHndsOffStrWhlDlTmd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvrItqDStat	1	IIPutTxLKATrqOvrItqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIDStatChksm	1	IIPutTxLKATrqOvrIDStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.30 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	24
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSource	13
DTCDData.DTCNumber	43937
DTCDData.DTCFailType	236
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	7
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	22		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	44		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	115		
LKATrqOvriDlvdRC_Cnt_M_u8	240		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventID_Cnt_M_u8	21		
LastReportedGMStatus_Cnt_M_u8	55		
PrevWarningIndSignal_Cnt_M_u8[0]	1		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	749573120		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.370000005		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	38		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	62026		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3688151552		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	3.79999995		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.899999976		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	3.5999999		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	0.75		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	14	14	✓
CTCEventId_Cnt_M_u8	14	14	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	244	244	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCStFldPwrUpSt	0	0	✓
DTCDData.DTCStNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCStFldCdCldStat	1	1	✓
DTCDData.DTCStNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	241	241	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	55	55	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3688151552	3688151552	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItTqDlrd	1	IIPutTxElPwrStItTqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrStItTqDlvd	1	IIPutTxLKAEIPwrStItTqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WmIndRqdSt_778	1	IIPutTxDTCl_WmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.31 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	23
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSorce	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCDData.DTCNumber	892
DTCDData.DTCFailType	195
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaultype	215
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	13
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	99
LKATrqOvrldDivdRC_Cnt_M_u8	138
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52
LastReportedDTCEventID_Cnt_M_u8	9
LastReportedGMStatus_Cnt_M_u8	57
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	4056460800
Steering_Torque_Overlay_Stat_CE_c[0]	24
Steering_Torque_Overlay_Stat_CE_c[1]	28
Steering_Torque_Overlay_Stat_CE_c[2]	32
Steering_Torque_Overlay_Stat_CE_c[3]	36
Steering_Torque_Overlay_Stat_CE_c[4]	40
Steering_Torque_Overlay_Stat_CE_c[5]	44
Steering_Torque_Overlay_Stat_CE_c[6]	48
Steering_Torque_Overlay_Stat_CE_c[7]	52
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.389999986

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	39		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	215		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	46606		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3248030720		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	3.9000001		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.769999981		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-4.46000004		
target_Rte_Read_Ap_SrlComOutput_LKAState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	23	23	✔
CTCEventId_Cnt_M_u8	15	15	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	3	3	✔
DTCDData.DTCFailType	232	232	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdClrdStat	1	1	✔
DTCDData.DTCTstNPsdCdClrdSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	14	14	✔
GMStatus_Cnt_M_u8[0]	4	4	✔
GMStatus_Cnt_M_u8[1]	8	8	✔
GMStatus_Cnt_M_u8[2]	12	12	✔
GMStatus_Cnt_M_u8[3]	16	16	✔
GMStatus_Cnt_M_u8[4]	20	20	✔
GMStatus_Cnt_M_u8[5]	24	24	✔
GMStatus_Cnt_M_u8[6]	28	28	✔
GMStatus_Cnt_M_u8[7]	32	32	✔
GMStatus_Cnt_M_u8[8]	36	36	✔
GMStatus_Cnt_M_u8[9]	40	40	✔
GMStatus_Cnt M_u8[10]	44	44	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDlvdRC_Cnt_M_u8	138	138	✓
LastReportedDTCEventID_Cnt_M_u8	9	9	✓
LastReportedGMStatus_Cnt_M_u8	57	57	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4056460800	4056460800	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItTqDlrd	1	IIPutTxElPwrStItTqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.32 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	32
CTCEventId_Cnt_M_u8	26
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	49
DTCDData.DTCNumber	62641
DTCDData.DTCFailType	18

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	50
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	12
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	205
LKATrqOvriDlvdRC_Cnt_M_u8	37
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	42
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	54
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	66
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	78
LastReportedDTCEventID_Cnt_M_u8	21
LastReportedGMStatus_Cnt_M_u8	59
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	847034624
Steering_Torque_Overlay_Stat_CE_c[0]	36
Steering_Torque_Overlay_Stat_CE_c[1]	42
Steering_Torque_Overlay_Stat_CE_c[2]	48
Steering_Torque_Overlay_Stat_CE_c[3]	54
Steering_Torque_Overlay_Stat_CE_c[4]	60
Steering_Torque_Overlay_Stat_CE_c[5]	66
Steering_Torque_Overlay_Stat_CE_c[6]	72
Steering_Torque_Overlay_Stat_CE_c[7]	78
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.409999996
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	40

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	60171		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	400799488		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	4		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.400000006		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-4.13000011		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.49000001		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	32	32	✔
CTCEventId_Cnt_M_u8	27	27	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	1	1	✔
DTCDData.DTCFailType	174	174	✔
DTCDData.DTCWmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✔
ESCRollCount_Cnt_M_u08	13	13	✔
GMStatus_Cnt_M_u8[0]	3	3	✔
GMStatus_Cnt_M_u8[1]	6	6	✔
GMStatus_Cnt_M_u8[2]	9	9	✔
GMStatus_Cnt_M_u8[3]	12	12	✔
GMStatus_Cnt_M_u8[4]	15	15	✔
GMStatus_Cnt_M_u8[5]	18	18	✔
GMStatus_Cnt_M_u8[6]	21	21	✔
GMStatus_Cnt_M_u8[7]	24	24	✔
GMStatus_Cnt_M_u8[8]	27	27	✔
GMStatus_Cnt_M_u8[9]	30	30	✔
GMStatus_Cnt_M_u8[10]	33	33	✔
GMStatus_Cnt_M_u8[11]	36	36	✔
GMStatus_Cnt_M_u8[12]	39	39	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvriDlvdRC_Cnt_M_u8	38	38	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	59	59	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	847034624	847034624	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrItqDStat	1	IIPutTxTrqOvrItqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtmD	1	IIPutTxHndsOffStrWhlDtmD	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrItqDStat	1	IIPutTxLKATrqOvrItqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.33 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	23
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	12
DTCDData.DTCNumber	13756
DTCDData.DTCFailType	161
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	14
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	22		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	44		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	16		
LKATrqOvriDlvdRC_Cnt_M_u8	117		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104		
LastReportedDTCEventID_Cnt_M_u8	18		
LastReportedGMStatus_Cnt_M_u8	61		
PrevWarningIndSignal_Cnt_M_u8[0]	0		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	575444992		
Steering_Torque_Overlay_Stat_CE_c[0]	48		
Steering_Torque_Overlay_Stat_CE_c[1]	56		
Steering_Torque_Overlay_Stat_CE_c[2]	64		
Steering_Torque_Overlay_Stat_CE_c[3]	72		
Steering_Torque_Overlay_Stat_CE_c[4]	80		
Steering_Torque_Overlay_Stat_CE_c[5]	88		
Steering_Torque_Overlay_Stat_CE_c[6]	96		
Steering_Torque_Overlay_Stat_CE_c[7]	104		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.430000007		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	41		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	14		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	26753		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	3549404672		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	4.09999999		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.1199999997		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	7.420000008		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.200000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	12	12	✓
CTCEventId_Cnt_M_u8	24	24	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	129	129	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	3	3	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	117	117	✓
LastReportedDTCEventID_Cnt_M_u8	18	18	✓
LastReportedGMStatus_Cnt_M_u8	61	61	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	575444992	575444992	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItTqDlrd	1	IIPutTxElPwrStItTqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrc_778	1	IIPutTxDTCl_DTCSrc_778	1	✓
IIPutTxDTCl_DTCCurrent_778	1	IIPutTxDTCl_DTCCurrent_778	1	✓
IIPutTxDTCl_DTCCurrentStatus_778	1	IIPutTxDTCl_DTCCurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFidCdClrdStat_778	1	IIPutTxDTCl_TstFidCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFidPwrUpSt_778	1	IIPutTxDTCl_TstFidPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCCurrentStatus_778	1	IIPutTxDTCl_DTCCurrentStatus_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.34 (Repeat Count = 1)

Name	Input Value
CTCEventIdSV_Cnt_M_u8	4
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSrc	2
DTCDData.DTCCurrent	0
DTCDData.DTCCurrentStatus	175
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCurrentStatus	100
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	4
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[11]	12		
GMStatus_Cnt_M_u8[12]	13		
GMStatus_Cnt_M_u8[13]	14		
GMStatus_Cnt_M_u8[14]	15		
GMStatus_Cnt_M_u8[15]	16		
GMStatus_Cnt_M_u8[16]	17		
GMStatus_Cnt_M_u8[17]	18		
GMStatus_Cnt_M_u8[18]	19		
GMStatus_Cnt_M_u8[19]	20		
GMStatus_Cnt_M_u8[20]	21		
GMStatus_Cnt_M_u8[21]	22		
GMStatus_Cnt_M_u8[22]	23		
GMStatus_Cnt_M_u8[23]	24		
GMStatus_Cnt_M_u8[24]	25		
GMStatus_Cnt_M_u8[25]	26		
GMStatus_Cnt_M_u8[26]	27		
GMStatus_Cnt_M_u8[27]	28		
GMStatus_Cnt_M_u8[28]	29		
GMStatus_Cnt_M_u8[29]	30		
GMStatus_Cnt_M_u8[30]	31		
GMStatus_Cnt_M_u8[31]	32		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	54		
LKATrqOvrldDlvdRC_Cnt_M_u8	78		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130		
LastReportedDTCEventID_Cnt_M_u8	31		
LastReportedGMStatus_Cnt_M_u8	63		
PrevWarningIndSignal_Cnt_M_u8[0]	0		
PrevWarningIndSignal_Cnt_M_u8[1]	0		
PrevWarningIndSignal_Cnt_M_u8[2]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3977837312		
Steering_Torque_Overlay_Stat_CE_c[0]	60		
Steering_Torque_Overlay_Stat_CE_c[1]	70		
Steering_Torque_Overlay_Stat_CE_c[2]	80		
Steering_Torque_Overlay_Stat_CE_c[3]	90		
Steering_Torque_Overlay_Stat_CE_c[4]	100		
Steering_Torque_Overlay_Stat_CE_c[5]	110		
Steering_Torque_Overlay_Stat_CE_c[6]	120		
Steering_Torque_Overlay_Stat_CE_c[7]	130		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.449999988		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	42		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	19163		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2498226432		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	4.19999981		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.419999987		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	7.30000019		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	2.09999999		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	4	4	✓
CTCEventId_Cnt_M_u8	15	15	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCDData.DTCTTriggered	0	0	✓
DTCDData.DTCSrcSource	49	49	✓
DTCDData.DTCNNumber	3	3	✓
DTCDData.DTCFailType	72	72	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPSdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPSdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	5	5	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	78	78	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	63	63	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3977837312	3977837312	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcldIO	1	IIPutTxStrngAsstRdcldIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.35 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	15
CTCEventId_Cnt_M_u8	34
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSorce	4
DTCDData.DTCNumber	65535
DTCDData.DTCFailType	199
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaultype	148
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	1
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	44		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	166		
LKATrqOvrldDlvdRC_Cnt_M_u8	210		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156		
LastReportedDTCEventID_Cnt_M_u8	13		
LastReportedGMStatus_Cnt_M_u8	65		
PrevWarningIndSignal_Cnt_M_u8[0]	1		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2919223808		
Steering_Torque_Overlay_Stat_CE_c[0]	72		
Steering_Torque_Overlay_Stat_CE_c[1]	84		
Steering_Torque_Overlay_Stat_CE_c[2]	96		
Steering_Torque_Overlay_Stat_CE_c[3]	108		
Steering_Torque_Overlay_Stat_CE_c[4]	120		
Steering_Torque_Overlay_Stat_CE_c[5]	132		
Steering_Torque_Overlay_Stat_CE_c[6]	144		
Steering_Torque_Overlay_Stat_CE_c[7]	156		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.469999999		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	43		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	148		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	33689		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3821733888		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	4.300000019		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.300000012		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	2.29999995		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-0.800000012		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	15	15	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCDData.DTCTTriggered	0	0	✓
DTCDData.DTCSrcSource	4	4	✓
DTCDData.DTCNumber	65535	65535	✓
DTCDData.DTCFailType	199	199	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdpwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdpCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	148	148	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	2	2	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	19	19	✓
GMStatus_Cnt_M_u8[2]	19	19	✓
GMStatus_Cnt_M_u8[3]	19	19	✓
GMStatus_Cnt_M_u8[4]	19	19	✓
GMStatus_Cnt_M_u8[5]	19	19	✓
GMStatus_Cnt_M_u8[6]	19	19	✓
GMStatus_Cnt_M_u8[7]	19	19	✓
GMStatus_Cnt_M_u8[8]	19	19	✓
GMStatus_Cnt_M_u8[9]	19	19	✓
GMStatus_Cnt_M_u8[10]	19	19	✓
GMStatus_Cnt_M_u8[11]	19	19	✓
GMStatus_Cnt_M_u8[12]	19	19	✓
GMStatus_Cnt_M_u8[13]	19	19	✓
GMStatus_Cnt_M_u8[14]	19	19	✓
GMStatus_Cnt_M_u8[15]	19	19	✓
GMStatus_Cnt_M_u8[16]	19	19	✓
GMStatus_Cnt_M_u8[17]	19	19	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	19	19	✓
GMStatus_Cnt_M_u8[20]	19	19	✓
GMStatus_Cnt_M_u8[21]	19	19	✓
GMStatus_Cnt_M_u8[22]	19	19	✓
GMStatus_Cnt_M_u8[23]	19	19	✓
GMStatus_Cnt_M_u8[24]	19	19	✓
GMStatus_Cnt_M_u8[25]	19	19	✓
GMStatus_Cnt_M_u8[26]	19	19	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[27]	19	19	✓
GMStatus_Cnt_M_u8[28]	19	19	✓
GMStatus_Cnt_M_u8[29]	19	19	✓
GMStatus_Cnt_M_u8[30]	19	19	✓
GMStatus_Cnt_M_u8[31]	19	19	✓
LKATrqOvriDivdRC_Cnt_M_u8	210	210	✓
LastReportedDTCEventID_Cnt_M_u8	13	13	✓
LastReportedGMStatus_Cnt_M_u8	65	65	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2919223808	2919223808	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.36 (Repeat Count = 1)



Name	Input Value
CTCEventIdSV_Cnt_M_u8	27
CTCEventId_Cnt_M_u8	23
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	6
DTCDData.DTCNumber	38439
DTCDData.DTCFailType	103
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	152
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	3
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	158
LKATrqOvrlDlvdRC_Cnt_M_u8	206
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	9
LastReportedGMStatus_Cnt_M_u8	67
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	929516800		
Steering_Torque_Overlay_Stat_CE_c[0]	84		
Steering_Torque_Overlay_Stat_CE_c[1]	98		
Steering_Torque_Overlay_Stat_CE_c[2]	112		
Steering_Torque_Overlay_Stat_CE_c[3]	126		
Steering_Torque_Overlay_Stat_CE_c[4]	140		
Steering_Torque_Overlay_Stat_CE_c[5]	154		
Steering_Torque_Overlay_Stat_CE_c[6]	168		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.49000001		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	44		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	152		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	27131		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3999116032		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	4.4000001		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.800000012		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.77999997		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	27	27	✔
CTCEventId_Cnt_M_u8	24	24	✔
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	0	0	✔
DTCDData.DTCFailType	0	0	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	0	0	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	4	4	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	207	207	✓
LastReportedDTCEventID_Cnt_M_u8	9	9	✓
LastReportedGMStatus_Cnt_M_u8	67	67	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	929516800	929516800	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrItqDStat	1	IIPutTxTrqOvrItqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtmD	1	IIPutTxHndsOffStrWhlDtmD	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrItqDStat	1	IIPutTxLKATrqOvrItqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.37 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	18
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	8
DTCDData.DTCTNumber	18845
DTCDData.DTCTFailType	0
DTCDData.DTCTWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCTHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCTCurrentStatus	0
DTCDData.DTCTCodeSupported	1
DTCDData.DTCTFaulttype	67
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	8
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	44		
GMStatus_Cnt_M_u8[11]	48		
GMStatus_Cnt_M_u8[12]	52		
GMStatus_Cnt_M_u8[13]	56		
GMStatus_Cnt_M_u8[14]	60		
GMStatus_Cnt_M_u8[15]	64		
GMStatus_Cnt_M_u8[16]	68		
GMStatus_Cnt_M_u8[17]	72		
GMStatus_Cnt_M_u8[18]	76		
GMStatus_Cnt_M_u8[19]	80		
GMStatus_Cnt_M_u8[20]	84		
GMStatus_Cnt_M_u8[21]	88		
GMStatus_Cnt_M_u8[22]	92		
GMStatus_Cnt_M_u8[23]	96		
GMStatus_Cnt_M_u8[24]	100		
GMStatus_Cnt_M_u8[25]	104		
GMStatus_Cnt_M_u8[26]	108		
GMStatus_Cnt_M_u8[27]	112		
GMStatus_Cnt_M_u8[28]	116		
GMStatus_Cnt_M_u8[29]	120		
GMStatus_Cnt_M_u8[30]	124		
GMStatus_Cnt_M_u8[31]	128		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	17		
LKATrqOvrldlvdRC_Cnt_M_u8	55		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventID_Cnt_M_u8	31		
LastReportedGMStatus_Cnt_M_u8	69		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2799492096		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.50999999		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	45		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	67		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	29952		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3639722496		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	4.5		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.129999995		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	9.13000011		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-0.939999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	12	12	✔
CTCEventId_Cnt_M_u8	19	19	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNNumber	2	*none*	✓
DTCDData.DTCFailType	68	*none*	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	9	9	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDlvdRC_Cnt_M_u8	56	56	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	69	69	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2799492096	2799492096	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDltSt	1	IIPutTxHndsOffStrWhlDltSt	1	✓
IIPutTxHndsOffStrWhlDltMtd	1	IIPutTxHndsOffStrWhlDltMtd	1	✓
IIPutTxHndsOffStrWhlDltStV	1	IIPutTxHndsOffStrWhlDltStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDltStGroup	1	IIPutTxHndsOffStrWhlDltStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSources_778	1	IIPutTxDTCl_DTCSources_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTCTInfo_778	1	IIPutTxDTCTInfo_778	1	✓

Test Step 2.38 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	14
CTCEventId_Cnt_M_u8	8
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCTData.DTCTriggered	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCSource	10
DTCDData.DTCNumber	49158
DTCDData.DTCFailType	255
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	205
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	17
LKATrqOvrIdlvdRC_Cnt_M_u8	20
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26
LastReportedDTCEventID_Cnt_M_u8	7
LastReportedGMStatus_Cnt_M_u8	71
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3849858816
Steering_Torque_Overlay_Stat_CE_c[0]	12
Steering_Torque_Overlay_Stat_CE_c[1]	14
Steering_Torque_Overlay_Stat_CE_c[2]	16
Steering_Torque_Overlay_Stat_CE_c[3]	18
Steering_Torque_Overlay_Stat_CE_c[4]	20
Steering_Torque_Overlay_Stat_CE_c[5]	22
Steering_Torque_Overlay_Stat_CE_c[6]	24
Steering_Torque_Overlay_Stat_CE_c[7]	26
k_LKAMfgEnable_Cnt_lgc	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_MaxHOWEstimate_Uls_f32	0.529999971		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	46		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	205		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	51563		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	709983488		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	4.59999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.129999995		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-5.19999981		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.5		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	14	14	✓
CTCEventId_Cnt_M_u8	9	9	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	104	104	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	20	20	✓
LastReportedDTCEventID_Cnt_M_u8	7	7	✓
LastReportedGMStatus_Cnt_M_u8	71	71	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3849858816	3849858816	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItItqDlrd	1	IIPutTxElPwrStItItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WmIndRqdSt_778	1	IIPutTxDTCl_WmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.39 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	26
CTCEventId_Cnt_M_u8	20
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	12

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCNumber	55958
DTCDData.DTCFailType	169
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	125
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	10
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	194
LKATrqOvrldvRC_Cnt_M_u8	163
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52
LastReportedDTCEventID_Cnt_M_u8	5
LastReportedGMStatus_Cnt_M_u8	73
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	1924281856
Steering_Torque_Overlay_Stat_CE_c[0]	24
Steering_Torque_Overlay_Stat_CE_c[1]	28
Steering_Torque_Overlay_Stat_CE_c[2]	32
Steering_Torque_Overlay_Stat_CE_c[3]	36
Steering_Torque_Overlay_Stat_CE_c[4]	40
Steering_Torque_Overlay_Stat_CE_c[5]	44
Steering_Torque_Overlay_Stat_CE_c[6]	48
Steering_Torque_Overlay_Stat_CE_c[7]	52
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.550000012

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	47		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	125		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	23479		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1927171072		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	4.69999981		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.600000024		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	4.59000015		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	2.44000006		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	26	26	✔
CTCEventId_Cnt_M_u8	21	21	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	35	35	✔
DTCDData.DTCFailType	40	40	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	1	1	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	11	11	✔
GMStatus_Cnt_M_u8[0]	1	1	✔
GMStatus_Cnt_M_u8[1]	2	2	✔
GMStatus_Cnt_M_u8[2]	3	3	✔
GMStatus_Cnt_M_u8[3]	4	4	✔
GMStatus_Cnt_M_u8[4]	5	5	✔
GMStatus_Cnt_M_u8[5]	6	6	✔
GMStatus_Cnt_M_u8[6]	7	7	✔
GMStatus_Cnt_M_u8[7]	8	8	✔
GMStatus_Cnt_M_u8[8]	9	9	✔
GMStatus_Cnt_M_u8[9]	10	10	✔
GMStatus_Cnt_M_u8[10]	11	11	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrDlvdRC_Cnt_M_u8	164	164	✓
LastReportedDTCEventID_Cnt_M_u8	5	5	✓
LastReportedGMStatus_Cnt_M_u8	73	73	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1924281856	1924281856	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrItqDStat	1	IIPutTxTrqOvrItqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtmD	1	IIPutTxHndsOffStrWhlDtmD	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrItqDStat	1	IIPutTxLKATrqOvrItqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.40 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	15
CTCEventId_Cnt_M_u8	26
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSource	14
DTCDData.DTCNumber	16771
DTCDData.DTCFailType	82
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	185
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	14
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	22		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	44		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	217		
LKATrqOvriDlvdRC_Cnt_M_u8	49		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	42		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	54		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	66		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	78		
LastReportedDTCEventID_Cnt_M_u8	26		
LastReportedGMStatus_Cnt_M_u8	75		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	534782208		
Steering_Torque_Overlay_Stat_CE_c[0]	36		
Steering_Torque_Overlay_Stat_CE_c[1]	42		
Steering_Torque_Overlay_Stat_CE_c[2]	48		
Steering_Torque_Overlay_Stat_CE_c[3]	54		
Steering_Torque_Overlay_Stat_CE_c[4]	60		
Steering_Torque_Overlay_Stat_CE_c[5]	66		
Steering_Torque_Overlay_Stat_CE_c[6]	72		
Steering_Torque_Overlay_Stat_CE_c[7]	78		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.569999993		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	48		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	185		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	9777		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2469650176		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	4.80000019		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.800000012		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	10		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.49000001		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	26	26	✓
CTCEventId_Cnt_M_u8	26	26	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	10	10	✓
DTCDData.DTCFailType	140	140	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	15	15	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	50	50	✓
LastReportedDTCEventID_Cnt_M_u8	26	26	✓
LastReportedGMStatus_Cnt_M_u8	75	75	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2469650176	2469650176	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItItqDlrd	1	IIPutTxElPwrStItItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDltSt	1	IIPutTxHndsOffStrWhlDltSt	1	✓
IIPutTxHndsOffStrWhlDltMd	1	IIPutTxHndsOffStrWhlDltMd	1	✓
IIPutTxHndsOffStrWhlDltStV	1	IIPutTxHndsOffStrWhlDltStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrStItItqDlvd	1	IIPutTxLKAEIPwrStItItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDltStGroup	1	IIPutTxHndsOffStrWhlDltStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdCldSt_778	1	IIPutTxDTCL_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.41 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	25
CTCEventId_Cnt_M_u8	16
CurrentDTCSentThisIC_Cnt_M_lgc	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTriggered	0
DTCDData.DTCSrcSource	16
DTCDData.DTCNumber	22759
DTCDData.DTCFailType	17
DTCDData.DTCWrmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	145
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	11
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	14
LKATrqOvrldvRC_Cnt_M_u8	205
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104
LastReportedDTCEventID_Cnt_M_u8	9
LastReportedGMStatus_Cnt_M_u8	77
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	2311217152
Steering_Torque_Overlay_Stat_CE_c[0]	48
Steering_Torque_Overlay_Stat_CE_c[1]	56
Steering_Torque_Overlay_Stat_CE_c[2]	64
Steering_Torque_Overlay_Stat_CE_c[3]	72
Steering_Torque_Overlay_Stat_CE_c[4]	80
Steering_Torque_Overlay_Stat_CE_c[5]	88
Steering_Torque_Overlay_Stat_CE_c[6]	96
Steering_Torque_Overlay_Stat_CE_c[7]	104

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.589999974		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	49		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	145		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	45741		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	876553728		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	4.9000001		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.899999976		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-4.86999989		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.55799997		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	25	25	✓
CTCEventId_Cnt_M_u8	17	17	✓
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSOURCE	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldrStat	0	0	✓
DTCDData.DTCTstNPsdCdCldrSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	0	0	✓
ESCROLLCount_Cnt_M_u08	12	12	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SriComOutput_Per1



Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrrDlvdRC_Cnt_M_u8	206	206	✓
LastReportedDTCEventID_Cnt_M_u8	9	9	✓
LastReportedGMStatus_Cnt_M_u8	77	77	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2311217152	2311217152	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrItqDStat	1	IIPutTxTrqOvrItqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtmD	1	IIPutTxHndsOffStrWhlDtmD	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrItqDStat	1	IIPutTxLKATrqOvrItqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCI_DTCTriggered_778	1	IIPutTxDTCI_DTCTriggered_778	1	✓
IIPutTxDTCI_DTCSources_778	1	IIPutTxDTCI_DTCSources_778	1	✓
IIPutTxDTCI_DTCNumber_778	1	IIPutTxDTCI_DTCNumber_778	1	✓
IIPutTxDTCI_DTCFailType_778	1	IIPutTxDTCI_DTCFailType_778	1	✓
IIPutTxDTCI_CodeSupported_778	1	IIPutTxDTCI_CodeSupported_778	1	✓
IIPutTxDTCI_CurrentStatus_778	1	IIPutTxDTCI_CurrentStatus_778	1	✓
IIPutTxDTCI_TstNPsdCdCldSt_778	1	IIPutTxDTCI_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCI_TstFldCdCldStat_778	1	IIPutTxDTCI_TstFldCdCldStat_778	1	✓
IIPutTxDTCI_HistStat_778	1	IIPutTxDTCI_HistStat_778	1	✓
IIPutTxDTCI_TstNPsdPwrUpSt_778	1	IIPutTxDTCI_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCI_TstFldPwrUpSt_778	1	IIPutTxDTCI_TstFldPwrUpSt_778	1	✓
IIPutTxDTCI_WrnIndRqdSt_778	1	IIPutTxDTCI_WrnIndRqdSt_778	1	✓
IIPutTxDTCI_DTCFaultType_778	1	IIPutTxDTCI_DTCFaultType_778	1	✓
IIPutTxDTCIInfo_778	1	IIPutTxDTCIInfo_778	1	✓

Test Step 2.42 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	6
CTCEventId_Cnt_M_u8	10
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSources	18
DTCDData.DTCNumber	56270
DTCDData.DTCFailType	166
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	92
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	5
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	33		
GMStatus_Cnt_M_u8[11]	36		
GMStatus_Cnt_M_u8[12]	39		
GMStatus_Cnt_M_u8[13]	42		
GMStatus_Cnt_M_u8[14]	45		
GMStatus_Cnt_M_u8[15]	48		
GMStatus_Cnt_M_u8[16]	51		
GMStatus_Cnt_M_u8[17]	54		
GMStatus_Cnt_M_u8[18]	57		
GMStatus_Cnt_M_u8[19]	60		
GMStatus_Cnt_M_u8[20]	63		
GMStatus_Cnt_M_u8[21]	66		
GMStatus_Cnt_M_u8[22]	69		
GMStatus_Cnt_M_u8[23]	72		
GMStatus_Cnt_M_u8[24]	75		
GMStatus_Cnt_M_u8[25]	78		
GMStatus_Cnt_M_u8[26]	81		
GMStatus_Cnt_M_u8[27]	84		
GMStatus_Cnt_M_u8[28]	87		
GMStatus_Cnt_M_u8[29]	90		
GMStatus_Cnt_M_u8[30]	93		
GMStatus_Cnt_M_u8[31]	96		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	41		
LKATrqOvriDlvdRC_Cnt_M_u8	1		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156		
LastReportedDTCEventID_Cnt_M_u8	29		
LastReportedGMStatus_Cnt_M_u8	79		
PrevWarningIndSignal_Cnt_M_u8[0]	1		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	711186944		
Steering_Torque_Overlay_Stat_CE_c[0]	72		
Steering_Torque_Overlay_Stat_CE_c[1]	84		
Steering_Torque_Overlay_Stat_CE_c[2]	96		
Steering_Torque_Overlay_Stat_CE_c[3]	108		
Steering_Torque_Overlay_Stat_CE_c[4]	120		
Steering_Torque_Overlay_Stat_CE_c[5]	132		
Steering_Torque_Overlay_Stat_CE_c[6]	144		
Steering_Torque_Overlay_Stat_CE_c[7]	156		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.610000014		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	50		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	92		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	20588		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2570506240		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	5		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.75999999		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	1.21000004		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-0.300000012		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	6	6	✓
CTCEventId_Cnt_M_u8	11	11	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSrc	49	49	✓
DTCDData.DTCNbr	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	6	6	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvriDlvdRC_Cnt_M_u8	2	2	✓
LastReportedDTCEventID_Cnt_M_u8	29	29	✓
LastReportedGMStatus_Cnt_M_u8	79	79	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	711186944	711186944	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDltSt	1	IIPutTxHndsOffStrWhlDltSt	1	✓
IIPutTxHndsOffStrWhlDltMd	1	IIPutTxHndsOffStrWhlDltMd	1	✓
IIPutTxHndsOffStrWhlDltStV	1	IIPutTxHndsOffStrWhlDltStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDltStGroup	1	IIPutTxHndsOffStrWhlDltStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSources_778	1	IIPutTxDTCl_DTCSources_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.43 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	10
CTCEventId_Cnt_M_u8	24
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCTData.DTCTriggered	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCSource	20
DTCDData.DTCNumber	27244
DTCDData.DTCFailType	41
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	66
DTCTriggeredFlag_Cnt_M_Igc[0]	0
DTCTriggeredFlag_Cnt_M_Igc[1]	0
DTCTriggeredFlag_Cnt_M_Igc[2]	1
DTCTriggeredFlag_Cnt_M_Igc[3]	1
DTCTriggeredFlag_Cnt_M_Igc[4]	1
DTCTriggeredFlag_Cnt_M_Igc[5]	0
DTCTriggeredFlag_Cnt_M_Igc[6]	1
DTCTriggeredFlag_Cnt_M_Igc[7]	1
DTCTriggeredFlag_Cnt_M_Igc[8]	0
DTCTriggeredFlag_Cnt_M_Igc[9]	1
DTCTriggeredFlag_Cnt_M_Igc[10]	0
DTCTriggeredFlag_Cnt_M_Igc[11]	1
DTCTriggeredFlag_Cnt_M_Igc[12]	1
DTCTriggeredFlag_Cnt_M_Igc[13]	1
DTCTriggeredFlag_Cnt_M_Igc[14]	0
DTCTriggeredFlag_Cnt_M_Igc[15]	1
DTCTriggeredFlag_Cnt_M_Igc[16]	0
DTCTriggeredFlag_Cnt_M_Igc[17]	1
DTCTriggeredFlag_Cnt_M_Igc[18]	0
DTCTriggeredFlag_Cnt_M_Igc[19]	1
DTCTriggeredFlag_Cnt_M_Igc[20]	0
DTCTriggeredFlag_Cnt_M_Igc[21]	1
DTCTriggeredFlag_Cnt_M_Igc[22]	0
DTCTriggeredFlag_Cnt_M_Igc[23]	1
DTCTriggeredFlag_Cnt_M_Igc[24]	1
DTCTriggeredFlag_Cnt_M_Igc[25]	1
DTCTriggeredFlag_Cnt_M_Igc[26]	0
DTCTriggeredFlag_Cnt_M_Igc[27]	0
DTCTriggeredFlag_Cnt_M_Igc[28]	1
DTCTriggeredFlag_Cnt_M_Igc[29]	0
DTCTriggeredFlag_Cnt_M_Igc[30]	1
DTCTriggeredFlag_Cnt_M_Igc[31]	1
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	7
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	69
LKATrqOvrldlvdRC_Cnt_M_u8	210
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	20
LastReportedGMStatus_Cnt_M_u8	81
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	1012610304
Steering_Torque_Overlay_Stat_CE_c[0]	84
Steering_Torque_Overlay_Stat_CE_c[1]	98
Steering_Torque_Overlay_Stat_CE_c[2]	112
Steering_Torque_Overlay_Stat_CE_c[3]	126
Steering_Torque_Overlay_Stat_CE_c[4]	140
Steering_Torque_Overlay_Stat_CE_c[5]	154
Steering_Torque_Overlay_Stat_CE_c[6]	168
Steering_Torque_Overlay_Stat_CE_c[7]	182
k_LKAMfgEnable_Cnt_lgc	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_MaxHOWEstimate_Uls_f32	0.629999995		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	51		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	66		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	63906		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	389698304		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	5.09999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.109999999		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-7.69999981		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	2.33999991		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	10	10	✓
CTCEventId_Cnt_M_u8	25	25	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	8	8	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	210	210	✓
LastReportedDTCEventID_Cnt_M_u8	20	20	✓
LastReportedGMStatus_Cnt_M_u8	81	81	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1012610304	1012610304	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItTqDlrd	1	IIPutTxElPwrStItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrcSource_778	1	IIPutTxDTCl_DTCSrcSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WmIndRqdSt_778	1	IIPutTxDTCl_WmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.44 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	35
CTCEventId_Cnt_M_u8	10
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSrcSource	22

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCNumber	12420
DTCDData.DTCFailType	41
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	113
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	6
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	224
LKATrqOvrDivdRC_Cnt_M_u8	241
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	83
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	676026112
Steering_Torque_Overlay_Stat_CE_c[0]	12
Steering_Torque_Overlay_Stat_CE_c[1]	14
Steering_Torque_Overlay_Stat_CE_c[2]	16
Steering_Torque_Overlay_Stat_CE_c[3]	18
Steering_Torque_Overlay_Stat_CE_c[4]	20
Steering_Torque_Overlay_Stat_CE_c[5]	22
Steering_Torque_Overlay_Stat_CE_c[6]	24
Steering_Torque_Overlay_Stat_CE_c[7]	26
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.649999976

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	52		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	113		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	42122		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1045652736		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	5.19999981		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.319999993		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	10		
target_Rte_Read_Ap_SrlComOutput_LKAState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	35	35	✔
CTCEventId_Cnt_M_u8	11	11	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	0	0	✔
DTCDData.DTCFailType	0	0	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	0	0	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	7	7	✔
GMStatus_Cnt_M_u8[0]	2	2	✔
GMStatus_Cnt_M_u8[1]	4	4	✔
GMStatus_Cnt_M_u8[2]	6	6	✔
GMStatus_Cnt_M_u8[3]	8	8	✔
GMStatus_Cnt_M_u8[4]	10	10	✔
GMStatus_Cnt_M_u8[5]	12	12	✔
GMStatus_Cnt_M_u8[6]	14	14	✔
GMStatus_Cnt_M_u8[7]	16	16	✔
GMStatus_Cnt_M_u8[8]	18	18	✔
GMStatus_Cnt_M_u8[9]	20	20	✔
GMStatus_Cnt_M_u8[10]	22	22	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrDlvdRC_Cnt_M_u8	242	242	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	83	83	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	676026112	676026112	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrItqDStat	1	IIPutTxTrqOvrItqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtmD	1	IIPutTxHndsOffStrWhlDtmD	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrItqDStat	1	IIPutTxLKATrqOvrItqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIDStatChksm	1	IIPutTxLKATrqOvrIDStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.45 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	10
CTCEventId_Cnt_M_u8	13
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	24
DTCDData.DTCNumber	61885
DTCDData.DTCFailType	111
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	215
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	11		
GMStatus_Cnt_M_u8[11]	12		
GMStatus_Cnt_M_u8[12]	13		
GMStatus_Cnt_M_u8[13]	14		
GMStatus_Cnt_M_u8[14]	15		
GMStatus_Cnt_M_u8[15]	16		
GMStatus_Cnt_M_u8[16]	17		
GMStatus_Cnt_M_u8[17]	18		
GMStatus_Cnt_M_u8[18]	19		
GMStatus_Cnt_M_u8[19]	20		
GMStatus_Cnt_M_u8[20]	21		
GMStatus_Cnt_M_u8[21]	22		
GMStatus_Cnt_M_u8[22]	23		
GMStatus_Cnt_M_u8[23]	24		
GMStatus_Cnt_M_u8[24]	25		
GMStatus_Cnt_M_u8[25]	26		
GMStatus_Cnt_M_u8[26]	27		
GMStatus_Cnt_M_u8[27]	28		
GMStatus_Cnt_M_u8[28]	29		
GMStatus_Cnt_M_u8[29]	30		
GMStatus_Cnt_M_u8[30]	31		
GMStatus_Cnt_M_u8[31]	32		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	127		
LKATrqOvrDlvdRC_Cnt_M_u8	62		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventID_Cnt_M_u8	31		
LastReportedGMStatus_Cnt_M_u8	85		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	1222163968		
Steering_Torque_Overlay_Stat_CE_c[0]	24		
Steering_Torque_Overlay_Stat_CE_c[1]	28		
Steering_Torque_Overlay_Stat_CE_c[2]	32		
Steering_Torque_Overlay_Stat_CE_c[3]	36		
Steering_Torque_Overlay_Stat_CE_c[4]	40		
Steering_Torque_Overlay_Stat_CE_c[5]	44		
Steering_Torque_Overlay_Stat_CE_c[6]	48		
Steering_Torque_Overlay_Stat_CE_c[7]	52		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.670000017		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	53		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	215		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	21756		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	7902208		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	5.30000019		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.5		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	4.19000006		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	2.05999994		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	10	10	✓
CTCEventId_Cnt_M_u8	14	14	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNNumber	3	*none*	✓
DTCDData.DTCFailType	72	*none*	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvriDlvdRC_Cnt_M_u8	62	62	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	85	85	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1222163968	1222163968	✓

Test Step Call Trace ✓

Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItItqDlrd	1	IIPutTxElPwrStItItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDItTrqDlrd	1	IIPutTxTrqOvriDItTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrmIndRqdSt_778	1	IIPutTxDTCL_WrmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.46 (Repeat Count = 1) ✓

Name	Input Value
CTCEventIdSV_Cnt_M_u8	11
CTCEventId_Cnt_M_u8	10
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	26
DTCDData.DTCNumber	1158
DTCDData.DTCFailType	119
DTCDData.DTCWrmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	53
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	13
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	33		
GMStatus_Cnt_M_u8[11]	36		
GMStatus_Cnt_M_u8[12]	39		
GMStatus_Cnt_M_u8[13]	42		
GMStatus_Cnt_M_u8[14]	45		
GMStatus_Cnt_M_u8[15]	48		
GMStatus_Cnt_M_u8[16]	51		
GMStatus_Cnt_M_u8[17]	54		
GMStatus_Cnt_M_u8[18]	57		
GMStatus_Cnt_M_u8[19]	60		
GMStatus_Cnt_M_u8[20]	63		
GMStatus_Cnt_M_u8[21]	66		
GMStatus_Cnt_M_u8[22]	69		
GMStatus_Cnt_M_u8[23]	72		
GMStatus_Cnt_M_u8[24]	75		
GMStatus_Cnt_M_u8[25]	78		
GMStatus_Cnt_M_u8[26]	81		
GMStatus_Cnt_M_u8[27]	84		
GMStatus_Cnt_M_u8[28]	87		
GMStatus_Cnt_M_u8[29]	90		
GMStatus_Cnt_M_u8[30]	93		
GMStatus_Cnt_M_u8[31]	96		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	92		
LKATrqOvriDlvdRC_Cnt_M_u8	58		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104		
LastReportedDTCEventID_Cnt_M_u8	17		
LastReportedGMStatus_Cnt_M_u8	87		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3093112832		
Steering_Torque_Overlay_Stat_CE_c[0]	48		
Steering_Torque_Overlay_Stat_CE_c[1]	56		
Steering_Torque_Overlay_Stat_CE_c[2]	64		
Steering_Torque_Overlay_Stat_CE_c[3]	72		
Steering_Torque_Overlay_Stat_CE_c[4]	80		
Steering_Torque_Overlay_Stat_CE_c[5]	88		
Steering_Torque_Overlay_Stat_CE_c[6]	96		
Steering_Torque_Overlay_Stat_CE_c[7]	104		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.6899999998		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	54		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	53		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	46431		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3689655808		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	5.4000001		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.5299999971		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-9.60000038		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.32000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	11	11	✓
CTCEventId_Cnt_M_u8	11	11	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNNumber	7	7	✓
DTCDData.DTCFailType	8	8	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	14	14	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvriDlvdRC_Cnt_M_u8	59	59	✓
LastReportedDTCEventID_Cnt_M_u8	17	17	✓
LastReportedGMStatus_Cnt_M_u8	87	87	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3093112832	3093112832	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDlvdARC	1	IIPutTxTrqOvriDlvdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMtd	1	IIPutTxHndsOffStrWhlDlMtd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.47 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	30
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	28
DTCDData.DTCNumber	21115

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCFailType	253
DTCDData.DTCWmIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaultype	53
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	12
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	11
LKATrqOvrDlvdRC_Cnt_M_u8	85
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130
LastReportedDTCEventID_Cnt_M_u8	16
LastReportedGMStatus_Cnt_M_u8	89
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCTFlag_mS_M_u32p0	3777448704
Steering_Torque_Overlay_Stat_CE_c[0]	60
Steering_Torque_Overlay_Stat_CE_c[1]	70
Steering_Torque_Overlay_Stat_CE_c[2]	80
Steering_Torque_Overlay_Stat_CE_c[3]	90
Steering_Torque_Overlay_Stat_CE_c[4]	100
Steering_Torque_Overlay_Stat_CE_c[5]	110
Steering_Torque_Overlay_Stat_CE_c[6]	120
Steering_Torque_Overlay_Stat_CE_c[7]	130
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.709999979
k_SComTrqPosPol_Cnt_s08	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
target_Dem_GetEventStatus_EventStatusExtended	55		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	53		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	53887		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3222518016		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	5.5		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.800000012		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	2.069999993		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.20000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	30	30	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCData.DTCTriggered	1	1	✔
DTCData.DTCSource	28	28	✔
DTCData.DTCNumber	21115	21115	✔
DTCData.DTCFailType	253	253	✔
DTCData.DTCWmIndRqdSt	1	1	✔
DTCData.DTCTstFldPwrUpSt	1	1	✔
DTCData.DTCTstNPsdPwrupSt	1	1	✔
DTCData.DTCHistStat	1	1	✔
DTCData.DTCTstFldCdCldStat	1	1	✔
DTCData.DTCTstNPsdCdCldSt	0	0	✔
DTCData.DTCCurrentStatus	1	1	✔
DTCData.DTCCodeSupported	1	1	✔
DTCData.DTCFaulttype	53	53	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	13	13	✔
GMStatus_Cnt_M_u8[0]	2	2	✔
GMStatus_Cnt_M_u8[1]	3	3	✔
GMStatus_Cnt_M_u8[2]	3	3	✔
GMStatus_Cnt_M_u8[3]	3	3	✔
GMStatus_Cnt_M_u8[4]	3	3	✔
GMStatus_Cnt_M_u8[5]	3	3	✔
GMStatus_Cnt_M_u8[6]	3	3	✔
GMStatus_Cnt_M_u8[7]	3	3	✔
GMStatus_Cnt_M_u8[8]	3	3	✔
GMStatus_Cnt_M_u8[9]	3	3	✔
GMStatus_Cnt_M_u8[10]	3	3	✔
GMStatus_Cnt_M_u8[11]	3	3	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SriComOutput_Per1



Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[12]	3	3	✓
GMStatus_Cnt_M_u8[13]	3	3	✓
GMStatus_Cnt_M_u8[14]	3	3	✓
GMStatus_Cnt_M_u8[15]	3	3	✓
GMStatus_Cnt_M_u8[16]	3	3	✓
GMStatus_Cnt_M_u8[17]	3	3	✓
GMStatus_Cnt_M_u8[18]	3	3	✓
GMStatus_Cnt_M_u8[19]	3	3	✓
GMStatus_Cnt_M_u8[20]	3	3	✓
GMStatus_Cnt_M_u8[21]	3	3	✓
GMStatus_Cnt_M_u8[22]	3	3	✓
GMStatus_Cnt_M_u8[23]	3	3	✓
GMStatus_Cnt_M_u8[24]	3	3	✓
GMStatus_Cnt_M_u8[25]	3	3	✓
GMStatus_Cnt_M_u8[26]	3	3	✓
GMStatus_Cnt_M_u8[27]	3	3	✓
GMStatus_Cnt_M_u8[28]	3	3	✓
GMStatus_Cnt_M_u8[29]	3	3	✓
GMStatus_Cnt_M_u8[30]	3	3	✓
GMStatus_Cnt_M_u8[31]	3	3	✓
LKATrqOvriDlvdRC_Cnt_M_u8	85	85	✓
LastReportedDTCEventID_Cnt_M_u8	16	16	✓
LastReportedGMStatus_Cnt_M_u8	89	89	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3777448704	3777448704	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdCldSt_778	1	IIPutTxDTCL_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.48 (Repeat Count = 1) ✓

Name	Input Value
CTCEventIdSV_Cnt_M_u8	28
CTCEventId_Cnt_M_u8	20
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	30
DTCDData.DTCNumber	24831
DTCDData.DTCFailType	196
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	222
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	164
LKATrqOvriDlvdRC_Cnt_M_u8	250
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	20
LastReportedGMStatus_Cnt_M_u8	91
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2624068864		
Steering_Torque_Overlay_Stat_CE_c[0]	84		
Steering_Torque_Overlay_Stat_CE_c[1]	98		
Steering_Torque_Overlay_Stat_CE_c[2]	112		
Steering_Torque_Overlay_Stat_CE_c[3]	126		
Steering_Torque_Overlay_Stat_CE_c[4]	140		
Steering_Torque_Overlay_Stat_CE_c[5]	154		
Steering_Torque_Overlay_Stat_CE_c[6]	168		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.730000019		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	56		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	222		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	61250		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1063779072		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	5.5999999		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.99000001		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-7.80000019		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.02999997		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	28	28	✓
CTCEventId_Cnt_M_u8	21	21	✓
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWrnIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPNsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPNsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	3	3	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrrDlvdRC_Cnt_M_u8	251	251	✓
LastReportedDTCEventID_Cnt_M_u8	20	20	✓
LastReportedGMStatus_Cnt_M_u8	91	91	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	2624068864	2624068864	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCI_DTCTriggered_778	1	IIPutTxDTCI_DTCTriggered_778	1	✓
IIPutTxDTCI_DTCSource_778	1	IIPutTxDTCI_DTCSource_778	1	✓
IIPutTxDTCI_DTCNumber_778	1	IIPutTxDTCI_DTCNumber_778	1	✓
IIPutTxDTCI_DTCFailType_778	1	IIPutTxDTCI_DTCFailType_778	1	✓
IIPutTxDTCI_CodeSupported_778	1	IIPutTxDTCI_CodeSupported_778	1	✓
IIPutTxDTCI_CurrentStatus_778	1	IIPutTxDTCI_CurrentStatus_778	1	✓
IIPutTxDTCI_TstNPsdCdClrdSt_778	1	IIPutTxDTCI_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCI_TstFldCdClrdStat_778	1	IIPutTxDTCI_TstFldCdClrdStat_778	1	✓
IIPutTxDTCI_HistStat_778	1	IIPutTxDTCI_HistStat_778	1	✓
IIPutTxDTCI_TstNPsdPwrUpSt_778	1	IIPutTxDTCI_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCI_TstFldPwrUpSt_778	1	IIPutTxDTCI_TstFldPwrUpSt_778	1	✓
IIPutTxDTCI_WrnIndRqdSt_778	1	IIPutTxDTCI_WrnIndRqdSt_778	1	✓
IIPutTxDTCI_DTCFaultType_778	1	IIPutTxDTCI_DTCFaultType_778	1	✓
IIPutTxDTCTInfo_778	1	IIPutTxDTCTInfo_778	1	✓

Test Step 2.49 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	6
CTCEventId_Cnt_M_u8	21
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	32
DTCDData.DTCNumber	42083
DTCDData.DTCFailType	182
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	8
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	4
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	40		
GMStatus_Cnt_M_u8[10]	44		
GMStatus_Cnt_M_u8[11]	48		
GMStatus_Cnt_M_u8[12]	52		
GMStatus_Cnt_M_u8[13]	56		
GMStatus_Cnt_M_u8[14]	60		
GMStatus_Cnt_M_u8[15]	64		
GMStatus_Cnt_M_u8[16]	68		
GMStatus_Cnt_M_u8[17]	72		
GMStatus_Cnt_M_u8[18]	76		
GMStatus_Cnt_M_u8[19]	80		
GMStatus_Cnt_M_u8[20]	84		
GMStatus_Cnt_M_u8[21]	88		
GMStatus_Cnt_M_u8[22]	92		
GMStatus_Cnt_M_u8[23]	96		
GMStatus_Cnt_M_u8[24]	100		
GMStatus_Cnt_M_u8[25]	104		
GMStatus_Cnt_M_u8[26]	108		
GMStatus_Cnt_M_u8[27]	112		
GMStatus_Cnt_M_u8[28]	116		
GMStatus_Cnt_M_u8[29]	120		
GMStatus_Cnt_M_u8[30]	124		
GMStatus_Cnt_M_u8[31]	128		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	23		
LKATrqOvriDlvdRC_Cnt_M_u8	206		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventID_Cnt_M_u8	11		
LastReportedGMStatus_Cnt_M_u8	93		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	1058696192		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.75		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	57		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	8		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	17516		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3004355072		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	5.69999981		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.899999976		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-7.80000019		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.10000002		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	6	6	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	22	22	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	70	70	✓
DTCDData.DTCFailType	80	80	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdClrdStat	1	1	✓
DTCDData.DTCTstNPsdCdClrdSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaultype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	5	5	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDlvdRC_Cnt_M_u8	206	206	✓
LastReportedDTCEventID_Cnt_M_u8	11	11	✓
LastReportedGMStatus_Cnt_M_u8	93	93	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1058696192	1058696192	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcldIO	1	IIPutTxStrngAsstRdcldIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.50 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	2
CTCEventId_Cnt_M_u8	18
CurrentDTCSThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	34
DTCDData.DTCNumber	46609
DTCDData.DTCFailType	42
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaultype	9
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	1
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	44		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	215		
LKATrqOvrldDlvdRC_Cnt_M_u8	4		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156		
LastReportedDTCEventID_Cnt_M_u8	31		
LastReportedGMStatus_Cnt_M_u8	95		
PrevWarningIndSignal_Cnt_M_u8[0]	1		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3478930944		
Steering_Torque_Overlay_Stat_CE_c[0]	72		
Steering_Torque_Overlay_Stat_CE_c[1]	84		
Steering_Torque_Overlay_Stat_CE_c[2]	96		
Steering_Torque_Overlay_Stat_CE_c[3]	108		
Steering_Torque_Overlay_Stat_CE_c[4]	120		
Steering_Torque_Overlay_Stat_CE_c[5]	132		
Steering_Torque_Overlay_Stat_CE_c[6]	144		
Steering_Torque_Overlay_Stat_CE_c[7]	156		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.769999981		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	58		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	9		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	22783		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2357713920		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	5.80000019		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.720000029		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	6.76999998		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	0.709999979		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	2	2	✓
CTCEventId_Cnt_M_u8	19	19	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCDData.DTCTTriggered	0	0	✓
DTCDData.DTCSrcSource	49	49	✓
DTCDData.DTCNNumber	2	*none*	✓
DTCDData.DTCFailType	68	*none*	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	2	2	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	4	4	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	95	95	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3478930944	3478930944	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrc_778	1	IIPutTxDTCl_DTCSrc_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.51 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	17
CTCEventId_Cnt_M_u8	28
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	36
DTCDData.DTCNumber	12114
DTCDData.DTCFailType	169
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaultype	33
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	3
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[11]	12		
GMStatus_Cnt_M_u8[12]	13		
GMStatus_Cnt_M_u8[13]	14		
GMStatus_Cnt_M_u8[14]	15		
GMStatus_Cnt_M_u8[15]	16		
GMStatus_Cnt_M_u8[16]	17		
GMStatus_Cnt_M_u8[17]	18		
GMStatus_Cnt_M_u8[18]	19		
GMStatus_Cnt_M_u8[19]	20		
GMStatus_Cnt_M_u8[20]	21		
GMStatus_Cnt_M_u8[21]	22		
GMStatus_Cnt_M_u8[22]	23		
GMStatus_Cnt_M_u8[23]	24		
GMStatus_Cnt_M_u8[24]	25		
GMStatus_Cnt_M_u8[25]	26		
GMStatus_Cnt_M_u8[26]	27		
GMStatus_Cnt_M_u8[27]	28		
GMStatus_Cnt_M_u8[28]	29		
GMStatus_Cnt_M_u8[29]	30		
GMStatus_Cnt_M_u8[30]	31		
GMStatus_Cnt_M_u8[31]	32		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	147		
LKATrqOvrldDlvdRC_Cnt_M_u8	248		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182		
LastReportedDTCEventID_Cnt_M_u8	15		
LastReportedGMStatus_Cnt_M_u8	97		
PrevWarningIndSignal_Cnt_M_u8[0]	0		
PrevWarningIndSignal_Cnt_M_u8[1]	0		
PrevWarningIndSignal_Cnt_M_u8[2]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	102887680		
Steering_Torque_Overlay_Stat_CE_c[0]	84		
Steering_Torque_Overlay_Stat_CE_c[1]	98		
Steering_Torque_Overlay_Stat_CE_c[2]	112		
Steering_Torque_Overlay_Stat_CE_c[3]	126		
Steering_Torque_Overlay_Stat_CE_c[4]	140		
Steering_Torque_Overlay_Stat_CE_c[5]	154		
Steering_Torque_Overlay_Stat_CE_c[6]	168		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.790000021		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	59		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	8857		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2692165376		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	5.9000001		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.300000012		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-4.01999998		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.38		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	17	17	✓
CTCEventId_Cnt_M_u8	29	29	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCDData.DTCTTriggered	0	0	✓
DTCDData.DTCSrcSource	49	49	✓
DTCDData.DTCNNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	4	4	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	248	248	✓
LastReportedDTCEventID_Cnt_M_u8	15	15	✓
LastReportedGMStatus_Cnt_M_u8	97	97	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	102887680	102887680	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcldIO	1	IIPutTxStrngAsstRdcldIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.52 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	21
CTCEventId_Cnt_M_u8	3
CurrentDTCSThisIC_Cnt_M_lgc	0
DTCDData.DTCSTriggered	0
DTCDData.DTCSorce	38
DTCDData.DTCNumber	16126
DTCDData.DTCFailType	198
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaultype	149
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	8
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[11]	12		
GMStatus_Cnt_M_u8[12]	13		
GMStatus_Cnt_M_u8[13]	14		
GMStatus_Cnt_M_u8[14]	15		
GMStatus_Cnt_M_u8[15]	16		
GMStatus_Cnt_M_u8[16]	17		
GMStatus_Cnt_M_u8[17]	18		
GMStatus_Cnt_M_u8[18]	19		
GMStatus_Cnt_M_u8[19]	20		
GMStatus_Cnt_M_u8[20]	21		
GMStatus_Cnt_M_u8[21]	22		
GMStatus_Cnt_M_u8[22]	23		
GMStatus_Cnt_M_u8[23]	24		
GMStatus_Cnt_M_u8[24]	25		
GMStatus_Cnt_M_u8[25]	26		
GMStatus_Cnt_M_u8[26]	27		
GMStatus_Cnt_M_u8[27]	28		
GMStatus_Cnt_M_u8[28]	29		
GMStatus_Cnt_M_u8[29]	30		
GMStatus_Cnt_M_u8[30]	31		
GMStatus_Cnt_M_u8[31]	32		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	72		
LKATrqOvrldDlvdRC_Cnt_M_u8	210		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventID_Cnt_M_u8	3		
LastReportedGMStatus_Cnt_M_u8	99		
PrevWarningIndSignal_Cnt_M_u8[0]	1		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2091381504		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.810000002		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	60		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	149		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	1435		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1255612672		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	6		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.0799999982		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-9.039999996		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	0.00999999978		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	21	21	✓
CTCEventId_Cnt_M_u8	4	4	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCDData.DTCTTriggered	0	0	✓
DTCDData.DTCSrcSource	49	49	✓
DTCDData.DTCNNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	9	9	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	211	211	✓
LastReportedDTCEventID_Cnt_M_u8	3	3	✓
LastReportedGMStatus_Cnt_M_u8	99	99	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2091381504	2091381504	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WmIndRqdSt_778	1	IIPutTxDTCl_WmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.53 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	1
CTCEventId_Cnt_M_u8	19
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCTData.DTCTriggered	0
DTCTData.DTCSOURCE	40

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCNumber	12990
DTCDData.DTCFailType	145
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	140
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	45
LKATrqOvrDivdRC_Cnt_M_u8	227
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	101
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	288549376
Steering_Torque_Overlay_Stat_CE_c[0]	72
Steering_Torque_Overlay_Stat_CE_c[1]	84
Steering_Torque_Overlay_Stat_CE_c[2]	96
Steering_Torque_Overlay_Stat_CE_c[3]	108
Steering_Torque_Overlay_Stat_CE_c[4]	120
Steering_Torque_Overlay_Stat_CE_c[5]	132
Steering_Torque_Overlay_Stat_CE_c[6]	144
Steering_Torque_Overlay_Stat_CE_c[7]	156
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.829999983

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	61		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	140		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	26937		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2765971456		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	6.0999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.400000006		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-3.77999997		
target_Rte_Read_Ap_SrlComOutput_LKAState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	2.96000004		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	1	1	✓
CTCEventId_Cnt_M_u8	20	20	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt M_u8[10]	44	44	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SriComOutput_Per1



Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvrDlvdRC_Cnt_M_u8	228	228	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	101	101	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	288549376	288549376	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrlTrqDStat	1	IIPutTxTrqOvrlTrqDStat	1	✓
IIPutTxTrqOvrlDvrdARC	1	IIPutTxTrqOvrlDvrdARC	1	✓
IIPutTxTrqOvrlDltTrqDlrd	1	IIPutTxTrqOvrlDltTrqDlrd	1	✓
IIPutTxTrqOvrlDChksm	1	IIPutTxTrqOvrlDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.54 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	4
CTCEventId_Cnt_M_u8	2
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	42
DTCDData.DTCNumber	11630
DTCDData.DTCFailType	70
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	40
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	10
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	40		
GMStatus_Cnt_M_u8[10]	44		
GMStatus_Cnt_M_u8[11]	48		
GMStatus_Cnt_M_u8[12]	52		
GMStatus_Cnt_M_u8[13]	56		
GMStatus_Cnt_M_u8[14]	60		
GMStatus_Cnt_M_u8[15]	64		
GMStatus_Cnt_M_u8[16]	68		
GMStatus_Cnt_M_u8[17]	72		
GMStatus_Cnt_M_u8[18]	76		
GMStatus_Cnt_M_u8[19]	80		
GMStatus_Cnt_M_u8[20]	84		
GMStatus_Cnt_M_u8[21]	88		
GMStatus_Cnt_M_u8[22]	92		
GMStatus_Cnt_M_u8[23]	96		
GMStatus_Cnt_M_u8[24]	100		
GMStatus_Cnt_M_u8[25]	104		
GMStatus_Cnt_M_u8[26]	108		
GMStatus_Cnt_M_u8[27]	112		
GMStatus_Cnt_M_u8[28]	116		
GMStatus_Cnt_M_u8[29]	120		
GMStatus_Cnt_M_u8[30]	124		
GMStatus_Cnt_M_u8[31]	128		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	232		
LKATrqOvriDlvdRC_Cnt_M_u8	53		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventID_Cnt_M_u8	31		
LastReportedGMStatus_Cnt_M_u8	103		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3848844288		
Steering_Torque_Overlay_Stat_CE_c[0]	24		
Steering_Torque_Overlay_Stat_CE_c[1]	28		
Steering_Torque_Overlay_Stat_CE_c[2]	32		
Steering_Torque_Overlay_Stat_CE_c[3]	36		
Steering_Torque_Overlay_Stat_CE_c[4]	40		
Steering_Torque_Overlay_Stat_CE_c[5]	44		
Steering_Torque_Overlay_Stat_CE_c[6]	48		
Steering_Torque_Overlay_Stat_CE_c[7]	52		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.850000024		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	62		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	37217		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	374790656		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	6.19999981		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.5		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-1.89999998		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.5		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	4	4	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	3	3	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSrc	49	49	✓
DTCDData.DTCNumber	3	*none*	✓
DTCDData.DTCFailType	72	*none*	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaultype	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	11	11	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvrDlvdRC_Cnt_M_u8	53	53	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	103	103	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3848844288	3848844288	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSTItITqDlrd	1	IIPutTxElPwrSTItITqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFidCdClrdStat_778	1	IIPutTxDTCl_TstFidCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFidPwrUpSt_778	1	IIPutTxDTCl_TstFidPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.55 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	11
CTCEventId_Cnt_M_u8	16
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	44
DTCDData.DTCNumber	42994
DTCDData.DTCFailType	195
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFidPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFidCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	19
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	14
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	20		
GMStatus_Cnt_M_u8[10]	22		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	44		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	56		
LKATrqOvrlDlvdRC_Cnt_M_u8	68		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	42		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	54		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	66		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	78		
LastReportedDTCEventID_Cnt_M_u8	30		
LastReportedGMStatus_Cnt_M_u8	105		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3342116608		
Steering_Torque_Overlay_Stat_CE_c[0]	36		
Steering_Torque_Overlay_Stat_CE_c[1]	42		
Steering_Torque_Overlay_Stat_CE_c[2]	48		
Steering_Torque_Overlay_Stat_CE_c[3]	54		
Steering_Torque_Overlay_Stat_CE_c[4]	60		
Steering_Torque_Overlay_Stat_CE_c[5]	66		
Steering_Torque_Overlay_Stat_CE_c[6]	72		
Steering_Torque_Overlay_Stat_CE_c[7]	78		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.870000005		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	63		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	19		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	42409		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	75642112		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	6.30000019		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.170000002		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-3.5999999		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.11000001		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	11	11	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	17	17	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	181	181	✓
DTCDData.DTCFailType	164	164	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaultype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	15	15	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrDlvdRC_Cnt_M_u8	69	69	✓
LastReportedDTCEventID_Cnt_M_u8	30	30	✓
LastReportedGMStatus_Cnt_M_u8	105	105	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3342116608	3342116608	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrcSource_778	1	IIPutTxDTCl_DTCSrcSource_778	1	✓
IIPutTxDTCl_DTCCNumber_778	1	IIPutTxDTCl_DTCCNumber_778	1	✓
IIPutTxDTCl_DTCCFailType_778	1	IIPutTxDTCl_DTCCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFidCdCldStat_778	1	IIPutTxDTCl_TstFidCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFidPwrUpSt_778	1	IIPutTxDTCl_TstFidPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCCFaultType_778	1	IIPutTxDTCl_DTCCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.56 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	22
CTCEventId_Cnt_M_u8	17
CurrentDTCSentThisIC_Cnt_M_lgc	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTriggered	0
DTCDData.DTCSrc	46
DTCDData.DTCNumber	17807
DTCDData.DTCFailType	178
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	0
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	11
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	177
LKATrqOvrldvldRC_Cnt_M_u8	90
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	107
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	2688571648
Steering_Torque_Overlay_Stat_CE_c[0]	60
Steering_Torque_Overlay_Stat_CE_c[1]	70
Steering_Torque_Overlay_Stat_CE_c[2]	80
Steering_Torque_Overlay_Stat_CE_c[3]	90
Steering_Torque_Overlay_Stat_CE_c[4]	100
Steering_Torque_Overlay_Stat_CE_c[5]	110
Steering_Torque_Overlay_Stat_CE_c[6]	120
Steering_Torque_Overlay_Stat_CE_c[7]	130

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.889999986		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	64		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	56602		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	162158336		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	6.4000001		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.899999976		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	9.90999985		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	2.81100011		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	22	22	✓
CTCEventId_Cnt_M_u8	18	18	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSorce	49	49	✓
DTCDData.DTCNumber	2	*none*	✓
DTCDData.DTCFailType	68	*none*	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdClrdStat	1	1	✓
DTCDData.DTCTstNPsdCdClrdSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	12	12	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvrDlvdRC_Cnt_M_u8	90	90	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	107	107	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCTFlag_ms_M_u32p0	2688571648	2688571648	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSorce_778	1	IIPutTxDTCL_DTCSorce_778	1	✓
IIPutTxDTCL_DTCTNumber_778	1	IIPutTxDTCL_DTCTNumber_778	1	✓
IIPutTxDTCL_DTCTFailType_778	1	IIPutTxDTCL_DTCTFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCTFaultType_778	1	IIPutTxDTCL_DTCTFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.57 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	34
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCTData.DTCTriggered	0
DTCTData.DTCSorce	48

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCNumber	16803
DTCDData.DTCFailType	156
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	255
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	5
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	61
LKATrqOvrDivdRC_Cnt_M_u8	88
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	109
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	4018255872
Steering_Torque_Overlay_Stat_CE_c[0]	72
Steering_Torque_Overlay_Stat_CE_c[1]	84
Steering_Torque_Overlay_Stat_CE_c[2]	96
Steering_Torque_Overlay_Stat_CE_c[3]	108
Steering_Torque_Overlay_Stat_CE_c[4]	120
Steering_Torque_Overlay_Stat_CE_c[5]	132
Steering_Torque_Overlay_Stat_CE_c[6]	144
Steering_Torque_Overlay_Stat_CE_c[7]	156
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.910000026

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	65		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	255		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	55506		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3770400256		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	6.5		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.0599999987		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	10		
target_Rte_Read_Ap_SrlComOutput_LKAState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-1.60000002		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	34	34	✔
CTCEventId_Cnt_M_u8	15	15	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	3	*none*	✔
DTCDData.DTCFailType	72	*none*	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	1	1	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	6	6	✔
GMStatus_Cnt_M_u8[0]	3	3	✔
GMStatus_Cnt_M_u8[1]	6	6	✔
GMStatus_Cnt_M_u8[2]	9	9	✔
GMStatus_Cnt_M_u8[3]	12	12	✔
GMStatus_Cnt_M_u8[4]	15	15	✔
GMStatus_Cnt_M_u8[5]	18	18	✔
GMStatus_Cnt_M_u8[6]	21	21	✔
GMStatus_Cnt_M_u8[7]	24	24	✔
GMStatus_Cnt_M_u8[8]	27	27	✔
GMStatus_Cnt_M_u8[9]	30	30	✔
GMStatus_Cnt_M_u8[10]	33	33	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvrIDvdRC_Cnt_M_u8	88	88	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	109	109	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4018255872	4018255872	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItTqDlrd	1	IIPutTxElPwrStItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WmIndRqdSt_778	1	IIPutTxDTCl_WmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.58 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	29
CTCEventId_Cnt_M_u8	34
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSorce	2

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCNumber	50530
DTCDData.DTCFailType	47
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	40
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	7
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	38
LKATrqOvrldDivdRC_Cnt_M_u8	32
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	27
LastReportedGMStatus_Cnt_M_u8	111
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	1106877184
Steering_Torque_Overlay_Stat_CE_c[0]	84
Steering_Torque_Overlay_Stat_CE_c[1]	98
Steering_Torque_Overlay_Stat_CE_c[2]	112
Steering_Torque_Overlay_Stat_CE_c[3]	126
Steering_Torque_Overlay_Stat_CE_c[4]	140
Steering_Torque_Overlay_Stat_CE_c[5]	154
Steering_Torque_Overlay_Stat_CE_c[6]	168
Steering_Torque_Overlay_Stat_CE_c[7]	182
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.930000007

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	66		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	9831		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3320023296		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	6.5999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.230000004		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-1.570000005		
target_Rte_Read_Ap_SrlComOutput_LKAState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.10000002		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	29	29	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	2	2	✔
DTCDData.DTCNumber	50530	50530	✔
DTCDData.DTCFailType	47	47	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	1	1	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdCldStat	0	0	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	40	40	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✔
ESCRollCount_Cnt_M_u08	8	8	✔
GMStatus_Cnt_M_u8[0]	2	2	✔
GMStatus_Cnt_M_u8[1]	1	1	✔
GMStatus_Cnt_M_u8[2]	1	1	✔
GMStatus_Cnt_M_u8[3]	1	1	✔
GMStatus_Cnt_M_u8[4]	1	1	✔
GMStatus_Cnt_M_u8[5]	1	1	✔
GMStatus_Cnt_M_u8[6]	1	1	✔
GMStatus_Cnt_M_u8[7]	1	1	✔
GMStatus_Cnt_M_u8[8]	1	1	✔
GMStatus_Cnt_M_u8[9]	1	1	✔
GMStatus_Cnt M_u8[10]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[11]	1	1	✓
GMStatus_Cnt_M_u8[12]	1	1	✓
GMStatus_Cnt_M_u8[13]	1	1	✓
GMStatus_Cnt_M_u8[14]	1	1	✓
GMStatus_Cnt_M_u8[15]	1	1	✓
GMStatus_Cnt_M_u8[16]	1	1	✓
GMStatus_Cnt_M_u8[17]	1	1	✓
GMStatus_Cnt_M_u8[18]	1	1	✓
GMStatus_Cnt_M_u8[19]	1	1	✓
GMStatus_Cnt_M_u8[20]	1	1	✓
GMStatus_Cnt_M_u8[21]	1	1	✓
GMStatus_Cnt_M_u8[22]	1	1	✓
GMStatus_Cnt_M_u8[23]	1	1	✓
GMStatus_Cnt_M_u8[24]	1	1	✓
GMStatus_Cnt_M_u8[25]	1	1	✓
GMStatus_Cnt_M_u8[26]	1	1	✓
GMStatus_Cnt_M_u8[27]	1	1	✓
GMStatus_Cnt_M_u8[28]	1	1	✓
GMStatus_Cnt_M_u8[29]	1	1	✓
GMStatus_Cnt_M_u8[30]	1	1	✓
GMStatus_Cnt_M_u8[31]	1	1	✓
LKATrqOvrDlvdRC_Cnt_M_u8	33	33	✓
LastReportedDTCEventID_Cnt_M_u8	27	27	✓
LastReportedGMStatus_Cnt_M_u8	111	111	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1106877184	1106877184	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.59 (Repeat Count = 1)

Name	Input Value
CTCEventIdSV_Cnt_M_u8	19
CTCEventId_Cnt_M_u8	9
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	5
DTCDData.DTCNumber	49713
DTCDData.DTCFailType	245
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaultype	130
DTCTTriggeredFlag_Cnt_M_lgc[0]	0
DTCTTriggeredFlag_Cnt_M_lgc[1]	0
DTCTTriggeredFlag_Cnt_M_lgc[2]	0
DTCTTriggeredFlag_Cnt_M_lgc[3]	0
DTCTTriggeredFlag_Cnt_M_lgc[4]	0
DTCTTriggeredFlag_Cnt_M_lgc[5]	0
DTCTTriggeredFlag_Cnt_M_lgc[6]	0
DTCTTriggeredFlag_Cnt_M_lgc[7]	0
DTCTTriggeredFlag_Cnt_M_lgc[8]	0
DTCTTriggeredFlag_Cnt_M_lgc[9]	0
DTCTTriggeredFlag_Cnt_M_lgc[10]	0
DTCTTriggeredFlag_Cnt_M_lgc[11]	0
DTCTTriggeredFlag_Cnt_M_lgc[12]	0
DTCTTriggeredFlag_Cnt_M_lgc[13]	0
DTCTTriggeredFlag_Cnt_M_lgc[14]	0
DTCTTriggeredFlag_Cnt_M_lgc[15]	0
DTCTTriggeredFlag_Cnt_M_lgc[16]	0
DTCTTriggeredFlag_Cnt_M_lgc[17]	0
DTCTTriggeredFlag_Cnt_M_lgc[18]	0
DTCTTriggeredFlag_Cnt_M_lgc[19]	0
DTCTTriggeredFlag_Cnt_M_lgc[20]	0
DTCTTriggeredFlag_Cnt_M_lgc[21]	0
DTCTTriggeredFlag_Cnt_M_lgc[22]	0
DTCTTriggeredFlag_Cnt_M_lgc[23]	0
DTCTTriggeredFlag_Cnt_M_lgc[24]	0
DTCTTriggeredFlag_Cnt_M_lgc[25]	0
DTCTTriggeredFlag_Cnt_M_lgc[26]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	6
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	117		
LKATrqOvrIdlvdRC_Cnt_M_u8	243		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventId_Cnt_M_u8	26		
LastReportedGMStatus_Cnt_M_u8	113		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	2044588544		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.949999988		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	67		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	130		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	27507		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1196959744		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	6.69999981		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.560000002		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-4.0999999		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-2.96000004		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	9	9	✓
CTCEventId_Cnt_M_u8	9	9	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	3	3	✓
DTCDData.DTCFailType	232	232	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrUpSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdClrdStat	1	1	✓
DTCDData.DTCTstNPsdCdClrdSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	7	7	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrDlvdRC_Cnt_M_u8	244	244	✓
LastReportedDTCEventID_Cnt_M_u8	26	26	✓
LastReportedGMStatus_Cnt_M_u8	113	113	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1196959744	1196959744	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.60 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	21
CTCEventId_Cnt_M_u8	21
CurrentDTCSThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	8
DTCDData.DTCNumber	25505
DTCDData.DTCFailType	209
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaultType	144
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	20		
GMStatus_Cnt_M_u8[10]	22		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	46		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	92		
LKATrqOvrlDlvdRC_Cnt_M_u8	168		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26		
LastReportedDTCEventID_Cnt_M_u8	3		
LastReportedGMStatus_Cnt_M_u8	115		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	1951198464		
Steering_Torque_Overlay_Stat_CE_c[0]	12		
Steering_Torque_Overlay_Stat_CE_c[1]	14		
Steering_Torque_Overlay_Stat_CE_c[2]	16		
Steering_Torque_Overlay_Stat_CE_c[3]	18		
Steering_Torque_Overlay_Stat_CE_c[4]	20		
Steering_Torque_Overlay_Stat_CE_c[5]	22		
Steering_Torque_Overlay_Stat_CE_c[6]	24		
Steering_Torque_Overlay_Stat_CE_c[7]	26		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.970000029		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	68		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	144		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	17132		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3761654528		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	6.80000019		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.129999995		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-6.63000011		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.75		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	21	21	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	22	22	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaultype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	46	46	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrDlvdRC_Cnt_M_u8	168	168	✓
LastReportedDTCEventID_Cnt_M_u8	3	3	✓
LastReportedGMStatus_Cnt_M_u8	115	115	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1951198464	1951198464	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSTtItqDlrd	1	IIPutTxElPwrSTtItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFidCdClrdStat_778	1	IIPutTxDTCl_TstFidCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFidPwrUpSt_778	1	IIPutTxDTCl_TstFidPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.61 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	6
CTCEventId_Cnt_M_u8	19
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	11
DTCDData.DTCNumber	10174
DTCDData.DTCFailType	169
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFidPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFidCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	25
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	13
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	1
GMStatus_Cnt_M_u8[2]	1
GMStatus_Cnt_M_u8[3]	1
GMStatus_Cnt_M_u8[4]	1
GMStatus_Cnt_M_u8[5]	1
GMStatus_Cnt_M_u8[6]	1
GMStatus_Cnt_M_u8[7]	1
GMStatus_Cnt_M_u8[8]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	1		
GMStatus_Cnt_M_u8[10]	1		
GMStatus_Cnt_M_u8[11]	1		
GMStatus_Cnt_M_u8[12]	1		
GMStatus_Cnt_M_u8[13]	1		
GMStatus_Cnt_M_u8[14]	1		
GMStatus_Cnt_M_u8[15]	1		
GMStatus_Cnt_M_u8[16]	1		
GMStatus_Cnt_M_u8[17]	1		
GMStatus_Cnt_M_u8[18]	1		
GMStatus_Cnt_M_u8[19]	1		
GMStatus_Cnt_M_u8[20]	1		
GMStatus_Cnt_M_u8[21]	1		
GMStatus_Cnt_M_u8[22]	1		
GMStatus_Cnt_M_u8[23]	1		
GMStatus_Cnt_M_u8[24]	1		
GMStatus_Cnt_M_u8[25]	1		
GMStatus_Cnt_M_u8[26]	1		
GMStatus_Cnt_M_u8[27]	1		
GMStatus_Cnt_M_u8[28]	1		
GMStatus_Cnt_M_u8[29]	1		
GMStatus_Cnt_M_u8[30]	1		
GMStatus_Cnt_M_u8[31]	1		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	89		
LKATrqOvrlDlvdRC_Cnt_M_u8	243		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventID_Cnt_M_u8	20		
LastReportedGMStatus_Cnt_M_u8	117		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	246152192		
Steering_Torque_Overlay_Stat_CE_c[0]	24		
Steering_Torque_Overlay_Stat_CE_c[1]	28		
Steering_Torque_Overlay_Stat_CE_c[2]	32		
Steering_Torque_Overlay_Stat_CE_c[3]	36		
Steering_Torque_Overlay_Stat_CE_c[4]	40		
Steering_Torque_Overlay_Stat_CE_c[5]	44		
Steering_Torque_Overlay_Stat_CE_c[6]	48		
Steering_Torque_Overlay_Stat_CE_c[7]	52		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.99000001		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	69		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	25		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	14508		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2917655040		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	6.90000001		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.3499999994		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-6.579999992		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	0.300000012		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	6	6	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	20	20	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	159	159	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	14	14	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	1	1	✓
GMStatus_Cnt_M_u8[2]	1	1	✓
GMStatus_Cnt_M_u8[3]	1	1	✓
GMStatus_Cnt_M_u8[4]	1	1	✓
GMStatus_Cnt_M_u8[5]	1	1	✓
GMStatus_Cnt_M_u8[6]	1	1	✓
GMStatus_Cnt_M_u8[7]	1	1	✓
GMStatus_Cnt_M_u8[8]	1	1	✓
GMStatus_Cnt_M_u8[9]	1	1	✓
GMStatus_Cnt_M_u8[10]	1	1	✓
GMStatus_Cnt_M_u8[11]	1	1	✓
GMStatus_Cnt_M_u8[12]	1	1	✓
GMStatus_Cnt_M_u8[13]	1	1	✓
GMStatus_Cnt_M_u8[14]	1	1	✓
GMStatus_Cnt_M_u8[15]	1	1	✓
GMStatus_Cnt_M_u8[16]	1	1	✓
GMStatus_Cnt_M_u8[17]	1	1	✓
GMStatus_Cnt_M_u8[18]	1	1	✓
GMStatus_Cnt_M_u8[19]	1	1	✓
GMStatus_Cnt_M_u8[20]	1	1	✓
GMStatus_Cnt_M_u8[21]	1	1	✓
GMStatus_Cnt_M_u8[22]	1	1	✓
GMStatus_Cnt_M_u8[23]	1	1	✓
GMStatus_Cnt_M_u8[24]	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	1	1	✓
GMStatus_Cnt_M_u8[26]	1	1	✓
GMStatus_Cnt_M_u8[27]	1	1	✓
GMStatus_Cnt_M_u8[28]	1	1	✓
GMStatus_Cnt_M_u8[29]	1	1	✓
GMStatus_Cnt_M_u8[30]	1	1	✓
GMStatus_Cnt_M_u8[31]	1	1	✓
LKATrqOvriDlvdRC_Cnt_M_u8	243	243	✓
LastReportedDTCEventID_Cnt_M_u8	20	20	✓
LastReportedGMStatus_Cnt_M_u8	117	117	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	246152192	246152192	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.62 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	32
CTCEventId_Cnt_M_u8	22
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSorce	14
DTCDData.DTCNumber	37411
DTCDData.DTCFailType	17
DTCDData.DTCWmIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaultype	17
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	12
GMStatus_Cnt_M_u8[0]	147
GMStatus_Cnt_M_u8[1]	147
GMStatus_Cnt_M_u8[2]	147
GMStatus_Cnt_M_u8[3]	147
GMStatus_Cnt_M_u8[4]	147
GMStatus_Cnt_M_u8[5]	147
GMStatus_Cnt_M_u8[6]	147
GMStatus_Cnt_M_u8[7]	147
GMStatus_Cnt_M_u8[8]	147
GMStatus_Cnt_M_u8[9]	147
GMStatus_Cnt_M_u8[10]	147

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[11]	147		
GMStatus_Cnt_M_u8[12]	147		
GMStatus_Cnt_M_u8[13]	147		
GMStatus_Cnt_M_u8[14]	147		
GMStatus_Cnt_M_u8[15]	147		
GMStatus_Cnt_M_u8[16]	147		
GMStatus_Cnt_M_u8[17]	147		
GMStatus_Cnt_M_u8[18]	147		
GMStatus_Cnt_M_u8[19]	147		
GMStatus_Cnt_M_u8[20]	147		
GMStatus_Cnt_M_u8[21]	147		
GMStatus_Cnt_M_u8[22]	147		
GMStatus_Cnt_M_u8[23]	147		
GMStatus_Cnt_M_u8[24]	147		
GMStatus_Cnt_M_u8[25]	147		
GMStatus_Cnt_M_u8[26]	147		
GMStatus_Cnt_M_u8[27]	147		
GMStatus_Cnt_M_u8[28]	147		
GMStatus_Cnt_M_u8[29]	147		
GMStatus_Cnt_M_u8[30]	147		
GMStatus_Cnt_M_u8[31]	147		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	184		
LKATrqOvrldDlvdRC_Cnt_M_u8	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	42		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	54		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	66		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	78		
LastReportedDTCEventID_Cnt_M_u8	7		
LastReportedGMStatus_Cnt_M_u8	119		
PrevWarningIndSignal_Cnt_M_u8[0]	1		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	1384828672		
Steering_Torque_Overlay_Stat_CE_c[0]	36		
Steering_Torque_Overlay_Stat_CE_c[1]	42		
Steering_Torque_Overlay_Stat_CE_c[2]	48		
Steering_Torque_Overlay_Stat_CE_c[3]	54		
Steering_Torque_Overlay_Stat_CE_c[4]	60		
Steering_Torque_Overlay_Stat_CE_c[5]	66		
Steering_Torque_Overlay_Stat_CE_c[6]	72		
Steering_Torque_Overlay_Stat_CE_c[7]	78		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.0199999996		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	70		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	17		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	37610		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2884574464		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	7		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.400000006		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	3.5		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.63999999		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	22	22	✓
CTCEventId_Cnt_M_u8	22	22	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCDData.DTCTTriggered	1	1	✓
DTCDData.DTCSrcSource	49	49	✓
DTCDData.DTCNNumber	2	2	✓
DTCDData.DTCFaiType	148	148	✓
DTCDData.DTCWmIndRqdSt	1	1	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	13	13	✓
GMStatus_Cnt_M_u8[0]	147	147	✓
GMStatus_Cnt_M_u8[1]	147	147	✓
GMStatus_Cnt_M_u8[2]	147	147	✓
GMStatus_Cnt_M_u8[3]	147	147	✓
GMStatus_Cnt_M_u8[4]	147	147	✓
GMStatus_Cnt_M_u8[5]	147	147	✓
GMStatus_Cnt_M_u8[6]	147	147	✓
GMStatus_Cnt_M_u8[7]	147	147	✓
GMStatus_Cnt_M_u8[8]	147	147	✓
GMStatus_Cnt_M_u8[9]	147	147	✓
GMStatus_Cnt_M_u8[10]	147	147	✓
GMStatus_Cnt_M_u8[11]	147	147	✓
GMStatus_Cnt_M_u8[12]	147	147	✓
GMStatus_Cnt_M_u8[13]	147	147	✓
GMStatus_Cnt_M_u8[14]	147	147	✓
GMStatus_Cnt_M_u8[15]	147	147	✓
GMStatus_Cnt_M_u8[16]	147	147	✓
GMStatus_Cnt_M_u8[17]	147	147	✓
GMStatus_Cnt_M_u8[18]	147	147	✓
GMStatus_Cnt_M_u8[19]	147	147	✓
GMStatus_Cnt_M_u8[20]	147	147	✓
GMStatus_Cnt_M_u8[21]	147	147	✓
GMStatus_Cnt_M_u8[22]	147	147	✓
GMStatus_Cnt_M_u8[23]	147	147	✓
GMStatus_Cnt_M_u8[24]	147	147	✓
GMStatus_Cnt_M_u8[25]	147	147	✓
GMStatus_Cnt_M_u8[26]	147	147	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[27]	147	147	✓
GMStatus_Cnt_M_u8[28]	147	147	✓
GMStatus_Cnt_M_u8[29]	147	147	✓
GMStatus_Cnt_M_u8[30]	147	147	✓
GMStatus_Cnt_M_u8[31]	147	147	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	7	7	✓
LastReportedGMStatus_Cnt_M_u8	119	119	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2884574464	2884574464	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMtd	1	IIPutTxHndsOffStrWhIDtMtd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSources_778	1	IIPutTxDTCl_DTCSources_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.63 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	11
CTCEventId_Cnt_M_u8	3
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCSrc	17
DTCDData.DTCNumber	7872
DTCDData.DTCFailType	119
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	100
DTCTriggeredFlag_Cnt_M_Igc[0]	1
DTCTriggeredFlag_Cnt_M_Igc[1]	0
DTCTriggeredFlag_Cnt_M_Igc[2]	1
DTCTriggeredFlag_Cnt_M_Igc[3]	0
DTCTriggeredFlag_Cnt_M_Igc[4]	1
DTCTriggeredFlag_Cnt_M_Igc[5]	1
DTCTriggeredFlag_Cnt_M_Igc[6]	1
DTCTriggeredFlag_Cnt_M_Igc[7]	0
DTCTriggeredFlag_Cnt_M_Igc[8]	1
DTCTriggeredFlag_Cnt_M_Igc[9]	0
DTCTriggeredFlag_Cnt_M_Igc[10]	1
DTCTriggeredFlag_Cnt_M_Igc[11]	0
DTCTriggeredFlag_Cnt_M_Igc[12]	1
DTCTriggeredFlag_Cnt_M_Igc[13]	0
DTCTriggeredFlag_Cnt_M_Igc[14]	1
DTCTriggeredFlag_Cnt_M_Igc[15]	0
DTCTriggeredFlag_Cnt_M_Igc[16]	1
DTCTriggeredFlag_Cnt_M_Igc[17]	1
DTCTriggeredFlag_Cnt_M_Igc[18]	1
DTCTriggeredFlag_Cnt_M_Igc[19]	0
DTCTriggeredFlag_Cnt_M_Igc[20]	0
DTCTriggeredFlag_Cnt_M_Igc[21]	1
DTCTriggeredFlag_Cnt_M_Igc[22]	0
DTCTriggeredFlag_Cnt_M_Igc[23]	1
DTCTriggeredFlag_Cnt_M_Igc[24]	1
DTCTriggeredFlag_Cnt_M_Igc[25]	1
DTCTriggeredFlag_Cnt_M_Igc[26]	0
DTCTriggeredFlag_Cnt_M_Igc[27]	1
DTCTriggeredFlag_Cnt_M_Igc[28]	0
DTCTriggeredFlag_Cnt_M_Igc[29]	1
DTCTriggeredFlag_Cnt_M_Igc[30]	1
DTCTriggeredFlag_Cnt_M_Igc[31]	0
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	70
LKATrqOvrIDlvdRC_Cnt_M_u8	128
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	121
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	1039816192
Steering_Torque_Overlay_Stat_CE_c[0]	48
Steering_Torque_Overlay_Stat_CE_c[1]	56
Steering_Torque_Overlay_Stat_CE_c[2]	64
Steering_Torque_Overlay_Stat_CE_c[3]	72
Steering_Torque_Overlay_Stat_CE_c[4]	80
Steering_Torque_Overlay_Stat_CE_c[5]	88
Steering_Torque_Overlay_Stat_CE_c[6]	96
Steering_Torque_Overlay_Stat_CE_c[7]	104
k_LKAMfgEnable_Cnt_lgc	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_MaxHOWEstimate_Uls_f32	0.0399999991		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	71		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	49595		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3968166912		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	7.09999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.439999998		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-1.38		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.35000002		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	11	11	✓
CTCEventId_Cnt_M_u8	4	4	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	3	3	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvriDlvdRC_Cnt_M_u8	129	129	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	121	121	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1039816192	1039816192	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.64 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	21
CTCEventId_Cnt_M_u8	6
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	20
DTCDData.DTCNumber	17797
DTCDData.DTCFailType	25
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	235
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	4
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	40		
GMStatus_Cnt_M_u8[10]	44		
GMStatus_Cnt_M_u8[11]	48		
GMStatus_Cnt_M_u8[12]	52		
GMStatus_Cnt_M_u8[13]	56		
GMStatus_Cnt_M_u8[14]	60		
GMStatus_Cnt_M_u8[15]	64		
GMStatus_Cnt_M_u8[16]	68		
GMStatus_Cnt_M_u8[17]	72		
GMStatus_Cnt_M_u8[18]	76		
GMStatus_Cnt_M_u8[19]	80		
GMStatus_Cnt_M_u8[20]	84		
GMStatus_Cnt_M_u8[21]	88		
GMStatus_Cnt_M_u8[22]	92		
GMStatus_Cnt_M_u8[23]	96		
GMStatus_Cnt_M_u8[24]	100		
GMStatus_Cnt_M_u8[25]	104		
GMStatus_Cnt_M_u8[26]	108		
GMStatus_Cnt_M_u8[27]	112		
GMStatus_Cnt_M_u8[28]	116		
GMStatus_Cnt_M_u8[29]	120		
GMStatus_Cnt_M_u8[30]	124		
GMStatus_Cnt_M_u8[31]	128		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	136		
LKATrqOvrldlvdRC_Cnt_M_u8	189		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130		
LastReportedDTCEventID_Cnt_M_u8	14		
LastReportedGMStatus_Cnt_M_u8	123		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2257043712		
Steering_Torque_Overlay_Stat_CE_c[0]	60		
Steering_Torque_Overlay_Stat_CE_c[1]	70		
Steering_Torque_Overlay_Stat_CE_c[2]	80		
Steering_Torque_Overlay_Stat_CE_c[3]	90		
Steering_Torque_Overlay_Stat_CE_c[4]	100		
Steering_Torque_Overlay_Stat_CE_c[5]	110		
Steering_Torque_Overlay_Stat_CE_c[6]	120		
Steering_Torque_Overlay_Stat_CE_c[7]	130		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.0599999987		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	72		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	235		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	44197		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	717127424		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	7.19999981		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.200000003		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-1.33000004		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	2.83999991		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	21	21	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	7	7	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTTriggered	0	0	✓
DTCDData.DTCSSource	49	49	✓
DTCDData.DTCNumber	5	5	✓
DTCDData.DTCFailType	220	220	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	5	5	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDlvdRC_Cnt_M_u8	189	189	✓
LastReportedDTCEventID_Cnt_M_u8	14	14	✓
LastReportedGMStatus_Cnt_M_u8	123	123	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2257043712	2257043712	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrcSource_778	1	IIPutTxDTCl_DTCSrcSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.65 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	21
CTCEventId_Cnt_M_u8	10
CurrentDTCSThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	23
DTCDData.DTCNumber	56162
DTCDData.DTCFailType	168
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	64
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	1
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	44		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	46		
LKATrqOvrldDlvdRC_Cnt_M_u8	186		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156		
LastReportedDTCEventID_Cnt_M_u8	21		
LastReportedGMStatus_Cnt_M_u8	125		
PrevWarningIndSignal_Cnt_M_u8[0]	1		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	4232806400		
Steering_Torque_Overlay_Stat_CE_c[0]	72		
Steering_Torque_Overlay_Stat_CE_c[1]	84		
Steering_Torque_Overlay_Stat_CE_c[2]	96		
Steering_Torque_Overlay_Stat_CE_c[3]	108		
Steering_Torque_Overlay_Stat_CE_c[4]	120		
Steering_Torque_Overlay_Stat_CE_c[5]	132		
Steering_Torque_Overlay_Stat_CE_c[6]	144		
Steering_Torque_Overlay_Stat_CE_c[7]	156		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.0799999982		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	73		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	64		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	62931		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1612662272		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	7.30000019		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.400000006		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	4.9000001		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.24000001		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	21	21	✓
CTCEventId_Cnt_M_u8	11	11	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSrcSource	49	49	✓
DTCDData.DTCNNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	2	2	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	187	187	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	125	125	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4232806400	4232806400	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WmIndRqdSt_778	1	IIPutTxDTCl_WmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.66 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	27
CTCEventId_Cnt_M_u8	0
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	26

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCDData.DTCNumber	43848
DTCDData.DTCFailType	199
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	51
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	3
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	105
LKATrqOvrDivdRC_Cnt_M_u8	216
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	0
LastReportedGMStatus_Cnt_M_u8	127
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	1555841792
Steering_Torque_Overlay_Stat_CE_c[0]	84
Steering_Torque_Overlay_Stat_CE_c[1]	98
Steering_Torque_Overlay_Stat_CE_c[2]	112
Steering_Torque_Overlay_Stat_CE_c[3]	126
Steering_Torque_Overlay_Stat_CE_c[4]	140
Steering_Torque_Overlay_Stat_CE_c[5]	154
Steering_Torque_Overlay_Stat_CE_c[6]	168
Steering_Torque_Overlay_Stat_CE_c[7]	182
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.100000001

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	74		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	51		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	44165		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	534311168		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	7.4000001		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.200000003		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-3.0999999		
target_Rte_Read_Ap_SrlComOutput_LKAState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	3		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	27	27	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	0	0	✔
DTCDData.DTCFailType	220	220	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	1	1	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	4	4	✔
GMStatus_Cnt_M_u8[0]	1	1	✔
GMStatus_Cnt_M_u8[1]	2	2	✔
GMStatus_Cnt_M_u8[2]	3	3	✔
GMStatus_Cnt_M_u8[3]	4	4	✔
GMStatus_Cnt_M_u8[4]	5	5	✔
GMStatus_Cnt_M_u8[5]	6	6	✔
GMStatus_Cnt_M_u8[6]	7	7	✔
GMStatus_Cnt_M_u8[7]	8	8	✔
GMStatus_Cnt_M_u8[8]	9	9	✔
GMStatus_Cnt_M_u8[9]	10	10	✔
GMStatus_Cnt_M_u8[10]	11	11	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvriDlvdRC_Cnt_M_u8	217	217	✓
LastReportedDTCEventID_Cnt_M_u8	0	0	✓
LastReportedGMStatus_Cnt_M_u8	127	127	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1555841792	1555841792	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrItqDStat	1	IIPutTxTrqOvrItqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtmD	1	IIPutTxHndsOffStrWhlDtmD	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrItqDStat	1	IIPutTxLKATrqOvrItqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.67 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	35
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_Igc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	49
DTCDData.DTCNumber	65535
DTCDData.DTCFailType	255
DTCDData.DTCWrnIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	255
DTCTriggeredFlag_Cnt_M_Igc[0]	1
DTCTriggeredFlag_Cnt_M_Igc[1]	1
DTCTriggeredFlag_Cnt_M_Igc[2]	1
DTCTriggeredFlag_Cnt_M_Igc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	4294967295
DemDTCNum_Cnt_M_u32[1]	4294967295
DemDTCNum_Cnt_M_u32[2]	4294967295
DemDTCNum_Cnt_M_u32[3]	4294967295
DemDTCNum_Cnt_M_u32[4]	4294967295
DemDTCNum_Cnt_M_u32[5]	4294967295
DemDTCNum_Cnt_M_u32[6]	4294967295
DemDTCNum_Cnt_M_u32[7]	4294967295
DemDTCNum_Cnt_M_u32[8]	4294967295
DemDTCNum_Cnt_M_u32[9]	4294967295
DemDTCNum_Cnt_M_u32[10]	4294967295
DemDTCNum_Cnt_M_u32[11]	4294967295
DemDTCNum_Cnt_M_u32[12]	4294967295
DemDTCNum_Cnt_M_u32[13]	4294967295
DemDTCNum_Cnt_M_u32[14]	4294967295
DemDTCNum_Cnt_M_u32[15]	4294967295
DemDTCNum_Cnt_M_u32[16]	4294967295
DemDTCNum_Cnt_M_u32[17]	4294967295
DemDTCNum_Cnt_M_u32[18]	4294967295
DemDTCNum_Cnt_M_u32[19]	4294967295
DemDTCNum_Cnt_M_u32[20]	4294967295
DemDTCNum_Cnt_M_u32[21]	4294967295
DemDTCNum_Cnt_M_u32[22]	4294967295
DemDTCNum_Cnt_M_u32[23]	4294967295
DemDTCNum_Cnt_M_u32[24]	4294967295
DemDTCNum_Cnt_M_u32[25]	4294967295
DemDTCNum_Cnt_M_u32[26]	4294967295
DemDTCNum_Cnt_M_u32[27]	4294967295
DemDTCNum_Cnt_M_u32[28]	4294967295
DemDTCNum_Cnt_M_u32[29]	4294967295
DemDTCNum_Cnt_M_u32[30]	4294967295
DemDTCNum_Cnt_M_u32[31]	4294967295
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	15
GMStatus_Cnt_M_u8[0]	147
GMStatus_Cnt_M_u8[1]	147
GMStatus_Cnt_M_u8[2]	147
GMStatus_Cnt_M_u8[3]	147
GMStatus_Cnt_M_u8[4]	147
GMStatus_Cnt_M_u8[5]	147
GMStatus_Cnt_M_u8[6]	147
GMStatus_Cnt_M_u8[7]	147
GMStatus_Cnt_M_u8[8]	147
GMStatus_Cnt_M_u8[9]	147

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	147		
GMStatus_Cnt_M_u8[11]	147		
GMStatus_Cnt_M_u8[12]	147		
GMStatus_Cnt_M_u8[13]	147		
GMStatus_Cnt_M_u8[14]	147		
GMStatus_Cnt_M_u8[15]	147		
GMStatus_Cnt_M_u8[16]	147		
GMStatus_Cnt_M_u8[17]	147		
GMStatus_Cnt_M_u8[18]	147		
GMStatus_Cnt_M_u8[19]	147		
GMStatus_Cnt_M_u8[20]	147		
GMStatus_Cnt_M_u8[21]	147		
GMStatus_Cnt_M_u8[22]	147		
GMStatus_Cnt_M_u8[23]	147		
GMStatus_Cnt_M_u8[24]	147		
GMStatus_Cnt_M_u8[25]	147		
GMStatus_Cnt_M_u8[26]	147		
GMStatus_Cnt_M_u8[27]	147		
GMStatus_Cnt_M_u8[28]	147		
GMStatus_Cnt_M_u8[29]	147		
GMStatus_Cnt_M_u8[30]	147		
GMStatus_Cnt_M_u8[31]	147		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	255		
LKATrqOvrldlvdRC_Cnt_M_u8	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	255		
LastReportedDTCEventID_Cnt_M_u8	35		
LastReportedGMStatus_Cnt_M_u8	147		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	4294967295		
Steering_Torque_Overlay_Stat_CE_c[0]	255		
Steering_Torque_Overlay_Stat_CE_c[1]	255		
Steering_Torque_Overlay_Stat_CE_c[2]	255		
Steering_Torque_Overlay_Stat_CE_c[3]	255		
Steering_Torque_Overlay_Stat_CE_c[4]	255		
Steering_Torque_Overlay_Stat_CE_c[5]	255		
Steering_Torque_Overlay_Stat_CE_c[6]	255		
Steering_Torque_Overlay_Stat_CE_c[7]	255		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	1		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	255		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	255		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	65535		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	4294967295		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	10.2299995		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	1		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	3		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	35	35	✔
CTCEventId Cnt M u8	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	65535	65535	✓
DTCDData.DTCFailType	255	255	✓
DTCDData.DTCWmIndRqdSt	1	1	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	255	255	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	0	0	✓
GMStatus_Cnt_M_u8[0]	147	147	✓
GMStatus_Cnt_M_u8[1]	147	147	✓
GMStatus_Cnt_M_u8[2]	147	147	✓
GMStatus_Cnt_M_u8[3]	147	147	✓
GMStatus_Cnt_M_u8[4]	147	147	✓
GMStatus_Cnt_M_u8[5]	147	147	✓
GMStatus_Cnt_M_u8[6]	147	147	✓
GMStatus_Cnt_M_u8[7]	147	147	✓
GMStatus_Cnt_M_u8[8]	147	147	✓
GMStatus_Cnt_M_u8[9]	147	147	✓
GMStatus_Cnt_M_u8[10]	147	147	✓
GMStatus_Cnt_M_u8[11]	147	147	✓
GMStatus_Cnt_M_u8[12]	147	147	✓
GMStatus_Cnt_M_u8[13]	147	147	✓
GMStatus_Cnt_M_u8[14]	147	147	✓
GMStatus_Cnt_M_u8[15]	147	147	✓
GMStatus_Cnt_M_u8[16]	147	147	✓
GMStatus_Cnt_M_u8[17]	147	147	✓
GMStatus_Cnt_M_u8[18]	147	147	✓
GMStatus_Cnt_M_u8[19]	147	147	✓
GMStatus_Cnt_M_u8[20]	147	147	✓
GMStatus_Cnt_M_u8[21]	147	147	✓
GMStatus_Cnt_M_u8[22]	147	147	✓
GMStatus_Cnt_M_u8[23]	147	147	✓
GMStatus_Cnt_M_u8[24]	147	147	✓
GMStatus_Cnt_M_u8[25]	147	147	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	147	147	✓
GMStatus_Cnt_M_u8[27]	147	147	✓
GMStatus_Cnt_M_u8[28]	147	147	✓
GMStatus_Cnt_M_u8[29]	147	147	✓
GMStatus_Cnt_M_u8[30]	147	147	✓
GMStatus_Cnt_M_u8[31]	147	147	✓
LKATrqOvriDlvdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	35	35	✓
LastReportedGMStatus_Cnt_M_u8	147	147	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4294967295	4294967295	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrStTtTqDlvd	1	IIPutTxLKAEIPwrStTtTqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.68 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	24	
CTCEventId_Cnt_M_u8	15	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DTCTriggered	0	
DTCDData.DTCSOURCE	32	
DTCDData.DTCTNumber	37103	
DTCDData.DTCTFailType	2	
DTCDData.DTCTWrnIndRqdSt	1	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	0	
DTCDData.DTCTHistStat	0	
DTCDData.DTCTstFldCdClrdStat	0	
DTCDData.DTCTstNPsdCdClrdSt	0	
DTCDData.DTCTCurrentStatus	0	
DTCDData.DTCTCodeSupported	0	
DTCDData.DTCTFaulttype	132	
DTCTriggeredFlag_Cnt_M_lgc[0]	1	
DTCTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTriggeredFlag_Cnt_M_lgc[2]	1	
DTCTriggeredFlag_Cnt_M_lgc[3]	0	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	1	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	0	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	0	
DTCTriggeredFlag_Cnt_M_lgc[14]	1	
DTCTriggeredFlag_Cnt_M_lgc[15]	0	
DTCTriggeredFlag_Cnt_M_lgc[16]	1	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	0	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	226		
LKATrqOvrldvldRC_Cnt_M_u8	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26		
LastReportedDTCEventID_Cnt_M_u8	8		
LastReportedGMStatus_Cnt_M_u8	131		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	2036651264		
Steering_Torque_Overlay_Stat_CE_c[0]	12		
Steering_Torque_Overlay_Stat_CE_c[1]	14		
Steering_Torque_Overlay_Stat_CE_c[2]	16		
Steering_Torque_Overlay_Stat_CE_c[3]	18		
Steering_Torque_Overlay_Stat_CE_c[4]	20		
Steering_Torque_Overlay_Stat_CE_c[5]	22		
Steering_Torque_Overlay_Stat_CE_c[6]	24		
Steering_Torque_Overlay_Stat_CE_c[7]	26		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.140000001		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	76		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	132		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	1591		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3155620608		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	7.5999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.699999988		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-5.63999987		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	2.36999989		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	24	24	✔
CTCEventId_Cnt_M_u8	16	16	✔
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	3	3	✔
DTCDData.DTCFailType	132	132	✔
DTCDData.DTCWrmIndRqdSt	1	1	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdClrdStat	0	0	✔
DTCDData.DTCTstNPsdCdClrdSt	0	0	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvriDivdRC_Cnt_M_u8	96	96	✓
LastReportedDTCEventID_Cnt_M_u8	8	8	✓
LastReportedGMStatus_Cnt_M_u8	131	131	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	2036651264	2036651264	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSTtItqDlrd	1	IIPutTxElPwrSTtItqDlrd	1	✓
IIPutTxTrqOvrlTrqDStat	1	IIPutTxTrqOvrlTrqDStat	1	✓
IIPutTxTrqOvrlDvrdARC	1	IIPutTxTrqOvrlDvrdARC	1	✓
IIPutTxTrqOvrlDltTrqDlrd	1	IIPutTxTrqOvrlDltTrqDlrd	1	✓
IIPutTxTrqOvrlDChksm	1	IIPutTxTrqOvrlDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCCurrentStatus_778	1	IIPutTxDTCl_DTCCurrentStatus_778	1	✓
IIPutTxDTCl_DTCCodeSupported_778	1	IIPutTxDTCl_DTCCodeSupported_778	1	✓
IIPutTxDTCl_DTCCurrentStatus_778	1	IIPutTxDTCl_DTCCurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.69 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	27
CTCEventId_Cnt_M_u8	19
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	35
DTCDData.DTCCurrentStatus	15219
DTCDData.DTCCodeSupported	136
DTCDData.DTCCurrentStatus	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCCurrentStatus	72
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	10
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	202		
LKATrqOvrIDlvdRC_Cnt_M_u8	166		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventID_Cnt_M_u8	17		
LastReportedGMStatus_Cnt_M_u8	1		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCSFlag_mS_M_u32p0	2701411328		
Steering_Torque_Overlay_Stat_CE_c[0]	24		
Steering_Torque_Overlay_Stat_CE_c[1]	28		
Steering_Torque_Overlay_Stat_CE_c[2]	32		
Steering_Torque_Overlay_Stat_CE_c[3]	36		
Steering_Torque_Overlay_Stat_CE_c[4]	40		
Steering_Torque_Overlay_Stat_CE_c[5]	44		
Steering_Torque_Overlay_Stat_CE_c[6]	48		
Steering_Torque_Overlay_Stat_CE_c[7]	52		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.159999996		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	77		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	7275		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3471174144		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	7.69999981		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.689999998		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-6.09000015		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	27	27	✔
CTCEventId_Cnt_M_u8	20	20	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	1	1	✔
DTCDData.DTCFailType	114	114	✔
DTCDData.DTCWrnIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrUpSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	0	0	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	11	11	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	167	167	✓
LastReportedDTCEventID_Cnt_M_u8	17	17	✓
LastReportedGMStatus_Cnt_M_u8	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	2701411328	2701411328	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SriComOutput_Per1



Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.70 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	9
CTCEventId_Cnt_M_u8	20
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	38
DTCDData.DTCNumber	1061
DTCDData.DTCFailType	156
DTCDData.DTCWmIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	231
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	14
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	222
LKATrqOvrDivdRC_Cnt_M_u8	209
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	42
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	54
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	66
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	78
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	147
PrevWarningIndSignal_Cnt_M_u8[0]	1
PrevWarningIndSignal_Cnt_M_u8[1]	1
PrevWarningIndSignal_Cnt_M_u8[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	916584192
Steering_Torque_Overlay_Stat_CE_c[0]	36
Steering_Torque_Overlay_Stat_CE_c[1]	42
Steering_Torque_Overlay_Stat_CE_c[2]	48
Steering_Torque_Overlay_Stat_CE_c[3]	54
Steering_Torque_Overlay_Stat_CE_c[4]	60
Steering_Torque_Overlay_Stat_CE_c[5]	66
Steering_Torque_Overlay_Stat_CE_c[6]	72
Steering_Torque_Overlay_Stat_CE_c[7]	78
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.180000007
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	78
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	231
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	57036
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2870281472
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	7.80000019
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.400000006
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	2.25
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	0.970000029

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	9	9	✓
CTCEventId_Cnt_M_u8	21	21	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	2	*none*	✓
DTCDData.DTCFailType	68	*none*	✓
DTCDData.DTCWmIndRqdSt	1	1	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	15	15	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDvdRC_Cnt_M_u8	210	210	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	147	147	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	916584192	916584192	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDvrdRC	1	IIPutTxLKATrqOvrIDvrdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.71 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	19
CTCEventId_Cnt_M_u8	28

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
CurrentDTCSThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	41
DTCDData.DTCNNumber	16731
DTCDData.DTCFailType	221
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	56
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	11
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	231
LKATrqOvriDlvdRC_Cnt_M_u8	207
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104
LastReportedDTCEventID_Cnt_M_u8	25
LastReportedGMStatus_Cnt_M_u8	55
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCTFlag_mS_M_u32p0	1079303680
Steering_Torque_Overlay_Stat_CE_c[0]	48
Steering_Torque_Overlay_Stat_CE_c[1]	56
Steering_Torque_Overlay_Stat_CE_c[2]	64
Steering_Torque_Overlay_Stat_CE_c[3]	72
Steering_Torque_Overlay_Stat_CE_c[4]	80
Steering_Torque_Overlay_Stat_CE_c[5]	88
Steering_Torque_Overlay_Stat_CE_c[6]	96

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
Steering_Torque_Overlay_Stat_CE_c[7]	104		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.200000003		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	79		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	30900		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	1219736576		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	7.9000001		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.550000012		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-8.30000019		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	19	19	✓
CTCEventId_Cnt_M_u8	29	29	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	2	2	✓
DTCDData.DTCFailType	208	208	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrUpSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	12	12	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	207	207	✓
LastReportedDTCEventID_Cnt_M_u8	25	25	✓
LastReportedGMStatus_Cnt_M_u8	55	55	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1079303680	1079303680	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.72 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	18
CTCEventId_Cnt_M_u8	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
CurrentDTCSThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSrc	44
DTCDData.DTCNbr	62420
DTCDData.DTCFailType	80
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	237
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	5
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	57
LKATrqOvriDlvdRC_Cnt_M_u8	13
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130
LastReportedDTCEventID_Cnt_M_u8	8
LastReportedGMStatus_Cnt_M_u8	2
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKAState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	4086835456
Steering_Torque_Overlay_Stat_CE_c[0]	0
Steering_Torque_Overlay_Stat_CE_c[1]	0
Steering_Torque_Overlay_Stat_CE_c[2]	0
Steering_Torque_Overlay_Stat_CE_c[3]	0
Steering_Torque_Overlay_Stat_CE_c[4]	0
Steering_Torque_Overlay_Stat_CE_c[5]	0
Steering_Torque_Overlay_Stat_CE_c[6]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
Steering_Torque_Overlay_Stat_CE_c[7]	0		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.219999999		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	80		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	237		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	14296		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	2303960832		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	8		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.100000001		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-0.300000012		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	0.449999988		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	1	1	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	11	11	✔
DTCDData.DTCFailType	184	184	✔
DTCDData.DTCWmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	0	0	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[31]	0	0	✔
ESCRollCount_Cnt_M_u08	6	6	✔
GMStatus_Cnt_M_u8[0]	1	1	✔
GMStatus_Cnt_M_u8[1]	2	2	✔
GMStatus_Cnt_M_u8[2]	3	3	✔
GMStatus_Cnt_M_u8[3]	4	4	✔
GMStatus_Cnt_M_u8[4]	5	5	✔
GMStatus_Cnt_M_u8[5]	6	6	✔
GMStatus_Cnt_M_u8[6]	7	7	✔
GMStatus_Cnt_M_u8[7]	8	8	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	14	14	✓
LastReportedDTCEventID_Cnt_M_u8	8	8	✓
LastReportedGMStatus_Cnt_M_u8	2	2	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2303960832	2303960832	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.73 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	20
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	47
DTCDData.DTCNumber	3605
DTCDData.DTCFailType	71
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	70
DTCTriggeredFlag_Cnt_M_lgc[0]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	7
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	11
LKATrqOvrrDlvdRC_Cnt_M_u8	0
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	27
LastReportedGMStatus_Cnt_M_u8	4
PrevWarningIndSignal_Cnt_M_u8[0]	0
PrevWarningIndSignal_Cnt_M_u8[1]	1
PrevWarningIndSignal_Cnt_M_u8[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKAState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3636086784
Steering_Torque_Overlay_Stat_CE_c[0]	255
Steering_Torque_Overlay_Stat_CE_c[1]	255
Steering_Torque_Overlay_Stat_CE_c[2]	255
Steering_Torque_Overlay_Stat_CE_c[3]	255
Steering_Torque_Overlay_Stat_CE_c[4]	255
Steering_Torque_Overlay_Stat_CE_c[5]	255
Steering_Torque_Overlay_Stat_CE_c[6]	255
Steering_Torque_Overlay_Stat_CE_c[7]	255
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.239999995
k_SComTrqPosPol_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	81
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	70
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	50136
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1795149312
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	8.10000038
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.360000014
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	9.02000046
target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data	0
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	20	20	✓
CTCEventId_Cnt_M_u8	15	15	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	10	10	✓
DTCDData.DTCFailType	240	240	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	8	8	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvrIDvdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	27	27	✓
LastReportedGMStatus_Cnt_M_u8	4	4	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	3636086784	3636086784	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItITqDlrd	1	IIPutTxElPwrStItITqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.74 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	10
CTCEventId_Cnt_M_u8	2
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	1
DTCDData.DTCNumber	55886
DTCDData.DTCFailType	156
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	125
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	6
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	30		
GMStatus_Cnt_M_u8[10]	33		
GMStatus_Cnt_M_u8[11]	36		
GMStatus_Cnt_M_u8[12]	39		
GMStatus_Cnt_M_u8[13]	42		
GMStatus_Cnt_M_u8[14]	45		
GMStatus_Cnt_M_u8[15]	48		
GMStatus_Cnt_M_u8[16]	51		
GMStatus_Cnt_M_u8[17]	54		
GMStatus_Cnt_M_u8[18]	57		
GMStatus_Cnt_M_u8[19]	60		
GMStatus_Cnt_M_u8[20]	63		
GMStatus_Cnt_M_u8[21]	66		
GMStatus_Cnt_M_u8[22]	69		
GMStatus_Cnt_M_u8[23]	72		
GMStatus_Cnt_M_u8[24]	75		
GMStatus_Cnt_M_u8[25]	78		
GMStatus_Cnt_M_u8[26]	81		
GMStatus_Cnt_M_u8[27]	84		
GMStatus_Cnt_M_u8[28]	87		
GMStatus_Cnt_M_u8[29]	90		
GMStatus_Cnt_M_u8[30]	93		
GMStatus_Cnt_M_u8[31]	96		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	149		
LKATrqOvrlDlvdRC_Cnt_M_u8	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26		
LastReportedDTCEventID_Cnt_M_u8	19		
LastReportedGMStatus_Cnt_M_u8	6		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3700419328		
Steering_Torque_Overlay_Stat_CE_c[0]	12		
Steering_Torque_Overlay_Stat_CE_c[1]	14		
Steering_Torque_Overlay_Stat_CE_c[2]	16		
Steering_Torque_Overlay_Stat_CE_c[3]	18		
Steering_Torque_Overlay_Stat_CE_c[4]	20		
Steering_Torque_Overlay_Stat_CE_c[5]	22		
Steering_Torque_Overlay_Stat_CE_c[6]	24		
Steering_Torque_Overlay_Stat_CE_c[7]	26		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.25999999		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	82		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	125		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	29588		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	190273792		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	8.19999981		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.819999993		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-4.51000023		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-2.52999997		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	10	10	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	3	3	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	144	144	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	7	7	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvriDlvdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	19	19	✓
LastReportedGMStatus_Cnt_M_u8	6	6	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3700419328	3700419328	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcldIO	1	IIPutTxStrngAsstRdcldIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItItqDlrd	1	IIPutTxElPwrStItItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDltSt	1	IIPutTxHndsOffStrWhlDltSt	1	✓
IIPutTxHndsOffStrWhlDltMd	1	IIPutTxHndsOffStrWhlDltMd	1	✓
IIPutTxHndsOffStrWhlDltStV	1	IIPutTxHndsOffStrWhlDltStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrStItItqDlvd	1	IIPutTxLKAEIPwrStItItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDltStGroup	1	IIPutTxHndsOffStrWhlDltStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WmIndRqdSt_778	1	IIPutTxDTCl_WmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.75 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	4

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCDData.DTCNumber	35642
DTCDData.DTCFailType	93
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	240
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	104
LKATrqOvrDivdRC_Cnt_M_u8	63
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130
LastReportedDTCEventID_Cnt_M_u8	13
LastReportedGMStatus_Cnt_M_u8	8
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	2885878528
Steering_Torque_Overlay_Stat_CE_c[0]	60
Steering_Torque_Overlay_Stat_CE_c[1]	70
Steering_Torque_Overlay_Stat_CE_c[2]	80
Steering_Torque_Overlay_Stat_CE_c[3]	90
Steering_Torque_Overlay_Stat_CE_c[4]	100
Steering_Torque_Overlay_Stat_CE_c[5]	110
Steering_Torque_Overlay_Stat_CE_c[6]	120
Steering_Torque_Overlay_Stat_CE_c[7]	130
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.280000001

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	83		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	240		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	48500		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	380219648		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	8.30000019		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.400000006		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	6.48000002		
target_Rte_Read_Ap_SrlComOutput_LKAState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	2.29999995		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	14	14	✔
CTCEventId_Cnt_M_u8	14	14	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	1	1	✔
DTCDData.DTCFailType	69	69	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	10	10	✔
GMStatus_Cnt_M_u8[0]	1	1	✔
GMStatus_Cnt_M_u8[1]	2	2	✔
GMStatus_Cnt_M_u8[2]	3	3	✔
GMStatus_Cnt_M_u8[3]	4	4	✔
GMStatus_Cnt_M_u8[4]	5	5	✔
GMStatus_Cnt_M_u8[5]	6	6	✔
GMStatus_Cnt_M_u8[6]	7	7	✔
GMStatus_Cnt_M_u8[7]	8	8	✔
GMStatus_Cnt_M_u8[8]	9	9	✔
GMStatus_Cnt_M_u8[9]	10	10	✔
GMStatus_Cnt_M_u8[10]	11	11	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvriDvdrC_Cnt_M_u8	63	63	✓
LastReportedDTCEventID_Cnt_M_u8	13	13	✓
LastReportedGMStatus_Cnt_M_u8	8	8	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	380219648	380219648	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIdIO	1	IIPutTxStrngAsstRdcIdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItItqDlrd	1	IIPutTxElPwrStItItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvdrARC	1	IIPutTxTrqOvriDvdrARC	1	✓
IIPutTxTrqOvriDItTrqDlrd	1	IIPutTxTrqOvriDItTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSources_778	1	IIPutTxDTCl_DTCSources_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmlndRqdSt_778	1	IIPutTxDTCl_WrmlndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.76 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	19
CTCEventId_Cnt_M_u8	28
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCTData.DTCTriggered	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCSource	7
DTCDData.DTCNumber	4682
DTCDData.DTCFailType	117
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	139
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	13
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	11
LKATrqOvrIDlvdRC_Cnt_M_u8	105
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	23
LastReportedGMStatus_Cnt_M_u8	10
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	2204219904
Steering_Torque_Overlay_Stat_CE_c[0]	72
Steering_Torque_Overlay_Stat_CE_c[1]	84
Steering_Torque_Overlay_Stat_CE_c[2]	96
Steering_Torque_Overlay_Stat_CE_c[3]	108
Steering_Torque_Overlay_Stat_CE_c[4]	120
Steering_Torque_Overlay_Stat_CE_c[5]	132
Steering_Torque_Overlay_Stat_CE_c[6]	144
Steering_Torque_Overlay_Stat_CE_c[7]	156
k_LKAMfgEnable_Cnt_lgc	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_MaxHOWEstimate_Uls_f32	0.300000012		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	84		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	139		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	47598		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2141564928		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-9.69999981		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.5		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-2.04299998		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	19	19	✓
CTCEventId_Cnt_M_u8	29	29	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	14	14	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDlvdRC_Cnt_M_u8	106	106	✓
LastReportedDTCEventID_Cnt_M_u8	23	23	✓
LastReportedGMStatus_Cnt_M_u8	10	10	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2204219904	2204219904	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtmD	1	IIPutTxHndsOffStrWhlDtmD	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDltTrqDlvd	1	IIPutTxLKATrqOvrIDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCI_DTCTriggered_778	1	IIPutTxDTCI_DTCTriggered_778	1	✓
IIPutTxDTCI_DTCSOURCE_778	1	IIPutTxDTCI_DTCSOURCE_778	1	✓
IIPutTxDTCI_DTCNumber_778	1	IIPutTxDTCI_DTCNumber_778	1	✓
IIPutTxDTCI_DTCFailType_778	1	IIPutTxDTCI_DTCFailType_778	1	✓
IIPutTxDTCI_CodeSupported_778	1	IIPutTxDTCI_CodeSupported_778	1	✓
IIPutTxDTCI_CurrentStatus_778	1	IIPutTxDTCI_CurrentStatus_778	1	✓
IIPutTxDTCI_TstNPsdCdCldSt_778	1	IIPutTxDTCI_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCI_TstFldCdCldStat_778	1	IIPutTxDTCI_TstFldCdCldStat_778	1	✓
IIPutTxDTCI_HistStat_778	1	IIPutTxDTCI_HistStat_778	1	✓
IIPutTxDTCI_TstNPsdPwrUpSt_778	1	IIPutTxDTCI_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCI_TstFldPwrUpSt_778	1	IIPutTxDTCI_TstFldPwrUpSt_778	1	✓
IIPutTxDTCI_WrnIndRqdSt_778	1	IIPutTxDTCI_WrnIndRqdSt_778	1	✓
IIPutTxDTCI_DTCFaultType_778	1	IIPutTxDTCI_DTCFaultType_778	1	✓
IIPutTxDTCIInfo_778	1	IIPutTxDTCIInfo_778	1	✓

Test Step 2.77 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	10
DTCDData.DTCNumber	3704
DTCDData.DTCFailType	184
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	102
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	12
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	33		
GMStatus_Cnt_M_u8[11]	36		
GMStatus_Cnt_M_u8[12]	39		
GMStatus_Cnt_M_u8[13]	42		
GMStatus_Cnt_M_u8[14]	45		
GMStatus_Cnt_M_u8[15]	48		
GMStatus_Cnt_M_u8[16]	51		
GMStatus_Cnt_M_u8[17]	54		
GMStatus_Cnt_M_u8[18]	57		
GMStatus_Cnt_M_u8[19]	60		
GMStatus_Cnt_M_u8[20]	63		
GMStatus_Cnt_M_u8[21]	66		
GMStatus_Cnt_M_u8[22]	69		
GMStatus_Cnt_M_u8[23]	72		
GMStatus_Cnt_M_u8[24]	75		
GMStatus_Cnt_M_u8[25]	78		
GMStatus_Cnt_M_u8[26]	81		
GMStatus_Cnt_M_u8[27]	84		
GMStatus_Cnt_M_u8[28]	87		
GMStatus_Cnt_M_u8[29]	90		
GMStatus_Cnt_M_u8[30]	93		
GMStatus_Cnt_M_u8[31]	96		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	164		
LKATrqOvriDlvdRC_Cnt_M_u8	0		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182		
LastReportedDTCEventID_Cnt_M_u8	20		
LastReportedGMStatus_Cnt_M_u8	12		
PrevWarningIndSignal_Cnt_M_u8[0]	1		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	14783744		
Steering_Torque_Overlay_Stat_CE_c[0]	84		
Steering_Torque_Overlay_Stat_CE_c[1]	98		
Steering_Torque_Overlay_Stat_CE_c[2]	112		
Steering_Torque_Overlay_Stat_CE_c[3]	126		
Steering_Torque_Overlay_Stat_CE_c[4]	140		
Steering_Torque_Overlay_Stat_CE_c[5]	154		
Steering_Torque_Overlay_Stat_CE_c[6]	168		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.319999993		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	85		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	102		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	40092		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	929936128		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-9.5		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.0599999987		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-3.9000001		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-2.20000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	12	12	✓
CTCEventId_Cnt_M_u8	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	10	10	✓
DTCDData.DTCNNumber	3704	3704	✓
DTCDData.DTCFailType	184	184	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	102	102	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	13	13	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	3	3	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	3	3	✓
GMStatus_Cnt_M_u8[4]	3	3	✓
GMStatus_Cnt_M_u8[5]	3	3	✓
GMStatus_Cnt_M_u8[6]	3	3	✓
GMStatus_Cnt_M_u8[7]	3	3	✓
GMStatus_Cnt_M_u8[8]	3	3	✓
GMStatus_Cnt_M_u8[9]	3	3	✓
GMStatus_Cnt_M_u8[10]	3	3	✓
GMStatus_Cnt_M_u8[11]	3	3	✓
GMStatus_Cnt_M_u8[12]	3	3	✓
GMStatus_Cnt_M_u8[13]	3	3	✓
GMStatus_Cnt_M_u8[14]	3	3	✓
GMStatus_Cnt_M_u8[15]	3	3	✓
GMStatus_Cnt_M_u8[16]	3	3	✓
GMStatus_Cnt_M_u8[17]	3	3	✓
GMStatus_Cnt_M_u8[18]	3	3	✓
GMStatus_Cnt_M_u8[19]	3	3	✓
GMStatus_Cnt_M_u8[20]	3	3	✓
GMStatus_Cnt_M_u8[21]	3	3	✓
GMStatus_Cnt_M_u8[22]	3	3	✓
GMStatus_Cnt_M_u8[23]	3	3	✓
GMStatus_Cnt_M_u8[24]	3	3	✓
GMStatus_Cnt_M_u8[25]	3	3	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	3	3	✓
GMStatus_Cnt_M_u8[27]	3	3	✓
GMStatus_Cnt_M_u8[28]	3	3	✓
GMStatus_Cnt_M_u8[29]	3	3	✓
GMStatus_Cnt_M_u8[30]	3	3	✓
GMStatus_Cnt_M_u8[31]	3	3	✓
LKATrqOvriDlvdRC_Cnt_M_u8	1	1	✓
LastReportedDTCEventID_Cnt_M_u8	20	20	✓
LastReportedGMStatus_Cnt_M_u8	12	12	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	14783744	14783744	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrStTtTqDlvd	1	IIPutTxLKAEIPwrStTtTqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.78 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	7	
CTCEventId_Cnt_M_u8	9	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DTCTriggered	0	
DTCDData.DTCSOURCE	13	
DTCDData.DTCTNumber	54744	
DTCDData.DTCTFailType	65	
DTCDData.DTCTWrnIndRqdSt	0	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	0	
DTCDData.DTCTHistStat	1	
DTCDData.DTCTstFldCdClrdStat	1	
DTCDData.DTCTstNPsdCdClrdSt	1	
DTCDData.DTCTCurrentStatus	1	
DTCDData.DTCTCodeSupported	0	
DTCDData.DTCTFaulttype	67	
DTCTriggeredFlag_Cnt_M_lgc[0]	1	
DTCTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTriggeredFlag_Cnt_M_lgc[2]	1	
DTCTriggeredFlag_Cnt_M_lgc[3]	0	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	1	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	0	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	0	
DTCTriggeredFlag_Cnt_M_lgc[14]	1	
DTCTriggeredFlag_Cnt_M_lgc[15]	0	
DTCTriggeredFlag_Cnt_M_lgc[16]	1	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	0	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	97		
LKATrqOvrlDlvdRC_Cnt_M_u8	255		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventID_Cnt_M_u8	4		
LastReportedGMStatus_Cnt_M_u8	14		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3985507328		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.340000004		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	86		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	67		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	56381		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	669100544		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-9.30000019		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.0199999996		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	9.30000019		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	0.899999976		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	7	7	✔
CTCEventId_Cnt_M_u8	10	10	✔
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	29	29	✔
DTCDData.DTCFailType	76	76	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	3	3	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrDivdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	4	4	✓
LastReportedGMStatus_Cnt_M_u8	14	14	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	3985507328	3985507328	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTqV	1	IIPutTxLKADrvAppldTqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTq	1	IIPutTxLKADrvAppldTq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTqGroup	1	IIPutTxLKADrvAppldTqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCI_DTCTriggered_778	1	IIPutTxDTCI_DTCTriggered_778	1	✓
IIPutTxDTCI_DTCSource_778	1	IIPutTxDTCI_DTCSource_778	1	✓
IIPutTxDTCI_DTCNumber_778	1	IIPutTxDTCI_DTCNumber_778	1	✓
IIPutTxDTCI_DTCFailType_778	1	IIPutTxDTCI_DTCFailType_778	1	✓
IIPutTxDTCI_CodeSupported_778	1	IIPutTxDTCI_CodeSupported_778	1	✓
IIPutTxDTCI_CurrentStatus_778	1	IIPutTxDTCI_CurrentStatus_778	1	✓
IIPutTxDTCI_TstNPsdCdClrdSt_778	1	IIPutTxDTCI_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCI_TstFldCdClrdStat_778	1	IIPutTxDTCI_TstFldCdClrdStat_778	1	✓
IIPutTxDTCI_HistStat_778	1	IIPutTxDTCI_HistStat_778	1	✓
IIPutTxDTCI_TstNPsdPwrUpSt_778	1	IIPutTxDTCI_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCI_TstFldPwrUpSt_778	1	IIPutTxDTCI_TstFldPwrUpSt_778	1	✓
IIPutTxDTCI_WrnIndRqdSt_778	1	IIPutTxDTCI_WrnIndRqdSt_778	1	✓
IIPutTxDTCI_DTCFaultType_778	1	IIPutTxDTCI_DTCFaultType_778	1	✓
IIPutTxDTCTInfo_778	1	IIPutTxDTCTInfo_778	1	✓

Test Step 2.79 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	2
CTCEventId_Cnt_M_u8	18
CurrentDTCSThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	16
DTCDData.DTCNumber	46609
DTCDData.DTCFailType	42
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	9
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	4
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	20		
GMStatus_Cnt_M_u8[10]	22		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	44		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	96		
LKATrqOvrDlvdRC_Cnt_M_u8	195		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156		
LastReportedDTCEventID_Cnt_M_u8	31		
LastReportedGMStatus_Cnt_M_u8	16		
PrevWarningIndSignal_Cnt_M_u8[0]	0		
PrevWarningIndSignal_Cnt_M_u8[1]	0		
PrevWarningIndSignal_Cnt_M_u8[2]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3478930944		
Steering_Torque_Overlay_Stat_CE_c[0]	72		
Steering_Torque_Overlay_Stat_CE_c[1]	84		
Steering_Torque_Overlay_Stat_CE_c[2]	96		
Steering_Torque_Overlay_Stat_CE_c[3]	108		
Steering_Torque_Overlay_Stat_CE_c[4]	120		
Steering_Torque_Overlay_Stat_CE_c[5]	132		
Steering_Torque_Overlay_Stat_CE_c[6]	144		
Steering_Torque_Overlay_Stat_CE_c[7]	156		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.360000014		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	87		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	9		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	22783		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2357713920		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-9.10000038		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.0599999987		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	3.25999999		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	2	2	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	19	19	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	2	*none*	✓
DTCDData.DTCFailType	68	*none*	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaultype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	5	5	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	195	195	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	16	16	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3478930944	3478930944	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItTqDlrd	1	IIPutTxElPwrStItTqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.80 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	19
CTCEventId_Cnt_M_u8	13
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSorce	25
DTCDData.DTCNumber	32160
DTCDData.DTCFailType	122
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaultype	58
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	0
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	44		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	231		
LKATrqOvrldDlvdRC_Cnt_M_u8	77		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182		
LastReportedDTCEventID_Cnt_M_u8	7		
LastReportedGMStatus_Cnt_M_u8	22		
PrevWarningIndSignal_Cnt_M_u8[0]	1		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	283927808		
Steering_Torque_Overlay_Stat_CE_c[0]	84		
Steering_Torque_Overlay_Stat_CE_c[1]	98		
Steering_Torque_Overlay_Stat_CE_c[2]	112		
Steering_Torque_Overlay_Stat_CE_c[3]	126		
Steering_Torque_Overlay_Stat_CE_c[4]	140		
Steering_Torque_Overlay_Stat_CE_c[5]	154		
Steering_Torque_Overlay_Stat_CE_c[6]	168		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.419999987		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	88		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	38829		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	221381376		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-8.5		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.779999971		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-7.94000006		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	19	19	✓
CTCEventId_Cnt_M_u8	14	14	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSrc	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	220	220	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	1	1	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	78	78	✓
LastReportedDTCEventID_Cnt_M_u8	7	7	✓
LastReportedGMStatus_Cnt_M_u8	22	22	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	283927808	283927808	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcclIO	1	IIPutTxStrngAsstRdcclIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStTtITqDlrd	1	IIPutTxElPwrStTtITqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDlITrqDlrd	1	IIPutTxTrqOvriDlITrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKAState_State_enum	1	Rte_Read_Ap_SriComOutput_LKAState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrStTtITqDlvd	1	IIPutTxLKAEIPwrStTtITqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDlITrqDlvd	1	IIPutTxLKATrqOvriDlITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.81 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	24
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSource	28
DTCDData.DTCNumber	43937
DTCDData.DTCFailType	236

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	7
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	15
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	57
LKATrqOvriDlvdRC_Cnt_M_u8	240
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208
LastReportedDTCEventID_Cnt_M_u8	21
LastReportedGMStatus_Cnt_M_u8	24
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	749573120
Steering_Torque_Overlay_Stat_CE_c[0]	96
Steering_Torque_Overlay_Stat_CE_c[1]	112
Steering_Torque_Overlay_Stat_CE_c[2]	128
Steering_Torque_Overlay_Stat_CE_c[3]	144
Steering_Torque_Overlay_Stat_CE_c[4]	160
Steering_Torque_Overlay_Stat_CE_c[5]	176
Steering_Torque_Overlay_Stat_CE_c[6]	192
Steering_Torque_Overlay_Stat_CE_c[7]	208
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.439999998
k_SComTrqPosPol_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	89

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	62026		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3688151552		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-8.30000019		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.0209999997		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	1.77999997		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	0.980000019		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	14	14	✔
CTCEventId_Cnt_M_u8	14	14	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	1	1	✔
DTCDData.DTCFailType	244	244	✔
DTCDData.DTCWmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	0	0	✔
GMStatus_Cnt_M_u8[0]	2	2	✔
GMStatus_Cnt_M_u8[1]	4	4	✔
GMStatus_Cnt_M_u8[2]	6	6	✔
GMStatus_Cnt_M_u8[3]	8	8	✔
GMStatus_Cnt_M_u8[4]	10	10	✔
GMStatus_Cnt_M_u8[5]	12	12	✔
GMStatus_Cnt_M_u8[6]	14	14	✔
GMStatus_Cnt_M_u8[7]	16	16	✔
GMStatus_Cnt_M_u8[8]	18	18	✔
GMStatus_Cnt_M_u8[9]	20	20	✔
GMStatus_Cnt_M_u8[10]	22	22	✔
GMStatus_Cnt_M_u8[11]	24	24	✔
GMStatus_Cnt_M_u8[12]	26	26	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	241	241	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	24	24	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3688151552	3688151552	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrARC	1	IIPutTxTrqOvrIDvrARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.82 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	23
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	31
DTCDData.DTCNumber	892
DTCDData.DTCFailType	195
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	215
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	11
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	11
LKATrqOvrDlvdRC_Cnt_M_u8	138
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52
LastReportedDTCEventID_Cnt_M_u8	9
LastReportedGMStatus_Cnt_M_u8	26
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	4056460800
Steering_Torque_Overlay_Stat_CE_c[0]	24
Steering_Torque_Overlay_Stat_CE_c[1]	28
Steering_Torque_Overlay_Stat_CE_c[2]	32
Steering_Torque_Overlay_Stat_CE_c[3]	36
Steering_Torque_Overlay_Stat_CE_c[4]	40
Steering_Torque_Overlay_Stat_CE_c[5]	44
Steering_Torque_Overlay_Stat_CE_c[6]	48
Steering_Torque_Overlay_Stat_CE_c[7]	52
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.460000008
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	90
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	46606
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3248030720
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-8.10000038
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.0320000015
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	4.57999992
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	0
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.5

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	23	23	✓
CTCEventId_Cnt_M_u8	15	15	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	3	3	✓
DTCDData.DTCFailType	232	232	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	12	12	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDvdrRC_Cnt_M_u8	138	138	✓
LastReportedDTCEventID_Cnt_M_u8	9	9	✓
LastReportedGMStatus_Cnt_M_u8	26	26	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4056460800	4056460800	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIdIO	1	IIPutTxStrngAsstRdcIdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvdrARC	1	IIPutTxTrqOvriDvdrARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSources_778	1	IIPutTxDTCl_DTCSources_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.83 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	10
CTCEventId_Cnt_M_u8	2
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSources	34
DTCDData.DTCNumber	55886
DTCDData.DTCFailType	156
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaultType	125
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	11
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	149
LKATrqOvrDlvdRC_Cnt_M_u8	255
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26
LastReportedDTCEventID_Cnt_M_u8	19
LastReportedGMStatus_Cnt_M_u8	28
PrevWarningIndSignal_Cnt_M_u8[0]	1
PrevWarningIndSignal_Cnt_M_u8[1]	1
PrevWarningIndSignal_Cnt_M_u8[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	0
Steering_Torque_Overlay_Stat_CE_c[0]	12
Steering_Torque_Overlay_Stat_CE_c[1]	14
Steering_Torque_Overlay_Stat_CE_c[2]	16
Steering_Torque_Overlay_Stat_CE_c[3]	18
Steering_Torque_Overlay_Stat_CE_c[4]	20
Steering_Torque_Overlay_Stat_CE_c[5]	22
Steering_Torque_Overlay_Stat_CE_c[6]	24
Steering_Torque_Overlay_Stat_CE_c[7]	26
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.479999989
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	91
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	125
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	29588
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	190273792
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-7.9000001
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.200000003
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	9.10000038
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.58000004

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	10	10	✓
CTCEventId_Cnt_M_u8	3	3	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	144	144	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	12	12	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvrDlvdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	19	19	✓
LastReportedGMStatus_Cnt_M_u8	28	28	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	0	0	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTqDlrd	1	IIPutTxTrqOvrIDItTqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKAState_State_enum	1	Rte_Read_Ap_SriComOutput_LKAState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTqDlvd	1	IIPutTxLKATrqOvrIDItTqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.84 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	14

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
CurrentDTCSThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSOURCE	37
DTCDData.DTCNumber	35642
DTCDData.DTCFailType	93
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	240
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	5
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	104
LKATrqOvriDlvdRC_Cnt_M_u8	63
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130
LastReportedDTCEventID_Cnt_M_u8	13
LastReportedGMStatus_Cnt_M_u8	30
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCTFlag_mS_M_u32p0	4294967295
Steering_Torque_Overlay_Stat_CE_c[0]	60
Steering_Torque_Overlay_Stat_CE_c[1]	70
Steering_Torque_Overlay_Stat_CE_c[2]	80
Steering_Torque_Overlay_Stat_CE_c[3]	90
Steering_Torque_Overlay_Stat_CE_c[4]	100
Steering_Torque_Overlay_Stat_CE_c[5]	110
Steering_Torque_Overlay_Stat_CE_c[6]	120

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
Steering_Torque_Overlay_Stat_CE_c[7]	130		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.5		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	92		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	240		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	48500		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	380219648		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-7.69999981		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.0250000004		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	7.53000021		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	2.0999999		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	14	14	✔
CTCEventId_Cnt_M_u8	14	14	✔
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	1	1	✔
DTCDData.DTCFailType	69	69	✔
DTCDData.DTCWmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdClrdStat	1	1	✔
DTCDData.DTCTstNPsdCdClrdSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	6	6	✔
GMStatus_Cnt_M_u8[0]	1	1	✔
GMStatus_Cnt_M_u8[1]	2	2	✔
GMStatus_Cnt_M_u8[2]	3	3	✔
GMStatus_Cnt_M_u8[3]	4	4	✔
GMStatus_Cnt_M_u8[4]	5	5	✔
GMStatus_Cnt_M_u8[5]	6	6	✔
GMStatus_Cnt_M_u8[6]	7	7	✔
GMStatus_Cnt_M_u8[7]	8	8	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	64	64	✓
LastReportedDTCEventID_Cnt_M_u8	13	13	✓
LastReportedGMStatus_Cnt_M_u8	30	30	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	380219648	380219648	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCI_DTCTriggered_778	1	IIPutTxDTCI_DTCTriggered_778	1	✓
IIPutTxDTCI_DTCSOURCE_778	1	IIPutTxDTCI_DTCSOURCE_778	1	✓
IIPutTxDTCI_DTCNumber_778	1	IIPutTxDTCI_DTCNumber_778	1	✓
IIPutTxDTCI_DTCFailType_778	1	IIPutTxDTCI_DTCFailType_778	1	✓
IIPutTxDTCI_CodeSupported_778	1	IIPutTxDTCI_CodeSupported_778	1	✓
IIPutTxDTCI_CurrentStatus_778	1	IIPutTxDTCI_CurrentStatus_778	1	✓
IIPutTxDTCI_TstNPsdCdClrdSt_778	1	IIPutTxDTCI_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCI_TstFldCdClrdStat_778	1	IIPutTxDTCI_TstFldCdClrdStat_778	1	✓
IIPutTxDTCI_HistStat_778	1	IIPutTxDTCI_HistStat_778	1	✓
IIPutTxDTCI_TstNPsdPwrUpSt_778	1	IIPutTxDTCI_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCI_TstFldPwrUpSt_778	1	IIPutTxDTCI_TstFldPwrUpSt_778	1	✓
IIPutTxDTCI_WrnIndRqdSt_778	1	IIPutTxDTCI_WrnIndRqdSt_778	1	✓
IIPutTxDTCI_DTCFaultType_778	1	IIPutTxDTCI_DTCFaultType_778	1	✓
IIPutTxDTCTInfo_778	1	IIPutTxDTCTInfo_778	1	✓

Test Step 2.85 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	19
CTCEventId_Cnt_M_u8	28
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	40
DTCDData.DTCNumber	4682
DTCDData.DTCFailType	117
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaultType	139
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	7
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	40		
GMStatus_Cnt_M_u8[10]	44		
GMStatus_Cnt_M_u8[11]	48		
GMStatus_Cnt_M_u8[12]	52		
GMStatus_Cnt_M_u8[13]	56		
GMStatus_Cnt_M_u8[14]	60		
GMStatus_Cnt_M_u8[15]	64		
GMStatus_Cnt_M_u8[16]	68		
GMStatus_Cnt_M_u8[17]	72		
GMStatus_Cnt_M_u8[18]	76		
GMStatus_Cnt_M_u8[19]	80		
GMStatus_Cnt_M_u8[20]	84		
GMStatus_Cnt_M_u8[21]	88		
GMStatus_Cnt_M_u8[22]	92		
GMStatus_Cnt_M_u8[23]	96		
GMStatus_Cnt_M_u8[24]	100		
GMStatus_Cnt_M_u8[25]	104		
GMStatus_Cnt_M_u8[26]	108		
GMStatus_Cnt_M_u8[27]	112		
GMStatus_Cnt_M_u8[28]	116		
GMStatus_Cnt_M_u8[29]	120		
GMStatus_Cnt_M_u8[30]	124		
GMStatus_Cnt_M_u8[31]	128		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	11		
LKATrqOvrlDlvdRC_Cnt_M_u8	105		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156		
LastReportedDTCEventID_Cnt_M_u8	23		
LastReportedGMStatus_Cnt_M_u8	32		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3967127296		
Steering_Torque_Overlay_Stat_CE_c[0]	72		
Steering_Torque_Overlay_Stat_CE_c[1]	84		
Steering_Torque_Overlay_Stat_CE_c[2]	96		
Steering_Torque_Overlay_Stat_CE_c[3]	108		
Steering_Torque_Overlay_Stat_CE_c[4]	120		
Steering_Torque_Overlay_Stat_CE_c[5]	132		
Steering_Torque_Overlay_Stat_CE_c[6]	144		
Steering_Torque_Overlay_Stat_CE_c[7]	156		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.519999981		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	93		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	139		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	47598		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2141564928		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-7.5		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.449999988		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-9.52000046		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.08000004		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	19	19	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	29	29	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	8	8	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDlvdRC_Cnt_M_u8	106	106	✓
LastReportedDTCEventID_Cnt_M_u8	23	23	✓
LastReportedGMStatus_Cnt_M_u8	32	32	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3967127296	3967127296	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSTtITqDlrd	1	IIPutTxElPwrSTtITqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrSTtITqDlvd	1	IIPutTxLKAEIPwrSTtITqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrcSource_778	1	IIPutTxDTCl_DTCSrcSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnlndRqdSt_778	1	IIPutTxDTCl_WrnlndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.86 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	2
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTriggered	1
DTCDData.DTCSrcSource	1
DTCDData.DTCNumber	46609
DTCDData.DTCFailType	42
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	9
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	13
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	57
LKATrqOvrDlvdRC_Cnt_M_u8	195
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	38
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3478930944
Steering_Torque_Overlay_Stat_CE_c[0]	0
Steering_Torque_Overlay_Stat_CE_c[1]	0
Steering_Torque_Overlay_Stat_CE_c[2]	0
Steering_Torque_Overlay_Stat_CE_c[3]	0
Steering_Torque_Overlay_Stat_CE_c[4]	0
Steering_Torque_Overlay_Stat_CE_c[5]	0
Steering_Torque_Overlay_Stat_CE_c[6]	0
Steering_Torque_Overlay_Stat_CE_c[7]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.579999983		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	94		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	9		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	22783		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2357713920		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-6.9000001		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.660000026		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-0.899999976		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	0.310000002		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	2	2	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSorce	1	1	✓
DTCDData.DTCNumber	46609	46609	✓
DTCDData.DTCFailType	42	42	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	9	9	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	14	14	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	17	17	✓
GMStatus_Cnt_M_u8[2]	17	17	✓
GMStatus_Cnt_M_u8[3]	17	17	✓
GMStatus_Cnt_M_u8[4]	17	17	✓
GMStatus_Cnt_M_u8[5]	17	17	✓
GMStatus_Cnt_M_u8[6]	17	17	✓
GMStatus_Cnt_M_u8[7]	17	17	✓
GMStatus_Cnt_M_u8[8]	17	17	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[9]	17	17	✓
GMStatus_Cnt_M_u8[10]	17	17	✓
GMStatus_Cnt_M_u8[11]	17	17	✓
GMStatus_Cnt_M_u8[12]	17	17	✓
GMStatus_Cnt_M_u8[13]	17	17	✓
GMStatus_Cnt_M_u8[14]	17	17	✓
GMStatus_Cnt_M_u8[15]	17	17	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	17	17	✓
GMStatus_Cnt_M_u8[18]	17	17	✓
GMStatus_Cnt_M_u8[19]	17	17	✓
GMStatus_Cnt_M_u8[20]	17	17	✓
GMStatus_Cnt_M_u8[21]	17	17	✓
GMStatus_Cnt_M_u8[22]	17	17	✓
GMStatus_Cnt_M_u8[23]	17	17	✓
GMStatus_Cnt_M_u8[24]	17	17	✓
GMStatus_Cnt_M_u8[25]	17	17	✓
GMStatus_Cnt_M_u8[26]	17	17	✓
GMStatus_Cnt_M_u8[27]	17	17	✓
GMStatus_Cnt_M_u8[28]	17	17	✓
GMStatus_Cnt_M_u8[29]	17	17	✓
GMStatus_Cnt_M_u8[30]	17	17	✓
GMStatus_Cnt_M_u8[31]	17	17	✓
LKATrqOvrrDlvdRC_Cnt_M_u8	195	195	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	38	38	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3478930944	3478930944	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdCldSt_778	1	IIPutTxDTCL_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.87 (Repeat Count = 1)



Name	Input Value
CTCEventIdSV_Cnt_M_u8	17
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSorce	2
DTCDData.DTCNNumber	12114
DTCDData.DTCFailType	169
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	33
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	12
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	11
LKATrqOvriDlvdRC_Cnt_M_u8	248
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	15
LastReportedGMStatus_Cnt_M_u8	40
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	102887680		
Steering_Torque_Overlay_Stat_CE_c[0]	255		
Steering_Torque_Overlay_Stat_CE_c[1]	255		
Steering_Torque_Overlay_Stat_CE_c[2]	255		
Steering_Torque_Overlay_Stat_CE_c[3]	255		
Steering_Torque_Overlay_Stat_CE_c[4]	255		
Steering_Torque_Overlay_Stat_CE_c[5]	255		
Steering_Torque_Overlay_Stat_CE_c[6]	255		
Steering_Torque_Overlay_Stat_CE_c[7]	255		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.600000024		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	95		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	33		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	8857		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2692165376		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-6.69999981		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.300000012		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	4.23000002		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	17	17	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSThisIC_Cnt_M_Igc	0	0	✔
DTCData.DTCTriggered	1	1	✔
DTCData.DTCSource	2	2	✔
DTCData.DTCNumber	12114	12114	✔
DTCData.DTCFailType	169	169	✔
DTCData.DTCWmIndRqdSt	0	0	✔
DTCData.DTCTstFldPwrUpSt	1	1	✔
DTCData.DTCTstNPsdPwrupSt	0	0	✔
DTCData.DTCHistStat	1	1	✔
DTCData.DTCTstFldCdClrdStat	0	0	✔
DTCData.DTCTstNPsdCdClrdSt	1	1	✔
DTCData.DTCCurrentStatus	0	0	✔
DTCData.DTCCodeSupported	0	0	✔
DTCData.DTCFaulttype	33	33	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[17]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[20]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[21]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[22]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[23]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	13	13	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	19	19	✓
GMStatus_Cnt_M_u8[2]	19	19	✓
GMStatus_Cnt_M_u8[3]	19	19	✓
GMStatus_Cnt_M_u8[4]	19	19	✓
GMStatus_Cnt_M_u8[5]	19	19	✓
GMStatus_Cnt_M_u8[6]	19	19	✓
GMStatus_Cnt_M_u8[7]	19	19	✓
GMStatus_Cnt_M_u8[8]	19	19	✓
GMStatus_Cnt_M_u8[9]	19	19	✓
GMStatus_Cnt_M_u8[10]	19	19	✓
GMStatus_Cnt_M_u8[11]	19	19	✓
GMStatus_Cnt_M_u8[12]	19	19	✓
GMStatus_Cnt_M_u8[13]	19	19	✓
GMStatus_Cnt_M_u8[14]	19	19	✓
GMStatus_Cnt_M_u8[15]	19	19	✓
GMStatus_Cnt_M_u8[16]	19	19	✓
GMStatus_Cnt_M_u8[17]	19	19	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	19	19	✓
GMStatus_Cnt_M_u8[20]	19	19	✓
GMStatus_Cnt_M_u8[21]	19	19	✓
GMStatus_Cnt_M_u8[22]	19	19	✓
GMStatus_Cnt_M_u8[23]	19	19	✓
GMStatus_Cnt_M_u8[24]	19	19	✓
GMStatus_Cnt_M_u8[25]	19	19	✓
GMStatus_Cnt_M_u8[26]	19	19	✓
GMStatus_Cnt_M_u8[27]	19	19	✓
GMStatus_Cnt_M_u8[28]	19	19	✓
GMStatus_Cnt_M_u8[29]	19	19	✓
GMStatus_Cnt_M_u8[30]	19	19	✓
GMStatus_Cnt_M_u8[31]	19	19	✓
LKATrqOvrlDlvdRC_Cnt_M_u8	248	248	✓
LastReportedDTCEventID_Cnt_M_u8	15	15	✓
LastReportedGMStatus_Cnt_M_u8	40	40	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	102887680	102887680	✓



Test Step Call Trace



SrlComOutput Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.88 (Repeat Count = 1) ✓

Name	Input Value
CTCEventIdSV_Cnt_M_u8	17
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	3
DTCDData.DTCNumber	59730
DTCDData.DTCFailType	82
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	175
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	149
LKATrqOvrDivdRC_Cnt_M_u8	147
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	25
LastReportedGMStatus_Cnt_M_u8	42
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	952683008		
Steering_Torque_Overlay_Stat_CE_c[0]	12		
Steering_Torque_Overlay_Stat_CE_c[1]	14		
Steering_Torque_Overlay_Stat_CE_c[2]	16		
Steering_Torque_Overlay_Stat_CE_c[3]	18		
Steering_Torque_Overlay_Stat_CE_c[4]	20		
Steering_Torque_Overlay_Stat_CE_c[5]	22		
Steering_Torque_Overlay_Stat_CE_c[6]	24		
Steering_Torque_Overlay_Stat_CE_c[7]	26		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.620000005		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	96		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	175		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	40531		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3710140416		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	3.09999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.200000003		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	0.550000012		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	0.439999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	17	17	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	3	3	✓
DTCDData.DTCNumber	59730	59730	✓
DTCDData.DTCFailType	82	82	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrUpSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdClrdStat	0	0	✓
DTCDData.DTCTstNPsdCdClrdSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	175	175	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	3	3	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	1	1	✓
GMStatus_Cnt_M_u8[2]	1	1	✓
GMStatus_Cnt_M_u8[3]	1	1	✓
GMStatus_Cnt_M_u8[4]	1	1	✓
GMStatus_Cnt_M_u8[5]	1	1	✓
GMStatus_Cnt_M_u8[6]	1	1	✓
GMStatus_Cnt_M_u8[7]	1	1	✓
GMStatus_Cnt_M_u8[8]	1	1	✓
GMStatus_Cnt_M_u8[9]	1	1	✓
GMStatus_Cnt_M_u8[10]	1	1	✓
GMStatus_Cnt_M_u8[11]	1	1	✓
GMStatus_Cnt_M_u8[12]	1	1	✓
GMStatus_Cnt_M_u8[13]	1	1	✓
GMStatus_Cnt_M_u8[14]	1	1	✓
GMStatus_Cnt_M_u8[15]	1	1	✓
GMStatus_Cnt_M_u8[16]	1	1	✓
GMStatus_Cnt_M_u8[17]	1	1	✓
GMStatus_Cnt_M_u8[18]	1	1	✓
GMStatus_Cnt_M_u8[19]	1	1	✓
GMStatus_Cnt_M_u8[20]	1	1	✓
GMStatus_Cnt_M_u8[21]	1	1	✓
GMStatus_Cnt_M_u8[22]	1	1	✓
GMStatus_Cnt_M_u8[23]	1	1	✓
GMStatus_Cnt_M_u8[24]	1	1	✓
GMStatus_Cnt_M_u8[25]	1	1	✓
GMStatus_Cnt_M_u8[26]	1	1	✓
GMStatus_Cnt_M_u8[27]	1	1	✓
GMStatus_Cnt_M_u8[28]	1	1	✓
GMStatus_Cnt_M_u8[29]	1	1	✓
GMStatus_Cnt_M_u8[30]	1	1	✓
GMStatus_Cnt_M_u8[31]	1	1	✓
LKATrqOvrDivdRC_Cnt_M_u8	147	147	✓
LastReportedDTCEventID_Cnt_M_u8	25	25	✓
LastReportedGMStatus_Cnt_M_u8	42	42	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	952683008	952683008	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.89 (Repeat Count = 1) ✓

Name	Input Value
CTCEventIdSV_Cnt_M_u8	19
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	4
DTCDData.DTCNumber	32160
DTCDData.DTCFailType	122
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	58
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	4
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	194
LKATrqOvriDlvdRC_Cnt_M_u8	77
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	7
LastReportedGMStatus_Cnt_M_u8	44
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	283927808		
Steering_Torque_Overlay_Stat_CE_c[0]	84		
Steering_Torque_Overlay_Stat_CE_c[1]	98		
Steering_Torque_Overlay_Stat_CE_c[2]	112		
Steering_Torque_Overlay_Stat_CE_c[3]	126		
Steering_Torque_Overlay_Stat_CE_c[4]	140		
Steering_Torque_Overlay_Stat_CE_c[5]	154		
Steering_Torque_Overlay_Stat_CE_c[6]	168		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.639999986		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	0		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	58		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	38829		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	221381376		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	3.20000005		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.360000014		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	0.779999971		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-2.5999999		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	19	19	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSThisIC_Cnt_M_Igc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	4	4	✔
DTCDData.DTCNumber	32160	32160	✔
DTCDData.DTCFailType	122	122	✔
DTCDData.DTCWmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	0	0	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	58	58	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	5	5	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	1	1	✓
GMStatus_Cnt_M_u8[2]	1	1	✓
GMStatus_Cnt_M_u8[3]	1	1	✓
GMStatus_Cnt_M_u8[4]	1	1	✓
GMStatus_Cnt_M_u8[5]	1	1	✓
GMStatus_Cnt_M_u8[6]	1	1	✓
GMStatus_Cnt_M_u8[7]	1	1	✓
GMStatus_Cnt_M_u8[8]	1	1	✓
GMStatus_Cnt_M_u8[9]	1	1	✓
GMStatus_Cnt_M_u8[10]	1	1	✓
GMStatus_Cnt_M_u8[11]	1	1	✓
GMStatus_Cnt_M_u8[12]	1	1	✓
GMStatus_Cnt_M_u8[13]	1	1	✓
GMStatus_Cnt_M_u8[14]	1	1	✓
GMStatus_Cnt_M_u8[15]	1	1	✓
GMStatus_Cnt_M_u8[16]	1	1	✓
GMStatus_Cnt_M_u8[17]	1	1	✓
GMStatus_Cnt_M_u8[18]	1	1	✓
GMStatus_Cnt_M_u8[19]	1	1	✓
GMStatus_Cnt_M_u8[20]	1	1	✓
GMStatus_Cnt_M_u8[21]	1	1	✓
GMStatus_Cnt_M_u8[22]	1	1	✓
GMStatus_Cnt_M_u8[23]	1	1	✓
GMStatus_Cnt_M_u8[24]	1	1	✓
GMStatus_Cnt_M_u8[25]	1	1	✓
GMStatus_Cnt_M_u8[26]	1	1	✓
GMStatus_Cnt_M_u8[27]	1	1	✓
GMStatus_Cnt_M_u8[28]	1	1	✓
GMStatus_Cnt_M_u8[29]	1	1	✓
GMStatus_Cnt_M_u8[30]	1	1	✓
GMStatus_Cnt_M_u8[31]	1	1	✓
LKATrqOvrlDlvdRC_Cnt_M_u8	78	78	✓
LastReportedDTCEventID_Cnt_M_u8	7	7	✓
LastReportedGMStatus_Cnt_M_u8	44	44	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	283927808	283927808	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.90 (Repeat Count = 1)

Name	Input Value
CTCEventIdSV_Cnt_M_u8	24
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSource	5
DTCDData.DTCNumber	43937
DTCDData.DTCFailType	236
DTCDData.DTCWrnIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaultType	7
DTCTTriggeredFlag_Cnt_M_lgc[0]	0
DTCTTriggeredFlag_Cnt_M_lgc[1]	1
DTCTTriggeredFlag_Cnt_M_lgc[2]	0
DTCTTriggeredFlag_Cnt_M_lgc[3]	1
DTCTTriggeredFlag_Cnt_M_lgc[4]	1
DTCTTriggeredFlag_Cnt_M_lgc[5]	1
DTCTTriggeredFlag_Cnt_M_lgc[6]	0
DTCTTriggeredFlag_Cnt_M_lgc[7]	0
DTCTTriggeredFlag_Cnt_M_lgc[8]	1
DTCTTriggeredFlag_Cnt_M_lgc[9]	1
DTCTTriggeredFlag_Cnt_M_lgc[10]	1
DTCTTriggeredFlag_Cnt_M_lgc[11]	0
DTCTTriggeredFlag_Cnt_M_lgc[12]	1
DTCTTriggeredFlag_Cnt_M_lgc[13]	1
DTCTTriggeredFlag_Cnt_M_lgc[14]	0
DTCTTriggeredFlag_Cnt_M_lgc[15]	1
DTCTTriggeredFlag_Cnt_M_lgc[16]	0
DTCTTriggeredFlag_Cnt_M_lgc[17]	1
DTCTTriggeredFlag_Cnt_M_lgc[18]	1
DTCTTriggeredFlag_Cnt_M_lgc[19]	1
DTCTTriggeredFlag_Cnt_M_lgc[20]	0
DTCTTriggeredFlag_Cnt_M_lgc[21]	1
DTCTTriggeredFlag_Cnt_M_lgc[22]	0
DTCTTriggeredFlag_Cnt_M_lgc[23]	1
DTCTTriggeredFlag_Cnt_M_lgc[24]	0
DTCTTriggeredFlag_Cnt_M_lgc[25]	1
DTCTTriggeredFlag_Cnt_M_lgc[26]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	1
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	217		
LKATrqOvrIdlvdRC_Cnt_M_u8	240		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventId_Cnt_M_u8	21		
LastReportedGMStatus_Cnt_M_u8	46		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	749573120		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.660000026		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	255		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	7		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	62026		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3688151552		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	3.29999995		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.0280000009		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-0.270000011		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	24	24	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSource	5	5	✔
DTCDData.DTCNumber	43937	43937	✔
DTCDData.DTCFailType	236	236	✔
DTCDData.DTCWmIndRqdSt	1	1	✔
DTCDData.DTCTstFldPwrUpSt	1	1	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdClrdStat	1	1	✔
DTCDData.DTCTstNPsdCdClrdSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	7	7	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	2	2	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	147	147	✓
GMStatus_Cnt_M_u8[2]	147	147	✓
GMStatus_Cnt_M_u8[3]	147	147	✓
GMStatus_Cnt_M_u8[4]	147	147	✓
GMStatus_Cnt_M_u8[5]	147	147	✓
GMStatus_Cnt_M_u8[6]	147	147	✓
GMStatus_Cnt_M_u8[7]	147	147	✓
GMStatus_Cnt_M_u8[8]	147	147	✓
GMStatus_Cnt_M_u8[9]	147	147	✓
GMStatus_Cnt_M_u8[10]	147	147	✓
GMStatus_Cnt_M_u8[11]	147	147	✓
GMStatus_Cnt_M_u8[12]	147	147	✓
GMStatus_Cnt_M_u8[13]	147	147	✓
GMStatus_Cnt_M_u8[14]	147	147	✓
GMStatus_Cnt_M_u8[15]	147	147	✓
GMStatus_Cnt_M_u8[16]	147	147	✓
GMStatus_Cnt_M_u8[17]	147	147	✓
GMStatus_Cnt_M_u8[18]	147	147	✓
GMStatus_Cnt_M_u8[19]	147	147	✓
GMStatus_Cnt_M_u8[20]	147	147	✓
GMStatus_Cnt_M_u8[21]	147	147	✓
GMStatus_Cnt_M_u8[22]	147	147	✓
GMStatus_Cnt_M_u8[23]	147	147	✓
GMStatus_Cnt_M_u8[24]	147	147	✓
GMStatus_Cnt_M_u8[25]	147	147	✓
GMStatus_Cnt_M_u8[26]	147	147	✓
GMStatus_Cnt_M_u8[27]	147	147	✓
GMStatus_Cnt_M_u8[28]	147	147	✓
GMStatus_Cnt_M_u8[29]	147	147	✓
GMStatus_Cnt_M_u8[30]	147	147	✓
GMStatus_Cnt_M_u8[31]	147	147	✓
LKATrqOvrDlvdRC_Cnt_M_u8	241	241	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	46	46	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	749573120	749573120	✓



Test Step Call Trace



2016-06-29, 14:00:09+0530

450

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrStItTqDlvd	1	IIPutTxLKAEIPwrStItTqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFidCdClrdStat_778	1	IIPutTxDTCl_TstFidCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFidPwrUpSt_778	1	IIPutTxDTCl_TstFidPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.91 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	23	
CTCEventId_Cnt_M_u8	35	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DTCTriggered	1	
DTCDData.DTCSource	6	
DTCDData.DTCNumber	892	
DTCDData.DTCFailType	195	
DTCDData.DTCWrmIndRqdSt	1	
DTCDData.DTCTstFidPwrUpSt	1	
DTCDData.DTCTstNPsdPwrUpSt	1	
DTCDData.DTCHistStat	0	
DTCDData.DTCTstFidCdClrdStat	1	
DTCDData.DTCTstNPsdCdClrdSt	1	
DTCDData.DTCCurrentStatus	0	
DTCDData.DTCCodeSupported	1	
DTCDData.DTCFaulttype	215	
DTCTriggeredFlag_Cnt_M_lgc[0]	0	
DTCTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTriggeredFlag_Cnt_M_lgc[2]	1	
DTCTriggeredFlag_Cnt_M_lgc[3]	1	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	0	
DTCTriggeredFlag_Cnt_M_lgc[6]	1	
DTCTriggeredFlag_Cnt_M_lgc[7]	1	
DTCTriggeredFlag_Cnt_M_lgc[8]	0	
DTCTriggeredFlag_Cnt_M_lgc[9]	1	
DTCTriggeredFlag_Cnt_M_lgc[10]	0	
DTCTriggeredFlag_Cnt_M_lgc[11]	1	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	1	
DTCTriggeredFlag_Cnt_M_lgc[14]	0	
DTCTriggeredFlag_Cnt_M_lgc[15]	1	
DTCTriggeredFlag_Cnt_M_lgc[16]	0	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	0	
DTCTriggeredFlag_Cnt_M_lgc[19]	1	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	
DTCTriggeredFlag_Cnt_M_lgc[26]	0	
DTCTriggeredFlag_Cnt_M_lgc[27]	0	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	3
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	14

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKATrqOvrldIvdRC_Cnt_M_u8	138		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventID_Cnt_M_u8	9		
LastReportedGMStatus_Cnt_M_u8	48		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKAState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	4056460800		
Steering_Torque_Overlay_Stat_CE_c[0]	24		
Steering_Torque_Overlay_Stat_CE_c[1]	28		
Steering_Torque_Overlay_Stat_CE_c[2]	32		
Steering_Torque_Overlay_Stat_CE_c[3]	36		
Steering_Torque_Overlay_Stat_CE_c[4]	40		
Steering_Torque_Overlay_Stat_CE_c[5]	44		
Steering_Torque_Overlay_Stat_CE_c[6]	48		
Steering_Torque_Overlay_Stat_CE_c[7]	52		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.680000007		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	99		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	46606		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3248030720		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	3.4000001		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.25		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-2.5		
target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-0.920000017		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	23	23	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	6	6	✓
DTCDData.DTCNumber	892	892	✓
DTCDData.DTCFailType	195	195	✓
DTCDData.DTCWmIndRqdSt	1	1	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrUpSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	215	215	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	4	4	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	3	3	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	3	3	✓
GMStatus_Cnt_M_u8[4]	3	3	✓
GMStatus_Cnt_M_u8[5]	3	3	✓
GMStatus_Cnt_M_u8[6]	3	3	✓
GMStatus_Cnt_M_u8[7]	3	3	✓
GMStatus_Cnt_M_u8[8]	3	3	✓
GMStatus_Cnt_M_u8[9]	3	3	✓
GMStatus_Cnt_M_u8[10]	3	3	✓
GMStatus_Cnt_M_u8[11]	3	3	✓
GMStatus_Cnt_M_u8[12]	3	3	✓
GMStatus_Cnt_M_u8[13]	3	3	✓
GMStatus_Cnt_M_u8[14]	3	3	✓
GMStatus_Cnt_M_u8[15]	3	3	✓
GMStatus_Cnt_M_u8[16]	3	3	✓
GMStatus_Cnt_M_u8[17]	3	3	✓
GMStatus_Cnt_M_u8[18]	3	3	✓
GMStatus_Cnt_M_u8[19]	3	3	✓
GMStatus_Cnt_M_u8[20]	3	3	✓
GMStatus_Cnt_M_u8[21]	3	3	✓
GMStatus_Cnt_M_u8[22]	3	3	✓
GMStatus_Cnt_M_u8[23]	3	3	✓
GMStatus_Cnt_M_u8[24]	3	3	✓
GMStatus_Cnt_M_u8[25]	3	3	✓
GMStatus_Cnt_M_u8[26]	3	3	✓
GMStatus_Cnt_M_u8[27]	3	3	✓
GMStatus_Cnt_M_u8[28]	3	3	✓
GMStatus_Cnt_M_u8[29]	3	3	✓
GMStatus_Cnt_M_u8[30]	3	3	✓
GMStatus_Cnt_M_u8[31]	3	3	✓
LKATrqOvriDivdRC_Cnt_M_u8	138	138	✓
LastReportedDTCEventID_Cnt_M_u8	9	9	✓
LastReportedGMStatus_Cnt_M_u8	48	48	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4056460800	4056460800	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.92 (Repeat Count = 1) ✓

Name	Input Value
CTCEventIdSV_Cnt_M_u8	6
CTCEventId_Cnt_M_u8	10
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	7
DTCDData.DTCNumber	56270
DTCDData.DTCFailType	166
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	92
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	8
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	41
LKATrqOvriDivdRC_Cnt_M_u8	1
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	29
LastReportedGMStatus_Cnt_M_u8	50
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	711186944		
Steering_Torque_Overlay_Stat_CE_c[0]	72		
Steering_Torque_Overlay_Stat_CE_c[1]	84		
Steering_Torque_Overlay_Stat_CE_c[2]	96		
Steering_Torque_Overlay_Stat_CE_c[3]	108		
Steering_Torque_Overlay_Stat_CE_c[4]	120		
Steering_Torque_Overlay_Stat_CE_c[5]	132		
Steering_Torque_Overlay_Stat_CE_c[6]	144		
Steering_Torque_Overlay_Stat_CE_c[7]	156		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.699999988		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	100		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	92		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	20588		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2570506240		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	3.5		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.259999999		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-1.39999998		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	6	6	✓
CTCEventId_Cnt_M_u8	11	11	✓
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✓
DTCData.DTCTriggered	0	0	✓
DTCData.DTCSource	49	49	✓
DTCData.DTCNumber	0	0	✓
DTCData.DTCFailType	0	0	✓
DTCData.DTCWrmIndRqdSt	0	0	✓
DTCData.DTCTstFldPwrUpSt	0	0	✓
DTCData.DTCTstNPsdPwrUpSt	0	0	✓
DTCData.DTCHistStat	0	0	✓
DTCData.DTCTstFldCdCldStat	0	0	✓
DTCData.DTCTstNPsdCdCldSt	0	0	✓
DTCData.DTCCurrentStatus	0	0	✓
DTCData.DTCCodeSupported	0	0	✓
DTCData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	9	9	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvrDivdRC_Cnt_M_u8	2	2	✓
LastReportedDTCEventID_Cnt_M_u8	29	29	✓
LastReportedGMStatus_Cnt_M_u8	50	50	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	711186944	711186944	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDltSt	1	IIPutTxHndsOffStrWhlDltSt	1	✓
IIPutTxHndsOffStrWhlDltMd	1	IIPutTxHndsOffStrWhlDltMd	1	✓
IIPutTxHndsOffStrWhlDltStV	1	IIPutTxHndsOffStrWhlDltStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDltTrqDlvd	1	IIPutTxLKATrqOvrIDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDltStGroup	1	IIPutTxHndsOffStrWhlDltStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIDltStChksm	1	IIPutTxLKATrqOvrIDltStChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdCldSt_778	1	IIPutTxDTCL_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.93 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	10
CTCEventId_Cnt_M_u8	24
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	8
DTCDData.DTCNumber	27244
DTCDData.DTCFailType	41
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	66
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	22		
GMStatus_Cnt_M_u8[11]	24		
GMStatus_Cnt_M_u8[12]	26		
GMStatus_Cnt_M_u8[13]	28		
GMStatus_Cnt_M_u8[14]	30		
GMStatus_Cnt_M_u8[15]	32		
GMStatus_Cnt_M_u8[16]	34		
GMStatus_Cnt_M_u8[17]	36		
GMStatus_Cnt_M_u8[18]	38		
GMStatus_Cnt_M_u8[19]	40		
GMStatus_Cnt_M_u8[20]	42		
GMStatus_Cnt_M_u8[21]	44		
GMStatus_Cnt_M_u8[22]	46		
GMStatus_Cnt_M_u8[23]	48		
GMStatus_Cnt_M_u8[24]	50		
GMStatus_Cnt_M_u8[25]	52		
GMStatus_Cnt_M_u8[26]	54		
GMStatus_Cnt_M_u8[27]	56		
GMStatus_Cnt_M_u8[28]	58		
GMStatus_Cnt_M_u8[29]	60		
GMStatus_Cnt_M_u8[30]	62		
GMStatus_Cnt_M_u8[31]	64		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	69		
LKATrqOvrDlvdRC_Cnt_M_u8	210		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182		
LastReportedDTCEventID_Cnt_M_u8	20		
LastReportedGMStatus_Cnt_M_u8	52		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	1012610304		
Steering_Torque_Overlay_Stat_CE_c[0]	84		
Steering_Torque_Overlay_Stat_CE_c[1]	98		
Steering_Torque_Overlay_Stat_CE_c[2]	112		
Steering_Torque_Overlay_Stat_CE_c[3]	126		
Steering_Torque_Overlay_Stat_CE_c[4]	140		
Steering_Torque_Overlay_Stat_CE_c[5]	154		
Steering_Torque_Overlay_Stat_CE_c[6]	168		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.720000029		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	101		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	66		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	63906		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	389698304		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	3.5999999		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.939999998		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-4.30000019		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	10	10	✓
CTCEventId_Cnt_M_u8	25	25	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDlvdRC_Cnt_M_u8	211	211	✓
LastReportedDTCEventID_Cnt_M_u8	20	20	✓
LastReportedGMStatus_Cnt_M_u8	52	52	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1012610304	1012610304	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItItqDlrd	1	IIPutTxElPwrStItItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMtd	1	IIPutTxHndsOffStrWhlDtMtd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrStItItqDlvd	1	IIPutTxLKAEIPwrStItItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSources_778	1	IIPutTxDTCl_DTCSources_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.94 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	10
CTCEventId_Cnt_M_u8	10
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCSource	9
DTCDData.DTCNumber	12420
DTCDData.DTCFailType	41
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	113
DTCTriggeredFlag_Cnt_M_Igc[0]	0
DTCTriggeredFlag_Cnt_M_Igc[1]	1
DTCTriggeredFlag_Cnt_M_Igc[2]	0
DTCTriggeredFlag_Cnt_M_Igc[3]	1
DTCTriggeredFlag_Cnt_M_Igc[4]	1
DTCTriggeredFlag_Cnt_M_Igc[5]	1
DTCTriggeredFlag_Cnt_M_Igc[6]	0
DTCTriggeredFlag_Cnt_M_Igc[7]	0
DTCTriggeredFlag_Cnt_M_Igc[8]	1
DTCTriggeredFlag_Cnt_M_Igc[9]	1
DTCTriggeredFlag_Cnt_M_Igc[10]	0
DTCTriggeredFlag_Cnt_M_Igc[11]	0
DTCTriggeredFlag_Cnt_M_Igc[12]	1
DTCTriggeredFlag_Cnt_M_Igc[13]	1
DTCTriggeredFlag_Cnt_M_Igc[14]	0
DTCTriggeredFlag_Cnt_M_Igc[15]	1
DTCTriggeredFlag_Cnt_M_Igc[16]	0
DTCTriggeredFlag_Cnt_M_Igc[17]	1
DTCTriggeredFlag_Cnt_M_Igc[18]	1
DTCTriggeredFlag_Cnt_M_Igc[19]	1
DTCTriggeredFlag_Cnt_M_Igc[20]	0
DTCTriggeredFlag_Cnt_M_Igc[21]	1
DTCTriggeredFlag_Cnt_M_Igc[22]	0
DTCTriggeredFlag_Cnt_M_Igc[23]	1
DTCTriggeredFlag_Cnt_M_Igc[24]	0
DTCTriggeredFlag_Cnt_M_Igc[25]	1
DTCTriggeredFlag_Cnt_M_Igc[26]	0
DTCTriggeredFlag_Cnt_M_Igc[27]	1
DTCTriggeredFlag_Cnt_M_Igc[28]	0
DTCTriggeredFlag_Cnt_M_Igc[29]	1
DTCTriggeredFlag_Cnt_M_Igc[30]	1
DTCTriggeredFlag_Cnt_M_Igc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	10
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	3
GMStatus_Cnt_M_u8[2]	5
GMStatus_Cnt_M_u8[3]	7
GMStatus_Cnt_M_u8[4]	9
GMStatus_Cnt_M_u8[5]	11
GMStatus_Cnt_M_u8[6]	13
GMStatus_Cnt_M_u8[7]	15
GMStatus_Cnt_M_u8[8]	17
GMStatus_Cnt_M_u8[9]	19
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	23
GMStatus_Cnt_M_u8[12]	25
GMStatus_Cnt_M_u8[13]	27
GMStatus_Cnt_M_u8[14]	29
GMStatus_Cnt_M_u8[15]	31
GMStatus_Cnt_M_u8[16]	33
GMStatus_Cnt_M_u8[17]	35
GMStatus_Cnt_M_u8[18]	37
GMStatus_Cnt_M_u8[19]	39
GMStatus_Cnt_M_u8[20]	41
GMStatus_Cnt_M_u8[21]	43
GMStatus_Cnt_M_u8[22]	45
GMStatus_Cnt_M_u8[23]	47
GMStatus_Cnt_M_u8[24]	49
GMStatus_Cnt_M_u8[25]	51
GMStatus_Cnt_M_u8[26]	53
GMStatus_Cnt_M_u8[27]	55
GMStatus_Cnt_M_u8[28]	57
GMStatus_Cnt_M_u8[29]	59
GMStatus_Cnt_M_u8[30]	61
GMStatus_Cnt_M_u8[31]	63
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	224
LKATrqOvrIdlvdRC_Cnt_M_u8	241
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	54
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	676026112
Steering_Torque_Overlay_Stat_CE_c[0]	12
Steering_Torque_Overlay_Stat_CE_c[1]	14
Steering_Torque_Overlay_Stat_CE_c[2]	16
Steering_Torque_Overlay_Stat_CE_c[3]	18
Steering_Torque_Overlay_Stat_CE_c[4]	20
Steering_Torque_Overlay_Stat_CE_c[5]	22
Steering_Torque_Overlay_Stat_CE_c[6]	24
Steering_Torque_Overlay_Stat_CE_c[7]	26
k_LKAMfgEnable_Cnt_lgc	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_MaxHOWEstimate_Uls_f32	0.74000001		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	102		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	113		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1045652736		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	3.70000005		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.319999993		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-8.80000019		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.75999999		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	10	10	✓
CTCEventId_Cnt_M_u8	10	10	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	9	9	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	11	11	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	3	3	✓
GMStatus_Cnt_M_u8[2]	5	5	✓
GMStatus_Cnt_M_u8[3]	7	7	✓
GMStatus_Cnt_M_u8[4]	9	9	✓
GMStatus_Cnt_M_u8[5]	11	11	✓
GMStatus_Cnt_M_u8[6]	13	13	✓
GMStatus_Cnt_M_u8[7]	15	15	✓
GMStatus_Cnt_M_u8[8]	17	17	✓
GMStatus_Cnt_M_u8[9]	19	19	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	23	23	✓
GMStatus_Cnt_M_u8[12]	25	25	✓
GMStatus_Cnt_M_u8[13]	27	27	✓
GMStatus_Cnt_M_u8[14]	29	29	✓
GMStatus_Cnt_M_u8[15]	31	31	✓
GMStatus_Cnt_M_u8[16]	33	33	✓
GMStatus_Cnt_M_u8[17]	35	35	✓
GMStatus_Cnt_M_u8[18]	37	37	✓
GMStatus_Cnt_M_u8[19]	39	39	✓
GMStatus_Cnt_M_u8[20]	41	41	✓
GMStatus_Cnt_M_u8[21]	43	43	✓
GMStatus_Cnt_M_u8[22]	45	45	✓
GMStatus_Cnt_M_u8[23]	47	47	✓
GMStatus_Cnt_M_u8[24]	49	49	✓
GMStatus_Cnt_M_u8[25]	51	51	✓
GMStatus_Cnt_M_u8[26]	53	53	✓
GMStatus_Cnt_M_u8[27]	55	55	✓
GMStatus_Cnt_M_u8[28]	57	57	✓
GMStatus_Cnt_M_u8[29]	59	59	✓
GMStatus_Cnt_M_u8[30]	61	61	✓
GMStatus_Cnt_M_u8[31]	63	63	✓
LKATrqOvriDlvdRC_Cnt_M_u8	242	242	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	54	54	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	676026112	676026112	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.95 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	13
CTCEventId_Cnt_M_u8	13
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	10
DTCDData.DTCNumber	61885
DTCDData.DTCFailType	111
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	215
DTCTTriggeredFlag_Cnt_M_lgc[0]	1
DTCTTriggeredFlag_Cnt_M_lgc[1]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	14
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	127
LKATrqOvrDivdRC_Cnt_M_u8	62
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52
LastReportedDTCEventID_Cnt_M_u8	33
LastReportedGMStatus_Cnt_M_u8	56
PrevWarningIndSignal_Cnt_M_u8[0]	0
PrevWarningIndSignal_Cnt_M_u8[1]	0
PrevWarningIndSignal_Cnt_M_u8[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	1222163968
Steering_Torque_Overlay_Stat_CE_c[0]	24
Steering_Torque_Overlay_Stat_CE_c[1]	28
Steering_Torque_Overlay_Stat_CE_c[2]	32
Steering_Torque_Overlay_Stat_CE_c[3]	36
Steering_Torque_Overlay_Stat_CE_c[4]	40
Steering_Torque_Overlay_Stat_CE_c[5]	44
Steering_Torque_Overlay_Stat_CE_c[6]	48
Steering_Torque_Overlay_Stat_CE_c[7]	52
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.75999999
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	103
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	7902208
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	3.79999995
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.5
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-4.80000019
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.96800005

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	13	13	✓
CTCEventId_Cnt_M_u8	14	14	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	224	224	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	15	15	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDvdrRC_Cnt_M_u8	62	62	✓
LastReportedDTCEventID_Cnt_M_u8	13	13	✓
LastReportedGMStatus_Cnt_M_u8	14	14	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_ms_M_u32p0	1222163968	1222163968	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_ms_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_ms_u16	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvdrARC	1	IIPutTxTrqOvrIDvdrARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmlndRqdSt_778	1	IIPutTxDTCl_WrmlndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.96 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	34
CTCEventId_Cnt_M_u8	34
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	11
DTCDData.DTCNumber	1158
DTCDData.DTCFailType	119
DTCDData.DTCWrmlndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	53
DTCTriggeredFlag_Cnt_M_lgc[0]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	11
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	38
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	92
LKATrqOvrIdlvdRC_Cnt_M_u8	58
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104
LastReportedDTCEventID_Cnt_M_u8	17
LastReportedGMStatus_Cnt_M_u8	58
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKAState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3093112832
Steering_Torque_Overlay_Stat_CE_c[0]	48
Steering_Torque_Overlay_Stat_CE_c[1]	56
Steering_Torque_Overlay_Stat_CE_c[2]	64
Steering_Torque_Overlay_Stat_CE_c[3]	72
Steering_Torque_Overlay_Stat_CE_c[4]	80
Steering_Torque_Overlay_Stat_CE_c[5]	88
Steering_Torque_Overlay_Stat_CE_c[6]	96
Steering_Torque_Overlay_Stat_CE_c[7]	104
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.779999971
k_SComTrqPosPol_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	104
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	53
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	53757
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3689655808
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	3.9000001
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.629999995
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	10
target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data	2
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	34	34	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	11	11	✓
DTCDData.DTCNumber	1158	1158	✓
DTCDData.DTCFailType	119	119	✓
DTCDData.DTCWmIndRqdSt	1	1	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	53	53	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	12	12	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	17	17	✓
GMStatus_Cnt_M_u8[2]	17	17	✓
GMStatus_Cnt_M_u8[3]	17	17	✓
GMStatus_Cnt_M_u8[4]	17	17	✓
GMStatus_Cnt_M_u8[5]	17	17	✓
GMStatus_Cnt_M_u8[6]	17	17	✓
GMStatus_Cnt_M_u8[7]	17	17	✓
GMStatus_Cnt_M_u8[8]	17	17	✓
GMStatus_Cnt_M_u8[9]	17	17	✓
GMStatus_Cnt_M_u8[10]	17	17	✓
GMStatus_Cnt_M_u8[11]	17	17	✓
GMStatus_Cnt_M_u8[12]	17	17	✓
GMStatus_Cnt_M_u8[13]	17	17	✓
GMStatus_Cnt_M_u8[14]	17	17	✓
GMStatus_Cnt_M_u8[15]	17	17	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	17	17	✓
GMStatus_Cnt_M_u8[18]	17	17	✓
GMStatus_Cnt_M_u8[19]	17	17	✓
GMStatus_Cnt_M_u8[20]	17	17	✓
GMStatus_Cnt_M_u8[21]	17	17	✓
GMStatus_Cnt_M_u8[22]	17	17	✓
GMStatus_Cnt_M_u8[23]	17	17	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	17	17	✓
GMStatus_Cnt_M_u8[25]	17	17	✓
GMStatus_Cnt_M_u8[26]	17	17	✓
GMStatus_Cnt_M_u8[27]	17	17	✓
GMStatus_Cnt_M_u8[28]	17	17	✓
GMStatus_Cnt_M_u8[29]	17	17	✓
GMStatus_Cnt_M_u8[30]	17	17	✓
GMStatus_Cnt_M_u8[31]	17	17	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	59	59	✓
LastReportedDTCEventID_Cnt_M_u8	17	17	✓
LastReportedGMStatus_Cnt_M_u8	58	58	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3093112832	3093112832	✓



Test Step Call Trace



SrlComOutput Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrStTtTqDlvd	1	IIPutTxLKAEIPwrStTtTqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNNumber_778	1	IIPutTxDTCl_DTCNNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.97 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	30	
CTCEventId_Cnt_M_u8	0	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DCTriggered	1	
DTCDData.DTCSOURCE	12	
DTCDData.DTCNNumber	21115	
DTCDData.DTCFailType	253	
DTCDData.DTCWrnIndRqdSt	0	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	0	
DTCDData.DTCHistStat	1	
DTCDData.DTCTstFldCdClrdStat	0	
DTCDData.DTCTstNPsdCdClrdSt	0	
DTCDData.DTCCurrentStatus	1	
DTCDData.DTCCodeSupported	1	
DTCDData.DTCFaulttype	53	
DTCTriggeredFlag_Cnt_M_lgc[0]	0	
DTCTriggeredFlag_Cnt_M_lgc[1]	1	
DTCTriggeredFlag_Cnt_M_lgc[2]	0	
DTCTriggeredFlag_Cnt_M_lgc[3]	1	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	0	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	1	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	1	
DTCTriggeredFlag_Cnt_M_lgc[14]	0	
DTCTriggeredFlag_Cnt_M_lgc[15]	1	
DTCTriggeredFlag_Cnt_M_lgc[16]	0	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	1	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	0	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	0	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	5
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	3
GMStatus_Cnt_M_u8[2]	5
GMStatus_Cnt_M_u8[3]	7
GMStatus_Cnt_M_u8[4]	9
GMStatus_Cnt_M_u8[5]	11
GMStatus_Cnt_M_u8[6]	13
GMStatus_Cnt_M_u8[7]	15
GMStatus_Cnt_M_u8[8]	17
GMStatus_Cnt_M_u8[9]	19
GMStatus_Cnt_M_u8[10]	21
GMStatus_Cnt_M_u8[11]	23
GMStatus_Cnt_M_u8[12]	25
GMStatus_Cnt_M_u8[13]	27
GMStatus_Cnt_M_u8[14]	29
GMStatus_Cnt_M_u8[15]	31
GMStatus_Cnt_M_u8[16]	33
GMStatus_Cnt_M_u8[17]	35
GMStatus_Cnt_M_u8[18]	37
GMStatus_Cnt_M_u8[19]	39
GMStatus_Cnt_M_u8[20]	41
GMStatus_Cnt_M_u8[21]	43
GMStatus_Cnt_M_u8[22]	45
GMStatus_Cnt_M_u8[23]	47
GMStatus_Cnt_M_u8[24]	49
GMStatus_Cnt_M_u8[25]	51
GMStatus_Cnt_M_u8[26]	53
GMStatus_Cnt_M_u8[27]	55
GMStatus_Cnt_M_u8[28]	57
GMStatus_Cnt_M_u8[29]	59
GMStatus_Cnt_M_u8[30]	61
GMStatus_Cnt_M_u8[31]	63

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	114		
LKATrqOvrIdlvdRC_Cnt_M_u8	85		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130		
LastReportedDTCEventID_Cnt_M_u8	16		
LastReportedGMStatus_Cnt_M_u8	60		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3777448704		
Steering_Torque_Overlay_Stat_CE_c[0]	60		
Steering_Torque_Overlay_Stat_CE_c[1]	70		
Steering_Torque_Overlay_Stat_CE_c[2]	80		
Steering_Torque_Overlay_Stat_CE_c[3]	90		
Steering_Torque_Overlay_Stat_CE_c[4]	100		
Steering_Torque_Overlay_Stat_CE_c[5]	110		
Steering_Torque_Overlay_Stat_CE_c[6]	120		
Steering_Torque_Overlay_Stat_CE_c[7]	130		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.800000012		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	105		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	53		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	53887		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	0		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	4		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.474999994		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-8.72000027		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	0	0	✔
CTCEventId_Cnt_M_u8	0	0	✔
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSorce	49	49	✔
DTCDData.DTCNumber	0	0	✔
DTCDData.DTCFailType	115	115	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstINPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdClrdStat	0	0	✔
DTCDData.DTCTstINPsdCdClrdSt	0	0	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	6	6	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	3	3	✓
GMStatus_Cnt_M_u8[2]	5	5	✓
GMStatus_Cnt_M_u8[3]	7	7	✓
GMStatus_Cnt_M_u8[4]	9	9	✓
GMStatus_Cnt_M_u8[5]	11	11	✓
GMStatus_Cnt_M_u8[6]	13	13	✓
GMStatus_Cnt_M_u8[7]	15	15	✓
GMStatus_Cnt_M_u8[8]	17	17	✓
GMStatus_Cnt_M_u8[9]	19	19	✓
GMStatus_Cnt_M_u8[10]	21	21	✓
GMStatus_Cnt_M_u8[11]	23	23	✓
GMStatus_Cnt_M_u8[12]	25	25	✓
GMStatus_Cnt_M_u8[13]	27	27	✓
GMStatus_Cnt_M_u8[14]	29	29	✓
GMStatus_Cnt_M_u8[15]	31	31	✓
GMStatus_Cnt_M_u8[16]	33	33	✓
GMStatus_Cnt_M_u8[17]	35	35	✓
GMStatus_Cnt_M_u8[18]	37	37	✓
GMStatus_Cnt_M_u8[19]	39	39	✓
GMStatus_Cnt_M_u8[20]	41	41	✓
GMStatus_Cnt_M_u8[21]	43	43	✓
GMStatus_Cnt_M_u8[22]	45	45	✓
GMStatus_Cnt_M_u8[23]	47	47	✓
GMStatus_Cnt_M_u8[24]	49	49	✓
GMStatus_Cnt_M_u8[25]	51	51	✓
GMStatus_Cnt_M_u8[26]	53	53	✓
GMStatus_Cnt_M_u8[27]	55	55	✓
GMStatus_Cnt_M_u8[28]	57	57	✓
GMStatus_Cnt_M_u8[29]	59	59	✓
GMStatus_Cnt_M_u8[30]	61	61	✓
GMStatus_Cnt_M_u8[31]	63	63	✓
LKATrqOvrDivdRC_Cnt_M_u8	85	85	✓
LastReportedDTCEventID_Cnt_M_u8	16	16	✓
LastReportedGMStatus_Cnt_M_u8	60	60	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSTtItqDlrd	1	IIPutTxElPwrSTtItqDlrd	1	✓
IIPutTxTrqOvrlTrqDStat	1	IIPutTxTrqOvrlTrqDStat	1	✓
IIPutTxTrqOvrlDvrdARC	1	IIPutTxTrqOvrlDvrdARC	1	✓
IIPutTxTrqOvrlDltTrqDlrd	1	IIPutTxTrqOvrlDltTrqDlrd	1	✓
IIPutTxTrqOvrlDChksm	1	IIPutTxTrqOvrlDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrc_778	1	IIPutTxDTCl_DTCSrc_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.98 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	28
CTCEventId_Cnt_M_u8	5
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSrc	13
DTCDData.DTCNumber	24831
DTCDData.DTCFailType	196
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	222
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	7
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[25]	26		
GMStatus_Cnt_M_u8[26]	27		
GMStatus_Cnt_M_u8[27]	28		
GMStatus_Cnt_M_u8[28]	29		
GMStatus_Cnt_M_u8[29]	30		
GMStatus_Cnt_M_u8[30]	31		
GMStatus_Cnt_M_u8[31]	32		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	89		
LKATrqOvrIDlvdRC_Cnt_M_u8	250		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182		
LastReportedDTCEventID_Cnt_M_u8	20		
LastReportedGMStatus_Cnt_M_u8	62		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	2624068864		
Steering_Torque_Overlay_Stat_CE_c[0]	84		
Steering_Torque_Overlay_Stat_CE_c[1]	98		
Steering_Torque_Overlay_Stat_CE_c[2]	112		
Steering_Torque_Overlay_Stat_CE_c[3]	126		
Steering_Torque_Overlay_Stat_CE_c[4]	140		
Steering_Torque_Overlay_Stat_CE_c[5]	154		
Steering_Torque_Overlay_Stat_CE_c[6]	168		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.819999993		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	106		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	222		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	61250		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	4294967295		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-4.5		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.0199999996		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-1.79999995		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-1.52999997		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	5	5	✔
CTCEventId_Cnt_M_u8	5	5	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	1	1	✔
DTCDData.DTCFailType	64	64	✔
DTCDData.DTCWrIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	0	0	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	8	8	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvriDlvdRC_Cnt_M_u8	251	251	✓
LastReportedDTCEventID_Cnt_M_u8	20	20	✓
LastReportedGMStatus_Cnt_M_u8	62	62	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	4294967295	4294967295	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrlTrqDStat	1	IIPutTxTrqOvrlTrqDStat	1	✓
IIPutTxTrqOvrlDvrdARC	1	IIPutTxTrqOvrlDvrdARC	1	✓
IIPutTxTrqOvrlDltTrqDlrd	1	IIPutTxTrqOvrlDltTrqDlrd	1	✓
IIPutTxTrqOvrlDChksm	1	IIPutTxTrqOvrlDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDltSt	1	IIPutTxHndsOffStrWhlDltSt	1	✓
IIPutTxHndsOffStrWhlDltMd	1	IIPutTxHndsOffStrWhlDltMd	1	✓
IIPutTxHndsOffStrWhlDltStV	1	IIPutTxHndsOffStrWhlDltStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDltStGroup	1	IIPutTxHndsOffStrWhlDltStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.99 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	6
CTCEventId_Cnt_M_u8	0
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	14
DTCDData.DTCNumber	42083
DTCDData.DTCFailType	182
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	8
DTCTriggeredFlag_Cnt_M_lgc[0]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	6
GMStatus_Cnt_M_u8[0]	6
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	115
LKATrqOvrIdlvdRC_Cnt_M_u8	206
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208
LastReportedDTCEventID_Cnt_M_u8	11
LastReportedGMStatus_Cnt_M_u8	64
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKAState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	1058696192
Steering_Torque_Overlay_Stat_CE_c[0]	96
Steering_Torque_Overlay_Stat_CE_c[1]	112
Steering_Torque_Overlay_Stat_CE_c[2]	128
Steering_Torque_Overlay_Stat_CE_c[3]	144
Steering_Torque_Overlay_Stat_CE_c[4]	160
Steering_Torque_Overlay_Stat_CE_c[5]	176
Steering_Torque_Overlay_Stat_CE_c[6]	192
Steering_Torque_Overlay_Stat_CE_c[7]	208
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.839999974
k_SComTrqPosPol_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	107
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	8
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	17516
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3426999952
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-4.30000019
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.0240000002
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-2.29999995
target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data	3
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	0.779999971

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	0	0	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	5	5	✓
DTCDData.DTCFailType	220	220	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	7	7	✓
GMStatus_Cnt_M_u8[0]	6	6	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	206	206	✓
LastReportedDTCEventID_Cnt_M_u8	11	11	✓
LastReportedGMStatus_Cnt_M_u8	64	64	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3426999552	3426999552	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.100 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	19
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	18
DTCDData.DTCNumber	32160
DTCDData.DTCFailType	122
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	58
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	194
LKATrqOvrDivdRC_Cnt_M_u8	77
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	7
LastReportedGMStatus_Cnt_M_u8	72
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	283927808
Steering_Torque_Overlay_Stat_CE_c[0]	84
Steering_Torque_Overlay_Stat_CE_c[1]	98
Steering_Torque_Overlay_Stat_CE_c[2]	112
Steering_Torque_Overlay_Stat_CE_c[3]	126
Steering_Torque_Overlay_Stat_CE_c[4]	140
Steering_Torque_Overlay_Stat_CE_c[5]	154
Steering_Torque_Overlay_Stat_CE_c[6]	168
Steering_Torque_Overlay_Stat_CE_c[7]	182
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.639999986
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	108
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	58
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	38829
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	221381376
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-3.5
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-4.59000015
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	2.47000003

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	19	19	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	18	18	✓
DTCDData.DTCNumber	32160	32160	✓
DTCDData.DTCFailType	122	122	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	58	58	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	3	3	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	17	17	✓
GMStatus_Cnt_M_u8[2]	17	17	✓
GMStatus_Cnt_M_u8[3]	17	17	✓
GMStatus_Cnt_M_u8[4]	17	17	✓
GMStatus_Cnt_M_u8[5]	17	17	✓
GMStatus_Cnt_M_u8[6]	17	17	✓
GMStatus_Cnt_M_u8[7]	17	17	✓
GMStatus_Cnt_M_u8[8]	17	17	✓
GMStatus_Cnt_M_u8[9]	17	17	✓
GMStatus_Cnt_M_u8[10]	17	17	✓
GMStatus_Cnt_M_u8[11]	17	17	✓
GMStatus_Cnt_M_u8[12]	17	17	✓
GMStatus_Cnt_M_u8[13]	17	17	✓
GMStatus_Cnt_M_u8[14]	17	17	✓
GMStatus_Cnt_M_u8[15]	17	17	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	17	17	✓
GMStatus_Cnt_M_u8[18]	17	17	✓
GMStatus_Cnt_M_u8[19]	17	17	✓
GMStatus_Cnt_M_u8[20]	17	17	✓
GMStatus_Cnt_M_u8[21]	17	17	✓
GMStatus_Cnt_M_u8[22]	17	17	✓
GMStatus_Cnt_M_u8[23]	17	17	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	17	17	✓
GMStatus_Cnt_M_u8[25]	17	17	✓
GMStatus_Cnt_M_u8[26]	17	17	✓
GMStatus_Cnt_M_u8[27]	17	17	✓
GMStatus_Cnt_M_u8[28]	17	17	✓
GMStatus_Cnt_M_u8[29]	17	17	✓
GMStatus_Cnt_M_u8[30]	17	17	✓
GMStatus_Cnt_M_u8[31]	17	17	✓
LKATrqOvriDlvdRC_Cnt_M_u8	78	78	✓
LastReportedDTCEventID_Cnt_M_u8	7	7	✓
LastReportedGMStatus_Cnt_M_u8	72	72	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	283927808	283927808	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrStTtTqDlvd	1	IIPutTxLKAEIPwrStTtTqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNNumber_778	1	IIPutTxDTCl_DTCNNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.101 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	24	
CTCEventId_Cnt_M_u8	35	
CurrentDTCSentThisIC_Cnt_M_lgc	0	
DTCDData.DTCTriggered	1	
DTCDData.DTCSOURCE	19	
DTCDData.DTCNNumber	43937	
DTCDData.DTCFailType	236	
DTCDData.DTCWrnIndRqdSt	1	
DTCDData.DTCTstFldPwrUpSt	1	
DTCDData.DTCTstNPsdPwrUpSt	1	
DTCDData.DTCHistStat	0	
DTCDData.DTCTstFldCdClrdStat	1	
DTCDData.DTCTstNPsdCdClrdSt	0	
DTCDData.DTCCurrentStatus	0	
DTCDData.DTCCodeSupported	1	
DTCDData.DTCFaulttype	7	
DTCTriggeredFlag_Cnt_M_lgc[0]	0	
DTCTriggeredFlag_Cnt_M_lgc[1]	1	
DTCTriggeredFlag_Cnt_M_lgc[2]	0	
DTCTriggeredFlag_Cnt_M_lgc[3]	1	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	0	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	1	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	1	
DTCTriggeredFlag_Cnt_M_lgc[14]	0	
DTCTriggeredFlag_Cnt_M_lgc[15]	1	
DTCTriggeredFlag_Cnt_M_lgc[16]	0	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	1	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	0	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	4
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	217		
LKATrqOvrldlvdRC_Cnt_M_u8	240		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventID_Cnt_M_u8	21		
LastReportedGMStatus_Cnt_M_u8	74		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	749573120		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.660000026		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	109		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	7		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	62026		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3688151552		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-3.29999995		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	1		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	3.20000005		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	0.389999986		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	24	24	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSrc	19	19	✔
DTCDData.DTCNumber	43937	43937	✔
DTCDData.DTCFailType	236	236	✔
DTCDData.DTCWrmIndRqdSt	1	1	✔
DTCDData.DTCTstFldPwrUpSt	1	1	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdClrdStat	1	1	✔
DTCDData.DTCTstNPsdCdClrdSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	7	7	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	5	5	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	19	19	✓
GMStatus_Cnt_M_u8[2]	19	19	✓
GMStatus_Cnt_M_u8[3]	19	19	✓
GMStatus_Cnt_M_u8[4]	19	19	✓
GMStatus_Cnt_M_u8[5]	19	19	✓
GMStatus_Cnt_M_u8[6]	19	19	✓
GMStatus_Cnt_M_u8[7]	19	19	✓
GMStatus_Cnt_M_u8[8]	19	19	✓
GMStatus_Cnt_M_u8[9]	19	19	✓
GMStatus_Cnt_M_u8[10]	19	19	✓
GMStatus_Cnt_M_u8[11]	19	19	✓
GMStatus_Cnt_M_u8[12]	19	19	✓
GMStatus_Cnt_M_u8[13]	19	19	✓
GMStatus_Cnt_M_u8[14]	19	19	✓
GMStatus_Cnt_M_u8[15]	19	19	✓
GMStatus_Cnt_M_u8[16]	19	19	✓
GMStatus_Cnt_M_u8[17]	19	19	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	19	19	✓
GMStatus_Cnt_M_u8[20]	19	19	✓
GMStatus_Cnt_M_u8[21]	19	19	✓
GMStatus_Cnt_M_u8[22]	19	19	✓
GMStatus_Cnt_M_u8[23]	19	19	✓
GMStatus_Cnt_M_u8[24]	19	19	✓
GMStatus_Cnt_M_u8[25]	19	19	✓
GMStatus_Cnt_M_u8[26]	19	19	✓
GMStatus_Cnt_M_u8[27]	19	19	✓
GMStatus_Cnt_M_u8[28]	19	19	✓
GMStatus_Cnt_M_u8[29]	19	19	✓
GMStatus_Cnt_M_u8[30]	19	19	✓
GMStatus_Cnt_M_u8[31]	19	19	✓
LKATrqOvriDivdRC_Cnt_M_u8	241	241	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	74	74	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	749573120	749573120	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.102 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	23	
CTCEventId_Cnt_M_u8	35	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DTCTriggered	1	
DTCDData.DTCSource	20	
DTCDData.DTCNumber	892	
DTCDData.DTCFailType	195	
DTCDData.DTCWrnIndRqdSt	1	
DTCDData.DTCTstFldPwrUpSt	1	
DTCDData.DTCTstNPsdPwrUpSt	1	
DTCDData.DTCHistStat	0	
DTCDData.DTCTstFldCdCldStat	1	
DTCDData.DTCTstNPsdCdCldSt	1	
DTCDData.DTCCurrentStatus	0	
DTCDData.DTCCodeSupported	1	
DTCDData.DTCFaulttype	215	
DTCTTriggeredFlag_Cnt_M_lgc[0]	0	
DTCTTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTTriggeredFlag_Cnt_M_lgc[2]	1	
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTTriggeredFlag_Cnt_M_lgc[5]	0	
DTCTTriggeredFlag_Cnt_M_lgc[6]	1	
DTCTTriggeredFlag_Cnt_M_lgc[7]	1	
DTCTTriggeredFlag_Cnt_M_lgc[8]	0	
DTCTTriggeredFlag_Cnt_M_lgc[9]	1	
DTCTTriggeredFlag_Cnt_M_lgc[10]	0	
DTCTTriggeredFlag_Cnt_M_lgc[11]	1	
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	
DTCTTriggeredFlag_Cnt_M_lgc[14]	0	
DTCTTriggeredFlag_Cnt_M_lgc[15]	1	
DTCTTriggeredFlag_Cnt_M_lgc[16]	0	
DTCTTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTTriggeredFlag_Cnt_M_lgc[18]	0	
DTCTTriggeredFlag_Cnt_M_lgc[19]	1	
DTCTTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	
DTCTTriggeredFlag_Cnt_M_lgc[26]	0	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	8
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	14		
LKATrqOvrIdlvdRC_Cnt_M_u8	138		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventID_Cnt_M_u8	9		
LastReportedGMStatus_Cnt_M_u8	76		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	4056460800		
Steering_Torque_Overlay_Stat_CE_c[0]	24		
Steering_Torque_Overlay_Stat_CE_c[1]	28		
Steering_Torque_Overlay_Stat_CE_c[2]	32		
Steering_Torque_Overlay_Stat_CE_c[3]	36		
Steering_Torque_Overlay_Stat_CE_c[4]	40		
Steering_Torque_Overlay_Stat_CE_c[5]	44		
Steering_Torque_Overlay_Stat_CE_c[6]	48		
Steering_Torque_Overlay_Stat_CE_c[7]	52		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.680000007		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	110		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	215		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	46606		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3248030720		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-3.0999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.0320000015		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	1.38		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	0.819999993		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	23	23	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSource	20	20	✔
DTCDData.DTCNumber	892	892	✔
DTCDData.DTCFailType	195	195	✔
DTCDData.DTCWrmIndRqdSt	1	1	✔
DTCDData.DTCTstFldPwrUpSt	1	1	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdClrdStat	1	1	✔
DTCDData.DTCTstNPsdCdClrdSt	1	1	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	215	215	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	9	9	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	17	17	✓
GMStatus_Cnt_M_u8[2]	17	17	✓
GMStatus_Cnt_M_u8[3]	17	17	✓
GMStatus_Cnt_M_u8[4]	17	17	✓
GMStatus_Cnt_M_u8[5]	17	17	✓
GMStatus_Cnt_M_u8[6]	17	17	✓
GMStatus_Cnt_M_u8[7]	17	17	✓
GMStatus_Cnt_M_u8[8]	17	17	✓
GMStatus_Cnt_M_u8[9]	17	17	✓
GMStatus_Cnt_M_u8[10]	17	17	✓
GMStatus_Cnt_M_u8[11]	17	17	✓
GMStatus_Cnt_M_u8[12]	17	17	✓
GMStatus_Cnt_M_u8[13]	17	17	✓
GMStatus_Cnt_M_u8[14]	17	17	✓
GMStatus_Cnt_M_u8[15]	17	17	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	17	17	✓
GMStatus_Cnt_M_u8[18]	17	17	✓
GMStatus_Cnt_M_u8[19]	17	17	✓
GMStatus_Cnt_M_u8[20]	17	17	✓
GMStatus_Cnt_M_u8[21]	17	17	✓
GMStatus_Cnt_M_u8[22]	17	17	✓
GMStatus_Cnt_M_u8[23]	17	17	✓
GMStatus_Cnt_M_u8[24]	17	17	✓
GMStatus_Cnt_M_u8[25]	17	17	✓
GMStatus_Cnt_M_u8[26]	17	17	✓
GMStatus_Cnt_M_u8[27]	17	17	✓
GMStatus_Cnt_M_u8[28]	17	17	✓
GMStatus_Cnt_M_u8[29]	17	17	✓
GMStatus_Cnt_M_u8[30]	17	17	✓
GMStatus_Cnt_M_u8[31]	17	17	✓
LKATrqOvrDlvdRC_Cnt_M_u8	139	139	✓
LastReportedDTCEventID_Cnt_M_u8	9	9	✓
LastReportedGMStatus_Cnt_M_u8	76	76	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4056460800	4056460800	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrStItTqDlvd	1	IIPutTxLKAEIPwrStItTqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.103 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	10	
CTCEventId_Cnt_M_u8	10	
CurrentDTCSentThisIC_Cnt_M_lgc	0	
DTCDData.DTCTriggered	0	
DTCDData.DTCSource	23	
DTCDData.DTCNumber	12420	
DTCDData.DTCFailType	41	
DTCDData.DTCWrmIndRqdSt	0	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	0	
DTCDData.DTCHistStat	0	
DTCDData.DTCTstFldCdClrdStat	0	
DTCDData.DTCTstNPsdCdClrdSt	0	
DTCDData.DTCCurrentStatus	0	
DTCDData.DTCCodeSupported	0	
DTCDData.DTCFaulttype	113	
DTCTriggeredFlag_Cnt_M_lgc[0]	0	
DTCTriggeredFlag_Cnt_M_lgc[1]	1	
DTCTriggeredFlag_Cnt_M_lgc[2]	0	
DTCTriggeredFlag_Cnt_M_lgc[3]	1	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	0	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	1	
DTCTriggeredFlag_Cnt_M_lgc[10]	0	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	1	
DTCTriggeredFlag_Cnt_M_lgc[14]	0	
DTCTriggeredFlag_Cnt_M_lgc[15]	1	
DTCTriggeredFlag_Cnt_M_lgc[16]	0	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	1	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	0	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	
DTCTriggeredFlag_Cnt_M_lgc[26]	0	
DTCTriggeredFlag_Cnt_M_lgc[27]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	6
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	3
GMStatus_Cnt_M_u8[2]	5
GMStatus_Cnt_M_u8[3]	7
GMStatus_Cnt_M_u8[4]	9
GMStatus_Cnt_M_u8[5]	11
GMStatus_Cnt_M_u8[6]	13
GMStatus_Cnt_M_u8[7]	15
GMStatus_Cnt_M_u8[8]	17
GMStatus_Cnt_M_u8[9]	19
GMStatus_Cnt_M_u8[10]	21
GMStatus_Cnt_M_u8[11]	23
GMStatus_Cnt_M_u8[12]	25
GMStatus_Cnt_M_u8[13]	27
GMStatus_Cnt_M_u8[14]	29
GMStatus_Cnt_M_u8[15]	31
GMStatus_Cnt_M_u8[16]	33
GMStatus_Cnt_M_u8[17]	35
GMStatus_Cnt_M_u8[18]	37
GMStatus_Cnt_M_u8[19]	39
GMStatus_Cnt_M_u8[20]	41
GMStatus_Cnt_M_u8[21]	43
GMStatus_Cnt_M_u8[22]	45
GMStatus_Cnt_M_u8[23]	47
GMStatus_Cnt_M_u8[24]	49
GMStatus_Cnt_M_u8[25]	51
GMStatus_Cnt_M_u8[26]	53
GMStatus_Cnt_M_u8[27]	55
GMStatus_Cnt_M_u8[28]	57
GMStatus_Cnt_M_u8[29]	59
GMStatus_Cnt_M_u8[30]	61
GMStatus_Cnt_M_u8[31]	63
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	224

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKATrqOvrIdlvdRC_Cnt_M_u8	241		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26		
LastReportedDTCEventID_Cnt_M_u8	31		
LastReportedGMStatus_Cnt_M_u8	82		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	676026112		
Steering_Torque_Overlay_Stat_CE_c[0]	12		
Steering_Torque_Overlay_Stat_CE_c[1]	14		
Steering_Torque_Overlay_Stat_CE_c[2]	16		
Steering_Torque_Overlay_Stat_CE_c[3]	18		
Steering_Torque_Overlay_Stat_CE_c[4]	20		
Steering_Torque_Overlay_Stat_CE_c[5]	22		
Steering_Torque_Overlay_Stat_CE_c[6]	24		
Steering_Torque_Overlay_Stat_CE_c[7]	26		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	111		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	113		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	0		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1045652736		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-2.9000001		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.360000014		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	3.70000005		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	0.699999988		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	10	10	✓
CTCEventId_Cnt_M_u8	11	11	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrUpSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	7	7	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	3	3	✓
GMStatus_Cnt_M_u8[2]	5	5	✓
GMStatus_Cnt_M_u8[3]	7	7	✓
GMStatus_Cnt_M_u8[4]	9	9	✓
GMStatus_Cnt_M_u8[5]	11	11	✓
GMStatus_Cnt_M_u8[6]	13	13	✓
GMStatus_Cnt_M_u8[7]	15	15	✓
GMStatus_Cnt_M_u8[8]	17	17	✓
GMStatus_Cnt_M_u8[9]	19	19	✓
GMStatus_Cnt_M_u8[10]	21	21	✓
GMStatus_Cnt_M_u8[11]	23	23	✓
GMStatus_Cnt_M_u8[12]	25	25	✓
GMStatus_Cnt_M_u8[13]	27	27	✓
GMStatus_Cnt_M_u8[14]	29	29	✓
GMStatus_Cnt_M_u8[15]	31	31	✓
GMStatus_Cnt_M_u8[16]	33	33	✓
GMStatus_Cnt_M_u8[17]	35	35	✓
GMStatus_Cnt_M_u8[18]	37	37	✓
GMStatus_Cnt_M_u8[19]	39	39	✓
GMStatus_Cnt_M_u8[20]	41	41	✓
GMStatus_Cnt_M_u8[21]	43	43	✓
GMStatus_Cnt_M_u8[22]	45	45	✓
GMStatus_Cnt_M_u8[23]	47	47	✓
GMStatus_Cnt_M_u8[24]	49	49	✓
GMStatus_Cnt_M_u8[25]	51	51	✓
GMStatus_Cnt_M_u8[26]	53	53	✓
GMStatus_Cnt_M_u8[27]	55	55	✓
GMStatus_Cnt_M_u8[28]	57	57	✓
GMStatus_Cnt_M_u8[29]	59	59	✓
GMStatus_Cnt_M_u8[30]	61	61	✓
GMStatus_Cnt_M_u8[31]	63	63	✓
LKATrqOvriDlvdRC_Cnt_M_u8	242	242	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	82	82	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	676026112	676026112	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SrlComOutput_Per1



Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.104 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	0
CTCEventId_Cnt_M_u8	0
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	24
DTCDData.DTCNumber	61885
DTCDData.DTCFailType	111
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	215
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	11
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	127
LKATrqOvrDivdRC_Cnt_M_u8	62
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52
LastReportedDTCEventID_Cnt_M_u8	33
LastReportedGMStatus_Cnt_M_u8	84
PrevWarningIndSignal_Cnt_M_u8[0]	0
PrevWarningIndSignal_Cnt_M_u8[1]	0
PrevWarningIndSignal_Cnt_M_u8[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	1222163968
Steering_Torque_Overlay_Stat_CE_c[0]	24
Steering_Torque_Overlay_Stat_CE_c[1]	28
Steering_Torque_Overlay_Stat_CE_c[2]	32
Steering_Torque_Overlay_Stat_CE_c[3]	36
Steering_Torque_Overlay_Stat_CE_c[4]	40
Steering_Torque_Overlay_Stat_CE_c[5]	44
Steering_Torque_Overlay_Stat_CE_c[6]	48
Steering_Torque_Overlay_Stat_CE_c[7]	52
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	1
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	112
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	7902208
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-2.70000005
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.0250000004
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	0.620000005
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.39999998

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	220	220	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	12	12	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDvdrRC_Cnt_M_u8	62	62	✓
LastReportedDTCEventID_Cnt_M_u8	0	0	✓
LastReportedGMStatus_Cnt_M_u8	2	2	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_ms_M_u32p0	1222163968	1222163968	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_ms_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_ms_u16	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSources_778	1	IIPutTxDTCl_DTCSources_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmlndRqdSt_778	1	IIPutTxDTCl_WrmlndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.105 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	10
CTCEventId_Cnt_M_u8	10
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSources	25
DTCDData.DTCNumber	1158
DTCDData.DTCFailType	119
DTCDData.DTCWrmlndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	53
DTCTriggeredFlag_Cnt_M_lgc[0]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	5
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	38
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	92
LKATrqOvrrlDlvdRC_Cnt_M_u8	58
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104
LastReportedDTCEventID_Cnt_M_u8	17
LastReportedGMStatus_Cnt_M_u8	86
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKAState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3093112832
Steering_Torque_Overlay_Stat_CE_c[0]	48
Steering_Torque_Overlay_Stat_CE_c[1]	56
Steering_Torque_Overlay_Stat_CE_c[2]	64
Steering_Torque_Overlay_Stat_CE_c[3]	72
Steering_Torque_Overlay_Stat_CE_c[4]	80
Steering_Torque_Overlay_Stat_CE_c[5]	88
Steering_Torque_Overlay_Stat_CE_c[6]	96
Steering_Torque_Overlay_Stat_CE_c[7]	104
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.779999971
k_SComTrqPosPol_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	113
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	53
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	53757
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3689655808
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-2.5
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.25
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-1.79999995
target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data	2
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.79999995

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	10	10	✓
CTCEventId_Cnt_M_u8	11	11	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	4	4	✓
DTCDData.DTCFailType	76	76	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	6	6	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	38	38	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	59	59	✓
LastReportedDTCEventID_Cnt_M_u8	10	10	✓
LastReportedGMStatus_Cnt_M_u8	38	38	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3093112832	3093112832	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIdIO	1	IIPutTxStrngAsstRdcIdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMId	1	IIPutTxHndsOffStrWhlDtMId	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDltTrqDlvd	1	IIPutTxLKATrqOvrIDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.106 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	30

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
CTCEventId_Cnt_M_u8	0
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTTriggered	0
DTCDData.DTCSSource	26
DTCDData.DTCNumber	21115
DTCDData.DTCFailType	253
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	53
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	7
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	3
GMStatus_Cnt_M_u8[2]	5
GMStatus_Cnt_M_u8[3]	7
GMStatus_Cnt_M_u8[4]	9
GMStatus_Cnt_M_u8[5]	11
GMStatus_Cnt_M_u8[6]	13
GMStatus_Cnt_M_u8[7]	15
GMStatus_Cnt_M_u8[8]	17
GMStatus_Cnt_M_u8[9]	19
GMStatus_Cnt_M_u8[10]	21
GMStatus_Cnt_M_u8[11]	23
GMStatus_Cnt_M_u8[12]	25
GMStatus_Cnt_M_u8[13]	27
GMStatus_Cnt_M_u8[14]	29
GMStatus_Cnt_M_u8[15]	31
GMStatus_Cnt_M_u8[16]	33
GMStatus_Cnt_M_u8[17]	35
GMStatus_Cnt_M_u8[18]	37
GMStatus_Cnt_M_u8[19]	39
GMStatus_Cnt_M_u8[20]	41
GMStatus_Cnt_M_u8[21]	43
GMStatus_Cnt_M_u8[22]	45
GMStatus_Cnt_M_u8[23]	47
GMStatus_Cnt_M_u8[24]	49
GMStatus_Cnt_M_u8[25]	51
GMStatus_Cnt_M_u8[26]	53
GMStatus_Cnt_M_u8[27]	55
GMStatus_Cnt_M_u8[28]	57
GMStatus_Cnt_M_u8[29]	59
GMStatus_Cnt_M_u8[30]	61
GMStatus_Cnt_M_u8[31]	63
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	114
LKATrqOvrDlvdRC_Cnt_M_u8	85
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130
LastReportedDTCEventID_Cnt_M_u8	16
LastReportedGMStatus_Cnt_M_u8	88
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3777448704
Steering_Torque_Overlay_Stat_CE_c[0]	60
Steering_Torque_Overlay_Stat_CE_c[1]	70
Steering_Torque_Overlay_Stat_CE_c[2]	80
Steering_Torque_Overlay_Stat_CE_c[3]	90
Steering_Torque_Overlay_Stat_CE_c[4]	100
Steering_Torque_Overlay_Stat_CE_c[5]	110

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
Steering_Torque_Overlay_Stat_CE_c[6]	120		
Steering_Torque_Overlay_Stat_CE_c[7]	130		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.800000012		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	114		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	53		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	53887		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	0		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-2.29999995		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.699999988		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-7.69999981		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	0.00999999978		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	30	30	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✔
DTCData.DTCTriggered	0	0	✔
DTCData.DTCSource	49	49	✔
DTCData.DTCNumber	1	1	✔
DTCData.DTCFailType	99	99	✔
DTCData.DTCWmIndRqdSt	0	0	✔
DTCData.DTCTstFldPwrUpSt	1	1	✔
DTCData.DTCTstNPsdPwrupSt	0	0	✔
DTCData.DTCHistStat	1	1	✔
DTCData.DTCTstFldCdCldStat	1	1	✔
DTCData.DTCTstNPsdCdCldSt	0	0	✔
DTCData.DTCCurrentStatus	0	0	✔
DTCData.DTCCodeSupported	0	0	✔
DTCData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[21]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	8	8	✔
GMStatus_Cnt_M_u8[0]	1	1	✔
GMStatus_Cnt_M_u8[1]	3	3	✔
GMStatus_Cnt_M_u8[2]	5	5	✔
GMStatus_Cnt_M_u8[3]	7	7	✔
GMStatus_Cnt_M_u8[4]	9	9	✔
GMStatus_Cnt_M_u8[5]	11	11	✔
GMStatus_Cnt_M_u8[6]	13	13	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[7]	15	15	✓
GMStatus_Cnt_M_u8[8]	17	17	✓
GMStatus_Cnt_M_u8[9]	19	19	✓
GMStatus_Cnt_M_u8[10]	21	21	✓
GMStatus_Cnt_M_u8[11]	23	23	✓
GMStatus_Cnt_M_u8[12]	25	25	✓
GMStatus_Cnt_M_u8[13]	27	27	✓
GMStatus_Cnt_M_u8[14]	29	29	✓
GMStatus_Cnt_M_u8[15]	31	31	✓
GMStatus_Cnt_M_u8[16]	33	33	✓
GMStatus_Cnt_M_u8[17]	35	35	✓
GMStatus_Cnt_M_u8[18]	37	37	✓
GMStatus_Cnt_M_u8[19]	39	39	✓
GMStatus_Cnt_M_u8[20]	41	41	✓
GMStatus_Cnt_M_u8[21]	43	43	✓
GMStatus_Cnt_M_u8[22]	45	45	✓
GMStatus_Cnt_M_u8[23]	47	47	✓
GMStatus_Cnt_M_u8[24]	49	49	✓
GMStatus_Cnt_M_u8[25]	51	51	✓
GMStatus_Cnt_M_u8[26]	53	53	✓
GMStatus_Cnt_M_u8[27]	55	55	✓
GMStatus_Cnt_M_u8[28]	57	57	✓
GMStatus_Cnt_M_u8[29]	59	59	✓
GMStatus_Cnt_M_u8[30]	61	61	✓
GMStatus_Cnt_M_u8[31]	63	63	✓
LKATrqOvrIDvdrC_Cnt_M_u8	85	85	✓
LastReportedDTCEventID_Cnt_M_u8	16	16	✓
LastReportedGMStatus_Cnt_M_u8	88	88	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3777448704	3777448704	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcldIO	1	IIPutTxStrngAsstRdcldIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.107 (Repeat Count = 1)

Name	Input Value
CTCEventIdSV_Cnt_M_u8	28
CTCEventId_Cnt_M_u8	5

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSource	27
DTCDData.DTCNumber	24831
DTCDData.DTCFailType	196
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	222
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	6
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	89
LKATrqOvriDlvdRC_Cnt_M_u8	250
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	20
LastReportedGMStatus_Cnt_M_u8	90
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKAState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	2624068864
Steering_Torque_Overlay_Stat_CE_c[0]	84
Steering_Torque_Overlay_Stat_CE_c[1]	98
Steering_Torque_Overlay_Stat_CE_c[2]	112
Steering_Torque_Overlay_Stat_CE_c[3]	126
Steering_Torque_Overlay_Stat_CE_c[4]	140
Steering_Torque_Overlay_Stat_CE_c[5]	154
Steering_Torque_Overlay_Stat_CE_c[6]	168

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.819999993		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	115		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	222		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	61250		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	4294967295		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-2.0999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.796999991		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	6.46000004		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-1.70000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	5	5	✓
CTCEventId_Cnt_M_u8	5	5	✓
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	64	64	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	7	7	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	251	251	✓
LastReportedDTCEventID_Cnt_M_u8	20	20	✓
LastReportedGMStatus_Cnt_M_u8	90	90	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4294967295	4294967295	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.108 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	6
CTCEventId_Cnt_M_u8	0
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	28
DTCDData.DTCNumber	42083
DTCDData.DTCFailType	182
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaultType	8
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	6
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	40		
GMStatus_Cnt_M_u8[10]	44		
GMStatus_Cnt_M_u8[11]	48		
GMStatus_Cnt_M_u8[12]	52		
GMStatus_Cnt_M_u8[13]	56		
GMStatus_Cnt_M_u8[14]	60		
GMStatus_Cnt_M_u8[15]	64		
GMStatus_Cnt_M_u8[16]	68		
GMStatus_Cnt_M_u8[17]	72		
GMStatus_Cnt_M_u8[18]	76		
GMStatus_Cnt_M_u8[19]	80		
GMStatus_Cnt_M_u8[20]	84		
GMStatus_Cnt_M_u8[21]	88		
GMStatus_Cnt_M_u8[22]	92		
GMStatus_Cnt_M_u8[23]	96		
GMStatus_Cnt_M_u8[24]	100		
GMStatus_Cnt_M_u8[25]	104		
GMStatus_Cnt_M_u8[26]	108		
GMStatus_Cnt_M_u8[27]	112		
GMStatus_Cnt_M_u8[28]	116		
GMStatus_Cnt_M_u8[29]	120		
GMStatus_Cnt_M_u8[30]	124		
GMStatus_Cnt_M_u8[31]	128		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	115		
LKATrqOvrlDlvdRC_Cnt_M_u8	206		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventID_Cnt_M_u8	11		
LastReportedGMStatus_Cnt_M_u8	92		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	1058696192		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.839999974		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	116		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	17516		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3426999552		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-1.89999998		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.165999994		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-0.300000012		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.14999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	0	0	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTTriggered	1	1	✓
DTCDData.DTCSSource	49	49	✓
DTCDData.DTCNumber	5	5	✓
DTCDData.DTCFailType	220	220	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	6	6	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDlvdRC_Cnt_M_u8	206	206	✓
LastReportedDTCEventID_Cnt_M_u8	11	11	✓
LastReportedGMStatus_Cnt_M_u8	92	92	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3426999552	3426999552	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcldIO	1	IIPutTxStrngAsstRdcldIO	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSTItTqDlrd	1	IIPutTxElPwrSTItTqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrcSource_778	1	IIPutTxDTCl_DTCSrcSource_778	1	✓
IIPutTxDTCl_DTCCNumber_778	1	IIPutTxDTCl_DTCCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.109 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	23
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	29
DTCDData.DTCNumber	892
DTCDData.DTCFailType	195
DTCDData.DTCWrmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	215
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	13
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	44		
GMStatus_Cnt_M_u8[11]	48		
GMStatus_Cnt_M_u8[12]	52		
GMStatus_Cnt_M_u8[13]	56		
GMStatus_Cnt_M_u8[14]	60		
GMStatus_Cnt_M_u8[15]	64		
GMStatus_Cnt_M_u8[16]	68		
GMStatus_Cnt_M_u8[17]	72		
GMStatus_Cnt_M_u8[18]	76		
GMStatus_Cnt_M_u8[19]	80		
GMStatus_Cnt_M_u8[20]	84		
GMStatus_Cnt_M_u8[21]	88		
GMStatus_Cnt_M_u8[22]	92		
GMStatus_Cnt_M_u8[23]	96		
GMStatus_Cnt_M_u8[24]	100		
GMStatus_Cnt_M_u8[25]	104		
GMStatus_Cnt_M_u8[26]	108		
GMStatus_Cnt_M_u8[27]	112		
GMStatus_Cnt_M_u8[28]	116		
GMStatus_Cnt_M_u8[29]	120		
GMStatus_Cnt_M_u8[30]	124		
GMStatus_Cnt_M_u8[31]	128		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	0		
LKATrqOvriDlvdRC_Cnt_M_u8	138		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventID_Cnt_M_u8	9		
LastReportedGMStatus_Cnt_M_u8	94		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	4056460800		
Steering_Torque_Overlay_Stat_CE_c[0]	24		
Steering_Torque_Overlay_Stat_CE_c[1]	28		
Steering_Torque_Overlay_Stat_CE_c[2]	32		
Steering_Torque_Overlay_Stat_CE_c[3]	36		
Steering_Torque_Overlay_Stat_CE_c[4]	40		
Steering_Torque_Overlay_Stat_CE_c[5]	44		
Steering_Torque_Overlay_Stat_CE_c[6]	48		
Steering_Torque_Overlay_Stat_CE_c[7]	52		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.860000014		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	117		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	0		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	46606		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3248030720		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-1.70000005		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	1		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	5.82000017		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	23	23	✓
CTCEventId_Cnt_M_u8	15	15	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	3	3	✓
DTCDData.DTCFailType	232	232	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	14	14	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDlvdRC_Cnt_M_u8	138	138	✓
LastReportedDTCEventID_Cnt_M_u8	9	9	✓
LastReportedGMStatus_Cnt_M_u8	94	94	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4056460800	4056460800	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.110 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	32
CTCEventId_Cnt_M_u8	26
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	30
DTCDData.DTCTNumber	62641
DTCDData.DTCTFailType	18
DTCDData.DTCTWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCTHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCTCurrentStatus	0
DTCDData.DTCTCodeSupported	0
DTCDData.DTCTFaultType	50
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	12
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[12]	39		
GMStatus_Cnt_M_u8[13]	42		
GMStatus_Cnt_M_u8[14]	45		
GMStatus_Cnt_M_u8[15]	48		
GMStatus_Cnt_M_u8[16]	51		
GMStatus_Cnt_M_u8[17]	54		
GMStatus_Cnt_M_u8[18]	57		
GMStatus_Cnt_M_u8[19]	60		
GMStatus_Cnt_M_u8[20]	63		
GMStatus_Cnt_M_u8[21]	66		
GMStatus_Cnt_M_u8[22]	69		
GMStatus_Cnt_M_u8[23]	72		
GMStatus_Cnt_M_u8[24]	75		
GMStatus_Cnt_M_u8[25]	78		
GMStatus_Cnt_M_u8[26]	81		
GMStatus_Cnt_M_u8[27]	84		
GMStatus_Cnt_M_u8[28]	87		
GMStatus_Cnt_M_u8[29]	90		
GMStatus_Cnt_M_u8[30]	93		
GMStatus_Cnt_M_u8[31]	96		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	255		
LKATrqOvrDlvdRC_Cnt_M_u8	37		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	42		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	54		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	66		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	78		
LastReportedDTCEventID_Cnt_M_u8	21		
LastReportedGMStatus_Cnt_M_u8	96		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	847034624		
Steering_Torque_Overlay_Stat_CE_c[0]	36		
Steering_Torque_Overlay_Stat_CE_c[1]	42		
Steering_Torque_Overlay_Stat_CE_c[2]	48		
Steering_Torque_Overlay_Stat_CE_c[3]	54		
Steering_Torque_Overlay_Stat_CE_c[4]	60		
Steering_Torque_Overlay_Stat_CE_c[5]	66		
Steering_Torque_Overlay_Stat_CE_c[6]	72		
Steering_Torque_Overlay_Stat_CE_c[7]	78		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.879999995		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	118		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	60171		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	400799488		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-1.5		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.200000003		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	2.51699996		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.5		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	32	32	✔
CTCEventId_Cnt_M_u8	27	27	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCDData.DTCSrcSource	49	49	✓
DTCDData.DTCNNumber	1	1	✓
DTCDData.DTCFailType	174	174	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	13	13	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	38	38	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	96	96	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	847034624	847034624	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrcSource_778	1	IIPutTxDTCl_DTCSrcSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.111 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	23
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSrcSource	31
DTCDData.DTCNumber	13756
DTCDData.DTCFailType	161
DTCDData.DTCWrnIndRqdSt	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	14
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	14
LKATrqOvriDlvdRC_Cnt_M_u8	117
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104
LastReportedDTCEventID_Cnt_M_u8	18
LastReportedGMStatus_Cnt_M_u8	98
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	575444992
Steering_Torque_Overlay_Stat_CE_c[0]	48
Steering_Torque_Overlay_Stat_CE_c[1]	56
Steering_Torque_Overlay_Stat_CE_c[2]	64
Steering_Torque_Overlay_Stat_CE_c[3]	72
Steering_Torque_Overlay_Stat_CE_c[4]	80
Steering_Torque_Overlay_Stat_CE_c[5]	88
Steering_Torque_Overlay_Stat_CE_c[6]	96
Steering_Torque_Overlay_Stat_CE_c[7]	104
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.8999999976
k_SComTrqPosPoL_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	119
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	26753		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3549404672		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-1.29999995		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.294		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	7.48000002		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.60000002		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	12	12	✓
CTCEventId_Cnt_M_u8	24	24	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	129	129	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	3	3	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrIDvdrC_Cnt_M_u8	117	117	✓
LastReportedDTCEventID_Cnt_M_u8	18	18	✓
LastReportedGMStatus_Cnt_M_u8	98	98	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCTFlag_ms_M_u32p0	575444992	575444992	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvdrARC	1	IIPutTxTrqOvrIDvdrARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSources_778	1	IIPutTxDTCL_DTCSources_778	1	✓
IIPutTxDTCL_DTCTNumber_778	1	IIPutTxDTCL_DTCTNumber_778	1	✓
IIPutTxDTCL_DTCTFailType_778	1	IIPutTxDTCL_DTCTFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCTFaultType_778	1	IIPutTxDTCL_DTCTFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.112 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	19
CTCEventId_Cnt_M_u8	13
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSources	9
DTCDData.DTCTNumber	32160
DTCDData.DTCTFailType	122
DTCDData.DTCTWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	58
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
ESCRollCount_Cnt_M_u08	4
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	89
LKATrqOvrldlvdRC_Cnt_M_u8	77
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	7
LastReportedGMStatus_Cnt_M_u8	53
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	283927808
Steering_Torque_Overlay_Stat_CE_c[0]	84
Steering_Torque_Overlay_Stat_CE_c[1]	98
Steering_Torque_Overlay_Stat_CE_c[2]	112
Steering_Torque_Overlay_Stat_CE_c[3]	126
Steering_Torque_Overlay_Stat_CE_c[4]	140
Steering_Torque_Overlay_Stat_CE_c[5]	154
Steering_Torque_Overlay_Stat_CE_c[6]	168
Steering_Torque_Overlay_Stat_CE_c[7]	182
k_LKAMfgEnable_Cnt_Igc	1
k_MaxHOWEstimate_Uls_f32	0.349999994
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	120
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	58
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	38829

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	221381376		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-10.2399998		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.699999988		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	3.06999993		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-1.99100006		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	19	19	✓
CTCEventId_Cnt_M_u8	14	14	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSrc	49	49	✓
DTCDData.DTCNbr	0	0	✓
DTCDData.DTCFailType	220	220	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaultType	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	5	5	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	78	78	✓
LastReportedDTCEventID_Cnt_M_u8	7	7	✓
LastReportedGMStatus_Cnt_M_u8	53	53	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	283927808	283927808	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcldIO	1	IIPutTxStrngAsstRdcldIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SrlComOutput_Per1



Test Step 2.113 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	24
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSrcSource	13
DTCDData.DTCNumber	43937
DTCDData.DTCFailType	236
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	7
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	1
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	115
LKATrqOvrDIvdRC_Cnt_M_u8	240
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208
LastReportedDTCEventID_Cnt_M_u8	21
LastReportedGMStatus_Cnt_M_u8	55
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	749573120
Steering_Torque_Overlay_Stat_CE_c[0]	96

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.370000005		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	121		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	62026		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3688151552		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	10.22999995		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.899999976		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	3.59999999		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	0.75		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	14	14	✔
CTCEventId_Cnt_M_u8	14	14	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	1	1	✔
DTCDData.DTCFailType	244	244	✔
DTCDData.DTCWmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	2	2	✔
GMStatus_Cnt_M_u8[0]	2	2	✔
GMStatus_Cnt_M_u8[1]	4	4	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrDlvdRC_Cnt_M_u8	241	241	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	55	55	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3688151552	3688151552	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCI_DTCTriggered_778	1	IIPutTxDTCI_DTCTriggered_778	1	✓
IIPutTxDTCI_DTCSOURCE_778	1	IIPutTxDTCI_DTCSOURCE_778	1	✓
IIPutTxDTCI_DTCNumber_778	1	IIPutTxDTCI_DTCNumber_778	1	✓
IIPutTxDTCI_DTCFailType_778	1	IIPutTxDTCI_DTCFailType_778	1	✓
IIPutTxDTCI_CodeSupported_778	1	IIPutTxDTCI_CodeSupported_778	1	✓
IIPutTxDTCI_CurrentStatus_778	1	IIPutTxDTCI_CurrentStatus_778	1	✓
IIPutTxDTCI_TstNPsdCdClrdSt_778	1	IIPutTxDTCI_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCI_TstFldCdClrdStat_778	1	IIPutTxDTCI_TstFldCdClrdStat_778	1	✓
IIPutTxDTCI_HistStat_778	1	IIPutTxDTCI_HistStat_778	1	✓
IIPutTxDTCI_TstNPsdPwrUpSt_778	1	IIPutTxDTCI_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCI_TstFldPwrUpSt_778	1	IIPutTxDTCI_TstFldPwrUpSt_778	1	✓
IIPutTxDTCI_WrnIndRqdSt_778	1	IIPutTxDTCI_WrnIndRqdSt_778	1	✓
IIPutTxDTCI_DTCFaultType_778	1	IIPutTxDTCI_DTCFaultType_778	1	✓
IIPutTxDTCTInfo_778	1	IIPutTxDTCTInfo_778	1	✓

Test Step 2.114 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	23
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	0
DTCDData.DTCNumber	892
DTCDData.DTCFailType	195
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	215
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	3
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	40		
GMStatus_Cnt_M_u8[10]	44		
GMStatus_Cnt_M_u8[11]	48		
GMStatus_Cnt_M_u8[12]	52		
GMStatus_Cnt_M_u8[13]	56		
GMStatus_Cnt_M_u8[14]	60		
GMStatus_Cnt_M_u8[15]	64		
GMStatus_Cnt_M_u8[16]	68		
GMStatus_Cnt_M_u8[17]	72		
GMStatus_Cnt_M_u8[18]	76		
GMStatus_Cnt_M_u8[19]	80		
GMStatus_Cnt_M_u8[20]	84		
GMStatus_Cnt_M_u8[21]	88		
GMStatus_Cnt_M_u8[22]	92		
GMStatus_Cnt_M_u8[23]	96		
GMStatus_Cnt_M_u8[24]	100		
GMStatus_Cnt_M_u8[25]	104		
GMStatus_Cnt_M_u8[26]	108		
GMStatus_Cnt_M_u8[27]	112		
GMStatus_Cnt_M_u8[28]	116		
GMStatus_Cnt_M_u8[29]	120		
GMStatus_Cnt_M_u8[30]	124		
GMStatus_Cnt_M_u8[31]	128		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	99		
LKATrqOvriDlvdRC_Cnt_M_u8	138		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventID_Cnt_M_u8	9		
LastReportedGMStatus_Cnt_M_u8	57		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	4056460800		
Steering_Torque_Overlay_Stat_CE_c[0]	24		
Steering_Torque_Overlay_Stat_CE_c[1]	28		
Steering_Torque_Overlay_Stat_CE_c[2]	32		
Steering_Torque_Overlay_Stat_CE_c[3]	36		
Steering_Torque_Overlay_Stat_CE_c[4]	40		
Steering_Torque_Overlay_Stat_CE_c[5]	44		
Steering_Torque_Overlay_Stat_CE_c[6]	48		
Steering_Torque_Overlay_Stat_CE_c[7]	52		
k_LKAMfgEnable_Cnt_lgc	0		
k_MaxHOWEstimate_Uls_f32	0.389999986		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	122		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	215		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	46606		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3248030720		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	0		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.769999981		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-4.46000004		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	23	23	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	15	15	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	3	3	✓
DTCDData.DTCFailType	232	232	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	4	4	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	104	104	✓
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDlvdRC_Cnt_M_u8	138	138	✓
LastReportedDTCEventID_Cnt_M_u8	9	9	✓
LastReportedGMStatus_Cnt_M_u8	57	57	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4056460800	4056460800	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.115 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	32
CTCEventId_Cnt_M_u8	26
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSorce	49
DTCDData.DTCNumber	62641
DTCDData.DTCFailType	18
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaultype	50
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	8
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[11]	36		
GMStatus_Cnt_M_u8[12]	39		
GMStatus_Cnt_M_u8[13]	42		
GMStatus_Cnt_M_u8[14]	45		
GMStatus_Cnt_M_u8[15]	48		
GMStatus_Cnt_M_u8[16]	51		
GMStatus_Cnt_M_u8[17]	54		
GMStatus_Cnt_M_u8[18]	57		
GMStatus_Cnt_M_u8[19]	60		
GMStatus_Cnt_M_u8[20]	63		
GMStatus_Cnt_M_u8[21]	66		
GMStatus_Cnt_M_u8[22]	69		
GMStatus_Cnt_M_u8[23]	72		
GMStatus_Cnt_M_u8[24]	75		
GMStatus_Cnt_M_u8[25]	78		
GMStatus_Cnt_M_u8[26]	81		
GMStatus_Cnt_M_u8[27]	84		
GMStatus_Cnt_M_u8[28]	87		
GMStatus_Cnt_M_u8[29]	90		
GMStatus_Cnt_M_u8[30]	93		
GMStatus_Cnt_M_u8[31]	96		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	205		
LKATrqOvrldDlvdRC_Cnt_M_u8	37		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	42		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	54		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	60		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	66		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	78		
LastReportedDTCEventID_Cnt_M_u8	21		
LastReportedGMStatus_Cnt_M_u8	59		
PrevWarningIndSignal_Cnt_M_u8[0]	1		
PrevWarningIndSignal_Cnt_M_u8[1]	1		
PrevWarningIndSignal_Cnt_M_u8[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	847034624		
Steering_Torque_Overlay_Stat_CE_c[0]	36		
Steering_Torque_Overlay_Stat_CE_c[1]	42		
Steering_Torque_Overlay_Stat_CE_c[2]	48		
Steering_Torque_Overlay_Stat_CE_c[3]	54		
Steering_Torque_Overlay_Stat_CE_c[4]	60		
Steering_Torque_Overlay_Stat_CE_c[5]	66		
Steering_Torque_Overlay_Stat_CE_c[6]	72		
Steering_Torque_Overlay_Stat_CE_c[7]	78		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.409999996		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	123		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	60171		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	400799488		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	4.699999981		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.400000006		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-4.13000011		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.49000001		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	32	32	✓
CTCEventId_Cnt_M_u8	27	27	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCDData.DTCTTriggered	0	0	✓
DTCDData.DTCSrcSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	174	174	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdpwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdpCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	9	9	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvriDlvdRC_Cnt_M_u8	38	38	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	59	59	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	847034624	847034624	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcclIO	1	IIPutTxStrngAsstRdcclIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStTtITqDlrd	1	IIPutTxElPwrStTtITqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDlITrqDlrd	1	IIPutTxTrqOvriDlITrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKAState_State_enum	1	Rte_Read_Ap_SriComOutput_LKAState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrStTtITqDlvd	1	IIPutTxLKAEIPwrStTtITqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDlITrqDlvd	1	IIPutTxLKATrqOvriDlITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.116 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	23
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	12
DTCDData.DTCNumber	13756
DTCDData.DTCFailType	161

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	14
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	16
LKATrqOvriDlvdRC_Cnt_M_u8	117
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104
LastReportedDTCEventID_Cnt_M_u8	18
LastReportedGMStatus_Cnt_M_u8	61
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	575444992
Steering_Torque_Overlay_Stat_CE_c[0]	48
Steering_Torque_Overlay_Stat_CE_c[1]	56
Steering_Torque_Overlay_Stat_CE_c[2]	64
Steering_Torque_Overlay_Stat_CE_c[3]	72
Steering_Torque_Overlay_Stat_CE_c[4]	80
Steering_Torque_Overlay_Stat_CE_c[5]	88
Steering_Torque_Overlay_Stat_CE_c[6]	96
Steering_Torque_Overlay_Stat_CE_c[7]	104
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.430000007
k_SComTrqPosPol_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	124

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	14		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	26753		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3549404672		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-4.0999999		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.119999997		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	7.42000008		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.20000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	12	12	✔
CTCEventId_Cnt_M_u8	24	24	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	1	1	✔
DTCDData.DTCFailType	129	129	✔
DTCDData.DTCWmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	1	1	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	1	1	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	10	10	✔
GMStatus_Cnt_M_u8[0]	2	2	✔
GMStatus_Cnt_M_u8[1]	4	4	✔
GMStatus_Cnt_M_u8[2]	6	6	✔
GMStatus_Cnt_M_u8[3]	8	8	✔
GMStatus_Cnt_M_u8[4]	10	10	✔
GMStatus_Cnt_M_u8[5]	12	12	✔
GMStatus_Cnt_M_u8[6]	14	14	✔
GMStatus_Cnt_M_u8[7]	16	16	✔
GMStatus_Cnt_M_u8[8]	18	18	✔
GMStatus_Cnt_M_u8[9]	20	20	✔
GMStatus_Cnt_M_u8[10]	22	22	✔
GMStatus_Cnt_M_u8[11]	24	24	✔
GMStatus_Cnt_M_u8[12]	26	26	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	117	117	✓
LastReportedDTCEventID_Cnt_M_u8	18	18	✓
LastReportedGMStatus_Cnt_M_u8	61	61	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	575444992	575444992	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcldIO	1	IIPutTxStrngAsstRdcldIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrcSource_778	1	IIPutTxDTCl_DTCSrcSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.117 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	4
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSrcSource	2
DTCDData.DTCNumber	0
DTCDData.DTCFailType	175
DTCDData.DTCWrnIndRqdSt	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	100
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	10
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	54
LKATrqOvriDlvdRC_Cnt_M_u8	78
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	63
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3977837312
Steering_Torque_Overlay_Stat_CE_c[0]	60
Steering_Torque_Overlay_Stat_CE_c[1]	70
Steering_Torque_Overlay_Stat_CE_c[2]	80
Steering_Torque_Overlay_Stat_CE_c[3]	90
Steering_Torque_Overlay_Stat_CE_c[4]	100
Steering_Torque_Overlay_Stat_CE_c[5]	110
Steering_Torque_Overlay_Stat_CE_c[6]	120
Steering_Torque_Overlay_Stat_CE_c[7]	130
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.449999988
k_SComTrqPosPoL_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	125
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	19163		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2498226432		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	1.20000005		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.419999987		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	7.30000019		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	2.0999999		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	4	4	✓
CTCEventId_Cnt_M_u8	15	15	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	3	3	✓
DTCDData.DTCFailType	72	72	✓
DTCDData.DTCWrnIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	11	11	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDvdRC_Cnt_M_u8	78	78	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	63	63	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3977837312	3977837312	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrIDtrqDStat	1	IIPutTxTrqOvrIDtrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSrcSource_778	1	IIPutTxDTCl_DTCSrcSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.118 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	15
CTCEventId_Cnt_M_u8	34
CurrentDTCSThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	4
DTCDData.DTCNumber	65535
DTCDData.DTCFailType	199
DTCDData.DTCWrnIndRqdSt	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	148
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	14
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	166
LKATrqOvriDlvdRC_Cnt_M_u8	210
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	13
LastReportedGMStatus_Cnt_M_u8	65
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	2919223808
Steering_Torque_Overlay_Stat_CE_c[0]	72
Steering_Torque_Overlay_Stat_CE_c[1]	84
Steering_Torque_Overlay_Stat_CE_c[2]	96
Steering_Torque_Overlay_Stat_CE_c[3]	108
Steering_Torque_Overlay_Stat_CE_c[4]	120
Steering_Torque_Overlay_Stat_CE_c[5]	132
Steering_Torque_Overlay_Stat_CE_c[6]	144
Steering_Torque_Overlay_Stat_CE_c[7]	156
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.4699999999
k_SComTrqPosPoL_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	126
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	148

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	33689		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3821733888		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	4.30000019		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.300000012		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	2.29999995		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-0.800000012		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	15	15	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSorce	4	4	✓
DTCDData.DTCNumber	65535	65535	✓
DTCDData.DTCFailType	199	199	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	148	148	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	15	15	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	17	17	✓
GMStatus_Cnt_M_u8[2]	17	17	✓
GMStatus_Cnt_M_u8[3]	17	17	✓
GMStatus_Cnt_M_u8[4]	17	17	✓
GMStatus_Cnt_M_u8[5]	17	17	✓
GMStatus_Cnt_M_u8[6]	17	17	✓
GMStatus_Cnt_M_u8[7]	17	17	✓
GMStatus_Cnt_M_u8[8]	17	17	✓
GMStatus_Cnt_M_u8[9]	17	17	✓
GMStatus_Cnt_M_u8[10]	17	17	✓
GMStatus_Cnt_M_u8[11]	17	17	✓
GMStatus_Cnt_M_u8[12]	17	17	✓
GMStatus_Cnt M_u8[13]	17	17	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[14]	17	17	✓
GMStatus_Cnt_M_u8[15]	17	17	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	17	17	✓
GMStatus_Cnt_M_u8[18]	17	17	✓
GMStatus_Cnt_M_u8[19]	17	17	✓
GMStatus_Cnt_M_u8[20]	17	17	✓
GMStatus_Cnt_M_u8[21]	17	17	✓
GMStatus_Cnt_M_u8[22]	17	17	✓
GMStatus_Cnt_M_u8[23]	17	17	✓
GMStatus_Cnt_M_u8[24]	17	17	✓
GMStatus_Cnt_M_u8[25]	17	17	✓
GMStatus_Cnt_M_u8[26]	17	17	✓
GMStatus_Cnt_M_u8[27]	17	17	✓
GMStatus_Cnt_M_u8[28]	17	17	✓
GMStatus_Cnt_M_u8[29]	17	17	✓
GMStatus_Cnt_M_u8[30]	17	17	✓
GMStatus_Cnt_M_u8[31]	17	17	✓
LKATrqOvrDivdRC_Cnt_M_u8	210	210	✓
LastReportedDTCEventID_Cnt_M_u8	13	13	✓
LastReportedGMStatus_Cnt_M_u8	65	65	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2919223808	2919223808	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.119 (Repeat Count = 1) ✓

Name	Input Value
CTCEventIdSV_Cnt_M_u8	27
CTCEventId_Cnt_M_u8	23
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	6
DTCDData.DTCNumber	38439
DTCDData.DTCFailType	103
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	152
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	11
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	158
LKATrqOvrlDlvdRC_Cnt_M_u8	206
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	98
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	126
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	140
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	154
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	168
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	182
LastReportedDTCEventID_Cnt_M_u8	9
LastReportedGMStatus_Cnt_M_u8	67
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	929516800		
Steering_Torque_Overlay_Stat_CE_c[0]	84		
Steering_Torque_Overlay_Stat_CE_c[1]	98		
Steering_Torque_Overlay_Stat_CE_c[2]	112		
Steering_Torque_Overlay_Stat_CE_c[3]	126		
Steering_Torque_Overlay_Stat_CE_c[4]	140		
Steering_Torque_Overlay_Stat_CE_c[5]	154		
Steering_Torque_Overlay_Stat_CE_c[6]	168		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.49000001		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	127		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	152		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	27131		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3999116032		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	4.4000001		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.800000012		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.77999997		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	27	27	✔
CTCEventId_Cnt_M_u8	24	24	✔
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	0	0	✔
DTCDData.DTCFailType	0	0	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	0	0	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	12	12	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrldIvdRC_Cnt_M_u8	207	207	✓
LastReportedDTCEventID_Cnt_M_u8	9	9	✓
LastReportedGMStatus_Cnt_M_u8	67	67	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	929516800	929516800	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrItqDStat	1	IIPutTxTrqOvrItqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtmD	1	IIPutTxHndsOffStrWhlDtmD	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrItqDStat	1	IIPutTxLKATrqOvrItqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIDStatChksm	1	IIPutTxLKATrqOvrIDStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.120 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	18
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSOURCE	8
DTCDData.DTCTNumber	18845
DTCDData.DTCTFailType	0
DTCDData.DTCTWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCTHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCTCurrentStatus	0
DTCDData.DTCTCodeSupported	1
DTCDData.DTCTFaulttype	67
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	5
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[10]	44		
GMStatus_Cnt_M_u8[11]	48		
GMStatus_Cnt_M_u8[12]	52		
GMStatus_Cnt_M_u8[13]	56		
GMStatus_Cnt_M_u8[14]	60		
GMStatus_Cnt_M_u8[15]	64		
GMStatus_Cnt_M_u8[16]	68		
GMStatus_Cnt_M_u8[17]	72		
GMStatus_Cnt_M_u8[18]	76		
GMStatus_Cnt_M_u8[19]	80		
GMStatus_Cnt_M_u8[20]	84		
GMStatus_Cnt_M_u8[21]	88		
GMStatus_Cnt_M_u8[22]	92		
GMStatus_Cnt_M_u8[23]	96		
GMStatus_Cnt_M_u8[24]	100		
GMStatus_Cnt_M_u8[25]	104		
GMStatus_Cnt_M_u8[26]	108		
GMStatus_Cnt_M_u8[27]	112		
GMStatus_Cnt_M_u8[28]	116		
GMStatus_Cnt_M_u8[29]	120		
GMStatus_Cnt_M_u8[30]	124		
GMStatus_Cnt_M_u8[31]	128		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	17		
LKATrqOvriDlvdRC_Cnt_M_u8	55		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208		
LastReportedDTCEventID_Cnt_M_u8	31		
LastReportedGMStatus_Cnt_M_u8	69		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCTFlag_mS_M_u32p0	2799492096		
Steering_Torque_Overlay_Stat_CE_c[0]	96		
Steering_Torque_Overlay_Stat_CE_c[1]	112		
Steering_Torque_Overlay_Stat_CE_c[2]	128		
Steering_Torque_Overlay_Stat_CE_c[3]	144		
Steering_Torque_Overlay_Stat_CE_c[4]	160		
Steering_Torque_Overlay_Stat_CE_c[5]	176		
Steering_Torque_Overlay_Stat_CE_c[6]	192		
Steering_Torque_Overlay_Stat_CE_c[7]	208		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.50999999		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	128		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	67		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	29952		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3639722496		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	4.5		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.129999995		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	9.13000011		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-0.939999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	12	12	✓
CTCEventId_Cnt_M_u8	19	19	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNNumber	2	*none*	✓
DTCDData.DTCFailType	68	*none*	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	6	6	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	8	8	✓
GMStatus_Cnt_M_u8[2]	12	12	✓
GMStatus_Cnt_M_u8[3]	16	16	✓
GMStatus_Cnt_M_u8[4]	20	20	✓
GMStatus_Cnt_M_u8[5]	24	24	✓
GMStatus_Cnt_M_u8[6]	28	28	✓
GMStatus_Cnt_M_u8[7]	32	32	✓
GMStatus_Cnt_M_u8[8]	36	36	✓
GMStatus_Cnt_M_u8[9]	40	40	✓
GMStatus_Cnt_M_u8[10]	44	44	✓
GMStatus_Cnt_M_u8[11]	48	48	✓
GMStatus_Cnt_M_u8[12]	52	52	✓
GMStatus_Cnt_M_u8[13]	56	56	✓
GMStatus_Cnt_M_u8[14]	60	60	✓
GMStatus_Cnt_M_u8[15]	64	64	✓
GMStatus_Cnt_M_u8[16]	68	68	✓
GMStatus_Cnt_M_u8[17]	72	72	✓
GMStatus_Cnt_M_u8[18]	76	76	✓
GMStatus_Cnt_M_u8[19]	80	80	✓
GMStatus_Cnt_M_u8[20]	84	84	✓
GMStatus_Cnt_M_u8[21]	88	88	✓
GMStatus_Cnt_M_u8[22]	92	92	✓
GMStatus_Cnt_M_u8[23]	96	96	✓
GMStatus_Cnt_M_u8[24]	100	100	✓
GMStatus_Cnt_M_u8[25]	104	104	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[26]	108	108	✓
GMStatus_Cnt_M_u8[27]	112	112	✓
GMStatus_Cnt_M_u8[28]	116	116	✓
GMStatus_Cnt_M_u8[29]	120	120	✓
GMStatus_Cnt_M_u8[30]	124	124	✓
GMStatus_Cnt_M_u8[31]	128	128	✓
LKATrqOvriDlvdRC_Cnt_M_u8	56	56	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	69	69	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2799492096	2799492096	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItItqDlrd	1	IIPutTxElPwrStItItqDlrd	1	✓
IIPutTxTrqOvriTrqDStat	1	IIPutTxTrqOvriTrqDStat	1	✓
IIPutTxTrqOvriDvrdARC	1	IIPutTxTrqOvriDvrdARC	1	✓
IIPutTxTrqOvriDltTrqDlrd	1	IIPutTxTrqOvriDltTrqDlrd	1	✓
IIPutTxTrqOvriDChksm	1	IIPutTxTrqOvriDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDltSt	1	IIPutTxHndsOffStrWhlDltSt	1	✓
IIPutTxHndsOffStrWhlDltMtd	1	IIPutTxHndsOffStrWhlDltMtd	1	✓
IIPutTxHndsOffStrWhlDltStV	1	IIPutTxHndsOffStrWhlDltStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrStItItqDlvd	1	IIPutTxLKAEIPwrStItItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDltStGroup	1	IIPutTxHndsOffStrWhlDltStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSources_778	1	IIPutTxDTCl_DTCSources_778	1	✓
IIPutTxDTCl_DTCTNumber_778	1	IIPutTxDTCl_DTCTNumber_778	1	✓
IIPutTxDTCl_DTCTFailType_778	1	IIPutTxDTCl_DTCTFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCTFaultType_778	1	IIPutTxDTCl_DTCTFaultType_778	1	✓
IIPutTxDTCTInfo_778	1	IIPutTxDTCTInfo_778	1	✓

Test Step 2.121 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	14
CTCEventId_Cnt_M_u8	8
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCTData.DTCTTriggered	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCSource	10
DTCDData.DTCNumber	49158
DTCDData.DTCFailType	255
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	205
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	7
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	17
LKATrqOvrIdlvdRC_Cnt_M_u8	20
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26
LastReportedDTCEventID_Cnt_M_u8	7
LastReportedGMStatus_Cnt_M_u8	71
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3849858816
Steering_Torque_Overlay_Stat_CE_c[0]	12
Steering_Torque_Overlay_Stat_CE_c[1]	14
Steering_Torque_Overlay_Stat_CE_c[2]	16
Steering_Torque_Overlay_Stat_CE_c[3]	18
Steering_Torque_Overlay_Stat_CE_c[4]	20
Steering_Torque_Overlay_Stat_CE_c[5]	22
Steering_Torque_Overlay_Stat_CE_c[6]	24
Steering_Torque_Overlay_Stat_CE_c[7]	26
k_LKAMfgEnable_Cnt_lgc	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_MaxHOWEstimate_Uls_f32	0.529999971		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	129		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	205		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	51563		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	709983488		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	4.5999999		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.129999995		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-5.19999981		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.5		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	14	14	✓
CTCEventId_Cnt_M_u8	9	9	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	104	104	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	8	8	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	20	20	✓
LastReportedDTCEventID_Cnt_M_u8	7	7	✓
LastReportedGMStatus_Cnt_M_u8	71	71	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3849858816	3849858816	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStItItqDlrd	1	IIPutTxElPwrStItItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSorce_778	1	IIPutTxDTCl_DTCSorce_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WmIndRqdSt_778	1	IIPutTxDTCl_WmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 2.122 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	29
CTCEventId_Cnt_M_u8	34
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSorce	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCNumber	54010
DTCDData.DTCFailType	69
DTCDData.DTCWmIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	1
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	207
LKATrqOvrDivdRC_Cnt_M_u8	49
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26
LastReportedDTCEventID_Cnt_M_u8	21
LastReportedGMStatus_Cnt_M_u8	1
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3967127296
Steering_Torque_Overlay_Stat_CE_c[0]	12
Steering_Torque_Overlay_Stat_CE_c[1]	14
Steering_Torque_Overlay_Stat_CE_c[2]	16
Steering_Torque_Overlay_Stat_CE_c[3]	18
Steering_Torque_Overlay_Stat_CE_c[4]	20
Steering_Torque_Overlay_Stat_CE_c[5]	22
Steering_Torque_Overlay_Stat_CE_c[6]	24
Steering_Torque_Overlay_Stat_CE_c[7]	26
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0.100000001

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	130		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	53757		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3426999552		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	1.10000002		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.889999986		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-10		
target_Rte_Read_Ap_SrlComOutput_LKAState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.20000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	29	29	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	1	1	✔
DTCDData.DTCNumber	54010	54010	✔
DTCDData.DTCFailType	69	69	✔
DTCDData.DTCWrmIndRqdSt	1	1	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✔
ESCRollCount_Cnt_M_u08	3	3	✔
GMStatus_Cnt_M_u8[0]	1	1	✔
GMStatus_Cnt_M_u8[1]	129	129	✔
GMStatus_Cnt_M_u8[2]	129	129	✔
GMStatus_Cnt_M_u8[3]	129	129	✔
GMStatus_Cnt_M_u8[4]	129	129	✔
GMStatus_Cnt_M_u8[5]	129	129	✔
GMStatus_Cnt_M_u8[6]	129	129	✔
GMStatus_Cnt_M_u8[7]	129	129	✔
GMStatus_Cnt_M_u8[8]	129	129	✔
GMStatus_Cnt_M_u8[9]	129	129	✔
GMStatus_Cnt M_u8[10]	129	129	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SriComOutput_Per1



Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[11]	129	129	✓
GMStatus_Cnt_M_u8[12]	129	129	✓
GMStatus_Cnt_M_u8[13]	129	129	✓
GMStatus_Cnt_M_u8[14]	129	129	✓
GMStatus_Cnt_M_u8[15]	129	129	✓
GMStatus_Cnt_M_u8[16]	129	129	✓
GMStatus_Cnt_M_u8[17]	129	129	✓
GMStatus_Cnt_M_u8[18]	129	129	✓
GMStatus_Cnt_M_u8[19]	129	129	✓
GMStatus_Cnt_M_u8[20]	129	129	✓
GMStatus_Cnt_M_u8[21]	129	129	✓
GMStatus_Cnt_M_u8[22]	129	129	✓
GMStatus_Cnt_M_u8[23]	129	129	✓
GMStatus_Cnt_M_u8[24]	129	129	✓
GMStatus_Cnt_M_u8[25]	129	129	✓
GMStatus_Cnt_M_u8[26]	129	129	✓
GMStatus_Cnt_M_u8[27]	129	129	✓
GMStatus_Cnt_M_u8[28]	129	129	✓
GMStatus_Cnt_M_u8[29]	129	129	✓
GMStatus_Cnt_M_u8[30]	129	129	✓
GMStatus_Cnt_M_u8[31]	129	129	✓
LKATrqOvrDlvdRC_Cnt_M_u8	49	49	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3967127296	3967127296	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 2.123 (Repeat Count = 1) ✓

Name	Input Value
CTCEventIdSV_Cnt_M_u8	25
CTCEventId_Cnt_M_u8	33
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	3
DTCDData.DTCNumber	10044
DTCDData.DTCFailType	172
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	109
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	4
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	57
LKATrqOvrlDlvdRC_Cnt_M_u8	239
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52
LastReportedDTCEventID_Cnt_M_u8	17
LastReportedGMStatus_Cnt_M_u8	3
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2335839744		
Steering_Torque_Overlay_Stat_CE_c[0]	24		
Steering_Torque_Overlay_Stat_CE_c[1]	28		
Steering_Torque_Overlay_Stat_CE_c[2]	32		
Steering_Torque_Overlay_Stat_CE_c[3]	36		
Steering_Torque_Overlay_Stat_CE_c[4]	40		
Steering_Torque_Overlay_Stat_CE_c[5]	44		
Steering_Torque_Overlay_Stat_CE_c[6]	48		
Steering_Torque_Overlay_Stat_CE_c[7]	52		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.200000003		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	131		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	109		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	49026		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3464965120		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	1.20000005		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.620000005		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	0.200000003		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	25	25	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSource	3	3	✔
DTCDData.DTCNumber	10044	10044	✔
DTCDData.DTCFailType	172	172	✔
DTCDData.DTCWmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdClrdStat	0	0	✔
DTCDData.DTCTstNPsdCdClrdSt	0	0	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	109	109	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	5	5	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	131	131	✓
GMStatus_Cnt_M_u8[2]	131	131	✓
GMStatus_Cnt_M_u8[3]	131	131	✓
GMStatus_Cnt_M_u8[4]	131	131	✓
GMStatus_Cnt_M_u8[5]	131	131	✓
GMStatus_Cnt_M_u8[6]	131	131	✓
GMStatus_Cnt_M_u8[7]	131	131	✓
GMStatus_Cnt_M_u8[8]	131	131	✓
GMStatus_Cnt_M_u8[9]	131	131	✓
GMStatus_Cnt_M_u8[10]	131	131	✓
GMStatus_Cnt_M_u8[11]	131	131	✓
GMStatus_Cnt_M_u8[12]	131	131	✓
GMStatus_Cnt_M_u8[13]	131	131	✓
GMStatus_Cnt_M_u8[14]	131	131	✓
GMStatus_Cnt_M_u8[15]	131	131	✓
GMStatus_Cnt_M_u8[16]	131	131	✓
GMStatus_Cnt_M_u8[17]	131	131	✓
GMStatus_Cnt_M_u8[18]	131	131	✓
GMStatus_Cnt_M_u8[19]	131	131	✓
GMStatus_Cnt_M_u8[20]	131	131	✓
GMStatus_Cnt_M_u8[21]	131	131	✓
GMStatus_Cnt_M_u8[22]	131	131	✓
GMStatus_Cnt_M_u8[23]	131	131	✓
GMStatus_Cnt_M_u8[24]	131	131	✓
GMStatus_Cnt_M_u8[25]	131	131	✓
GMStatus_Cnt_M_u8[26]	131	131	✓
GMStatus_Cnt_M_u8[27]	131	131	✓
GMStatus_Cnt_M_u8[28]	131	131	✓
GMStatus_Cnt_M_u8[29]	131	131	✓
GMStatus_Cnt_M_u8[30]	131	131	✓
GMStatus_Cnt_M_u8[31]	131	131	✓
LKATrqOvrldIvdRC_Cnt_M_u8	240	240	✓
LastReportedDTCEventID_Cnt_M_u8	17	17	✓
LastReportedGMStatus_Cnt_M_u8	3	3	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCTFlag_mS_M_u32p0	2335839744	2335839744	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrStTtItqDlvd	1	IIPutTxLKAEIPwrStTtItqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Case 3: Path Test

Specification

Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS3.1 5657.00 Cycles
TS3.2 40956.00 Cycles
TS3.3 10210.00 Cycles
TS3.4 10213.00 Cycles
TS3.5 10181.00 Cycles
TS3.6 10420.00 Cycles
TS3.7 10232.00 Cycles
TS3.8 10205.00 Cycles
TS3.9 9982.00 Cycles
TS3.10 10236.00 Cycles
TS3.11 10196.00 Cycles
TS3.12 10420.00 Cycles
TS3.13 10247.00 Cycles
TS3.14 10456.00 Cycles
TS3.15 10251.00 Cycles
TS3.16 10212.00 Cycles
TS3.17 5871.00 Cycles

Description

Vector Description:

TS3.1(CTCEventId_Cnt_M_u8 >= (D_NUMOFDEMEVENTS_CNT_U08 + 1U))=false &&(GMStatus_Cnt_M_u8[CTCEventId_Cnt_M_u8]) &
D_FAILEDTHISCYC_CNT_U8 == D_FAILEDTHISCYC_CNT_U8)=false &&(CurrentDTCSentThisIC_Cnt_M_lgc == TRUE)=false && (TRUE ==
k_LKAMfgEnable_Cnt_lgc)=false
TS3.2(CTCEventId_Cnt_M_u8 >= (D_NUMOFDEMEVENTS_CNT_U08 + 1U))=true && (i = 1U; i <= D_NUMOFDEMEVENTS_CNT_U08; i+
)=true/false && (TRUE == k_LKAMfgEnable_Cnt_lgc)=true && (TRUE == T1OutofRangeActive_Cnt_T_lgc)=true &&(TRUE ==
TorqueSensorFault_Cnt_T_lgc)=true &&(TRUE == TorqueSensorFault_Cnt_T_lgc)=true &&(D_VALID_CNT_U08 !=
HndsOffStrVhldtStV_Cnt_T_u08)=true &&(HOWEstimate_Uls_T_f32 > k_MaxHOWEstimate_Uls_f32)=false &&F1orF2FaultPresent_Cnt_T_lgc
== TRUE)=true &&Limit_m(DriverAppliedTorque_HwNm_T_f32, D_LKADRIVERAPPLIEDTORQUEMIN_NM_F32,
D_LKADRIVERAPPLIEDTORQUEMAX_NM_F32)=false &&Limit_m(DriverAppliedTorque_HwNm_T_f32,
D_LKADRIVERAPPLIEDTORQUEMIN_NM_F32, D_LKADRIVERAPPLIEDTORQUEMAX_NM_F32)=true &&(sint16)
(DriverAppliedTorque_HwNm_T_f32 / D_LKADRIVERAPPLIEDTORQUESF_NM_F32) * k_SComTrqPosPol_Cnt_s08=true/false
TS3.3 (TRUE == T1OutofRangeActive_Cnt_T_lgc)=false &&(TRUE == T2OutofRangeActive_Cnt_T_lgc)=true &&(HOWEstimate_Uls_T_f32 >
k_MaxHOWEstimate_Uls_f32)=true &&F1orF2FaultPresent_Cnt_T_lgc == TRUE)=false
TS3.4(TotalTorque_HwNm_T_f32>=D_TOTALTORQUEMAX_NM_F32)=False
(HOWEstimate_Uls_T_f32 > k_MaxHOWEstimate_Uls_f32)=True
TS3.5(GMStatus_Cnt_M_u8[CTCEventId_Cnt_M_u8]) & D_FAILEDTHISCYC_CNT_U8 == D_FAILEDTHISCYC_CNT_U8)=true &&
(DTCTriggeredFlag_Cnt_M_lgc[CTCEventId_Cnt_M_u8] == FALSE)=false && (TRUE == T1OutofRangeActive_Cnt_T_lgc)=false &&(TRUE ==
T2OutofRangeActive_Cnt_T_lgc)=true
TS3.6(GMStatus_Cnt_M_u8[CTCEventId_Cnt_M_u8]) & D_FAILEDTHISCYC_CNT_U8 == D_FAILEDTHISCYC_CNT_U8)=true &&
(DTCTriggeredFlag_Cnt_M_lgc[CTCEventId_Cnt_M_u8] == FALSE)=true
TS3.7(CurrentDTCSentThisIC_Cnt_M_lgc == TRUE)=true &&(TRUE == T1vsT2Active_Cnt_T_lgc)=false && (TRUE ==
T1OutofRangeActive_Cnt_T_lgc)=false &&(TRUE == T2OutofRangeActive_Cnt_T_lgc)=false && (TRUE ==
TrqSensorNotTrimmedActive_Cnt_T_lgc)=false &&(TRUE == TorqueSensorFault_Cnt_T_lgc)=false &&(TRUE == TorqueSensorFault_Cnt_T_lgc)
=false &&(TRUE == VehicleSpeedMissing_Cnt_T_lgc)=true
TS3.8(CTCEventIdSV_Cnt_M_u8 != CTCEventId_Cnt_M_u8)=true && (TRUE == T1OutofRangeActive_Cnt_T_lgc)=false &&(TRUE ==
T2OutofRangeActive_Cnt_T_lgc)=false && (TRUE == TrqSensorNotTrimmedActive_Cnt_T_lgc)=true
TS3.9(
(((GMStatus_Cnt_M_u8[CTCEventId_Cnt_M_u8]) & D_FAILEDTHISCYC_CNT_U8) == D_FAILEDTHISCYC_CNT_U8) &&
(DTCTriggeredFlag_Cnt_M_lgc[CTCEventId_Cnt_M_u8] == FALSE)
)=False
(CurrentDTCSentThisIC_Cnt_M_lgc == TRUE)=False
(CTCEventId_Cnt_M_u8>=D_NUMOFDEMEVENTS_CNT_U08)=True"
TS3.10(TRUE == TorqueSensorFault_Cnt_T_lgc)=false &&(TRUE == VehicleSpeedMissing_Cnt_T_lgc)=false &&(TRUE ==
VehicleSpeedInvalid_Cnt_T_lgc)=false &&(D_VALID_CNT_U08 != HndsOffStrVhldtStV_Cnt_T_u08)=false &&(TRUE ==
k_LKAMfgEnable_Cnt_lgc)=true
TS3.11(TRUE == TorqueSensorFault_Cnt_T_lgc)=false &&(TRUE == VehicleSpeedMissing_Cnt_T_lgc)=false &&(TRUE ==
VehicleSpeedInvalid_Cnt_T_lgc)=true
TS3.12 (CTCEventIdSV_Cnt_M_u8 != CTCEventId_Cnt_M_u8)=false &&(TimeoutElapsedTime_mS_T_u16p0 > 1500U)=false
TS3.13(TimeoutElapsedTime_mS_T_u16p0 > 1500U)=true
TS3.14(((GMStatus_Cnt_M_u8[CTCEventId_Cnt_M_u8]) & D_FAILEDTHISCYC_CNT_U8) == D_FAILEDTHISCYC_CNT_U8) &&
(DTCTriggeredFlag_Cnt_M_lgc[CTCEventId_Cnt_M_u8] == FALSE)
)=True
(CTCEventIdSV_Cnt_M_u8 != CTCEventId_Cnt_M_u8)=False
(TimeoutElapsedTime_mS_T_u16p0 > 1500U)=True
(CTCEventId_Cnt_M_u8>=D_NUMOFDEMEVENTS_CNT_U08)=True"
TS3.15(((GMStatus_Cnt_M_u8[CTCEventId_Cnt_M_u8]) & D_FAILEDTHISCYC_CNT_U8) == D_FAILEDTHISCYC_CNT_U8) &&
(DTCTriggeredFlag_Cnt_M_lgc[CTCEventId_Cnt_M_u8] == FALSE)
)=True
(CTCEventIdSV_Cnt_M_u8 != CTCEventId_Cnt_M_u8)=False
(TimeoutElapsedTime_mS_T_u16p0 > 1500U)=True
(CTCEventId_Cnt_M_u8<=1U)=True"
TS3.16(((GMStatus_Cnt_M_u8[CTCEventId_Cnt_M_u8]) & D_FAILEDTHISCYC_CNT_U8) == D_FAILEDTHISCYC_CNT_U8) &&
(DTCTriggeredFlag_Cnt_M_lgc[CTCEventId_Cnt_M_u8] == FALSE)
)=False
(CurrentDTCSentThisIC_Cnt_M_lgc == TRUE)=True
(CTCEventId_Cnt_M_u8<=1U)=True"
TS3.17(ESCTotalTorqueDelivered_HwNm_f32<=D_ESCTOTALTRQLOLMT_HWNM_F32)=True

Test Step 3.1 (Repeat Count = 1)

Name	Input Value
CTCEventIdSV_Cnt_M_u8	0
CTCEventId_Cnt_M_u8	0
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	0
DTCDData.DTCSource	0
DTCDData.DTCNumber	0
DTCDData.DTCFailType	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	0
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	0
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	0
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	0
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	0
DemDTCNum_Cnt_M_u32[1]	0
DemDTCNum_Cnt_M_u32[2]	0
DemDTCNum_Cnt_M_u32[3]	0
DemDTCNum_Cnt_M_u32[4]	0
DemDTCNum_Cnt_M_u32[5]	0
DemDTCNum_Cnt_M_u32[6]	0
DemDTCNum_Cnt_M_u32[7]	0
DemDTCNum_Cnt_M_u32[8]	0
DemDTCNum_Cnt_M_u32[9]	0
DemDTCNum_Cnt_M_u32[10]	0
DemDTCNum_Cnt_M_u32[11]	0
DemDTCNum_Cnt_M_u32[12]	0
DemDTCNum_Cnt_M_u32[13]	0
DemDTCNum_Cnt_M_u32[14]	0
DemDTCNum_Cnt_M_u32[15]	0
DemDTCNum_Cnt_M_u32[16]	0
DemDTCNum_Cnt_M_u32[17]	0
DemDTCNum_Cnt_M_u32[18]	0
DemDTCNum_Cnt_M_u32[19]	0
DemDTCNum_Cnt_M_u32[20]	0
DemDTCNum_Cnt_M_u32[21]	0
DemDTCNum_Cnt_M_u32[22]	0
DemDTCNum_Cnt_M_u32[23]	0
DemDTCNum_Cnt_M_u32[24]	0
DemDTCNum_Cnt_M_u32[25]	0
DemDTCNum_Cnt_M_u32[26]	0
DemDTCNum_Cnt_M_u32[27]	0
DemDTCNum_Cnt_M_u32[28]	0
DemDTCNum_Cnt_M_u32[29]	0
DemDTCNum_Cnt_M_u32[30]	0
DemDTCNum_Cnt_M_u32[31]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	1
GMStatus_Cnt_M_u8[2]	1
GMStatus_Cnt_M_u8[3]	1
GMStatus_Cnt_M_u8[4]	1
GMStatus_Cnt_M_u8[5]	1
GMStatus_Cnt_M_u8[6]	1
GMStatus_Cnt_M_u8[7]	1
GMStatus_Cnt_M_u8[8]	1
GMStatus_Cnt_M_u8[9]	1
GMStatus_Cnt_M_u8[10]	1
GMStatus_Cnt_M_u8[11]	1
GMStatus_Cnt_M_u8[12]	1
GMStatus_Cnt_M_u8[13]	1
GMStatus_Cnt_M_u8[14]	1
GMStatus_Cnt_M_u8[15]	1
GMStatus_Cnt_M_u8[16]	1
GMStatus_Cnt_M_u8[17]	1
GMStatus_Cnt_M_u8[18]	1
GMStatus_Cnt_M_u8[19]	1
GMStatus_Cnt_M_u8[20]	1
GMStatus_Cnt_M_u8[21]	1
GMStatus_Cnt_M_u8[22]	1
GMStatus_Cnt_M_u8[23]	1
GMStatus_Cnt_M_u8[24]	1
GMStatus_Cnt_M_u8[25]	1
GMStatus_Cnt_M_u8[26]	1
GMStatus_Cnt_M_u8[27]	1
GMStatus_Cnt_M_u8[28]	1
GMStatus_Cnt_M_u8[29]	1
GMStatus_Cnt_M_u8[30]	1
GMStatus_Cnt_M_u8[31]	1
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	0
LKATrqOvriDlvdRC_Cnt_M_u8	0
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	0
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	0
LastReportedDTCEventID_Cnt_M_u8	0
LastReportedGMStatus_Cnt_M_u8	1
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	0
Steering_Torque_Overlay_Stat_CE_c[0]	12
Steering_Torque_Overlay_Stat_CE_c[1]	14
Steering_Torque_Overlay_Stat_CE_c[2]	16
Steering_Torque_Overlay_Stat_CE_c[3]	18
Steering_Torque_Overlay_Stat_CE_c[4]	20
Steering_Torque_Overlay_Stat_CE_c[5]	22
Steering_Torque_Overlay_Stat_CE_c[6]	24
Steering_Torque_Overlay_Stat_CE_c[7]	26
k_LKAMfgEnable_Cnt_lgc	0
k_MaxHOWEstimate_Uls_f32	0
k_SComTrqPosPol_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	0		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-10.2399998		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-3		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	0	0	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	49	49	✔
DTCDData.DTCNumber	0	0	✔
DTCDData.DTCFailType	0	0	✔
DTCDData.DTCWmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdCldStat	0	0	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[10]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[12]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[18]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[25]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[29]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✔
ESCRollCount_Cnt_M_u08	3	3	✔
GMStatus_Cnt_M_u8[0]	1	1	✔
GMStatus_Cnt_M_u8[1]	1	1	✔
GMStatus_Cnt_M_u8[2]	1	1	✔
GMStatus_Cnt_M_u8[3]	1	1	✔
GMStatus_Cnt_M_u8[4]	1	1	✔
GMStatus_Cnt_M_u8[5]	1	1	✔
GMStatus_Cnt_M_u8[6]	1	1	✔
GMStatus_Cnt_M_u8[7]	1	1	✔
GMStatus_Cnt_M_u8[8]	1	1	✔
GMStatus_Cnt_M_u8[9]	1	1	✔
GMStatus_Cnt_M_u8[10]	1	1	✔
GMStatus_Cnt_M_u8[11]	1	1	✔
GMStatus_Cnt_M_u8[12]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[13]	1	1	✓
GMStatus_Cnt_M_u8[14]	1	1	✓
GMStatus_Cnt_M_u8[15]	1	1	✓
GMStatus_Cnt_M_u8[16]	1	1	✓
GMStatus_Cnt_M_u8[17]	1	1	✓
GMStatus_Cnt_M_u8[18]	1	1	✓
GMStatus_Cnt_M_u8[19]	1	1	✓
GMStatus_Cnt_M_u8[20]	1	1	✓
GMStatus_Cnt_M_u8[21]	1	1	✓
GMStatus_Cnt_M_u8[22]	1	1	✓
GMStatus_Cnt_M_u8[23]	1	1	✓
GMStatus_Cnt_M_u8[24]	1	1	✓
GMStatus_Cnt_M_u8[25]	1	1	✓
GMStatus_Cnt_M_u8[26]	1	1	✓
GMStatus_Cnt_M_u8[27]	1	1	✓
GMStatus_Cnt_M_u8[28]	1	1	✓
GMStatus_Cnt_M_u8[29]	1	1	✓
GMStatus_Cnt_M_u8[30]	1	1	✓
GMStatus_Cnt_M_u8[31]	1	1	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	0	0	✓
LastReportedGMStatus_Cnt_M_u8	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	0	0	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChkism	1	IIPutTxTrqOvrIDChkism	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 3.2 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	35
CTCEventId_Cnt_M_u8	35
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSOURCE	49
DTCDData.DTCNumber	65535
DTCDData.DTCFailType	255
DTCDData.DTCWrnIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCTData.DTCTstNPsdPwrupSt	1
DTCTData.DTCHistStat	1
DTCTData.DTCTstFldCdCldStat	1
DTCTData.DTCTstNPsdCdCldSt	1
DTCTData.DTCCurrentStatus	1
DTCTData.DTCCodeSupported	1
DTCTData.DTCFaulttype	255
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	4294967295
DemDTCNum_Cnt_M_u32[1]	4294967295
DemDTCNum_Cnt_M_u32[2]	4294967295
DemDTCNum_Cnt_M_u32[3]	4294967295
DemDTCNum_Cnt_M_u32[4]	4294967295
DemDTCNum_Cnt_M_u32[5]	4294967295
DemDTCNum_Cnt_M_u32[6]	4294967295
DemDTCNum_Cnt_M_u32[7]	4294967295
DemDTCNum_Cnt_M_u32[8]	4294967295
DemDTCNum_Cnt_M_u32[9]	4294967295
DemDTCNum_Cnt_M_u32[10]	4294967295
DemDTCNum_Cnt_M_u32[11]	4294967295
DemDTCNum_Cnt_M_u32[12]	4294967295
DemDTCNum_Cnt_M_u32[13]	4294967295
DemDTCNum_Cnt_M_u32[14]	4294967295
DemDTCNum_Cnt_M_u32[15]	4294967295
DemDTCNum_Cnt_M_u32[16]	4294967295
DemDTCNum_Cnt_M_u32[17]	4294967295
DemDTCNum_Cnt_M_u32[18]	4294967295
DemDTCNum_Cnt_M_u32[19]	4294967295
DemDTCNum_Cnt_M_u32[20]	4294967295
DemDTCNum_Cnt_M_u32[21]	4294967295
DemDTCNum_Cnt_M_u32[22]	4294967295
DemDTCNum_Cnt_M_u32[23]	4294967295
DemDTCNum_Cnt_M_u32[24]	4294967295
DemDTCNum_Cnt_M_u32[25]	4294967295
DemDTCNum_Cnt_M_u32[26]	4294967295
DemDTCNum_Cnt_M_u32[27]	4294967295
DemDTCNum_Cnt_M_u32[28]	4294967295
DemDTCNum_Cnt_M_u32[29]	4294967295
DemDTCNum_Cnt_M_u32[30]	4294967295
DemDTCNum_Cnt_M_u32[31]	4294967295
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
ESCRollCount_Cnt_M_u08	4
GMStatus_Cnt_M_u8[0]	147
GMStatus_Cnt_M_u8[1]	147
GMStatus_Cnt_M_u8[2]	147
GMStatus_Cnt_M_u8[3]	147
GMStatus_Cnt_M_u8[4]	147
GMStatus_Cnt_M_u8[5]	147
GMStatus_Cnt_M_u8[6]	147
GMStatus_Cnt_M_u8[7]	147
GMStatus_Cnt_M_u8[8]	147
GMStatus_Cnt_M_u8[9]	147
GMStatus_Cnt_M_u8[10]	147
GMStatus_Cnt_M_u8[11]	147
GMStatus_Cnt_M_u8[12]	147
GMStatus_Cnt_M_u8[13]	147
GMStatus_Cnt_M_u8[14]	147
GMStatus_Cnt_M_u8[15]	147
GMStatus_Cnt_M_u8[16]	147
GMStatus_Cnt_M_u8[17]	147
GMStatus_Cnt_M_u8[18]	147
GMStatus_Cnt_M_u8[19]	147
GMStatus_Cnt_M_u8[20]	147
GMStatus_Cnt_M_u8[21]	147
GMStatus_Cnt_M_u8[22]	147
GMStatus_Cnt_M_u8[23]	147
GMStatus_Cnt_M_u8[24]	147
GMStatus_Cnt_M_u8[25]	147
GMStatus_Cnt_M_u8[26]	147
GMStatus_Cnt_M_u8[27]	147
GMStatus_Cnt_M_u8[28]	147
GMStatus_Cnt_M_u8[29]	147
GMStatus_Cnt_M_u8[30]	147
GMStatus_Cnt_M_u8[31]	147
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	255
LKATrqOvrDlvdRC_Cnt_M_u8	255
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	255
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	255
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	255
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	255
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	255
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	255
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	255
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	255
LastReportedDTCEventID_Cnt_M_u8	35
LastReportedGMStatus_Cnt_M_u8	147
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	4294967295
Steering_Torque_Overlay_Stat_CE_c[0]	24
Steering_Torque_Overlay_Stat_CE_c[1]	28
Steering_Torque_Overlay_Stat_CE_c[2]	32
Steering_Torque_Overlay_Stat_CE_c[3]	36
Steering_Torque_Overlay_Stat_CE_c[4]	40
Steering_Torque_Overlay_Stat_CE_c[5]	44
Steering_Torque_Overlay_Stat_CE_c[6]	48
Steering_Torque_Overlay_Stat_CE_c[7]	52
k_LKAMfgEnable_Cnt_Igc	1
k_MaxHOWEstimate_Uls_f32	1
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	255
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	255
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	4294967295		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	10.2299995		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	1		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	3		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	35	35	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	65535	65535	✓
DTCDData.DTCFailType	255	255	✓
DTCDData.DTCWmIndRqdSt	1	1	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	255	255	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	5	5	✓
GMStatus_Cnt_M_u8[0]	147	147	✓
GMStatus_Cnt_M_u8[1]	147	147	✓
GMStatus_Cnt_M_u8[2]	147	147	✓
GMStatus_Cnt_M_u8[3]	147	147	✓
GMStatus_Cnt_M_u8[4]	147	147	✓
GMStatus_Cnt_M_u8[5]	147	147	✓
GMStatus_Cnt_M_u8[6]	147	147	✓
GMStatus_Cnt_M_u8[7]	147	147	✓
GMStatus_Cnt_M_u8[8]	147	147	✓
GMStatus_Cnt_M_u8[9]	147	147	✓
GMStatus_Cnt_M_u8[10]	147	147	✓
GMStatus_Cnt_M_u8[11]	147	147	✓
GMStatus_Cnt_M_u8[12]	147	147	✓
GMStatus_Cnt_M_u8[13]	147	147	✓
GMStatus_Cnt_M_u8[14]	147	147	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[15]	147	147	✓
GMStatus_Cnt_M_u8[16]	147	147	✓
GMStatus_Cnt_M_u8[17]	147	147	✓
GMStatus_Cnt_M_u8[18]	147	147	✓
GMStatus_Cnt_M_u8[19]	147	147	✓
GMStatus_Cnt_M_u8[20]	147	147	✓
GMStatus_Cnt_M_u8[21]	147	147	✓
GMStatus_Cnt_M_u8[22]	147	147	✓
GMStatus_Cnt_M_u8[23]	147	147	✓
GMStatus_Cnt_M_u8[24]	147	147	✓
GMStatus_Cnt_M_u8[25]	147	147	✓
GMStatus_Cnt_M_u8[26]	147	147	✓
GMStatus_Cnt_M_u8[27]	147	147	✓
GMStatus_Cnt_M_u8[28]	147	147	✓
GMStatus_Cnt_M_u8[29]	147	147	✓
GMStatus_Cnt_M_u8[30]	147	147	✓
GMStatus_Cnt_M_u8[31]	147	147	✓
LKATrqOvriDlvdRC_Cnt_M_u8	0	0	✓
LastReportedDTCEventID_Cnt_M_u8	35	35	✓
LastReportedGMStatus_Cnt_M_u8	147	147	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	4294967295	4294967295	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrStTtTqDlvd	1	IIPutTxLKAEIPwrStTtTqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSOURCE_778	1	IIPutTxDTCl_DTCSOURCE_778	1	✓
IIPutTxDTCl_DTCNNumber_778	1	IIPutTxDTCl_DTCNNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 3.3 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	29	
CTCEventId_Cnt_M_u8	34	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DTCTriggered	0	
DTCDData.DTCSOURCE	1	
DTCDData.DTCNNumber	54010	
DTCDData.DTCFailType	69	
DTCDData.DTCWrnIndRqdSt	1	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	0	
DTCDData.DTCHistStat	1	
DTCDData.DTCTstFldCdClrdStat	1	
DTCDData.DTCTstNPsdCdClrdSt	0	
DTCDData.DTCCurrentStatus	0	
DTCDData.DTCCodeSupported	0	
DTCDData.DTCFaulttype	1	
DTCTriggeredFlag_Cnt_M_lgc[0]	0	
DTCTriggeredFlag_Cnt_M_lgc[1]	1	
DTCTriggeredFlag_Cnt_M_lgc[2]	0	
DTCTriggeredFlag_Cnt_M_lgc[3]	1	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	0	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	1	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	1	
DTCTriggeredFlag_Cnt_M_lgc[14]	0	
DTCTriggeredFlag_Cnt_M_lgc[15]	1	
DTCTriggeredFlag_Cnt_M_lgc[16]	0	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	1	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	0	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	1
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	207		
LKATrqOvrldIvdRC_Cnt_M_u8	49		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26		
LastReportedDTCEventID_Cnt_M_u8	21		
LastReportedGMStatus_Cnt_M_u8	1		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3967127296		
Steering_Torque_Overlay_Stat_CE_c[0]	36		
Steering_Torque_Overlay_Stat_CE_c[1]	42		
Steering_Torque_Overlay_Stat_CE_c[2]	48		
Steering_Torque_Overlay_Stat_CE_c[3]	54		
Steering_Torque_Overlay_Stat_CE_c[4]	60		
Steering_Torque_Overlay_Stat_CE_c[5]	66		
Steering_Torque_Overlay_Stat_CE_c[6]	72		
Steering_Torque_Overlay_Stat_CE_c[7]	78		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.100000001		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	1		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	53757		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3426999552		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	1.29999995		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.889999986		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.20000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	29	29	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✔
DTCDData.DTCTriggered	0	0	✔
DTCDData.DTCSource	1	1	✔
DTCDData.DTCNumber	54010	54010	✔
DTCDData.DTCFailType	69	69	✔
DTCDData.DTCWrmIndRqdSt	1	1	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrupSt	0	0	✔
DTCDData.DTCHistStat	1	1	✔
DTCDData.DTCTstFldCdCldStat	1	1	✔
DTCDData.DTCTstNPsdCdCldSt	0	0	✔
DTCDData.DTCCurrentStatus	0	0	✔
DTCDData.DTCCodeSupported	0	0	✔
DTCDData.DTCFaulttype	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[1]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	2	2	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	3	3	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	3	3	✓
GMStatus_Cnt_M_u8[4]	3	3	✓
GMStatus_Cnt_M_u8[5]	3	3	✓
GMStatus_Cnt_M_u8[6]	3	3	✓
GMStatus_Cnt_M_u8[7]	3	3	✓
GMStatus_Cnt_M_u8[8]	3	3	✓
GMStatus_Cnt_M_u8[9]	3	3	✓
GMStatus_Cnt_M_u8[10]	3	3	✓
GMStatus_Cnt_M_u8[11]	3	3	✓
GMStatus_Cnt_M_u8[12]	3	3	✓
GMStatus_Cnt_M_u8[13]	3	3	✓
GMStatus_Cnt_M_u8[14]	3	3	✓
GMStatus_Cnt_M_u8[15]	3	3	✓
GMStatus_Cnt_M_u8[16]	3	3	✓
GMStatus_Cnt_M_u8[17]	3	3	✓
GMStatus_Cnt_M_u8[18]	3	3	✓
GMStatus_Cnt_M_u8[19]	3	3	✓
GMStatus_Cnt_M_u8[20]	3	3	✓
GMStatus_Cnt_M_u8[21]	3	3	✓
GMStatus_Cnt_M_u8[22]	3	3	✓
GMStatus_Cnt_M_u8[23]	3	3	✓
GMStatus_Cnt_M_u8[24]	3	3	✓
GMStatus_Cnt_M_u8[25]	3	3	✓
GMStatus_Cnt_M_u8[26]	3	3	✓
GMStatus_Cnt_M_u8[27]	3	3	✓
GMStatus_Cnt_M_u8[28]	3	3	✓
GMStatus_Cnt_M_u8[29]	3	3	✓
GMStatus_Cnt_M_u8[30]	3	3	✓
GMStatus_Cnt_M_u8[31]	3	3	✓
LKATrqOvriDivdRC_Cnt_M_u8	50	50	✓
LastReportedDTCEventID_Cnt_M_u8	21	21	✓
LastReportedGMStatus_Cnt_M_u8	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3967127296	3967127296	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdCldSt_778	1	IIPutTxDTCl_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCl_TstFldCdCldStat_778	1	IIPutTxDTCl_TstFldCdCldStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 3.4 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	25	
CTCEventId_Cnt_M_u8	33	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DTCTriggered	1	
DTCDData.DTCSource	3	
DTCDData.DTCNumber	10044	
DTCDData.DTCFailType	172	
DTCDData.DTCWrnIndRqdSt	0	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	0	
DTCDData.DTCHistStat	0	
DTCDData.DTCTstFldCdCldStat	0	
DTCDData.DTCTstNPsdCdCldSt	0	
DTCDData.DTCCurrentStatus	1	
DTCDData.DTCCodeSupported	1	
DTCDData.DTCFaulttype	109	
DTCTTriggeredFlag_Cnt_M_lgc[0]	1	
DTCTTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTTriggeredFlag_Cnt_M_lgc[2]	0	
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTTriggeredFlag_Cnt_M_lgc[6]	0	
DTCTTriggeredFlag_Cnt_M_lgc[7]	1	
DTCTTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTTriggeredFlag_Cnt_M_lgc[9]	0	
DTCTTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	
DTCTTriggeredFlag_Cnt_M_lgc[14]	1	
DTCTTriggeredFlag_Cnt_M_lgc[15]	0	
DTCTTriggeredFlag_Cnt_M_lgc[16]	1	
DTCTTriggeredFlag_Cnt_M_lgc[17]	0	
DTCTTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTTriggeredFlag_Cnt_M_lgc[19]	0	
DTCTTriggeredFlag_Cnt_M_lgc[20]	1	
DTCTTriggeredFlag_Cnt_M_lgc[21]	0	
DTCTTriggeredFlag_Cnt_M_lgc[22]	1	
DTCTTriggeredFlag_Cnt_M_lgc[23]	0	
DTCTTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	
DTCTTriggeredFlag_Cnt_M_lgc[26]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	3
GMStatus_Cnt_M_u8[0]	4
GMStatus_Cnt_M_u8[1]	8
GMStatus_Cnt_M_u8[2]	12
GMStatus_Cnt_M_u8[3]	16
GMStatus_Cnt_M_u8[4]	20
GMStatus_Cnt_M_u8[5]	24
GMStatus_Cnt_M_u8[6]	28
GMStatus_Cnt_M_u8[7]	32
GMStatus_Cnt_M_u8[8]	36
GMStatus_Cnt_M_u8[9]	40
GMStatus_Cnt_M_u8[10]	44
GMStatus_Cnt_M_u8[11]	48
GMStatus_Cnt_M_u8[12]	52
GMStatus_Cnt_M_u8[13]	56
GMStatus_Cnt_M_u8[14]	60
GMStatus_Cnt_M_u8[15]	64
GMStatus_Cnt_M_u8[16]	68
GMStatus_Cnt_M_u8[17]	72
GMStatus_Cnt_M_u8[18]	76
GMStatus_Cnt_M_u8[19]	80
GMStatus_Cnt_M_u8[20]	84
GMStatus_Cnt_M_u8[21]	88
GMStatus_Cnt_M_u8[22]	92
GMStatus_Cnt_M_u8[23]	96
GMStatus_Cnt_M_u8[24]	100
GMStatus_Cnt_M_u8[25]	104
GMStatus_Cnt_M_u8[26]	108
GMStatus_Cnt_M_u8[27]	112
GMStatus_Cnt_M_u8[28]	116
GMStatus_Cnt_M_u8[29]	120
GMStatus_Cnt_M_u8[30]	124
GMStatus_Cnt_M_u8[31]	128
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	57		
LKATrqOvrIdlvdRC_Cnt_M_u8	239		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventId_Cnt_M_u8	17		
LastReportedGMStatus_Cnt_M_u8	3		
PrevWarningIndSignal_Cnt_M_u08[0]	0		
PrevWarningIndSignal_Cnt_M_u08[1]	0		
PrevWarningIndSignal_Cnt_M_u08[2]	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2335839744		
Steering_Torque_Overlay_Stat_CE_c[0]	48		
Steering_Torque_Overlay_Stat_CE_c[1]	56		
Steering_Torque_Overlay_Stat_CE_c[2]	64		
Steering_Torque_Overlay_Stat_CE_c[3]	72		
Steering_Torque_Overlay_Stat_CE_c[4]	80		
Steering_Torque_Overlay_Stat_CE_c[5]	88		
Steering_Torque_Overlay_Stat_CE_c[6]	96		
Steering_Torque_Overlay_Stat_CE_c[7]	104		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.200000003		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	2		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	109		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	49026		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3464965120		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	1.39999998		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.620000005		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	0.200000003		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	25	25	✔
CTCEventId_Cnt_M_u8	1	1	✔
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✔
DTCDData.DTCTriggered	1	1	✔
DTCDData.DTCSource	3	3	✔
DTCDData.DTCNumber	10044	10044	✔
DTCDData.DTCFailType	172	172	✔
DTCDData.DTCWrmIndRqdSt	0	0	✔
DTCDData.DTCTstFldPwrUpSt	0	0	✔
DTCDData.DTCTstNPsdPwrUpSt	0	0	✔
DTCDData.DTCHistStat	0	0	✔
DTCDData.DTCTstFldCdClrdStat	0	0	✔
DTCDData.DTCTstNPsdCdClrdSt	0	0	✔
DTCDData.DTCCurrentStatus	1	1	✔
DTCDData.DTCCodeSupported	1	1	✔
DTCDData.DTCFaulttype	109	109	✔
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✔
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✔
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✔

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	4	4	✓
GMStatus_Cnt_M_u8[0]	4	4	✓
GMStatus_Cnt_M_u8[1]	1	1	✓
GMStatus_Cnt_M_u8[2]	1	1	✓
GMStatus_Cnt_M_u8[3]	1	1	✓
GMStatus_Cnt_M_u8[4]	1	1	✓
GMStatus_Cnt_M_u8[5]	1	1	✓
GMStatus_Cnt_M_u8[6]	1	1	✓
GMStatus_Cnt_M_u8[7]	1	1	✓
GMStatus_Cnt_M_u8[8]	1	1	✓
GMStatus_Cnt_M_u8[9]	1	1	✓
GMStatus_Cnt_M_u8[10]	1	1	✓
GMStatus_Cnt_M_u8[11]	1	1	✓
GMStatus_Cnt_M_u8[12]	1	1	✓
GMStatus_Cnt_M_u8[13]	1	1	✓
GMStatus_Cnt_M_u8[14]	1	1	✓
GMStatus_Cnt_M_u8[15]	1	1	✓
GMStatus_Cnt_M_u8[16]	1	1	✓
GMStatus_Cnt_M_u8[17]	1	1	✓
GMStatus_Cnt_M_u8[18]	1	1	✓
GMStatus_Cnt_M_u8[19]	1	1	✓
GMStatus_Cnt_M_u8[20]	1	1	✓
GMStatus_Cnt_M_u8[21]	1	1	✓
GMStatus_Cnt_M_u8[22]	1	1	✓
GMStatus_Cnt_M_u8[23]	1	1	✓
GMStatus_Cnt_M_u8[24]	1	1	✓
GMStatus_Cnt_M_u8[25]	1	1	✓
GMStatus_Cnt_M_u8[26]	1	1	✓
GMStatus_Cnt_M_u8[27]	1	1	✓
GMStatus_Cnt_M_u8[28]	1	1	✓
GMStatus_Cnt_M_u8[29]	1	1	✓
GMStatus_Cnt_M_u8[30]	1	1	✓
GMStatus_Cnt_M_u8[31]	1	1	✓
LKATrqOvrDlvdRC_Cnt_M_u8	240	240	✓
LastReportedDTCEventID_Cnt_M_u8	17	17	✓
LastReportedGMStatus_Cnt_M_u8	3	3	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2335839744	2335839744	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFidCdClrdStat_778	1	IIPutTxDTCl_TstFidCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFidPwrUpSt_778	1	IIPutTxDTCl_TstFidPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 3.5 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	8	
CTCEventId_Cnt_M_u8	30	
CurrentDTCSentThisIC_Cnt_M_lgc	0	
DTCDData.DTCTriggered	1	
DTCDData.DTCSource	7	
DTCDData.DTCNumber	28091	
DTCDData.DTCFailType	97	
DTCDData.DTCWrmIndRqdSt	0	
DTCDData.DTCTstFidPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	0	
DTCDData.DTCHistStat	0	
DTCDData.DTCTstFidCdClrdStat	1	
DTCDData.DTCTstNPsdCdClrdSt	1	
DTCDData.DTCCurrentStatus	1	
DTCDData.DTCCodeSupported	1	
DTCDData.DTCFaulttype	249	
DTCTriggeredFlag_Cnt_M_lgc[0]	1	
DTCTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTriggeredFlag_Cnt_M_lgc[2]	1	
DTCTriggeredFlag_Cnt_M_lgc[3]	0	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	1	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	0	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	0	
DTCTriggeredFlag_Cnt_M_lgc[14]	1	
DTCTriggeredFlag_Cnt_M_lgc[15]	0	
DTCTriggeredFlag_Cnt_M_lgc[16]	1	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	0	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	
DTCTriggeredFlag_Cnt_M_lgc[26]	0	
DTCTriggeredFlag_Cnt_M_lgc[27]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	8
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	149

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKATrqOvrDIvdRC_Cnt_M_u8	210		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104		
LastReportedDTCEventID_Cnt_M_u8	19		
LastReportedGMStatus_Cnt_M_u8	7		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKAState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	2575908864		
Steering_Torque_Overlay_Stat_CE_c[0]	60		
Steering_Torque_Overlay_Stat_CE_c[1]	70		
Steering_Torque_Overlay_Stat_CE_c[2]	80		
Steering_Torque_Overlay_Stat_CE_c[3]	90		
Steering_Torque_Overlay_Stat_CE_c[4]	100		
Steering_Torque_Overlay_Stat_CE_c[5]	110		
Steering_Torque_Overlay_Stat_CE_c[6]	120		
Steering_Torque_Overlay_Stat_CE_c[7]	130		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.400000006		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	3		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	249		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	2008		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	137299456		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	1.5		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.400000006		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	0		
target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data	3		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.10000002		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	8	8	✓
CTCEventId_Cnt_M_u8	31	31	✓
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdClrdStat	0	0	✓
DTCDData.DTCTstNPsdCdClrdSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	9	9	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvriDivdRC_Cnt_M_u8	211	211	✓
LastReportedDTCEventID_Cnt_M_u8	19	19	✓
LastReportedGMStatus_Cnt_M_u8	7	7	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2575908864	2575908864	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SrlComOutput_Per1



Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SrlComOutput_WarningIndicatorHandler	1	SrlComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	Rte_Read_Ap_SrlComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrStTtITqDlrd	1	IIPutTxElPwrStTtITqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	Rte_Read_Ap_SrlComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrStTtITqDlvd	1	IIPutTxLKAEIPwrStTtITqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 3.6 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	12
CTCEventId_Cnt_M_u8	14
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	9
DTCDData.DTCNumber	35642
DTCDData.DTCFailType	93
DTCDData.DTCWmIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	240
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	104
LKATrqOvrDlvdRC_Cnt_M_u8	63
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	60
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	70
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	90
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	100
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	110
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	130
LastReportedDTCEventID_Cnt_M_u8	13
LastReportedGMStatus_Cnt_M_u8	9
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	2885878528
Steering_Torque_Overlay_Stat_CE_c[0]	72
Steering_Torque_Overlay_Stat_CE_c[1]	84
Steering_Torque_Overlay_Stat_CE_c[2]	96
Steering_Torque_Overlay_Stat_CE_c[3]	108
Steering_Torque_Overlay_Stat_CE_c[4]	120
Steering_Torque_Overlay_Stat_CE_c[5]	132
Steering_Torque_Overlay_Stat_CE_c[6]	144
Steering_Torque_Overlay_Stat_CE_c[7]	156
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.5
k_SComTrqPosPol_Cnt_s08	-1
target_Dem_GetEventStatus_EventStatusExtended	4
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	240
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	48500
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	380219648
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	1.60000002
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.439999999
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-3.5999999
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-2.0999999

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	14	14	✓
CTCEventId_Cnt_M_u8	14	14	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	69	*none*	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	64	64	✓
LastReportedDTCEventID_Cnt_M_u8	13	13	✓
LastReportedGMStatus_Cnt_M_u8	9	9	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	380219648	380219648	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 3.7 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	7
CTCEventId_Cnt_M_u8	9
CurrentDTCSentThisIC_Cnt_M_lgc	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTriggered	1
DTCDData.DTCSrc	15
DTCDData.DTCNumber	54744
DTCDData.DTCFailType	65
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPsdCdCldSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	67
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	10
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	77
LKATrqOvrldDlvdRC_Cnt_M_u8	106
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208
LastReportedDTCEventID_Cnt_M_u8	4
LastReportedGMStatus_Cnt_M_u8	15
PrevWarningIndSignal_Cnt_M_u08[0]	1
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3985507328
Steering_Torque_Overlay_Stat_CE_c[0]	84
Steering_Torque_Overlay_Stat_CE_c[1]	98
Steering_Torque_Overlay_Stat_CE_c[2]	112
Steering_Torque_Overlay_Stat_CE_c[3]	126
Steering_Torque_Overlay_Stat_CE_c[4]	140
Steering_Torque_Overlay_Stat_CE_c[5]	154
Steering_Torque_Overlay_Stat_CE_c[6]	168
Steering_Torque_Overlay_Stat_CE_c[7]	182

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.800000012		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	5		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	67		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	56381		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	669100544		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	1.70000005		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.810000002		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	5.96999979		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	2.70000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	7	7	✓
CTCEventId_Cnt_M_u8	10	10	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSorce	49	49	✓
DTCDData.DTCNumber	29	29	✓
DTCDData.DTCFailType	76	76	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	11	11	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrldIvdRC_Cnt_M_u8	107	107	✓
LastReportedDTCEventID_Cnt_M_u8	4	4	✓
LastReportedGMStatus_Cnt_M_u8	15	15	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3985507328	3985507328	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrStatChksm	1	IIPutTxLKATrqOvrStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 3.8 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	7
CTCEventId_Cnt_M_u8	9
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	15
DTCDData.DTCNumber	54744
DTCDData.DTCFailType	65
DTCDData.DTCWmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	67
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	14
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	77
LKATrqOvrDivdRC_Cnt_M_u8	106
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208
LastReportedDTCEventID_Cnt_M_u8	4
LastReportedGMStatus_Cnt_M_u8	15
PrevWarningIndSignal_Cnt_M_u8[0]	0
PrevWarningIndSignal_Cnt_M_u8[1]	1
PrevWarningIndSignal_Cnt_M_u8[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	3985507328
Steering_Torque_Overlay_Stat_CE_c[0]	96
Steering_Torque_Overlay_Stat_CE_c[1]	112
Steering_Torque_Overlay_Stat_CE_c[2]	128
Steering_Torque_Overlay_Stat_CE_c[3]	144
Steering_Torque_Overlay_Stat_CE_c[4]	160
Steering_Torque_Overlay_Stat_CE_c[5]	176
Steering_Torque_Overlay_Stat_CE_c[6]	192
Steering_Torque_Overlay_Stat_CE_c[7]	208
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.800000012
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	6
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	67
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	56381
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	669100544
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	3
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	1.79999995
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.810000002
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	5.96999979
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	2
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	2.70000005

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	7	7	✓
CTCEventId_Cnt_M_u8	10	10	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	29	29	✓
DTCDData.DTCFailType	76	76	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	15	15	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	4	4	✓
GMStatus_Cnt_M_u8[2]	6	6	✓
GMStatus_Cnt_M_u8[3]	8	8	✓
GMStatus_Cnt_M_u8[4]	10	10	✓
GMStatus_Cnt_M_u8[5]	12	12	✓
GMStatus_Cnt_M_u8[6]	14	14	✓
GMStatus_Cnt_M_u8[7]	16	16	✓
GMStatus_Cnt_M_u8[8]	18	18	✓
GMStatus_Cnt_M_u8[9]	20	20	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	24	24	✓
GMStatus_Cnt_M_u8[12]	26	26	✓
GMStatus_Cnt_M_u8[13]	28	28	✓
GMStatus_Cnt_M_u8[14]	30	30	✓
GMStatus_Cnt_M_u8[15]	32	32	✓
GMStatus_Cnt_M_u8[16]	34	34	✓
GMStatus_Cnt_M_u8[17]	36	36	✓
GMStatus_Cnt_M_u8[18]	38	38	✓
GMStatus_Cnt_M_u8[19]	40	40	✓
GMStatus_Cnt_M_u8[20]	42	42	✓
GMStatus_Cnt_M_u8[21]	44	44	✓
GMStatus_Cnt_M_u8[22]	46	46	✓
GMStatus_Cnt_M_u8[23]	48	48	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	50	50	✓
GMStatus_Cnt_M_u8[25]	52	52	✓
GMStatus_Cnt_M_u8[26]	54	54	✓
GMStatus_Cnt_M_u8[27]	56	56	✓
GMStatus_Cnt_M_u8[28]	58	58	✓
GMStatus_Cnt_M_u8[29]	60	60	✓
GMStatus_Cnt_M_u8[30]	62	62	✓
GMStatus_Cnt_M_u8[31]	64	64	✓
LKATrqOvrIDvldRC_Cnt_M_u8	107	107	✓
LastReportedDTCEventID_Cnt_M_u8	4	4	✓
LastReportedGMStatus_Cnt_M_u8	15	15	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3985507328	3985507328	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDvldRC	1	IIPutTxLKATrqOvrIDvldRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFidCdClrdStat_778	1	IIPutTxDTCL_TstFidCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFidPwrUpSt_778	1	IIPutTxDTCL_TstFidPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 3.9 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	15
CTCEventId_Cnt_M_u8	34
CurrentDTCSentThisIC_Cnt_M_lgc	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTriggered	0
DTCDData.DTCSrc	4
DTCDData.DTCNumber	65535
DTCDData.DTCFailType	199
DTCDData.DTCWrnIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	148
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	0
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	0
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	1
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	0
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	1
DTCTriggeredFlag_Cnt_M_lgc[29]	0
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	1500
DemDTCNum_Cnt_M_u32[1]	3000
DemDTCNum_Cnt_M_u32[2]	4500
DemDTCNum_Cnt_M_u32[3]	6000
DemDTCNum_Cnt_M_u32[4]	7500
DemDTCNum_Cnt_M_u32[5]	9000
DemDTCNum_Cnt_M_u32[6]	10500
DemDTCNum_Cnt_M_u32[7]	12000
DemDTCNum_Cnt_M_u32[8]	13500
DemDTCNum_Cnt_M_u32[9]	15000
DemDTCNum_Cnt_M_u32[10]	16500
DemDTCNum_Cnt_M_u32[11]	18000
DemDTCNum_Cnt_M_u32[12]	19500
DemDTCNum_Cnt_M_u32[13]	21000
DemDTCNum_Cnt_M_u32[14]	22500
DemDTCNum_Cnt_M_u32[15]	24000
DemDTCNum_Cnt_M_u32[16]	25500
DemDTCNum_Cnt_M_u32[17]	27000
DemDTCNum_Cnt_M_u32[18]	28500
DemDTCNum_Cnt_M_u32[19]	30000
DemDTCNum_Cnt_M_u32[20]	31500
DemDTCNum_Cnt_M_u32[21]	33000
DemDTCNum_Cnt_M_u32[22]	34500
DemDTCNum_Cnt_M_u32[23]	36000
DemDTCNum_Cnt_M_u32[24]	37500
DemDTCNum_Cnt_M_u32[25]	39000
DemDTCNum_Cnt_M_u32[26]	40500
DemDTCNum_Cnt_M_u32[27]	42000

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[28]	43500
DemDTCNum_Cnt_M_u32[29]	45000
DemDTCNum_Cnt_M_u32[30]	46500
DemDTCNum_Cnt_M_u32[31]	48000
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	11
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	4
GMStatus_Cnt_M_u8[2]	6
GMStatus_Cnt_M_u8[3]	8
GMStatus_Cnt_M_u8[4]	10
GMStatus_Cnt_M_u8[5]	12
GMStatus_Cnt_M_u8[6]	14
GMStatus_Cnt_M_u8[7]	16
GMStatus_Cnt_M_u8[8]	18
GMStatus_Cnt_M_u8[9]	20
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	24
GMStatus_Cnt_M_u8[12]	26
GMStatus_Cnt_M_u8[13]	28
GMStatus_Cnt_M_u8[14]	30
GMStatus_Cnt_M_u8[15]	32
GMStatus_Cnt_M_u8[16]	34
GMStatus_Cnt_M_u8[17]	36
GMStatus_Cnt_M_u8[18]	38
GMStatus_Cnt_M_u8[19]	40
GMStatus_Cnt_M_u8[20]	42
GMStatus_Cnt_M_u8[21]	44
GMStatus_Cnt_M_u8[22]	46
GMStatus_Cnt_M_u8[23]	48
GMStatus_Cnt_M_u8[24]	50
GMStatus_Cnt_M_u8[25]	52
GMStatus_Cnt_M_u8[26]	54
GMStatus_Cnt_M_u8[27]	56
GMStatus_Cnt_M_u8[28]	58
GMStatus_Cnt_M_u8[29]	60
GMStatus_Cnt_M_u8[30]	62
GMStatus_Cnt_M_u8[31]	64
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	5
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	166
LKATrqOvrDlvdRC_Cnt_M_u8	210
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	13
LastReportedGMStatus_Cnt_M_u8	65
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	2919223808
Steering_Torque_Overlay_Stat_CE_c[0]	72
Steering_Torque_Overlay_Stat_CE_c[1]	84
Steering_Torque_Overlay_Stat_CE_c[2]	96
Steering_Torque_Overlay_Stat_CE_c[3]	108
Steering_Torque_Overlay_Stat_CE_c[4]	120
Steering_Torque_Overlay_Stat_CE_c[5]	132
Steering_Torque_Overlay_Stat_CE_c[6]	144
Steering_Torque_Overlay_Stat_CE_c[7]	156

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.469999999		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	7		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	148		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	33689		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3821733888		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	1.89999998		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.300000012		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	2.29999995		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	0		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-0.800000012		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	15	15	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSorce	4	4	✓
DTCDData.DTCNumber	65535	65535	✓
DTCDData.DTCFailType	199	199	✓
DTCDData.DTCWrmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	148	148	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	12	12	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	3	3	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	3	3	✓
GMStatus_Cnt_M_u8[4]	3	3	✓
GMStatus_Cnt_M_u8[5]	3	3	✓
GMStatus_Cnt_M_u8[6]	3	3	✓
GMStatus_Cnt_M_u8[7]	3	3	✓
GMStatus_Cnt_M_u8[8]	3	3	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[9]	3	3	✓
GMStatus_Cnt_M_u8[10]	3	3	✓
GMStatus_Cnt_M_u8[11]	3	3	✓
GMStatus_Cnt_M_u8[12]	3	3	✓
GMStatus_Cnt_M_u8[13]	3	3	✓
GMStatus_Cnt_M_u8[14]	3	3	✓
GMStatus_Cnt_M_u8[15]	3	3	✓
GMStatus_Cnt_M_u8[16]	3	3	✓
GMStatus_Cnt_M_u8[17]	3	3	✓
GMStatus_Cnt_M_u8[18]	3	3	✓
GMStatus_Cnt_M_u8[19]	3	3	✓
GMStatus_Cnt_M_u8[20]	3	3	✓
GMStatus_Cnt_M_u8[21]	3	3	✓
GMStatus_Cnt_M_u8[22]	3	3	✓
GMStatus_Cnt_M_u8[23]	3	3	✓
GMStatus_Cnt_M_u8[24]	3	3	✓
GMStatus_Cnt_M_u8[25]	3	3	✓
GMStatus_Cnt_M_u8[26]	3	3	✓
GMStatus_Cnt_M_u8[27]	3	3	✓
GMStatus_Cnt_M_u8[28]	3	3	✓
GMStatus_Cnt_M_u8[29]	3	3	✓
GMStatus_Cnt_M_u8[30]	3	3	✓
GMStatus_Cnt_M_u8[31]	3	3	✓
LKATrqOvriDlvdRC_Cnt_M_u8	211	211	✓
LastReportedDTCEventID_Cnt_M_u8	13	13	✓
LastReportedGMStatus_Cnt_M_u8	65	65	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	2919223808	2919223808	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrStItTqDlvd	1	IIPutTxLKAEIPwrStItTqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 3.10 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	11	
CTCEventId_Cnt_M_u8	10	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DTCTriggered	0	
DTCDData.DTCSource	26	
DTCDData.DTCNumber	1158	
DTCDData.DTCFailType	119	
DTCDData.DTCWrmIndRqdSt	1	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	1	
DTCDData.DTCHistStat	0	
DTCDData.DTCTstFldCdClrdStat	1	
DTCDData.DTCTstNPsdCdClrdSt	1	
DTCDData.DTCCurrentStatus	1	
DTCDData.DTCCodeSupported	0	
DTCDData.DTCFaulttype	53	
DTCTriggeredFlag_Cnt_M_lgc[0]	1	
DTCTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTriggeredFlag_Cnt_M_lgc[2]	1	
DTCTriggeredFlag_Cnt_M_lgc[3]	0	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	1	
DTCTriggeredFlag_Cnt_M_lgc[7]	0	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	0	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	0	
DTCTriggeredFlag_Cnt_M_lgc[14]	1	
DTCTriggeredFlag_Cnt_M_lgc[15]	0	
DTCTriggeredFlag_Cnt_M_lgc[16]	1	
DTCTriggeredFlag_Cnt_M_lgc[17]	1	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	0	
DTCTriggeredFlag_Cnt_M_lgc[20]	0	
DTCTriggeredFlag_Cnt_M_lgc[21]	1	
DTCTriggeredFlag_Cnt_M_lgc[22]	0	
DTCTriggeredFlag_Cnt_M_lgc[23]	1	
DTCTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	
DTCTriggeredFlag_Cnt_M_lgc[26]	0	
DTCTriggeredFlag_Cnt_M_lgc[27]	1	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	5
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	3
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	92

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKATrqOvrIdivdRC_Cnt_M_u8	58		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104		
LastReportedDTCEventID_Cnt_M_u8	17		
LastReportedGMStatus_Cnt_M_u8	87		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKAState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	3093112832		
Steering_Torque_Overlay_Stat_CE_c[0]	84		
Steering_Torque_Overlay_Stat_CE_c[1]	98		
Steering_Torque_Overlay_Stat_CE_c[2]	112		
Steering_Torque_Overlay_Stat_CE_c[3]	126		
Steering_Torque_Overlay_Stat_CE_c[4]	140		
Steering_Torque_Overlay_Stat_CE_c[5]	154		
Steering_Torque_Overlay_Stat_CE_c[6]	168		
Steering_Torque_Overlay_Stat_CE_c[7]	182		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.689999998		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	8		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	53		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	46431		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3689655808		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	0		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	2		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.529999971		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-9.60000038		
target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data	2		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.32000005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	11	11	✓
CTCEventId_Cnt_M_u8	11	11	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	7	7	✓
DTCDData.DTCFailType	8	8	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	1	1	✓
DTCDData.DTCTstNPsdPwrUpSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	6	6	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvriDlvdRC_Cnt_M_u8	59	59	✓
LastReportedDTCEventID_Cnt_M_u8	17	17	✓
LastReportedGMStatus_Cnt_M_u8	87	87	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3093112832	3093112832	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530

SriComOutput_Per1



Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcIO	1	IIPutTxStrngAsstRdcIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhIDtSt	1	IIPutTxHndsOffStrWhIDtSt	1	✓
IIPutTxHndsOffStrWhIDtMd	1	IIPutTxHndsOffStrWhIDtMd	1	✓
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WmIndRqdSt_778	1	IIPutTxDTCL_WmIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 3.11 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	6
CTCEventId_Cnt_M_u8	10
CurrentDTCSentThisIC_Cnt_M_lgc	0
DTCDData.DTCTriggered	1
DTCDData.DTCSource	7
DTCDData.DTCNumber	56270
DTCDData.DTCFailType	166
DTCDData.DTCWmIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	1
DTCDData.DTCFaulttype	92
DTCTTriggeredFlag_Cnt_M_lgc[0]	1
DTCTTriggeredFlag_Cnt_M_lgc[1]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	7
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	6
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	41
LKATrqOvrDlvdRC_Cnt_M_u8	1
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	29
LastReportedGMStatus_Cnt_M_u8	50
PrevWarningIndSignal_Cnt_M_u8[0]	0
PrevWarningIndSignal_Cnt_M_u8[1]	1
PrevWarningIndSignal_Cnt_M_u8[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	711186944
Steering_Torque_Overlay_Stat_CE_c[0]	12
Steering_Torque_Overlay_Stat_CE_c[1]	14
Steering_Torque_Overlay_Stat_CE_c[2]	16
Steering_Torque_Overlay_Stat_CE_c[3]	18
Steering_Torque_Overlay_Stat_CE_c[4]	20
Steering_Torque_Overlay_Stat_CE_c[5]	22
Steering_Torque_Overlay_Stat_CE_c[6]	24
Steering_Torque_Overlay_Stat_CE_c[7]	26
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.699999988
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	9
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	92
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	20588
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2570506240
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	2.0999999
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.25999999
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-1.39999998
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	6	6	✓
CTCEventId_Cnt_M_u8	11	11	✓
CurrentDTCSentThisIC_Cnt_M_lgc	0	0	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	0	0	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	0	0	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	8	8	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvrDlvdRC_Cnt_M_u8	2	2	✓
LastReportedDTCEventID_Cnt_M_u8	29	29	✓
LastReportedGMStatus_Cnt_M_u8	50	50	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	711186944	711186944	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKAState_State_enum	1	Rte_Read_Ap_SriComOutput_LKAState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmlndRqdSt_778	1	IIPutTxDTCl_WrmlndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 3.12 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	10
CTCEventId_Cnt_M_u8	10
CurrentDTCSentThisIC_Cnt_M_lgc	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTriggered	1
DTCDData.DTCSrcSource	9
DTCDData.DTCNumber	12420
DTCDData.DTCFailType	41
DTCDData.DTCWrmIndRqdSt	0
DTCDData.DTCTstFldPwrUpSt	1
DTCDData.DTCTstNPsdPwrupSt	0
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	113
DTCTriggeredFlag_Cnt_M_lgc[0]	0
DTCTriggeredFlag_Cnt_M_lgc[1]	1
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	1
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	0
DTCTriggeredFlag_Cnt_M_lgc[15]	1
DTCTriggeredFlag_Cnt_M_lgc[16]	0
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	1
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	0
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	6
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	3
GMStatus_Cnt_M_u8[2]	5
GMStatus_Cnt_M_u8[3]	7
GMStatus_Cnt_M_u8[4]	9
GMStatus_Cnt_M_u8[5]	11
GMStatus_Cnt_M_u8[6]	13
GMStatus_Cnt_M_u8[7]	15
GMStatus_Cnt_M_u8[8]	17
GMStatus_Cnt_M_u8[9]	19
GMStatus_Cnt_M_u8[10]	22
GMStatus_Cnt_M_u8[11]	23
GMStatus_Cnt_M_u8[12]	25
GMStatus_Cnt_M_u8[13]	27
GMStatus_Cnt_M_u8[14]	29
GMStatus_Cnt_M_u8[15]	31
GMStatus_Cnt_M_u8[16]	33
GMStatus_Cnt_M_u8[17]	35
GMStatus_Cnt_M_u8[18]	37
GMStatus_Cnt_M_u8[19]	39
GMStatus_Cnt_M_u8[20]	41
GMStatus_Cnt_M_u8[21]	43
GMStatus_Cnt_M_u8[22]	45
GMStatus_Cnt_M_u8[23]	47
GMStatus_Cnt_M_u8[24]	49
GMStatus_Cnt_M_u8[25]	51
GMStatus_Cnt_M_u8[26]	53
GMStatus_Cnt_M_u8[27]	55
GMStatus_Cnt_M_u8[28]	57
GMStatus_Cnt_M_u8[29]	59
GMStatus_Cnt_M_u8[30]	61
GMStatus_Cnt_M_u8[31]	63
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	0
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	224
LKATrqOvrldDlvdRC_Cnt_M_u8	241
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	12
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	14
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	16
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	18
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	20
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	22
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	24
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	26
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	54
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	676026112
Steering_Torque_Overlay_Stat_CE_c[0]	24
Steering_Torque_Overlay_Stat_CE_c[1]	28
Steering_Torque_Overlay_Stat_CE_c[2]	32
Steering_Torque_Overlay_Stat_CE_c[3]	36
Steering_Torque_Overlay_Stat_CE_c[4]	40
Steering_Torque_Overlay_Stat_CE_c[5]	44
Steering_Torque_Overlay_Stat_CE_c[6]	48
Steering_Torque_Overlay_Stat_CE_c[7]	52

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.74000001		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	10		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	113		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1045652736		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	3		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	2.20000005		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.319999993		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-8.80000019		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.75999999		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	10	10	✓
CTCEventId_Cnt_M_u8	10	10	✓
CurrentDTCSentThisIC_Cnt_M_Igc	0	0	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSorce	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	9	9	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldrStat	0	0	✓
DTCDData.DTCTstNPsdCdCldrSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	7	7	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	3	3	✓
GMStatus_Cnt_M_u8[2]	5	5	✓
GMStatus_Cnt_M_u8[3]	7	7	✓
GMStatus_Cnt_M_u8[4]	9	9	✓
GMStatus_Cnt_M_u8[5]	11	11	✓
GMStatus_Cnt_M_u8[6]	13	13	✓
GMStatus_Cnt_M_u8[7]	15	15	✓
GMStatus_Cnt_M_u8[8]	17	17	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[9]	19	19	✓
GMStatus_Cnt_M_u8[10]	22	22	✓
GMStatus_Cnt_M_u8[11]	23	23	✓
GMStatus_Cnt_M_u8[12]	25	25	✓
GMStatus_Cnt_M_u8[13]	27	27	✓
GMStatus_Cnt_M_u8[14]	29	29	✓
GMStatus_Cnt_M_u8[15]	31	31	✓
GMStatus_Cnt_M_u8[16]	33	33	✓
GMStatus_Cnt_M_u8[17]	35	35	✓
GMStatus_Cnt_M_u8[18]	37	37	✓
GMStatus_Cnt_M_u8[19]	39	39	✓
GMStatus_Cnt_M_u8[20]	41	41	✓
GMStatus_Cnt_M_u8[21]	43	43	✓
GMStatus_Cnt_M_u8[22]	45	45	✓
GMStatus_Cnt_M_u8[23]	47	47	✓
GMStatus_Cnt_M_u8[24]	49	49	✓
GMStatus_Cnt_M_u8[25]	51	51	✓
GMStatus_Cnt_M_u8[26]	53	53	✓
GMStatus_Cnt_M_u8[27]	55	55	✓
GMStatus_Cnt_M_u8[28]	57	57	✓
GMStatus_Cnt_M_u8[29]	59	59	✓
GMStatus_Cnt_M_u8[30]	61	61	✓
GMStatus_Cnt_M_u8[31]	63	63	✓
LKATrqOvrldDlvdRC_Cnt_M_u8	242	242	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	54	54	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	676026112	676026112	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDITrqDlrd	1	IIPutTxTrqOvrIDITrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDtSt	1	IIPutTxHndsOffStrWhlDtSt	1	✓
IIPutTxHndsOffStrWhlDtMd	1	IIPutTxHndsOffStrWhlDtMd	1	✓
IIPutTxHndsOffStrWhlDtStV	1	IIPutTxHndsOffStrWhlDtStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDITrqDlvd	1	IIPutTxLKATrqOvrIDITrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDtStGroup	1	IIPutTxHndsOffStrWhlDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 3.13 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	13
CTCEventId_Cnt_M_u8	13
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	1
DTCDData.DTCSource	10
DTCDData.DTCNumber	61885
DTCDData.DTCFailType	111
DTCDData.DTCWrnIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	1
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaultType	215
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	9
GMStatus_Cnt_M_u8[0]	1
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
GMStatus_Cnt_M_u8[9]	10		
GMStatus_Cnt_M_u8[10]	11		
GMStatus_Cnt_M_u8[11]	12		
GMStatus_Cnt_M_u8[12]	13		
GMStatus_Cnt_M_u8[13]	14		
GMStatus_Cnt_M_u8[14]	15		
GMStatus_Cnt_M_u8[15]	16		
GMStatus_Cnt_M_u8[16]	17		
GMStatus_Cnt_M_u8[17]	18		
GMStatus_Cnt_M_u8[18]	19		
GMStatus_Cnt_M_u8[19]	20		
GMStatus_Cnt_M_u8[20]	21		
GMStatus_Cnt_M_u8[21]	22		
GMStatus_Cnt_M_u8[22]	23		
GMStatus_Cnt_M_u8[23]	24		
GMStatus_Cnt_M_u8[24]	25		
GMStatus_Cnt_M_u8[25]	26		
GMStatus_Cnt_M_u8[26]	27		
GMStatus_Cnt_M_u8[27]	28		
GMStatus_Cnt_M_u8[28]	29		
GMStatus_Cnt_M_u8[29]	30		
GMStatus_Cnt_M_u8[30]	31		
GMStatus_Cnt_M_u8[31]	32		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2		
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	127		
LKATrqOvrlDlvdRC_Cnt_M_u8	62		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventID_Cnt_M_u8	31		
LastReportedGMStatus_Cnt_M_u8	56		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SrlComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SrlComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	1222163968		
Steering_Torque_Overlay_Stat_CE_c[0]	36		
Steering_Torque_Overlay_Stat_CE_c[1]	42		
Steering_Torque_Overlay_Stat_CE_c[2]	48		
Steering_Torque_Overlay_Stat_CE_c[3]	54		
Steering_Torque_Overlay_Stat_CE_c[4]	60		
Steering_Torque_Overlay_Stat_CE_c[5]	66		
Steering_Torque_Overlay_Stat_CE_c[6]	72		
Steering_Torque_Overlay_Stat_CE_c[7]	78		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	0.75999999		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	11		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	215		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	65535		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	7902208		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	2.29999995		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.5		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	-4.80000019		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	-1.96800005		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	13	13	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventId_Cnt_M_u8	14	14	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTTriggered	1	1	✓
DTCDData.DTCSSource	49	49	✓
DTCDData.DTCNumber	1	1	✓
DTCDData.DTCFailType	224	224	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaultype	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	10	10	✓
GMStatus_Cnt_M_u8[0]	1	1	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	63	63	✓
LastReportedDTCEventID_Cnt_M_u8	13	13	✓
LastReportedGMStatus_Cnt_M_u8	14	14	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1222163968	1222163968	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrIDlvdRC	1	IIPutTxTrqOvrIDlvdRC	1	✓
IIPutTxTrqOvrIDlvdRC	1	IIPutTxTrqOvrIDlvdRC	1	✓
IIPutTxTrqOvrIDlvdRC	1	IIPutTxTrqOvrIDlvdRC	1	✓
IIPutTxTrqOvrIDlvdRC	1	IIPutTxTrqOvrIDlvdRC	1	✓
IIPutTxTrqOvrIDlvdRC	1	IIPutTxTrqOvrIDlvdRC	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSource_778	1	IIPutTxDTCL_DTCSource_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdCldSt_778	1	IIPutTxDTCL_TstNPsdCdCldSt_778	1	✓
IIPutTxDTCL_TstFldCdCldStat_778	1	IIPutTxDTCL_TstFldCdCldStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

Test Step 3.14 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	34
CTCEventId_Cnt_M_u8	34

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
CurrentDTCSThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	11
DTCDData.DTCNumber	1158
DTCDData.DTCFailType	119
DTCDData.DTCWmIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrupSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdCldStat	1
DTCDData.DTCTstNPsdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	53
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	0
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	13
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	38
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	4
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	92
LKATrqOvriDlvdRC_Cnt_M_u8	58
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	48
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	56
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	64
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	80
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	88
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	104
LastReportedDTCEventID_Cnt_M_u8	17
LastReportedGMStatus_Cnt_M_u8	58
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	0
PrevWarningIndSignal_Cnt_M_u08[2]	0
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCTFlag_mS_M_u32p0	3093112832
Steering_Torque_Overlay_Stat_CE_c[0]	48
Steering_Torque_Overlay_Stat_CE_c[1]	56
Steering_Torque_Overlay_Stat_CE_c[2]	64
Steering_Torque_Overlay_Stat_CE_c[3]	72
Steering_Torque_Overlay_Stat_CE_c[4]	80
Steering_Torque_Overlay_Stat_CE_c[5]	88
Steering_Torque_Overlay_Stat_CE_c[6]	96

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value		
Steering_Torque_Overlay_Stat_CE_c[7]	104		
k_LKAMfgEnable_Cnt_Igc	1		
k_MaxHOWEstimate_Uls_f32	0.779999971		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	12		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	53		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	53757		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3689655808		
target_Rte_Read_Ap_SrlComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SrlComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SrlComOutput_ESCTorqueDelivered_HwNm_f32_data	-6.5		
target_Rte_Read_Ap_SrlComOutput_HOWEstimate_Uls_f32_data	0.629999995		
target_Rte_Read_Ap_SrlComOutput_HwTrq_HwNm_f32_data	10		
target_Rte_Read_Ap_SrlComOutput_LKASState_State_enum_data	2		
target_Rte_Read_Ap_SrlComOutput_LKATrqDelivered_HwNm_f32_data	1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	34	34	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	11	11	✓
DTCDData.DTCNumber	1158	1158	✓
DTCDData.DTCFailType	119	119	✓
DTCDData.DTCWmIndRqdSt	1	1	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrUpSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	53	53	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	14	14	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	17	17	✓
GMStatus_Cnt_M_u8[2]	17	17	✓
GMStatus_Cnt_M_u8[3]	17	17	✓
GMStatus_Cnt_M_u8[4]	17	17	✓
GMStatus_Cnt_M_u8[5]	17	17	✓
GMStatus_Cnt_M_u8[6]	17	17	✓
GMStatus_Cnt_M_u8[7]	17	17	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[8]	17	17	✓
GMStatus_Cnt_M_u8[9]	17	17	✓
GMStatus_Cnt_M_u8[10]	17	17	✓
GMStatus_Cnt_M_u8[11]	17	17	✓
GMStatus_Cnt_M_u8[12]	17	17	✓
GMStatus_Cnt_M_u8[13]	17	17	✓
GMStatus_Cnt_M_u8[14]	17	17	✓
GMStatus_Cnt_M_u8[15]	17	17	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	17	17	✓
GMStatus_Cnt_M_u8[18]	17	17	✓
GMStatus_Cnt_M_u8[19]	17	17	✓
GMStatus_Cnt_M_u8[20]	17	17	✓
GMStatus_Cnt_M_u8[21]	17	17	✓
GMStatus_Cnt_M_u8[22]	17	17	✓
GMStatus_Cnt_M_u8[23]	17	17	✓
GMStatus_Cnt_M_u8[24]	17	17	✓
GMStatus_Cnt_M_u8[25]	17	17	✓
GMStatus_Cnt_M_u8[26]	17	17	✓
GMStatus_Cnt_M_u8[27]	17	17	✓
GMStatus_Cnt_M_u8[28]	17	17	✓
GMStatus_Cnt_M_u8[29]	17	17	✓
GMStatus_Cnt_M_u8[30]	17	17	✓
GMStatus_Cnt_M_u8[31]	17	17	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	59	59	✓
LastReportedDTCEventID_Cnt_M_u8	17	17	✓
LastReportedGMStatus_Cnt_M_u8	58	58	✓
PrevWarningIndSignal_Cnt_M_u8[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u8[2]	0	0	✓
StartTimerToSetDTCFlag_mS_M_u32p0	3093112832	3093112832	✓



Test Step Call Trace



SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

SrlComOutput_Per1



© Report created by TESSY V3.1.13, report template V2.1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Actual Function	Count	Expected Function	Count	Result
IIPutTxHndsOffStrWhIDtStV	1	IIPutTxHndsOffStrWhIDtStV	1	✓
IIPutTxLKATrqOvriTrqDStat	1	IIPutTxLKATrqOvriTrqDStat	1	✓
IIPutTxLKAEIPwrSttItqDlvd	1	IIPutTxLKAEIPwrSttItqDlvd	1	✓
IIPutTxLKATrqOvriDlvdRC	1	IIPutTxLKATrqOvriDlvdRC	1	✓
IIPutTxLKATrqOvriDltTrqDlvd	1	IIPutTxLKATrqOvriDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhIDtStGroup	1	IIPutTxHndsOffStrWhIDtStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvriStatChksm	1	IIPutTxLKATrqOvriStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrmIndRqdSt_778	1	IIPutTxDTCl_WrmIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 3.15 (Repeat Count = 1)		✓
Name	Input Value	
CTCEventIdSV_Cnt_M_u8	0	
CTCEventId_Cnt_M_u8	0	
CurrentDTCSentThisIC_Cnt_M_lgc	1	
DTCDData.DTCTriggered	1	
DTCDData.DTCSource	24	
DTCDData.DTCNumber	61885	
DTCDData.DTCFailType	111	
DTCDData.DTCWrmIndRqdSt	1	
DTCDData.DTCTstFldPwrUpSt	0	
DTCDData.DTCTstNPsdPwrUpSt	1	
DTCDData.DTCHistStat	0	
DTCDData.DTCTstFldCdClrdStat	1	
DTCDData.DTCTstNPsdCdClrdSt	0	
DTCDData.DTCCurrentStatus	1	
DTCDData.DTCCodeSupported	0	
DTCDData.DTCFaulttype	215	
DTCTriggeredFlag_Cnt_M_lgc[0]	0	
DTCTriggeredFlag_Cnt_M_lgc[1]	0	
DTCTriggeredFlag_Cnt_M_lgc[2]	0	
DTCTriggeredFlag_Cnt_M_lgc[3]	1	
DTCTriggeredFlag_Cnt_M_lgc[4]	1	
DTCTriggeredFlag_Cnt_M_lgc[5]	1	
DTCTriggeredFlag_Cnt_M_lgc[6]	0	
DTCTriggeredFlag_Cnt_M_lgc[7]	1	
DTCTriggeredFlag_Cnt_M_lgc[8]	1	
DTCTriggeredFlag_Cnt_M_lgc[9]	0	
DTCTriggeredFlag_Cnt_M_lgc[10]	1	
DTCTriggeredFlag_Cnt_M_lgc[11]	0	
DTCTriggeredFlag_Cnt_M_lgc[12]	1	
DTCTriggeredFlag_Cnt_M_lgc[13]	0	
DTCTriggeredFlag_Cnt_M_lgc[14]	1	
DTCTriggeredFlag_Cnt_M_lgc[15]	0	
DTCTriggeredFlag_Cnt_M_lgc[16]	1	
DTCTriggeredFlag_Cnt_M_lgc[17]	0	
DTCTriggeredFlag_Cnt_M_lgc[18]	1	
DTCTriggeredFlag_Cnt_M_lgc[19]	0	
DTCTriggeredFlag_Cnt_M_lgc[20]	1	
DTCTriggeredFlag_Cnt_M_lgc[21]	0	
DTCTriggeredFlag_Cnt_M_lgc[22]	1	
DTCTriggeredFlag_Cnt_M_lgc[23]	0	
DTCTriggeredFlag_Cnt_M_lgc[24]	1	
DTCTriggeredFlag_Cnt_M_lgc[25]	1	
DTCTriggeredFlag_Cnt_M_lgc[26]	1	
DTCTriggeredFlag_Cnt_M_lgc[27]	0	

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	220
DemDTCNum_Cnt_M_u32[1]	240
DemDTCNum_Cnt_M_u32[2]	260
DemDTCNum_Cnt_M_u32[3]	280
DemDTCNum_Cnt_M_u32[4]	300
DemDTCNum_Cnt_M_u32[5]	320
DemDTCNum_Cnt_M_u32[6]	340
DemDTCNum_Cnt_M_u32[7]	360
DemDTCNum_Cnt_M_u32[8]	380
DemDTCNum_Cnt_M_u32[9]	400
DemDTCNum_Cnt_M_u32[10]	420
DemDTCNum_Cnt_M_u32[11]	440
DemDTCNum_Cnt_M_u32[12]	460
DemDTCNum_Cnt_M_u32[13]	480
DemDTCNum_Cnt_M_u32[14]	500
DemDTCNum_Cnt_M_u32[15]	520
DemDTCNum_Cnt_M_u32[16]	540
DemDTCNum_Cnt_M_u32[17]	560
DemDTCNum_Cnt_M_u32[18]	580
DemDTCNum_Cnt_M_u32[19]	600
DemDTCNum_Cnt_M_u32[20]	620
DemDTCNum_Cnt_M_u32[21]	640
DemDTCNum_Cnt_M_u32[22]	660
DemDTCNum_Cnt_M_u32[23]	680
DemDTCNum_Cnt_M_u32[24]	700
DemDTCNum_Cnt_M_u32[25]	720
DemDTCNum_Cnt_M_u32[26]	740
DemDTCNum_Cnt_M_u32[27]	760
DemDTCNum_Cnt_M_u32[28]	780
DemDTCNum_Cnt_M_u32[29]	800
DemDTCNum_Cnt_M_u32[30]	820
DemDTCNum_Cnt_M_u32[31]	840
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	12
GMStatus_Cnt_M_u8[0]	2
GMStatus_Cnt_M_u8[1]	2
GMStatus_Cnt_M_u8[2]	3
GMStatus_Cnt_M_u8[3]	4
GMStatus_Cnt_M_u8[4]	5
GMStatus_Cnt_M_u8[5]	6
GMStatus_Cnt_M_u8[6]	7
GMStatus_Cnt_M_u8[7]	8
GMStatus_Cnt_M_u8[8]	9
GMStatus_Cnt_M_u8[9]	10
GMStatus_Cnt_M_u8[10]	11
GMStatus_Cnt_M_u8[11]	12
GMStatus_Cnt_M_u8[12]	13
GMStatus_Cnt_M_u8[13]	14
GMStatus_Cnt_M_u8[14]	15
GMStatus_Cnt_M_u8[15]	16
GMStatus_Cnt_M_u8[16]	17
GMStatus_Cnt_M_u8[17]	18
GMStatus_Cnt_M_u8[18]	19
GMStatus_Cnt_M_u8[19]	20
GMStatus_Cnt_M_u8[20]	21
GMStatus_Cnt_M_u8[21]	22
GMStatus_Cnt_M_u8[22]	23
GMStatus_Cnt_M_u8[23]	24
GMStatus_Cnt_M_u8[24]	25
GMStatus_Cnt_M_u8[25]	26
GMStatus_Cnt_M_u8[26]	27
GMStatus_Cnt_M_u8[27]	28
GMStatus_Cnt_M_u8[28]	29
GMStatus_Cnt_M_u8[29]	30
GMStatus_Cnt_M_u8[30]	31
GMStatus_Cnt_M_u8[31]	32
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	2
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	127

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
LKATrqOvrDlvdRC_Cnt_M_u8	62		
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	24		
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	28		
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	32		
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	36		
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	40		
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	44		
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	48		
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	52		
LastReportedDTCEventID_Cnt_M_u8	31		
LastReportedGMStatus_Cnt_M_u8	84		
PrevWarningIndSignal_Cnt_M_u08[0]	1		
PrevWarningIndSignal_Cnt_M_u08[1]	1		
PrevWarningIndSignal_Cnt_M_u08[2]	1		
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data		
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data		
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data		
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data		
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data		
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data		
StartTimerToSetDTCFlag_mS_M_u32p0	1222163968		
Steering_Torque_Overlay_Stat_CE_c[0]	60		
Steering_Torque_Overlay_Stat_CE_c[1]	70		
Steering_Torque_Overlay_Stat_CE_c[2]	80		
Steering_Torque_Overlay_Stat_CE_c[3]	90		
Steering_Torque_Overlay_Stat_CE_c[4]	100		
Steering_Torque_Overlay_Stat_CE_c[5]	110		
Steering_Torque_Overlay_Stat_CE_c[6]	120		
Steering_Torque_Overlay_Stat_CE_c[7]	130		
k_LKAMfgEnable_Cnt_lgc	1		
k_MaxHOWEstimate_Uls_f32	1		
k_SComTrqPosPol_Cnt_s08	1		
target_Dem_GetEventStatus_EventStatusExtended	13		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	215		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	7902208		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	0		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-6.30000019		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.0250000004		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	0.6200000005		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-1.39999998		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	0	0	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	1	1	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	0	0	✓
DTCDData.DTCFailType	220	220	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrUpSt	0	0	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	0	0	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	13	13	✓
GMStatus_Cnt_M_u8[0]	2	2	✓
GMStatus_Cnt_M_u8[1]	2	2	✓
GMStatus_Cnt_M_u8[2]	3	3	✓
GMStatus_Cnt_M_u8[3]	4	4	✓
GMStatus_Cnt_M_u8[4]	5	5	✓
GMStatus_Cnt_M_u8[5]	6	6	✓
GMStatus_Cnt_M_u8[6]	7	7	✓
GMStatus_Cnt_M_u8[7]	8	8	✓
GMStatus_Cnt_M_u8[8]	9	9	✓
GMStatus_Cnt_M_u8[9]	10	10	✓
GMStatus_Cnt_M_u8[10]	11	11	✓
GMStatus_Cnt_M_u8[11]	12	12	✓
GMStatus_Cnt_M_u8[12]	13	13	✓
GMStatus_Cnt_M_u8[13]	14	14	✓
GMStatus_Cnt_M_u8[14]	15	15	✓
GMStatus_Cnt_M_u8[15]	16	16	✓
GMStatus_Cnt_M_u8[16]	17	17	✓
GMStatus_Cnt_M_u8[17]	18	18	✓
GMStatus_Cnt_M_u8[18]	19	19	✓
GMStatus_Cnt_M_u8[19]	20	20	✓
GMStatus_Cnt_M_u8[20]	21	21	✓
GMStatus_Cnt_M_u8[21]	22	22	✓
GMStatus_Cnt_M_u8[22]	23	23	✓
GMStatus_Cnt_M_u8[23]	24	24	✓
GMStatus_Cnt_M_u8[24]	25	25	✓
GMStatus_Cnt_M_u8[25]	26	26	✓
GMStatus_Cnt_M_u8[26]	27	27	✓
GMStatus_Cnt_M_u8[27]	28	28	✓
GMStatus_Cnt_M_u8[28]	29	29	✓
GMStatus_Cnt_M_u8[29]	30	30	✓
GMStatus_Cnt_M_u8[30]	31	31	✓
GMStatus_Cnt_M_u8[31]	32	32	✓
LKATrqOvriDlvdRC_Cnt_M_u8	63	63	✓
LastReportedDTCEventID_Cnt_M_u8	0	0	✓
LastReportedGMStatus_Cnt_M_u8	2	2	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	1222163968	1222163968	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrlTrqDStat	1	IIPutTxTrqOvrlTrqDStat	1	✓
IIPutTxTrqOvrlDvrdARC	1	IIPutTxTrqOvrlDvrdARC	1	✓
IIPutTxTrqOvrlDltTrqDlrd	1	IIPutTxTrqOvrlDltTrqDlrd	1	✓
IIPutTxTrqOvrlDChksm	1	IIPutTxTrqOvrlDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDltSt	1	IIPutTxHndsOffStrWhlDltSt	1	✓
IIPutTxHndsOffStrWhlDltMd	1	IIPutTxHndsOffStrWhlDltMd	1	✓
IIPutTxHndsOffStrWhlDltStV	1	IIPutTxHndsOffStrWhlDltStV	1	✓
IIPutTxLKATrqOvrlTrqDStat	1	IIPutTxLKATrqOvrlTrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrlDlvdRC	1	IIPutTxLKATrqOvrlDlvdRC	1	✓
IIPutTxLKATrqOvrlDltTrqDlvd	1	IIPutTxLKATrqOvrlDltTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDltStGroup	1	IIPutTxHndsOffStrWhlDltStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrlStatChksm	1	IIPutTxLKATrqOvrlStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFldCdClrdStat_778	1	IIPutTxDTCl_TstFldCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFldPwrUpSt_778	1	IIPutTxDTCl_TstFldPwrUpSt_778	1	✓
IIPutTxDTCl_WrnIndRqdSt_778	1	IIPutTxDTCl_WrnIndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 3.16 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	30
CTCEventId_Cnt_M_u8	0
CurrentDTCSentThisIC_Cnt_M_lgc	1
DTCDData.DTCTriggered	0
DTCDData.DTCSource	31
DTCDData.DTCNumber	25199
DTCDData.DTCFailType	62
DTCDData.DTCWmIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPsdPwrUpSt	1
DTCDData.DTCHistStat	0
DTCDData.DTCTstFldCdClrdStat	0
DTCDData.DTCTstNPsdCdClrdSt	0
DTCDData.DTCCurrentStatus	0
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	183
DTCTriggeredFlag_Cnt_M_lgc[0]	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Input Value
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	0
DTCTriggeredFlag_Cnt_M_lgc[3]	1
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	0
DTCTriggeredFlag_Cnt_M_lgc[7]	1
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	1
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	0
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	1
DTCTriggeredFlag_Cnt_M_lgc[21]	0
DTCTriggeredFlag_Cnt_M_lgc[22]	1
DTCTriggeredFlag_Cnt_M_lgc[23]	0
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	1
DTCTriggeredFlag_Cnt_M_lgc[27]	0
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	0
DTCTriggeredFlag_Cnt_M_lgc[31]	1
DemDTCNum_Cnt_M_u32[0]	100
DemDTCNum_Cnt_M_u32[1]	200
DemDTCNum_Cnt_M_u32[2]	300
DemDTCNum_Cnt_M_u32[3]	400
DemDTCNum_Cnt_M_u32[4]	500
DemDTCNum_Cnt_M_u32[5]	600
DemDTCNum_Cnt_M_u32[6]	700
DemDTCNum_Cnt_M_u32[7]	800
DemDTCNum_Cnt_M_u32[8]	900
DemDTCNum_Cnt_M_u32[9]	1000
DemDTCNum_Cnt_M_u32[10]	1100
DemDTCNum_Cnt_M_u32[11]	1200
DemDTCNum_Cnt_M_u32[12]	1300
DemDTCNum_Cnt_M_u32[13]	1400
DemDTCNum_Cnt_M_u32[14]	1500
DemDTCNum_Cnt_M_u32[15]	1600
DemDTCNum_Cnt_M_u32[16]	1700
DemDTCNum_Cnt_M_u32[17]	1800
DemDTCNum_Cnt_M_u32[18]	1900
DemDTCNum_Cnt_M_u32[19]	2000
DemDTCNum_Cnt_M_u32[20]	2100
DemDTCNum_Cnt_M_u32[21]	2200
DemDTCNum_Cnt_M_u32[22]	2300
DemDTCNum_Cnt_M_u32[23]	2400
DemDTCNum_Cnt_M_u32[24]	2500
DemDTCNum_Cnt_M_u32[25]	2600
DemDTCNum_Cnt_M_u32[26]	2700
DemDTCNum_Cnt_M_u32[27]	2800
DemDTCNum_Cnt_M_u32[28]	2900
DemDTCNum_Cnt_M_u32[29]	3000
DemDTCNum_Cnt_M_u32[30]	3100
DemDTCNum_Cnt_M_u32[31]	3200
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	2
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrq_1	1
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	135
LKATrqOvrIdlvdRC_Cnt_M_u8	88
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	72
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	84
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	108
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	120
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	132
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	156
LastReportedDTCEventID_Cnt_M_u8	31
LastReportedGMStatus_Cnt_M_u8	31
PrevWarningIndSignal_Cnt_M_u8[0]	0
PrevWarningIndSignal_Cnt_M_u8[1]	1
PrevWarningIndSignal_Cnt_M_u8[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKAState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	496943616
Steering_Torque_Overlay_Stat_CE_c[0]	72
Steering_Torque_Overlay_Stat_CE_c[1]	84
Steering_Torque_Overlay_Stat_CE_c[2]	96
Steering_Torque_Overlay_Stat_CE_c[3]	108
Steering_Torque_Overlay_Stat_CE_c[4]	120
Steering_Torque_Overlay_Stat_CE_c[5]	132
Steering_Torque_Overlay_Stat_CE_c[6]	144
Steering_Torque_Overlay_Stat_CE_c[7]	156
k_LKAMfgEnable_Cnt_lgc	1
k_MaxHOWEstimate_Uls_f32	0.129999995
k_SComTrqPosPol_Cnt_s08	1
target_Dem_GetEventStatus_EventStatusExtended	14
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	183
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	55162
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2703390720
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data	1
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	2
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-6.0999999
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.280000001
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	10
target_Rte_Read_Ap_SriComOutput_LKAState_State_enum_data	2
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	2.70000005

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SrlComOutput_Per1

Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	30	30	✓
CTCEventId_Cnt_M_u8	1	1	✓
CurrentDTCSentThisIC_Cnt_M_lgc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	12	*none*	✓
DTCDData.DTCFailType	128	*none*	✓
DTCDData.DTCWmIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	0	0	✓
DTCDData.DTCHistStat	1	1	✓
DTCDData.DTCTstFldCdCldStat	1	1	✓
DTCDData.DTCTstNPsdCdCldSt	1	1	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[2]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[3]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[6]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[7]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[13]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[17]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[20]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[21]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[22]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[23]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[26]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[27]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_lgc[30]	0	0	✓
DTCTriggeredFlag_Cnt_M_lgc[31]	1	1	✓
ESCRollCount_Cnt_M_u08	3	3	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvrIDlvdRC_Cnt_M_u8	89	89	✓
LastReportedDTCEventID_Cnt_M_u8	31	31	✓
LastReportedGMStatus_Cnt_M_u8	31	31	✓
PrevWarningIndSignal_Cnt_M_u08[0]	0	*none*	✓
PrevWarningIndSignal_Cnt_M_u08[1]	0	0	✓
PrevWarningIndSignal_Cnt_M_u08[2]	1	1	✓
StartTimerToSetDTCFlag_mS_M_u32p0	496943616	496943616	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItTqDlrd	1	IIPutTxElPwrSttItTqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDItTrqDlrd	1	IIPutTxTrqOvrIDItTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	Rte_Read_Ap_SriComOutput_LKASState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32	1	✓
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_GetNTCAActive	6	✓
IIPutTxLKADrvAppldTrqV	1	IIPutTxLKADrvAppldTrqV	1	✓
IIPutTxHndsOffStrWhlDlSt	1	IIPutTxHndsOffStrWhlDlSt	1	✓
IIPutTxHndsOffStrWhlDlMd	1	IIPutTxHndsOffStrWhlDlMd	1	✓
IIPutTxHndsOffStrWhlDlStV	1	IIPutTxHndsOffStrWhlDlStV	1	✓
IIPutTxLKATrqOvrITrqDStat	1	IIPutTxLKATrqOvrITrqDStat	1	✓
IIPutTxLKAEIPwrSttItTqDlvd	1	IIPutTxLKAEIPwrSttItTqDlvd	1	✓
IIPutTxLKATrqOvrIDlvdRC	1	IIPutTxLKATrqOvrIDlvdRC	1	✓
IIPutTxLKATrqOvrIDItTrqDlvd	1	IIPutTxLKATrqOvrIDItTrqDlvd	1	✓
IIPutTxLKADrvAppldTrq	1	IIPutTxLKADrvAppldTrq	1	✓
IIPutTxHndsOffStrWhlDlStGroup	1	IIPutTxHndsOffStrWhlDlStGroup	1	✓
IIPutTxLKADrvAppldTrqGroup	1	IIPutTxLKADrvAppldTrqGroup	1	✓
IIPutTxLKATrqOvrIStatChksm	1	IIPutTxLKATrqOvrIStatChksm	1	✓
IIPutTxDTCl_DTCTriggered_778	1	IIPutTxDTCl_DTCTriggered_778	1	✓
IIPutTxDTCl_DTCSource_778	1	IIPutTxDTCl_DTCSource_778	1	✓
IIPutTxDTCl_DTCNumber_778	1	IIPutTxDTCl_DTCNumber_778	1	✓
IIPutTxDTCl_DTCFailType_778	1	IIPutTxDTCl_DTCFailType_778	1	✓
IIPutTxDTCl_CodeSupported_778	1	IIPutTxDTCl_CodeSupported_778	1	✓
IIPutTxDTCl_CurrentStatus_778	1	IIPutTxDTCl_CurrentStatus_778	1	✓
IIPutTxDTCl_TstNPsdCdClrdSt_778	1	IIPutTxDTCl_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCl_TstFidCdClrdStat_778	1	IIPutTxDTCl_TstFidCdClrdStat_778	1	✓
IIPutTxDTCl_HistStat_778	1	IIPutTxDTCl_HistStat_778	1	✓
IIPutTxDTCl_TstNPsdPwrUpSt_778	1	IIPutTxDTCl_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCl_TstFidPwrUpSt_778	1	IIPutTxDTCl_TstFidPwrUpSt_778	1	✓
IIPutTxDTCl_WrmlndRqdSt_778	1	IIPutTxDTCl_WrmlndRqdSt_778	1	✓
IIPutTxDTCl_DTCFaultType_778	1	IIPutTxDTCl_DTCFaultType_778	1	✓
IIPutTxDTClInfo_778	1	IIPutTxDTClInfo_778	1	✓

Test Step 3.17 (Repeat Count = 1)	
Name	Input Value
CTCEventIdSV_Cnt_M_u8	15
CTCEventId_Cnt_M_u8	6
CurrentDTCSentThisIS_Cnt_M_lgc	1

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DTCDData.DTCTriggered	1
DTCDData.DTCSrc	35
DTCDData.DTCNumber	58986
DTCDData.DTCFailType	3
DTCDData.DTCWrmIndRqdSt	1
DTCDData.DTCTstFldPwrUpSt	0
DTCDData.DTCTstNPSdPwrupSt	1
DTCDData.DTCHistStat	1
DTCDData.DTCTstFldCdCldStat	0
DTCDData.DTCTstNPSdCdCldSt	1
DTCDData.DTCCurrentStatus	1
DTCDData.DTCCodeSupported	0
DTCDData.DTCFaulttype	106
DTCTriggeredFlag_Cnt_M_lgc[0]	1
DTCTriggeredFlag_Cnt_M_lgc[1]	0
DTCTriggeredFlag_Cnt_M_lgc[2]	1
DTCTriggeredFlag_Cnt_M_lgc[3]	0
DTCTriggeredFlag_Cnt_M_lgc[4]	1
DTCTriggeredFlag_Cnt_M_lgc[5]	1
DTCTriggeredFlag_Cnt_M_lgc[6]	1
DTCTriggeredFlag_Cnt_M_lgc[7]	0
DTCTriggeredFlag_Cnt_M_lgc[8]	1
DTCTriggeredFlag_Cnt_M_lgc[9]	0
DTCTriggeredFlag_Cnt_M_lgc[10]	1
DTCTriggeredFlag_Cnt_M_lgc[11]	0
DTCTriggeredFlag_Cnt_M_lgc[12]	1
DTCTriggeredFlag_Cnt_M_lgc[13]	0
DTCTriggeredFlag_Cnt_M_lgc[14]	1
DTCTriggeredFlag_Cnt_M_lgc[15]	0
DTCTriggeredFlag_Cnt_M_lgc[16]	1
DTCTriggeredFlag_Cnt_M_lgc[17]	1
DTCTriggeredFlag_Cnt_M_lgc[18]	1
DTCTriggeredFlag_Cnt_M_lgc[19]	0
DTCTriggeredFlag_Cnt_M_lgc[20]	0
DTCTriggeredFlag_Cnt_M_lgc[21]	1
DTCTriggeredFlag_Cnt_M_lgc[22]	0
DTCTriggeredFlag_Cnt_M_lgc[23]	1
DTCTriggeredFlag_Cnt_M_lgc[24]	1
DTCTriggeredFlag_Cnt_M_lgc[25]	1
DTCTriggeredFlag_Cnt_M_lgc[26]	0
DTCTriggeredFlag_Cnt_M_lgc[27]	1
DTCTriggeredFlag_Cnt_M_lgc[28]	0
DTCTriggeredFlag_Cnt_M_lgc[29]	1
DTCTriggeredFlag_Cnt_M_lgc[30]	1
DTCTriggeredFlag_Cnt_M_lgc[31]	0
DemDTCNum_Cnt_M_u32[0]	115
DemDTCNum_Cnt_M_u32[1]	130
DemDTCNum_Cnt_M_u32[2]	145
DemDTCNum_Cnt_M_u32[3]	160
DemDTCNum_Cnt_M_u32[4]	175
DemDTCNum_Cnt_M_u32[5]	190
DemDTCNum_Cnt_M_u32[6]	205
DemDTCNum_Cnt_M_u32[7]	220
DemDTCNum_Cnt_M_u32[8]	235
DemDTCNum_Cnt_M_u32[9]	250
DemDTCNum_Cnt_M_u32[10]	265
DemDTCNum_Cnt_M_u32[11]	280
DemDTCNum_Cnt_M_u32[12]	295
DemDTCNum_Cnt_M_u32[13]	310
DemDTCNum_Cnt_M_u32[14]	325
DemDTCNum_Cnt_M_u32[15]	340
DemDTCNum_Cnt_M_u32[16]	355
DemDTCNum_Cnt_M_u32[17]	370
DemDTCNum_Cnt_M_u32[18]	385
DemDTCNum_Cnt_M_u32[19]	400
DemDTCNum_Cnt_M_u32[20]	415
DemDTCNum_Cnt_M_u32[21]	430
DemDTCNum_Cnt_M_u32[22]	445
DemDTCNum_Cnt_M_u32[23]	460
DemDTCNum_Cnt_M_u32[24]	475
DemDTCNum_Cnt_M_u32[25]	490
DemDTCNum_Cnt_M_u32[26]	505
DemDTCNum_Cnt_M_u32[27]	520

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value
DemDTCNum_Cnt_M_u32[28]	535
DemDTCNum_Cnt_M_u32[29]	550
DemDTCNum_Cnt_M_u32[30]	565
DemDTCNum_Cnt_M_u32[31]	580
Dem_GetEventStatus(EventStatusExtended)	target_Dem_GetEventStatus_EventStatusExtended
Dem_GetIndicatorStatus(Dem_IndicatorStatus)	target_Dem_GetIndicatorStatus_Dem_IndicatorStatus
ESCRollCount_Cnt_M_u08	1
GMStatus_Cnt_M_u8[0]	3
GMStatus_Cnt_M_u8[1]	6
GMStatus_Cnt_M_u8[2]	9
GMStatus_Cnt_M_u8[3]	12
GMStatus_Cnt_M_u8[4]	15
GMStatus_Cnt_M_u8[5]	18
GMStatus_Cnt_M_u8[6]	21
GMStatus_Cnt_M_u8[7]	24
GMStatus_Cnt_M_u8[8]	27
GMStatus_Cnt_M_u8[9]	30
GMStatus_Cnt_M_u8[10]	33
GMStatus_Cnt_M_u8[11]	36
GMStatus_Cnt_M_u8[12]	39
GMStatus_Cnt_M_u8[13]	42
GMStatus_Cnt_M_u8[14]	45
GMStatus_Cnt_M_u8[15]	48
GMStatus_Cnt_M_u8[16]	51
GMStatus_Cnt_M_u8[17]	54
GMStatus_Cnt_M_u8[18]	57
GMStatus_Cnt_M_u8[19]	60
GMStatus_Cnt_M_u8[20]	63
GMStatus_Cnt_M_u8[21]	66
GMStatus_Cnt_M_u8[22]	69
GMStatus_Cnt_M_u8[23]	72
GMStatus_Cnt_M_u8[24]	75
GMStatus_Cnt_M_u8[25]	78
GMStatus_Cnt_M_u8[26]	81
GMStatus_Cnt_M_u8[27]	84
GMStatus_Cnt_M_u8[28]	87
GMStatus_Cnt_M_u8[29]	90
GMStatus_Cnt_M_u8[30]	93
GMStatus_Cnt_M_u8[31]	96
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_1	7
LKADrvAppldTrqGroup.LKADrvAppldTrqGroup.LKADrvAppldTrq_0	235
LKATrqOvrldDlvdRC_Cnt_M_u8	212
LKA_Steering_Trq_Overlay_Stat_HS_c[0]	96
LKA_Steering_Trq_Overlay_Stat_HS_c[1]	112
LKA_Steering_Trq_Overlay_Stat_HS_c[2]	128
LKA_Steering_Trq_Overlay_Stat_HS_c[3]	144
LKA_Steering_Trq_Overlay_Stat_HS_c[4]	160
LKA_Steering_Trq_Overlay_Stat_HS_c[5]	176
LKA_Steering_Trq_Overlay_Stat_HS_c[6]	192
LKA_Steering_Trq_Overlay_Stat_HS_c[7]	208
LastReportedDTCEventID_Cnt_M_u8	27
LastReportedGMStatus_Cnt_M_u8	35
PrevWarningIndSignal_Cnt_M_u08[0]	0
PrevWarningIndSignal_Cnt_M_u08[1]	1
PrevWarningIndSignal_Cnt_M_u08[2]	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc(data)	target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_lgc_data
Rte_Read_Ap_SriComOutput_ESCState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data
Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32(data)	target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data
Rte_Read_Ap_SriComOutput_LKASState_State_enum(data)	target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data
Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32(data)	target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data
StartTimerToSetDTCFlag_mS_M_u32p0	619924480
Steering_Torque_Overlay_Stat_CE_c[0]	96
Steering_Torque_Overlay_Stat_CE_c[1]	112
Steering_Torque_Overlay_Stat_CE_c[2]	128
Steering_Torque_Overlay_Stat_CE_c[3]	144
Steering_Torque_Overlay_Stat_CE_c[4]	160
Steering_Torque_Overlay_Stat_CE_c[5]	176
Steering_Torque_Overlay_Stat_CE_c[6]	192
Steering_Torque_Overlay_Stat_CE_c[7]	208

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Input Value		
k_LKAMfgEnable_Cnt_Igc	0		
k_MaxHOWEstimate_Uls_f32	0.170000002		
k_SComTrqPosPol_Cnt_s08	-1		
target_Dem_GetEventStatus_EventStatusExtended	16		
target_Dem_GetIndicatorStatus_Dem_IndicatorStatus	1		
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	51561		
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_Curren	109359616		
target_Rte_Read_Ap_SriComOutput_DiagRmpToZeroActive_Cnt_Igc_data	1		
target_Rte_Read_Ap_SriComOutput_ESCState_State_enum_data	4		
target_Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32_data	-5.699999981		
target_Rte_Read_Ap_SriComOutput_HOWEstimate_Uls_f32_data	0.899999976		
target_Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32_data	-8.81000042		
target_Rte_Read_Ap_SriComOutput_LKASState_State_enum_data	1		
target_Rte_Read_Ap_SriComOutput_LKATrqDelivered_HwNm_f32_data	-0.0599999987		
Name	Actual Value	Expected Value	Result
CTCEventIdSV_Cnt_M_u8	15	15	✓
CTCEventId_Cnt_M_u8	7	7	✓
CurrentDTCSentThisIC_Cnt_M_Igc	1	1	✓
DTCDData.DTCTriggered	0	0	✓
DTCDData.DTCSource	49	49	✓
DTCDData.DTCNumber	2	2	✓
DTCDData.DTCFailType	8	8	✓
DTCDData.DTCWrnIndRqdSt	0	0	✓
DTCDData.DTCTstFldPwrUpSt	0	0	✓
DTCDData.DTCTstNPsdPwrupSt	1	1	✓
DTCDData.DTCHistStat	0	0	✓
DTCDData.DTCTstFldCdCldStat	0	0	✓
DTCDData.DTCTstNPsdCdCldSt	0	0	✓
DTCDData.DTCCurrentStatus	1	1	✓
DTCDData.DTCCodeSupported	1	1	✓
DTCDData.DTCFaulttype	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[0]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[1]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[2]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[3]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[4]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[5]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[6]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[7]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[8]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[9]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[10]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[11]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[12]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[13]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[14]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[15]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[16]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[17]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[18]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[19]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[20]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[21]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[22]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[23]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[24]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[25]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[26]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[27]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[28]	0	0	✓
DTCTriggeredFlag_Cnt_M_Igc[29]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[30]	1	1	✓
DTCTriggeredFlag_Cnt_M_Igc[31]	0	0	✓
ESCRollCount_Cnt_M_u08	2	2	✓
GMStatus_Cnt_M_u8[0]	3	3	✓
GMStatus_Cnt_M_u8[1]	6	6	✓
GMStatus_Cnt_M_u8[2]	9	9	✓
GMStatus_Cnt_M_u8[3]	12	12	✓
GMStatus_Cnt_M_u8[4]	15	15	✓
GMStatus_Cnt_M_u8[5]	18	18	✓
GMStatus_Cnt_M_u8[6]	21	21	✓
GMStatus_Cnt_M_u8[7]	24	24	✓
GMStatus_Cnt_M_u8[8]	27	27	✓

TEST DETAILS REPORT

2016-06-29, 14:00:09+0530



SriComOutput_Per1

Name	Actual Value	Expected Value	Result
GMStatus_Cnt_M_u8[9]	30	30	✓
GMStatus_Cnt_M_u8[10]	33	33	✓
GMStatus_Cnt_M_u8[11]	36	36	✓
GMStatus_Cnt_M_u8[12]	39	39	✓
GMStatus_Cnt_M_u8[13]	42	42	✓
GMStatus_Cnt_M_u8[14]	45	45	✓
GMStatus_Cnt_M_u8[15]	48	48	✓
GMStatus_Cnt_M_u8[16]	51	51	✓
GMStatus_Cnt_M_u8[17]	54	54	✓
GMStatus_Cnt_M_u8[18]	57	57	✓
GMStatus_Cnt_M_u8[19]	60	60	✓
GMStatus_Cnt_M_u8[20]	63	63	✓
GMStatus_Cnt_M_u8[21]	66	66	✓
GMStatus_Cnt_M_u8[22]	69	69	✓
GMStatus_Cnt_M_u8[23]	72	72	✓
GMStatus_Cnt_M_u8[24]	75	75	✓
GMStatus_Cnt_M_u8[25]	78	78	✓
GMStatus_Cnt_M_u8[26]	81	81	✓
GMStatus_Cnt_M_u8[27]	84	84	✓
GMStatus_Cnt_M_u8[28]	87	87	✓
GMStatus_Cnt_M_u8[29]	90	90	✓
GMStatus_Cnt_M_u8[30]	93	93	✓
GMStatus_Cnt_M_u8[31]	96	96	✓
LKATrqOvrDlvdRC_Cnt_M_u8	212	212	✓
LastReportedDTCEventID_Cnt_M_u8	27	27	✓
LastReportedGMStatus_Cnt_M_u8	35	35	✓
PrevWarningIndSignal_Cnt_M_u8[0]	1	*none*	✓
PrevWarningIndSignal_Cnt_M_u8[1]	1	1	✓
PrevWarningIndSignal_Cnt_M_u8[2]	1	1	✓
StartTimerToSetDTCFlag_ms_M_u32p0	619924480	619924480	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IISetEvent	1	IISetEvent	1	✓
IIPutTxPwrStrIO	1	IIPutTxPwrStrIO	1	✓
SriComOutput_WarningIndicatorHandler	1	SriComOutput_WarningIndicatorHandler	1	✓
Dem_GetIndicatorStatus	1	Dem_GetIndicatorStatus	1	✓
IIPutTxStrngAsstRdcdIO	1	IIPutTxStrngAsstRdcdIO	1	✓
Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	Rte_Read_Ap_SriComOutput_ESCState_State_enum	1	✓
Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	Rte_Read_Ap_SriComOutput_ESCTorqueDelivered_HwNm_f32	1	✓
Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	Rte_Read_Ap_SriComOutput_HwTrq_HwNm_f32	1	✓
IIPutTxElPwrSttItqDlrd	1	IIPutTxElPwrSttItqDlrd	1	✓
IIPutTxTrqOvrITrqDStat	1	IIPutTxTrqOvrITrqDStat	1	✓
IIPutTxTrqOvrIDvrdARC	1	IIPutTxTrqOvrIDvrdARC	1	✓
IIPutTxTrqOvrIDltTrqDlrd	1	IIPutTxTrqOvrIDltTrqDlrd	1	✓
IIPutTxTrqOvrIDChksm	1	IIPutTxTrqOvrIDChksm	1	✓
CanPartOffline	1	CanPartOffline	1	✓
IIPutTxDTCL_DTCTriggered_778	1	IIPutTxDTCL_DTCTriggered_778	1	✓
IIPutTxDTCL_DTCSources_778	1	IIPutTxDTCL_DTCSources_778	1	✓
IIPutTxDTCL_DTCNumber_778	1	IIPutTxDTCL_DTCNumber_778	1	✓
IIPutTxDTCL_DTCFailType_778	1	IIPutTxDTCL_DTCFailType_778	1	✓
IIPutTxDTCL_CodeSupported_778	1	IIPutTxDTCL_CodeSupported_778	1	✓
IIPutTxDTCL_CurrentStatus_778	1	IIPutTxDTCL_CurrentStatus_778	1	✓
IIPutTxDTCL_TstNPsdCdClrdSt_778	1	IIPutTxDTCL_TstNPsdCdClrdSt_778	1	✓
IIPutTxDTCL_TstFldCdClrdStat_778	1	IIPutTxDTCL_TstFldCdClrdStat_778	1	✓
IIPutTxDTCL_HistStat_778	1	IIPutTxDTCL_HistStat_778	1	✓
IIPutTxDTCL_TstNPsdPwrUpSt_778	1	IIPutTxDTCL_TstNPsdPwrUpSt_778	1	✓
IIPutTxDTCL_TstFldPwrUpSt_778	1	IIPutTxDTCL_TstFldPwrUpSt_778	1	✓
IIPutTxDTCL_WrnIndRqdSt_778	1	IIPutTxDTCL_WrnIndRqdSt_778	1	✓
IIPutTxDTCL_DTCFaultType_778	1	IIPutTxDTCL_DTCFaultType_778	1	✓
IIPutTxDTCLInfo_778	1	IIPutTxDTCLInfo_778	1	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530

SriComOutput_BusOffHandler



Project	GMSriComOutput
Module	GMSriComOutput
Test Object	SriComOutput_BusOffHandler

Instrumentation: Test Object Only

Statement (C0) Coverage	100 %
Decision Coverage	100 %
Branch (C1) Coverage	100 %
MCC Coverage	100 %
MC/DC Coverage	100 %

Statistics

Total Testcases	3
Successful	3 ✓
Failed	0
Not Executed	0

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrIComOutput_BusOffHandler

Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrIComOutput
Configuration File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\src\Ap_SrIComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\utp\contract -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
Module 'GMSrIComOutput'	***** Unit Test Description***** Name of Tester:Namrata Morbale Code File(s) Under Test:Ap_SrIComOutput.c Code File(s) Version:5 Module Design Document:Serial_Communication_Output_MDD.doc Module Design Document Version:3 Data Dictionary Version:3 Unit Test Plan Version:1 Optimization Level:Level 2 Compiler (CodeGen) Version:TMS470_4.9.5 Model Type:Excel Macro Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32 Total FLASH Used (Bytes):3574 Total RAM Used (Bytes):304 Total CALS Used (Bytes):15 Special Test Requirements:NA Test Date:6/29/2016 Comments:Note1:Inline function defined in Globalmacro.h is not unit tested. Note2:In function ""SrIComOutput_Per1"" and ""SrIComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue. Note3:In function ""SrIComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_lgc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_lgc=False control goes to else path. Note4:In function ""SrIComOutput_Per1"", 100% path coverage is not acheived because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKATorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKATorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note5:In function ""SrIComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SrIComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SrIComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "". Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference. *****

Attributes

Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530

SrlComOutput_BusOffHandler



Test Case 1: Metrics Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment) CPU Cycles: TS 1.1 1612 Cycles TS 1.2 1591 Cycles
Description	Vector Description: TS 1.1"Longest Execution Path: if (BusOffPresentChannel0_Cnt_M_lgc == TRUE)=>FALSE , else if (BusOffDiagActiveChannel0_Cnt_M_lgc == TRUE)=>TRUE if (BusOffPresentChannel1_Cnt_M_lgc == TRUE)=>FALSE , else if (BusOffDiagActiveChannel1_Cnt_M_lgc == TRUE)=>TRUE, if (ElapsedTime_mS_T_u16 >= k_BusOffRecoveryTimeChannel1_mS_u16)=>FALSE " TS 1.2"Shortest Execution Path: if (BusOffPresentChannel0_Cnt_M_lgc == TRUE)=>TRUE, if (ElapsedTime_mS_T_u16 >= k_BusOffFaultTimeChannel0_mS_u16)=>TRUE, if (BusOffPresentChannel1_Cnt_M_lgc == TRUE)=>TRUE if (ElapsedTime_mS_T_u16 >= k_BusOffFaultTimeChannel1_mS_u16)=>TRUE"

Test Step 1.1 (Repeat Count = 1)

Name	Input Value		
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc	1		
BusOffDiagActiveChannel1_Cnt_M_lgc	1		
BusOffFltChannel0DetectionTimer_mS_M_u32	3973381665		
BusOffFltChannel0RecoverTimer_mS_M_u32	4221959842		
BusOffFltChannel1DetectionTimer_mS_M_u32	3313785296		
BusOffFltChannel1RecoverTimer_mS_M_u32	1924756999		
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc	0		
BusOffPresentChannel1_Cnt_M_lgc	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum	0		
k_BusOffFaultTimeChannel0_mS_u16	32540		
k_BusOffFaultTimeChannel1_mS_u16	32540		
k_BusOffRecoveryTimeChannel0_mS_u16	0		
k_BusOffRecoveryTimeChannel1_mS_u16	39530		
target_BusOffCE_Cnt_T_lgc	0		
target_BusOffHS_Cnt_T_lgc	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1839329192		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFltChannel0DetectionTimer_mS_M_u32	1839329192	1839329192	✓
BusOffFltChannel0RecoverTimer_mS_M_u32	1839329192	1839329192	✓
BusOffFltChannel1DetectionTimer_mS_M_u32	1839329192	1839329192	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	1839329192	1839329192	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530

SrlComOutput_BusOffHandler



Test Step 1.2 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295
BusOffFitChannel0RecoverTimer_mS_M_u32	1356285497
BusOffFitChannel1DetectionTimer_mS_M_u32	280775064
BusOffFitChannel1RecoverTimer_mS_M_u32	176554267
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	34946
k_BusOffFaultTimeChannel1_mS_u16	31388
k_BusOffRecoveryTimeChannel0_mS_u16	25881
k_BusOffRecoveryTimeChannel1_mS_u16	64680
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	49757
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3903181889

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3903181889	3903181889	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	280775064	280775064	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3903181889	3903181889	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

TEST DETAILS REPORT

SrlComOutput_BusOffHandler

2016-06-29, 13:53:50+0530



Test Case 2: Range Test



TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS 2.1 1071 Cycles
TS 2.2 1592 Cycles
TS 2.3 1347 Cycles
TS 2.4 1339 Cycles
TS 2.5 1074 Cycles
TS 2.6 1330 Cycles
TS 2.7 1345 Cycles
TS 2.8 1330 Cycles
TS 2.9 1337 Cycles
TS 2.10 1591 Cycles
TS 2.11 1338 Cycles
TS 2.12 1592 Cycles
TS 2.13 1076 Cycles
TS 2.14 1329 Cycles
TS 2.15 1592 Cycles
TS 2.16 1076 Cycles
TS 2.17 1070 Cycles
TS 2.18 1082 Cycles
TS 2.19 1073 Cycles
TS 2.20 1338 Cycles
TS 2.21 1074 Cycles
TS 2.22 1077 Cycles
TS 2.23 1330 Cycles
TS 2.24 1074 Cycles
TS 2.25 1599 Cycles
TS 2.26 1330 Cycles
TS 2.27 1345 Cycles
TS 2.28 1080 Cycles
TS 2.29 1082 Cycles
TS 2.30 1073 Cycles
TS 2.31 1329 Cycles
TS 2.32 1071 Cycles
TS 2.33 1075 Cycles
TS 2.34 1078 Cycles
TS 2.35 1337 Cycles
TS 2.36 1591 Cycles
TS 2.37 1330 Cycles
TS 2.38 1332 Cycles
TS 2.39 1076 Cycles
TS 2.40 1330 Cycles
TS 2.41 1330 Cycles
TS 2.42 1075 Cycles
TS 2.43 1078 Cycles
TS 2.44 1083 Cycles
TS 2.45 1330 Cycles
TS 2.46 1601 Cycles
TS 2.47 1611 Cycles
TS 2.48 1631 Cycles
TS 2.49 1623 Cycles
TS 2.50 1645 Cycles

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SriComOutput_BusOffHandler

Description	Vector Description:
	TS2.1All_Min
	TS2.2All_Max
	TS2.3BusOffHS_Cnt_T_lgc=>FALSE
	TS2.4BusOffHS_Cnt_T_lgc=>TRUE
	TS2.5BusOffCE_Cnt_T_lgc=>FALSE
	TS2.6BusOffCE_Cnt_T_lgc=>TRUE
	TS2.7BusOffPresentChannel0_Cnt_M_lgc=>FALSE
	TS2.8BusOffPresentChannel0_Cnt_M_lgc=>TRUE
	TS2.9BusOffDiagActiveChannel0_Cnt_M_lgc=>FALSE
	TS2.10BusOffDiagActiveChannel0_Cnt_M_lgc=>TRUE
	TS2.11BusOffFitChannel0RecoverTimer_mS_M_u32=>Min
	TS2.12BusOffFitChannel0RecoverTimer_mS_M_u32=>Max
	TS2.13BusOffFitChannel0RecoverTimer_mS_M_u32=>Pos
	TS2.14BusOffFitChannel0DetectionTimer_mS_M_u32=>Min
	TS2.15BusOffFitChannel0DetectionTimer_mS_M_u32=>Max
	TS2.16BusOffFitChannel0DetectionTimer_mS_M_u32=>Pos
	TS2.17BusOffFitChannel1RecoverTimer_mS_M_u32=>Min
	TS2.18BusOffFitChannel1RecoverTimer_mS_M_u32=>Max
	TS2.19BusOffFitChannel1RecoverTimer_mS_M_u32=>Pos
	TS2.20BusOffFitChannel1DetectionTimer_mS_M_u32=>Min
	TS2.21BusOffFitChannel1DetectionTimer_mS_M_u32=>Max
	TS2.22BusOffFitChannel1DetectionTimer_mS_M_u32=>Pos
	TS2.23k_BusOffFaultTimeChannel0_mS_u16=>Min
	TS2.24k_BusOffFaultTimeChannel0_mS_u16=>Max
	TS2.25k_BusOffFaultTimeChannel0_mS_u16=>Pos
	TS2.26k_BusOffFaultTimeChannel0_mS_u16=>Default
	TS2.27k_BusOffRecoveryTimeChannel0_mS_u16=>Min/Default
	TS2.28k_BusOffRecoveryTimeChannel0_mS_u16=>Max
	TS2.29k_BusOffRecoveryTimeChannel0_mS_u16=>Pos
	TS2.30BusOffPresentChannel1_Cnt_M_lgc=>FALSE
	TS2.31BusOffPresentChannel1_Cnt_M_lgc=>TRUE
	TS2.32BusOffDiagActiveChannel1_Cnt_M_lgc=>FALSE
	TS2.33BusOffDiagActiveChannel1_Cnt_M_lgc=>TRUE
	TS2.34k_BusOffFaultTimeChannel1_mS_u16=>Min
	TS2.35k_BusOffFaultTimeChannel1_mS_u16=>Max
	TS2.36k_BusOffFaultTimeChannel1_mS_u16=>Pos
	TS2.37k_BusOffFaultTimeChannel1_mS_u16=>Default
	TS2.38k_BusOffRecoveryTimeChannel1_mS_u16=>Min/Default
	TS2.39k_BusOffRecoveryTimeChannel1_mS_u16=>Max
	TS2.40k_BusOffRecoveryTimeChannel1_mS_u16=>Pos
	TS2.41Rte_Call_SystemTime_GetSystemTime_mS_u32=>Min
	TS2.42Rte_Call_SystemTime_GetSystemTime_mS_u32=>Max
	TS2.43Rte_Call_SystemTime_GetSystemTime_mS_u32=>Pos
	TS2.44Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16=>Min
	TS2.45Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16=>Max
	TS2.46Rte_Call_SystemTime_DtrmnElapsedTime_mS_u16=>Pos
	TS2.47SysPwrMd_Cnt_T_enum==>off
	TS2.48SysPwrMd_Cnt_T_enum ==>Accessory
	TS2.49SysPwrMd_Cnt_T_enum ==>Run
	TS2.50SysPwrMd_Cnt_T_enum ==>CrankRequest

Test Step 2.1 (Repeat Count = 1)

Name	Input Value		
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc	0		
BusOffDiagActiveChannel1_Cnt_M_lgc	0		
BusOffFitChannel0DetectionTimer_mS_M_u32	0		
BusOffFitChannel0RecoverTimer_mS_M_u32	0		
BusOffFitChannel1DetectionTimer_mS_M_u32	0		
BusOffFitChannel1RecoverTimer_mS_M_u32	0		
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc	0		
BusOffPresentChannel1_Cnt_M_lgc	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum	0		
k_BusOffFaultTimeChannel0_mS_u16	0		
k_BusOffFaultTimeChannel1_mS_u16	0		
k_BusOffRecoveryTimeChannel0_mS_u16	0		
k_BusOffRecoveryTimeChannel1_mS_u16	0		
target_BusOffCE_Cnt_T_lgc	0		
target_BusOffHS_Cnt_T_lgc	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	0	0	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Actual Value	Expected Value	Result
Status	0x0000	0x0000	
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.2 (Repeat Count = 1)				
Name	Input Value			
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc			
BusOffDiagActiveChannel0_Cnt_M_lgc	1			
BusOffDiagActiveChannel1_Cnt_M_lgc	1			
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295			
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295			
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295			
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295			
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc			
BusOffPresentChannel0_Cnt_M_lgc	1			
BusOffPresentChannel1_Cnt_M_lgc	1			
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime			
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime			
SysPwrMd_Cnt_T_enum	3			
k_BusOffFaultTimeChannel0_mS_u16	65535			
k_BusOffFaultTimeChannel1_mS_u16	65535			
k_BusOffRecoveryTimeChannel0_mS_u16	65535			
k_BusOffRecoveryTimeChannel1_mS_u16	65535			
target_BusOffCE_Cnt_T_lgc	1			
target_BusOffHS_Cnt_T_lgc	1			
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_El	65535			
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	4294967295			
Name	Actual Value	Expected Value	Result	
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓	
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓	
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✓	
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295	4294967295	✓	
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295	4294967295	✓	
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295	4294967295	✓	
NTC	0x0110	0x0110	✓	
Param	0x0001	0x0001	✓	
Status	0x0001	0x0001	✓	

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.3 (Repeat Count = 1)				
Name	Input Value			
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc			
BusOffDiagActiveChannel0_Cnt_M_lgc	1			
BusOffDiagActiveChannel1_Cnt_M_lgc	1			
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295			
BusOffFitChannel0RecoverTimer_mS_M_u32	0			
BusOffFitChannel1DetectionTimer_mS_M_u32	1894110714			
BusOffFitChannel1RecoverTimer_mS_M_u32	3861796421			
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc			
BusOffPresentChannel0_Cnt_M_lgc	1			
BusOffPresentChannel1_Cnt_M_lgc	0			

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum	0		
k_BusOffFaultTimeChannel0_mS_u16	60825		
k_BusOffFaultTimeChannel1_mS_u16	22795		
k_BusOffRecoveryTimeChannel0_mS_u16	25882		
k_BusOffRecoveryTimeChannel1_mS_u16	8229		
target_BusOffCE_Cnt_T_lgc	0		
target_BusOffHS_Cnt_T_lgc	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	11354		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3072927859		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3072927859	3072927859	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3072927859	3072927859	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3072927859	3072927859	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.4 (Repeat Count = 1)				✓
Name		Input Value		
BusOffCE_Cnt_T_lgc		target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc		0		
BusOffDiagActiveChannel1_Cnt_M_lgc		1		
BusOffFitChannel0DetectionTimer_mS_M_u32		3739593150		
BusOffFitChannel0RecoverTimer_mS_M_u32		2061747645		
BusOffFitChannel1DetectionTimer_mS_M_u32		1932051216		
BusOffFitChannel1RecoverTimer_mS_M_u32		3193379438		
BusOffHS_Cnt_T_lgc		target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc		0		
BusOffPresentChannel1_Cnt_M_lgc		0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum		1		
k_BusOffFaultTimeChannel0_mS_u16		10778		
k_BusOffFaultTimeChannel1_mS_u16		62158		
k_BusOffRecoveryTimeChannel0_mS_u16		15197		
k_BusOffRecoveryTimeChannel1_mS_u16		28600		
target_BusOffCE_Cnt_T_lgc		1		
target_BusOffHS_Cnt_T_lgc		1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela		47437		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren		2738556798		
Name	Actual Value	Expected Value	Result	
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓	
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓	
BusOffFitChannel0DetectionTimer_mS_M_u32	2738556798	2738556798	✓	
BusOffFitChannel0RecoverTimer_mS_M_u32	2738556798	2738556798	✓	
BusOffFitChannel1DetectionTimer_mS_M_u32	2738556798	2738556798	✓	
BusOffFitChannel1RecoverTimer_mS_M_u32	2738556798	2738556798	✓	
NTC	0x0100	0x0100	✓	
Param	0x0001	0x0001	✓	
Status	0x0000	0x0000	✓	
NTC	0x0110	0x0110	✓	
Param	0x0001	0x0001	✓	
Status	0x0000	0x0000	✓	

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.5 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	1246334520
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295
BusOffFitChannel1DetectionTimer_mS_M_u32	1665706824
BusOffFitChannel1RecoverTimer_mS_M_u32	4193367413
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	2
k_BusOffFaultTimeChannel0_mS_u16	64680
k_BusOffFaultTimeChannel1_mS_u16	9295
k_BusOffRecoveryTimeChannel0_mS_u16	30312
k_BusOffRecoveryTimeChannel1_mS_u16	54157
target_BusOffCE_Cnt_T_lgc	0
target_BusOffHS_Cnt_T_lgc	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	44983
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1430223038

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1430223038	1430223038	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1430223038	1430223038	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	1665706824	1665706824	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	4193367413	4193367413	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.6 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	1356285497
BusOffFitChannel0RecoverTimer_mS_M_u32	0
BusOffFitChannel1DetectionTimer_mS_M_u32	729974407
BusOffFitChannel1RecoverTimer_mS_M_u32	490622811
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	0
k_BusOffFaultTimeChannel0_mS_u16	15049
k_BusOffFaultTimeChannel1_mS_u16	25858
k_BusOffRecoveryTimeChannel0_mS_u16	56097

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
k_BusOffRecoveryTimeChannel1_mS_u16	10981		
target_BusOffCE_Cnt_T_lgc	1		
target_BusOffHS_Cnt_T_lgc	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	55747		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3106101192		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1356285497	1356285497	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3106101192	3106101192	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3106101192	3106101192	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3106101192	3106101192	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.7 (Repeat Count = 1)				
Name		Input Value		
BusOffCE_Cnt_T_lgc		target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc		1		
BusOffDiagActiveChannel1_Cnt_M_lgc		1		
BusOffFitChannel0DetectionTimer_mS_M_u32		3953105980		
BusOffFitChannel0RecoverTimer_mS_M_u32		1944666162		
BusOffFitChannel1DetectionTimer_mS_M_u32		672947379		
BusOffFitChannel1RecoverTimer_mS_M_u32		947495828		
BusOffHS_Cnt_T_lgc		target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc		0		
BusOffPresentChannel1_Cnt_M_lgc		0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum		1		
k_BusOffFaultTimeChannel0_mS_u16		60017		
k_BusOffFaultTimeChannel1_mS_u16		22013		
k_BusOffRecoveryTimeChannel0_mS_u16		5555		
k_BusOffRecoveryTimeChannel1_mS_u16		32711		
target_BusOffCE_Cnt_T_lgc		1		
target_BusOffHS_Cnt_T_lgc		1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela		24947		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren		2370584731		
Name		Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc		0	0	
BusOffDiagActiveChannel1_Cnt_M_lgc		1	1	
BusOffFitChannel0DetectionTimer_mS_M_u32		2370584731	2370584731	
BusOffFitChannel0RecoverTimer_mS_M_u32		2370584731	2370584731	
BusOffFitChannel1DetectionTimer_mS_M_u32		672947379	672947379	
BusOffFitChannel1RecoverTimer_mS_M_u32		947495828	947495828	
NTC		0x0100	0x0100	
Param		0x0001	0x0001	
Status		0x0000	0x0000	

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530

SrlComOutput_BusOffHandler



Test Step 2.8 (Repeat Count = 1) ✓

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	2061747645
BusOffFitChannel0RecoverTimer_mS_M_u32	4078039705
BusOffFitChannel1DetectionTimer_mS_M_u32	1140263597
BusOffFitChannel1RecoverTimer_mS_M_u32	386778569
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	2
k_BusOffFaultTimeChannel0_mS_u16	28632
k_BusOffFaultTimeChannel1_mS_u16	36500
k_BusOffRecoveryTimeChannel0_mS_u16	47030
k_BusOffRecoveryTimeChannel1_mS_u16	17447
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	31532
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2839643349

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2061747645	2061747645	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	2839643349	2839643349	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	2839643349	2839643349	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	2839643349	2839643349	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace ✓

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.9 (Repeat Count = 1) ✓

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	4167849
BusOffFitChannel0RecoverTimer_mS_M_u32	1555615171
BusOffFitChannel1DetectionTimer_mS_M_u32	2003570018
BusOffFitChannel1RecoverTimer_mS_M_u32	2583579405
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	0
k_BusOffFaultTimeChannel0_mS_u16	40570
k_BusOffFaultTimeChannel1_mS_u16	65016
k_BusOffRecoveryTimeChannel0_mS_u16	0
k_BusOffRecoveryTimeChannel1_mS_u16	23359
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	62334
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1957662919

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SriComOutput_BusOffHandler

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFltChannel0DetectionTimer_mS_M_u32	4167849	4167849	✓
BusOffFltChannel0RecoverTimer_mS_M_u32	1957662919	1957662919	✓
BusOffFltChannel1DetectionTimer_mS_M_u32	2003570018	2003570018	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	1957662919	1957662919	✓

Test Step Call Trace ✓

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.10 (Repeat Count = 1) ✓

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	2016567863
BusOffFltChannel0RecoverTimer_mS_M_u32	4267903143
BusOffFltChannel1DetectionTimer_mS_M_u32	3544954158
BusOffFltChannel1RecoverTimer_mS_M_u32	3016533201
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	16326
k_BusOffFaultTimeChannel1_mS_u16	10177
k_BusOffRecoveryTimeChannel0_mS_u16	53323
k_BusOffRecoveryTimeChannel1_mS_u16	790
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	31050
target_Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3080840142

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFltChannel0DetectionTimer_mS_M_u32	2016567863	2016567863	✓
BusOffFltChannel0RecoverTimer_mS_M_u32	3080840142	3080840142	✓
BusOffFltChannel1DetectionTimer_mS_M_u32	3544954158	3544954158	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	3080840142	3080840142	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

Test Step Call Trace ✓

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SriComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SriComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SriComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SriComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.11 (Repeat Count = 1) ✓

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	2346189251
BusOffFltChannel0RecoverTimer_mS_M_u32	0
BusOffFltChannel1DetectionTimer_mS_M_u32	2218074122
BusOffFltChannel1RecoverTimer_mS_M_u32	1424814936
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
BusOffPresentChannel1_Cnt_M_lgc	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum	2		
k_BusOffFaultTimeChannel0_mS_u16	61618		
k_BusOffFaultTimeChannel1_mS_u16	25461		
k_BusOffRecoveryTimeChannel0_mS_u16	55520		
k_BusOffRecoveryTimeChannel1_mS_u16	17834		
target_BusOffCE_Cnt_T_lgc	1		
target_BusOffHS_Cnt_T_lgc	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	32276		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3048395838		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	2346189251	2346189251	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3048395838	3048395838	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	2218074122	2218074122	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3048395838	3048395838	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.12 (Repeat Count = 1)				✔
Name		Input Value		
BusOffCE_Cnt_T_lgc		target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc		1		
BusOffDiagActiveChannel1_Cnt_M_lgc		0		
BusOffFitChannel0DetectionTimer_mS_M_u32		2898070163		
BusOffFitChannel0RecoverTimer_mS_M_u32		4294967295		
BusOffFitChannel1DetectionTimer_mS_M_u32		270336042		
BusOffFitChannel1RecoverTimer_mS_M_u32		1767109984		
BusOffHS_Cnt_T_lgc		target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc		1		
BusOffPresentChannel1_Cnt_M_lgc		1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum		0		
k_BusOffFaultTimeChannel0_mS_u16		13677		
k_BusOffFaultTimeChannel1_mS_u16		54644		
k_BusOffRecoveryTimeChannel0_mS_u16		48255		
k_BusOffRecoveryTimeChannel1_mS_u16		25447		
target_BusOffCE_Cnt_T_lgc		1		
target_BusOffHS_Cnt_T_lgc		1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela		62435		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren		3427553675		
Name		Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc		1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc		1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32		2898070163	2898070163	✔
BusOffFitChannel0RecoverTimer_mS_M_u32		3427553675	3427553675	✔
BusOffFitChannel1DetectionTimer_mS_M_u32		270336042	270336042	✔
BusOffFitChannel1RecoverTimer_mS_M_u32		3427553675	3427553675	✔
NTC		0x0110	0x0110	✔
Param		0x0001	0x0001	✔
Status		0x0001	0x0001	✔

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530

SrlComOutput_BusOffHandler



Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.13 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	0
BusOffFitChannel0RecoverTimer_mS_M_u32	2729593150
BusOffFitChannel1DetectionTimer_mS_M_u32	3782661189
BusOffFitChannel1RecoverTimer_mS_M_u32	2505595112
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	50513
k_BusOffFaultTimeChannel1_mS_u16	23164
k_BusOffRecoveryTimeChannel0_mS_u16	9605
k_BusOffRecoveryTimeChannel1_mS_u16	60825
target_BusOffCE_Cnt_T_lgc	0
target_BusOffHS_Cnt_T_lgc	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	19690
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3561892702

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	3561892702	3561892702	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3561892702	3561892702	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3782661189	3782661189	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3561892702	3561892702	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.14 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	0
BusOffFitChannel0RecoverTimer_mS_M_u32	1246334520
BusOffFitChannel1DetectionTimer_mS_M_u32	32931645
BusOffFitChannel1RecoverTimer_mS_M_u32	2167135746
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	2
k_BusOffFaultTimeChannel0_mS_u16	47282
k_BusOffFaultTimeChannel1_mS_u16	9251
k_BusOffRecoveryTimeChannel0_mS_u16	22238

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
k_BusOffRecoveryTimeChannel1_mS_u16	10778		
target_BusOffCE_Cnt_T_lgc	0		
target_BusOffHS_Cnt_T_lgc	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	13990		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	420180266		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	420180266	420180266	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	420180266	420180266	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	32931645	32931645	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	420180266	420180266	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

Test Step Call Trace					✓
Actual Function	Count	Expected Function	Count	Result	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓	
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓	
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓	
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓	

Test Step 2.15 (Repeat Count = 1)				✓
Name		Input Value		
BusOffCE_Cnt_T_lgc		target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc		1		
BusOffDiagActiveChannel1_Cnt_M_lgc		0		
BusOffFitChannel0DetectionTimer_mS_M_u32		4294967295		
BusOffFitChannel0RecoverTimer_mS_M_u32		1356285497		
BusOffFitChannel1DetectionTimer_mS_M_u32		280775064		
BusOffFitChannel1RecoverTimer_mS_M_u32		176554267		
BusOffHS_Cnt_T_lgc		target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc		1		
BusOffPresentChannel1_Cnt_M_lgc		1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum		0		
k_BusOffFaultTimeChannel0_mS_u16		34946		
k_BusOffFaultTimeChannel1_mS_u16		31388		
k_BusOffRecoveryTimeChannel0_mS_u16		25881		
k_BusOffRecoveryTimeChannel1_mS_u16		64680		
target_BusOffCE_Cnt_T_lgc		1		
target_BusOffHS_Cnt_T_lgc		1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela		49757		
target Rte Call Ap SrlComOutput SystemTime GetSystemTime mS u32 Curren		3903181889		
Name		Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc		1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc		1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32		4294967295	4294967295	✓
BusOffFitChannel0RecoverTimer_mS_M_u32		3903181889	3903181889	✓
BusOffFitChannel1DetectionTimer_mS_M_u32		280775064	280775064	✓
BusOffFitChannel1RecoverTimer_mS_M_u32		3903181889	3903181889	✓
NTC		0x0110	0x0110	✓
Param		0x0001	0x0001	✓
Status		0x0001	0x0001	✓

Test Step Call Trace					✓
Actual Function	Count	Expected Function	Count	Result	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓	
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓	
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓	
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓	

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530

SrlComOutput_BusOffHandler



Test Step 2.16 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_Igc	target_BusOffCE_Cnt_T_Igc
BusOffDiagActiveChannel0_Cnt_M_Igc	0
BusOffDiagActiveChannel1_Cnt_M_Igc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	1239593150
BusOffFitChannel0RecoverTimer_mS_M_u32	3953105980
BusOffFitChannel1DetectionTimer_mS_M_u32	2029058766
BusOffFitChannel1RecoverTimer_mS_M_u32	3978790070
BusOffHS_Cnt_T_Igc	target_BusOffHS_Cnt_T_Igc
BusOffPresentChannel0_Cnt_M_Igc	0
BusOffPresentChannel1_Cnt_M_Igc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	48424
k_BusOffFaultTimeChannel1_mS_u16	33279
k_BusOffRecoveryTimeChannel0_mS_u16	13073
k_BusOffRecoveryTimeChannel1_mS_u16	15049
target_BusOffCE_Cnt_T_Igc	0
target_BusOffHS_Cnt_T_Igc	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	27251
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2484519884

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_Igc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_Igc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2484519884	2484519884	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	2484519884	2484519884	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	2029058766	2029058766	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	2484519884	2484519884	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.17 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_Igc	target_BusOffCE_Cnt_T_Igc
BusOffDiagActiveChannel0_Cnt_M_Igc	0
BusOffDiagActiveChannel1_Cnt_M_Igc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	2016567863
BusOffFitChannel0RecoverTimer_mS_M_u32	2061747645
BusOffFitChannel1DetectionTimer_mS_M_u32	744697633
BusOffFitChannel1RecoverTimer_mS_M_u32	0
BusOffHS_Cnt_T_Igc	target_BusOffHS_Cnt_T_Igc
BusOffPresentChannel0_Cnt_M_Igc	0
BusOffPresentChannel1_Cnt_M_Igc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	2
k_BusOffFaultTimeChannel0_mS_u16	39530
k_BusOffFaultTimeChannel1_mS_u16	61116
k_BusOffRecoveryTimeChannel0_mS_u16	58477
k_BusOffRecoveryTimeChannel1_mS_u16	60017
target_BusOffCE_Cnt_T_Igc	0
target_BusOffHS_Cnt_T_Igc	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	56972
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2653016018

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_Igc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_Igc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2653016018	2653016018	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Actual Value	Expected Value	Result
BusOffFltChannel0RecoverTimer_mS_M_u32	2653016018	2653016018	
BusOffFltChannel1DetectionTimer_mS_M_u32	2653016018	2653016018	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	2653016018	2653016018	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.18 (Repeat Count = 1)				
Name	Input Value			
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc			
BusOffDiagActiveChannel0_Cnt_M_lgc	1			
BusOffDiagActiveChannel1_Cnt_M_lgc	1			
BusOffFltChannel0DetectionTimer_mS_M_u32	2346189251			
BusOffFltChannel0RecoverTimer_mS_M_u32	4167849			
BusOffFltChannel1DetectionTimer_mS_M_u32	4106390335			
BusOffFltChannel1RecoverTimer_mS_M_u32	4294967295			
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc			
BusOffPresentChannel0_Cnt_M_lgc	1			
BusOffPresentChannel1_Cnt_M_lgc	0			
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime			
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime			
SysPwrMd_Cnt_T_enum	0			
k_BusOffFaultTimeChannel0_mS_u16	30588			
k_BusOffFaultTimeChannel1_mS_u16	29645			
k_BusOffRecoveryTimeChannel0_mS_u16	4022			
k_BusOffRecoveryTimeChannel1_mS_u16	28632			
target_BusOffCE_Cnt_T_lgc	1			
target_BusOffHS_Cnt_T_lgc	1			
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	4481			
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1059205007			
Name	Actual Value	Expected Value	Result	
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓	
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓	
BusOffFltChannel0DetectionTimer_mS_M_u32	2346189251	2346189251	✓	
BusOffFltChannel0RecoverTimer_mS_M_u32	1059205007	1059205007	✓	
BusOffFltChannel1DetectionTimer_mS_M_u32	4106390335	4106390335	✓	
BusOffFltChannel1RecoverTimer_mS_M_u32	4294967295	4294967295	✓	

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.19 (Repeat Count = 1)				
Name	Input Value			
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc			
BusOffDiagActiveChannel0_Cnt_M_lgc	0			
BusOffDiagActiveChannel1_Cnt_M_lgc	1			
BusOffFltChannel0DetectionTimer_mS_M_u32	2898070163			
BusOffFltChannel0RecoverTimer_mS_M_u32	2016567863			
BusOffFltChannel1DetectionTimer_mS_M_u32	652843089			
BusOffFltChannel1RecoverTimer_mS_M_u32	1329593150			
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc			
BusOffPresentChannel0_Cnt_M_lgc	0			

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
BusOffPresentChannel1_Cnt_M_lgc	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum	1		
k_BusOffFaultTimeChannel0_mS_u16	22532		
k_BusOffFaultTimeChannel1_mS_u16	57842		
k_BusOffRecoveryTimeChannel0_mS_u16	8229		
k_BusOffRecoveryTimeChannel1_mS_u16	40570		
target_BusOffCE_Cnt_T_lgc	0		
target_BusOffHS_Cnt_T_lgc	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	37881		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	4165916706		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	4165916706	4165916706	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	4165916706	4165916706	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	652843089	652843089	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	1329593150	1329593150	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.20 (Repeat Count = 1)				✓
Name		Input Value		
BusOffCE_Cnt_T_lgc		target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc		0		
BusOffDiagActiveChannel1_Cnt_M_lgc		1		
BusOffFitChannel0DetectionTimer_mS_M_u32		1944666162		
BusOffFitChannel0RecoverTimer_mS_M_u32		2346189251		
BusOffFitChannel1DetectionTimer_mS_M_u32		0		
BusOffFitChannel1RecoverTimer_mS_M_u32		131738029		
BusOffHS_Cnt_T_lgc		target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc		0		
BusOffPresentChannel1_Cnt_M_lgc		0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum		2		
k_BusOffFaultTimeChannel0_mS_u16		12028		
k_BusOffFaultTimeChannel1_mS_u16		29110		
k_BusOffRecoveryTimeChannel0_mS_u16		28600		
k_BusOffRecoveryTimeChannel1_mS_u16		16326		
target_BusOffCE_Cnt_T_lgc		0		
target_BusOffHS_Cnt_T_lgc		0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela		23810		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren		1723068811		
Name	Actual Value	Expected Value	Result	
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓	
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓	
BusOffFitChannel0DetectionTimer_mS_M_u32	1723068811	1723068811	✓	
BusOffFitChannel0RecoverTimer_mS_M_u32	1723068811	1723068811	✓	
BusOffFitChannel1DetectionTimer_mS_M_u32	1723068811	1723068811	✓	
BusOffFitChannel1RecoverTimer_mS_M_u32	1723068811	1723068811	✓	
NTC	0x0100	0x0100	✓	
Param	0x0001	0x0001	✓	
Status	0x0000	0x0000	✓	
NTC	0x0110	0x0110	✓	
Param	0x0001	0x0001	✓	
Status	0x0000	0x0000	✓	

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.21 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	4078039705
BusOffFitChannel0RecoverTimer_mS_M_u32	2898070163
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295
BusOffFitChannel1RecoverTimer_mS_M_u32	1730250954
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	0
k_BusOffFaultTimeChannel0_mS_u16	41300
k_BusOffFaultTimeChannel1_mS_u16	41300
k_BusOffRecoveryTimeChannel0_mS_u16	54157
k_BusOffRecoveryTimeChannel1_mS_u16	61618
target_BusOffCE_Cnt_T_lgc	0
target_BusOffHS_Cnt_T_lgc	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	51470
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1852121206

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1852121206	1852121206	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1852121206	1852121206	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295	4294967295	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	1730250954	1730250954	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.22 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	1555615171
BusOffFitChannel0RecoverTimer_mS_M_u32	1944666162
BusOffFitChannel1DetectionTimer_mS_M_u32	2439593150
BusOffFitChannel1RecoverTimer_mS_M_u32	2138001447
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	39281
k_BusOffFaultTimeChannel1_mS_u16	39281
k_BusOffRecoveryTimeChannel0_mS_u16	10981

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
k_BusOffRecoveryTimeChannel1_mS_u16	13677		
target_BusOffCE_Cnt_T_lgc	1		
target_BusOffHS_Cnt_T_lgc	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	18596		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4269617388		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1555615171	1555615171	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	4269617388	4269617388	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	4269617388	4269617388	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	4269617388	4269617388	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.23 (Repeat Count = 1)				
Name		Input Value		
BusOffCE_Cnt_T_lgc		target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc		0		
BusOffDiagActiveChannel1_Cnt_M_lgc		0		
BusOffFitChannel0DetectionTimer_mS_M_u32		4267903143		
BusOffFitChannel0RecoverTimer_mS_M_u32		4078039705		
BusOffFitChannel1DetectionTimer_mS_M_u32		340025677		
BusOffFitChannel1RecoverTimer_mS_M_u32		705030171		
BusOffHS_Cnt_T_lgc		target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc		0		
BusOffPresentChannel1_Cnt_M_lgc		1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum		2		
k_BusOffFaultTimeChannel0_mS_u16		0		
k_BusOffFaultTimeChannel1_mS_u16		0		
k_BusOffRecoveryTimeChannel0_mS_u16		32711		
k_BusOffRecoveryTimeChannel1_mS_u16		50513		
target_BusOffCE_Cnt_T_lgc		0		
target_BusOffHS_Cnt_T_lgc		0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		12198		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		1791563905		
Name	Actual Value	Expected Value	Result	
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓	
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓	
BusOffFitChannel0DetectionTimer_mS_M_u32	1791563905	1791563905	✓	
BusOffFitChannel0RecoverTimer_mS_M_u32	1791563905	1791563905	✓	
BusOffFitChannel1DetectionTimer_mS_M_u32	340025677	340025677	✓	
BusOffFitChannel1RecoverTimer_mS_M_u32	1791563905	1791563905	✓	
NTC	0x0100	0x0100	✓	
Param	0x0001	0x0001	✓	
Status	0x0000	0x0000	✓	
NTC	0x0110	0x0110	✓	
Param	0x0001	0x0001	✓	
Status	0x0001	0x0001	✓	

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Test Step 2.24 (Repeat Count = 1) ✓

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	1317627907
BusOffFltChannel0RecoverTimer_mS_M_u32	1555615171
BusOffFltChannel1DetectionTimer_mS_M_u32	1215337533
BusOffFltChannel1RecoverTimer_mS_M_u32	1522237236
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	0
k_BusOffFaultTimeChannel0_mS_u16	65535
k_BusOffFaultTimeChannel1_mS_u16	65535
k_BusOffRecoveryTimeChannel0_mS_u16	17447
k_BusOffRecoveryTimeChannel1_mS_u16	47282
target_BusOffCE_Cnt_T_lgc	0
target_BusOffHS_Cnt_T_lgc	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	31748
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4101945562

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFltChannel0DetectionTimer_mS_M_u32	4101945562	4101945562	✓
BusOffFltChannel0RecoverTimer_mS_M_u32	4101945562	4101945562	✓
BusOffFltChannel1DetectionTimer_mS_M_u32	1215337533	1215337533	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	1522237236	1522237236	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace ✓

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.25 (Repeat Count = 1) ✓

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	4221959842
BusOffFltChannel0RecoverTimer_mS_M_u32	4267903143
BusOffFltChannel1DetectionTimer_mS_M_u32	2478357172
BusOffFltChannel1RecoverTimer_mS_M_u32	3474385282
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	13677
k_BusOffFaultTimeChannel1_mS_u16	13677
k_BusOffRecoveryTimeChannel0_mS_u16	23359
k_BusOffRecoveryTimeChannel1_mS_u16	34946
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	41680
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3146080493

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFltChannel0DetectionTimer_mS_M_u32	4221959842	4221959842	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Actual Value	Expected Value	Result
BusOffFitChannel0RecoverTimer_mS_M_u32	3146080493	3146080493	
BusOffFitChannel1DetectionTimer_mS_M_u32	3146080493	3146080493	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3146080493	3146080493	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.26 (Repeat Count = 1)

Name	Input Value		
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc	0		
BusOffDiagActiveChannel1_Cnt_M_lgc	1		
BusOffFitChannel0DetectionTimer_mS_M_u32	2119330630		
BusOffFitChannel0RecoverTimer_mS_M_u32	1317627907		
BusOffFitChannel1DetectionTimer_mS_M_u32	986753449		
BusOffFitChannel1RecoverTimer_mS_M_u32	526492108		
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc	0		
BusOffPresentChannel1_Cnt_M_lgc	1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum	2		
k_BusOffFaultTimeChannel0_mS_u16	1000		
k_BusOffFaultTimeChannel1_mS_u16	1000		
k_BusOffRecoveryTimeChannel0_mS_u16	790		
k_BusOffRecoveryTimeChannel1_mS_u16	48424		
target_BusOffCE_Cnt_T_lgc	0		
target_BusOffHS_Cnt_T_lgc	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	34471		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3791435509		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32	3791435509	3791435509	✔
BusOffFitChannel0RecoverTimer_mS_M_u32	3791435509	3791435509	✔
BusOffFitChannel1DetectionTimer_mS_M_u32	986753449	986753449	✔
BusOffFitChannel1RecoverTimer_mS_M_u32	3791435509	3791435509	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.27 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	3973381665

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value
BusOffFitChannel0RecoverTimer_mS_M_u32	4221959842
BusOffFitChannel1DetectionTimer_mS_M_u32	3313785296
BusOffFitChannel1RecoverTimer_mS_M_u32	1924756999
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	0
k_BusOffFaultTimeChannel0_mS_u16	32540
k_BusOffFaultTimeChannel1_mS_u16	32540
k_BusOffRecoveryTimeChannel0_mS_u16	0
k_BusOffRecoveryTimeChannel1_mS_u16	39530
target_BusOffCE_Cnt_T_lgc	0
target_BusOffHS_Cnt_T_lgc	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	19705
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1839329192

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1839329192	1839329192	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1839329192	1839329192	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3313785296	3313785296	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	1924756999	1924756999	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.28 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	2899086231
BusOffFitChannel0RecoverTimer_mS_M_u32	2119330630
BusOffFitChannel1DetectionTimer_mS_M_u32	2422532780
BusOffFitChannel1RecoverTimer_mS_M_u32	3985430462
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	4620
k_BusOffFaultTimeChannel1_mS_u16	4620
k_BusOffRecoveryTimeChannel0_mS_u16	65535
k_BusOffRecoveryTimeChannel1_mS_u16	30588
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	8561
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4085748062

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2899086231	2899086231	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	2119330630	2119330630	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	2422532780	2422532780	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3985430462	3985430462	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.29 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	50782532
BusOffFitChannel0RecoverTimer_mS_M_u32	3973381665
BusOffFitChannel1DetectionTimer_mS_M_u32	4227646013
BusOffFitChannel1RecoverTimer_mS_M_u32	2282040120
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	2
k_BusOffFaultTimeChannel0_mS_u16	60421
k_BusOffFaultTimeChannel1_mS_u16	60421
k_BusOffRecoveryTimeChannel0_mS_u16	42112
k_BusOffRecoveryTimeChannel1_mS_u16	55218
target_BusOffCE_Cnt_T_lgc	0
target_BusOffHS_Cnt_T_lgc	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	21481
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	827644878

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	50782532	50782532	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3973381665	3973381665	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	4227646013	4227646013	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	827644878	827644878	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.30 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	652294597
BusOffFitChannel0RecoverTimer_mS_M_u32	2899086231
BusOffFitChannel1DetectionTimer_mS_M_u32	1889078943
BusOffFitChannel1RecoverTimer_mS_M_u32	2555580428
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	0
k_BusOffFaultTimeChannel0_mS_u16	28859
k_BusOffFaultTimeChannel1_mS_u16	28859
k_BusOffRecoveryTimeChannel0_mS_u16	4520
k_BusOffRecoveryTimeChannel1_mS_u16	38620
target_BusOffCE_Cnt_T_lgc	0
target_BusOffHS_Cnt_T_lgc	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	27331

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2262440084		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFltChannel0DetectionTimer_mS_M_u32	2262440084	2262440084	✔
BusOffFltChannel0RecoverTimer_mS_M_u32	2262440084	2262440084	✔
BusOffFltChannel1DetectionTimer_mS_M_u32	1889078943	1889078943	✔
BusOffFltChannel1RecoverTimer_mS_M_u32	2555580428	2555580428	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.31 (Repeat Count = 1)				
Name		Input Value		
BusOffCE_Cnt_T_lgc		target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc		0		
BusOffDiagActiveChannel1_Cnt_M_lgc		1		
BusOffFltChannel0DetectionTimer_mS_M_u32		104612948		
BusOffFltChannel0RecoverTimer_mS_M_u32		50782532		
BusOffFltChannel1DetectionTimer_mS_M_u32		1033077435		
BusOffFltChannel1RecoverTimer_mS_M_u32		1737034940		
BusOffHS_Cnt_T_lgc		target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc		0		
BusOffPresentChannel1_Cnt_M_lgc		1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTim		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum		1		
k_BusOffFaultTimeChannel0_mS_u16		2793		
k_BusOffFaultTimeChannel1_mS_u16		2793		
k_BusOffRecoveryTimeChannel0_mS_u16		26741		
k_BusOffRecoveryTimeChannel1_mS_u16		10764		
target_BusOffCE_Cnt_T_lgc		0		
target_BusOffHS_Cnt_T_lgc		0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela		61600		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren		3003207712		
Name	Actual Value	Expected Value	Result	
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0		
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1		
BusOffFltChannel0DetectionTimer_mS_M_u32	3003207712	3003207712		
BusOffFltChannel0RecoverTimer_mS_M_u32	3003207712	3003207712		
BusOffFltChannel1DetectionTimer_mS_M_u32	1033077435	1033077435		
BusOffFltChannel1RecoverTimer_mS_M_u32	3003207712	3003207712		
NTC	0x0100	0x0100		
Param	0x0001	0x0001		
Status	0x0000	0x0000		
NTC	0x0110	0x0110		
Param	0x0001	0x0001		
Status	0x0001	0x0001		

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Test Step 2.32 (Repeat Count = 1)				
Name	Input Value			
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc			
BusOffDiagActiveChannel0_Cnt_M_lgc	0			
BusOffDiagActiveChannel1_Cnt_M_lgc	0			
BusOffFitChannel0DetectionTimer_mS_M_u32	1011278496			
BusOffFitChannel0RecoverTimer_mS_M_u32	652294597			
BusOffFitChannel1DetectionTimer_mS_M_u32	2220883010			
BusOffFitChannel1RecoverTimer_mS_M_u32	2377469754			
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc			
BusOffPresentChannel0_Cnt_M_lgc	0			
BusOffPresentChannel1_Cnt_M_lgc	0			
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime			
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime			
SysPwrMd_Cnt_T_enum	2			
k_BusOffFaultTimeChannel0_mS_u16	62580			
k_BusOffFaultTimeChannel1_mS_u16	62580			
k_BusOffRecoveryTimeChannel0_mS_u16	46662			
k_BusOffRecoveryTimeChannel1_mS_u16	14680			
target_BusOffCE_Cnt_T_lgc	0			
target_BusOffHS_Cnt_T_lgc	0			
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	9281			
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	613865157			
Name	Actual Value	Expected Value	Result	
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓	
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓	
BusOffFitChannel0DetectionTimer_mS_M_u32	613865157	613865157	✓	
BusOffFitChannel0RecoverTimer_mS_M_u32	613865157	613865157	✓	
BusOffFitChannel1DetectionTimer_mS_M_u32	613865157	613865157	✓	
BusOffFitChannel1RecoverTimer_mS_M_u32	613865157	613865157	✓	
NTC	0x0100	0x0100	✓	
Param	0x0001	0x0001	✓	
Status	0x0000	0x0000	✓	
NTC	0x0110	0x0110	✓	
Param	0x0001	0x0001	✓	
Status	0x0000	0x0000	✓	

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.33 (Repeat Count = 1)				
Name	Input Value			
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc			
BusOffDiagActiveChannel0_Cnt_M_lgc	0			
BusOffDiagActiveChannel1_Cnt_M_lgc	1			
BusOffFitChannel0DetectionTimer_mS_M_u32	182109366			
BusOffFitChannel0RecoverTimer_mS_M_u32	104612948			
BusOffFitChannel1DetectionTimer_mS_M_u32	3453754701			
BusOffFitChannel1RecoverTimer_mS_M_u32	4105035950			
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc			
BusOffPresentChannel0_Cnt_M_lgc	0			
BusOffPresentChannel1_Cnt_M_lgc	0			
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime			
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime			
SysPwrMd_Cnt_T_enum	0			
k_BusOffFaultTimeChannel0_mS_u16	31747			
k_BusOffFaultTimeChannel1_mS_u16	31747			
k_BusOffRecoveryTimeChannel0_mS_u16	35074			
k_BusOffRecoveryTimeChannel1_mS_u16	58671			
target_BusOffCE_Cnt_T_lgc	0			
target_BusOffHS_Cnt_T_lgc	0			
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	11119			
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3243810254			
Name	Actual Value	Expected Value	Result	
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓	
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓	

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Actual Value	Expected Value	Result
BusOffFitChannel0DetectionTimer_mS_M_u32	3243810254	3243810254	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3243810254	3243810254	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3453754701	3453754701	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	4105035950	4105035950	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace					✓
Actual Function	Count	Expected Function	Count	Result	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓	
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓	
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓	

Test Step 2.34 (Repeat Count = 1) ✓

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	3748819617
BusOffFitChannel0RecoverTimer_mS_M_u32	1011278496
BusOffFitChannel1DetectionTimer_mS_M_u32	3527207520
BusOffFitChannel1RecoverTimer_mS_M_u32	4000133609
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	16570
k_BusOffFaultTimeChannel1_mS_u16	0
k_BusOffRecoveryTimeChannel0_mS_u16	29693
k_BusOffRecoveryTimeChannel1_mS_u16	63449
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	1431
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3197582565

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	3748819617	3748819617	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3197582565	3197582565	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3197582565	3197582565	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3197582565	3197582565	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace					✓
Actual Function	Count	Expected Function	Count	Result	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓	
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓	
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓	

Test Step 2.35 (Repeat Count = 1) ✓

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	530037193
BusOffFitChannel0RecoverTimer_mS_M_u32	182109366
BusOffFitChannel1DetectionTimer_mS_M_u32	70982200
BusOffFitChannel1RecoverTimer_mS_M_u32	3895554299
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value
BusOffPresentChannel0_Cnt_M_Igc	1
BusOffPresentChannel1_Cnt_M_Igc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	2
k_BusOffFaultTimeChannel0_mS_u16	55579
k_BusOffFaultTimeChannel1_mS_u16	65535
k_BusOffRecoveryTimeChannel0_mS_u16	28062
k_BusOffRecoveryTimeChannel1_mS_u16	49144
target_BusOffCE_Cnt_T_Igc	1
target_BusOffHS_Cnt_T_Igc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	58132
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	3888356062

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_Igc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_Igc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	530037193	530037193	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3888356062	3888356062	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	70982200	70982200	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3888356062	3888356062	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.36 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_Igc	target_BusOffCE_Cnt_T_Igc
BusOffDiagActiveChannel0_Cnt_M_Igc	1
BusOffDiagActiveChannel1_Cnt_M_Igc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	3011938866
BusOffFitChannel0RecoverTimer_mS_M_u32	3748819617
BusOffFitChannel1DetectionTimer_mS_M_u32	580719151
BusOffFitChannel1RecoverTimer_mS_M_u32	267463338
BusOffHS_Cnt_T_Igc	target_BusOffHS_Cnt_T_Igc
BusOffPresentChannel0_Cnt_M_Igc	1
BusOffPresentChannel1_Cnt_M_Igc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	0
k_BusOffFaultTimeChannel0_mS_u16	22316
k_BusOffFaultTimeChannel1_mS_u16	12452
k_BusOffRecoveryTimeChannel0_mS_u16	21163
k_BusOffRecoveryTimeChannel1_mS_u16	12901
target_BusOffCE_Cnt_T_Igc	1
target_BusOffHS_Cnt_T_Igc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	26581
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	1722143059

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_Igc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_Igc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	3011938866	3011938866	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1722143059	1722143059	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	580719151	580719151	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	1722143059	1722143059	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530

SrlComOutput_BusOffHandler



Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.37 (Repeat Count = 1)				
Name	Input Value			
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc			
BusOffDiagActiveChannel0_Cnt_M_lgc	0			
BusOffDiagActiveChannel1_Cnt_M_lgc	0			
BusOffFitChannel0DetectionTimer_mS_M_u32	2019950303			
BusOffFitChannel0RecoverTimer_mS_M_u32	530037193			
BusOffFitChannel1DetectionTimer_mS_M_u32	3403856094			
BusOffFitChannel1RecoverTimer_mS_M_u32	3714298874			
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc			
BusOffPresentChannel0_Cnt_M_lgc	0			
BusOffPresentChannel1_Cnt_M_lgc	1			
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime			
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime			
SysPwrMd_Cnt_T_enum	1			
k_BusOffFaultTimeChannel0_mS_u16	14724			
k_BusOffFaultTimeChannel1_mS_u16	1000			
k_BusOffRecoveryTimeChannel0_mS_u16	57840			
k_BusOffRecoveryTimeChannel1_mS_u16	116			
target_BusOffCE_Cnt_T_lgc	0			
target_BusOffHS_Cnt_T_lgc	0			
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	51060			
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	947628747			
Name	Actual Value	Expected Value	Result	
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓	
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓	
BusOffFitChannel0DetectionTimer_mS_M_u32	947628747	947628747	✓	
BusOffFitChannel0RecoverTimer_mS_M_u32	947628747	947628747	✓	
BusOffFitChannel1DetectionTimer_mS_M_u32	3403856094	3403856094	✓	
BusOffFitChannel1RecoverTimer_mS_M_u32	947628747	947628747	✓	
NTC	0x0100	0x0100	✓	
Param	0x0001	0x0001	✓	
Status	0x0000	0x0000	✓	
NTC	0x0110	0x0110	✓	
Param	0x0001	0x0001	✓	
Status	0x0001	0x0001	✓	

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.38 (Repeat Count = 1)				
Name	Input Value			
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc			
BusOffDiagActiveChannel0_Cnt_M_lgc	1			
BusOffDiagActiveChannel1_Cnt_M_lgc	0			
BusOffFitChannel0DetectionTimer_mS_M_u32	2749249828			
BusOffFitChannel0RecoverTimer_mS_M_u32	3011938866			
BusOffFitChannel1DetectionTimer_mS_M_u32	513365892			
BusOffFitChannel1RecoverTimer_mS_M_u32	1427923961			
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc			
BusOffPresentChannel0_Cnt_M_lgc	1			
BusOffPresentChannel1_Cnt_M_lgc	0			
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime			
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime			

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value
SysPwrMd_Cnt_T_enum	2
k_BusOffFaultTimeChannel0_mS_u16	3323
k_BusOffFaultTimeChannel1_mS_u16	0
k_BusOffRecoveryTimeChannel0_mS_u16	18840
k_BusOffRecoveryTimeChannel1_mS_u16	0
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	31289
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	90465543

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2749249828	2749249828	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	90465543	90465543	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	90465543	90465543	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	90465543	90465543	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.39 (Repeat Count = 1)				✔
Name		Input Value		
BusOffCE_Cnt_T_lgc		target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc		0		
BusOffDiagActiveChannel1_Cnt_M_lgc		0		
BusOffFitChannel0DetectionTimer_mS_M_u32		1786924653		
BusOffFitChannel0RecoverTimer_mS_M_u32		2019950303		
BusOffFitChannel1DetectionTimer_mS_M_u32		3337019614		
BusOffFitChannel1RecoverTimer_mS_M_u32		242703394		
BusOffHS_Cnt_T_lgc		target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc		0		
BusOffPresentChannel1_Cnt_M_lgc		1		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum		0		
k_BusOffFaultTimeChannel0_mS_u16		52026		
k_BusOffFaultTimeChannel1_mS_u16		52026		
k_BusOffRecoveryTimeChannel0_mS_u16		10137		
k_BusOffRecoveryTimeChannel1_mS_u16		65535		
target_BusOffCE_Cnt_T_lgc		0		
target_BusOffHS_Cnt_T_lgc		0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela		26129		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren		2742837091		
Name		Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc		0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc		1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32		2742837091	2742837091	✔
BusOffFitChannel0RecoverTimer_mS_M_u32		2742837091	2742837091	✔
BusOffFitChannel1DetectionTimer_mS_M_u32		3337019614	3337019614	✔
BusOffFitChannel1RecoverTimer_mS_M_u32		2742837091	2742837091	✔
NTC		0x0100	0x0100	✔
Param		0x0001	0x0001	✔
Status		0x0000	0x0000	✔

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.40 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	1625499818
BusOffFitChannel0RecoverTimer_mS_M_u32	2749249828
BusOffFitChannel1DetectionTimer_mS_M_u32	3946204200
BusOffFitChannel1RecoverTimer_mS_M_u32	1893154369
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	5547
k_BusOffFaultTimeChannel1_mS_u16	31145
k_BusOffRecoveryTimeChannel0_mS_u16	6836
k_BusOffRecoveryTimeChannel1_mS_u16	34565
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	38512
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1838444304

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1625499818	1625499818	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1838444304	1838444304	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	1838444304	1838444304	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	1838444304	1838444304	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.41 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	104711241
BusOffFitChannel0RecoverTimer_mS_M_u32	1786924653
BusOffFitChannel1DetectionTimer_mS_M_u32	3508479400
BusOffFitChannel1RecoverTimer_mS_M_u32	4275504771
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	2
k_BusOffFaultTimeChannel0_mS_u16	2125
k_BusOffFaultTimeChannel1_mS_u16	2125
k_BusOffRecoveryTimeChannel0_mS_u16	54702
k_BusOffRecoveryTimeChannel1_mS_u16	38574

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
target_BusOffCE_Cnt_T_lgc	0		
target_BusOffHS_Cnt_T_lgc	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	29911		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3508479400	3508479400	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.42 (Repeat Count = 1)				✓
Name		Input Value		
BusOffCE_Cnt_T_lgc		target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc		0		
BusOffDiagActiveChannel1_Cnt_M_lgc		1		
BusOffFitChannel0DetectionTimer_mS_M_u32		1246334520		
BusOffFitChannel0RecoverTimer_mS_M_u32		1625499818		
BusOffFitChannel1DetectionTimer_mS_M_u32		1475957856		
BusOffFitChannel1RecoverTimer_mS_M_u32		1817281359		
BusOffHS_Cnt_T_lgc		target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc		0		
BusOffPresentChannel1_Cnt_M_lgc		0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum		0		
k_BusOffFaultTimeChannel0_mS_u16		32741		
k_BusOffFaultTimeChannel1_mS_u16		32741		
k_BusOffRecoveryTimeChannel0_mS_u16		9305		
k_BusOffRecoveryTimeChannel1_mS_u16		39326		
target_BusOffCE_Cnt_T_lgc		0		
target_BusOffHS_Cnt_T_lgc		0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		34204		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		4294967295		
Name		Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc		0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc		1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32		4294967295	4294967295	✓
BusOffFitChannel0RecoverTimer_mS_M_u32		4294967295	4294967295	✓
BusOffFitChannel1DetectionTimer_mS_M_u32		1475957856	1475957856	✓
BusOffFitChannel1RecoverTimer_mS_M_u32		1817281359	1817281359	✓
NTC		0x0100	0x0100	✓
Param		0x0001	0x0001	✓
Status		0x0000	0x0000	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Test Step 2.43 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	1356285497
BusOffFitChannel0RecoverTimer_mS_M_u32	104711241
BusOffFitChannel1DetectionTimer_mS_M_u32	1072722438
BusOffFitChannel1RecoverTimer_mS_M_u32	939309710
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	31110
k_BusOffFaultTimeChannel1_mS_u16	5547
k_BusOffRecoveryTimeChannel0_mS_u16	36064
k_BusOffRecoveryTimeChannel1_mS_u16	46468
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	29477
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	234577

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	1356285497	1356285497	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	234577	234577	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	234577	234577	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	234577	234577	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.44 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	3953105980
BusOffFitChannel0RecoverTimer_mS_M_u32	1246334520
BusOffFitChannel1DetectionTimer_mS_M_u32	3730734968
BusOffFitChannel1RecoverTimer_mS_M_u32	219715415
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	2
k_BusOffFaultTimeChannel0_mS_u16	9247
k_BusOffFaultTimeChannel1_mS_u16	9247
k_BusOffRecoveryTimeChannel0_mS_u16	61
k_BusOffRecoveryTimeChannel1_mS_u16	59923
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1148692970

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	3953105980	3953105980	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1148692970	1148692970	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3730734968	3730734968	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Actual Value	Expected Value	Result
BusOffFitChannel1RecoverTimer_mS_M_u32	1148692970	1148692970	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.45 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	0
BusOffFitChannel0RecoverTimer_mS_M_u32	1356285497
BusOffFitChannel1DetectionTimer_mS_M_u32	1037570068
BusOffFitChannel1RecoverTimer_mS_M_u32	4249868551
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	4520
k_BusOffFaultTimeChannel1_mS_u16	4520
k_BusOffRecoveryTimeChannel0_mS_u16	51915
k_BusOffRecoveryTimeChannel1_mS_u16	17167
target_BusOffCE_Cnt_T_lgc	0
target_BusOffHS_Cnt_T_lgc	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3109709954

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	3109709954	3109709954	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3109709954	3109709954	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	1037570068	1037570068	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3109709954	3109709954	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.46 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	0
BusOffFitChannel0RecoverTimer_mS_M_u32	3953105980
BusOffFitChannel1DetectionTimer_mS_M_u32	1034796526
BusOffFitChannel1RecoverTimer_mS_M_u32	4003070099
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum	2		
k_BusOffFaultTimeChannel0_mS_u16	0		
k_BusOffFaultTimeChannel1_mS_u16	3323		
k_BusOffRecoveryTimeChannel0_mS_u16	45892		
k_BusOffRecoveryTimeChannel1_mS_u16	8580		
target_BusOffCE_Cnt_T_lgc	1		
target_BusOffHS_Cnt_T_lgc	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	12542		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	297671690		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	297671690	297671690	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	297671690	297671690	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	297671690	297671690	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.47 (Repeat Count = 1)				
Name		Input Value		
BusOffCE_Cnt_T_lgc		target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc		1		
BusOffDiagActiveChannel1_Cnt_M_lgc		0		
BusOffFitChannel0DetectionTimer_mS_M_u32		1356285497		
BusOffFitChannel0RecoverTimer_mS_M_u32		104711241		
BusOffFitChannel1DetectionTimer_mS_M_u32		1072722438		
BusOffFitChannel1RecoverTimer_mS_M_u32		939309710		
BusOffHS_Cnt_T_lgc		target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc		1		
BusOffPresentChannel1_Cnt_M_lgc		0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum		0		
k_BusOffFaultTimeChannel0_mS_u16		31110		
k_BusOffFaultTimeChannel1_mS_u16		5547		
k_BusOffRecoveryTimeChannel0_mS_u16		36064		
k_BusOffRecoveryTimeChannel1_mS_u16		46468		
target_BusOffCE_Cnt_T_lgc		1		
target_BusOffHS_Cnt_T_lgc		1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela		29477		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren		234577		
Name		Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc		1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc		0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32		1356285497	1356285497	✓
BusOffFitChannel0RecoverTimer_mS_M_u32		234577	234577	✓
BusOffFitChannel1DetectionTimer_mS_M_u32		234577	234577	✓
BusOffFitChannel1RecoverTimer_mS_M_u32		234577	234577	✓
NTC		0x0110	0x0110	✓
Param		0x0001	0x0001	✓
Status		0x0000	0x0000	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.48 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	3953105980
BusOffFitChannel0RecoverTimer_mS_M_u32	1246334520
BusOffFitChannel1DetectionTimer_mS_M_u32	3730734968
BusOffFitChannel1RecoverTimer_mS_M_u32	219715415
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	1
k_BusOffFaultTimeChannel0_mS_u16	9247
k_BusOffFaultTimeChannel1_mS_u16	9247
k_BusOffRecoveryTimeChannel0_mS_u16	61
k_BusOffRecoveryTimeChannel1_mS_u16	59923
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1148692970

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	3953105980	3953105980	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1148692970	1148692970	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3730734968	3730734968	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	1148692970	1148692970	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 2.49 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	0
BusOffFitChannel0RecoverTimer_mS_M_u32	1356285497
BusOffFitChannel1DetectionTimer_mS_M_u32	1037570068
BusOffFitChannel1RecoverTimer_mS_M_u32	4249868551
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	2
k_BusOffFaultTimeChannel0_mS_u16	4520
k_BusOffFaultTimeChannel1_mS_u16	4520
k_BusOffRecoveryTimeChannel0_mS_u16	51915
k_BusOffRecoveryTimeChannel1_mS_u16	17167
target_BusOffCE_Cnt_T_lgc	0
target_BusOffHS_Cnt_T_lgc	0
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Current	3109709954		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✔
BusOffFltChannel0DetectionTimer_mS_M_u32	3109709954	3109709954	✔
BusOffFltChannel0RecoverTimer_mS_M_u32	3109709954	3109709954	✔
BusOffFltChannel1DetectionTimer_mS_M_u32	1037570068	1037570068	✔
BusOffFltChannel1RecoverTimer_mS_M_u32	3109709954	3109709954	✔
NTC	0x0100	0x0100	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0001	0x0001	✔

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 2.50 (Repeat Count = 1)

Name	Input Value		
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc	1		
BusOffDiagActiveChannel1_Cnt_M_lgc	1		
BusOffFltChannel0DetectionTimer_mS_M_u32	0		
BusOffFltChannel0RecoverTimer_mS_M_u32	3953105980		
BusOffFltChannel1DetectionTimer_mS_M_u32	1034796526		
BusOffFltChannel1RecoverTimer_mS_M_u32	4003070099		
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc	1		
BusOffPresentChannel1_Cnt_M_lgc	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTin	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum	3		
k_BusOffFaultTimeChannel0_mS_u16	0		
k_BusOffFaultTimeChannel1_mS_u16	3323		
k_BusOffRecoveryTimeChannel0_mS_u16	45892		
k_BusOffRecoveryTimeChannel1_mS_u16	8580		
target_BusOffCE_Cnt_T_lgc	1		
target_BusOffHS_Cnt_T_lgc	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	12542		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	297671690		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✔
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✔
BusOffFltChannel0DetectionTimer_mS_M_u32	0	0	✔
BusOffFltChannel0RecoverTimer_mS_M_u32	297671690	297671690	✔
BusOffFltChannel1DetectionTimer_mS_M_u32	297671690	297671690	✔
BusOffFltChannel1RecoverTimer_mS_M_u32	297671690	297671690	✔
NTC	0x0110	0x0110	✔
Param	0x0001	0x0001	✔
Status	0x0000	0x0000	✔

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530

SriComOutput_BusOffHandler



Test Case 3: Path Test

Specification	Performance Metrics: (With "None" Instrumentation and "WithPS" Environment) CPU Cycles: TS 3.1 1071 Cycles TS 3.2 1592 Cycles TS 3.3 1347 Cycles TS 3.4 1074 Cycles TS 3.5 1345 Cycles TS 3.6 1336 Cycles TS 3.7 1080 Cycles TS 3.8 1082 Cycles
Description	Vector Description: TS3.1"if (BusOffPresentChannel0_Cnt_M_Igc == TRUE) =>FALSE else if (BusOffDiagActiveChannel0_Cnt_M_Igc == TRUE)>=>FALSE if (BusOffPresentChannel1_Cnt_M_Igc == TRUE)>=>FALSE else if (BusOffDiagActiveChannel1_Cnt_M_Igc == TRUE)>=>FALSE" TS3.2"if (BusOffPresentChannel0_Cnt_M_Igc == TRUE) =>TRUE if (ElapsedTime_mS_T_u16 >= k_BusOffFaultTimeChannel0_mS_u16) => TRUE if (BusOffPresentChannel1_Cnt_M_Igc == TRUE)>=>TRUE if (ElapsedTime_mS_T_u16 >= k_BusOffFaultTimeChannel1_mS_u16)>=>TRUE " TS3.3"if (ElapsedTime_mS_T_u16 >= k_BusOffFaultTimeChannel0_mS_u16)>=>FALSE else if (BusOffDiagActiveChannel1_Cnt_M_Igc == TRUE)>=>TRUE if (ElapsedTime_mS_T_u16 >= k_BusOffRecoveryTimeChannel1_mS_u16)>=>TRUE" TS3.4" if (ElapsedTime_mS_T_u16 >= k_BusOffRecoveryTimeChannel1_mS_u16)>=>FALSE" TS3.5"else if (BusOffDiagActiveChannel0_Cnt_M_Igc == TRUE)>=>TRUE if (ElapsedTime_mS_T_u16 >= k_BusOffRecoveryTimeChannel0_mS_u16)>=>TRUE" TS3.6if (ElapsedTime_mS_T_u16 >= k_BusOffFaultTimeChannel1_mS_u16)>=>FALSE TS3.7if (ElapsedTime_mS_T_u16 >= k_BusOffRecoveryTimeChannel0_mS_u16)>=>FALSE TS3.8(ElapsedTime_mS_T_u16 >= k_BusOffFaultTimeChannel0_mS_u16)=true && ysPwrMd_Cnt_T_enum == Run)=true

Test Step 3.1 (Repeat Count = 1)

Name	Input Value		
BusOffCE_Cnt_T_Igc	target_BusOffCE_Cnt_T_Igc		
BusOffDiagActiveChannel0_Cnt_M_Igc	0		
BusOffDiagActiveChannel1_Cnt_M_Igc	0		
BusOffFitChannel0DetectionTimer_mS_M_u32	0		
BusOffFitChannel0RecoverTimer_mS_M_u32	0		
BusOffFitChannel1DetectionTimer_mS_M_u32	0		
BusOffFitChannel1RecoverTimer_mS_M_u32	0		
BusOffHS_Cnt_T_Igc	target_BusOffHS_Cnt_T_Igc		
BusOffPresentChannel0_Cnt_M_Igc	0		
BusOffPresentChannel1_Cnt_M_Igc	0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum	0		
k_BusOffFaultTimeChannel0_mS_u16	0		
k_BusOffFaultTimeChannel1_mS_u16	0		
k_BusOffRecoveryTimeChannel0_mS_u16	0		
k_BusOffRecoveryTimeChannel1_mS_u16	0		
target_BusOffCE_Cnt_T_Igc	0		
target_BusOffHS_Cnt_T_Igc	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	0		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_Igc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_Igc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	0	0	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	0	0	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	0	0	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	0	0	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 3.2 (Repeat Count = 1)				
Name	Input Value			
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc			
BusOffDiagActiveChannel0_Cnt_M_lgc	1			
BusOffDiagActiveChannel1_Cnt_M_lgc	1			
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295			
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295			
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295			
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295			
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc			
BusOffPresentChannel0_Cnt_M_lgc	1			
BusOffPresentChannel1_Cnt_M_lgc	1			
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime			
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime			
SysPwrMd_Cnt_T_enum	1			
k_BusOffFaultTimeChannel0_mS_u16	65535			
k_BusOffFaultTimeChannel1_mS_u16	65535			
k_BusOffRecoveryTimeChannel0_mS_u16	65535			
k_BusOffRecoveryTimeChannel1_mS_u16	65535			
target_BusOffCE_Cnt_T_lgc	1			
target_BusOffHS_Cnt_T_lgc	1			
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	65535			
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4294967295			
Name	Actual Value	Expected Value	Result	
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓	
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓	
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✓	
BusOffFitChannel0RecoverTimer_mS_M_u32	4294967295	4294967295	✓	
BusOffFitChannel1DetectionTimer_mS_M_u32	4294967295	4294967295	✓	
BusOffFitChannel1RecoverTimer_mS_M_u32	4294967295	4294967295	✓	
NTC	0x0110	0x0110	✓	
Param	0x0001	0x0001	✓	
Status	0x0001	0x0001	✓	

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 3.3 (Repeat Count = 1)				
Name	Input Value			
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc			
BusOffDiagActiveChannel0_Cnt_M_lgc	1			
BusOffDiagActiveChannel1_Cnt_M_lgc	1			
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295			
BusOffFitChannel0RecoverTimer_mS_M_u32	0			
BusOffFitChannel1DetectionTimer_mS_M_u32	1894110714			
BusOffFitChannel1RecoverTimer_mS_M_u32	3861796421			
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc			
BusOffPresentChannel0_Cnt_M_lgc	1			
BusOffPresentChannel1_Cnt_M_lgc	0			
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime			
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime			
SysPwrMd_Cnt_T_enum	2			
k_BusOffFaultTimeChannel0_mS_u16	60825			
k_BusOffFaultTimeChannel1_mS_u16	22795			
k_BusOffRecoveryTimeChannel0_mS_u16	25882			

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
k_BusOffRecoveryTimeChannel1_mS_u16	8229		
target_BusOffCE_Cnt_T_lgc	0		
target_BusOffHS_Cnt_T_lgc	0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	11354		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	3072927859		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	4294967295	4294967295	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	3072927859	3072927859	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	3072927859	3072927859	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	3072927859	3072927859	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓

Test Step 3.4 (Repeat Count = 1)				✔
Name		Input Value		
BusOffCE_Cnt_T_lgc		target_BusOffCE_Cnt_T_lgc		
BusOffDiagActiveChannel0_Cnt_M_lgc		0		
BusOffDiagActiveChannel1_Cnt_M_lgc		1		
BusOffFitChannel0DetectionTimer_mS_M_u32		1246334520		
BusOffFitChannel0RecoverTimer_mS_M_u32		4294967295		
BusOffFitChannel1DetectionTimer_mS_M_u32		1665706824		
BusOffFitChannel1RecoverTimer_mS_M_u32		4193367413		
BusOffHS_Cnt_T_lgc		target_BusOffHS_Cnt_T_lgc		
BusOffPresentChannel0_Cnt_M_lgc		0		
BusOffPresentChannel1_Cnt_M_lgc		0		
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime		target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime		
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)		target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime		
SysPwrMd_Cnt_T_enum		3		
k_BusOffFaultTimeChannel0_mS_u16		64680		
k_BusOffFaultTimeChannel1_mS_u16		9295		
k_BusOffRecoveryTimeChannel0_mS_u16		30312		
k_BusOffRecoveryTimeChannel1_mS_u16		54157		
target_BusOffCE_Cnt_T_lgc		0		
target_BusOffHS_Cnt_T_lgc		0		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela		44983		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren		1430223038		
Name		Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc		0	0	✔
BusOffDiagActiveChannel1_Cnt_M_lgc		1	1	✔
BusOffFitChannel0DetectionTimer_mS_M_u32		1430223038	1430223038	✔
BusOffFitChannel0RecoverTimer_mS_M_u32		1430223038	1430223038	✔
BusOffFitChannel1DetectionTimer_mS_M_u32		1665706824	1665706824	✔
BusOffFitChannel1RecoverTimer_mS_M_u32		4193367413	4193367413	✔
NTC		0x0100	0x0100	✔
Param		0x0001	0x0001	✔
Status		0x0000	0x0000	✔

Test Step Call Trace				
Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Test Step 3.5 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFitChannel0DetectionTimer_mS_M_u32	3953105980
BusOffFitChannel0RecoverTimer_mS_M_u32	1944666162
BusOffFitChannel1DetectionTimer_mS_M_u32	672947379
BusOffFitChannel1RecoverTimer_mS_M_u32	947495828
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	0
k_BusOffFaultTimeChannel0_mS_u16	60017
k_BusOffFaultTimeChannel1_mS_u16	22013
k_BusOffRecoveryTimeChannel0_mS_u16	5555
k_BusOffRecoveryTimeChannel1_mS_u16	32711
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	24947
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	2370584731

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	0	0	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	2370584731	2370584731	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	2370584731	2370584731	✓
BusOffFitChannel1DetectionTimer_mS_M_u32	672947379	672947379	✓
BusOffFitChannel1RecoverTimer_mS_M_u32	947495828	947495828	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 3.6 (Repeat Count = 1)

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFitChannel0DetectionTimer_mS_M_u32	4167849
BusOffFitChannel0RecoverTimer_mS_M_u32	1555615171
BusOffFitChannel1DetectionTimer_mS_M_u32	2003570018
BusOffFitChannel1RecoverTimer_mS_M_u32	2583579405
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	1
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	0
k_BusOffFaultTimeChannel0_mS_u16	40570
k_BusOffFaultTimeChannel1_mS_u16	65016
k_BusOffRecoveryTimeChannel0_mS_u16	0
k_BusOffRecoveryTimeChannel1_mS_u16	23359
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	62334
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	1957662919

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFitChannel0DetectionTimer_mS_M_u32	4167849	4167849	✓
BusOffFitChannel0RecoverTimer_mS_M_u32	1957662919	1957662919	✓

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Actual Value	Expected Value	Result
BusOffFltChannel1DetectionTimer_mS_M_u32	2003570018	2003570018	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	1957662919	1957662919	✓

Test Step Call Trace ✓

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 3.7 (Repeat Count = 1) ✓

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	1
BusOffDiagActiveChannel1_Cnt_M_lgc	1
BusOffFltChannel0DetectionTimer_mS_M_u32	2899086231
BusOffFltChannel0RecoverTimer_mS_M_u32	2119330630
BusOffFltChannel1DetectionTimer_mS_M_u32	2422532780
BusOffFltChannel1RecoverTimer_mS_M_u32	3985430462
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	0
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	0
k_BusOffFaultTimeChannel0_mS_u16	4620
k_BusOffFaultTimeChannel1_mS_u16	4620
k_BusOffRecoveryTimeChannel0_mS_u16	65535
k_BusOffRecoveryTimeChannel1_mS_u16	30588
target_BusOffCE_Cnt_T_lgc	1
target_BusOffHS_Cnt_T_lgc	1
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime	8561
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime	4085748062

Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	1	1	✓
BusOffFltChannel0DetectionTimer_mS_M_u32	2899086231	2899086231	✓
BusOffFltChannel0RecoverTimer_mS_M_u32	2119330630	2119330630	✓
BusOffFltChannel1DetectionTimer_mS_M_u32	2422532780	2422532780	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	3985430462	3985430462	✓

Test Step Call Trace ✓

Actual Function	Count	Expected Function	Count	Result
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓

Test Step 3.8 (Repeat Count = 1) ✓

Name	Input Value
BusOffCE_Cnt_T_lgc	target_BusOffCE_Cnt_T_lgc
BusOffDiagActiveChannel0_Cnt_M_lgc	0
BusOffDiagActiveChannel1_Cnt_M_lgc	0
BusOffFltChannel0DetectionTimer_mS_M_u32	2061747645
BusOffFltChannel0RecoverTimer_mS_M_u32	4078039705
BusOffFltChannel1DetectionTimer_mS_M_u32	1140263597
BusOffFltChannel1RecoverTimer_mS_M_u32	386778569
BusOffHS_Cnt_T_lgc	target_BusOffHS_Cnt_T_lgc
BusOffPresentChannel0_Cnt_M_lgc	1
BusOffPresentChannel1_Cnt_M_lgc	0
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16(ElapsedTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_ElapsedTime
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32(CurrentTime)	target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_CurrentTime
SysPwrMd_Cnt_T_enum	2
k_BusOffFaultTimeChannel0_mS_u16	28632
k_BusOffFaultTimeChannel1_mS_u16	36500
k_BusOffRecoveryTimeChannel0_mS_u16	47030

TEST DETAILS REPORT

2016-06-29, 13:53:50+0530



SrlComOutput_BusOffHandler

Name	Input Value		
k_BusOffRecoveryTimeChannel1_mS_u16	17447		
target_BusOffCE_Cnt_T_lgc	1		
target_BusOffHS_Cnt_T_lgc	1		
target_Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16_Ela	31532		
target_Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32_Curren	2839643349		
Name	Actual Value	Expected Value	Result
BusOffDiagActiveChannel0_Cnt_M_lgc	1	1	✓
BusOffDiagActiveChannel1_Cnt_M_lgc	0	0	✓
BusOffFltChannel0DetectionTimer_mS_M_u32	2061747645	2061747645	✓
BusOffFltChannel0RecoverTimer_mS_M_u32	2839643349	2839643349	✓
BusOffFltChannel1DetectionTimer_mS_M_u32	2839643349	2839643349	✓
BusOffFltChannel1RecoverTimer_mS_M_u32	2839643349	2839643349	✓
NTC	0x0100	0x0100	✓
Param	0x0001	0x0001	✓
Status	0x0001	0x0001	✓
NTC	0x0110	0x0110	✓
Param	0x0001	0x0001	✓
Status	0x0000	0x0000	✓

Test Step Call Trace					✓
Actual Function	Count	Expected Function	Count	Result	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓	
Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	Rte_Call_Ap_SrlComOutput_SystemTime_DtrmnElapsedTime_mS_u16	1	✓	
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓	
Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	Rte_Call_Ap_SrlComOutput_SystemTime_GetSystemTime_mS_u32	1	✓	
Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	Rte_Call_Ap_SrlComOutput_NxtrDiagMgr_SetNTCStatus	1	✓	

TEST DETAILS REPORT

2016-06-29, 13:47:50+0530

ApplNwmBusoffEnd



Project	GMSrIComOutput
Module	GMSrIComOutput
Test Object	ApplNwmBusoffEnd

Instrumentation: Test Object Only

Statement (C0) Coverage	100 %
Branch (C1) Coverage	100 %

Statistics

Total Testcases	1
Successful	1 ✓
Failed	0
Not Executed	0

Module Properties

Project Root Directory	D:\Synergy_Work_Area\GMSrIComOutput
Configuration File	D:\Synergy_Work_Area\GMSrIComOutput\UnitTestEnv\config\TMS570_GCC_UDE_CCS4_Config.xml
Target Environment	TI TMS 570 PLS UDE (Default)
Kind of Test	Unit Test
Linker Options	
Source File(s)	
File	\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\src\Ap_SrIComOutput.c
Compiler Options	-D_DATA_ACCESS= -Dconst= -Dextern= -Dmemcpy=memcpy_dup -Dstatic= -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\utp\contract -I\$(PROJECTROOT)\GMSrIComOutput\GMSrIComOutput\include -I\$(PROJECTROOT)\NxrLib\include -I\$(PROJECTROOT)\StdDef\include -I\$(Compiler Install Path)\include

Comments/Description/Specification

Name	Text
------	------

TEST DETAILS REPORT

2016-06-29, 13:47:50+0530

ApplNwmBusoffEnd



Module 'GMSrComOutput'

***** Unit Test Description*****

Name of Tester:Namrata Morbale
Code File(s) Under Test:Ap_SrComOutput.c
Code File(s) Version:5
Module Design Document:Serial_Communication_Output_MDD.doc
Module Design Document Version:3
Data Dictionary Version:3
Unit Test Plan Version:1
Optimization Level:Level 2
Compiler (CodeGen) Version:TMS470_4.9.5
Model Type:Excel Macro
Model Version:Nexteer EPS Unit Test Tool 2.7d/EPS Library 1.32
Total FLASH Used (Bytes):3574
Total RAM Used (Bytes):304
Total CALS Used (Bytes):15
Special Test Requirements:NA
Test Date:6/29/2016
Comments:Note1:Inline function defined in Globalmacro.h is not unit tested.

Note2:In function ""SriComOutput_Per1"" and ""SriComOutput_Per2"",typecasting code is added in VBA to avoid overflow issue.

Note3:In function ""SriComOutput_Per1"",100% path coverage is not achieved because at src line 1081, condition ""else if (TRUE == k_LKAMfgEnable_Cnt_Igc)=False"" cannot be covered as if we make k_LKAMfgEnable_Cnt_Igc=False control goes to else path.

Note4:In function ""SriComOutput_Per1"", 100% path coverage is not achieved because at src line 1062 conditions ""(DriverAppliedTorque_HwNm_T_f32 >= 10.23f) = True"" and ""(DriverAppliedTorque_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1066 ""(LKATorqueDelivered_HwNm_T_f32 >= 10.23f) = True"" and ""(LKATorqueDelivered_HwNm_T_f32 <= -10.24f) = True"" cannot be covered due to usage of ""Limit_m"" macro.

Note5:In function ""SriComOutput_Per2"", 100% path coverage is not achieved because at src line 1292 conditions ""(SriComHwPos_HwDeg_T_f32 >= 2047.9375f) = True""and ""(SriComHwPos_HwDeg_T_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro. Similarly at src line 1298 conditions ""(HandwheelVel_HwDegpS_f32 >= 2047.0f) = True"" and ""(HandwheelVel_HwDegpS_f32 <= -2048.0f) = True"" cannot be covered due to usage of ""Limit_m"" macro.

Note6: The range of the parameter ""txObject"" is used as 0 to 1 in UTP for functions "" Appl_1E5MsgTxAck_HS and Appl_1E5MsgTxAck_CE "".

Note7: ""CBD_Sandbox_dbg.map"" map file is embedded for reference.

Attributes	
Name	Value
Compiler Install Path	\$(ProgramFiles)\Texas Instruments\ccsv4\tools\compiler\tms470_4.9.5
Float Precision	9
InitObjDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\obj
InitSrcDir	\$(PROJECTROOT)\UnitTestEnv\static_build_files\src
Linker File	\$(PROJECTROOT)\UnitTestEnv\static_build_files\sys_link.cmd
Makefile Template	\$(PROJECTROOT)\UnitTestEnv\config\Nexteer_ts_make_ude_ti_tms570.tpl
Target Install Path	\$(ProgramFiles)\pls\UDE 4.4
Timer Enabled	False
Timer Prescale	0
Timer Resolution	1
Timer Unit	Cycles
UDE Config File	\$(PROJECTROOT)\UnitTestEnv\config\TMS570_UDE_12PIN_JTAG.cfg
Workspace File	D:\Synergy_Work_Area\GMSrComOutput\UnitTestEnv\config\UDE_TMS570_DEBUG.WSP

Test Case 1: Range Test ✓

Specification Performance Metrics:
(With "None" Instrumentation and "WithPS"
Environment)

CPU Cycles:

TS1.1 16 Cycles

Description Vector Description:

TS1.1No functionality present in source

Test Step 1.1 (Repeat Count = 1) ✓

Test Step Call Trace ✓

Actual Function	Count	Expected Function	Count	Result
none	0	*** No Call Expected ***	0	✓