

Index

1. Overview
 - What is Runebrace
 - Why Runebrace
 - Getting Help
2. Getting Started
 - Downloading and Installing
 - UI Overview
 - Your First Project
 - Understanding File Types
3. Supporting Models
 - Basic workflow
 - Placing supports
 - Features
 -
 - Presets
4. Working with Meshes
 - Repairs
 - Replacing a Mesh/Model
 - Cutting a Mesh
5. Hollowing
6. Printing and Slicing

Glossary

See the Glossary for a list of commonly used terms and definitions.

Overview

Getting Started

Downloading and Installing

OS/Platform Differences

- Keyboard shortcuts

UI Overview

Your First Project

Understanding File Types

Supporting Models

Supporting Overview

Basic Workflow

Features

Support Basics

- Horizontal line of layers

Manual Supports

Symmetry

Path Supports

Path supports


Line “What happens when you draw support lines or arcs is that it simulates a mouse clicking on various points along this line (depending on the set distance) and performs a mouse raycast on the model. If the raycast hits the geometry and the face is not parallel to the build plate or tilted upwards, a support is placed. It is likely that there are some raycast misses, so the support cannot be placed and is skipped. It’s not a matter of whether the surface is flat... the geometry must be under the ray cast by the mouse and be a valid point for a support.”

Arc

Circle

Fill Basics

We’ll start with a basic example, then show a more complex, practical example after. Triangle Fills will be covered in a separate section below.



All examples start from this point.




Figure 1: Polygon Fill button

Polygon Fill Polygon Fill takes three or more selected supports as the corners of a polygon and fills the area inside it with supports.

Perimeter and Fill Perimeter & Fill does the same but also lays supports along the outline itself, which is the difference the highlighted border in the icon is showing.




Figure 2: Poly fill




Figure 3: Poly fill with border

Circle Fill Circle Fill takes exactly three supports, builds the circle that passes through their contact points, and fills that.




Figure 4: Circle fill

Triangle Painting

Rim

Presets

Working with Meshes

Hollowing

Printing and Slicing

Glossary

Here are common terms and phrases used in Runebrace.

Path Path applies to Line, Arc, and Circle. For two selected supports, Runebrace builds a path using a raycast between two points. For three selected supports, Runebrace will build a path by creating a curve that passes through all three supports' contact points.

Rim In triangle mode, “Rim” denotes the border of a painted triangle selection. It is determined from the mesh edges, and can have both an outer border *plus* the borders of any holes inside that particular selection. See also: “Outer Rim Only” and “All boundaries” options in the Triangle Paint panel.