

Hu v. Hyundai Motor America

AG Case No. NC-1-1249605441 · VIN: KM8KNDDF9RU253237

EXHIBIT 20 — DASHBOARD PHOTOGRAPHS: BATTERY RANGE DEGRADATION TIMELINE

Consumer: Jimmy Y. Hu · Hearing: June 9, 2026 · Arbitrator: Maneesha Sharma

PURPOSE

Four chronological dashboard photographs documenting progressive battery range degradation. These photographs visually corroborate the defect timeline in Repair Orders (Ex. 4), Smart Diagnosis Report (Ex. 10), and Days Out of Service Summary (Ex. 11). All photos taken from the vehicle's own instrument cluster.

Photo	Date	Odometer	Charge	Range Shown	Significance
1	Feb 19, 2025	7,223 mi	91%	127 mi	First degradation — >50% range loss ■
2	Apr 1, 2025	8,087 mi	41%	17 mi	Pre-service severity
3	Apr 3, 2025	8,128 mi	100%	37 mi ★	Day vehicle dropped off — corroborates RO #358530
4	Aug 12, 2025	8,276 mi	10%	23 mi	Coolant warning 5 days post-pickup ■

Photo 1 — Feb 19, 2025 (7,223 mi) — FIRST DOCUMENTED DEGRADATION: 127 mi at 91% Charge [CRITICAL]



CRITICAL EVIDENCE. Only 127 miles at 91% charge. At delivery (May 2024), 90% charge yielded approximately 270 miles — this represents greater than 50% loss in functional range, and is the first documented manifestation of the battery defect. Consumer first became aware of the defect at this date. The Hyundai Smart Diagnosis report (Exhibit 10) documents the underlying fault codes.

Photo 2 — Apr 1, 2025 (8,087 mi) — Accelerating Failure: Only 17 mi at 41% Charge



Two days before Consumer drove the vehicle to Paramus Hyundai on April 3. Only 17 miles at 41% charge — a functioning IONIQ 5 at 41% charge would show approximately 110+ miles of range. The vehicle was becoming completely unusable for any meaningful travel. This photograph corroborates the urgency of Consumer's decision to bring the vehicle directly to Paramus Hyundai on April 3, 2025.

Photo 3 — Apr 3, 2025 (8,128 mi) — PIVOTAL: Only 37 mi at 100% Full Charge — Day Consumer Drove to Paramus and Left Vehicle for Service [PIVOTAL]



THE KEY PHOTOGRAPH IN THIS EXHIBIT. Dashboard shows only 37 miles at 100% charge with Level 2 charging confirmed complete. A fully charged 2024 Hyundai IONIQ 5 SEL AWD should display approximately 266+ miles at 100% charge. This photograph directly corroborates Repair Order #358530 (Exhibit 4), in which Paramus Hyundai confirmed 'deviations in multiple cells' via Techline diagnostics. Consumer drove the vehicle to the service center on this date, left it with Paramus Hyundai, and received a loaner vehicle. The vehicle remained at the service center for 126 consecutive days. Odometer reads 8,128 miles — consistent with RO documentation.

Photo 4 — Aug 12, 2025 (8,276 mi) — 'Refill Coolant' Warning: 5 Days After Pickup



Consumer retrieved the vehicle on August 7, 2025 after 126 consecutive days in service. Just 5 days later — August 12, 2025 — the dashboard displayed a prominent 'Refill coolant' warning with orange alert icon. The vehicle was immediately returned to Paramus Hyundai for service completed August 28–29, 2025. Odometer reads 8,276 — only 148 miles driven in 5 days post-pickup. Combined with the April–August repair period, total documented loss-of-use reaches 179+ days.