



KM8KND9F9RU253237

BB8AANJ0332601080341

01/08/26 12:50



Smart Diagnosis



KM8KND9F9RU253237
B28AANJ0332601080341

IONIQ 5 (NE EV)/2024/70kW+160kW



System Status

7

ECU Upgrade

Vehicle Information

Mapping Status

0



Not Supported

All DTC(5 System, 7 DTCs)

(See video)

Powertrain Chassis Body

SYSTEM / DTC CODE DESCRIPTION

State

VCMS | Vehicle Charging Management System
PIB4D92 Battery Charger Coupler Temperature too High

History

ABSESC | ABS/ESC
C110213 Battery Voltage Low


ADAS_DRV | ADAS Driving ECU
C188186 FR/RR_C_RDR Signal Error Fault

C_RADAR | Corner Radar
C270754 Control Module Missing Calibration (Front Right)

ICU | Integrated Central Control Unit
B235300 Dedicated DRL RH SCG

ICU | Integrated Central Control Unit
B258A00 External Tail Lamp Front Right Circuit Short to Ground

ICU | Integrated Central Control Unit
C162800 CAN Time-Out CLU



These are the codes in the system we need 4 hours of diagnosis \$1040 of diagnose the vehicle IN order to see what else the vehicle needs.



Rescan



Erase all DTC



Report

S/W Ver.

NNH-02-0102

VCI Ver.

03.25

Res Ver.

NNH-02-000A

OS Ver.



KM8KND9F9RU253237

BB8AANJ0332601080341

01/08/26 12:50



Smart Diagnosis



KM8KND9F9RU253237
B28AANJ0332601080341

IONIQ 5 (NE EV)/2024/70kW+160kW



System Status

7

ECU Upgrade

Vehicle Information

Mapping Status



Not Supported

All DTC(5 System, 7 DTCs)

(See video)

Powertrain Chassis Body

SYSTEM / DTC CODE DESCRIPTION

State

VCMS | Vehicle Charging Management System
PIB4D92 Battery Charger Coupler Temperature too High

History

ABSESC | ABS/ESC
C110213 Battery Voltage Low


ADAS_DRV | ADAS Driving ECU
C188186 FR/RR_C_RDR Signal Error Fault

C_RADAR | Corner Radar
C270754 Control Module Missing Calibration (Front Right)

ICU | Integrated Central Control Unit
B235300 Dedicated DRL RH SCG

ICU | Integrated Central Control Unit
B258A00 External Tail Lamp Front Right Circuit Short to Ground

ICU | Integrated Central Control Unit
C162800 CAN Time-Out CLU



These are the codes in the system we need 4 hours of diagnosis \$1040 of diagnose the vehicle IN order to see what else the vehicle needs.



Erase all DTC



Report

S/W Ver.

NNH-02-0102

VCI Ver.

03.25

Res Ver.

NNH-02-0008

OS Ver.