

J.S.T. Mfg. Co., Ltd.

du I	J.S. I. Mfg. Co., Ltd.		Page	1/2
Title of Document:	Request for Change	Issue No.		Rev.
		G21-05752		0
Customer:		Issue date:		
Customer.		September 1, 2021		
Title subject:	EH/PH/VH connectors: Addition of resin material for header	Revision date:		

Please take note that we would like to add the resin material manufacturer for header of the EH/PH/VH connectors as follows.

1. Target product and Part number

Series	Туре	Part number
EH	Top entry type	B*B-EH-() (LF)(SN) B*B-EH-A-() (LF)(SN)
	Side entry type	S*B-EH-() (LF)(SN)
PH	Top entry type	B*B-PH-K-() (LF)(SN)
ΓΠ	Side entry type	S*B-PH-K-() (LF)(SN)
	Top entry type	B*P-VH-() (LF)(SN)
VH	Side entry type	S*P-VH-() (LF)(SN) B*PS-VH-() (LF)(SN)



Note) Number of circuits is indicated in *.

A character of an alphabet showing color is indicated in ().

2. Timing of the change

Production is scheduled to start in mid-September 2021 or later.

Prepared by:	Checked by:	Reviewed by:	Approved by:
F.Kuriyama	M. Veda	M.Araki	T.Fujiwara

IAR-4101-1-2

JST

EH/PH/VH connectors: Addition of resin material for header Title subject:

No.

G21-05752

3. Contents

The resin material manufacturer for header of the aforementioned products shall be added as follows. As for the additional product (made of additional resin), we will be applying for UL/CSA certification one by one. Until UL/CSA certification are obtained for the additional products, "(SU)" as identification symbol is suffixed to the conventional part number in order to distinguish with the current product. Identification symbol "(SU)" will be deleted after obtaining UL/CSA certification, and unify to original part numbers.

	Resin material maker	Resin part No.	Part No.	Product code
Current product	Toray Industries, Inc.	CM3004V0	B*B-EH-() (LF)(SN) B*B-EH-A-() (LF)(SN) S*B-EH-() (LF)(SN) B*B-PH-K-() (LF)(SN) S*B-PH-K-() (LF)(SN) B*P-VH-() (LF)(SN) S*P-VH-() (LF)(SN)	Current code
Additional product (Advance release product) (Applying for UL/CSA)	KINGFA (金発)	PA66-RNG00	B*B-EH-() (LF)(SN)(SU) B*B-EH-A-() (LF)(SN)(SU) S*B-EH-() (LF)(SN) (SU) B*B-PH-K-() (LF)(SN) (SU) S*B-PH-K-() (LF)(SN) (SU) B*P-VH-() (LF)(SN) (SU) S*P-VH-() (LF)(SN) (SU) B*PS-VH-() (LF)(SN) (SU)	New code
Additional product (After UL/CSA certification)	Toray Industries, Inc. KINGFA (金発)	CM3004V0 PA66-RNG00	B*B-EH-() (LF)(SN) B*B-EH-A-() (LF)(SN) S*B-EH-() (LF)(SN) B*B-PH-K-() (LF)(SN) S*B-PH-K-() (LF)(SN) B*P-VH-() (LF)(SN) S*P-VH-() (LF)(SN)	Current code

4. Reason for the change

This change will be carried out because availability of the resin material for header shall be improved.

Your thought understanding and consideration would be very much appreciated.