


ESP32 native TX → LR2021: strict packet acceptance



SF7 · BW203.125 kHz · 19/20 accepted · all 20 payloads exact

*Mixed header-valid/header-error IRQ: rejected. One fresh attempt per cell; one indoor board pair.