



B5 MAX

Metal Bath Heating and Cooling Instrument

Software Operation Manual

Shanghai Quanxinpin Biotechnology Co., Ltd.

April 22, 2026

1 Overview

1.1 Purpose of This Manual

The purpose of this manual is to enable users to correctly, safely, and effectively operate the Metal Bath Heating and Cooling Control System, achieving precise temperature control to meet laboratory and industrial application requirements.

1.2 Icon Definitions

The following table lists the icons:

2 System Login

After powering on, the screen displays the boot screen (~3s), then enters self-test. The system checks sensors within 10s.



Figure 2-1 Power-On Self-Test Page

After successful self-test, the system enters Manual Setting.



Figure 2-2 Manual Setting Main Page

3 Manual Mode

3.1 Manual Mode Page Overview



Figure 3-1 Manual Mode Page

3.2 Temperature Setting

3.3 Time Setting

3.4 Rate Mode

3.5 Common Temperature Shortcuts

3.6 Return to Room Temperature

4 Program Control

4.1 Program Control Page Overview




Figure 4-1 Program Control Page

4.2 Program Editing

4.2.1 Program Library Page



Figure 4-2 Program Library Page

4.2.3 Program Edit Page




Figure 4-3 Program Edit Page

5 Run Curve




Figure 5-1 Run Curve Page

6 System Settings

6.1 System Settings Overview



QR Code

Important Notes

1. Stop before turning off. Wait for room temp.
2. Do not restart immediately after shutdown.